

TL  
242  
.B33  
v.2

DOT HS-802 026

# **NATIONAL PARTS RETURN PROGRAM Volume II Technical Report**

**Contract No. DOT-HS-5-01166  
September 1976  
Final Report**

**PREPARED FOR  
U.S. DEPARTMENT OF TRANSPORTATION  
National Highway Traffic Safety Administration  
Washington, D.C. 20590**

**Document is available to the public through  
the National Technical Information Service,  
Springfield, Virginia 22161**

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no liability for its contents or use thereof.

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                                      |                                                                                                                                             |           |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| 1. Report No.<br>DOT HS-802 026                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 2. Government Accession No.                          | 3. Recipient's Catalog No.                                                                                                                  |           |
| 4. Title and Subtitle<br>National Parts Return Program;<br>Volume II Technical Report,                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                                                      | 5. Report Date<br>September 1976                                                                                                            |           |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                                      | 6. Performing Organization Code                                                                                                             |           |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                                      | 8. Performing Organization Report No.                                                                                                       |           |
| 7. Author(s)<br>B. Beddow J. Peizer G. Whiddon                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                                                      | 10. Work Unit No. (TRAIS)                                                                                                                   |           |
| 9. Performing Organization Name and Address<br>Kappa Systems Incorporated<br>1501 Wilson Blvd.<br>Arlington, Virginia 22209                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                      | 11. Contract or Grant No.<br>DOT-HS-5-01166                                                                                                 |           |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                                      | 13. Type of Report and Period Covered<br>Final Report<br>1 July 1975 to 30 June 1976                                                        |           |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                                      | 14. Sponsoring Agency Code                                                                                                                  |           |
| 12. Sponsoring Agency Name and Address<br>Department of Transportation<br>National Highway Traffic Safety Administration<br>Office of Defects Investigation                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                      |                                                                                                                                             |           |
| 15. Supplementary Notes                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                                                      |                                                                                                                                             |           |
| 16. Abstract<br><br>The National Parts Return Program involves the voluntary submittal by independent automotive Repair shops of failed automotive components. The purpose of this program is to gather information on these components to assist the NHTSA to identify the existence of safety-related, manufacturing defects in design, materials, construction, on performance of motor vehicles and motor vehicle equipment. Under authority of the National Traffic and Motor Vehicle Safety Act of 1966, and amendments to the Act in 1974, the NHTSA can require manufacturers to conduct safety defect notification campaigns when it has been determined that a defect relating to motor vehicle safety exists. In addition, the information obtained from these parts is also valuable in preparing Federal Motor Vehicle Safety Standards. |                                                      |                                                                                                                                             |           |
| 17. Key Words<br>Parts Return Program<br>Defects Investigation                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                                                      | 18. Distribution Statement<br>Document is available to the public through the National Technical Information Service, Springfield, Va 22151 |           |
| 19. Security Classif. (of this report)<br>unclassified                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | 20. Security Classif. (of this page)<br>unclassified | 21. No. of Pages<br>244                                                                                                                     | 22. Price |


# METRIC CONVERSION FACTORS

## Approximate Conversions to Metric Measures

| Symbol                     | When You Know          | Multiply by                | To Find             | Symbol          |
|----------------------------|------------------------|----------------------------|---------------------|-----------------|
| <b>LENGTH</b>              |                        |                            |                     |                 |
| in                         | inches                 | *2.5                       | centimeters         | cm              |
| ft                         | feet                   | 30                         | centimeters         | cm              |
| yd                         | yards                  | 0.9                        | meters              | m               |
| mi                         | miles                  | 1.6                        | kilometers          | km              |
| <b>AREA</b>                |                        |                            |                     |                 |
| in <sup>2</sup>            | square inches          | 6.5                        | square centimeters  | cm <sup>2</sup> |
| ft <sup>2</sup>            | square feet            | 0.09                       | square meters       | m <sup>2</sup>  |
| yd <sup>2</sup>            | square yards           | 0.8                        | square meters       | m <sup>2</sup>  |
| mi <sup>2</sup>            | square miles           | 2.6                        | square kilometers   | km <sup>2</sup> |
|                            | acres                  | 0.4                        | hectares            | ha              |
| <b>MASS (weight)</b>       |                        |                            |                     |                 |
| oz                         | ounces                 | 28                         | grams               | g               |
| lb                         | pounds                 | 0.45                       | kilograms           | kg              |
|                            | short tons (2000 lb)   | 0.9                        | tonnes              | t               |
| <b>VOLUME</b>              |                        |                            |                     |                 |
| tsp                        | teaspoons              | 5                          | milliliters         | ml              |
| Tbsp                       | tablespoons            | 15                         | milliliters         | ml              |
| fl oz                      | fluid ounces           | 30                         | milliliters         | ml              |
| c                          | cups                   | 0.24                       | liters              | l               |
| pt                         | pints                  | 0.47                       | liters              | l               |
| qt                         | quarts                 | 0.95                       | liters              | l               |
| gal                        | gallons                | 3.8                        | liters              | l               |
| ft <sup>3</sup>            | cubic feet             | 0.03                       | cubic meters        | m <sup>3</sup>  |
| yd <sup>3</sup>            | cubic yards            | 0.76                       | cubic meters        | m <sup>3</sup>  |
| <b>TEMPERATURE (exact)</b> |                        |                            |                     |                 |
| °F                         | Fahrenheit temperature | 5/9 (after subtracting 32) | Celsius temperature | °C              |

## Approximate Conversions from Metric Measures

| Symbol                     | When You Know                     | Multiply by       | To Find                | Symbol          |
|----------------------------|-----------------------------------|-------------------|------------------------|-----------------|
| <b>LENGTH</b>              |                                   |                   |                        |                 |
| mm                         | millimeters                       | 0.04              | inches                 | in              |
| cm                         | centimeters                       | 0.4               | inches                 | in              |
| m                          | meters                            | 3.3               | feet                   | ft              |
| km                         | kilometers                        | 1.1               | yards                  | yd              |
|                            |                                   | 0.6               | miles                  | mi              |
| <b>AREA</b>                |                                   |                   |                        |                 |
| cm <sup>2</sup>            | square centimeters                | 0.16              | square inches          | in <sup>2</sup> |
| m <sup>2</sup>             | square meters                     | 1.2               | square yards           | yd <sup>2</sup> |
| km <sup>2</sup>            | square kilometers                 | 0.4               | square miles           | mi <sup>2</sup> |
| ha                         | hectares (10,000 m <sup>2</sup> ) | 2.5               | acres                  |                 |
| <b>MASS (weight)</b>       |                                   |                   |                        |                 |
| g                          | grams                             | 0.035             | ounces                 | oz              |
| kg                         | kilograms                         | 2.2               | pounds                 | lb              |
| t                          | tonnes (1000 kg)                  | 1.1               | short tons             |                 |
| <b>VOLUME</b>              |                                   |                   |                        |                 |
| ml                         | milliliters                       | 0.03              | fluid ounces           | fl oz           |
| l                          | liters                            | 2.1               | pints                  | pt              |
| l                          | liters                            | 1.06              | quarts                 | qt              |
| l                          | liters                            | 0.26              | gallons                | gal             |
| m <sup>3</sup>             | cubic meters                      | 35                | cubic feet             | ft <sup>3</sup> |
| m <sup>3</sup>             | cubic meters                      | 1.3               | cubic yards            | yd <sup>3</sup> |
| <b>TEMPERATURE (exact)</b> |                                   |                   |                        |                 |
| °C                         | Celsius temperature               | 9/5 (then add 32) | Fahrenheit temperature | °F              |



\*1 in. ± 2.54 (exact). For other exact conversions and more detailed tables, see NBS Misc. Publ. 286, Units of Weights and Measures, Price \$2.25, SD Catalog No. C13,10-286.

VOLUME II  
TECHNICAL REPORT  
TABLE OF CONTENTS

|                                                                | <u>Page No.</u> |
|----------------------------------------------------------------|-----------------|
| Technical Report Documentation Page                            |                 |
| Section 1: Parts Return Program Operations                     | 1- 1            |
| 1.0 General                                                    | 1- 1            |
| 1.1 Monthly Letter Type Progress Report                        | 1- 2            |
| 1.2 New Shop Enlistment Plan                                   | 1- 2            |
| 1.3 New Shop Identification Numbers                            | 1- 5            |
| 1.4 Automated Mailing List System                              | 1- 7            |
| 1.5 Preparation of the PRP Newsletter                          | 1- 8            |
| 1.6 Readdressing Old GEC Mailbags                              | 1- 9            |
| 1.7 Required Materials                                         | 1-11            |
| 1.7.1 Failed Part Tags and Failed Data Sheets                  | 1-11            |
| 1.7.2 The PRP HS-10 Form                                       | 1-11            |
| 1.7.3 Certificate of Participation                             | 1-14            |
| Section 2: Specific PRP Procedures                             | 2- 1            |
| 2.0 General                                                    | 2- 1            |
| 2.1 Processing of New Enrolled Shops                           | 2- 1            |
| 2.1.1 Preparation of Required Shop Materials                   | 2- 1            |
| 2.1.2 Processing Steps                                         | 2- 2            |
| 2.2 Processing of Failed Component or Information Received     | 2- 2            |
| 2.3 Monthly Report of Failed Parts Received                    | 2- 4            |
| 2.4 Shop Discontinuance                                        | 2- 4            |
| 2.5 Shop Participation                                         | 2- 5            |
| Section 3: Failed Part Summary                                 | 3- 1            |
| 3.0 General                                                    | 3- 1            |
| 3.1 Failed Part Summary                                        | 3- 2            |
| 3.2 Parts Received in Support of Investigations                | 3- 7            |
| 3.3 Detailed Records Stored in the ODI/Data Information System | 3-10            |
| Section 4: The PRP News                                        | 4- 1            |
| 4.0 General                                                    | 4- 1            |
| 4.1 Copies of PRP News                                         | 4- 2            |

## TABLE OF CONTENTS (continued)

### Page No.

#### List of Figures

|                                       |     |
|---------------------------------------|-----|
| Figure 1 - PRP Regional Offices       | 1-4 |
| Figure 2 - Total Participants by Area | 1-6 |

#### Attachments

|                                       |     |
|---------------------------------------|-----|
| 1. Shop Questionnaire                 | A-1 |
| 2. Introductory Letters 1 and 2       | A-2 |
| 3. Letter to Morton Grove Post Office | A-3 |
| 4. Certificate of Participation       | A-4 |
| 5. Monthly Report                     | A-5 |

VOLUME II  
TECHNICAL REPORT

SECTION 1  
PARTS RETURN PROGRAM OPERATIONS  
1 July 1975 through 30 June 1976

1.0      General

Upon assuming the responsibility for operation of the PRP on 1 July 1975 certain tasks were identified as priority items. These included:

- Separately identify active participants from inactive participants. We established the criteria to distinguish between active and inactive by stating that any shop which contributed a failed part in the previous year would be considered active. The purpose of this analysis was to provide us with an indication as to the level of activity we were assuming.
- Establishing a more concise and easily used unique shop coding scheme.
- Defining the computer related data file design for both the automated mailing label system and ODI Data Information System PRP records.
- Re-evaluating the current newsletter and designing a layout which would attract new shop participation.
- Assessing our inventory of mailbags on hand and establishing procedures to obtain as many as possible already in the hands of PRP enrollees. We decided that it was imperative that active participants be resupplied with new KSI addressed mailbags first.
- Making final selection of our PRP Regional Representatives in strategic geographic locations.
- Securing a failed parts storage facility which was in close proximity to our Arlington, Virginia offices.

- Developing, preparing, then reproducing required materials such as a) PRP letterhead, b) failed part bags, c) form acknowledgment letters, d) failed component sheets, e) PRP HS-10 forms, f) and new Certificates of Participation.

#### 1.1 Monthly Letter Type Progress Reports

Our contract did not require the submittal of monthly progress reports, however, we felt that this type of project status reporting mechanism would be beneficial to the NHTSA in several ways. First, it highlights accomplishments over the preceding reporting period, second, it can identify potential problem areas and therefore, corrective action can be initiated promptly, and third, these reports become a historical reference and record of project development and performance.

We proposed in July 1975 to replace the required three oral briefings outlined in our contract with these twelve monthly letter progress reports and our proposal was accepted by the NHTSA. The format of the progress report was designed to provide the following information:

- Accomplishments made during the reporting period.
- Funds committed during the reporting period.
- What is planned for accomplishment during the next reporting period.
- Items of timely interest including results, trends, etc.
- Problems or delays experienced and recommendations for solutions.
- Specific action required by the ODI to alleviate a problem.
- Summaries of Parts Received including Failed Data Sheets.

Copies of delivered progress reports are retained by the Office of Defects Investigation and the Office of Contracts and Procurement of the NHTSA.

#### 1.2 New Shop Enlistment Plan

Our approach to new shop enrollment was to follow the guidelines established by the NHTSA and to solicit new enrollees via the telephone. Our unique approach, however, was to identify one key PRP Regional Representative in each of 10 geographic regions established by KSI.

The rationale for state assignments within regions was based primarily on the first character of the zip code. This scheme interfaced nicely with the scheme

developed for the new shop identification numbers (see Section 1.3). There was one exception to this scheme, however, and that was the state of New Jersey. The first character of the zip code for New Jersey is 0, however, for convenience we grouped this state in Region 1.

The regions we established and the locations of our initial PRP Regional Representatives are indicated in Figure 1. In total, five new shop enrollment campaigns were conducted. These enrollment campaigns were conducted in Regions 1, 2A, 5, 8, and 9. Each Regional Representative was briefed on conducting the enrollment campaign and the background of the PRP prior to commencing their contacts. In most campaigns automotive repair shop names and telephone numbers were taken from the yellow pages of the local telephone books.

Each Regional Representative was sent a separate list of existing active and inactive PRP enrollees in their region. This procedure eliminated the possibility of contacting a shop already enrolled in the program.


In most regions, the Regional Representative was instructed to telephone contact all shops from their inactive lists as a follow-up procedure. Green questionnaires were filled out and sent back to our Arlington, Virginia offices for review. A large number of these telephone contacts resulted in deletion of the shop from the program due to non-interest, out of business, etc. A relatively small number of those shops contacted via this method became active participants. We believe the reason for this high deletion rate was that these shops had been PRP enrollees for quite some time (2 years or more) and had never actively participated. The probability that they would become active participants at this time was very low.

We found, on the average, that approximately 80% of those shops contacted by telephone agreed to enroll in the program. A total of 402 new shops were enlisted during the contract period.

In order to evaluate different follow-up procedures for new shops which had recently enrolled in the program, we initiated two different approaches. These different approaches were tested in Seattle, Washington and Norfolk, Virginia. In Seattle, after a period of 30 days we sent each new shop which had not sent in a part a stern letter suggesting that the shop might be asked to withdraw from the program if they did not contribute failed parts in the near future. In Norfolk, we had the Regional Representative

Figure 1

# NATIONAL PARTS RETURN PROGRAM REGIONAL OFFICES



telephone each shop after a period of 30 days had elapsed. Each approach had basically the same good result.

As each new shop was enrolled into the program a "Shop Questionnaire" was completed and sent to the Arlington office. A copy of the questionnaire is presented in Attachment 1. Once screened and accepted at our Arlington office by key staff personnel, the new shop was sent a "shop kit" (a description of the shop kit is provided in following sections of this report).

Current PRP geographic enrollment distribution is depicted in Figure 2 as of 30 April 1976. For the months of May and June 1976, recently completed enrollment campaigns in the western regions will increase their total enrollment by approximately 100 enrollees.

### 1.3 New Shop Identification Numbers

The development of the current shop identification number coding scheme was predicated on our desire to associate the assigned PRP regions with a shop number readily identified within a specific region. Similarly, we were interested in identifying the state and local geographic area of the shop. For this reason, we decided that the best choice of unique shop identification numbers would be an eight character code number, the first five of which would be their zip code and the last three a numerical sequence number for that state.

The five character zip code identifies the exact geographic location of the shop and the three sequential numeric characters identify the unique record of that shop within the state. These last three characters uniquely identify each shop from all other shops located in the same city, etc.

A major task was encountered when the new scheme was accepted by the NHTSA and we proceeded to reassign new shop identification numbers to over 1800 existing shops. Once the numbers had been assigned, state by state, the names and addresses of these shops along with the new identification numbers were released to our computer data preparation section.

Our existing operational procedures require that a log of the highest sequential number assigned in each state be maintained daily. As new shops are enrolled, the last task accomplished after screening their questionnaire is the assignment of their unique identification number.




Figure 2  
TOTAL PARTICIPANTS BY AREA

#### 1.4 Automated Mailing List System

In order to expedite the preparation of a large volume of labels in use for addressing the newsletter and the Defect Investigatory Cases Report and to provide a tool for the maintenance of records, KSI developed and implemented the automated PRP mailing list system.

The shop identification file from which the mailing label system operates currently consists of 1077 addresses. The data entry format is as follows:

##### Columns

##### Card 1

|       | <u>Field Description</u>                         |
|-------|--------------------------------------------------|
| 1- 6  | Unique Record #                                  |
| 7-22  | First Name                                       |
| 23-38 | Last Name                                        |
| 39-70 | Title                                            |
| 71-78 | Unused                                           |
| 79    | Card #1                                          |
| 80    | Action Code: A = Add<br>M = Modify<br>D = Delete |

##### Card 2

|       |                                                  |
|-------|--------------------------------------------------|
| 1- 6  | Unique Record # (Dup card 1, columns 1-6)        |
| 7-38  | Shop Name                                        |
| 39-47 | Shop ID#                                         |
| 48-64 | Unused                                           |
| 65-70 | Date of Enrollment                               |
| 71-78 | Unused                                           |
| 79    | Card #2                                          |
| 80    | Action Code: A = Add<br>M = Modify<br>D = Delete |

##### Card 3

|       |                                           |
|-------|-------------------------------------------|
| 1- 6  | Unique Record # (Dup card 1, columns 1-6) |
| 7-38  | Mailing Address                           |
| 39-54 | City                                      |
| 55-56 | State                                     |
| 57-61 | Zip Code                                  |
| 62-64 | Area Code                                 |
| 65-71 | Telephone Number                          |

Columns  
Card (cont)

Field Description

|       |                                                  |
|-------|--------------------------------------------------|
| 72    | Enter "A" to designate Active Participant        |
| 73-78 | Unused                                           |
| 79    | Card #3                                          |
| 80    | Action Code: A = Add<br>M = Modify<br>D = Delete |

This system provides several PRP monitoring functions as well as producing name and address labels. These additional functions include recording the mailbag numbers written on the mailbags sent to a specific shop and identifying active participants from inactive participants. Once each month, this file is updated and new listings of both inactive and active participant records are produced. As developments occur during the month they are entered manually on the listings until such time as the next data file updating takes place.

The current system is operated on a Datapoint 2200 mini-computer located in our Arlington offices. The operating programs are written in Databus and the data resides on a disk.

#### 1.5 Preparation of the PRP Newsletter

The backbone of the PRP in terms of maintaining two way communications with over 2000 enrollees, is through the preparation and distribution of the newsletter. This single document is responsible for the increase of active participation in the program. Although there are other documents such as the Investigatory Cases Report which, when distributed to the enrollees has an impact on participation, the distribution of the newsletter on schedule and in its present format is the single highest source of motivation to PRP members in terms of obtaining failed parts.

We recognized this fact early in the contract year and immediately decided to prepare and distribute a newsletter tailored more to capturing new shop participants. Our concern has been to develop a document which would appeal to shops which were interested in furthering highway safety.

We felt that by publishing articles particularly tailored to special interests of individual shops, listing by name each shop who contributed a part, and providing a histogram type of chart matching active participants against inactive participants by

region, special enthusiasm and interest could be developed. We are convinced this approach works as 144 new active shops were brought into the program last year as opposed to 46 the year before.

We also felt that by providing information on what the NHTSA was accomplishing in the area of defects investigations and initiation of recall campaigns was extremely important. We believe the shops need to have some insight into the purpose of the program, what their failed parts might be used for and what has happened in the past. We therefore concentrated on articles describing current recall campaigns, completed investigations, and interesting statistical articles taken from such publications as the National Highway Safety Needs Report, a report by the Secretary of Transportation to the United State Congress dated April 1976 and a NHTSA publication, Traffic 74. We have encouraged members to respond directly to the newsletter by creating a "forum" in our article 'Items of Interest'. Selected comments from members are published and information on particular problems is often specifically requested. We believe this feature has been instrumental in developing and maintaining interest in the program as the volume of telephone calls and letters related to these articles has increased over the contract period.

The procedures for monthly newsletter preparation required that we supply the NHTSA Contract Technical Manager (CTM) with a draft copy of a specific newsletter the last week of the month covered. The draft is approved and returned to KSI by the following week. Rework as required takes place during this time and the final draft of the newsletter is sent to our graphics section at the end of the first week of the following month. Our reproduction facility receives the approved copy early in the second week of the following month. Since we had preprinted PRP 'masks' for the front page, reproduction amounted to making a reproducible plate of any photographs to be used and offset printing of the newsletter. Originally, 2000 newsletters were printed. Upon completion of our last enrollment campaign this number was increased to 2300 (April 1976). The overall time period for initial preparation to distribution of the newsletter takes approximately three weeks. Our target for distribution is the 15th of the month following the month reported on.

#### 1.6 Readdressing Old GEC Mailbags

Shortly after 1 July 1975 (the start of this contract period) 600 mailbags plus

other assorted materials were received from General Environment Corporation. We felt it was imperative to readdress these mailbags and send them to our estimated 191 active participants as quickly as possible to prevent any decrease in program continuity resulting from a switch in support contractors.

In the meantime, two letters were prepared and signed by the Director of the Office of Defects Investigation. Each letter introduced KSI as the new contractor succeeding GEC. The first letter was sent to our 191 active participants (see Attachment 2) and the second was sent to approximately 1667 inactive participants.

Prior to purchasing new bags, the program operations were based on first, maintaining continuity with our 191 active participants and second, securing mailbags that had been previously distributed to the 1667 inactive participants. The records maintenance and extensive communication required to try and obtain these mailbags from the inactive shops were difficult and expensive. This problem resulted from the previous requirement to supply each enrolled shop with at least three mailbags (this contract period initially required five mailbags be sent to active shops and two mailbags to new enrollees).

At the time we assumed program responsibility we estimated that there were approximately 5000 mailbags in the hands of the PRP enrollees. Even with our extensive efforts to secure these bags for the program, we were only successful in obtaining approximately 800 mailbags.

In the interim, the NHTSA Contract Technical Manager issued instructions to the local post office involved in the previous contract asking their assistance in forwarding mailbags to KSI (see Attachment 3). This was a great help and allowed program operations to continue on an otherwise critical situation.

All 600 mailbags received from GEC initially were readdressed via a silk screening and painting procedure. This was accomplished within two weeks after receipt. Contacts with the U. S. Post Office Department were necessary prior to our producing the template in order to obtain approval. Once this approval was obtained the actual silk screening process proved very efficient and successful.

A new order for 2500 mailbags was placed in February 1976 and received in March 1976.

## 1.7 Required Materials

Numerous letters, mostly form letters have been prepared over the period of this contract. All of which are contained in our individual monthly progress reports. Certain items however, need to be discussed in this report.

### 1.7.1 Failed Part Tags and Failed Data Sheets

The failed part tags are utilized by the shop to identify the failed part and vehicle at the time they send in the part. Omission of owner name and address and failure to use the protective plastic covers supplied was an initial recurrence. The failed data sheets were used by our analysts at KSI to record and expand pertinent information on the failed part. Photographs or other information were attached to these documents.

No major changes to the layout or format were incorporated into these documents. A few fields of information were rearranged and expanded.

### 1.7.2 The PRP HS-10 Form

A complete revision of this form was required for two basic reasons. First, data fields being used on the form were restricted and currently being used by the computer software to record the file update date. This meant that all data recorded in these fields was subsequently lost at the time of file updating. Secondly, an expansion of the PRP file was required to include other data fields proposed and accepted by the ODI CTM.

The format of the PRP File within the ODI DIS Vehicle Owner File is as follows:

| <u>Columns</u> | <u>Field Description</u>                 |
|----------------|------------------------------------------|
| <u>Card A1</u> |                                          |
| 1- 6           | Unique PRP #                             |
| 7-18           | Part owner's last name                   |
| 19-30          | Part owner's first name & middle initial |
| 31-40          | Part owner's city                        |
| 41-42          | Part owner's state                       |
| 43-47          | Part owner's zip code                    |
| 48-53          | Date part received                       |
| 54-72          | Space is unusable                        |
| 73-75          | Initials of coder                        |
| 76-77          | Source ID "PR"                           |
| 78-79          | Group ID "A" Sequence "1"                |

## Columns

Card A1 (cont)

80

Field Description

Action Code: A = Add  
 M = Modify  
 D = Delete

Card A2

1- 6  
 7-15  
 16-25  
 26-33  
 34-63  
 64-77  
 78-79  
 80

Unique PRP # (Dup card A1, columns 1-6)  
 Shop ID number  
 Part owner's telephone number (if available)  
 Unused  
 Part owner's street address  
 Space is unusable  
 Group ID "A" Sequence "2"  
 Action Code: A = Add  
 M = Modify  
 D = Delete

Card B1

1- 6  
 7-11  
 12-13  
 14-15  
 16-17  
 18-33  
 34-36  
 37-39  
 40-45  
 46-51  
 52  
 53-68  
 69-70  
 71  
 72  
 73  
 74  
 75-77  
 78-79  
 80

Unique PRP # (Dup card A1, columns 1-6)  
 Manufacturer/make/model code  
 Vehicle model year  
 Vehicle category  
 Body style  
 Vehicle identification number  
 Cubic inch displacement (CID)  
 Horsepower  
 Vehicle mileage at failure  
 Date part removed from vehicle  
 Vehicle "N" (New) or "U" (Used)  
 Other vehicle model names  
 Source "PR"  
 Failure type - check code  
 Property damage - check code  
 Environmental conditions - check code  
 Driving conditions  
 Monitored by  
 Group ID "B" Sequence "1"  
 Action Code: A = Add  
 M = Modify  
 D = Delete

Columns  
Card B2

Field Description

|       |                                                                                                                                     |
|-------|-------------------------------------------------------------------------------------------------------------------------------------|
| 1- 6  | Unique PRP # (Dup card A1, columns 1-6)                                                                                             |
| 7-11  | Component classification code                                                                                                       |
| 12-13 | Component location - check codes                                                                                                    |
| 14-15 | Failure/fault code                                                                                                                  |
| 16-43 | Component part no. - Left justify                                                                                                   |
| 44    | Original (O) equipment or Replacement (R)                                                                                           |
|       | Market                                                                                                                              |
| 45-50 | Component mileage at failure                                                                                                        |
| 51-59 | Inventory Control "Bin" #                                                                                                           |
| 51-53 | Bin location, i. e. , 100, 110, 120, etc                                                                                            |
| 54-55 | Number of part within bin, i. e. , 09 = ninth part in bin                                                                           |
| 56-59 | Alpha description of part location:<br>DOT1 ODI Office<br>DOT2 ODI Storage<br>DOT3 ODI Testing<br>INV1 KSI Storage<br>DISP Disposed |
| 60-61 | Number of failure occurrences                                                                                                       |
| 62-65 | Federal Motor Vehicle Safety Standard-check applicable list                                                                         |
| 66    | Hazard category - check codes                                                                                                       |
| 67    | Accident? "Y" = Yes                                                                                                                 |
| 68-69 | Number of injuries - Right justify                                                                                                  |
| 70-71 | Number of fatalities - Right justify                                                                                                |
| 72-77 | Number of parts received from shop - Right justify - zero fill                                                                      |
| 78-79 | Group ID "B" Sequence "2"                                                                                                           |
| 80    | Action Code: A = Add<br>M = Modify<br>D = Delete                                                                                    |

Card B3

|       |                                                  |
|-------|--------------------------------------------------|
| 1- 6  | Unique PRP # (dup card A1, columns 1-6)          |
| 7-76  | Comments - failure description                   |
| 77    | Unusable                                         |
| 78-79 | Group ID "B" Sequence "3"                        |
| 80    | Action Code: A = Add<br>M = Modify<br>D = Delete |

Columns  
Card B4

Field Description

|       |                                         |
|-------|-----------------------------------------|
| 1- 6  | Unique PRP # (Dup card A1, columns 1-6) |
| 7-14  | Special report number                   |
| 15-77 | Unusable                                |
| 78-79 | Group ID "B" Sequence "4"               |
| 80    | Action Code: A = Add                    |
|       | M = Modify                              |
|       | D = Delete                              |

1.7.3 Certificate of Participation

Each shop which contributes at least one failed part to the PRP receives two framed certificates. Since these certificates were the only visible reward to a shop for their time and effort, we felt that the existing certificate required some rework.

The current certificate  $8\frac{1}{2}$ " x 11" is printed on parchment paper and is in two colors - red and black. Attachment 4 is a copy.

## SECTION 2

### SPECIFIC PRP PROCEDURES

#### 2.0 General

The operation of the Parts Return Program required that certain procedures be carried out routinely and on a daily basis, others on an intermittent basis, and some only on occasion. The processing of returned parts occurred daily, the processing of new enrolled shops was a function performed only during enrollment campaigns, and the function of contacting other interested automotive associations for support was on a periodic basis.

#### 2.1 Processing of New Enrolled Shops

After contact by our Regional Representatives and completion of the shop questionnaire, the new shop name and address were added to all necessary records and the materials required for participation were forwarded to the shop.

##### 2.1.1 Preparation of Required Shop Materials

Prior to enrolling new shops in the program all printed materials were produced. These items were then assembled into shop kits. Each shop kit contained:

- An introductory letter
- One (1) mailbag for returning parts. Each mailbag was pre-addressed and postage-free. In addition, each bag was assigned a bag identification number.
- Five (5) Part Tags, for part identification. Each tag carried the unique shop identification number.
- Five (5) plastic zip-lock envelopes for protection of part tags.
- Copies of previous PRP newsletters and Defects Investigatory Cases Report publications.
- Instructions on completing the failed part tag, and requests to place the tag in the protective cover.
- One page flyers requesting specific parts.

- Any other PRP promotional material available such as copies of articles published by the Automotive Service Council, the National Association of Trade and Technical Schools, or the American Automobile Association.

#### 2.1.2 Processing Steps

The following is a list of the steps performed in sequence for processing a newly enrolled shop.

- 1) A shop is contacted by our Regional Representative (usually by telephone) to participate in the Parts Return Program. When the shop agrees to enroll in the program a Shop Questionnaire is completed by the Regional Representative and forwarded to our Washington offices. After screening of the questionnaire, a unique shop ID number is assigned to the shop.
- 2) The name and address of the shop are added to the Parts Return Program automated mailing list as an inactive participant.
- 3) The appropriate Shop Identification Number is stamped on the failed part tags and the mailbag ID number is entered into the automated shop file records.
- 4) The Shop Kit is mailed to the shop.
- 5) The Shop Questionnaire is filed in the three ring binder with the shop ID number written in the upper right hand corner.

#### 2.2 Processing of Failed Component or Information Received

The following is a list of steps performed in processing the PRP inputs received.

##### Steps in Parts Processing

- a) Mailbags, letters, or telephone calls are received daily.
- b) The identification number recorded on the failed part tags is checked against the shop ID file listings to determine the shop that returned the part. Also the ID number on the mailbag is checked against the same file for shop verification.

- c) All information pertaining to the shop is recorded in the daily log. This assures that there is a record of every part received. Letters or telephone calls are also recorded in the log.
- d) Each entry on the daily log is checked against the shop file records to determine the status of the shop, i. e., active or inactive. If the shop is inactive, their name is forwarded to graphics where a certificate of participation is prepared.
- e) An acknowledgement letter confirming receipt of the parts is mailed to the shop. Mailbags replacing those returned are mailed to this shop. Numbers of returned bags are deleted from the automated mailing list and the new bag numbers are recorded.
- f) The parts are returned to their mailbags and sent to the storage facility for further processing.
- g) At the storage facility the parts are inspected and a failed data sheet completed for each part. A unique PRP number is assigned and a log showing the month assigned and bin number is completed. The completed failed data sheets are then sent to our data transcription section where HS-10 forms are prepared in accordance with the instructions specified in the ODI/DIS operations manual.
- h) A copy of the HS-10 form is forwarded to our keypunch section where computer input decks are prepared. The input is read into the vehicle owner letter file from which monthly computer generated reports are prepared.
- i) After the computer files have been satisfactorily updated, the completed failed data sheet and completed HS-10 form are submitted to the ODI CTM at the end of each month along with the progress report.
- j) If the failure is unique, or of special interest, a photograph is taken for use in the newsletter.
- k) Failed parts are stored in bins in the storage facility randomly. The bin # is recorded on the HS-10 form and added to the computer record. At any time this record can be retrieved and a location

of the part provided. Likewise, summaries can be automatically produced which list identical components. These features of the automated system make it unnecessary that similar components be physically grouped together in the storage facility.

- 1) Mailbags are sent to the laundry as required.

### 2.3 Monthly Report of Failed Parts Received

After the HS-10 forms have been keypunched for each part received, the card decks are used to provide updates to the ODI Data Information System Vehicle Owner Letter File. Each input record is uniquely identified by encoding a "P" as the first character of the ODI # field. This P distinguishes these records as belonging to the PRP. The remaining five character positions are filled with a sequential numeric value. This procedure provides that within the Vehicle Owner Letter File each recorded failed part has a unique record identification.

Monthly retrieval of these records from the information system in a format approved by the NHTSA CTM provides a detailed report of the failed parts for the month. Present capabilities provide that these monthly reports can be sorted by PRP #, unique shop code #, or component classification code. In other words, we can sort these reports to provide any of the following information.

- A listing by sequential PRP #s (a historical record)
- A listing grouping all of the records from the same shop together--this information tells us how many parts have been received from any one shop, state or region.
- A listing grouping all of the records of identical components--this information tells us how many identical parts we have received.

A copy of this report is Attachment 5. Note that this report is by PRP #.

### 2.4 Shop Discontinuance

As indicated previously in this final report we did not delete inactive shops from the PRP based upon a pre-established set of criteria, i. e., 12 months time limit to send in a part, etc. We did, however, initiate written and telephone follow-up campaigns to shops considered to be old inactive and to shops who were newly enrolled into the program. We found that the results of these follow-up campaigns were very beneficial to program operations. Previous experience in operating the PRP indicated that

an average of 12 months was needed from the time a shop was enrolled into the program to the time that shop submitted the first failed part. Our experience is presented in the table below which depicts averages from receipt of the last part in months. Note the reduction in time following either a written or telephone follow-up campaign.

|                      | <u>Ave. # of mos.<br/>between date of<br/>enrollment &amp; date<br/>of 1st part</u> | <u># of shops</u> | <u>Ave. # of mos.<br/>from date of last<br/>phone contact &amp;<br/>date of 1st part<br/>received</u> | <u># of shops<br/>contacted</u> | <u>Ave. # of mos.<br/>including post<br/>card campaigns<br/>as a contact</u> | <u># of shops<br/>affected</u> |
|----------------------|-------------------------------------------------------------------------------------|-------------------|-------------------------------------------------------------------------------------------------------|---------------------------------|------------------------------------------------------------------------------|--------------------------------|
| Region 0             | 31.5                                                                                | 8                 | 4.6                                                                                                   | 5                               | 4.0                                                                          | 1                              |
| Region 1             | 24.1                                                                                | 13                | 3.0                                                                                                   | 6                               | -                                                                            | 0                              |
| Region 2             | 17.0                                                                                | 12                | 2.3                                                                                                   | 6                               | -                                                                            | 0                              |
| Region 3             | 24.2                                                                                | 6                 | 1.0                                                                                                   | 1                               | -                                                                            | 0                              |
| Region 4             | 22.0                                                                                | 5                 | 4.2                                                                                                   | 4                               | -                                                                            | 0                              |
| Region 5             | 18.6                                                                                | 6                 | 4.6                                                                                                   | 3                               | 4.0                                                                          | 1                              |
| Region 6             | 20.0                                                                                | 4                 | 2.0                                                                                                   | 1                               | -                                                                            | 0                              |
| Region 7             | 18.6                                                                                | 5                 | -                                                                                                     | 0                               | 2.0                                                                          | 1                              |
| Region 8             | 26.1                                                                                | 10                | 3.3                                                                                                   | 6                               | -                                                                            | 0                              |
| Region 9             | 13.8                                                                                | 15                | 2.8                                                                                                   | 7                               | -                                                                            | 0                              |
| Totals &<br>Averages | 21.6                                                                                | 84                | 3.1                                                                                                   | 39                              | 3.3                                                                          | 3                              |

## 2.5 Shop Participation

A total of 232 individual shops contributed 942 failed parts to the program during this contract period. These figures represent, on the average, a yield of 4.06 parts from each shop. Of these 232 active program participants 144 were new KSI active shops and 88 were repetitive shops from the previous contract year. Of the 144 new KSI active shops 31 were enrolled by KSI and 113 enrolled by the previous contractor.

There were 402 new enrollees enlisted into the PRP during this contract period. Of these new enrollees 31 or 8% became active participants. It is apparent that this figure is not satisfactory and should be increased, to at least 20%. It is also apparent that more stringent screening on the part of the Regional Representative and the questionnaire review staff is required. It should be noted, however, that these

figures are a little misleading as a good number of the new enrollees were enlisted during the last quarter of the contract period and in many cases have not completed the average contribution time of three months (see previous table). In any event, we recognize the problem that enlisting new shops into the program is relatively easy while motivating them to become active participants is quite difficult.

## SECTION 3

### FAILED PART SUMMARY

#### 3.0 General

The failed parts received during this contract period covered 39 separate and distinct motor vehicle major component assembly areas. These major areas are listed below in Section 3.1 with a detailed identification of the part received, along with the quality of each.

The breakdown for the types of failed parts appears in the table below.

| <u>Major Assembly<br/>Classification</u>        | <u>% of Total<br/>Received</u> |
|-------------------------------------------------|--------------------------------|
| Brakes-hydraulic system                         | 24.3                           |
| Engine                                          | 14.0                           |
| Steering linkages                               | 9.8                            |
| Suspension-independent front                    | 9.8                            |
| Switch button ring-unspecified light            | 5.9                            |
| Exhaust system                                  | 4.4                            |
| Fuel carburetion                                | 4.0                            |
| Fuel systems                                    | 2.6                            |
| Engine cooling systems                          | 2.5                            |
| Electrical system - ignition                    | 2.2                            |
| Power train drive line                          | 1.9                            |
| Suspension, single - axle, rear                 | 1.8                            |
| Steering gear box                               | 1.7                            |
| Steering power assist                           | 1.7                            |
| Alternation regulator starter                   | 1.7                            |
| Throttle linkages and control                   | 1.4                            |
| Water-heater, defroster                         | 1.2                            |
| Visual systems-windshield wiper, washer & glass | <1.0                           |
| Train, transmission, automotive                 | <1.0                           |
| Steering wheel and column                       | <1.0                           |
| Steering gear rack and pinion                   | <1.0                           |
| Suspension - I beam, solid front                | <1.0                           |
| Wheels                                          | <1.0                           |
| Tires                                           | <1.0                           |
| Brakes-air systems                              | <1.0                           |
| Parking emergency brake-mechanical              | <1.0                           |
| Fuel injection system                           | <1.0                           |
| Exhaust/crankcase emission control devices      | <1.0                           |
| Power train clutch assembly                     | <1.0                           |
| Power train transmission                        | <1.0                           |

| <u>Major Assembly<br/>Classification</u>    | <u>% of Total<br/>Received</u> |
|---------------------------------------------|--------------------------------|
| Switch, solenoid, shift, vacuum             | < 1.0                          |
| Electrical system-battery, ignition, wiring | < 1.0                          |
| Communications - horn assembly              | < 1.0                          |
| Seat track anchors and seats                | < 1.0                          |
| Interior, instruments and instrument panel  | < 1.0                          |
| Structure-frame, members, and body          | < 1.0                          |
| Door assembly                               | < 1.0                          |
| Hood assembly                               | < 1.0                          |
| Equipment-jacks                             | < 1.0                          |

### 3.1 Failed Part Summary

| <u>Major Assembly<br/>Classification</u> | <u>Component<br/>Classification</u> | <u>Description</u>                                | <u>Quantity<br/>Received</u> |
|------------------------------------------|-------------------------------------|---------------------------------------------------|------------------------------|
| 01100                                    |                                     | Steering Wheel & Column                           |                              |
|                                          | 01110                               | Wheel-handlebar                                   | 1                            |
|                                          | 01140                               | Locking-Anti-theft device                         | 2                            |
|                                          | 01160                               | Column coupling                                   | <u>4</u>                     |
|                                          |                                     | TOTAL                                             | 7                            |
| 01200                                    |                                     | Steering Gear Box                                 |                              |
|                                          | 01210                               | Manual steering gear box                          | 2                            |
|                                          | 01220                               | Power steering gear box                           | 10                           |
|                                          | 01230                               | Unknown type steering gear box-<br>includes 01200 | <u>4</u>                     |
|                                          |                                     | TOTAL                                             | 16                           |
| 01300                                    |                                     | Steering Power Assist                             |                              |
|                                          | 01310                               | Pump                                              | 5                            |
|                                          | 01330                               | Hose-fluid                                        | <u>11</u>                    |
|                                          |                                     | TOTAL                                             | 16                           |
| 01400                                    |                                     | Steering Gear-Rack & Pinion                       |                              |
|                                          | 01430                               | Steering gear-rack                                | 1                            |
| 01500                                    |                                     | Steering Linkages                                 |                              |
|                                          | 01510                               | Arm pitman                                        | 3                            |
|                                          | 01520                               | Link, drag-connection                             | 4                            |
|                                          | 01530                               | Arm, idler & attachment                           | 34                           |
|                                          | 01540                               | Rod, relay-connecting                             | 1                            |

| <u>Major Assembly<br/>Classification</u> | <u>Component<br/>Classification</u> | <u>Description</u>             | <u>Quantity<br/>Received</u> |
|------------------------------------------|-------------------------------------|--------------------------------|------------------------------|
|                                          | 01550                               | Tie-rod, inner                 | 4                            |
|                                          | 01560                               | Tie-rod, end                   | 39                           |
|                                          | 01570                               | Sleeve, tie-rod-adjustable     | 4                            |
|                                          | 01580                               | Knuckle-spindle-arm            | <u>3</u>                     |
|                                          |                                     | TOTAL                          | 92                           |
| 02100                                    |                                     | Suspension-Independent- Front  |                              |
|                                          | 02110                               | Attaching mechanisms           | 3                            |
|                                          | 02120                               | Shock absorber                 | 6                            |
|                                          | 02130                               | Control arm-unknown type       | 19                           |
|                                          | 02140                               | Control arm-upper              | 21                           |
|                                          | 02150                               | Control arm-lower              | 35                           |
|                                          | 02160                               | Spindle-knuckle; steering      | 2                            |
|                                          | 02170                               | Bearing-wheel                  | <u>6</u>                     |
|                                          |                                     | TOTAL                          | 92                           |
| 02200                                    |                                     | Suspension-I Beam, Solid Front |                              |
|                                          | 02220                               | Leaf spring assembly           | 1                            |
|                                          | 02240                               | Shock absorber                 | 1                            |
|                                          | 02250                               | Spindle-knuckle                | 1                            |
|                                          | 02260                               | Bearing-wheel                  | <u>2</u>                     |
|                                          |                                     | TOTAL                          | 5                            |
| 02400                                    |                                     | Suspension Single Axle, Rear   |                              |
|                                          | 02420                               | Control arm                    | 4                            |
|                                          | 02450                               | Spring, coil and attachments   | 8                            |
|                                          | 02460                               | Shock absorber                 | <u>5</u>                     |
|                                          |                                     | TOTAL                          | 17                           |
| 02600                                    |                                     | Wheels                         |                              |
|                                          | 02620                               | Wheels-single                  | 6                            |
|                                          | 02630                               | Wheels-multiple                | <u>1</u>                     |
|                                          |                                     | TOTAL                          | 7                            |
| 02700                                    |                                     | Tires                          | 1                            |
| 03200                                    |                                     | Brakes-Hydraulic System        |                              |
|                                          | 03210                               | Pedals & Linkages              | 5                            |
|                                          | 03220                               | Power assist-vacuum system     | 17                           |
|                                          | 03230                               | Master cylinder                | 104                          |
|                                          | 03240                               | Lines-fittings                 | 58                           |

| <u>Major Assembly<br/>Classification</u> | <u>Component<br/>Classification</u> | <u>Description</u>                 | <u>Quantity<br/>Received</u> |
|------------------------------------------|-------------------------------------|------------------------------------|------------------------------|
|                                          | 03260                               | Shoe & drum system                 | 26                           |
|                                          | 03270                               | Shoe disc brake system             | <u>19</u>                    |
|                                          |                                     | TOTAL                              | 229                          |
| 03300                                    |                                     | Brakes-Air Systems                 |                              |
|                                          | 03320                               | Lines and fittings                 | 1                            |
| 04100                                    |                                     | Parking-Emergency Brake-Mechanical |                              |
|                                          | 04110                               | Lever setting mechanism            | 1                            |
|                                          | 04140                               | Release mechanism-automatic        | 1                            |
|                                          | 04150                               | Linkages and cables                | <u>1</u>                     |
|                                          |                                     | TOTAL                              | 3                            |
| 05100                                    |                                     | Engine                             |                              |
|                                          | 05110                               | Engine mounts                      | 84                           |
|                                          | 05130                               | Engine pulley, crankshaft          | 1                            |
|                                          | 05140                               | Engine flywheel                    | 2                            |
|                                          | 05150                               | Engine, other parts                | <u>45</u>                    |
|                                          |                                     | TOTAL                              | 132                          |
| 05200                                    |                                     | Engine Cooling System              |                              |
|                                          | 05210                               | Radiator                           | 2                            |
|                                          | 05220                               | Hoses                              | 2                            |
|                                          | 05230                               | Pump, water                        | 4                            |
|                                          | 05240                               | Fan                                | 11                           |
|                                          | 05250                               | Belts                              | 1                            |
|                                          | 05260                               | Thermostat                         | <u>3</u>                     |
|                                          |                                     | TOTAL                              | 23                           |
| 06100                                    |                                     | Fuel Systems                       |                              |
|                                          | 06110                               | Fuel tank assembly                 | 9                            |
|                                          | 06120                               | Fuel emission control              | 1                            |
|                                          | 06130                               | Fuel lines, fittings & pump        | <u>14</u>                    |
|                                          |                                     | TOTAL                              | 24                           |
| 06200                                    |                                     | Fuel Carburetion                   |                              |
|                                          | 06210                               | Carburetor-Unknown type            | 25                           |
|                                          | 06220                               | Carburetor-single                  | 3                            |
|                                          | 06230                               | Carburetor-double                  | 5                            |
|                                          | 06240                               | Carburetor-four barrel             | <u>5</u>                     |
|                                          |                                     | TOTAL                              | 38                           |

| <u>Major Assembly<br/>Classification</u> | <u>Component<br/>Classification</u> | <u>Description</u>              | <u>Quantity<br/>Received</u> |
|------------------------------------------|-------------------------------------|---------------------------------|------------------------------|
| 06300                                    |                                     | Fuel Injection System           |                              |
|                                          | 06320                               | Fuel injection-electrical       | 4                            |
| 06400                                    |                                     | Throttle Linkages & Control     |                              |
|                                          | 06430                               | Accelerator, flexible           | 13                           |
| 06500                                    |                                     | Exhaust/Crankcase Emission      |                              |
|                                          |                                     | Control Devices                 | 4                            |
|                                          | 06530                               | Check valve                     | <u>1</u>                     |
|                                          |                                     | TOTAL                           | 5                            |
| 06600                                    |                                     | Exhaust System                  |                              |
|                                          | 06610                               | Manifold-engine                 | 21                           |
|                                          | 06620                               | Pipe-exhaust                    | 15                           |
|                                          | 06630                               | Muffler-resonator               | 4                            |
|                                          | 06640                               | Tail pipe                       | <u>1</u>                     |
|                                          |                                     | TOTAL                           | 41                           |
| 07100                                    |                                     | Power Train Clutch Assembly     |                              |
|                                          | 07110                               | Pedal                           | 2                            |
|                                          | 07120                               | Linkage, flexible               | 2                            |
|                                          | 07130                               | Linkage, rigid                  | 1                            |
|                                          | 07170                               | Plate, drive, clutch            | <u>2</u>                     |
|                                          |                                     | TOTAL                           | 7                            |
| 07200                                    |                                     | Power Train Transmission        | 1                            |
|                                          | 07240                               | Transmission, Unknown type      | 1                            |
| 07300                                    |                                     | Power Train, Transmission       |                              |
|                                          |                                     | Automatic                       | 8                            |
|                                          | 07350                               | Switch, solenoid, shift, vacuum | 1                            |
| 07400                                    |                                     | Power Train Drive Line          |                              |
|                                          | 07410                               | Universal joint                 | 2                            |
|                                          | 07430                               | Bracket, support, center shaft  | 1                            |
|                                          | 07450                               | Differential unit               | 4                            |
|                                          | 07460                               | Axle assembly                   | 7                            |
|                                          | 07470                               | Other part                      | <u>4</u>                     |
|                                          |                                     | TOTAL                           | 18                           |
| 08100                                    |                                     | Electrical System               |                              |
|                                          | 08120                               | Battery                         | 1                            |

| <u>Major Assembly<br/>Classification</u> | <u>Component<br/>Classification</u> | <u>Description</u>                             | <u>Quantity<br/>Received</u> |
|------------------------------------------|-------------------------------------|------------------------------------------------|------------------------------|
| 08200                                    |                                     | Alternator, Regulator, Starter                 |                              |
|                                          | 08210                               | Alternator-generator                           | 3                            |
|                                          | 08220                               | Regulator                                      | 3                            |
|                                          | 08230                               | Starter                                        | 5                            |
|                                          | 08240                               | Other part                                     | <u>5</u>                     |
|                                          |                                     | TOTAL                                          | 16                           |
| 08300                                    |                                     | Electrical System Wiring                       |                              |
|                                          | 08320                               | Harness, rear-under dash                       | 1                            |
|                                          | 08340                               | Other part                                     | <u>2</u>                     |
|                                          |                                     | TOTAL                                          | 3                            |
| 08500                                    |                                     | Electrical System-Ignition                     | 1                            |
|                                          | 08510                               | Ignition Switch                                | 5                            |
|                                          | 08520                               | Switch, neutral start                          | 2                            |
|                                          | 08530                               | Wiring, primary and secondary                  | 5                            |
|                                          | 08540                               | Electronic control unit                        | 1                            |
|                                          | 08550                               | Other part                                     | <u>8</u>                     |
|                                          |                                     | TOTAL                                          | 21                           |
| 09100                                    |                                     | Switch-Button-Ring                             |                              |
|                                          |                                     | Unspecified light                              | 56                           |
| 09500                                    |                                     | Communications-Hood Assembly                   |                              |
|                                          | 09510                               | Horn assembly, button, ring                    | 1                            |
| 10100                                    |                                     | Visual Systems-Glass                           | 1                            |
| 10300                                    |                                     | Visual Systems-Windshield                      |                              |
|                                          |                                     | Wiper & Washer                                 |                              |
|                                          | 10310                               | Windshield Wiper                               | 9                            |
|                                          | 10320                               | Windshield Washer                              | <u>1</u>                     |
|                                          |                                     | TOTAL                                          | 10                           |
| 11000                                    |                                     | Heater, Defroster, Defogger<br>and Ventilation |                              |
|                                          | 11100                               | Water-heater, defroster, defogger              | 7                            |
|                                          | 11600                               | Air conditioner                                | <u>4</u>                     |
|                                          |                                     | TOTAL                                          | 11                           |
| 12300                                    |                                     | Seat Track Anchors & Seats                     |                              |
|                                          | 12310                               | Seat tracks and anchors                        | 1                            |

| <u>Major Assembly Classification</u> | <u>Component Classification</u> | <u>Description</u>                      | <u>Quantity Received</u> |
|--------------------------------------|---------------------------------|-----------------------------------------|--------------------------|
| 12400                                |                                 | Interior Instruments & Instrument Panel |                          |
|                                      | 12410                           | Instrument panel material & padding     | 1                        |
| 13100                                |                                 | Structure-Frame, Members & Body         |                          |
|                                      | 13110                           | Structure-frame, members                | 6                        |
| 13400                                |                                 | Door Assembly                           |                          |
|                                      | 13420                           | Hinge and attachments                   | 1                        |
| 13700                                |                                 | Hood Assembly                           |                          |
|                                      | 13720                           | Hinge and attachments                   | 3                        |
|                                      | 13730                           | Latches                                 | <u>2</u>                 |
|                                      |                                 | TOTAL                                   | 5                        |
| 15000                                |                                 | Equipment                               |                          |
|                                      | 15500                           | Jacks                                   | <u>2</u>                 |
|                                      |                                 | GRAND TOTAL PARTS RECEIVED              | <u>942</u>               |

### 3.2 Parts Received in Support of Investigations

As of 30 April 1976, 142 parts were determined to be of special interest to the NHTSA and were considered to support on-going investigations. The table below provides a summary of these failed parts.

| <u>Investigation (Case) No.</u> | <u>Component Description</u>   | <u>Vehicle Year/Make or Model</u> | <u>Quantity Received</u> |
|---------------------------------|--------------------------------|-----------------------------------|--------------------------|
| 161                             | Power Brake Vacuum Check Valve | 65 Jeep                           | 1                        |
|                                 |                                | 67 Pontiac                        | 1                        |
|                                 |                                | 68 Chevrolet                      | 1                        |
|                                 |                                | 69 Ford                           | 1                        |
|                                 |                                | 69 Oldsmobile                     | 2                        |
|                                 |                                | 70 Pontiac                        | 1                        |
|                                 |                                | 72 Chevelle                       | 1                        |
|                                 |                                | GM Unknown                        | <u>1</u>                 |
|                                 |                                | TOTAL                             | 9                        |

| <u>Investigation<br/>(Case) No.</u> | <u>Component<br/>Description</u> | <u>Vehicle Year/<br/>Make or Model</u> | <u>Quantity<br/>Received</u> |
|-------------------------------------|----------------------------------|----------------------------------------|------------------------------|
| 212                                 | Lower Control Arm                | 68 Ford                                | 2                            |
|                                     |                                  | 69 Ford                                | <u>2</u>                     |
|                                     |                                  | TOTAL                                  | 4                            |
| 258.5                               | Engine Mounts                    | 65 Buick                               | 2                            |
|                                     |                                  | 68 Buick                               | 1                            |
|                                     |                                  | 69 Pontiac                             | 1                            |
|                                     |                                  | 70 Buick                               | <u>1</u>                     |
|                                     |                                  | TOTAL                                  | 5                            |
| 266                                 | Ignition Switch                  | 69 Ford                                | 1                            |
| 282                                 | Wheel                            | 70 Ford                                | 1                            |
| C2-53                               | Brake Master Cylinder            | 68 Mercury                             | 1                            |
|                                     |                                  | 69 Fairlane                            | 2                            |
|                                     |                                  | 70 Maverick                            | 3                            |
|                                     |                                  | 70 Falcon                              | 1                            |
|                                     |                                  | 70 Mustang                             | 1                            |
|                                     |                                  | 71 Ford Truck                          | <u>1</u>                     |
|                                     |                                  | TOTAL                                  | 9                            |
| C4-18                               | Engine Mounts                    | 69 Fairlane                            | 2                            |
|                                     |                                  | 69 Mercury                             | <u>1</u>                     |
|                                     |                                  | TOTAL                                  | 3                            |
| C4-26                               | Power Steering Gear              | 72 Chevrolet                           | 1                            |
|                                     |                                  | 73 Ford                                | 1                            |
|                                     |                                  | 74 Ford Truck                          | <u>1</u>                     |
|                                     |                                  | TOTAL                                  | 3                            |
| C4-44                               | Carburetor Float                 | 68 Buick                               | 1                            |
|                                     |                                  | 68 Chevrolet                           | 3                            |
|                                     |                                  | 68 Cadillac                            | 1                            |
|                                     |                                  | 69 Chevrolet                           | 2                            |
|                                     |                                  | 69 Chevelle                            | 1                            |
|                                     |                                  | 69 Pontiac                             | 1                            |
|                                     |                                  | 71 Chevrolet                           | <u>1</u>                     |
|                                     |                                  | TOTAL                                  | 10                           |
| C4-53                               | Engine Mounts                    | 67 Chevrolet                           | 2                            |

| <u>Investigation<br/>(Case) No.</u> | <u>Component<br/>Description</u> | <u>Vehicle Year/<br/>Make or Model</u> | <u>Quantity<br/>Received</u> |
|-------------------------------------|----------------------------------|----------------------------------------|------------------------------|
| C4-58                               | Fuel Injectors                   | 72 Volvo                               | 4                            |
| C5-07                               | Timing Gear                      | 70 Pontiac                             | 1                            |
| EA4-229                             | Flexible Fan                     | 72 Ford                                | 1                            |
| EA6-013                             | Power Steering Hose              | 75 Ford Truck                          | 1                            |
| OCA*                                | Master Cylinder                  | 69 AMX                                 | 1                            |
|                                     |                                  | 69 Fury                                | 2                            |
|                                     |                                  | 69 Dodge Truck                         | 1                            |
|                                     |                                  | 69 Oldsmobile                          | 1                            |
|                                     |                                  | 69 Dart                                | 1                            |
|                                     |                                  | 69 Ford                                | 1                            |
|                                     |                                  | 70 Dart                                | 2                            |
|                                     |                                  | 70 Mercury                             | 1                            |
|                                     |                                  | 70 LTD                                 | 1                            |
|                                     |                                  | 70 Hornet                              | 1                            |
|                                     |                                  | 70 Chevrolet                           | 1                            |
|                                     |                                  | 70 Plymouth                            | 1                            |
|                                     |                                  | 70 Mustang                             | 1                            |
|                                     |                                  | 71 Plymouth                            | 1                            |
|                                     |                                  | 71 AMC                                 | 1                            |
|                                     |                                  | 71 Maverick                            | 1                            |
|                                     |                                  | 71 Ford                                | 2                            |
|                                     |                                  | 71 Oldsmobile                          | 1                            |
|                                     |                                  | 71 Chrysler                            | 1                            |
|                                     |                                  | 71 Pontiac                             | 1                            |
|                                     |                                  | 71 Mercury                             | 1                            |
|                                     |                                  | 72 Mark IV                             | 1                            |
|                                     |                                  | 72 Ford                                | 2                            |
|                                     |                                  | 72 Maverick                            | 1                            |
|                                     |                                  | 72 Capri                               | 1                            |
|                                     |                                  | 72 MGB                                 | 1                            |
|                                     |                                  | 72 Maverick                            | 1                            |
|                                     |                                  | 72 Fury                                | 1                            |
|                                     |                                  | 72 Oldsmobile                          | 1                            |
|                                     |                                  | 72 Plymouth                            | 1                            |
|                                     |                                  | 72 Mercury                             | 1                            |
|                                     |                                  | 72 Blazer                              | 1                            |
|                                     |                                  | 73 Chevrolet                           | 1                            |
|                                     |                                  | 73 Ford Truck                          | 1                            |
|                                     |                                  | 73 Marquis                             | 1                            |

\*OCA - Office of Crash Avoidance

| <u>Investigation<br/>(Case) No.</u> | <u>Component<br/>Description</u> | <u>Vehicle Year/<br/>Make or Model</u> | <u>Quantity<br/>Received</u> |
|-------------------------------------|----------------------------------|----------------------------------------|------------------------------|
| OCA                                 | Master Cylinder (cont)           | 73 Oldsmobile                          | 1                            |
|                                     |                                  | 73 Pontiac                             | 2                            |
|                                     |                                  | 73 Vega                                | 1                            |
|                                     |                                  | 73 Plymouth                            | 1                            |
|                                     |                                  | 74 Hornet                              | 1                            |
|                                     |                                  | 74 Chevrolet                           | 1                            |
|                                     |                                  | 75 Pinto                               | <u>1</u>                     |
|                                     |                                  | TOTAL                                  | 48                           |
| OCA                                 | Flexible Brake Hose              | 62 Buick                               | 1                            |
|                                     |                                  | 65 Buick                               | 2                            |
|                                     |                                  | 65 Ford                                | 2                            |
|                                     |                                  | 65 Plymouth                            | 1                            |
|                                     |                                  | 66 Chevrolet                           | 1                            |
|                                     |                                  | 68 Ford                                | 1                            |
|                                     |                                  | 69 Dart                                | 1                            |
|                                     |                                  | 69 Oldsmobile                          | 1                            |
|                                     |                                  | 70 Chevrolet                           | 2                            |
|                                     |                                  | 71 MG                                  | 2                            |
|                                     |                                  | 71 Toyota                              | 2                            |
|                                     |                                  | 72 Chevrolet                           | 1                            |
|                                     |                                  | 73 Dart                                | 2                            |
|                                     |                                  | 73 Duster                              | 2                            |
|                                     |                                  | 73 Plymouth                            | 2                            |
|                                     |                                  | 74 Hornet                              | 2                            |
|                                     |                                  | 74 AMC                                 | 2                            |
|                                     |                                  | 74 Dodge Truck                         | <u>2</u>                     |
|                                     |                                  | TOTAL                                  | 29                           |
| OCA                                 | Brake Proportioning<br>Valve     | 72 Oldsmobile                          | 1                            |
|                                     |                                  | 73 Chevrolet Van                       | 1                            |
|                                     |                                  | 73 Oldsmobile                          | 1                            |
|                                     |                                  | 74 Pontiac                             | 1                            |
|                                     |                                  | 74 Buick                               | 1                            |
|                                     |                                  | 75 Cadillac                            | <u>1</u>                     |
|                                     |                                  | TOTAL                                  | 6                            |
|                                     |                                  | GRAND TOTAL                            | <u><u>142</u></u>            |

### 3.3 Detailed Records Stored in the ODI/DATA Information System (DIS)

The Vehicle Owner Letter File of the ODI/DIS currently contains 1743 detailed records. These records depict the identification of the failed part, a description of the

failure, an identification of the make/model and body style of the motor vehicle involved and the model year. Also, included with this record is an identification of the shop that sent in the failed part, the unique PRP number, the date the part was received by the PRP, the mileage recorded at failure, and a location number where the part can be found in our storage facility.

The following pages include a cumulative report of all the parts received by the PRP from 1 July 1975 through 30 June 1976. The records in this report are grouped by component classification, i. e., steering, suspension, wheels, etc.

## PARTS RETURN PROGRAM

76/07/06 PAGE 0001

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                           | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                        | MAKE-MODEL                            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHGP<br>NUMBER |
|-------------------------------------------------------------------------|---------------|-----------------------|--------------------|----------------------------------------------------------|---------------------------------------|-------------------------|-----------------------|----------------|
| 30014                                                                   | P01184 B      | 760118                | 01110              | STEERING WHEEL-HANDLEBAR<br>73 043 CHEVROLET DIVISION    | D3 CAPRICE                            | 59 C                    | 045337                | 30313006       |
| TWO OF EIGHT SPOT WELDS ARE BROKEN                                      |               |                       |                    |                                                          |                                       |                         |                       |                |
| 30025                                                                   | P01251 B      | 760306                | 01140              | STEERING COLUMN LOCKING, ANTI-THEFT<br>69 155 VOLKSWAGEN | B3 SQUAREBACK SEDAN                   | 03 C                    | 000000                | 94101002       |
| RETAINING BRACKET FOR LOCKING PIN BROKE ON SLIDE ASSY                   |               |                       |                    |                                                          |                                       |                         |                       |                |
| 50011                                                                   | P01521 B      | 760501                | 01140              | STEERING COLUMN LOCKING, ANTI-THEFT<br>72 155 VOLKSWAGEN | 01 TYPE I                             | 03 C                    | 000000                | 94101002       |
| 2 EARS ON CAST PLATE BROKE-LOCK PIN LOCKED STEERING WHILE PARKING       |               |                       |                    |                                                          |                                       |                         |                       |                |
| 50005                                                                   | P01460 B      | 760412                | 01160              | STEERING COLUMN COUPLING<br>74 031 FORD DIVISION         | 66 PINTO WAGON                        | 54 C                    | 021276                | 29405006       |
| INNER SPLINES ON STRNG COUPLING WORN-THREADS ON BOLT STRIPPED           |               |                       |                    |                                                          |                                       |                         |                       |                |
| 50013                                                                   | P01543 B      | 760507                | 01160              | STEERING COLUMN COUPLING<br>72 031 FORD DIVISION         | 07 THUNDERBIRD                        | 33 C                    | 070874                | 68102003       |
| U-JOINT ON LOWER STEERING COLUMN SHAFT IS FROZEN                        |               |                       |                    |                                                          |                                       |                         |                       |                |
| 50005                                                                   | P01476 B      | 760409                | 01160              | STEERING COLUMN COUPLING<br>73 053 MERCURY               | 01 CAPRI                              | 56 C                    | 014000                | 63121005       |
| EXCESS MOVEMENT IN UNIV. JNT-SOFT RUBBER CAUSING PLAY IN STRNG&POOR TRK |               |                       |                    |                                                          |                                       |                         |                       |                |
| 30015                                                                   | P01233 B      | 760203                | 01160              | STEERING COLUMN COUPLING<br>70 181 AB VOLVO              | D1 VOLVO 164<br>164                   | 08 C                    | 084191                | 93702024       |
| RUBBER PORTION OF COUPLER SEPARATED FROM METAL AND SHOWS DETERIORATION  |               |                       |                    |                                                          |                                       |                         |                       |                |
| 30006                                                                   | P01087 B      | 751224                | 01200              | STEERING GEAR BOX<br>73 022 DODGE                        | 9A DODGE TRUCK AND VA<br>TRADESMAN100 | 53 C                    | 033000                | 92104022       |
| BINDING AND PLAY IN STEERING-2 FITTINGS OF BALL BEARINGS WEAK, BREAKING |               |                       |                    |                                                          |                                       |                         |                       |                |
| 50020                                                                   | P01579 B      | 760521                | 01210              | MANUAL STEERING GEAR BOX<br>72 022 DODGE                 | 9A DODGE TRUCK AND VA<br>200          | 57 C                    | 044000                | 44110013       |
| BEARING NOISE EVIDENT WHEN SHAFT IS ROTATED, PITMAN SHAFT SEAL GD COND  |               |                       |                    |                                                          |                                       |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0004

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, YR

| FIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>YR                                                                                                               | MANUFACTURER | MAKE-MODEL                   | FAULT HAZ-<br>COOL CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|-------------------------------------------------------------------------------------------------------------------------------|--------------|------------------------------|-------------------------|-----------------------|----------------|
| 40009         | P01438 B      | 760401                | 01212              | MANUAL STEERING SHAFT-SECTOR<br>74 031 FORD DIVISION                                                                          |              | A0 ECONCLINE SERIES<br>E-100 | 57 C                    | 034430                | 66001014       |
| 20016         | PC0977 B      | 751103                | 01220              | 1BALL BRNG EXCESS WEAR-1BALL BRNG RACE DAMAGED-1WORM GEAR DAMAGED<br>POWER STEERING GEAR BOX<br>71 031 FORD DIVISION          |              | 03 FORD                      | 57 C                    | 000000                | 01749012       |
| 30028         | P01281 B      | 760207                | 01220              | WEAR ON SHAFT OF SECTOR SHAFT-BALL BEARINGS IN GEAR BOX WORN<br>POWER STEERING GEAR BOX<br>73 031 FORD DIVISION               |              | 08 TORINO                    | 14 C                    | 017167                | 64111015       |
| 30007         | P01196 B      | 751224                | 01220              | NO VISIBLE DEFECTS - SUSPECT INTERNAL VALVE ASSEMBLY MALFUNCTION<br>POWER STEERING GLAR BOX<br>72 041 BUICK                   |              | 00 BUICK                     | 03 C                    | 059292                | 97301027       |
| 50010         | P01458 B      | 760402                | 01220              | HOUSING CRACKED AT THIN PART OF CASTING<br>POWER STEERING GEAR BOX<br>72 042 CADILLAC DIVISION                                |              | B1 CADILLAC-DE VILLE         | 08 C                    | 062000                | 48150012       |
| 30029         | P01304 B      | 760306                | 01220              | GEAR BOX CASING CRACKED AROUND CIRCUMFERENCE OF BASE AT SNAP RING GRV<br>POWER STEERING GEAR BOX<br>72 043 CHEVROLET DIVISION |              | C4 NOVA                      | 28 A                    | 033544                | 94101002       |
| 50004         | PC1470 B      | 760405                | 01220              | SUSPECT SEAL FAILURE IN PWR ASST - PUMP FAILED ON RTHAND TURN<br>POWER STEERING GEAR BOX<br>68 043 CHEVROLET DIVISION         |              | D3 CAPRICE                   | 32 C                    | 068296                | 14607007       |
| 30014         | P01203 B      | 760123                | 01220              | GEAR BOX HOUSING COVER LEAKS-PARTIAL DETERIORATION IS CAUSE<br>POWER STEERING GEAR BOX<br>74 043 CHEVROLET DIVISION           |              | E3 IMPALA                    | 08 C                    | 053000                | 23701047       |
| 50013         | PC1542 B      | 760507                | 01220              | CASING IS CRACKED AT BOTTOM END OF MAIN SHAFT PASSAGE CAUSING LEAKAGE<br>POWER STEERING GEAR BOX<br>60 043 CHEVROLET DIVISION |              | 03 CHEVROLET                 | 57 C                    | 000000                | 68102003       |

SHOP CLAIMES BEARING RACES EXCESS WORN

## PARTS RETURN PROGRAM

7/6/77/00 PAGE 0003

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, YR

| BIN NUMBER | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                                                                                                    | YR | MANUFACTURER | MAKE-MODEL                        | FAULT HAZ. CODE | HAZ. CAT. | MILEAGE AT FAILURE | SHCP NUMBER |
|------------|------------|-----------------|-----------------|-----------------------------------------------------------------------------------------------------------------------------------|----|--------------|-----------------------------------|-----------------|-----------|--------------------|-------------|
| 30019      | P01239     | B 760203        | 01220           | POWER STEERING GEAR BOX<br>74 044 OLDSMOBILE                                                                                      |    |              | 06 98                             | 03              | C         | 090000             | 76012007    |
| 30021      | P01209     | B 760306        | 01222           | POWER STEERING SHAFT-SECTOR<br>73 042 CADILLAC DIVISION                                                                           |    |              | 02 FLEETWOOD                      | 03              | B         | 019939             | 63105001    |
| 30010      | P01123     | B 751226        | 01230           | SHAFT BROKE AT END OF SPLINES ACROSS DIAMETER-DISCOLOR INDI HEAT BUILD<br>UNKNOWN TYPE STEERING, GEAR BOX<br>67 031 FORD DIVISION |    |              | AO ECONOMOLINE SERIES<br>E100 VAN | 03              | C         | 118732             | 40506004    |
| 30008      | P01117     | B 751226        | 01230           | SHAFT BROKEN APPROX IN HALF-BALL BEARINGS & RIPPED OUT & CUT IN HALF<br>UNKNOWN TYPE STEERING, GEAR BOX<br>72 031 FORD DIVISION   |    |              | G3 FORD-LTD                       | 32              | C         | 035710             | 90405010    |
| 20002      | P00464     | B 750710        | 01232           | EXCESSIVE LEAK FROM SECTOR SEAL HOUSING SHOWS SOME WEAR<br>UNKNOWN TYPE STEERING, SHAFT-SECTOR<br>56 031 FORD DIVISION            |    |              | 9A FORD TRUCK AND VAN             | 30              | A         | 000000             | 091605014   |
| 20010      | P00890     | B 751008        | 01310           | BEARINGS IN STEERING BOX BECAME MISALIGNED CAUSING DAMAGE TO SHAFT<br>STEERING POWER ASSIST-PUMP<br>72 031 FORD DIVISION          |    |              | G3 FORD-LTD                       | 32              | C         | 723500             | 54911007    |
|            | P01146     | B 751229        | 01310           | PUMP LEAKED OIL WHILE UNDER PRESSURE CAUSING LEAKS & HARD STEERING<br>STEERING POWER ASSIST-PUMP<br>75 031 FORD DIVISION          |    |              | 04 MAVERICK                       | 28              | C         | 012700             | 63105001    |
| 20003      | P00632     | B 750627        | 01310           | POWER STEERING PUMP NOT CREATING PRESSURE-PART NOT AVAILABLE<br>STEERING POWER ASSIST-PUMP<br>74 031 FORD DIVISION                |    |              | 05 MUSTANG                        | 28              | C         | 000000             | 012205003   |
| 30012      | P01180     | B 760107        | 01310           | POWER STEERING PUMP NOISY & INOPERATIVE<br>STEERING POWER ASSIST-PUMP<br>74 042 CADILLAC DIVISION                                 |    |              | A2 FLEETWOOD-ELDORADO             | 03              | C         | 029143             | 19805002    |
|            |            |                 |                 | STEERING PUMP SHAFT BROKE AT BASE OF GEAR RIBS                                                                                    |    |              |                                   |                 |           |                    |             |

# PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JULY 76

76/07/06 PAGE 0004

SORTED BY COMPONENT, MODEL, MDL YR

| SIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                  | MAKE-MODEL                          | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHIP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|-----------------------------------------------------------------------|-------------------------------------|-------------------------|-----------------------|----------------|
| 30015         | P01231 B      | 760203                | 01310              | STEERING POWER ASSIST-PUMP<br>68 043 CHEVROLET DIVISION               | EO PICK-UP MODELS<br>C-10           | 03 C                    | 062500                | 50702000       |
|               |               |                       |                    | MOUNTING BOLT EAR BROKEN AT BOLT HOLE                                 |                                     |                         |                       |                |
| 40002         | P01333 B      | 760320                | 01330              | STEERING POWER ASSIST-HOSE, FLUID<br>65 021 CHRYSLER DIVISION         | 01 CHRYSLER<br>4 D                  | 32 C                    | 079444                | 30501001       |
|               |               |                       |                    | PRESSURE HOSE LEAKS FLUID AT FITTING-RUBBER METAL CONNECTION          |                                     |                         |                       |                |
| 40026         | P01300 B      | 760300                | 01330              | STEERING POWER ASSIST-HOSE, FLUID<br>67 025 PLYMOUTH                  | 01 BARRACUDA                        | 08 C                    | 001976                | 06120003       |
|               |               |                       |                    | ONE INCH SPLIT LENGTHWISE AT PUMP END OF HOSE AT CONN W/METAL PORTION |                                     |                         |                       |                |
| 30010         | P01145 B      | 751229                | 01330              | STEERING POWER ASSIST-HOSE, FLUID<br>70 023 PLYMOUTH                  | 04 FURY                             | 08 C                    | 041000                | 30501004       |
|               |               |                       |                    | RUBBER PRESSURE HOSE RUPTURED OR CRACKED NEAR METAL FITTING           |                                     |                         |                       |                |
| 20013         | P00907 B      | 751020                | 01330              | STEERING POWER ASSIST-HOSE, FLUID<br>74 031 FORD DIVISION             | 9A FORD TRUCK AND VAN<br>314 T, 250 | 32 C                    | 016540                | 63121005       |
|               |               |                       |                    | SMALL PINHOLE IN CASING. LEAK SHOWED UP WHILE OPERATING               |                                     |                         |                       |                |
| 20015         | P00962 B      | 751030                | 01330              | STEERING POWER ASSIST-HOSE, FLUID<br>75 031 FORD DIVISION             | 9C F-250                            | 41 C                    | 011306                | 51103000       |
|               |               |                       |                    | 2IN PORTION OF HOSE DETERIORATED, LEAKED. LEAKS AT FITTING            |                                     |                         |                       |                |
| 40006         | P01385 B      | 760330                | 01330              | STEERING POWER ASSIST-HOSE, FLUID<br>76 033 MERCURY                   | 04 MERCURY                          | 21 C                    | 024000                | 19602003       |
|               |               |                       |                    | BRASS FITTING SEPARATED FROM POWER STEERING HOSE                      |                                     |                         |                       |                |
| 50005         | P01479 B      | 760412                | 01330              | STEERING POWER ASSIST-HOSE, FLUID<br>74 041 BUICK                     | 04 LE SABRE<br>Y                    | 32 C                    | 018345                | 60076001       |
|               |               |                       |                    | HOSE LEAKING AT BOTH ENDS WHERE IT JOINS METAL FITTINGS               |                                     |                         |                       |                |
| 20013         | P00911 B      | 751020                | 01330              | STEERING POWER ASSIST-HOSE, FLUID<br>68 042 CADILLAC DIVISION         | 61 CADILLAC-DE VILLE                | 32 C                    | 023982                | 54911007       |
|               |               |                       |                    | POWER STEERING HOSE BECAME BRITTLE & CRACKED, LEAKED UNDER PRESSURE   |                                     |                         |                       |                |

7/9/76

PAGE 0003

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, POL YR

| DI. NUMBER | PAP NUMBER | I D RECEIVED | DATE | COMPONENT CLASS | COMPONENT NAME                                                         | YR | MAKE-MODEL            | FAULT HAZ. CODE | HAZ. CAT. | MILEAGE AT FAILURE | SHOP NUMBER |
|------------|------------|--------------|------|-----------------|------------------------------------------------------------------------|----|-----------------------|-----------------|-----------|--------------------|-------------|
| 50003      | P01454 B   | 760402       |      | 01330           | STEERING POWER ASSIST-HOSE,FLUID<br>65 042 CADILLAC DIVISION           |    | 01 CADILLAC           | 32              | C         | 016795             | 98120073    |
|            |            |              |      |                 | PWR STEERING PRESSURE HOSE BLOWN AT SMALL FITTING END-LEAKS UNDR PRESS |    |                       |                 |           |                    |             |
| 50005      | P01461 B   | 760412       |      | 01330           | STEERING POWER ASSIST-HOSE,FLUID<br>73 043 CHEVROLET DIVISION          |    | D3 CAPRICE            | 06              | C         | 042062             | 12601026    |
|            |            |              |      |                 | HOSE IS SPLIT AT CRIMPED METAL EDGING-LEAKS FROM THIS SPOT             |    |                       |                 |           |                    |             |
| 30007      | P01112 B   | 751226       |      | 01330           | STEERING POWER ASSIST-HOSE,FLUID<br>74 043 CHEVROLET DIVISION          |    | E3 IMPALA             | 32              | C         | 009175             | 30501001    |
|            |            |              |      |                 | HOSE APPEARS TO BE LEAKING AT SWAGE JOINT-METAL TO RUBBER JOINT LEAKS  |    |                       |                 |           |                    |             |
| 50019      | P01582 B   | 760521       |      | 01430           | STEERING GEAR,RACK<br>71 163 FIAT S.P.A.                               |    | A3 FIAT 128           | 03              | C         | 000000             | 20009003    |
|            |            |              |      |                 | BUSHING IS BROKEN IN PIECES                                            |    |                       |                 |           |                    |             |
| 40001      | P01332 B   | 760320       |      | 01510           | STEERING LINKAGES-ARM,PITMAN<br>75 023 PLYMOUTH                        |    | 04 FURY<br>POLICE SPC | 57              | C         | 019168             | 01605008    |
|            |            |              |      |                 | EXCESS WEAR IN BALL STUD SOCKET GREASE BOOT SPLIT                      |    |                       |                 |           |                    |             |
| 50008      | P01506 B   | 760427       |      | 01510           | STEERING LINKAGES-ARM,PITMAN<br>73 031 FORD DIVISION                   |    | 07 THUNDERBIRD        | 03              | C         | 029854             | 98108037    |
|            |            |              |      |                 | BALL JOINT STUD BROKE OFF PITMAN ARM                                   |    |                       |                 |           |                    |             |
| 30010      | P01126 B   | 751226       |      | 01510           | STEERING LINKAGES-ARM,PITMAN<br>75 043 CHEVROLET DIVISION              |    | 09 VEGA               | 03              | C         | 073815             | 27107014    |
|            |            |              |      |                 | PITMAN SHAFT BROKE WHERE IT ENTERS GLAR BOX-POSSIBLE CASTING DEFECT    |    |                       |                 |           |                    |             |
| 20013      | P00908 B   | 751020       |      | 01520           | STEERING LINKAGES-LINK,DRAG-CONNECTION<br>74 031 FORD DIVISION         |    | 9A FORD TRUCK AND VAN | 36              | C         | 018900             | 63121005    |
|            |            |              |      |                 | EXCESSIVE WEAR OF BALL STUD END, NO GREASE LUBE, NO GREASE FITTING     |    |                       |                 |           |                    |             |
| 30002      | P01020 B   | 751119       |      | 01520           | STEERING LINKAGES-LINK,DRAG-CONNECTION<br>67 041 BUICK                 |    | 04 LE SABRE           | 57              | C         | 043260             | 63105001    |
|            |            |              |      |                 | LOOSE AT PITMAN ARM CONNECTION, EXHIBITS EXCESSIVE WEAR                |    |                       |                 |           |                    |             |

## PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06 PAGE 0005

SORTED BY COMPONENT, MODEL, M/L YR

| BIN NUMBER                                                            | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                            | MAKE-MODEL                          | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|-----------------------------------------------------------------------|-------------------|------------------|--------------------|------------------------------------------------------------------------------|-------------------------------------|-------------------------|-----------------------|----------------|
| 50002                                                                 | P01442 B          | 760401           | 01520              | STEERING LINKAGES-LINK, DRAG-CONNECTION<br>76 043 CHEVROLET DIVISION         | E3 IMPALA                           | 57 C                    | 005220                | 20313006       |
| EXCESSIVE WEAR AT JUNCTION OF TIE ROD END WITH DRAG CENTER LINK       |                   |                  |                    |                                                                              |                                     |                         |                       |                |
| 30011                                                                 | P01160 B          | 760106           | 01520              | STEERING LINKAGES-LINK, DRAG-CONNECTION<br>73 043 CHEVROLET DIVISION         | 9A CHEVROLET TRUCK AN<br>4-WHEEL DR | 57 C                    | 038199                | 81004032       |
| MOUNTING HOLE FOR DRAG LINK RUSTING AND ENLARGED DUE TO WEAR          |                   |                  |                    |                                                                              |                                     |                         |                       |                |
| 50011                                                                 | P01527 B          | 760501           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>66 110 INTERNATIONAL HARVESTER | 11 INTERNATIONAL TRUC<br>1200A      | 03 C                    | 060000                | 06516005       |
| STEER. ARM BROKE ON CURVED PORTION OF METAL 4" FROM FRAME MOUNTG HOLE |                   |                  |                    |                                                                              |                                     |                         |                       |                |
| 50001                                                                 | P01434 B          | 760331           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>00 000 UNKNOWN                 | 00 UNKNOWN                          | 53 C                    | 000000                | 60626008       |
| STIFF MOVEMENT IN BALL STUD SOCKET-TAG NOT READABLE                   |                   |                  |                    |                                                                              |                                     |                         |                       |                |
| 50001                                                                 | P01435 B          | 760331           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>00 000 UNKNOWN                 | 00 UNKNOWN                          | 57 C                    | 000000                | 60626008       |
| BALL STUD SOCK EXCES WORN-LACK OF LUBE/PIVOT POINT W/BRKT FROZEN      |                   |                  |                    |                                                                              |                                     |                         |                       |                |
| 50001                                                                 | P01433 B          | 760331           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>00 000 UNKNOWN                 | 00 UNKNOWN                          | 53 C                    | 000000                | 60626008       |
| STIFF MOVEMENT IN BALL STUD SOCKET                                    |                   |                  |                    |                                                                              |                                     |                         |                       |                |
| 20009                                                                 | P00855 B          | 750919           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>66 022 DODGE                   | 00 DODGE                            | 08 C                    | 046066                | 023222023      |
| IDLER ARM SOCKET CRACKED                                              |                   |                  |                    |                                                                              |                                     |                         |                       |                |
| 20009                                                                 | P00856 B          | 750919           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>72 023 PLYMOUTH                | 00 PLYMOUTH                         | 08 C                    | 067394                | 023222023      |
| STEERING IDLER ARM CRACKED                                            |                   |                  |                    |                                                                              |                                     |                         |                       |                |
| 20013                                                                 | P00931 B          | 751024           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>72 023 PLYMOUTH                | 00 PLYMOUTH                         | 57 C                    | 000000                | 60626008       |
| EXCESSIVE WEAR IN BALL STUD SOCKET                                    |                   |                  |                    |                                                                              |                                     |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0007

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MUL YR

| BIN NUMBER | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                                                                                                                | YR MANUFACTURER | MAKE-MODEL          | FAULT MAZ. CODE CAT. | MILEAGE AT FAILURE | SHOP NUMBER |
|------------|------------|-----------------|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------------|---------------------|----------------------|--------------------|-------------|
| 50011      | P01523 B   | 760501          | 01530           | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>69 023 PLYMOUTH                                                                                 |                 | 01 BARRACUDA        | 34 C                 | 0838864            | 90C04013    |
| 20013      | P00950 B   | 751024          | 01530           | BALL STUD SOCKET VERY LOOSE-NO GREASE ON ARM-<br>STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>67 023 PLYMOUTH                                |                 | 04 FURY             | 57 C                 | 051404             | 60626008    |
| 50019      | P01591 B   | 760607          | 01530           | IDLER ARM SOCKET FROZEN<br>STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>72 031 FORD DIVISION                                                 |                 | G3 FORD-LTD         | 33 C                 | 078341             | 03103010    |
| 50013      | P01541 B   | 760507          | 01530           | ARM LOCKD UP AT BUSHING ON FRAME BRKT. BRKT RIPPED FROM FRAME<br>STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>71 031 FORD DIVISION           |                 | H3 FORD-GALAXIE 500 | 33 C                 | 048194             | 68102003    |
| 20013      | P00951 B   | 751024          | 01530           | BUSHING BTWN IDLER ARM & FRAME BRKT FROZE, CAUSING ASSY TO SEP FRM FRAM<br>STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>00 031 FORD DIVISION |                 |                     | 57 C                 | 021845             | 60626008    |
| 40003      | P01371 B   | 760330          | 01530           | EXCESSIVE WEAR OF BUSHINGS<br>STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>68 031 FORD DIVISION                                              |                 |                     | 03 C                 | 063492             | 02140002    |
| 40004      | P01373 B   | 760330          | 01530           | IDLER ARM BRACKET BROKEN WHERE IT ATTACHES TO FRAME<br>STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>68 031 FORD DIVISION                     |                 | COUNTRY WG PRP      | 03 C                 | 074932             | 02140002    |
| 30023      | P01290 B   | 760214          | 01530           | IDLER ARM BRACKET IS BROKEN AT AREA WHERE ATTACHED TO FRAME<br>STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>69 031 FORD DIVISION             |                 |                     | 09 C                 | 061756             | 02140002    |
| 20013      | P00933 B   | 751024          | 01530           | FRAME RIPPED AT POINT OF IDLER ARM BRACKET ATTACHMENT - LIGHTLY RUSTED<br>STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>72 031 FORD DIVISION  |                 | 05 MUSTANG          | 57 C                 | 000000             | 60626008    |
|            |            |                 |                 | EXCESSIVE WEAR OF IDLER ARM                                                                                                                   |                 |                     |                      |                    |             |

PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06 PAGE 0008

SORTED BY COMPONENT, MODEL, HDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                         | MAKE-MODEL                   | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|---------------------------------------------------------------------------|------------------------------|-------------------------|-----------------------|----------------|
| 20013         | P00934        | B 751024              | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>72 031 FORD DIVISION        | 05 MUSTANG                   | 57 C                    | 000000                | 60626008       |
|               |               |                       |                    | EXCESSIVE WEAR OF IDLER ARM BUSHINGS                                      |                              |                         |                       |                |
| 40002         | P01337        | B 760324              | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>74 031 FORD DIVISION        | 9A FORD TRUCK AND VAN<br>VAN | 03 C                    | 025988                | 53511008       |
|               |               |                       |                    | BRACKET BROKE AT 90 DEGREE BEND, IRON PIECE CRACKED IN TWO-SHAFT OK       |                              |                         |                       |                |
| 20011         | P00891        | B 751001              | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>62 033 MERCURY              | 04 MERCURY                   | 57 C                    | 090465                | 61107005       |
|               |               |                       |                    | EXCESSIVE WEAR OF STEERING IDLER ARM                                      |                              |                         |                       |                |
| 30006         | P01093        | B 751224              | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>72 042 CADILLAC DIVISION    | B1 CADILLAC-DE VILLE         | 57 C                    | 015515                | 02140002       |
|               |               |                       |                    | NO LUBRICATION FITTING ON IDLER ARM CAUSES PREMATURE FAILURE              |                              |                         |                       |                |
| 20002         | P00473        | B 750716              | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>00 042 CADILLAC DIVISION    | 01 CADILLAC                  | 44 A                    | 000000                | 019963100      |
|               |               |                       |                    | POOR PERFORMANCE OF IDLER ARM & BRACKET CAUSED LOSS OF STEERING           |                              |                         |                       |                |
| 30003         | P01033        | B 751122              | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>72 042 CADILLAC DIVISION    | 02 FLEETWOOD                 | 33 C                    | 081930                | 190602026      |
|               |               |                       |                    | IDLER ARM W/BRACKET AND SMALL SECTION OF FRAME MOUNT-IDLER ARM FROZEN     |                              |                         |                       |                |
| 50022         | P01608        | B 760601              | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>65 043 CHEVROLET DIVISION   | A3 BELAIR                    | 21 C                    | 055000                | 51103030       |
|               |               |                       |                    | IDLER ARM SEPARATED FROM BRKT AT BUSHING BRKT IS CORRODED FIT IS LOOSE    |                              |                         |                       |                |
| 20016         | P00972        | B 751108              | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>70 043 CHEVROLET DIVISION   | C4 NOVA                      | 11 C                    | 080000                | 48197006       |
|               |               |                       |                    | FRAME BRACKET SEPARATED FROM IDLER ARM-NO EVIDENCE OF LUBE AT BUSHING     |                              |                         |                       |                |
| 20017         | P00991        | B 751114              | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>65 043 CHEVROLET DIVISION   | E3 IMPALA                    | 57 C                    | 063129                | 80910024       |
|               |               |                       |                    | WEAR AT BUSHING, HOLE, FOR STEERING LINKAGE CONNECTION-SUPPORT SHAFT FROZ |                              |                         |                       |                |

76/07/66

PAGE 0009

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX

SORTED BY COMPONENT, MODEL, YR

AS OF 30 JUN 76

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                           | MAKE-MODEL   | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|--------------------------------------------------------------------------|--------------|-------------------------|-----------------------|----------------|
| 40001         | P01324 B      | 760320                | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>65 043 CHEVROLET DIVISION  | E3 IMPALA    | 21 C                    | 058000                | 06114000       |
| 30005         | P01063 B      | 751206                | 01530              | ARM SEPARATED FROM BRACKET, EXCESS WEAR, LITE RUST AT JOINT              |              |                         |                       |                |
| 30005         | P01063 B      | 751206                | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>65 043 CHEVROLET DIVISION  | 02 CHEVELLE  | 11 C                    | 073420                | 23230003       |
| 40003         | P01346 B      | 760324                | 01530              | IDLER ARM SEPARATED FROM FRAME BRACKET-RUST, PITTING, AND EXCESSIVE WEAR |              |                         |                       |                |
| 40003         | P01346 B      | 760324                | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>71 043 CHEVROLET DIVISION  | 02 CHEVELLE  | 08 C                    | 094640                | 66032000       |
| 40001         | P01325 B      | 760320                | 01530              | METAL CRACKED AT LOWER BOLT HOLE ON MTG BRKT SOME WEAR AT IDLER JOINT    |              |                         |                       |                |
| 40001         | P01325 B      | 760320                | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>65 043 CHEVROLET DIVISION  | 03 CHEVROLET | 21 C                    | 060000                | 06114000       |
| 30021         | P01265 B      | 760206                | 01530              | EXCESS WEAR AT JOINT NO EVIDENCE OF LUBE-IDLER ARM SEP FROM BRACKET      |              |                         |                       |                |
| 30021         | P01265 B      | 760206                | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>65 043 CHEVROLET DIVISION  | 03 CHEVROLET | 03 C                    | 070000                | 03242000       |
| 20004         | P00710 B      | 750801                | 01530              | IDLER ARM SEPARATED FROM BRACKET - BRACKET BROKEN - WEAR EVIDENT         |              |                         |                       |                |
| 20004         | P00710 B      | 750801                | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>73 044 OLDSMOBILE          | 02 DELTA 88  | 34 C                    | 017118                | 04895001       |
| 20004         | P00711 B      | 750801                | 01530              | IDLER ARM ASSEMBLY (LOOSE) HAS TOO MUCH FREE PLAY                        |              |                         |                       |                |
| 20004         | P00711 B      | 750801                | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>65 044 OLDSMOBILE          | 03 F-85      | 34 C                    | 063439                | 04891000       |
| 20004         | P00709 B      | 750801                | 01530              | TOO MUCH FREE PLAY IN JOINT                                              |              |                         |                       |                |
| 20004         | P00709 B      | 750801                | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>70 044 OLDSMOBILE          | 03 F-85      | 34 C                    | 068656                | 04891000       |
| 30002         | P01023 B      | 751119                | 01530              | LOOSE IDLER ARM ASSEMBLY-TOO MUCH FREE PLAY IN STEERING                  |              |                         |                       |                |
| 30002         | P01023 B      | 751119                | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>68 045 PONTIAC DIVISION    | 01 FIREBIRD  | 21 C                    | 064531                | 53213000       |
|               |               |                       |                    | IDLER ARM SEPARATED FROM BRACKET-EXCESSIVE WEAR & CORROSION AT CONNECT   |              |                         |                       |                |

PARTS KILUCKY PROGRAM

76/07/06 PAGE 0010

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN NUMBER | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                      | MAKE-MODEL                          | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|------------|-------------------|------------------|--------------------|------------------------------------------------------------------------|-------------------------------------|-------------------------|-----------------------|----------------|
| 30015      | P01169 B          | 760106           | 01540              | STEERING LINKAGES-ROD, RELAY-CONNECTING<br>74 031 FORD DIVISION        | 9A FORD TRUCK AND VAN<br>F-350      | 57 C                    | 000000                | 46394015       |
|            |                   |                  |                    | ROD END BENT - PIN CAME OUT                                            |                                     |                         |                       |                |
| 50004      | P01471 D          | 760405           | 01550              | STEERING LINKAGES-TIE ROD, INNER<br>75 022 DODGE                       | 9A DODGE TRUCK AND VAN<br>B-200 VAN | 34 C                    | 043315                | 14607007       |
|            |                   |                  |                    | TIE ROD LOOSE IN SLEEVE W/ SLEEVE BOLTS TIGHTENED                      |                                     |                         |                       |                |
| 50004      | P01471 B          | 760405           | 01550              | STEERING LINKAGES-TIE ROD, INNER<br>75 022 DODGE                       | 9A DODGE TRUCK AND VAN<br>B-200 VAN | 34 C                    | 043315                | 14607007       |
|            |                   |                  |                    | INNER END OF TIE ROD ASSEMBLY LOOSE AT SLEEVE                          |                                     |                         |                       |                |
|            | P01453 B          | 760402           | 01550              | STEERING LINKAGES-TIE ROD, INNER<br>74 031 FORD DIVISION               | 06 PINTO                            | 28 C                    | 020000                | 48197006       |
|            |                   |                  |                    | NO PART SENT-SHOP NOTES HAVE NO SPECIFICS-CUSTOMER REFUSED SERVICE     |                                     |                         |                       |                |
| 20007      | P00818 B          | 750825           | 01550              | STEERING LINKAGES-TIE ROD, INNER<br>67 043 CHEVROLET DIVISION          | E3 IMPALA                           | 03 A                    | 077495                | 033145005      |
|            |                   |                  |                    | TIE ROD BROKE @ TIE ROD ADJUSTMENT SLEEVE                              |                                     |                         |                       |                |
| 20013      | P00940 B          | 751024           | 01560              | STEERING LINKAGES-TIE ROD, END<br>00 000 UNKNOWN                       | 00 UNKNOWN                          | 00 C                    | 000000                | 60626008       |
|            |                   |                  |                    | TIE ROD END NO APPARENT DEFECT                                         |                                     |                         |                       |                |
| 20013      | P00939 B          | 751024           | 01560              | STEERING LINKAGES-TIE ROD, END<br>00 000 UNKNOWN                       | 00 UNKNOWN                          | 57 C                    | 000000                | 60626008       |
|            |                   |                  |                    | EXCESSIVE WEAR OF TIE ROD END DUE TO LACK OF GREASE                    |                                     |                         |                       |                |
| 50001      | P01422 B          | 760331           | 01560              | STEERING LINKAGES-TIE ROD, END<br>00 000 UNKNOWN                       | 00 UNKNOWN                          | 57 C                    | 000000                | 60626008       |
|            |                   |                  |                    | EXCESS WEAR IN BALL STUD SOCKET EVIDENCE OF LACK OF LUBE TAG NOT LEGBL |                                     |                         |                       |                |
| 50001      | P01423 B          | 760331           | 01560              | STEERING LINKAGES-TIE ROD, END<br>00 000 UNKNOWN                       | 00 UNKNOWN                          | 57 C                    | 000000                | 60626008       |
|            |                   |                  |                    | EXCESS WEAR IN STUD SOCK TIE-ROD APPAR CUT W/TORCH TAG NOT READABLE    |                                     |                         |                       |                |

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                    | MAKE-MODEL    | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |          |
|---------------|-------------------|------------------|--------------------|----------------------------------------------------------------------|---------------|-------------------------|-----------------------|----------------|----------|
| 50001         | P01421 B          | 760331           | 01560              | STEERING LINKAGES-TIE ROD,END<br>00 000 UNKNOWN                      | 00 UNKNOWN    | 57                      | C                     | 000000         | 60626006 |
|               |                   |                  |                    | WEAR IN BALL STUD SOCKET TAG NOT READABLE                            |               |                         |                       |                |          |
| 50001         | P01419 B          | 760331           | 01560              | STEERING LINKAGES-TIE ROD,END<br>00 000 UNKNOWN                      | 00 UNKNOWN    | 57                      | C                     | 000000         | 60626006 |
|               |                   |                  |                    | SLIGHT WEAR IN BALL STUD SOCKET TAG NOT READABLE                     |               |                         |                       |                |          |
| 50001         | P01424 B          | 760331           | 01560              | STEERING LINKAGES-TIE ROD,END<br>00 000 UNKNOWN                      | 00 UNKNOWN    | 57                      | C                     | 000000         | 60626006 |
|               |                   |                  |                    | BALL STUD SOCK ONLY BALL IS WORN APPAR SEP FROM TIE-ROD-BODY         |               |                         |                       |                |          |
| 50001         | P01418 B          | 760331           | 01560              | STEERING LINKAGES-TIE ROD,END<br>00 000 UNKNOWN                      | 00 UNKNOWN    | 57                      | C                     | 000000         | 60626006 |
|               |                   |                  |                    | VERY SLIGHT WEAR IN BALL STUD SOCKET TAG NOT READABLE                |               |                         |                       |                |          |
| 50001         | P01420 B          | 760331           | 01560              | STEERING LINKAGES-TIE ROD,END<br>00 000 UNKNOWN                      | 00 UNKNOWN    | 57                      | C                     | 000000         | 60626008 |
|               |                   |                  |                    | EXCESS WEAR IN BALL STUD SOCKET EVIDENCE OF LACK OF LUBE TAG NOT LEG |               |                         |                       |                |          |
| 20011         | PC0883 B          | 751003           | 01560              | STEERING LINKAGES-TIE ROD,END<br>65 010 AMERICAN MOTORS              | 01 AMBASSADOR | 57                      | C                     | 001289         | 61107005 |
|               |                   |                  |                    | EXCESSIVE WEAR ON BALL STUD CAUSED TIE ROD TO FALL OFF               |               |                         |                       |                |          |
| 30001         | P00994 B          | 751114           | 01560              | STEERING LINKAGES-TIE ROD,END<br>68 022 DODGE                        | 02 CHARGER    | 57                      | C                     | 075000         | 19802003 |
|               |                   |                  |                    | GREASE RETAINING BOOT SPLIT, NO EVIDENCE OF LUBRICANT-BALL STUD WORN |               |                         |                       |                |          |
| 30011         | P01215 D          | 760123           | 01560              | STEERING LINKAGES-TIE ROD,END<br>71 022 DODGE                        | 08 DEMON      | 57                      | C                     | 057000         | 06416006 |
|               |                   |                  |                    | TIE ROD END HAS WEAR AT BALL STUD SOCKET - ROUGH ACTION              |               |                         |                       |                |          |
| 30011         | P01215 C          | 760123           | 01560              | STEERING LINKAGES-TIE ROD,END<br>71 022 DODGE                        | 08 DEMON      | 57                      | C                     | 057000         | 06416006 |
|               |                   |                  |                    | TIE ROD END BENT ALONG THREADS FOR SLEEVE                            |               |                         |                       |                |          |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0012

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                         | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                  | MAKE-MODEL                   | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|-----------------------------------------------------------------------|---------------|-----------------------|--------------------|-------------------------------------------------------|------------------------------|-------------------------|-----------------------|----------------|
| 20016                                                                 | P00976 B      | 751108                | 01560              | STEERING LINKAGES-TIE ROD,END<br>73 023 PLYMOUTH      | A6 VALIANT-DUSTER            | 03 C                    | 016620                | 46219002       |
| BOTTOM OF TIE ROD END MISSING-COULD CAUSE CONTAMINATION OF GREASE     |               |                       |                    |                                                       |                              |                         |                       |                |
| 40001                                                                 | P01329 C      | 760320                | 01560              | STEERING LINKAGES-TIE ROD,END<br>69 023 PLYMOUTH      | C4 FURY III                  | 08 C                    | 001823                | 66032002       |
| SOCKET HAS SOME WEAR GREASE BOOT CRACKED-GREASE PLUG STILL IN PLACE   |               |                       |                    |                                                       |                              |                         |                       |                |
| 40001                                                                 | P01329 E      | 760320                | 01560              | STEERING LINKAGES-TIE ROD,END<br>69 023 PLYMOUTH      | C4 FURY III                  | 08 C                    | 001823                | 66032002       |
| BALL STUD SOCKET HAS SOME WEAR GREASE BOOT SPLIT-PLUG STILL IN PLACE  |               |                       |                    |                                                       |                              |                         |                       |                |
| 40001                                                                 | P01329 D      | 760320                | 01560              | STEERING LINKAGES-TIE ROD,END<br>69 023 PLYMOUTH      | C4 FURY III                  | 57 C                    | 001823                | 66032002       |
| SOCKET HAS SOME WEAR DUE TO CRACKED GREASE BOOT-PLUG STILL IN PLACE   |               |                       |                    |                                                       |                              |                         |                       |                |
| 40001                                                                 | P01329 B      | 760320                | 01560              | STEERING LINKAGES-TIE ROD,END<br>69 023 PLYMOUTH      | C4 FURY III                  | 21 C                    | 001823                | 66032002       |
| BALL STUD SEPARATED FROM SOCKET BOOT CRACKED NO LUBE EVIDENT          |               |                       |                    |                                                       |                              |                         |                       |                |
| 20002                                                                 | P00460 B      | 750729                | 01560              | STEERING LINKAGES-TIE ROD,END<br>68 023 PLYMOUTH      | 06 VALIANT                   | 57 B                    | 043350                | 081003001      |
| LEFT TIE-ROD END WORE EXCESSIVELY AT JOINT                            |               |                       |                    |                                                       |                              |                         |                       |                |
| 50011                                                                 | P01528 B      | 760507                | 01560              | STEERING LINKAGES-TIE ROD,END<br>66 031 FORD DIVISION | 05 MUSTANG                   | 21 C                    | 081000                | 64110016       |
| BALL STUD SEPARATED FROM SOCKET NO GREASE FITTING ON TIE ROD-NO LUBE  |               |                       |                    |                                                       |                              |                         |                       |                |
| DOT1                                                                  | P00462 B      | 750725                | 01560              | STEERING LINKAGES-TIE ROD,END<br>71 031 FORD DIVISION | 06 PINTO                     | 21 A                    | 040000                | 055103001      |
| LEFT TIE ROD END CAME APART                                           |               |                       |                    |                                                       |                              |                         |                       |                |
| 30001                                                                 | P01007 B      | 751118                | 01560              | STEERING LINKAGES-TIE ROD,END<br>73 031 FORD DIVISION | 98 F100 2DR CONV. PU<br>F100 | 57 C                    | 038744                | 68510011       |
| 1 BALL STUD SOCKET TIE ROD END SHOWS EXCESSIVE WEAR-NO GREASE FITTING |               |                       |                    |                                                       |                              |                         |                       |                |

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN NUMBER | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME<br>YR MANUFACTURER                                      | MAKE-MODEL         | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHUP<br>NUMBER |
|------------|------------|-----------------|-----------------|------------------------------------------------------------------------|--------------------|-------------------------|-----------------------|----------------|
| 20015      | P00948 B   | 751024          | 01560           | STEERING LINKAGES-TIE ROD,END<br>69 032 LINCOLN                        | 00 LINCOLN         | 57 C                    | 000000                | 60626006       |
|            |            |                 |                 | EXCESSIVE WEAR DUE TO LACK OF LUBRICATION                              |                    |                         |                       |                |
| 20004      | POC487 B   | 750716          | 01560           | STEERING LINKAGES-TIE ROD,END<br>65 033 MERCURY                        | 02 COMET           | 34 C                    | 102878                | 013673001      |
|            |            |                 |                 | LEFT TIE ROD END EXCESSIVE LOOSENESS                                   |                    |                         |                       |                |
| 20004      | P00718 B   | 750805          | 01560           | STEERING LINKAGES-TIE ROD,END<br>66 043 CHEVROLET DIVISION             | A3 BELAIR          | 57 C                    | 046170                | 014217004      |
|            |            |                 |                 | EXCESSIVE WEAR OF TIE ROD END AT JOINT                                 |                    |                         |                       |                |
| 50011      | P01525 B   | 760501          | 01560           | STEERING LINKAGES-TIE ROD,END<br>64 043 CHEVROLET DIVISION             | B4 CHEVY II        | 21 C                    | 075906                | 14217004       |
|            |            |                 |                 | BALL STUD SEP FROM SOCKET- RUST ON PARTS- LACK OF LUBE                 |                    |                         |                       |                |
| 40007      | P01413 B   | 760401          | 01560           | STEERING LINKAGES-TIE ROD,END<br>73 043 CHEVROLET DIVISION             | E3 IMPALA          | 02 C                    | 075813                | 23513001       |
|            |            |                 |                 | TIE ROD BENT AT SLEEVE THREADS-STUD SOCKET ACTION OK-WEAR ON STUD BASE |                    |                         |                       |                |
| 50002      | P01442 C   | 760401          | 01560           | STEERING LINKAGES-TIE ROD,END<br>76 043 CHEVROLET DIVISION             | E3 IMPALA          | 57 C                    | 005220                | 30313006       |
|            |            |                 |                 | EXCESSIVE WEAR AT JUNCTION OF TIE ROD END WITH DRAG(CENTER)LINK        |                    |                         |                       |                |
| 20017      | P00980 B   | 751108          | 01560           | STEERING LINKAGES-TIE ROD,END<br>73 043 CHEVROLET DIVISION             | F2 CHEVELLE LAGUNA | 02 C                    | 036400                | 32805010       |
|            |            |                 |                 | TIE ROD END STUDS BENT IN ACCIDENT                                     |                    |                         |                       |                |
| 20017      | P00981 B   | 751108          | 01560           | STEERING LINKAGES-TIE ROD,END<br>69 043 CHEVROLET DIVISION             | 02 CHEVELLE        | 02 C                    | 054000                | 32805010       |
|            |            |                 |                 | TIE ROD BENT IN ACCIDENT-BENT AT SLEEVE                                |                    |                         |                       |                |
| 20010      | P00924 B   | 751020          | 01560           | STEERING LINKAGES-TIE ROD,END<br>73 043 CHEVROLET DIVISION             | 09 VEGA            | 11 C                    | 020880                | 19944103       |
|            |            |                 |                 | BALL AND SOCKET OF TIE ROD END SEPARATED-TIE ROD END HAD NO GREASE     |                    |                         |                       |                |

# PARTS RETURN PROGRAM

76/07/06 PAGE 0014

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MOL YR

| BIN NUMBER | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                                        | YR | MANUFACTURER | MAKE-MODEL                    | FAULT HAZ. CODE | HAZ. CAT. | MILEAGE AT FAILURE | SHOP NUMBER |
|------------|------------|-----------------|-----------------|-----------------------------------------------------------------------|----|--------------|-------------------------------|-----------------|-----------|--------------------|-------------|
| 20005      | P00793     | B 750812        | 01560           | STEERING LINKAGES-TIE ROD,END<br>06 043 CHEVROLET DIVISION            |    |              | 9B CHEVROLET VAN<br>SPORTSVAN | 02              | C         | 000000             | 032605010   |
|            |            |                 |                 | TIE ROD BENT NEAR ADJUSTMENT SLEEVE                                   |    |              |                               |                 |           |                    |             |
| 30002      | P01022     | B 751119        | 01560           | STEERING LINKAGES-TIE ROD,END<br>72 043 CHEVROLET DIVISION            |    |              | 9B CHEVROLET VAN<br>VAN       | 21              | C         | 004600             | 53213003    |
|            |            |                 |                 | BALL STUD SEPARATED FROM SOCKET-SOCKET EXCESSIVE INTERNAL WEAR & RUST |    |              |                               |                 |           |                    |             |
| 30002      | P01050     | B 751119        | 01560           | STEERING LINKAGES-TIE ROD,END<br>72 043 CHEVROLET DIVISION            |    |              | 9B CHEVROLET VAN<br>VAN       | 21              | C         | 004600             | 53213003    |
|            |            |                 |                 | BALL STUD SEPARATED FROM SOCKET-SOCKET EXCESSIVE INTERNAL WEAR & RUST |    |              |                               |                 |           |                    |             |
| 50019      | PC1585     | B 760601        | 01560           | STEERING LINKAGES-TIE ROD,END<br>72 043 CHEVROLET DIVISION            |    |              | 9B CHEVROLET VAN<br>G-10      | 21              | C         | 014387             | C214C002    |
|            |            |                 |                 | SEPARATION OF BALL STUD SOCKET NO LUBE EVIDENT. SOCKET IS RUSTY       |    |              |                               |                 |           |                    |             |
| 30008      | P01102     | B 751226        | 01560           | STEERING LINKAGES-TIE ROD,END<br>62 044 OLDSMOBILE                    |    |              | 02 DELTA 88                   | 57              | C         | 072000             | 19802003    |
|            |            |                 |                 | TIE ROD RUBBER SLEEVE RIPPED-JOINT HAS PLAY FROM WEAR-NO LUBE FITTING |    |              |                               |                 |           |                    |             |
| 50011      | PC1524     | B 760501        | 01560           | STEERING LINKAGES-TIE ROD,END<br>71 044 OLDSMOBILE                    |    |              | 02 DELTA 88                   | 21              | C         | 056549             | 83704045    |
|            |            |                 |                 | BALL STUD SEP AT SOCKET- NO EXCESS WEAR AT STUD OR SOCKET             |    |              |                               |                 |           |                    |             |
| 20011      | P00884     | B 751008        | 01560           | STEERING LINKAGES-TIE ROD,END<br>74 045 PONTIAC DIVISION              |    |              | C3 CATALINA                   | 34              | C         | 010615             | 14607007    |
|            |            |                 |                 | TO MUCH PLAY IN END CAUSED POOR HANDLING,SHIMMY,WANDERING AT 40MPH    |    |              |                               |                 |           |                    |             |
| 30012      | P01176     | B 760106        | 01560           | STEERING LINKAGES-TIE ROD,END<br>71 049 GMC                           |    |              | 9A GMC TRUCK<br>TRUCK         | 00              | C         | 036874             | 098223001   |
|            |            |                 |                 | GREASE FITTING EITHER FELL OR WAS TAKEN OUT-JOINT SLIGHTLY LOOSE-     |    |              |                               |                 |           |                    |             |
| 20013      | P00938     | B 751024        | 01570           | STEERING LINKAGES-SLEEVE,TIE ROD-ADJUSTAB<br>00 000 UNKNOWN           |    |              |                               | 49              | C         | 000000             | 60626008    |
|            |            |                 |                 | TIE ROD SLEEVE RUSTED                                                 |    |              |                               |                 |           |                    |             |

76/07/06

PAGE 0015

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUL 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN NUMBER | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                         | MAKE-MODEL                          | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHGP<br>NUMBER |
|------------|-------------------|------------------|--------------------|---------------------------------------------------------------------------|-------------------------------------|-------------------------|-----------------------|----------------|
| 30011      | P01215 B          | 760123           | 01570              | STEERING LINKAGES-SLEEVE, TIE ROD-ADJUSTAB<br>71 022 DODGE                | 08 DEMON                            | 03 C                    | 057000                | 06416006       |
|            |                   |                  |                    | TIE ROD SLEEVE IS BENT AND BROKEN - ONE TIE ROD END IS BENT               |                                     |                         |                       |                |
| 50004      | P01471 C          | 760405           | 01570              | STEERING LINKAGES-SLEEVE, TIE ROD-ADJUSTAB<br>75 022 DODGE                | 9A DODGE TRUCK AND VA<br>B-200 VAN  | 34 C                    | 043315                | 14607007       |
|            |                   |                  |                    | TIE ROD LOOSE IN SLEEVE W/ SLEEVE BOLTS TIGHTENED                         |                                     |                         |                       |                |
| 40007      | P01413 C          | 760401           | 01570              | STEERING LINKAGES-SLEEVE, TIE ROD-ADJUSTAB<br>74 043 CHEVROLET DIVISION   | E3 IMPALA                           | 03 C                    | 075813                | 23513001       |
|            |                   |                  |                    | TIE ROD SLEEVE BROKEN AT TIE ROD END (ROD BENT) LIGHT RUST INSIDE SLEEVE  |                                     |                         |                       |                |
| 40008      | P01338 B          | 760324           | 01580              | STEERING LINKAGES-KNUCKL-SPINDL-ARM<br>66 110 INTERNATIONAL HARVESTER     | 11 INTERNATIONAL TRUC<br>LDSTAR1600 | 03 C                    | 064000                | 98134058       |
|            |                   |                  |                    | SPINDLE BROKE OFF NEAR BASE BOTH BEARING RACES LEFT WEAR MARKS ON SPIN    |                                     |                         |                       |                |
| 30029      | P01308 B          | 760306           | 01580              | STEERING LINKAGES-KNUCKL-SPINDL-ARM<br>68 043 CHEVROLET DIVISION          | E3 IMPALA                           | 03 C                    | 058674                | 03102004       |
|            |                   |                  |                    | SPINDLE BROKE ACROSS DIAMETER AT BEARING - WHEEL BEARING FROZE            |                                     |                         |                       |                |
| 20005      | P00806 B          | 750918           | 01580              | STEERING LINKAGES-KNUCKL-SPINDL-ARM<br>70 043 CHEVROLET DIVISION          | 02 CHEVELLE                         | 03 C                    | 000000                | 000000000      |
|            |                   |                  |                    | STEERING SPINDLE BROKE APPROXIMATELY 1 INCH BELOW THREADS                 |                                     |                         |                       |                |
| 50023      | P01613 B          | 760601           | 02111              | SUSPN. INDP. FT. ATTACH. MECHANISMS-STRUT RO<br>66 043 CHEVROLET DIVISION | E3 IMPALA                           | 03 C                    | 068258                | 54911007       |
|            |                   |                  |                    | 5/8 IN DIA STRUT ROD BROKE ACROSS CIRC AT THREADS FOR FRONT MOUNT         |                                     |                         |                       |                |
| 30008      | P01122 B          | 751226           | 02113              | SUSPN. INDP. FT. ATTACH. MECH.-SPRING-COIL<br>75 022 DODGE                | 9A DODGE TRUCK AND VA<br>CARRY VAN  | 03 C                    | 018200                | 32809006       |
|            |                   |                  |                    | COIL SPRING BROKE IN 2 PLACES                                             |                                     |                         |                       |                |
| 50010      | P01511 B          | 760427           | 02113              | SUSPN. INDP. FT. ATTACH. MECH.-SPRING-COIL<br>73 043 CHEVROLET DIVISION   | E3 IMPALA                           | 03 C                    | 021570                | 12603050       |
|            |                   |                  |                    | SPRING BROKE 3RD COIL FROM BOTTOM CONTROL ARM                             |                                     |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0016

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                   | MAKE-MODEL         | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|------------------------------------------------------------------------|--------------------|-------------------------|-----------------------|----------------|
| 20001         | P00478        | B 750708              | 02120              | SUSPN. INDP. FT. SHOCK ABSORBER<br>71 010 AMERICAN MOTORS              | 04 GREMLIN         | 03 C                    | 037186                | 053140005      |
|               |               |                       |                    | SHOCK ABSORBER LOWER PLATE BROKE IN HALF                               |                    |                         |                       |                |
| 20007         | P00822        | B 750827              | 02120              | SUSPN. INDP. FT. SHOCK ABSORBER<br>65 031 FORD DIVISION                | 05 MUSTANG         | 03 C                    | 079233                | 090027012      |
|               |               |                       |                    | BASE PLATE BROKE AWAY FROM SHOCK                                       |                    |                         |                       |                |
| 50014         | P01554        | C 760507              | 02120              | SUSPN. INDP. FT. SHOCK ABSORBER<br>73 042 CADILLAC DIVISION            | A1 CADILLAC-CALAIS | 56 C                    | 036000                | 36108002       |
|               |               |                       |                    | BOTTOM SHOCK MOUNT BUSHING SHOWS SLIGHT WEAR-NO LEAKS-TOO WEAK FOR CAR |                    |                         |                       |                |
| 50014         | P01554        | B 760507              | 02120              | SUSPN. INDP. FT. SHOCK ABSORBER<br>73 042 CADILLAC DIVISION            | A1 CADILLAC-CALAIS | 56 C                    | 036000                | 36108002       |
|               |               |                       |                    | BOTTOM SHOCK MOUNT BUSHING SHOWS SLIGHT WEAR-NO LEAKS-TOO WEAK FOR CAR |                    |                         |                       |                |
| 30004         | P01058        | B 751206              | 02120              | SUSPN. INDP. FT. SHOCK ABSORBER<br>74 043 CHEVROLET DIVISION           | 08 MONTE CARLO     | 57 C                    | 008307                | 94122009       |
|               |               |                       |                    | LOWER BUSHING SOME WEAR-TAG SAYS WORN OUT-NO EVIDENCE OF LEAK/BREAKAGE |                    |                         |                       |                |
| 30004         | P01059        | B 751206              | 02120              | SUSPN. INDP. FT. SHOCK ABSORBER<br>74 043 CHEVROLET DIVISION           | 08 MONTE CARLO     | 57 C                    | 008307                | 94122009       |
|               |               |                       |                    | LOWER BUSHING SOME WEAR-TAG SAYS WORN OUT-NO EVIDENCE OF LEAK/BREAKAGE |                    |                         |                       |                |
| 30011         | P01141        | B 751229              | 02130              | SUSPN. INDP. FT. CONTROL ARM, UNKNOWN TYPE<br>70 031 FORD DIVISION     | 08 TORINO          | 03 C                    | 098000                | 21257001       |
|               |               |                       |                    | CONTROL ARM BROKE WHERE BALL JOINT ATTACHES-RUST ON BREAK-NO CRACKS    |                    |                         |                       |                |
| 20003         | P00820        | B 750827              | 02130              | SUSPN. INDP. FT. CONTROL ARM, UNKNOWN TYPE<br>69 045 PONTIAC DIVISION  | 01 FIREBIRD        | 03 B                    | 050037                | 090027012      |
|               |               |                       |                    | CONTROL ARM BOLT BROKE CAUSING POOR STEERING                           |                    |                         |                       |                |
| 20013         | P00944        | B 751024              | 02132              | SUSPN. INDP. FT. CTRL ARM UNK TYP-BALL JOINT<br>00 000 UNKNOWN         | 00 UNKNOWN         | 57 C                    | 000000                | 60626008       |
|               |               |                       |                    | BALL JOINT WORN                                                        |                    |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0017

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, YR

| BIN<br>NUMBER | PRP<br>NUMBER | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                      | MAKE-MODEL     | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|------------------|--------------------|------------------------------------------------------------------------|----------------|-------------------------|-----------------------|----------------|
| 20015         | P00954        | 6 751024         | 02132              | SUSPN.INDP.FT. CTRL ARM UNK TYP-BALL JOIN<br>00 000 UNKNOWN            | 00 000 UNKNOWN | 03                      | 000000                | 60626008       |
|               |               |                  |                    | SHANK OF BALL JOINT STUD BROKEN                                        |                |                         |                       |                |
| 50001         | P01430        | 8 760331         | 02132              | SUSPN.INDP.FT. CTRL ARM UNK-TYP-BALL JOIN<br>00 000 UNKNOWN            | 00 000 UNKNOWN | 57                      | 000000                | 60626008       |
|               |               |                  |                    | EXCESS WEAR IN BALL STUD SOCKET, VERTICAL PLAY-GREASE RET BOOT CRACKED |                |                         |                       |                |
| 50001         | P01427        | 6 760331         | 02132              | SUSPN.INDP.FT. CTRL ARM UNK TYP-BALL JOIN<br>00 000 UNKNOWN            | 00 000 UNKNOWN | 57                      | 000000                | 60626008       |
|               |               |                  |                    | EXCESS VERTICAL MOVEMENT IN BALL STUD SOCKET TAG NOT READABLE          |                |                         |                       |                |
| 50001         | P01428        | 8 760331         | 02132              | SUSPN.INDP.FT. CTRL ARM UNK TYP-BALL JOIN<br>00 000 UNKNOWN            | 00 000 UNKNOWN | 57                      | 000000                | 60626008       |
|               |               |                  |                    | EXCESSIVE WEAR IN BALL STUD SOCKET-EXCESSIVE VERTICAL MOVEMENT         |                |                         |                       |                |
| 50001         | P01429        | 9 760331         | 02132              | SUSPN.INDP.FT. CTRL ARM UNK TYP-BALL JOIN<br>00 000 UNKNOWN            | 00 000 UNKNOWN | 57                      | 000000                | 60626008       |
|               |               |                  |                    | EXCESSIVE PLAY IN BALL STUD SOCKET-EXCESS VERTICAL PLAY-NO EVID OF LUB |                |                         |                       |                |
| 50001         | P01426        | 6 760331         | 02132              | SUSPN.INDP.FT. CTRL ARM UNK TYP-BALL JOIN<br>00 000 UNKNOWN            | 00 000 UNKNOWN | 57                      | 000000                | 60626008       |
|               |               |                  |                    | SLIGHT WEAR IN BALL STUD SOCKET-GREASE BOOT CRACKED                    |                |                         |                       |                |
| 50001         | P01425        | 8 760331         | 02132              | SUSPN.INDP.FT. CTRL ARM UNK TYP-BALL JOIN<br>00 000 UNKNOWN            | 00 000 UNKNOWN | 57                      | 000000                | 60626008       |
|               |               |                  |                    | EXCES WEAR IN BALL STUD SOCK-NO LUBE EVIDENT-GREASE BOOT CRACKED       |                |                         |                       |                |
| 50001         | P01431        | 5 760331         | 02132              | SUSPN.INDP.FT. CTRL ARM UNK TYP-BALL JOIN<br>00 000 UNKNOWN            | 00 000 UNKNOWN | 57                      | 000000                | 60626008       |
|               |               |                  |                    | EXCESS WEAR IN BALL STUD SOCKET, VERTICAL PLAY-GREASE RET BOOT CRACKED |                |                         |                       |                |
| 50001         | P01432        | 8 760331         | 02132              | SUSPN.INDP.FT. CTRL ARM UNK TYP-BALL JOIN<br>00 000 UNKNOWN            | 00 000 UNKNOWN | 34                      | 000000                | 60626008       |
|               |               |                  |                    | EXCESSIVE VERTICAL MOVEMENT IN BALL STUD SOCKET                        |                |                         |                       |                |

# PARTS RETURN PROGRAM

76/07/06 PAGE 0012

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, NDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                                                    | MAKE-MODEL            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|------------------|--------------------|------------------------------------------------------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 30004         | P01054 B      | 751206           | 02132              | SUSPN. INDP. FT. CTRL ARM UNK TYP-BALL JOIN<br>63 010 AMERICAN MOTORS                                | 00 AMERICAN MOTORS    | 21 C                    | 096249                | 80226008       |
| 50011         | P01529 B      | 760501           | 02132              | SEPARATION OF BALL JOINT AT BALL STUD SOCKET-TORN AT ONE END-NO LUBE<br>64 031 FORD DIVISION         | 03 FORD               | 21 C                    | 091500                | 64110012       |
| 20017         | P00983 B      | 751108           | 02132              | BALL STUD SEP FROM SOCKET, METAL ON SKT CROWN RIPPED IN SIX PLACES<br>73 031 FORD DIVISION           | 08 TORINO             | 57 C                    | 000000                | 01749012       |
| 30005         | P01069 B      | 751206           | 02132              | EXCESSIVE WEAR IN BALL-STUD SOCKET, NO LUBE, JOINT BOTTOM WORE THRU<br>66 042 CADILLAC DIVISION      | 61 CADILLAC-DE VILLE  | 11 C                    | 072122                | 92632037       |
| 30006         | P01113 B      | 751226           | 02132              | BALL JOINT SEPARATED AT BALL STUD SOCKET-PORITION OF SOCKET, BOOT CRACK<br>74 043 CHEVROLET DIVISION | 04 CHEVY II/NOVA      | 09 C                    | 029685                | 03242005       |
| 30015         | P01238 B      | 760203           | 02132              | BALL JOINT RIPPED-LOST SOME GREASE WEAR NOT EXCESSIVE<br>69 044 OLDSMOBILE                           | 02 DELTA 68           | 03 C                    | 082699                | 70601009       |
| 50019         | P01584 B      | 760601           | 02132              | RING OVER BALL SOCKET BENT, TOP OF JOINT DENTED AT ONE POINT<br>70 045 PONTIAC DIVISION              | A4 TEMPEST/LEMANS GTG | 03 C                    | 032848                | 02140002       |
| 20013         | P00945 B      | 751024           | 02140              | JOINT STUD BROKE AT TAPER AT BASE OF THREADS RUINED SPINDLE AND ARM<br>00 000 UNKNOWN                | 00 UNKNOWN            | 57 C                    | 000000                | 60626008       |
| 40003         | P01362 B      | 760329           | 02140              | EXCESSIVE WEAR OF CONTROL ARM BUSHING<br>71 010 AMERICAN MOTORS                                      | 01 AMBASSADOR         | 08 C                    | 058000                | 53140014       |

BOTH SIDES OF CONTROL ARM CRACKED AT AREA CONNECTED TO FRAME

## PARTS RETURN PROGRAM

76/07/06 PAGE 0019

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                           | MAKE-MODEL  | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHIP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|-------------------------------------------------------------|-------------|-------------------------|-----------------------|----------------|
| 30025         | P01271 B      | 760207                | 02140              | SUSPN.INDP.FT. CONTROL ARM,UPPER<br>69 031 FORD DIVISION    | G3 FORD-LTO | 08 C                    | 061056                | 44107007       |
| 20010         | P00928 B      | 751020                | 02140              | SUSPN.INDP.FT. CONTROL ARM,UPPER<br>68 031 FORD DIVISION    | G2 FALCON   | 08 C                    | 000000                | 60659011       |
| 20010         | P00866 B      | 750925                | 02140              | SUSPN.INDP.FT. CONTROL ARM,UPPER<br>70 031 FORD DIVISION    | G2 FALCON   | 03 C                    | 085730                | 094101002      |
| 20005         | P00722 B      | 750807                | 02140              | SUSPN.INDP.FT. CONTROL ARM,UPPER<br>70 031 FORD DIVISION    | G8 TORINO   | 03 C                    | 065000                | 052404002      |
| 30005         | P01062 B      | 751206                | 02140              | SUSPN.INDP.FT. CONTROL ARM,UPPER<br>75 031 FORD DIVISION    | G9 GRANADA  | 03 A                    | 000000                | 91780010       |
| 20017         | P00979 B      | 751108                | 02140              | SUSPN.INDP.FT. CONTROL ARM,UPPER<br>62 033 MERCURY          | G2 COMET    | 09 C                    | 000000                | 32805014       |
| 50013         | P01538 B      | 760507                | 02141              | SUSPN.INDP.FT. CTRL ARM,UPPER-SHAFT,INNER<br>73 032 LINCOLN | A2 MARK IV  | 57 C                    | 039965                | 33604002       |
| 50017         | P01566 C      | 760512                | 02141              | SUSPN.INDP.FT. CTRL ARM,UPPER-SHAFT,INNER<br>67 033 MERCURY | G3 COUGAR   | 57 C                    | 060445                | 90027012       |
| 50010         | P01482 B      | 760412                | 02142              | SUSPN.INDP.FT. CTRL ARM UPPER-BALL JOINT<br>00 000 UNKNOWN  | 00 UNKNOWN  | 03 C                    | 000000                | 91605014       |

UPPER CONTROL ARM BUSHINGS CRACKED, WORN AND RUSTED-GREASE BOOT CRACKED

BOTH UPPER CONTROL ARMS CRACKED IN CENTER-PARALLEL TO CONT. ARM SHAFT

UPPER CONTROL ARM BROKE AT BALL JOINT

CONTROL ARM BROKE AT SUPPORT BRACKET

UPPER CNTRL ARM BROKE IN TWO AT MIDDLE-RESULT MINOR ACCIDENT

CONTROL ARM SHAFT & BUSHINGS FROZE, ELONGATED HOLE IN CONTROL ARM

RUBBER PORTION OF BUSHING IS EXCESS WORN

EXCESS WORN UPPER CTL ARM BUSHINGS-SHAFT HOLE IN ARM IS ELONGATED

BALL STUD JOINT BROKE 1/2 IN. FROM SOCKET-CNTRL ARM ASSEMBLY GOOD CONDIT

## PARTS RETURN PROGRAM

76/07/06 PAGE 0020

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS                                                    | COMPONENT<br>NAME<br>YR MANUFACTURER                                  | MAKE-MODEL                              | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|---------------|-----------------------|-----------------------------------------------------------------------|-----------------------------------------------------------------------|-----------------------------------------|-------------------------|-----------------------|----------------|
| 50002                                                                  | P01447 B      | 760401                | 02142                                                                 | SUSPN.INDP.FT. CTRL ARM UPPER-BALL JOINT<br>74 CIO AMERICAN MOTORS    | 04 GREMLIN                              | 57 C                    | 025545                | 66000000       |
| VERY SLIGHT WEAR IN BALL STUD SOCKET-GREASE BOOT SPLIT                 |               |                       |                                                                       |                                                                       |                                         |                         |                       |                |
| 40001                                                                  | P01326 B      | 760320                | 02142                                                                 | SUSPN.INDP.FT. CTRL ARM UPPER-BALL JOINT<br>70 023 PLYMOUTH           | 06 VALIANT                              | 21 C                    | 036000                | 06114006       |
| BALL STUD SEP FROM SOCKET BTM PLATE OF JOINT MISS - NO LUBE EVIDENT    |               |                       |                                                                       |                                                                       |                                         |                         |                       |                |
| 20011                                                                  | P00677 B      | 751008                | 02142                                                                 | SUSPN.INDP.FT. CTRL ARM UPPER-BALL JOINT<br>72 031 FORD DIVISION      | 03 FORD                                 | 03 C                    | 062090                | 11204002       |
| BALL JOINT BROKE & SEPARATED                                           |               |                       |                                                                       |                                                                       |                                         |                         |                       |                |
| 20004                                                                  | P00724 B      | 750808                | 02142                                                                 | SUSPN.INDP.FT. CTRL ARM UPPER-BALL JOINT<br>73 031 FORD DIVISION      | 04 MAVERICK                             | 37 C                    | 015140                | 014217004      |
| BALL JOINT NOISY (POSSBL CUT GREASE CUP LET WATER IN JOINT AND RU> ):  |               |                       |                                                                       |                                                                       |                                         |                         |                       |                |
| 30022                                                                  | P01311 B      | 760225                | 02142                                                                 | SUSPN.INDP.FT. CTRL ARM UPPER-BALL JOINT<br>71 033 MERCURY            | 05 MONTEGO                              | 34 C                    | 079000                | 90027012       |
| BALL STUD SOCKET EXHIBITS SOME WEAR LOOSE                              |               |                       |                                                                       |                                                                       |                                         |                         |                       |                |
| 50012                                                                  | P01532 B      | 760507                | 02142                                                                 | SUSPN.INDP.FT. CTRL ARM UPPER-BALL JOINT<br>68 042 CADILLAC DIVISION  | 01 CADILLAC                             | 21 C                    | 083000                | 64110016       |
| BALL STUD FORCED FROM SOCKET-SCRAPE MARKS ON CONTROL ARM PRT O SKT MSG |               |                       |                                                                       |                                                                       |                                         |                         |                       |                |
| 20011                                                                  | P00886 B      | 751006                | 02142                                                                 | SUSPN.INDP.FT. CTRL ARM UPPER-BALL JOINT<br>68 043 CHEVROLET DIVISION | 01 CAMARO                               | 68 C                    | 096084                | 92632037       |
| JAMCO KIT WAS USED WHEN BALL JOINT SHOULD HAVE BEEN REPLACED           |               |                       |                                                                       |                                                                       |                                         |                         |                       |                |
| P00854 C                                                               | 750919        | 02142                 | SUSPN.INDP.FT. CTRL ARM UPPER-BALL JOINT<br>00 043 CHEVROLET DIVISION | 9A CHEVROLET TRUCK AN<br>1/2 TON PICKUP                               | 21 C                                    | 095605                  | 098499007             |                |
| LEFT UPPER BALL JOINT CAME APART                                       |               |                       |                                                                       |                                                                       |                                         |                         |                       |                |
| 20009                                                                  | P00854 B      | 750919                | 02142                                                                 | SUSPN.INDP.FT. CTRL ARM UPPER-BALL JOINT<br>00 043 CHEVROLET DIVISION | 9A CHEVROLET TRUCK AN<br>1/2 TON PICKUP | 21 C                    | 095605                | 098499007      |
| RIGHT UPPER BALL-JOINT CAME APART                                      |               |                       |                                                                       |                                                                       |                                         |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0021

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME                          | MANUFACTURER              | YR | MAKE-MODEL                  | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |           |
|---------------|---------------|--------|------------------|--------------------|--------------------------------------------|---------------------------|----|-----------------------------|-------------------------|-----------------------|----------------|-----------|
| 30012         | P01174        | B      | 760106           | C2142              | SUSPN. INDP. FT. CTRL ARM UPPER-BALL JOINT | 66 043 CHEVROLET DIVISION |    | 9A CHEVROLET TRUCK AN TRUCK | 57                      | C                     | 046874         | 098223001 |
| 40009         | P01417        | B      | 760331           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER         | 00 000 UNKNOWN            |    | 00 UNKNOWN                  | 03                      | C                     | 000000         | 60626006  |
| 20010         | P00372        | B      | 750925           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER         | 72 010 AMERICAN MOTORS    |    | 07 MATADOR                  | 03                      | C                     | 000000         | 043214001 |
| 40005         | P01381        | B      | 760330           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER         | 74 021 CHRYSLER DIVISION  |    | 02 IMPERIAL                 | 03                      | C                     | 039435         | 94117018  |
| 20011         | P00895        | B      | 751008           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER         | 69 022 DODGE              |    | 05 DART                     | 57                      | C                     | 020000         | 17701015  |
| 20011         | P00894        | B      | 751008           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER         | 69 022 DODGE              |    | 05 DART                     | 57                      | C                     | 020000         | 17701015  |
| 20013         | P00910        | B      | 751020           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER         | 69 031 FORD DIVISION      |    | C3 FORD-CNTRY ESQUIRE       | 09                      | C                     | 087980         | 46219002  |
| 20010         | P00925        | B      | 751020           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER         | 68 031 FORD DIVISION      |    | G3 FORD-LTD                 | 08                      | C                     | 131599         | 19047001  |
| 20010         | P00896        | B      | 751009           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER         | 69 031 FORD DIVISION      |    | G3 FORD-LTD                 | 03                      | C                     | 000000         | 37209003  |

# PARTS RETURN PROGRAM

76/07/06 PAGE 0022

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, HDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME                                                      | YR | MANUFACTURER          | MAKE-MODEL              | FAULT HAZ.<br>CODE | HAZ.<br>CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|--------|------------------|--------------------|------------------------------------------------------------------------|----|-----------------------|-------------------------|--------------------|--------------|-----------------------|----------------|
| 20017         | P00985        | B      | 751108           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER                                     | 68 | 031 FORD DIVISION     | 00 FORD DIVISION        | 09                 | C            | 000000                | 53511008       |
|               |               |        |                  |                    | LOWER CONTROL ARM TORN AT BALL JOINT-BALL JOINT MOUNTING HOLES TORN    |    |                       |                         |                    |              |                       |                |
|               | P01549        | B      | 760428           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER                                     | 73 | 031 FORD DIVISION     | 05 MUSTANG              | 08                 | C            | 060725                | 94101002       |
|               |               |        |                  |                    | TOP CROWN OF LOWR CONTROL ARM CRACKED-SUSPECT MTL FATIGUE-NO PART SENT |    |                       |                         |                    |              |                       |                |
| 50006         | P01483        | B      | 760412           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER                                     | 70 | 031 FORD DIVISION     | 91 RANCHERO 500         | 09                 | C            | 057646                | 91605014       |
|               |               |        |                  |                    | LWR A FRAME TORN AT INNER BUSHING LOCATION-SEPARATED FRM CAR-NO RUBBER |    |                       |                         |                    |              |                       |                |
| 20010         | P00923        | B      | 751020           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER                                     | 72 | 032 LINCOLN           | 02 MARK III             | 08                 | C            | 057000                | 19944103       |
|               |               |        |                  |                    | CONTROL ARM SPLIT AT OUTER END                                         |    |                       |                         |                    |              |                       |                |
| 50020         | P01567        | B      | 760512           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER                                     | 66 | 042 CADILLAC DIVISION | B1 CADILLAC-DE VILLE    | 43                 | C            | 000000                | 90027012       |
|               |               |        |                  |                    | BALL JOINT FITS LOOSELY IN ARM - INNER SHAFT BUSHING SHOWS WEAR        |    |                       |                         |                    |              |                       |                |
|               | P01232        | B      | 760306           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER                                     | 69 | 045 PONTIAC DIVISION  | B4 LE MANS              | 03                 | C            | 000000                | 53209033       |
|               |               |        |                  |                    | PART NOT AVAIL - BALL JOINTS WERE REPLACED IN 6/75 POSS EXCESS STRESS  |    |                       |                         |                    |              |                       |                |
| 20009         | P00853        | B      | 750919           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER                                     | 73 | 125 GRP LOTUS CO LTD  | 01 LOTUS<br>EUROPA SPEC | 03                 | C            | 033900                | 092627017      |
|               |               |        |                  |                    | LEFT LOWER CONTROL ARM BROKE                                           |    |                       |                         |                    |              |                       |                |
|               | P00853        | C      | 750919           | 02150              | SUSPN. INDP. FT. CONTROL ARM-LOWER                                     | 73 | 125 GRP LOTUS CO LTD  | 01 LOTUS<br>EUROPA SPEC | 08                 | C            | 033900                | 092627017      |
|               |               |        |                  |                    | RIGHT LOWER CONTROL ARM CRACKED                                        |    |                       |                         |                    |              |                       |                |
|               | P01361        | B      | 760329           | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT                            | 71 | 010 AMERICAN MOTORS   | 06 JAVELIN              | 57                 | C            | 000000                | 53140014       |
|               |               |        |                  |                    | EXCESSIVE WEAR ON LOWER BALL JOINT                                     |    |                       |                         |                    |              |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0023

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                     | MAKE-MODEL           | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|--------------------------------------------------------------------------|----------------------|-------------------------|-----------------------|----------------|
| 20013         | PC0953 B      | 751024                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>00 020 CHRYSLER MOTORS    | 00 CHRYSLER MOTORS   | 57 C                    | 000000                | 60626008       |
|               |               |                       |                    | LOWER BALL JOINTS LOOSE IN SOCKET                                        |                      |                         |                       |                |
| 30012         | P01175 B      | 760106                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>69 022 DODGE              | 05 DART              | 57 C                    | 068768                | 098223001      |
|               |               |                       |                    | SOCKET WORN THIN-RIPPED-LITTLE EVIDENCE OF LUBRICATION                   |                      |                         |                       |                |
| 20009         | P00973 B      | 750925                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>72 023 PLYMOUTH           | 05 SATELLITE         | 03 C                    | 024857                | 016503010      |
|               |               |                       |                    | CAP BROKE OUT OF UPPER BALL JOINT-CAUSING IT TO FALL APART               |                      |                         |                       |                |
| 20013         | PC0917 B      | 751020                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>74 023 PLYMOUTH           | 06 VALIANT           | 33 C                    | 018420                | 15650013       |
|               |               |                       |                    | VERTICLE PLAY IN BALL JOINT SOCKET                                       |                      |                         |                       |                |
|               |               |                       |                    | NO PART SENT - SHOP COMMENT IS BALL JOINT CAME OUT                       |                      |                         |                       |                |
| 50008         | P01505 B      | 760427                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>74 041 BUICK              | 26 GRAN SPORT APOLLO | 57 C                    | 016561                | 44114014       |
|               |               |                       |                    | BALL JOINTS EXCESSIVELY WORN-AS SHOWN BY INDICATOR                       |                      |                         |                       |                |
| 50004         | P01467 B      | 760405                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>71 042 CADILLAC DIVISION  | 81 CADILLAC-DE VILLE | 03 C                    | 064000                | 36105002       |
|               |               |                       |                    | TOP THREADED SECTION OF BALL STUD BROKEN AT BASE OF THREADS              |                      |                         |                       |                |
| 50002         | P01436 B      | 760401                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>71 043 CHEVROLET DIVISION | EO PICK-UP MODELS    | 21 C                    | 000000                | 79605001       |
|               |               |                       |                    | BALL STUD SEPARATED FROM SOCKET AND DENTED-GREASE BOOT MISSING           |                      |                         |                       |                |
| 40005         | P01360 B      | 760330                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>69 043 CHEVROLET DIVISION | 01 CAMARO            | 03 C                    | 038000                | 01851013       |
|               |               |                       |                    | THREADED SECTION OF BALL JOINT USED TO SECURE TO LOWER A FRAME BROKE     |                      |                         |                       |                |

## PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06

PAGE 0024

SORTED BY COMPONENT, MODEL, YR

| BIN<br>NUMBER                                                         | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                     | MAKE-MODEL                              | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|-----------------------------------------------------------------------|---------------|-----------------------|--------------------|--------------------------------------------------------------------------|-----------------------------------------|-------------------------|-----------------------|----------------|
| 30017                                                                 | P01244 B      | 760203                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>69 043 CHEVROLET DIVISION | 01 CAMARO                               | 03 C                    | 079172                | 46204013       |
| THREADED PORTION OF STUD BROKE AT BASE - SOCKET HAS EXCESSIVE PLAY    |               |                       |                    |                                                                          |                                         |                         |                       |                |
| 30022                                                                 | P01282 B      | 760214                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>73 043 CHEVROLET DIVISION | 09 VEGA                                 | 03 C                    | 015213                | 50021001       |
| BALL JOINT STUD BROKEN - GREASE RETAINING BOOT SPLIT AND MISSING      |               |                       |                    |                                                                          |                                         |                         |                       |                |
|                                                                       | P00854 E      | 750919                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>00 043 CHEVROLET DIVISION | 9A CHEVROLET TRUCK AN<br>1/2 TON PICKUP | 57 C                    | 095605                | 098499007      |
| LEFT LOWER BALL JOINT MORE EXCESSIVELY                                |               |                       |                    |                                                                          |                                         |                         |                       |                |
|                                                                       | P00854 D      | 750919                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>00 043 CHEVROLET DIVISION | 9A CHEVROLET TRUCK AN<br>1/2 TON PICKUP | 57 C                    | 095605                | 098499007      |
| RIGHT LOWER BALL JOINT MORE EXCESSIVELY                               |               |                       |                    |                                                                          |                                         |                         |                       |                |
| 50003                                                                 | P01508 B      | 760427                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>68 044 OLDSMOBILE         | 01 CUTLASS                              | 03 C                    | 051200                | 23701047       |
| BALL JOINT STUD BROKE AT BASE OF THREADS                              |               |                       |                    |                                                                          |                                         |                         |                       |                |
| 50002                                                                 | P01448 B      | 760401                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>72 045 PONTIAC DIVISION   | B4 LE MANS                              | 03 C                    | 076407                | 00000000       |
| STUD BROKEN AT TOP, THREADED SECTION-MOVEMENT STIFF IN SOCKET         |               |                       |                    |                                                                          |                                         |                         |                       |                |
| 20002                                                                 | P00463 B      | 750710                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>69 155 VOLKSWAGEN         | 90 VOLKSWAGEN                           | 57 B                    | 000000                | 091605014      |
| LOWER BALL JOINT MORE EXCESSIVELY                                     |               |                       |                    |                                                                          |                                         |                         |                       |                |
| 50022                                                                 | P01601 B      | 760607                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>71 181 AB VOLVO           | 01 VOLVO                                | 44 C                    | 044000                | 06114006       |
| BALL STUD STIFF IN SOCKET - NO GREASE FITTING ON JOINT                |               |                       |                    |                                                                          |                                         |                         |                       |                |
| 50022                                                                 | P01601 C      | 760607                | 02152              | SUSPN. INDP. FT. CTRL ARM, LOWER-BALL JOINT<br>71 181 AB VOLVO           | 01 VOLVO                                | 21 C                    | 044000                | 06114008       |
| BALL STUD SEPARATED FROM SOCKET BOOT IS CRACKED BALL ON STUD CORRODED |               |                       |                    |                                                                          |                                         |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0025

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIR<br>NUMBER                                                          | PRP<br>NUMBER | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                   | MAKE-MODEL                       | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHIP<br>NUMBER |
|------------------------------------------------------------------------|---------------|------------------|--------------------|------------------------------------------------------------------------|----------------------------------|-------------------------|-----------------------|----------------|
| 30004                                                                  | P01056 B      | 751206           | 02160              | SUSPN.INDP.FT. SPINDLE-KNUCKLE,STEERING<br>67 033 MERCURY              | 04 MERCURY                       | 03 C                    | 065400                | 40503002       |
| BOLT SECTION OF SPINDLE,TO WHICH HUB ATTACHES,BROKE OFF-CROSS SECTION  |               |                  |                    |                                                                        |                                  |                         |                       |                |
| 20007                                                                  | P00831 B      | 750828           | 02160              | SUSPN.INDP.FT. SPINDLE-KNUCKLE,STEERING<br>74 043 CHEVROLET DIVISION   | F2 CHEVELLE LAGUNA               | 34 C                    | 023025                | 019300005      |
| LOOSE IN BALL JOINT                                                    |               |                  |                    |                                                                        |                                  |                         |                       |                |
| 50015                                                                  | P01558 B      | 760507           | 02170              | SUSPN.INDP.FT. -BEARING WHEEL<br>00 000 UNKNOWN                        | 00 UNKNOWN                       | 44 C                    | 000000                | 000000000      |
| FRONT WHEEL BEARINGS-VERY SLIGHT WEAR ON BEARINGS AND RACES-TAG ILLGBL |               |                  |                    |                                                                        |                                  |                         |                       |                |
|                                                                        | P00829 B      | 750827           | 02170              | SUSPN.INDP.FT. -BEARING WHEEL<br>72 021 CHRYSLER DIVISION              | A1 NEWPORT                       | 37 C                    | 040000                | 068510002      |
| WHEEL BEARING NOISY                                                    |               |                  |                    |                                                                        |                                  |                         |                       |                |
| 20007                                                                  | P00451 B      | 750722           | 02170              | SUSPN.INDP.FT. -BEARING WHEEL<br>74 031 FORD DIVISION                  | G3 FORD-LTD                      | 57 C                    | 000000                | 094133032      |
| RIGHT FRONT WHEEL BEARING WORE EXCESSIVELY                             |               |                  |                    |                                                                        |                                  |                         |                       |                |
| 20007                                                                  | P00824 B      | 750827           | 02170              | SUSPN.INDP.FT. -BEARING WHEEL<br>65 031 FORD DIVISION                  | 05 MUSTANG                       | 57 D                    | 079381                | 068510002      |
| WHEEL BEARINGS WORE EXCESSIVELY, POSSIBLY CAUSE OVER SIZE TIRES & WH   |               |                  |                    |                                                                        |                                  |                         |                       |                |
| 20007                                                                  | P00823 B      | 750827           | 02170              | SUSPN.INDP.FT. -BEARING WHEEL<br>72 032 LINCOLN                        | 01 CONTINENTAL                   | 21 C                    | 039482                | 068510002      |
| BEARING CAME APART, RACE & SEAL BROKE, VEH. ALMOST LOST WHEEL          |               |                  |                    |                                                                        |                                  |                         |                       |                |
| 20004                                                                  | P00459 B      | 750729           | 02170              | SUSPN.INDP.FT. -BEARING WHEEL<br>72 042 CADILLAC DIVISION              | B1 CADILLAC-DE VILLE             | 33 B                    | 000000                | 081003001      |
| FRONT WHEEL BEARING LOCKED-UP CAUSING POWER STEERING BELT TO BRAKE     |               |                  |                    |                                                                        |                                  |                         |                       |                |
| 30004                                                                  | P01057 B      | 751206           | 02224              | SUSPN.I BEAM,S/D,FT:U BOLT-SPRNG TO I BEA<br>66 043 CHEVROLET DIVISION | 9A CHEVROLET TRUCK AN<br>1/2 TON | 03 C                    | 000000                | 40503002       |
| U-BOLT BROKE IN 2 PLACES-CROSS SECTIONALLY AT POINT ON U-BEND          |               |                  |                    |                                                                        |                                  |                         |                       |                |

PARTS RETURN PROGRAM

76/07/06 PAGE 0026

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN NUMBER | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                      | MAKE-MODEL                               | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|------------|-------------------|------------------|--------------------|------------------------------------------------------------------------|------------------------------------------|-------------------------|-----------------------|----------------|
| 40002      | P01344 B          | 760324           | 02240              | SUSPN.I BEAM,S/D,FT: SHOCK ABSORBER<br>74 022 DODGE                    | 9A DODGE TRUCK AND VA<br>D-300           | 32 C                    | 002714                | 02140002       |
|            |                   |                  |                    | SHOCK LEAKS FLUID                                                      |                                          |                         |                       |                |
| 20005      | P00797 B          | 750813           | 02250              | SUSPN.I BEAM,S/D,FT: SPINDLE -- KNUCKLE<br>69 010 AMERICAN MOTORS      | 09 JEEP                                  | 03 C                    | 068204                | 091605014      |
|            |                   |                  |                    | RIGHT STEERING ARM BROKE                                               |                                          |                         |                       |                |
| 20005      | P00805 B          | 750814           | 02260              | SUSPN.I BEAM,S/D,FT: BEARING, WHEEL<br>00 022 DODGE                    | 9A DODGE TRUCK AND VA<br>M300 MOTOR HOME | 44 C                    | 000000                | 045406001      |
|            |                   |                  |                    | POOR PERFORMANCE OF WHEEL BEARING (FAIL PART TAG ILLEGIBLE)            |                                          |                         |                       |                |
| 50013      | P01549 B          | 760507           | 02360              | SUSPN.TWN I-BM,FT-SPINDLE-KNUCKLE STEERING<br>73 031 FORD DIVISION     | 9B F100 2DR CONV. PU<br>F-100            | 57 C                    | 027011                | 12601026       |
|            |                   |                  |                    | EXCESS WEAR ON INNER SURFACE OF METAL END BUSHING PLATE                |                                          |                         |                       |                |
| 30007      | P01097 B          | 751224           | 02400              | SUSPENSION SINGLE AXLE, REAR<br>71 031 FORD DIVISION                   | 06 PINTO                                 | 02 C                    | 060716                | 98944004       |
|            |                   |                  |                    | MOUNTING HOLE FOR SPRING ASSEMBLY BENT INWARD-WEAK STEEL               |                                          |                         |                       |                |
| 20004      | P00461 B          | 750729           | 02420              | SUSPN.SGL AXL R-CONTROL ARM<br>00 031 FORD DIVISION                    | G3 FORD-LTD                              | 03 A                    | 000000                | 078400011      |
|            |                   |                  |                    | LOWER CONTROL ARM BROKE                                                |                                          |                         |                       |                |
| 20015      | P00956 B          | 751024           | 02420              | SUSPN.SGL AXL R-CONTROL ARM<br>66 043 CHEVROLET DIVISION               | 00 CHEVROLET DIVISION                    | 03 C                    | 000000                | 60626006       |
|            |                   |                  |                    | BREAK IN CENTER OF ARM                                                 |                                          |                         |                       |                |
| 20001      | P00477 B          | 750708           | 02420              | SUSPN.SGL AXL R-CONTROL ARM<br>69 043 CHEVROLET DIVISION               | 06 CORVETTE                              | 49 B                    | 057520                | 053140005      |
|            |                   |                  |                    | LEFT REAR CONTROL ARM RUSTED AND BROKE                                 |                                          |                         |                       |                |
| 20017      | P00984 B          | 751108           | 02420              | SUSPN.SGL AXL R-CONTROL ARM<br>73 043 CHEVROLET DIVISION               | 08 MONTE CARLO                           | 09 C                    | 068785                | 23229005       |
|            |                   |                  |                    | REAR CONTROL ARM SHAFT AT AXLE HOUSING TORE OUT OF ONE SIDE OF CONTRAM |                                          |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAUL 0027

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN NUMBER | PKP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME<br>YR MANUFACTURER                                | MAKE-MODEL                  | FAULT HAZ. CODE CAT. | MILEAGE AT FAILURE | SHOP NUMBER |
|------------|------------|-----------------|-----------------|------------------------------------------------------------------|-----------------------------|----------------------|--------------------|-------------|
| 40010      | P01346 B   | 760324          | 02450           | SUSPN.SGL AXL R-SPRING, COIL&ATTACHMENTS<br>71 031 FORD DIVISION | H3 FORD-GALAXIE 500         | 03 C                 | 000000             | 36104001    |
|            |            |                 |                 | COIL SPRING BROKE IN TWO PIECES NEAR CENTER OF COILS             |                             |                      |                    |             |
|            | P00852 B   | 750919          | 02450           | SUSPN.SGL AXL R-SPRING, COIL&ATTACHMENTS<br>68 031 FORD DIVISION | 02 FALCON                   | 03 C                 | 042276             | 044310008   |
|            |            |                 |                 | CONTROL ARM RUSTED & BROKE                                       |                             |                      |                    |             |
| 20009      | P00851 B   | 750919          | 02450           | SUSPN.SGL AXL R-SPRING, COIL&ATTACHMENTS<br>73 031 FORD DIVISION | 08 TORINO                   | 03 C                 | 000000             | 023229005   |
|            |            |                 |                 | REAR COIL SPRING                                                 |                             |                      |                    |             |
| 20009      | P00838 B   | 750905          | 02450           | SUSPN.SGL AXL R-SPRING, COIL&ATTACHMENTS<br>72 033 MERCURY       | 04 MERCURY<br>STATION WAGON | 03 C                 | 048812             | 085004002   |
|            |            |                 |                 | BROKEN REAR COIL SPRING-MANUFACTURED BAD OR COLD                 |                             |                      |                    |             |
| 40010      | P01407 B   | 760331          | 02450           | SUSPN.SGL AXL R-SPRING, COIL&ATTACHMENTS<br>74 033 MERCURY       | 05 MONTEGO                  | 03 C                 | 011205             | 12601050    |
|            |            |                 |                 | COIL SPRING BROKEN AT END LIGHT LAYER OF RUST ON SPRING          |                             |                      |                    |             |
| 40010      | P01407 C   | 760331          | 02450           | SUSPN.SGL AXL R-SPRING, COIL&ATTACHMENTS<br>74 033 MERCURY       | 05 MONTEGO                  | 03 C                 | 011205             | 12601050    |
|            |            |                 |                 | COIL SPRING BROKEN AT END LIGHT LAYER OF RUST ON SPRING          |                             |                      |                    |             |
| 40010      | P01327 B   | 760320          | 02450           | SUSPN.SGL AXL R-SPRING, COIL&ATTACHMENTS<br>75 041 BUICK         | 04 LE SABRE                 | 03 C                 | 014692             | 36104001    |
|            |            |                 |                 | REAR COIL SPRING CRACKED AND BROKEN NEAR END                     |                             |                      |                    |             |
| 20015      | P00965 B   | 751030          | 02450           | SUSPN.SGL AXL R-SPRING, COIL&ATTACHMENTS<br>73 044 OLDSMOBILE    | 06 98                       | 03 C                 | 000000             | 040203001   |
|            |            |                 |                 | SPRING CRACKED                                                   |                             |                      |                    |             |
| 20013      | P00935 B   | 751024          | 02460           | SUSPN.SGL AXL R-SHOCK ABSORBER<br>00 000 UNKNOWN                 | 00 UNKNOWN                  | 03 C                 | 000000             | 60626008    |
|            |            |                 |                 | MOUNTING BRACKET BROKEN OFF SHOCK                                |                             |                      |                    |             |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0028

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,NDL YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS                                | COMPONENT NAME<br>YR MANUFACTURER                           | MAKE-MODEL         | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|---------------|--------|------------------|---------------------------------------------------|-------------------------------------------------------------|--------------------|-------------------------|-----------------------|----------------|
| 50014                                                                  | P01554        | D      | 760507           | 02460                                             | SUSPN.SGL AXL R-SHOCK ABSORBER<br>73 042 CADILLAC DIVISION  | A1 CADILLAC-CALAIS | 56 C                    | 036000                | 36108002       |
| SHOCK MOUNT BUSHINGS AT BOTH ENDS SHOW WEAR-TOP MT BENT SLIGHTLY-NO LK |               |        |                  |                                                   |                                                             |                    |                         |                       |                |
| 50014                                                                  | P01554        | E      | 760507           | 02460                                             | SUSPN.SGL AXL R-SHOCK ABSORBER<br>73 042 CADILLAC DIVISION  | A1 CADILLAC-CALAIS | 56 C                    | 036000                | 36108002       |
| SHOCK MOUNT BUSHINGS AT BOTH ENDS WORN-NO LEAKS-SHOCK TOO WEAK FOR CAR |               |        |                  |                                                   |                                                             |                    |                         |                       |                |
| 30004                                                                  | P01060        | B      | 751206           | 02460                                             | SUSPN.SGL AXL R-SHOCK ABSORBER<br>74 043 CHEVROLET DIVISION | 08 MONTE CARLO     | 57 C                    | 008307                | 094122009      |
| TAG SAYS WORN GUT-BUSHINGS SOME WEAR-NO EVIDENCE OF LEAKS OR BREAKAGE  |               |        |                  |                                                   |                                                             |                    |                         |                       |                |
| 30004                                                                  | P01061        | B      | 751206           | 02460                                             | SUSPN.SGL AXL R-SHOCK ABSORBER<br>74 043 CHEVROLET DIVISION | 08 MONTE CARLO     | 57 C                    | 008307                | 94122009       |
| BUSHINGS SOME WEAR-SHOCKS STILL RESISTANT-SHOP CLAIMS WORN OUT         |               |        |                  |                                                   |                                                             |                    |                         |                       |                |
| P01147                                                                 | B             | 751229 | 02620            | WHEELS, SINGLE<br>73 022 DODGE                    | 9A DODGE TRUCK AND VA<br>VAN                                | 08 C               | 040175                  | 98036056              |                |
| RIGHT FRONT RIM CRACKED JUST OUTSIDE OF LUG BOLTS,ON RIDGE-NO PART SEN |               |        |                  |                                                   |                                                             |                    |                         |                       |                |
| 30009                                                                  | P01073        | B      | 751223           | 02620                                             | WHEELS, SINGLE<br>67 023 PLYMOUTH                           | C4 FURY III        | 08 C                    | 101951                | 68510002       |
| WHEEL HAS 12 INCH CRACK ON INBOARD SIDE-TIRE MAY HAVE CAUSED CRACK     |               |        |                  |                                                   |                                                             |                    |                         |                       |                |
| P01335                                                                 | B             | 760324 | 02620            | WHEELS, SINGLE<br>76 042 CADILLAC DIVISION        | B1 CADILLAC-DE VILLE                                        | 03 B               | 005000                  | 63105001              |                |
| CRACK AROUND 2/3 CIRC OF WIRE WHEEL CENTER DISC&CRACK AT WELD AT 60MPH |               |        |                  |                                                   |                                                             |                    |                         |                       |                |
| P00485                                                                 | B             | 750708 | 02621            | WHEELS SNGL-RIM BASE<br>70 176 TOYOTA MOTR CO LTD | 01 TOYOTA                                                   | 08 C               | 054000                  | 093701023             |                |
| WHEEL CRACKED AT SPOKES                                                |               |        |                  |                                                   |                                                             |                    |                         |                       |                |
| 30001                                                                  | P01008        | B      | 751118           | 02622                                             | WHEELS SNGL-DISC-SPIDER<br>73 023 PLYMOUTH                  | A6 VALIANT-DUSTER  | 03 C                    | 032521                | 11204002       |
| RIM BROKE AT WELDS-CENTER PORTION BROKE AWAY FROM RIM                  |               |        |                  |                                                   |                                                             |                    |                         |                       |                |

# PARTS RETURN PROGRAM

76/07/06 PAGE 0029

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN NUMBER | PRP I<br>NUMBER D RECEIVED | DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME<br>YR MANUFACTURER                                                                                                 | MAKE-MODEL                      | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------|----------------------------|---------------|-----------------|-----------------------------------------------------------------------------------------------------------------------------------|---------------------------------|-------------------------|-----------------------|----------------|
| 30008      | P01116 B                   | 751226        | 02626           | WHEELS SNGL-CAP-COVER, HUB<br>67 043 CHEVROLET DIVISION                                                                           | E3 IMPALA                       | 08 C                    | 100000                | 01605008       |
| 20006      | P00930 B                   | 751020        | 02631           | CRACK ON INBOARD SURFACE OF WHEEL HUB-POSSIBLY DUE TO IMPACT<br>WHEELS MULTI-RIM BASE<br>70 031 FORD DIVISION                     | H3 FORD-GALAXIE 500             | 08 C                    | 056268                | 98270095       |
| 50005      | P01474 B                   | 760407        | 02637           | RIM CRACKED INNER SIDE AT RIM BASE-CRACK APPROX. 8 INCHES LONG<br>WHEELS MULTI-OTHER<br>73 W37 WHITE MOTOR CORP.                  | 02 WHITE TRUCK<br>FRT-LINER     | 03 C                    | 190000                | 65802014       |
| 40008      | P01410 B                   | 760401        | 03213           | CAST METAL 10 BOLT HUB BROKE AWAY FROM CENTER AND INTO FOUR PIECES<br>TIRES<br>00 000 UNKNOWN                                     | 00 UNKNOWN                      | 00 C                    | 000000                | 050702000      |
| 20004      | P00723 B                   | 750807        | 03213           | TIRE BRANDS WITH FREQUENT FAILURES OR CAUSING POOR HANDLING COND.<br>BRAKES HYDRAULIC-SWITCH, BRAKE LIGHT<br>69 023 PLYMOUTH      | 04 FURY                         | 03 C                    | 104000                | 63105001       |
| 30022      | P01283 B                   | 760214        | 03213           | PLASTIC HOUSING ON SWITCH CRACKED & BROKEN-1 ELEC TERMINAL BROKEN<br>BRAKES HYDRAULIC-SWITCH, BRAKE LIGHT<br>70 031 FORD DIVISION | 9A FORD TRUCK AND VAN<br>F350   | 28 C                    | 089000                | 052404002      |
| 50007      | P01493 B                   | 760414        | 03214           | BRAKE LIGHT SWITCH INOPERATIVE WHEN ACTUATED ON VEHICLE<br>BRAKES HYDRAULIC-SWITCH, BRAKE LIGHT<br>68 174 NISSAN MTR CO LTD       | 91 PICKUP TRUCK<br>PICK-UP      | 73 C                    | 071650                | 98108037       |
| 50007      | P01499 B                   | 760414        | 03214           | SHORT IN HYDRAULIC TYPE SWITCH<br>BRAKES HYDRAULIC-OTHER<br>72 031 FORD DIVISION                                                  | 98 F100 2DR CONV. PU<br>PU-F100 | 01 C                    | 002785                | 93305062       |
| 50007      | P01499 B                   | 760414        | 03214           | AIR BUBBLES ON INTERIOR WALL OF WHEEL CYLINDER-CASTING FLAW<br>BRAKES HYDRAULIC-OTHER<br>72 049 GMC                               | 9E JIMMY<br>4X4                 | 28 C                    | 033730                | 55805004       |

NO VISIBLE SIGNS OF FAILURE-POSSIBLE INTERNAL MALFUNCTION

# PARTS RETURN PROGRAM

76/07/06 PAGE 0020

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN NUMBER | PRP I NUMBER | DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                                         | YR | MAKE-MODEL                    | FAULT HAZ. CODE | HAZ. CAT. | MILEAGE AT FAILURE | SHOP NUMBER |
|------------|--------------|---------------|-----------------|------------------------------------------------------------------------|----|-------------------------------|-----------------|-----------|--------------------|-------------|
| 40001      | P01318 B     | 760320        | 03221           | BRKS-HYDRAULIC-PWR ASSIST-LINES-VACUUM<br>75 010 AMERICAN MOTORS       |    | OA PACER                      | 04              | C         | 000000             | 99027113    |
|            |              |               |                 | 5116" HOSE-DETERIORATED AT ONE END                                     |    |                               |                 |           |                    |             |
| 40002      | P01341 B     | 760324        | 03221           | BRKS-HYDRAULIC-PWR ASSIST-LINES-VACUUM<br>09 033 MERCURY               |    | E4 MERCURY-MONTEREY           | 49              | C         | 058000             | 92632025    |
|            |              |               |                 | SOME DETERIORATION INSIDE HOSE - HOSE SPLIT LENGTHWISE FOR INSPECTION  |    |                               |                 |           |                    |             |
| 20005      | P00719 B     | 750806        | 03221           | BRKS-HYDRAULIC-PWR ASSIST-LINES-VACUUM<br>71 042 CADILLAC DIVISION     |    | C1 CADILLAC-BROUGHAM          | 76              | C         | 057271             | 095207019   |
|            |              |               |                 | VACUUM HOSE COLLAPSED                                                  |    |                               |                 |           |                    |             |
| 50007      | P01491 B     | 760414        | 03223           | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>65 010 AMERICAN MOTORS        |    | A9 JEEP WAGONEER<br>JEEP      | 03              | C         | 101581             | 85004002    |
|            |              |               |                 | PLASTIC COVER ON CHECK VALVE BROKEN                                    |    |                               |                 |           |                    |             |
| 30010      | P01137 B     | 751229        | 03223           | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>69 031 FORD DIVISION          |    | G3 FORD-LTD                   | 03              | C         | 089111             | 91042007    |
|            |              |               |                 | 1/6 OF UPPER RIM OF VALVE BROKE OFF ALLOWING VALVE TO COME APART-CRACK |    |                               |                 |           |                    |             |
| 40004      | P01397 B     | 760331        | 03223           | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>67 031 FORD DIVISION          |    | H3 FORD-GALAXIE 500           | 03              | C         | 067313             | 63301003    |
|            |              |               |                 | SMALL CONNECTOR BROKEN OFF-LARGER HOSE IS INTACT, BUT HARD WITH AGE    |    |                               |                 |           |                    |             |
| 30003      | P01034 B     | 751122        | 03223           | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>69 031 FORD DIVISION          |    | 00 FORD DIVISION              | 03              | C         | 063322             | 32205026    |
|            |              |               |                 | TOP COVER BROKEN OFF, SIDE CRACKED, VALVE IS PLASTIC                   |    |                               |                 |           |                    |             |
| 30011      | P01159 B     | 760106        | 03223           | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>75 031 FORD DIVISION          |    | 9A FORD TRUCK AND VAN<br>F600 | 03              | C         | 024572             | 70130001    |
|            |              |               |                 | PLASTIC CHECK VALVE BROKE AT BASE OF THE BOWL INTO EIGHT PIECES        |    |                               |                 |           |                    |             |
|            |              |               |                 | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>00 040 GENERAL MOTORS         |    | 00 GENERAL MOTORS             | 28              | C         | 000000             | 070130001   |
|            |              |               |                 | VACUUM CHECK VALVE INOPERATIVE-POWER UNIT FAILURE                      |    |                               |                 |           |                    |             |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0031

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MILEAGE

| BIN NUMBER | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                     | MAKE-MODEL        | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------|-------------------|------------------|--------------------|--------------------------------------------------------------------|-------------------|-------------------------|-----------------------|----------------|
| 20001      | P00469 B          | 750710           | 03223              | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>72 043 CHEVROLET DIVISION | 02 CHEVELLE       | 03 B                    | 022360                | 063105001      |
| 30003      | P01036 B          | 751122           | 03223              | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>68 043 CHEVROLET DIVISION | 03 CHEVROLET      | 03 C                    | 083351                | 32205026       |
| 30003      | P01035 B          | 751122           | 03223              | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>69 044 OLDSMOBILE         | 00 OLDSMOBILE     | 03 C                    | 067800                | 32205026       |
| 30007      | P01103 B          | 751226           | 03223              | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>69 044 OLDSMOBILE         | 06 98             | 15 C                    | 047925                | 198C2003       |
| 30010      | P01136 B          | 751229           | 03223              | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>70 045 PONTIAC DIVISION   | 84 LE MANS        | 08 C                    | 000000                | 91042007       |
| 30006      | P01092 B          | 751224           | 03223              | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>67 045 PONTIAC DIVISION   | 01 FIREBIRD       | 03 C                    | 059257                | 90027012       |
| 30007      | P00807 B          | 750814           | 03224              | BRKS-HYDRAULIC-PWR ASSIST-BOOSTER<br>73 040 GENERAL MOTORS         | 00 GENERAL MOTORS | 08 C                    | 000000                | 032805010      |
| 30012      | P01225 B          | 760205           | 03224              | BRKS-HYDRAULIC-PWR ASSIST-BOOSTER<br>71 044 OLDSMOBILE             | 00 OLDSMOBILE     | 08 C                    | 055215                | 193800005      |
| 30013      | P00875 B          | 750919           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                          | 00 UNKNOWN        | 00 C                    | 000000                | 031401020      |

VACUUM CONTROL VALVE BROKE AND CAUSED PARTIAL LOSS OF SERVICE BRAKES

TOP OF VALVE W/VACUUM HOSE FITTING SEPARATED FROM BODY OF VALVE

TOP BROKEN OFF, SIDE CRACKED, VACUUM HOSE FITTING CRACKED-PLASTIC VALVE

TIP RIM SECTION BROKEN OFF-RIM HAS CRACKS ON ENTIRE CIRCUMFERENCE

POWER BRAKE CHECK VALVE RIM IS CRACKED-NUMEROUS OTHER CRACKS ON RIM

UPPER LIP OF CHECK VALVE PLASTIC APPEARS BRITTLE AND CORRODED

FLUID LEAKING BACK INTO BOOSTER UNIT CAUSING DIAPHRAGM TO SPLIT

POWER BRAKE BOOSTER SEPERATED IN HALF - NO PART SENT

FAIL PART TAG SOAKED WITH BRAKE FLUID-UNREADABLE

# PARTS RETURN PROGRAM

76/07/06 PAGE 0032

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                   | MAKE-MODEL | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|------------------------------------------------------------------------|------------|-------------------------|-----------------------|----------------|
|               | P00874        | B 750919              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 00 C                    | 000000                | 031401020      |
|               |               |                       |                    | FAIL PART TAG SOAKED WITH BRAKE FLUID-UNREADABLE                       |            |                         |                       |                |
| 20009         | P00905        | B 751008              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 00 C                    | 000000                | 19C47004       |
|               |               |                       |                    | FAIL PART TAG SOAKED WITH FLUID-UNREADABLE                             |            |                         |                       |                |
|               | P00904        | B 750808              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 00 C                    | 000000                | 063105C01      |
|               |               |                       |                    | FAIL PART TAG SOAKED WITH FLUID-UNREADABLE                             |            |                         |                       |                |
| 30012         | P01213        | B 760123              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 00 C                    | 000000                | 23513001       |
|               |               |                       |                    | SUSPECT INTERNAL LEAKAGE - MASTER CYLINDER RESERVOIRS DIRTY            |            |                         |                       |                |
| 30012         | P01164        | B 760106              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 00 A                    | 000000                | 23513001       |
|               |               |                       |                    | BARRELS VERY DIRTY-BRAKE FLUID CAUSED INK ON TAG TO RUN-NOW UNREADABLE |            |                         |                       |                |
| 30001         | P00996        | B 751114              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 28 C                    | 000000                | 55103C01       |
|               |               |                       |                    | MASTER CYLINDER CONTAMINATED W/ DIRT-NO DATA CARD RECEIVED             |            |                         |                       |                |
| 30001         | P00995        | B 751114              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 28 C                    | 000000                | 55103001       |
|               |               |                       |                    | MASTER CYLINDER CONTAMINATED W/ DIRT-COVER GASKET TORN-NO DATA CARD    |            |                         |                       |                |
| 30003         | P01037        | B 751122              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 13 C                    | 000000                | 00000000       |
|               |               |                       |                    | DIRT EVIDENT IN DUAL MSTR CYL RESERVOIRS AND AT LINE CONNECTION        |            |                         |                       |                |
| 50009         | P01519        | B 760419              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 28 C                    | 000000                | 51106004       |
|               |               |                       |                    | NO VISIBLE DEFECTS-POSSIBLE INTERNAL DEFECT                            |            |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0033

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                   | MAKE-MODEL | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|------------------------------------------------------------------------|------------|-------------------------|-----------------------|----------------|
| 50015         | P01555 B      | 760507                | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 28 C                    | 000000                | 00000000       |
|               |               |                       |                    | BRAKE MASTER CYL-SUSPECT INTERNAL MALFUNCTION-OUTSIDE NORM-TAG ILLEGBL |            |                         |                       |                |
| 50015         | P01557 B      | 760507                | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 28 C                    | 000000                | 00000000       |
|               |               |                       |                    | BRAKE MASTER CYL-SUSPECT INTERNAL MALFUNCTION-OUTSIDE NORM-TAG ILLEGBL |            |                         |                       |                |
| 50015         | P01556 B      | 760507                | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 000 UNKNOWN                              | 00 UNKNOWN | 28 C                    | 000000                | 00000000       |
|               |               |                       |                    | BRAKE MASTER CYL-SUSPECT INTERNAL MALFUNCTION-OUTSIDE NORM-TAG ILLEGBL |            |                         |                       |                |
| 50005         | P01473 B      | 760407                | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>69 010 AMERICAN MOTORS                      | A6 AMX     | 19 C                    | 083894                | 63105001       |
|               |               |                       |                    | PROBABLE INTERNAL MALFUNCTION-RESERVOIR DIRTY-POSSIBLE FLUID BY-PASS   |            |                         |                       |                |
| 30024         | P01270 B      | 760207                | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 010 AMERICAN MOTORS                      | 05 HORNET  | 28 C                    | 045953                | 51106004       |
|               |               |                       |                    | NO VISIBLE DEFECTS - SUSPECT INTERNAL LEAKAGE                          |            |                         |                       |                |
| 50022         | P01609 B      | 760601                | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>72 010 AMERICAN MOTORS                      | 05 HORNET  | 19 C                    | 036020                | 19047004       |
|               |               |                       |                    | EXTERNAL APPEAR NORM REAR CUP IS EXPANDED RESERVOIR APPEARS CLEAN      |            |                         |                       |                |
| 30016         | P01229 B      | 760203                | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>74 010 AMERICAN MOTORS                      | 05 HORNET  | 28 C                    | 000000                | 63105001       |
|               |               |                       |                    | PROBABLE INTERNAL LEAKAGE - NO SPECIFICS                               |            |                         |                       |                |
| 40007         | P01402 B      | 760331                | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>71 010 AMERICAN MOTORS                      | 06 JAVELIN | 28 C                    | 044496                | 63105001       |
|               |               |                       |                    | PROBABLE INTERNAL MALFUNCTION-RESERVOIR DIRTY-CONTAMINATED-NO VISIBLE  |            |                         |                       |                |
| 50033         | P01459 B      | 760406                | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>64 021 CHRYSLER DIVISION                    | A1 NEWPORT | 49 C                    | 089000                | 68510002       |
|               |               |                       |                    | WALLS OF CYLINDER AND RESERVOIR LIGHTLY CORRODED                       |            |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0034

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                     | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>MANUFACTURER                   | YR | MAKE-MODEL                  | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|-------------------------------------------------------------------|---------------|-----------------------|--------------------|-----------------------------------------------------|----|-----------------------------|-------------------------|-----------------------|----------------|
| 30005                                                             | P01065        | B 751206              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>67 021 CHRYSLER DIVISION |    | A1 NEWPORT                  | 28 C                    | 087064                | 19020002       |
| POSSIBLE INTERNAL LEAKAGE                                         |               |                       |                    |                                                     |    |                             |                         |                       |                |
| 30003                                                             | P01040        | B 751122              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>66 021 CHRYSLER DIVISION |    | A1 NEWPORT                  | 28 C                    | 042598                | 55103001       |
| EXTERIOR OF DUAL MSTR CYL APPEARS OK-INTERNAL PROBLEM             |               |                       |                    |                                                     |    |                             |                         |                       |                |
| 40006                                                             | P01394        | B 760331              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>69 021 CHRYSLER DIVISION |    | D1 300                      | 44 C                    | 061930                | 63105001       |
| POSS INTERNAL LEAKAGE BTWN CYL WALL & PISTONS NO VISABLE DEFECTS  |               |                       |                    |                                                     |    |                             |                         |                       |                |
| 30007                                                             | P01107        | B 751226              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 022 DODGE             |    | A5 DART-CUSTOM <sup>8</sup> | 00 A                    | 000000                | 000000000      |
| BARREL IS EXTREMELY DIRTY-RUBBER BOOT ON SHAFT RIPPED-MANUAL BRKS |               |                       |                    |                                                     |    |                             |                         |                       |                |
| 50023                                                             | P01621        | B 760607              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 022 DODGE             |    | A6 MONACO-POLARA            | 28 C                    | 072811                | 51106004       |
| EXTERNAL APPEARANCE NORMAL SUSPECT INTERNAL MALFUNCTION           |               |                       |                    |                                                     |    |                             |                         |                       |                |
| 30026                                                             | P01313        | B 760206              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>65 022 DODGE             |    | 05 DART                     | 32 C                    | 076490                | 90027012       |
| SHOP CLAIMS SECONDARY CUP LEAKING                                 |               |                       |                    |                                                     |    |                             |                         |                       |                |
| 30023                                                             | P01312        | B 760206              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>66 022 DODGE             |    | 05 DART                     | 28 C                    | 047581                | 90027012       |
| SUSPECT INTERNAL LEAKAGE                                          |               |                       |                    |                                                     |    |                             |                         |                       |                |
| 30017                                                             | P01243        | B 760203              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>69 022 DODGE             |    | 05 DART                     | 49 C                    | 109987                | 46204013       |
| INNER WALL OF CYLINDER RUSTED AND GROOVED                         |               |                       |                    |                                                     |    |                             |                         |                       |                |
| 20011                                                             | P00901        | B 751008              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 022 DODGE             |    | 05 DART                     | 19 C                    | 029593                | 66607011       |
| BRAKES FADE, NO PEDAL WHEN PRESSURE IS APPLIED                    |               |                       |                    |                                                     |    |                             |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0035

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN NUMBER | PRP I NUMBER | DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                                         | YR | MAKE-MODEL         | FAULT HAZ. CODE | HAZ. CAT. | MILEAGE AT FAILURE | SHOP NUMBER |
|------------|--------------|---------------|-----------------|------------------------------------------------------------------------|----|--------------------|-----------------|-----------|--------------------|-------------|
| 30014      | P01316 B     | 760225        | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>72 022 DODGE                                |    | 05 DART            | 44              | C         | 044000             | 47710001    |
|            |              |               |                 | POSS INTERNAL LEAKAGE - TAG NOT READABLE                               |    |                    |                 |           |                    |             |
| 1          | P01139 B     | 751229        | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>71 022 DODGE                                |    | 06 MONACO          | 19              | C         | 044471             | 30501001    |
|            |              |               |                 | CYLINDER BARKEL HAS A LITTLE RUST, MUCH DIRT, PRIMARY CUPS FAILED      |    |                    |                 |           |                    |             |
| 30010      | P01132 B     | 751228        | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>70 023 PLYMOUTH                             |    | A6 VALIANT-DUSTER  | 32              | C         | 084598             | 90027012    |
|            |              |               |                 | EXTERIOR OF MSTR CYLINDER OK-POSSIBLE INTERNAL LEAK OR PRIMARY CUP LEA |    |                    |                 |           |                    |             |
| 50002      | P01444 B     | 760401        | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>72 023 PLYMOUTH                             |    | A6 VALIANT-DUSTER  | 32              | C         | 035737             | 23513001    |
|            |              |               |                 | INTERNAL LEAKAGE OF SECONDARY SEAL RESULTS IN BRAKE LOSS               |    |                    |                 |           |                    |             |
| 40008      | P01411 B     | 760401        | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>73 023 PLYMOUTH                             |    | A6 VALIANT-DUSTER  | 28              | C         | 053497             | 23513001    |
|            |              |               |                 | BRK MSTR CYL RESERVOIR DIRTY-NO EXTERNAL-DAMAGE-POSS INTERNAL MALFUNCT |    |                    |                 |           |                    |             |
| 40006      | P01392 B     | 760331        | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>71 023 PLYMOUTH                             |    | C5 ROAD RUNNER     | 49              | C         | 000000             | 29611001    |
|            |              |               |                 | SOME CORROSION IS PRESENT ON CYLINDER WALL OF MASTER CYLINDER          |    |                    |                 |           |                    |             |
| 40006      | P01386 B     | 760330        | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>72 023 PLYMOUTH                             |    | H4 FURY GRAN COUPE | 32              | C         | 057641             | 19802003    |
|            |              |               |                 | NO VISIBLE DEFECTS, POSS INTERNAL BYPASS                               |    |                    |                 |           |                    |             |
| 30006      | P01082 B     | 751224        | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>69 023 PLYMOUTH                             |    | 04 FURY            | 49              | C         | 059522             | 30501001    |
|            |              |               |                 | SOME RUST SPOTS ON INTERIOR OF BARREL-FLUID REMAINING ON SIDES DIRTY   |    |                    |                 |           |                    |             |
| 30026      | P01307 B     | 760306        | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>69 023 PLYMOUTH                             |    | 04 FURY            | 28              | C         | 017713             | 79605020    |
|            |              |               |                 | INTERNAL LEAK, RUSTED                                                  |    |                    |                 |           |                    |             |

# PARTS RETURN PROGRAM

76/07/06 PAGE 0036

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                          | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER               | MAKE-MODEL                   | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|-------------------|------------------|--------------------|-------------------------------------------------|------------------------------|-------------------------|-----------------------|----------------|
| 50023                                                                  | P01612 B          | 760601           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>71 023 PLYMOUTH      | 04 FURY                      | 28 C                    | 068520                | 54911007       |
| NG VISIBLE DEFECTS POSS INTERNAL MALFUNCTION                           |                   |                  |                    |                                                 |                              |                         |                       |                |
| 30003                                                                  | P01027 B          | 751119           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>72 031 FORD DIVISION | A0 ECONOLINE SERIES<br>E-300 | 32 C                    | 000000                | 29611001       |
| DIRT IN BOTTOM OF MSTR CYL-BOOT LIP CRACKED-SECTION MISSING            |                   |                  |                    |                                                 |                              |                         |                       |                |
| 50006                                                                  | P01489 B          | 760414           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>75 031 FORD DIVISION | B6 PINTO WAGON               | 00 C                    | 020477                | 23513001       |
| NO VISIBLE DEFECTS - POSSIBLE INTERNAL MALFUNCTION                     |                   |                  |                    |                                                 |                              |                         |                       |                |
| 30014                                                                  | P01315 B          | 760225           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>73 031 FORD DIVISION | D3 FORD-CUSTOM               | 44 C                    | 104386                | 47710001       |
| POSS INTERNAL LEAKAGE - TAG NOT READABLE                               |                   |                  |                    |                                                 |                              |                         |                       |                |
| 30003                                                                  | P01028 B          | 751119           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 031 FORD DIVISION | G3 FORD-LTD                  | 28 C                    | 000000                | 29611001       |
| FILM IN BOTTOM OF MSTR CYL RESERVOIR-1 PISTON CUP TORN                 |                   |                  |                    |                                                 |                              |                         |                       |                |
| 30014                                                                  | P01205 B          | 760125           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>71 031 FORD DIVISION | G3 FORD-LTD                  | 32 C                    | 059623                | 23513001       |
| SECONDARY SEAL LEAKING - NO BRAKES - MASTER CYLINDER RESEVOIR DIRTY    |                   |                  |                    |                                                 |                              |                         |                       |                |
| 30011                                                                  | P01221 B          | 760123           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>71 031 FORD DIVISION | G3 FORD-LTD                  | 28 C                    | 064206                | 63105001       |
| NO BREAKS - SUSPECT INTERNAL LEAKAGE                                   |                   |                  |                    |                                                 |                              |                         |                       |                |
| 30014                                                                  | P01314 B          | 760225           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 031 FORD DIVISION | 00 FORD DIVISION             | 44 C                    | 000000                | 47710001       |
| POSS INTERNAL LEAKAGE TAG NOT READABLE                                 |                   |                  |                    |                                                 |                              |                         |                       |                |
| 30003                                                                  | P01039 B          | 751122           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>72 031 FORD DIVISION | 00 FORD DIVISION             | 28 C                    | 000000                | 55103001       |
| DIRT IN DUAL MSTR CYL RESERVOIR-BOOT CRACKED-POSSIBLE INTERNAL PROBLEM |                   |                  |                    |                                                 |                              |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0037

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN NUMBER                                                            | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER               | MAKE-MODEL  | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|-----------------------------------------------------------------------|-------------------|------------------|--------------------|-------------------------------------------------|-------------|-------------------------|-----------------------|----------------|
| 20017                                                                 | P00993 B          | 751114           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>69 031 FORD DIVISION | 01 FAIRLANE | 28 C                    | 050770                | 30501001       |
| MASTER CYLINDER APPEARS DIRTY, CONTAMINATED WITH SOME RUST            |                   |                  |                    |                                                 |             |                         |                       |                |
| 30016                                                                 | P01228 B          | 760203           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>69 031 FORD DIVISION | 01 FAIRLANE | 28 C                    | 052765                | 63105001       |
| PROBABLE INTERNAL LEAKAGE - NO SPECIFICS                              |                   |                  |                    |                                                 |             |                         |                       |                |
| 30016                                                                 | P01235 B          | 760203           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 031 FORD DIVISION | 04 MAVERICK | 28 C                    | 080517                | 00000000       |
| PISTON CYLINDER WALL ROUGH AND FLUID DIRTY - SEALS AND CASING INTACT  |                   |                  |                    |                                                 |             |                         |                       |                |
| 20002                                                                 | P00484 B          | 750708           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 031 FORD DIVISION | 04 MAVERICK | 44 C                    | 026392                | 090301029      |
| MASTER CYL.-CYL. TO CYL. BY PASS NOT OPERATING PROPERLY               |                   |                  |                    |                                                 |             |                         |                       |                |
| 50021                                                                 | P01595 B          | 760607           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 031 FORD DIVISION | 04 MAVERICK | 28 C                    | 024256                | 14607007       |
| EXTERNAL APPEARANCE NORMAL SUSPECT INT MALFUNCTION-REAR BRAKES SEIZED |                   |                  |                    |                                                 |             |                         |                       |                |
| 30013                                                                 | P01211 B          | 760123           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>71 031 FORD DIVISION | 04 MAVERICK | 33 C                    | 034320                | 14607007       |
| BRAKES LOCKED PEDAL GOES DOWN WHILE HOLDING PRESSURE                  |                   |                  |                    |                                                 |             |                         |                       |                |
| 30014                                                                 | P01204 B          | 760123           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>72 031 FORD DIVISION | 04 MAVERICK | 44 C                    | 031166                | 23513001       |
| PEDAL BLEEDS DOWN AT STOP - POSSIBLE INTERNAL LEAKAGE                 |                   |                  |                    |                                                 |             |                         |                       |                |
| 30004                                                                 | P01045 B          | 751122           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>72 031 FORD DIVISION | 04 MAVERICK | 28 C                    | 055493                | 19020002       |
| DUAL MSTR CYL HAS DIRT ON EXTERIOR, RESERVOIRS, LINE CONNECTIONS      |                   |                  |                    |                                                 |             |                         |                       |                |
| 30006                                                                 | P01088 B          | 751224           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 031 FORD DIVISION | 05 MUSTANG  | 76 C                    | 080784                | 90027012       |
| PRIMARY CUP CAUSED LOSS OF FLUID, PRESSURE                            |                   |                  |                    |                                                 |             |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0038

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                         | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>MANUFACTURER               | MAKE-MODEL                      | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|-----------------------------------------------------------------------|---------------|-----------------------|--------------------|-------------------------------------------------|---------------------------------|-------------------------|-----------------------|----------------|
| 50003                                                                 | P01463        | B 760406              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 031 FORD DIVISION | 05 MUSTANG                      | 49 C                    | 052011                | 68510002       |
| RUST IN RESERVOIR AND CYLINDER-LOST ALL PRESSURE                      |               |                       |                    |                                                 |                                 |                         |                       |                |
| 30014                                                                 | P01206        | B 760123              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>69 031 FORD DIVISION | 08 TORINO                       | 44 C                    | 023846                | 000000000      |
| BRAKE BLEEDS DOWN - SUSPECT INTERNAL LEAKAGE                          |               |                       |                    |                                                 |                                 |                         |                       |                |
| 50021                                                                 | P01593        | B 760607              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 031 FORD DIVISION | 08 TORINO                       | 28 C                    | 069992                | 29611001       |
| RIDGES WORN IN CYL SOME CORROSION, POSS LEAKAGE PAST CUPS CAUSED FAIL |               |                       |                    |                                                 |                                 |                         |                       |                |
| 50014                                                                 | P01551        | B 760507              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>72 031 FORD DIVISION | 08 TORINO                       | 49 C                    | 038487                | 29611001       |
| SLIGHT CORROSION ON CYL WALLS-FLUID APPEARS CONTAMINATED-RUST COLORED |               |                       |                    |                                                 |                                 |                         |                       |                |
| 30008                                                                 | P01119        | B 751226              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>68 031 FORD DIVISION | 9A FORD TRUCK AND VAN<br>PICKUP | 00 C                    | 080000                | 98036056       |
| SECOND MASTER CYLINDER TO FAIL-BARRELS VERY DIRTY                     |               |                       |                    |                                                 |                                 |                         |                       |                |
| 30024                                                                 | P01264        | B 760207              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>71 031 FORD DIVISION | 9A FORD TRUCK AND VAN<br>TRUCK  | 28 C                    | 018600                | 23513001       |
| FLUID DIRTY - SUSPECT INTERNAL LEAKAGE - NO VISIBLE DEFECTS           |               |                       |                    |                                                 |                                 |                         |                       |                |
| 20017                                                                 | P00992        | B 751114              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>73 031 FORD DIVISION | 9A FORD TRUCK AND VAN<br>F350   | 28 C                    | 022234                | 30501001       |
| INTERNAL DAMAGE OR CONTAMINATION TO PORTS OR CUPS-SEALS               |               |                       |                    |                                                 |                                 |                         |                       |                |
| 30005                                                                 | P01075        | B 751224              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>72 031 FORD DIVISION | 98 F100 2DR CONV. PU<br>F100    | 32 C                    | 042672                | 55103001       |
| MSTR CYLINDER LEAKS THRU COVER-RUBBER BOOT ON CYL SHAFT RIPPED        |               |                       |                    |                                                 |                                 |                         |                       |                |
| 50016                                                                 | P01564        | B 760512              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>73 032 LINCOLN       | A2 MARK IV                      | 28 C                    | 052799                | 90027012       |
| APPEARS NORMAL-SUSPECT INTERNAL MALFUNCTION (CUP LEAKAGE)             |               |                       |                    |                                                 |                                 |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0039

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN NUMBER                                                               | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT YR | COMPONENT NAME MANUFACTURER       | MAKE-MODEL          | FAULT HAZ. CODE CAT. | MILEAGE AT FAILURE | SHOP NUMBER |
|--------------------------------------------------------------------------|------------|-----------------|-----------------|--------------|-----------------------------------|---------------------|----------------------|--------------------|-------------|
| 30007                                                                    | P01110 B   | 751226          | 03230           | BRKS.        | HYDRAULIC-MSTR CYL 68 032 LINCOLN | 01 CONTINENTAL      | 44 C                 | 040910             | 19020002    |
| OWNER COMPLAINS NO BRAKES ON LIGHT PRESSURE-BARREL IS DIRTY              |            |                 |                 |              |                                   |                     |                      |                    |             |
| 30012                                                                    | P01163 B   | 760106          | 03230           | BRKS.        | HYDRAULIC-MSTR CYL 70 033 MERCURY | C4 MERCURY-MARQUIS  | 19 A                 | 043993             | 023513001   |
| FLUID IN BARRELS AND BARRELS THEMSELVES CLEAN-NO RUST-POSS.CUP FAILURE   |            |                 |                 |              |                                   |                     |                      |                    |             |
| 30004                                                                    | P01046 B   | 751122          | 03230           | BRKS.        | HYDRAULIC-MSTR CYL 73 033 MERCURY | C4 MERCURY-MARQUIS  | 28 C                 | 083013             | 70601002    |
| DUAL MSTR CYL-DIRT AT LINE CONNECTIONS-INTERNAL MALFUNCTION              |            |                 |                 |              |                                   |                     |                      |                    |             |
| 20017                                                                    | P00994 B   | 751114          | 03230           | BRKS.        | HYDRAULIC-MSTR CYL 67 033 MERCURY | E4 MERCURY-MONTEREY | 28 C                 | 023468             | 63105001    |
| MASTER CYLINDER CONTAMINATED W/ DIRT                                     |            |                 |                 |              |                                   |                     |                      |                    |             |
| 30006                                                                    | P01089 B   | 751224          | 03230           | BRKS.        | HYDRAULIC-MSTR CYL 67 033 MERCURY | F4 MERCURY-PARKLANE | 32 C                 | 096001             | 90027012    |
| MSTR CYLINDER HAS BLACK DEPOSITS IN BARREL-NO TESTS ON INTERNAL LEAK     |            |                 |                 |              |                                   |                     |                      |                    |             |
| 30010                                                                    | P01125 B   | 751226          | 03230           | BRKS.        | HYDRAULIC-MSTR CYL 72 033 MERCURY | 01 CAPRI            | 19 C                 | 048261             | 63015001    |
| NO BRAKES,BARRELS RELATIVELY CLEAN,POSSIBLE LEAK FROM PLASTIC BARRELS    |            |                 |                 |              |                                   |                     |                      |                    |             |
| 50016                                                                    | P01566 B   | 760512          | 03230           | BRKS.        | HYDRAULIC-MSTR CYL 67 033 MERCURY | 03 COUGAR           | 28 C                 | 060445             | 90027012    |
| NORMAL APPEARANCE - SUSPECT INTERNAL MALFUNCTION (CUP LEAKAGE)           |            |                 |                 |              |                                   |                     |                      |                    |             |
| 40008                                                                    | P01409 B   | 760401          | 03230           | BRKS.        | HYDRAULIC-MSTR CYL 72 033 MERCURY | 03 COUGAR           | 28 C                 | 038469             | 63105001    |
| NO EXTERNAL DEFECTS VISIBLE-RESERVOIR DIRTY-SUSPECT INTERNAL MALFUNCTION |            |                 |                 |              |                                   |                     |                      |                    |             |
| 3003                                                                     | P01029 B   | 751119          | 03230           | BRKS.        | HYDRAULIC-MSTR CYL 68 033 MERCURY | 04 MERCURY          | 49 C                 | 086031             | 29611001    |
| INTERNAL CORROSION                                                       |            |                 |                 |              |                                   |                     |                      |                    |             |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0040

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                         | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                 | MAKE-MODEL         | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|-----------------------------------------------------------------------|---------------|-----------------------|--------------------|------------------------------------------------------|--------------------|-------------------------|-----------------------|----------------|
| 30028                                                                 | P01311        | C 760225              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>71 033 MERCURY            | 05 MONTEGO         | 32 C                    | 079000                | 90027012       |
| NO VISIBLE DEFECT SUSPECT INTERNAL LEAKAGE                            |               |                       |                    |                                                      |                    |                         |                       |                |
| 50023                                                                 | P01619        | B 760607              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>67 041 BUICK              | 04 LE SABRE        | 28 C                    | 067306                | 51106004       |
| APPEARANCE IS NORMAL SUSPECT INTERNAL MALFUNCTION                     |               |                       |                    |                                                      |                    |                         |                       |                |
| 20017                                                                 | P00978        | B 751108              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>74 043 CHEVROLET DIVISION | A2 CHEVELLE-MALIBU | 07 C                    | 025372                | 14607007       |
| BROKEN PISTON LOCK RING-POSSIBLE CONTAMINATION OF METAL IN MASTER CYL |               |                       |                    |                                                      |                    |                         |                       |                |
| 30011                                                                 | P01153        | B 751229              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>73 043 CHEVROLET DIVISION | A9 VEGA NOTCHBACK  | 00 C                    | 008202                | 19020028       |
| DENT IN LIP OF MSTR CYL, BARRELS CLEAN, FLOAT UNKNOWN-INTERNAL LEAK?  |               |                       |                    |                                                      |                    |                         |                       |                |
| 50006                                                                 | P01488        | B 760413              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>72 043 CHEVROLET DIVISION | C0 BLAZER          | 32 C                    | 031700                | 55802006       |
| SHOP CLAIMS BLOWN PRIMARY SEAL-LEAKING                                |               |                       |                    |                                                      |                    |                         |                       |                |
| 30003                                                                 | P01041        | B 751122              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>66 043 CHEVROLET DIVISION | C4 NOVA            | 28 C                    | 000000                | 55103001       |
| EXTERIOR OK INTERNAL MALFUNCTION                                      |               |                       |                    |                                                      |                    |                         |                       |                |
| 50016                                                                 | P01565        | B 760512              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 043 CHEVROLET DIVISION | C4 NOVA            | 28 C                    | 038995                | 90027012       |
| EXPANSION CUPS ARE EXTENDED INTO RESERVOIR-POSSIBLE INTERNAL LEAKAGE  |               |                       |                    |                                                      |                    |                         |                       |                |
| 50014                                                                 | P01552        | B 760507              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>73 043 CHEVROLET DIVISION | D3 CAPRICE         | 32 C                    | 031676                | 63105001       |
| EXTERNAL AND RESERVOIR-MASTER CYL APPEARS NORM-POSS INTERNAL LEAKAGE  |               |                       |                    |                                                      |                    |                         |                       |                |
| 50008                                                                 | P01503        | B 760421              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>68 043 CHEVROLET DIVISION | E3 IMPALA          | 28 C                    | 020714                | 63105001       |
| NO VISIBLE SIGNS OF FAILURE - POSSIBLE INTERNAL MALFUNCTION           |               |                       |                    |                                                      |                    |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0041

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                  | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                 | MAKE-MODEL                   | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMER |
|----------------------------------------------------------------|---------------|-----------------------|--------------------|------------------------------------------------------|------------------------------|-------------------------|-----------------------|---------------|
| 30003                                                          | P01031        | B 751122              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>70 043 CHEVROLET DIVISION | E3 IMPALA                    | 49 C                    | 071674                | 46204013      |
| RUST ON CYLINDER WALL OF MASTER CYL-SLIGHT PITTING OF WALL     |               |                       |                    |                                                      |                              |                         |                       |               |
| 50009                                                          | P01518        | B 760419              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>73 043 CHEVROLET DIVISION | E3 IMPALA                    | 28 C                    | 000000                | 51106004      |
| NO VISIBLE DEFECTS-POSSIBLE INTERNAL MALFUNCTION               |               |                       |                    |                                                      |                              |                         |                       |               |
| 30012                                                          | P01212        | B 760123              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>73 043 CHEVROLET DIVISION | H3 CAPRICE EST WGN           | 32 C                    | 026154                | 23513001      |
| LEAKING FLUID IN POWER BOOSTER - SUSPECT INTERNAL LEAKAGE      |               |                       |                    |                                                      |                              |                         |                       |               |
| 30024                                                          | P01263        | B 760207              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 043 CHEVROLET DIVISION | 01 CAMARO                    | 28 C                    | 028079                | 23513001      |
| SUSPECT INTERNAL LEAKAGE - NO VISIBLE DEFECTS                  |               |                       |                    |                                                      |                              |                         |                       |               |
| 30001                                                          | P01005        | B 751118              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>00 043 CHEVROLET DIVISION | 02 CHEVELLE                  | 28 C                    | 030597                | 19047004      |
| DUAL MASTER CYLINDER-FRONT CHAMBER GASKET CUP COLLAPSED ON TOP |               |                       |                    |                                                      |                              |                         |                       |               |
| 30003                                                          | P01042        | B 751122              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>66 043 CHEVROLET DIVISION | 03 CHEVROLET                 | 28 C                    | 000000                | 55103001      |
| EXTERIOR OK INTERNAL MALFUNCTION                               |               |                       |                    |                                                      |                              |                         |                       |               |
| 20013                                                          | P00918        | B 751020              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>67 043 CHEVROLET DIVISION | 03 CHEVROLET                 | 49 C                    | 086267                | 29611001      |
| MASTER CYLINDER CORRODED-BRAKES INOPERATIVE                    |               |                       |                    |                                                      |                              |                         |                       |               |
| 50006                                                          | P01484        | B 760412              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>75 043 CHEVROLET DIVISION | 03 CHEVROLET                 | 32 C                    | 019326                | 91605014      |
| SHOP CLAIMS LOSS OF FLUID-PROBABLE INTERNAL MALFUNCTION        |               |                       |                    |                                                      |                              |                         |                       |               |
| 30010                                                          | P01148        | B 751229              | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>67 043 CHEVROLET DIVISION | 9A CHEVROLET TRUCK AN<br>C20 | 32 C                    | 000000                | 55103001      |
| BARRELS VERY DIRTY-SHOP CLAIMS INTERNAL LEAK                   |               |                       |                    |                                                      |                              |                         |                       |               |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0042

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                         | MAKE-MODEL            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|--------|------------------|--------------------|------------------------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 30001         | P01000        | B      | 751114           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>65 044 OLDSMOBILE                           | 00 OLDSMOBILE         | 28 C                    | 000000                | 19802003       |
|               |               |        |                  |                    | MASTER CYLINDER EXTERNALLY RUSTED-FLUID DIRTY                          |                       |                         |                       |                |
| 30018         | P01250        | C      | 760203           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>73 044 OLDSMOBILE                           | 00 OLDSMOBILE         | 32 C                    | 026729                | 63103004       |
|               |               |        |                  |                    | LEAKS AT REAR - NO SPECIFICS FROM SHOP                                 |                       |                         |                       |                |
| 40006         | P01384        | B      | 760330           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>72 044 OLDSMOBILE                           | 02 DELTA 88           | 32 C                    | 051994                | 23513001       |
|               |               |        |                  |                    | NO VISABLE DEFECT POSS INTERNAL BYPASS                                 |                       |                         |                       |                |
| 50002         | P01445        | B      | 760401           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>69 044 OLDSMOBILE                           | 06 98                 | 44 C                    | 031697                | 63105001       |
|               |               |        |                  |                    | INTERNAL MALFUNCTION-PEDAL FADES-NOT SPECIFIC                          |                       |                         |                       |                |
| 50007         | P01520        | B      | 760427           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>71 044 OLDSMOBILE                           | 06 98                 | 07 C                    | 042376                | 63105001       |
|               |               |        |                  |                    | MASTER CYLINDER RESERVOIR CONTAMINATED-NO OTHER SIGN OF FAILURE        |                       |                         |                       |                |
| 30018         | P01249        | B      | 760203           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>71 045 PONTIAC DIVISION                     | A3 BONNEVILLE         | 28 C                    | 083974                | 63105001       |
|               |               |        |                  |                    | SUSPECT INTERNAL LEAKAGE - COVER GASKET DIAPHRAM DISTORTED             |                       |                         |                       |                |
| 30003         | P01032        | B      | 751122           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>73 045 PONTIAC DIVISION                     | 84 LE MANS            | 28 C                    | 079030                | 23462032       |
|               |               |        |                  |                    | INTERNAL MALFUNCTION-CASING ALL RIGHT, FLUID DOES NOT APPEAR DIRTY     |                       |                         |                       |                |
|               | P01291        | B      | 760214           | 03230              | BRKS-HYDRAULIC-MSTR CYL<br>73 045 PONTIAC DIVISION                     | 02 GRAND PRIX         | 32 C                    | 032806                | 75701051       |
|               |               |        |                  |                    | LOSING BRAKE FLUID                                                     |                       |                         |                       |                |
| 30011         | P01155        | B      | 760106           | 03231              | BRKS-HYDRAULIC-MSTR CYL-COVER<br>74 042 CADILLAC DIVISION              | A2 FLEETWOOD-ELDORADO | 32 C                    | 000000                | 085012004      |
|               |               |        |                  |                    | MASTER CYLINDER COVER WOULD NOT SEAL-COVER NOT WARPED OR BENT-LOOKS OK |                       |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0043

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER                                                      | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                                   | MAKE-MODEL           | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|--------------------------------------------------------------------|---------------|-----------------------|--------------------|----------------------------------------------------------------------------------------|----------------------|-------------------------|-----------------------|----------------|
| 20003                                                              | P00825 B      | 750827                | 03232              | BRKS-HYDRAULIC-MSTR CYL-HOUSING<br>70 031 FORD DIVISION                                | 02 FALCON            | 49 C                    | 068631                | 063510002      |
| MOISTURE ACCUMULATION IN MASTER CYLINDER ERODED SEALING SURFACES   |               |                       |                    |                                                                                        |                      |                         |                       |                |
| 20015                                                              | P00961 B      | 751030                | 03233              | BRKS-HYDRAULIC-MSTR CYL-PISTONS-CUPS-SPRN<br>70 031 FORD DIVISION                      | 02 FALCON            | 28 C                    | 054893                | 030501001      |
| WASHERS & CUPS FAILED TO PRESSURE BOTH SIDES OF BRAKES             |               |                       |                    |                                                                                        |                      |                         |                       |                |
| 30025                                                              | P01298 B      | 760229                | 03234              | BRKS-HYDRAULIC-MSTR CYL-OTHER<br>70 031 FORD DIVISION                                  | 04 MAVERICK          | 28 C                    | 034710                | 14607007       |
| RESEVOIRS VERY DIRTY CUPS PART COLLAPSED POSS INTERNAL MALFUNCTION |               |                       |                    |                                                                                        |                      |                         |                       |                |
| 30006                                                              | P01080 B      | 751224                | 03234              | BRKS-HYDRAULIC-MSTR CYL-OTHER<br>72 122 BRITISH LEYLAND MOTOR CO A4 MG-MGB             |                      | 08 C                    | 021239                | 67501001       |
| SMALL RUBBER SEALS ON MSTR CYLINDER HAD SMALL SPLITS IN THEM       |               |                       |                    |                                                                                        |                      |                         |                       |                |
| 50019                                                              | P01536 B      | 760607                | 03240              | BRKS-HYDRAULIC-LINES,FITTINGS,<br>65 032 LINCOLN                                       | 01 CONTINENTAL       | 28 C                    | 014869                | 92703036       |
| INTERNAL MALFUNCTION SUSPECTED, CAUSED COMPLETE BRAKE FAILURE      |               |                       |                    |                                                                                        |                      |                         |                       |                |
| 40001                                                              | P01321 B      | 760320                | 03241              | BRKS-HYDRAULIC-LINES,METALLIC<br>70 110 INTERNATIONAL HARVESTER 12 SCOUT               |                      | 49 C                    | 069476                | 61108013       |
| STEEL LINES SEVERELY RUSTED                                        |               |                       |                    |                                                                                        |                      |                         |                       |                |
|                                                                    | P01461 B      | 760406                | 03241              | BRKS-HYDRAULIC-LINES,METALLIC<br>73 W57 WINNEBAGO INDUSTRIES, IN 00 WINNEBAGO INDUSTRI |                      | 06 C                    | 023717                | 68510002       |
| NO PART SENT-SHOP SAYS BRK LINE RUBBING ON EXHAUST PIPE            |               |                       |                    |                                                                                        |                      |                         |                       |                |
| 40001                                                              | P01323 B      | 760320                | 03241              | BRKS-HYDRAULIC-LINES,METALLIC<br>CO 000 UNKNOWN                                        | 00 UNKNOWN           | 10 C                    | 000000                | 61108013       |
| NO PARTS-SHOP COMMENTS ON DESIGN OF BRAKE TUBING                   |               |                       |                    |                                                                                        |                      |                         |                       |                |
| 30004                                                              | P01055 B      | 751206                | 03241              | BRKS-HYDRAULIC-LINES,METALLIC<br>73 010 AMERICAN MOTORS                                | E9 CJ-5 JEEP<br>CJ-5 | 09 C                    | 021012                | 80226008       |
| BRAKE LINE IS SEVERED IN 2 PIECES-CUT AREA HAS ROUGH EDGES-NO RUST |               |                       |                    |                                                                                        |                      |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0044

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                 | MAKE-MODEL               | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|----------------------------------------------------------------|--------------------------|-------------------------|-----------------------|----------------|
| 50007         | P01500 B      | 760427                | 03241              | BRKS-HYDRAULIC-LINES,METALLIC<br>66 010 AMERICAN MOTORS        | G9 JEEP TRUCK<br>JEEP PU | 49 C                    | 027099                | 55805004       |
|               |               |                       |                    | RUSTY AND CORRODED BRAKE LINES                                 |                          |                         |                       |                |
| 50019         | P01583 B      | 760601                | 03241              | BRKS-HYDRAULIC-LINES,METALLIC<br>74 022 DODGE                  | 05 DART                  | 06 C                    | 041531                | 02140002       |
|               |               |                       |                    | 3/16 IN. LINE FROM CYL TO BLOCK CHAFED BY STEER U-JOINT LEAKS  |                          |                         |                       |                |
| 50022         | P01607 B      | 760601                | 03241              | BRKS-HYDRAULIC-LINES,METALLIC<br>68 031 FORD DIVISION          | H3 FORD-GALAXIE 500      | 49 C                    | 000000                | 55423002       |
|               |               |                       |                    | BRAKE LINE TO REAR WHEELS SEVERLY RUSTED CAUSING LOSS OF FLUID |                          |                         |                       |                |
| 20007         | P00716 B      | 750805                | 03241              | BRKS-HYDRAULIC-LINES,METALLIC<br>64 041 BUICK                  | A2 CENTURY 350           | 49 C                    | 047189                | 055805004      |
|               |               |                       |                    | RUSTED THROUGH CAUSING BRAKE FLUID TO LEAK                     |                          |                         |                       |                |
| 40001         | P01322 B      | 760320                | 03241              | BRKS-HYDRAULIC-LINES,METALLIC<br>63 043 CHEVROLET DIVISION     | B4 CHEVY II              | 49 C                    | 060630                | 61108013       |
|               |               |                       |                    | STEEL LINES SEVERLY RUSTED                                     |                          |                         |                       |                |
| 30005         | P01066 B      | 751206                | 03241              | BRKS-HYDRAULIC-LINES,METALLIC<br>70 045 PONTIAC DIVISION       | A3 BONNEVILLE            | 06 C                    | 058552                | 19020002       |
|               |               |                       |                    | HOLE WORN IN METAL BRAKE LINE-APPROX 8 INCHES FROM FITTING     |                          |                         |                       |                |
| 50007         | P01494 B      | 760419                | 03241              | BRKS-HYDRAULIC-LINES,METALLIC<br>00 155 VOLKSWAGEN             | A1 111 CUSTOM BEETLE     | 49 C                    | 000000                | 51105009       |
|               |               |                       |                    | STEEL BRAKE LINE RUSTED THROUGH                                |                          |                         |                       |                |
| 30021         | P01310 B      | 760206                | 03242              | BRKS-HYDRAULIC-LINES-HOSE, NON-METALLIC<br>00 000 UNKNOWN      | 00 UNKNOWN               | 08 C                    | 000000                | 90027012       |
|               |               |                       |                    | HOSE SPLIT AT JOINING W/METAL END - BRAKE LINE SIDE            |                          |                         |                       |                |
| 20013         | P00936 B      | 751024                | 03242              | BRKS-HYDRAULIC-LINES-HOSE, NON-METALLIC<br>00 000 UNKNOWN      | 00 UNKNOWN               | 08 C                    | 000000                | 060626008      |
|               |               |                       |                    | BRAKE HOSE CRACKED                                             |                          |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0045

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                               | MAKE-MODEL                    | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|---------------|--------|------------------|--------------------|--------------------------------------------------------------------|-------------------------------|-------------------------|-----------------------|----------------|
| 50008                                                                  | P01504        | C      | 760427           | 03242              | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>74 010 AMERICAN MOTORS | 04 GREMLIN                    | 08 C                    | 000000                | 15223121       |
| HOSE CRACKED AWAY FRM METAL FITTING-SERVING AS MOUNTING PIECE TO FRAME |               |        |                  |                    |                                                                    |                               |                         |                       |                |
| 50008                                                                  | P01504        | B      | 760427           | 03242              | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>74 010 AMERICAN MOTORS | 04 GREMLIN                    | 08 C                    | 000000                | 15223121       |
| HOSE CRACKED AWAY FROM METAL FITTING THAT SERVES AS MNTNG PIECE TO FRM |               |        |                  |                    |                                                                    |                               |                         |                       |                |
| 50003                                                                  | P01452        | C      | 760402           | 03242              | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>74 010 AMERICAN MOTORS | 05 HORNET                     | 09 C                    | 028000                | 48197006       |
| BRK HOSE IS TORN AROUND CIRCUMFERENCE 3/8 IN FROM FRAME MOUNT END      |               |        |                  |                    |                                                                    |                               |                         |                       |                |
| 50003                                                                  | P01452        | B      | 760402           | 03242              | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>74 010 AMERICAN MOTORS | 05 HORNET                     | 09 C                    | 028000                | 48197006       |
| HOSE IS TORN AROUND CIRCUMFERENCE 3/8 IN FROM FRAME MOUNT END          |               |        |                  |                    |                                                                    |                               |                         |                       |                |
| 50017                                                                  | P01568        | B      | 760512           | 03242              | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>67 022 DODGE           | 05 DART                       | 08 C                    | 021453                | 90027012       |
| HOSE CRACKED 120 DEG AROUND CIRC 3/16" FROM FITTING AT BOTH ENDS       |               |        |                  |                    |                                                                    |                               |                         |                       |                |
| 30006                                                                  | P01081        | B      | 751224           | 03242              | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>69 022 DODGE           | 05 DART                       | 08 C                    | 023267                | 30501001       |
| FLEXIBLE HOSE SPLIT 1/8 INCH FROM FITTING-NUMEROUS CRACKS              |               |        |                  |                    |                                                                    |                               |                         |                       |                |
| 40001                                                                  | P01328        | C      | 760320           | 03242              | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>73 022 DODGE           | 05 DART                       | 08 C                    | 039489                | 17701024       |
| HOSE CRACKED AROUND CIRCUMFERENCE 3/8" FROM FITTING                    |               |        |                  |                    |                                                                    |                               |                         |                       |                |
| 40001                                                                  | P01328        | B      | 760320           | 03242              | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>73 022 DODGE           | 05 DART                       | 08 C                    | 039489                | 17701024       |
| HOSE CRACKED 3/8" FROM EACH FITTING - CRACKS ARE AROUND CIRCUMFERENCE  |               |        |                  |                    |                                                                    |                               |                         |                       |                |
| 30023                                                                  | P01288        | B      | 760214           | 03242              | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>74 022 DODGE           | 9A DODGE TRUCK AND VA<br>B-20 | 44 C                    | 018539                | 55423002       |
| HOSE RESTRICTED INSIDE - NOT SPECIFIC                                  |               |        |                  |                    |                                                                    |                               |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0046

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MCL YR

| BIN NUMBER | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                                          | MAKE-MODEL                         | FAULT HAZ. CODE | MILEAGE AT FAILURE | SHOP NUMBER |
|------------|------------|-----------------|-----------------|-------------------------------------------------------------------------|------------------------------------|-----------------|--------------------|-------------|
| 20011      | P00889 B   | 751008          | 03242           | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>74 022 DODGE                | 9A DODGE TRUCK AND VA<br>1/2 T 4X4 | 10 C            | 000000             | 84109006    |
|            |            |                 |                 | HOSE TOO SHORT-STEERING TURNS TOO FAR-STRETCHES HOSE UNTIL IT BREAKS    |                                    |                 |                    |             |
| 40002      | P01336 C   | 760324          | 03242           | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>73 023 PLYMOUTH             | A6 VALIANT-DUSTER                  | 32 C            | 037771             | 14607007    |
|            |            |                 |                 | HOSE SEVERED AT BOTH ENDS POSSIBLY DURING REMOVAL                       |                                    |                 |                    |             |
| 40002      | P01336 B   | 760324          | 03242           | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>73 023 PLYMOUTH             | A6 VALIANT-DUSTER                  | 08 C            | 037771             | 14607007    |
|            |            |                 |                 | HOSE CRACKED IN THREE PLACES 1/4"-1/2" FROM BRACKET END FITTING         |                                    |                 |                    |             |
| 30006      | P01091 B   | 751224          | 03242           | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>65 023 PLYMOUTH             | 06 VALIANT                         | 08 C            | 081273             | 90027012    |
|            |            |                 |                 | HOSE CRACKED-AT SHARP BENDS CIRCUMFERENCE OF HOSE CRACKED NEAR FITTING  |                                    |                 |                    |             |
| 40002      | P01334 B   | 760309          | 03242           | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>73 023 PLYMOUTH             | 06 VALIANT                         | 08 C            | 086377             | 30501001    |
|            |            |                 |                 | RUBBER CRACKED AROUND CIRC. 1/2" FROM METAL JOINT-BOTH ENDS             |                                    |                 |                    |             |
| 40002      | P01334 C   | 760309          | 03242           | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>73 023 PLYMOUTH             | 06 VALIANT                         | 08 C            | 086377             | 30501001    |
|            |            |                 |                 | RUBBER SPLIT 360 DEG AROUND CIRC - 3/8" FROM METAL FITTING              |                                    |                 |                    |             |
| 50022      | P01606 B   | 760601          | 03242           | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>75 031 FORD DIVISION        | D8 G. TORINO-WAGON                 | 28 C            | 030005             | 15697025    |
|            |            |                 |                 | NO CRACKS IN HOSE FITTINGS IN GOOD COND SUSPECT INTERNAL BLOCKAGE       |                                    |                 |                    |             |
| 50013      | P01546 B   | 760507          | 03242           | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>66 031 FORD DIVISION        | H3 FORD-GALAXIE 500                | 06 C            | 097267             | 54130001    |
|            |            |                 |                 | HOSE IS CHAFED IN 2 AREAS NEAR CTR, WORN DOWN THROUGH CORD              |                                    |                 |                    |             |
| 50013      | P01547 B   | 760507          | 03242           | BRKS. HYDRAULIC-LINES-HOSE, NON-METALLIC<br>68 031 FORD DIVISION        | 01 FAIRLANE                        | 08 B            | 071110             | 54130001    |
|            |            |                 |                 | HOSE IS SPLIT 360 DEG AROUND OUTER RUBBER LAYER EACH END 3/16" FROM FIT |                                    |                 |                    |             |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0047

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                       | MAKE-MODEL           | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|---------------|-----------------------|--------------------|----------------------------------------------------------------------|----------------------|-------------------------|-----------------------|----------------|
| 50013                                                                  | P01547 C      | 760507                | 03242              | BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>68 031 FORD DIVISION      | 01 FAIRLANE          | 03 B                    | 071110                | 54130001       |
| HOSE IS BROKEN AT BOTH ENDS FITTINGS BROKE OFF 3/16" FROM ENDS OF HOSE |               |                       |                    |                                                                      |                      |                         |                       |                |
| 20008                                                                  | P00834 B      | 750905                | 03242              | BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>68 031 FORD DIVISION      | 01 FAIRLANE          | 44 C                    | 018906                | 028208008      |
| RF BRAKE LINE PLUGGED UP-BRAKE FLUID WILL NOT FLOW THRU HOSE           |               |                       |                    |                                                                      |                      |                         |                       |                |
| 30011                                                                  | P01214 B      | 760123                | 03242              | BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>00 031 FORD DIVISION      | 03 FORD              | 07 C                    | 098000                | 96106037       |
| BRAKE HOSE CLOGGED INDICATING NO EXTERNAL WEAR                         |               |                       |                    |                                                                      |                      |                         |                       |                |
| 0008                                                                   | P00844 B      | 750911                | 03242              | BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>65 031 FORD DIVISION      | 05 MUSTANG           | 09 C                    | 000000                | 084117016      |
| HOSE CUT APROX 1/4 IN BELOW MALE CONNECTION                            |               |                       |                    |                                                                      |                      |                         |                       |                |
| 30021                                                                  | P01309 B      | 760306                | 03242              | BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>62 041 BUICK              | 04 LE SABRE          | 44 C                    | 093534                | 03102004       |
| HOSE IS OLD & CRACKED - POSS INTERNAL BLOCKAGE                         |               |                       |                    |                                                                      |                      |                         |                       |                |
| 20007                                                                  | P00449 B      | 750722                | 03242              | BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>65 041 BUICK              | 08 WILDCAT           | 08 B                    | 094601                | 094133032      |
| BRAKE HOSE CRACKED APPRX. 1/4 INCH FROM CONNECTION                     |               |                       |                    |                                                                      |                      |                         |                       |                |
| 30008                                                                  | P01101 B      | 751226                | 03242              | BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>65 041 BUICK              | 08 WILDCAT           | 08 C                    | 100188                | 19802003       |
| RUBBER BRAKE LINE BROKE OR CRACKED NEAR FITTING-NO SMALL CRACKS        |               |                       |                    |                                                                      |                      |                         |                       |                |
| 50017                                                                  | P01567 C      | 760512                | 03242              | BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>66 042 CADILLAC DIVISION  | 01 CADILLAC-DE VILLE | 03 C                    | 000000                | 90027012       |
| HOSE BROKE IN TWO AT META FITTING AT WHEEL CYL END                     |               |                       |                    |                                                                      |                      |                         |                       |                |
| 50004                                                                  | P01469 B      | 760405                | 03242              | BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>66 043 CHEVROLET DIVISION | A3 BELAIR            | 08 C                    | 063007                | 14007007       |
| HOSE SHOWS AGE W/ CRACKS AT END BY FITTINGS-SOME LEAKAGE OCCURRING     |               |                       |                    |                                                                      |                      |                         |                       |                |

# PARTS RETURN PROGRAM

76/07/06 PAGE 0048

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                                                                                           | MAKE-MODEL                | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|-------------------------|-----------------------|----------------|
| 50005         | P01472 B      | 760407                | 03242              | BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>70 043 CHEVROLET DIVISION                                                                           | E3 IMPALA                 | 06 C                    | 059921                | 66606005       |
| 30012         | P01168 B      | 760106                | 03242              | REAR AXLE BRK FLEX HOSE RUBS TAIL PIPE-HOLE WORN CAUSING FLUID LOSS<br>BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>70 043 CHEVROLET DIVISION    | 00 CHEVROLET DIVISION     | 76 A                    | 088011                | 19380005       |
|               | P00841 B      | 750827                | 03242              | INNERMOST RUBBER LINER OF BRAKE HOSE COLLAPSED-BLOCKED FLUID-DISC LOCK<br>BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>72 043 CHEVROLET DIVISION | 08 MONTE CARLO            | 32 C                    | 000000                | 012205003      |
| 50004         | P01466 B      | 760405                | 03242              | BRAKE HOSE LEAKS<br>BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>69 044 OLDSMOBILE                                                               | 02 DELTA 88               | 08 C                    | 049785                | 50702006       |
| 30015         | P01188 B      | 760118                | 03242              | FLEX BRAKE HOSE IS SPLIT NEAR FRAME MOUNT END<br>BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>71 122 BRITISH LEYLAND MOTOR CO C4 MG-MIDGET       |                           | 06 C                    | 030404                | 98105017       |
| 30004         | P01188 C      | 760118                | 03242              | EVIDENCE OF CHAFING ON ONE SIDE AT CENTER OF HOSE<br>BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>71 122 BRITISH LEYLAND MOTOR CO C4 MG-MIDGET   |                           | 06 C                    | 030404                | 98105017       |
| 30012         | P01183 B      | 760107                | 03242              | BRAKE HOSE IS WORN THROUGH TO UNDERLYING CLOTH LAYER<br>BRKS.HYDRAULIC-LINES-HOSE, NON-METALLIC<br>71 176 TOYOTA MOTR CO LTD                   | 01 TOYOTA                 | 32 C                    | 061000                | 98106082       |
| 30015         | P01189 B      | 760118                | 03243              | BRAKE HOSE LEAKS 1/4 IN FROM FITTING, OUTER RUBBER RIPPED-INNER EXPOSED<br>BRKS.HYDRAULIC-FITTINGS, METALLIC<br>68 043 CHEVROLET DIVISION      | E0 PICK-UP MODELS<br>C-10 | 08 C                    | 087005                | 98118071       |
| 30002         | P01014 B      | 751118                | 03245              | ONE OF THREE FEMALE CONNECTIONS WITH BRASS BRAKE FITTING T CRACKED<br>BRKS.HYDRAULIC-DIFFERENTIAL-PROPORTION.VL<br>73 022 DODGE                |                           | 28 C                    | 031349                | 90405016       |
|               |               |                       |                    | REAR BRAKE LOCK-UP, INTERNAL MALFUNCTION                                                                                                       |                           |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0049

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BTN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                      | MAKE-MODEL                                                                         | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------|-----------------------|----------------|
| 30002         | P01013 B      | 751118                | 03245              | BRKS-HYDRAULIC-DIFFERENTIAL-PROPORTION.VL<br>73 023 PLYMOUTH           | 01 BARRACUDA                                                                       | 28 C                    | 046000                | 90405016       |
| 30003         | P01010 B      | 751118                | 03245              | BRKS-HYDRAULIC-DIFFERENTIAL-PROPORTION.VL<br>74 041 BUICK              | INTERNAL MALFUNCTION-REAR BRAKE LOCK-UP                                            | 28 C                    | 046039                | 80903015       |
| 30001         | P01006 B      | 751118                | 03245              | BRKS-HYDRAULIC-DIFFERENTIAL-PROPORTION.VL<br>75 042 CADILLAC DIVISION  | 81 CADILLAC-DE VILLE                                                               | 28 C                    | 024000                | 19963104       |
| 20003         | P00833 B      | 750827                | 03245              | BRKS-HYDRAULIC-DIFFERENTIAL-PROPORTION.VL<br>73 043 CHEVROLET DIVISION | COMBINATION VALVE HAS INTERNAL MALFUNCTION,POSSIBLE FLUID CONTAMINATION            | 02 C                    | 025000                | 068510002      |
| 30018         | P01250 B      | 760203                | 03245              | BRKS-HYDRAULIC-DIFFERENTIAL-PROPORTION.VL<br>73 044 OLDSMOBILE         | 98 CHEVROLET VAN<br>CHEYENNE 30<br>FLUID RELEASE PIN BENT                          | 28 C                    | 026729                | 63103004       |
| 20004         | P00720 B      | 750806                | 03245              | BRKS-HYDRAULIC-DIFFERENTIAL-PROPORTION.VL<br>72 044 OLDSMOBILE         | SUSPECT INTERNAL MALFUNCTION - NO VISIBLE DEFECTS                                  | 32 A                    | 035000                | 006851001      |
| 30010         | P01144 B      | 751229                | 03245              | BRKS-HYDRAULIC-DIFFERENTIAL-PROPORTION.VL<br>74 045 PONTIAC DIVISION   | 02 DELTA 88<br>BENOIX<br>LOSS FLUID-TOTAL BRAKE FAILURE                            | 32 C                    | 012249                | 02888001       |
| 30011         | P01017 B      | 751118                | 03245              | BRKS-HYDRAULIC-DIFFERENTIAL-PROPORTION.VL<br>60 145 REGIE NDU RENAULT  | 84 LE MANS<br>BRAKE FLUID LEAKS OUT OF VALVE-NOT ABLE TO DISCOVER FROM WHERE       | 28 C                    | 000000                | 67501001       |
| 30011         | P01150 B      | 751229                | 03260              | BRKS-HYDRAULIC-SHOE AND DRUM SYSTEM<br>73 033 MERCURY                  | NO PART RECEIVED-PROBLEMS W/BRAKE PORTIONING VALVE-POOR ENGINEERING                | 21 C                    | 000000                | 52404002       |
|               |               |                       |                    |                                                                        | 02 COMET<br>SECONDARY SHOE & LINING SEPARATED-1 SIDE DETERIORATED RUB AGAINST DRUM |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06

PAGE 0050

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>MANUFACTURER                                    | MAKE-MODEL            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|---------------|-----------------------|--------------------|----------------------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 30011                                                                  | P01149 B      | 751229                | 03260              | BRKS. HYDRAULIC-SHOE AND DRUM SYSTEM<br>73 033 MERCURY               | 02 COMET              | 21 C                    | 000000                | 52404002       |
| PRIMARY SHOE & LINING SEPARATED-1 SIDE DETERIORATED                    |               |                       |                    |                                                                      |                       |                         |                       |                |
| 20013                                                                  | P00937 B      | 751024                | 03261              | BRKS. HYDR-SHOE AND DRUM WHEEL CYLINDERS<br>00 000 UNKNOWN           | 00 UNKNOWN            | 28 C                    | 000000                | 60026008       |
| BRAKE CYLINDER WEATHERED                                               |               |                       |                    |                                                                      |                       |                         |                       |                |
| 30008                                                                  | P01100 B      | 751226                | 03261              | BRKS. HYDR-SHOE AND DRUM WHEEL CYLINDERS<br>69 010 AMERICAN MOTORS   | 00 AMERICAN MOTORS    | 03 C                    | 053000                | 19602003       |
| BLEEDER BROKEN-BLEEDER BROKE METAL CASING WHICH SCREW FIT-NOT ALL PART |               |                       |                    |                                                                      |                       |                         |                       |                |
| 30015                                                                  | P01230 C      | 760203                | 03261              | BRKS. HYDR-SHOE AND DRUM WHEEL CYLINDERS<br>71 021 CHRYSLER DIVISION | 01 NEW YORKER         | 32 C                    | 049624                | 50702006       |
| CYLINDER WALL NOT PROPERLY MACHINED -SOURCE OF POSSIBLE LEAKAGE        |               |                       |                    |                                                                      |                       |                         |                       |                |
| 20003                                                                  | P00809 B      | 750820                | 03261              | BRKS. HYDR-SHOE AND DRUM WHEEL CYLINDERS<br>69 022 DODGE             | 05 DART               | 19 C                    | 011655                | 000000000      |
| BRAKES FADE AND OPERATE ERRATICLY                                      |               |                       |                    |                                                                      |                       |                         |                       |                |
| 50002                                                                  | P01449 B      | 760401                | 03261              | BRKS. HYDR-SHOE AND DRUM WHEEL CYLINDERS<br>68 031 FORD DIVISION     | 02 FALCON             | 32 C                    | 000000                | 31204007       |
| CYLINDER CUPS LEAK AT CYLINDER WALL                                    |               |                       |                    |                                                                      |                       |                         |                       |                |
| 20002                                                                  | P00458 B      | 750728                | 03261              | BRKS. HYDR-SHOE AND DRUM WHEEL CYLINDERS<br>74 045 PONTIAC DIVISION  | 03 PONTIAC            | 08 B                    | 016152                | 005482001      |
| BRAKE WHEEL CYL. CRACKED CAUSING A LOST OF BRAKE FLUID                 |               |                       |                    |                                                                      |                       |                         |                       |                |
| 30021                                                                  | P01272 B      | 760207                | 03261              | BRKS. HYDR-SHOE AND DRUM WHEEL CYLINDERS<br>70 155 VOLKSWAGEN        | B2 221 STATION WAGON/ | 21 C                    | 016911                | 01605008       |
| PISTONS FELL OUT OF WHEEL CYLINDER                                     |               |                       |                    |                                                                      |                       |                         |                       |                |
| 20001                                                                  | P00472 B      | 750708                | 03262              | BRKS. HYDR-SHOE AND DRUM SYSTEM-SHOES<br>00 022 DODGE                | 05 DART               | 03 C                    | 000000                | 019903107      |
| BRAKE SHOE HOLD DOWN PIN BROKE CAUSING SHOES TO COLLAPSE               |               |                       |                    |                                                                      |                       |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0051

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| SIN<br>NUMBER | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                      | MAKE-MODEL                        | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|--------|------------------|--------------------|------------------------------------------------------------------------|-----------------------------------|-------------------------|-----------------------|----------------|
| 30017         | P01248        | B      | 760203           | 03262              | BRKS.HYDR-SHOE AND DRUM SYSTEM-SHOES<br>72 023 PLYMOUTH                | A6 VALIANT-DUSTER                 | 08 C                    | 046500                | 40503002       |
|               |               |        |                  |                    | BRAKE SHOE CRACKED AT HOLE FOR SELF ADJUSTER CABLE GUIDE               |                                   |                         |                       |                |
|               | P01038        | C      | 751122           | 03262              | BRKS.HYDR-SHOE AND DRUM SYSTEM-SHOES<br>70 023 PLYMOUTH                | 05 SATELLITE                      | 21 C                    | 060000                | 48238012       |
|               |               |        |                  |                    | LINING SEPARATED FROM SHOE(BONDED LINING) LINING SHOWS LITTLE WEAR     |                                   |                         |                       |                |
| 50012         | P01531        | B      | 760501           | 03262              | BRKS.HYDR-SHOE AND DRUM SYSTEM-SHOES<br>70 031 FORD DIVISION           | 01 FAIRLANE                       | 58 C                    | 002700                | 17102009       |
|               |               |        |                  |                    | SECOND SHOE EXCESS WORN ON ONE SIDE ANCHOR PLATE NOT ALIGNED TO LINING |                                   |                         |                       |                |
| 50007         | P01495        | B      | 760421           | 03262              | BRKS.HYDR-SHOE AND DRUM SYSTEM-SHOES<br>73 031 FORD DIVISION           | 08 TORINO                         | 59 C                    | 033217                | 92703036       |
|               |               |        |                  |                    | BROKEN WELD CAUSED CENTER RIB TO SEPARATE FROM BRAKE LINING            |                                   |                         |                       |                |
| 20007         | P00796        | B      | 750812           | 03262              | BRKS.HYDR-SHOE AND DRUM SYSTEM-SHOES<br>00 031 FORD DIVISION           | 9A FORD TRUCK AND VAN<br>F600     | 08 C                    | 028000                | 070130001      |
|               |               |        |                  |                    | CRACKED BRAKE SHOE AND BROKEN SPOT WELD                                |                                   |                         |                       |                |
| 50008         | P01507        | B      | 760427           | 03262              | BRKS.HYDR-SHOE AND DRUM SYSTEM-SHOES<br>66 045 PONTIAC DIVISION        | 03 PONTIAC                        | 58 C                    | 086000                | 40503002       |
|               |               |        |                  |                    | NO PROBLEMS VISIBLE OTHER THAN UNEVEN WEAR OF LINING                   |                                   |                         |                       |                |
| 30012         | P01178        | B      | 760106           | 03263              | BRKS.HYDR-SHOE AND DRUM SYSTEM-LININGS<br>74 022 DODGE                 | 9A DODGE TRUCK AND VAN<br>3/4 VAN | 03 C                    | 013000                | 098105033      |
|               |               |        |                  |                    | RIVETED LINING BROKE IN HALF-REMAINING LINING SCORED-RIVETS BENT       |                                   |                         |                       |                |
| 30003         | P01185        | B      | 760118           | 03263              | BRKS.HYDR-SHOE AND DRUM SYSTEM-LININGS<br>00 031 FORD DIVISION         | 03 FORD                           | 57 C                    | 000000                | 22203030C      |
|               |               |        |                  |                    | AXLE SET OF BRAKE SHOES SHOW EXCESSIVE WEAR WELL PAST SAFETY MARGIN    |                                   |                         |                       |                |
| 20001         | P00471        | B      | 750708           | 03263              | BRKS.HYDR-SHOE AND DRUM SYSTEM-LININGS<br>72 042 CADILLAC DIVISION     | 01 CADILLAC                       | 03 C                    | 000000                | 019903107      |
|               |               |        |                  |                    | BRAKE SHOE HOLD DOWN PIN BROKE CAUSING DAMAGE TO DRUM & OTHER PARTS    |                                   |                         |                       |                |

## PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06

PAGE 0052

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER                                                         | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                         | MAKE-MODEL                                     | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|-----------------------------------------------------------------------|---------------|--------|------------------|--------------------|--------------------------------------------------------------|------------------------------------------------|-------------------------|-----------------------|----------------|
| 30021                                                                 | P01272        | C      | 760207           | 03263              | BRKS.HYDR-SHOE AND DRUM SYSTEM-LININGS<br>70 155 VOLKSWAGEN  | B2 221 STATION WAGON/<br>B2 221 STATION WAGON/ | 21 C                    | 016911                | C1605008       |
| LININGS WERE SEPARATED FROM SHOES AND EACH IS CRACKED IN HALF         |               |        |                  |                    |                                                              |                                                |                         |                       |                |
| 30027                                                                 | P01297        | B      | 760301           | 03264              | BRKS.HYDR-SHOE AND DRUM SYSTEM-DRUM<br>70 022 DODGE          | B5 DART-SWINGER                                | 21 C                    | 047347                | 53140017       |
| HUB SEPARATED FROM DRUM MARKS AT INNER BRNG LOCATION ON HUB           |               |        |                  |                    |                                                              |                                                |                         |                       |                |
| 30026                                                                 | P01297        | C      | 760301           | 03264              | BRKS.HYDR-SHOE AND DRUM SYSTEM-DRUM<br>70 022 DODGE          | B5 DART-SWINGER                                | 21 C                    | 047347                | 53140017       |
| HUB SEPARATED FROM DRUM ND EXCESSIVE WEAR ON BEARING RACES            |               |        |                  |                    |                                                              |                                                |                         |                       |                |
| 30003                                                                 | P01038        | B      | 751122           | 03264              | BRKS.HYDR-SHOE AND DRUM SYSTEM-DRUM<br>70 023 PLYMOUTH       | 05 SATELLITE                                   | 08 C                    | 060000                | 48238012       |
| BRAKE DRUM CRACKED-ACROSS SHOE CONTACT SURFACE,PERHAPS TURNED TOO FAR |               |        |                  |                    |                                                              |                                                |                         |                       |                |
|                                                                       | P01038        | D      | 751122           | 03265              | BRKS.HYDR-SHOE AND DRUM SYSTEM-OTHER<br>70 023 PLYMOUTH      | 05 SATELLITE                                   | 21 C                    | 060000                | 48238012       |
| CHATTER SPRING CAME APART WHEN DRUM CRACKED                           |               |        |                  |                    |                                                              |                                                |                         |                       |                |
| 50002                                                                 | P01441        | B      | 760401           | 03265              | BRKS.HYDR-SHOE AND DRUM SYSTEM-OTHER<br>72 031 FORD DIVISION | 9C F-250<br>F-250                              | 02 C                    | 020194                | 03060006       |
| BRAKE SPRING BENT AND WORN-ATTACHMENT HOOK BROKEN OFF                 |               |        |                  |                    |                                                              |                                                |                         |                       |                |
| 20006                                                                 | P00929        | B      | 751020           | 03265              | BRKS.HYDR-SHOE AND DRUM SYSTEM-OTHER<br>67 033 MERCURY       | E4 MERCURY-MONTEREY                            | 08 C                    | 000000                | 53404020       |
| WHEEL CYLINDER, BACKING PLATE, AND RETURN SPRING POST CRACKED         |               |        |                  |                    |                                                              |                                                |                         |                       |                |
| 20007                                                                 | P00444        | B      | 750722           | 03271              | BRKS HYDRAULIC-DISC-CALIPER<br>67 042 CADILLAC DIVISION      | A2 FLEETWOOD-ELDORADO                          | 49 C                    | 102840                | 054911007      |
| CALIPER PISTON CORRODED                                               |               |        |                  |                    |                                                              |                                                |                         |                       |                |
| 20016                                                                 | P00970        | B      | 751108           | 03271              | BRKS HYDRAULIC-DISC-CALIPER<br>72 154 DAIMLER-BENZ AG        | 01 MERCEDES-BENZ                               | 08 C                    | 018600                | 93301046       |
| CALIPER CYLINDER CRACKED ON OUTBOARD PISTON,BLEEDER VALVE CRACKED     |               |        |                  |                    |                                                              |                                                |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0053

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                            | MAKE-MODEL        | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|------------------------------------------------------------------------|---------------|-----------------------|--------------------|-----------------------------------------------------------------|-------------------|-------------------------|-----------------------|----------------|
| 40007                                                                  | P01416 B      | 760331                | 03272              | BRKS HYDRAULIC-DISC-PADS AND SHOES<br>00 000 UNKNOWN            | 00 UNKNOWN        | 57 C                    | 000000                | 60626008       |
| EXCESSIVE WEAR ON RIVETED PADS-TAG NOT READABLE                        |               |                       |                    |                                                                 |                   |                         |                       |                |
| 30007                                                                  | P01111 B      | 751226                | 03272              | BRKS HYDRAULIC-DISC-PADS AND SHOES<br>73 031 FORD DIVISION      | 06 PINTO          | 21 C                    | 024776                | 1710400E       |
| DISC PADS CAME APART RIVETS APPEAR SHEARED OFF-PLenty OF WEAR LEFT     |               |                       |                    |                                                                 |                   |                         |                       |                |
| 40001                                                                  | P01330 B      | 760320                | 03272              | BRKS HYDRAULIC-DISC-PADS AND SHOES<br>74 032 LINCOLN            | A2 MARK IV        | 21 C                    | 023600                | 44110013       |
| LINING SEPARATED FROM PLATE-LINING CRACKED AT ONE RIVET OTHERS OK      |               |                       |                    |                                                                 |                   |                         |                       |                |
| 30001                                                                  | P00998 B      | 751114                | 03272              | BRKS HYDRAULIC-DISC-PADS AND SHOES<br>69 045 PONTIAC DIVISION   | C3 CATALINA       | 57 C                    | 000000                | 198C2003       |
| EXCESSIVE WEAR ON PAD LINING                                           |               |                       |                    |                                                                 |                   |                         |                       |                |
| 30006                                                                  | P01086 B      | 751224                | 03272              | BRKS HYDRAULIC-DISC-PADS AND SHOES<br>72 045 PONTIAC DIVISION   | 02 GRAND PRIX     | 57 C                    | 042600                | 19802003       |
| PAD SURFACE SCORED-PADS AND RIVETS WORN DOWN-DUE TO LACK OF MAINTENANC |               |                       |                    |                                                                 |                   |                         |                       |                |
| 30008                                                                  | P01099 B      | 751226                | 03272              | BRKS HYDRAULIC-DISC-PADS AND SHOES<br>72 045 PONTIAC DIVISION   | 02 GRAND PRIX     | 57 C                    | 042000                | 19802003       |
| PADS WORN DOWN TO RIVETS AND SCORED-RIVETS WORN-ORIGINAL PADS          |               |                       |                    |                                                                 |                   |                         |                       |                |
| 40005                                                                  | P01379 B      | 760330                | 03272              | BRKS HYDRAULIC-DISC-PADS AND SHOES<br>73 176 TOYOTA MOTR CO LTD | 02 TOYOTA COROLLA | 57 C                    | 617000                | 01904029       |
| PADS WORN TO METAL-OUTBOARD PAD IS SCORED ON ONE END                   |               |                       |                    |                                                                 |                   |                         |                       |                |
| 30019                                                                  | P01247 B      | 760203                | 03273              | BRKS HYDRAULIC-DISC-KOTOR-DISC HUB<br>74 010 AMERICAN MOTORS    | 06 JAVELIN        | 43 C                    | 020000                | 19803001       |
| INNER RACE SPINS IN HUB - NO CRACKS EVIDENT                            |               |                       |                    |                                                                 |                   |                         |                       |                |
| 30029                                                                  | P01262 B      | 760207                | 03273              | BRKS HYDRAULIC-DISC-RCTOR-DISC HUB<br>74 010 AMERICAN MOTORS    | 06 JAVELIN        | 43 C                    | 020000                | 19803001       |
| INNER RACE SPINS IN HUB - NO CRACKS EVIDENT                            |               |                       |                    |                                                                 |                   |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06

PAGE 0054

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MOL YR

| BIN NUMBER                                                              | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                                                         | YR MANUFACTURER | MAKE-MODEL          | FAULT HAZ. CODE CAT. | MILEAGE AT FAILURE | SHIP NUMBER |
|-------------------------------------------------------------------------|------------|-----------------|-----------------|----------------------------------------------------------------------------------------|-----------------|---------------------|----------------------|--------------------|-------------|
| 50010                                                                   | P01477 B   | 760409          | 03273           | BRKS HYDRAULIC-DISC-ROTOR-DISC HUB<br>70 031 FORD DIVISION                             |                 | D3 FORD-CUSTOM      | 08 C                 | 059930             | 22150084    |
| INNER PAD SURFACE OF ROTOR HAS HAIRLINE CRACK ACROSS WIDTH OF FACE      |            |                 |                 |                                                                                        |                 |                     |                      |                    |             |
| 30013                                                                   | P01179 B   | 760106          | 03273           | BRKS HYDRAULIC-DISC-ROTOR-DISC HUB<br>73 031 FORD DIVISION                             |                 | H3 FORD-GALAXIE 500 | 08 C                 | 024002             | 98105033    |
| ROTOR FACING CRACKED IN 2 PLACES-HUB CRACKED IN 1 PLACE-BETW HUB-ROTOR  |            |                 |                 |                                                                                        |                 |                     |                      |                    |             |
| 20017                                                                   | P00982 B   | 751103          | 03273           | BRKS HYDRAULIC-DISC-ROTOR-DISC HUB<br>00 031 FORD DIVISION                             |                 | 06 PINTO            | 57 C                 | 000000             | 01749012    |
| INBOARD PAD SURFACE OF ROTOR WORN EXCESSIVELY TO COOLING FINS-MAJ BREAK |            |                 |                 |                                                                                        |                 |                     |                      |                    |             |
| 30005                                                                   | P01064 B   | 751206          | 03273           | BRKS HYDRAULIC-DISC-ROTOR-DISC HUB<br>69 041 BUICK                                     |                 | 06 SKYLARK          | 08 C                 | 030650             | 54911002    |
| INSIDE OF HUB HAS LONGITUDINAL CRACK EXTENDING 1/2 IN                   |            |                 |                 |                                                                                        |                 |                     |                      |                    |             |
| 30007                                                                   | P01095 B   | 751224          | 03273           | BRKS HYDRAULIC-DISC-ROTOR-DISC HUB<br>72 043 CHEVROLET DIVISION                        |                 | E3 IMPALA           | 50 C                 | 009093             | 02140002    |
| ROTOR SCORED BY PAD ROTOR VENTS-EXTREME FLAKING AND CORROSION           |            |                 |                 |                                                                                        |                 |                     |                      |                    |             |
| 30015                                                                   | P01190 B   | 760118          | 03273           | BRKS HYDRAULIC-DISC-ROTOR-DISC HUB<br>73 043 CHEVROLET DIVISION                        |                 | E3 IMPALA           | 03 C                 | 000000             | 24153008    |
| CRACKS IN BASE OF BRAKE ROTOR HUB PARALLEL TO SPINDLE                   |            |                 |                 |                                                                                        |                 |                     |                      |                    |             |
| 30009                                                                   | P01131 B   | 751228          | 03273           | BRKS HYDRAULIC-DISC-ROTOR-DISC HUB<br>67 122 BRITISH LEYLAND MOTOR CO 20 JAGUAR<br>XKE |                 |                     | 21 C                 | 068805             | 98108037    |
| HUB & ROTOR SPLIT AROUND CIRCUMFERENCE OF HUB LITE RUST UNMACHIND PART  |            |                 |                 |                                                                                        |                 |                     |                      |                    |             |
| 40005                                                                   | P01379 C   | 760330          | 03273           | BRKS HYDRAULIC-DISC-ROTOR-DISC HUB<br>73 176 TOYOTA MOTR CO LTD                        |                 | 02 TOYOTA COROLLA   | 50 C                 | 017000             | 01904029    |
| ROTOR IS SCORED SEVERELY, POSSIBLY RESULT OF WORN PADS                  |            |                 |                 |                                                                                        |                 |                     |                      |                    |             |
| 50005                                                                   | P01478 B   | 760412          | 03322           | BRAKES AIR SYSTEMS-LINES-HOSE, NON-METALLI<br>70 M02 MACK TRUCK, INC.                  |                 |                     | 06 C                 | 020000             | 60076001    |
| OUTER RUBBER LAYER IS BURNT & WORN-HOSE HAS HALF IN-LEAK-POOR LOCATION  |            |                 |                 |                                                                                        |                 |                     |                      |                    |             |

## PARTS RETURN PROGRAM

76/07/06 PAGE C055

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                                                     | MAKE-MODEL                       | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|-------------------|------------------|--------------------|-------------------------------------------------------------------------------------------------------|----------------------------------|-------------------------|-----------------------|----------------|
| 30002         | P01011 B          | 751118           | 04110              | PRKNG EMRGNCY BRK-MECH-LVR SETTLING MECH.<br>71 031 FCRD DIVISION<br>CABLE CATCH SLIDE ASSEMBLY BROKE | A0 ECONOLINE SERIES<br>ECONOLINE | 03 C                    | 050526                | 90405016       |
| 20004         | P00446 B          | 750722           | 04140              | PRKNG EMRG BRK MECH-RELEASE MECH-AUTOMATI<br>73 000 UNKNOWN                                           | 00 UNKNOWN                       | 03 C                    | 014644                | 094133032      |
| 30015         | P01195 B          | 760103           | 04150              | PRKNG EMRG BRK MECH-LINKAGES AND CABLES<br>00 000 UNKNOWN                                             | 00 UNKNOWN                       | 53 C                    | 000000                | 98106082       |
| 50023         | P01618 B          | 760607           | 05110              | ENGINE MOUNTS<br>00 000 UNKNOWN                                                                       | 00 UNKNOWN                       | 03 C                    | 000000                | 91605014       |
| 40007         | P01415 B          | 760331           | 05110              | ENGINE MOUNTS<br>72 021 CHRYSLER DIVISION                                                             | B1 NEW YORKER                    | 03 C                    | 057479                | 60626006       |
| 50008         | P01501 B          | 760421           | 05110              | ENGINE MOUNTS<br>72 022 DODGE                                                                         | 00 DODGE                         | 08 C                    | 000000                | 27103001       |
| 50018         | P01575 B          | 760521           | 05110              | ENGINE MOUNTS<br>72 023 PLYMOUTH                                                                      | A4 FURY I                        | 03 C                    | 061360                | 01230005       |
| 20011         | P00900 B          | 751009           | 05110              | ENGINE MOUNTS<br>72 023 PLYMOUTH                                                                      | A6 VALIANT-DUSTER                | 03 C                    | 023673                | 29379007       |
| 30015         | P01191 B          | 760118           | 05110              | ENGINE MOUNTS<br>70 023 PLYMOUTH                                                                      | 00 PLYMOUTH                      | 08 C                    | 075760                | 85004002       |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0056

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                         | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER  | MAKE-MODEL     | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHLP<br>NUMBER |
|-----------------------------------------------------------------------|---------------|-----------------------|--------------------|---------------------------------------|----------------|-------------------------|-----------------------|----------------|
| 20013                                                                 | P01053        | B 751024              | 05110              | ENGINE MOUNTS<br>67 023 PLYMOUTH      | 04 FURY        | 08 C                    | 051404                | 60626C08       |
| ENG MOUNT SPLIT WITHIN RUBBER BODY OF MOUNT                           |               |                       |                    |                                       |                |                         |                       |                |
| 20013                                                                 | P00949        | B 751024              | 05110              | ENGINE MOUNTS<br>67 023 PLYMOUTH      | 04 FURY        | 08 C                    | 051404                | 60626C08       |
| MOTOR MOUNTS SPLIT AND CRACKED                                        |               |                       |                    |                                       |                |                         |                       |                |
| 50019                                                                 | P01581        | C 760427              | 05110              | ENGINE MOUNTS<br>00 030 FORD MOTORS   | 00 FORD MOTORS | 03 C                    | 000000                | 91605014       |
| RUBBER PARTIALLY SEPARATED FROM METAL PORTION OF MOTOR MOUNT          |               |                       |                    |                                       |                |                         |                       |                |
| 50019                                                                 | P01581        | B 760427              | 05110              | ENGINE MOUNTS<br>00 030 FORD MOTORS   | 00 FORD MOTORS | 03 C                    | 000000                | 91605014       |
| RUBBER PARTIALLY SEPARATED FROM METAL PORTION OF MOTOR MOUNT          |               |                       |                    |                                       |                |                         |                       |                |
| 30002                                                                 | P01012        | B 751118              | 05110              | ENGINE MOUNTS<br>72 031 FORD DIVISION | B6 PINTO WAGON | 12 C                    | 045010                | 90405016       |
| RUBBER PART OF MOUNT DISTORTED-1 GUIDE PIN HOLE BROKEN AT EYE         |               |                       |                    |                                       |                |                         |                       |                |
| 30024                                                                 | P01296        | B 760301              | 05110              | ENGINE MOUNTS<br>69 031 FORD DIVISION | 03 FORD-CUSTOM | 08 C                    | 041054                | 29611001       |
| RUBBER SEPARATED FROM METAL                                           |               |                       |                    |                                       |                |                         |                       |                |
| 20013                                                                 | P00906        | B 751020              | 05110              | ENGINE MOUNTS<br>68 031 FORD DIVISION | G3 FORD-LTD    | 03 C                    | 000000                | 19047001       |
| LEFT SIDE MOTOR MOUNT SEPARATED-ENG SHIFTED PULLING BRAKE VACUUM LINE |               |                       |                    |                                       |                |                         |                       |                |
| 40001                                                                 | P01331        | B 760320              | 05110              | ENGINE MOUNTS<br>70 031 FORD DIVISION | G3 FORD-LTD    | 21 C                    | 054823                | 06120003       |
| RUBBER PORTION OF MOUNT SPLIT AT METAL BASE                           |               |                       |                    |                                       |                |                         |                       |                |
| 30012                                                                 | P01165        | B 760106              | 05110              | ENGINE MOUNTS<br>70 031 FORD DIVISION | G3 FORD-LTD    | 03 C                    | 052890                | 030501001      |
| 90 PERCENT OF RUBBER BLOCK HAS SEPARATED FROM PLATE-REST ON PLATE     |               |                       |                    |                                       |                |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0057

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                      | MAKE-MODEL          | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|---------------------------------------------------------------------------|---------------------|-------------------------|-----------------------|----------------|
| 30012         | P01165        | C 760106              | 05110              | ENGINE MOUNTS<br>70 031 FORD DIVISION                                     | 63 FORD-LTD         | 03 C                    | 052890                | 030501001      |
|               |               |                       |                    | 90 PERCENT OF RUBBER BLOCK REMAINS INTACT--SMALL LAYER LEFT ON PLATE      |                     |                         |                       |                |
| 30027         | P01305        | B 760306              | 05110              | ENGINE MOUNTS<br>69 031 FORD DIVISION                                     | 01 FAIRLANE         | 03 C                    | 060000                | 000000000      |
|               |               |                       |                    | RUBBER SEPARATED FROM METAL - FAN DAMAGED RADIATOR                        |                     |                         |                       |                |
| 30027         | P01305        | C 760306              | 05110              | ENGINE MOUNTS<br>69 031 FORD DIVISION                                     | 01 FAIRLANE         | 08 C                    | 060000                | 000000000      |
|               |               |                       |                    | RUBBER CRACKED AT BASE WHERE IT MEETS METAL                               |                     |                         |                       |                |
| DOT1          | P01114        | B 751226              | 05110              | ENGINE MOUNTS<br>67 031 FORD DIVISION                                     | 03 FORD             | 03 C                    | 000000                | 19803001       |
|               |               |                       |                    | MOST OF THE RUBBER IS ON BLOCK--VERY LITTLE REMAINS ON METAL PLATE        |                     |                         |                       |                |
| DOT1          | P01115        | B 751226              | 05110              | ENGINE MOUNTS<br>67 031 FORD DIVISION                                     | 03 FORD             | 03 C                    | 000000                | 19603001       |
|               |               |                       |                    | RUBBER SPLIT--90 PERCENT OF RUBBER BLOCK IS IN ONE PIECE--CAUSE IS RUBBER |                     |                         |                       |                |
| 40003         | P01347        | B 760324              | 05110              | ENGINE MOUNTS<br>68 031 FORD DIVISION                                     | 03 FORD<br>SUB      | 03 C                    | 068206                | 12601031       |
|               |               |                       |                    | RUBBER PORTION OF MOUNT SEPARATED NEAR JOINT WITH METAL BASE              |                     |                         |                       |                |
| 50022         | P01600        | B 760607              | 05110              | ENGINE MOUNTS<br>69 031 FORD DIVISION                                     | 03 FORD             | 03 C                    | 010567                | 98126073       |
|               |               |                       |                    | RUBBER SEPARATED FROM METAL NEAR BASE OF MOUNT                            |                     |                         |                       |                |
| 50008         | P01510        | B 760427              | 05110              | ENGINE MOUNTS<br>72 031 FORD DIVISION                                     | 03 FORD<br>SUBURBAN | 08 B                    | 041715                | 12603050       |
|               |               |                       |                    | RUBBER CRACKED & SEPARATED FROM METAL                                     |                     |                         |                       |                |
| 20016         | P00974        | B 751108              | 05110              | ENGINE MOUNTS<br>73 031 FORD DIVISION                                     | 04 MAVERICK         | 08 C                    | 000000                | 63105001       |
|               |               |                       |                    | RUBBER HAS BEGUN TO SEPARATE FROM METAL PORTION OF ENG MOUNTS             |                     |                         |                       |                |

# PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06

PAGE 0058

SORTED BY COMPONENT,MODEL,MDL YR

| BIN NUMBER                                                           | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER      | MAKE-MODEL        | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|----------------------------------------------------------------------|-------------------|------------------|--------------------|----------------------------------------|-------------------|-------------------------|-----------------------|----------------|
| 50018                                                                | P01574 B          | 760512           | 05110              | ENGINE MOUNTS<br>69 032 LINCOLN        | 01 CONTINENTAL    | 03 C                    | 076619                | 90027012       |
| COMPLETE SEPARATION OF RUBBER FROM METAL PORTION OF MOTOR MOUNT      |                   |                  |                    |                                        |                   |                         |                       |                |
| 50018                                                                | P01574 E          | 760512           | 05110              | ENGINE MOUNTS<br>69 032 LINCOLN        | 01 CONTINENTAL    | 03 C                    | 076619                | 90027012       |
| COMPLETE SEPARATION OF RUBBER FROM METAL PORTION OF MOTOR MOUNT      |                   |                  |                    |                                        |                   |                         |                       |                |
| 50018                                                                | P01574 D          | 760512           | 05110              | ENGINE MOUNTS<br>69 032 LINCOLN        | 01 CONTINENTAL    | 03 C                    | 076619                | 90027012       |
| COMPLETE SEPARATION OF RUBBER FROM METAL PORTION OF MOTOR MOUNT      |                   |                  |                    |                                        |                   |                         |                       |                |
| 50018                                                                | P01574 C          | 760512           | 05110              | ENGINE MOUNTS<br>69 032 LINCOLN        | 01 CONTINENTAL    | 03 C                    | 076619                | 90027012       |
| COMPLETE SEPARATION OF RUBBER FROM METAL PORTION OF MOTOR MOUNT      |                   |                  |                    |                                        |                   |                         |                       |                |
| 40001                                                                | P01320 B          | 760320           | 05110              | ENGINE MOUNTS<br>69 033 MERCURY        | 04 MERCURY        | 21 C                    | 000000                | 13901005       |
| RUBBER SEPARATED FROM METAL PORTION OF MOUNT                         |                   |                  |                    |                                        |                   |                         |                       |                |
| 50006                                                                | P01486 B          | 760412           | 05110              | ENGINE MOUNTS<br>00 040 GENERAL MOTORS | 00 GENERAL MOTORS | 09 C                    | 000000                | 91605014       |
| RUBBER SEPARATED FROM METAL ON REAR MOTOR MOUNT                      |                   |                  |                    |                                        |                   |                         |                       |                |
| 50023                                                                | P01617 B          | 760607           | 05110              | ENGINE MOUNTS<br>00 040 GENERAL MOTORS | 00 GENERAL MOTORS | 03 C                    | 000000                | 91605014       |
| RUBBER SEPARATED FROM MT BOTTOM PLATE W/ ONE LARGE STUD IS BENT      |                   |                  |                    |                                        |                   |                         |                       |                |
| 50023                                                                | P01616 B          | 760607           | 05110              | ENGINE MOUNTS<br>00 040 GENERAL MOTORS | 00 GENERAL MOTORS | 57 C                    | 000000                | 91605014       |
| MOUNT IN GO COND CUSHION SLIGHTLY COMPRESSED REAR MT POSS FOR A TRAN |                   |                  |                    |                                        |                   |                         |                       |                |
| 30022                                                                | P01217 B          | 760214           | 05110              | ENGINE MOUNTS<br>62 041 BUICK          | 00 BUICK          | 03 C                    | 036370                | 98126073       |
| RUBBER PORTION BROKE ON BOTH MOUNTS                                  |                   |                  |                    |                                        |                   |                         |                       |                |

PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06 PAGE 0059

SORTED BY COMPONENT, MODEL, MDL YR

| BIN NUMBER | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                  | MAKE-MODEL           | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------|-------------------|------------------|--------------------|----------------------------------------------------|----------------------|-------------------------|-----------------------|----------------|
| 50007      | P01492 B          | 760414           | 05110              | ENGINE MOUNTS<br>65 041 BUICK                      | 00 BUICK             | 03 C                    | 081292                | 85004002       |
|            |                   |                  |                    | RUBBER SEPARATED FROM METAL ON ENG MOUNTS          |                      |                         |                       |                |
| 20013      | P00952 B          | 751024           | 05110              | ENGINE MOUNTS<br>65 041 BUICK                      | 04 LE SABRE          | 08 C                    | 000000                | 60626008       |
|            |                   |                  |                    | MOTOR MOUNT SPLIT (A2-58)                          |                      |                         |                       |                |
| 20001      | P00468 B          | 750708           | 05110              | ENGINE MOUNTS<br>68 041 BUICK                      | 04 LE SABRE          | 03 A                    | 056420                | 063105001      |
|            |                   |                  |                    | ENGINE MOUNTS BROKE CAUSING THROTTLE TO STICK      |                      |                         |                       |                |
| 50003      | P01456 C          | 760402           | 05110              | ENGINE MOUNTS<br>00 041 BUICK                      | 05 RIVIERA           | 21 C                    | 000000                | 98126073       |
|            |                   |                  |                    | SEPARATION OF RUBBER FROM METAL ON MOTOR MOUNT     |                      |                         |                       |                |
| 50003      | P01456 B          | 760402           | 05110              | ENGINE MOUNTS<br>00 041 BUICK                      | 05 RIVIERA           | 21 C                    | 000000                | 98126073       |
|            |                   |                  |                    | SEPARATION FROM RUBBER AROUND METAL ON MOTOR MOUNT |                      |                         |                       |                |
| 20001      | P00466 B          | 750708           | 05110              | ENGINE MOUNTS<br>70 041 BUICK                      | 05 RIVIERA           | 03 A                    | 025603                | 063105001      |
|            |                   |                  |                    | ENGINE MOUNTS BROKE CAUSING THROTTLE TO STICK      |                      |                         |                       |                |
|            | P00448 B          | 750722           | 05110              | ENGINE MOUNTS<br>65 041 BUICK                      | 08 WILDCAT           | 03 B                    | 000000                | 094133032      |
|            |                   |                  |                    | ENGINE MOUNT BROKE CAUSING THROTTLE TO STICK       |                      |                         |                       |                |
| 30004      | P01044 B          | 751122           | 05110              | ENGINE MOUNTS<br>72 042 CADILLAC DIVISION          | A1 CADILLAC-CALAIS   | 03 C                    | 035500                | 19020002       |
|            |                   |                  |                    | RUBBER PORTION OF ENG MOUNT SEPARATED FROM METAL   |                      |                         |                       |                |
| 40005      | P01378 C          | 760330           | 05110              | ENGINE MOUNTS<br>70 042 CADILLAC DIVISION          | B1 CADILLAC-DE VILLE | 03 C                    | 057478                | 29611001       |
|            |                   |                  |                    | RUBBER SEPARATED FROM METAL (LEFT SIDE)            |                      |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0060

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| B IN<br>NUMBER | PRP I<br>NUMBER | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                               | MAKE-MODEL              | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|----------------|-----------------|------------------|--------------------|-----------------------------------------------------------------|-------------------------|-------------------------|-----------------------|----------------|
| 40005          | P01378 B        | 760330           | 05110              | ENGINE MOUNTS<br>70 042 CADILLAC DIVISION                       | B1 CADILLAC-DE VILLE    | 03 C                    | 057478                | 29611001       |
|                |                 |                  |                    | RUBBER SEPARATED FROM METAL (RIGHT SIDE)                        |                         |                         |                       |                |
| 50017          | P01571 B        | 760512           | 05110              | ENGINE MOUNTS<br>70 042 CADILLAC DIVISION                       | 01 CADILLAC             | 03 C                    | 079703                | 90027012       |
|                |                 |                  |                    | STUD BROKE FROM BOTTOM OF ENGINE MOUNT                          |                         |                         |                       |                |
| 40003          | P01356 B        | 760329           | 05110              | ENGINE MOUNTS<br>72 043 CHEVROLET DIVISION                      | A2 CHEVELLE-MALIBU      | 03 C                    | 032000                | 53140014       |
|                |                 |                  |                    | METAL SEPARATED FROM RUBBER                                     |                         |                         |                       |                |
| 30022          | P01273 B        | 760306           | 05110              | ENGINE MOUNTS<br>71 043 CHEVROLET DIVISION                      | B0 EL CAMINO            | 03 C                    | 086572                | 30501001       |
|                |                 |                  |                    | TWO-THIRDS SEPARATION OF METAL & RUBBER                         |                         |                         |                       |                |
| 40005          | P01377 C        | 760330           | 05110              | ENGINE MOUNTS<br>71 043 CHEVROLET DIVISION                      | C4 NOVA                 | 03 C                    | 002033                | 90027012       |
|                |                 |                  |                    | RUBBER SEPARATED FROM METAL (LEFT SIDE)                         |                         |                         |                       |                |
| 40005          | P01377 B        | 760330           | 05110              | ENGINE MOUNTS<br>71 043 CHEVROLET DIVISION                      | C4 NOVA                 | 03 C                    | 002033                | 90027012       |
|                |                 |                  |                    | RUBBER SEPARATED FROM METAL (RIGHT SIDE)                        |                         |                         |                       |                |
| 30003          | P01030 B        | 751122           | 05110              | ENGINE MOUNTS<br>68 043 CHEVROLET DIVISION                      | D3 CAPRICE              | 03 C                    | 062597                | 46204013       |
|                |                 |                  |                    | ENG MOUNT, RUBBER PORTION SEPARATED FROM METAL-RECALLED 71-0235 |                         |                         |                       |                |
| 40005          | P01375 B        | 760330           | 05110              | ENGINE MOUNTS<br>69 043 CHEVROLET DIVISION                      | E0 PICK-UP MODELS<br>PU | 03 C                    | 078564                | 90027012       |
|                |                 |                  |                    | RUBBER SEPARATED FROM METAL ON MOTOR MOUNTS                     |                         |                         |                       |                |
| 50017          | P01570 C        | 760512           | 05110              | ENGINE MOUNTS<br>63 043 CHEVROLET DIVISION                      | E3 IMPALA               | 03 C                    | 079265                | 90027012       |
|                |                 |                  |                    | RUBBER SEPARATED FROM METAL PORTION OF REAR MOTOR MOUNT         |                         |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0061

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | D<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>MANUFACTURER          | MAKE-MODEL            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|---------------|-----------------------|--------------------|--------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 50017                                                                  | P01570 D      | 760512                | 05110              | ENGINE MOUNTS<br>63 043 CHEVROLET DIVISION | E3 IMPALA             | 03 C                    | 079265                | 90027012       |
| RUBBER SEPARATED FROM METAL PORTION OF MOUNT STANDARD V-8 MOUNT        |               |                       |                    |                                            |                       |                         |                       |                |
| 50017                                                                  | P01570 E      | 760512                | 05110              | ENGINE MOUNTS<br>63 043 CHEVROLET DIVISION | E3 IMPALA             | 03 C                    | 079265                | 90027012       |
| SEPARATION OF RUBBER FROM METAL PORTION OF MOUNT STANDARD V-8 MOUNT    |               |                       |                    |                                            |                       |                         |                       |                |
| 30024                                                                  | P01295 B      | 760301                | 05110              | ENGINE MOUNTS<br>70 043 CHEVROLET DIVISION | E3 IMPALA             | 08 C                    | 085549                | 29611001       |
| RUBBER PARTIALLY SEPARATED FROM METAL A2-58 (RECALL 71-0235)           |               |                       |                    |                                            |                       |                         |                       |                |
| 20009                                                                  | P00848 B      | 750919                | 05110              | ENGINE MOUNTS<br>70 043 CHEVROLET DIVISION | E3 IMPALA             | 03 C                    | 013088                | 024017016      |
| ENGINE MOUNTS BROKE                                                    |               |                       |                    |                                            |                       |                         |                       |                |
| 30022                                                                  | P01187 B      | 760214                | 05110              | ENGINE MOUNTS<br>72 043 CHEVROLET DIVISION | E3 IMPALA             | 03 C                    | 085767                | 96126073       |
| RUBBER PARTIALLY SEPARATED FROM ONE MOUNT, OTHER COMPLETELY FROM METAL |               |                       |                    |                                            |                       |                         |                       |                |
| 50023                                                                  | P01615 B      | 760607                | 05110              | ENGINE MOUNTS<br>00 043 CHEVROLET DIVISION | 00 CHEVROLET DIVISION | 03 C                    | 000000                | 91605014       |
| RUBBER SEPARATED FROM METAL CHEVY SAFETY TYPE MT NO CARD WITH PART     |               |                       |                    |                                            |                       |                         |                       |                |
| 50023                                                                  | P01614 B      | 760607                | 05110              | ENGINE MOUNTS<br>00 043 CHEVROLET DIVISION | 00 CHEVROLET DIVISION | 03 C                    | 000000                | 91605014       |
| RUBBER SEPARATED FROM METAL CHEVY SAFETY TYPE MT NO CARD WITH PART     |               |                       |                    |                                            |                       |                         |                       |                |
| 30018                                                                  | P01253 B      | 760203                | 05110              | ENGINE MOUNTS<br>67 043 CHEVROLET DIVISION | 02 CHEVELLE           | 08 C                    | 068559                | 029611001      |
| RUBBER PORTION OF MOUNT CRACKED AND SEPARATED DUE TO EXCESSIVE FORCE   |               |                       |                    |                                            |                       |                         |                       |                |
| 30018                                                                  | P01253 C      | 760203                | 05110              | ENGINE MOUNTS<br>67 043 CHEVROLET DIVISION | 02 CHEVELLE           | 08 C                    | 068559                | 029611001      |
| RUBBER PORTION OF MOUNT CRACKED AND SEPARATED DUE TO EXCESSIVE FORCE   |               |                       |                    |                                            |                       |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0062

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, YR

| BIN NUMBER | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME<br>YR MANUFACTURER                                                                                 | MAKE-MODEL   | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------|------------|-----------------|-----------------|-------------------------------------------------------------------------------------------------------------------|--------------|-------------------------|-----------------------|----------------|
| 40008      | P01405 B   | 760331          | 05110           | ENGINE MOUNTS<br>71 043 CHEVROLET DIVISION                                                                        | 02 CHEVELLE  | 03 C                    | 000000                | 20009003       |
| 40008      | P01405 C   | 760331          | 05110           | RUBBER PORTION OF MOTOR MOUNT SEPARATED FROM METAL<br>ENGINE MOUNTS<br>71 043 CHEVROLET DIVISION                  | 02 CHEVELLE  | 03 C                    | 000000                | 20009003       |
| 50002      | P01450 B   | 760401          | 05110           | RUBBER SEPARATED FROM METAL<br>ENGINE MOUNTS<br>72 043 CHEVROLET DIVISION                                         | 02 CHEVELLE  | 03 C                    | 000000                | 31204007       |
| 50006      | P01485 C   | 760412          | 05110           | SEPARATION OF RUBBER FROM METAL ON MOTOR MOUNT<br>ENGINE MOUNTS<br>00 043 CHEVROLET DIVISION                      | 03 CHEVROLET | 09 C                    | 000000                | 91605014       |
| 50006      | P01485 B   | 760412          | 05110           | RUBBER SEPARATED FROM METAL ON MOTOR MOUNTS-FRONT<br>ENGINE MOUNTS<br>00 043 CHEVROLET DIVISION                   | 03 CHEVROLET | 09 C                    | 000000                | 91605014       |
| 50018      | P01573 B   | 760512          | 05110           | RUBBER SEPARATED FROM METAL ON MOTOR MOUNTS-FRONT<br>ENGINE MOUNTS<br>66 043 CHEVROLET DIVISION                   | 03 CHEVROLET | 03 C                    | 075964                | 90027012       |
| 30006      | P01077 B   | 751224          | 05110           | COMPLETE SEPARATION OF RUBBER FROM METAL-RECALL 71-0235 (A2-58)<br>ENGINE MOUNTS<br>66 043 CHEVROLET DIVISION     | 03 CHEVROLET | 03 C                    | 087428                | 98126073       |
| 30006      | P01094 B   | 751124          | 05110           | RECALLED 71-0235-RUBBER ON ENG MOUNT TORN COMPLETELY FROM BASE A258<br>ENGINE MOUNTS<br>66 043 CHEVROLET DIVISION | 03 CHEVROLET | 03 C                    | 087428                | 98126073       |
| 50003      | P01457 B   | 760402          | 05110           | RUBBER CRACKED EXTENSIVELY WOULD FAIL W/CONTINUED USE-710235-A258<br>ENGINE MOUNTS<br>67 043 CHEVROLET DIVISION   | 03 CHEVROLET | 21 C                    | 064010                | 98126073       |
|            |            |                 |                 | SEPARATION OF RUBBER FROM METAL ON ENGINE MOUNT =A258 C RECALL 71-0235                                            |              |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0063

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MILE YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER          | MAKE-MODEL                    | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|---------------|-----------------------|--------------------|--------------------------------------------|-------------------------------|-------------------------|-----------------------|----------------|
| 50003                                                                  | P01457        | C 760402              | 05110              | ENGINE MOUNTS<br>67 043 CHEVROLET DIVISION | 03 CHEVROLET                  | 21                      | C 064010              | 98126073       |
| SEPARATION OF RUBBER FROM METAL ON ENGINE MOUNT=A258 & RECALL 71-0235  |               |                       |                    |                                            |                               |                         |                       |                |
| 20010                                                                  | P00922        | B 751020              | 05110              | ENGINE MOUNTS<br>70 043 CHEVROLET DIVISION | 03 CHEVROLET                  | 03                      | C 097000              | 033145005      |
| MOTOR MOUNTS BROKE, SEPARATION OF RUBBER FROM METAL (A2-58)            |               |                       |                    |                                            |                               |                         |                       |                |
| 20013                                                                  | P00932        | B 751024              | 05110              | ENGINE MOUNTS<br>70 043 CHEVROLET DIVISION | 03 CHEVROLET                  | 03                      | C 000000              | 60626008       |
| CRACK IN ENGINE MOUNT (A2-58)                                          |               |                       |                    |                                            |                               |                         |                       |                |
| 50021                                                                  | P01598        | B 760607              | 05110              | ENGINE MOUNTS<br>74 043 CHEVROLET DIVISION | 09 VEGA                       | 03                      | C 040210              | 98126073       |
| RUBBER BEGINNING TO SEPARATE FROM METAL                                |               |                       |                    |                                            |                               |                         |                       |                |
| 40003                                                                  | P01351        | C 760329              | 05110              | ENGINE MOUNTS<br>72 043 CHEVROLET DIVISION | 9A CHEVROLET TRUCK AN<br>C-30 | 03                      | C 050000              | 52404002       |
| RUBBER SEPARATED FROM METAL - MOTOR MOUNTS BROKE                       |               |                       |                    |                                            |                               |                         |                       |                |
| 40003                                                                  | P01351        | B 760329              | 05110              | ENGINE MOUNTS<br>72 043 CHEVROLET DIVISION | 9A CHEVROLET TRUCK AN<br>C-30 | 03                      | C 050000              | 52404002       |
| RUBBER SEPARATED FROM METAL - MOTOR MOUNTS BROKE                       |               |                       |                    |                                            |                               |                         |                       |                |
| 50018                                                                  | P01572        | C 760512              | 05110              | ENGINE MOUNTS<br>69 044 OLDSMOBILE         | D1 CUTLASS-VSTA CRUSR         | 08                      | C 053006              | 90027012       |
| RUBBER PORTION IS CRACKED ALONG JOINT WITH METAL-RECALL 71-0235 (A258) |               |                       |                    |                                            |                               |                         |                       |                |
| 50018                                                                  | P01572        | B 760512              | 05110              | ENGINE MOUNTS<br>69 044 OLDSMOBILE         | D1 CUTLASS-VSTA CRUSR         | 08                      | C 053006              | 90027012       |
| RUBBER PORTION OF MOTOR MOUNT IS CRACKED AT METAL PORT-RECALL 71-0235  |               |                       |                    |                                            |                               |                         |                       |                |
| 40005                                                                  | P01376        | B 760330              | 05110              | ENGINE MOUNTS<br>7C 044 OLDSMOBILE         | 02 DELTA 88                   | 03                      | C 040673              | 90027012       |
| RUBBER SEPARATED FROM METAL ON MOTOR MOUNTS                            |               |                       |                    |                                            |                               |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0064

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                           | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                 | MAKE-MODEL                  | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SMCP<br>NUMBER |
|-------------------------------------------------------------------------|---------------|--------|------------------|--------------------|---------------------------------------------------|-----------------------------|-------------------------|-----------------------|----------------|
| 50013                                                                   | P01544        | C      | 760507           | 05110              | ENGINE MOUNTS<br>68 045 PONTIAC DIVISION          | C3 CATALINA                 | 03 C                    | 096285                | 54130001       |
| SEPARATION OF RUBBER FROM METAL PORTION OF MOUNT                        |               |        |                  |                    |                                                   |                             |                         |                       |                |
| 20016                                                                   | P00960        | B      | 751030           | 05110              | ENGINE MOUNTS<br>69 045 PONTIAC DIVISION          | D3 EXECUTIVE                | 03 C                    | 068797                | 030501001      |
| RUBBER SEPARATED FROM METAL, RUBBER SHOW CRACKS-BROKEN ON 1 SIDE        |               |        |                  |                    |                                                   |                             |                         |                       |                |
| 50008                                                                   | P01502        | B      | 760427           | 05110              | ENGINE MOUNTS<br>71 045 PONTIAC DIVISION          | E3 PONTIAC-GRAN VILLE       | 08 C                    | 054486                | 30501001       |
| RUBBER SPLIT AND SEPARATED FROM METAL                                   |               |        |                  |                    |                                                   |                             |                         |                       |                |
| 50008                                                                   | P01502        | C      | 760427           | 05110              | ENGINE MOUNTS<br>71 045 PONTIAC DIVISION          | E3 PONTIAC-GRAN VILLE       | 08 C                    | 054486                | 30501001       |
| RUBBER SPLIT AND SEPARATED FROM METAL                                   |               |        |                  |                    |                                                   |                             |                         |                       |                |
| 50003                                                                   | P01455        | B      | 760402           | 05110              | ENGINE MOUNTS<br>53 131 STUDEBAKER MOTORS         | 01 STUDEBAKER               | 21 C                    | 088387                | 92126073       |
| RUBBER PORTION OF ENG MOUNT FELL OFF FROM END OF SANDWICH TYPE MOUNT-L  |               |        |                  |                    |                                                   |                             |                         |                       |                |
| 50016                                                                   | P01561        | B      | 760512           | 05110              | ENGINE MOUNTS<br>74 152 AUDI NSU                  | B1 AUDI FOX                 | 03 C                    | 026439                | 90045061       |
| FRONT MOTOR MOUNT TORN IN TWO-MOUNT ALL METAL WITH NO RUBBER PORTION    |               |        |                  |                    |                                                   |                             |                         |                       |                |
| 20004                                                                   | P00725        | B      | 750808           | 05130              | ENGINE PULLEY, CRANKSHAFT<br>00 031 FORD DIVISION | 91 RANCHERO 500<br>RANCHERO | 03 C                    | 000000                | 000000000      |
| DAMPER ASSEMBLY BROKE KEY CONNECTING DAMPER TO CRANKSHAFT               |               |        |                  |                    |                                                   |                             |                         |                       |                |
| 50004                                                                   | PC1468        | B      | 760405           | 05140              | ENGINE FLYWHEEL<br>70 032 LINCOLN                 | 00 LINCOLN                  | 57 C                    | 064000                | 36108002       |
| SEVERAL TEETH WORN OFF FLYWHEEL-SEVERE WEAR ON 12 TEETH-LIGHTWEIGHT TYP |               |        |                  |                    |                                                   |                             |                         |                       |                |
| 20010                                                                   | P00927        | B      | 751020           | 05140              | ENGINE FLYWHEEL<br>70 041 BUICK                   | 06 SKYLARK                  | 08 C                    | 088700                | 60659011       |
| FLYWHEEL CRACKED-BOLTS NOT TORQUED PROPERLY-CRACK AROUND CENTER POLE    |               |        |                  |                    |                                                   |                             |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0065

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                        | MAKE-MODEL                     | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHIP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|--------------------------------------------------------------------------|--------------------------------|-------------------------|-----------------------|----------------|
| 40003         | P01364 B      | 760329                | 05150              | ENGINE-OTHER PARTS<br>72 010 AMERICAN MOTORS                             | 00 AMERICAN MOTORS             | 08 C                    | 000000                | 53140014       |
|               |               |                       |                    | VALVE SEALS ARE CRACKED                                                  |                                |                         |                       |                |
| 20013         | P00915 B      | 751020                | 05150              | ENGINE-OTHER PARTS<br>71 010 AMERICAN MOTORS                             | 01 AMBASSADOR                  | 49 C                    | 056000                | 53215010       |
|               |               |                       |                    | HOLE IN FREEZE PLUG LEAKED ENG COOLANT, HOLE CORRODED FROM W/IN ENG      |                                |                         |                       |                |
| 50005         | P01475 C      | 760408                | 05150              | ENGINE-OTHER PARTS<br>74 010 AMERICAN MOTORS                             | 05 HORNET                      | 33 C                    | 004800                | 44114014       |
|               |               |                       |                    | SHOP CLMS FROZEN EXHAUST VALVE CAUSED ROCKER ARM BREAK-NO WEAR APPARNT   |                                |                         |                       |                |
| 50005         | P01475 B      | 760408                | 05150              | ENGINE-OTHER PARTS<br>74 010 AMERICAN MOTORS                             | 05 HORNET                      | 03 C                    | 004800                | 44114014       |
|               |               |                       |                    | ROCKER ARM SHAFT BROKE AT R SHAFT STUD HOLE--SHOP BLAMES EXHST VLVE FRZN |                                |                         |                       |                |
| 30015         | P01236 B      | 760203                | 05150              | ENGINE-OTHER PARTS<br>75 022 DODGE                                       | 00 DODGE                       | 57 C                    | 000000                | 79605131       |
|               |               |                       |                    | VALVE SEAT AND STEM ARE WORN, SEAT EXCESSIVELY - VALVE FACE WARPED       |                                |                         |                       |                |
| 20007         | P00450 B      | 750722                | 05150              | ENGINE-OTHER PARTS<br>67 031 FORD DIVISION                               | 05 MUSTANG                     | 03 D                    | 064893                | 094133032      |
|               |               |                       |                    | OIL PUMP SHAFT BROKE                                                     |                                |                         |                       |                |
| 20007         | P00445 B      | 750722                | 05150              | ENGINE-OTHER PARTS<br>72 031 FORD DIVISION                               | 9A FORD TRUCK AND VAN          | 57 D                    | 000000                | 094133032      |
|               |               |                       |                    | ROCKER ARM STEM WORE EXCESSIVELY                                         |                                |                         |                       |                |
| 20017         | P00987 B      | 751114                | 05150              | ENGINE-OTHER PARTS<br>69 043 CHEVROLET DIVISION                          | E0 PICK-UP MODELS<br>C10 TRUCK | 00 C                    | 027431                | 80910024       |
|               |               |                       |                    | ONLY DISTRIBUTOR CASING SENT IN-SLIGHT WEAR ON SPLINES-NO CONCLUSION     |                                |                         |                       |                |
| 20011         | P00880 B      | 751008                | 05150              | ENGINE-OTHER PARTS<br>71 043 CHEVROLET DIVISION                          | E3 IMPALA                      | 14 C                    | 041256                | 611C7005       |
|               |               |                       |                    | ROCKER ARM METAL HARDNESS WRONG, PUSH ROD WENT THRU ROCKER               |                                |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0006

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YK

| BIN<br>NUMBER                                                           | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER               | MAKE-MODEL                         | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|-------------------------------------------------------------------------|-------------------|------------------|--------------------|-------------------------------------------------|------------------------------------|-------------------------|-----------------------|----------------|
| 20013                                                                   | P00914 B          | 751020           | 05150              | ENGINE-OTHER PARTS<br>72 043 CHEVROLET DIVISION | E3 IMPALA                          | 32 C                    | 045000                | 53215010       |
| OIL PRESSURE SENDING SWITCH LEAKS                                       |                   |                  |                    |                                                 |                                    |                         |                       |                |
| 30012                                                                   | P01177 B          | 760106           | 05150              | ENGINE-OTHER PARTS<br>72 043 CHEVROLET DIVISION | E3 IMPALA                          | 60 C                    | 055000                | 98105033       |
| WRONG SIZE CONNECTING ROD-TOO BIG-CAUSED BEARING FAILURE                |                   |                  |                    |                                                 |                                    |                         |                       |                |
| 50002                                                                   | P01440 B          | 760401           | 05150              | ENGINE-OTHER PARTS<br>74 043 CHEVROLET DIVISION | 01 CAMARO<br>2-28                  | 08 C                    | 012890                | 03060006       |
| VALVE SPRING CRACKED IN TWO PLACES-POSSIBLE ASSEMBLY DEFECT             |                   |                  |                    |                                                 |                                    |                         |                       |                |
| 30021                                                                   | P01276 B          | 760207           | 05150              | ENGINE-OTHER PARTS<br>00 043 CHEVROLET DIVISION | 03 CHEVROLET                       | 32 C                    | 000000                | 84111015       |
| OIL PRESSURE SWITCH LEAKS AT TOP                                        |                   |                  |                    |                                                 |                                    |                         |                       |                |
| 30002                                                                   | P01009 B          | 751118           | 05150              | ENGINE-OTHER PARTS<br>72 043 CHEVROLET DIVISION | 03 CHEVROLET                       | 57 C                    | 000000                | 15697025       |
| LOBES ON CAM SHOW EXCESSIVE WEAR-HEAT MARKS ON CAM LIFTER-BOTTOMS WORN  |                   |                  |                    |                                                 |                                    |                         |                       |                |
| 20010                                                                   | P00921 B          | 751020           | 05150              | ENGINE-OTHER PARTS<br>71 043 CHEVROLET DIVISION | 9A CHEVROLET TRUCK AN<br>30 SERIES | 57 C                    | 014750                | 22601028       |
| CAMSHAFT LOBES SHOW EXCESSIVE WEAR-ROUNDED,LIFTERS DISHED ON BOTTOM     |                   |                  |                    |                                                 |                                    |                         |                       |                |
| 30007                                                                   | P01106 B          | 751226           | 05150              | ENGINE-OTHER PARTS<br>70 044 OLDSMOBILE         | 06 98                              | 32 C                    | 045000                | 19802003       |
| OIL PRESSURE SWITCH LEAKS EITHER FROM PLASTIC/METAL JOINT AT END/MIDDLE |                   |                  |                    |                                                 |                                    |                         |                       |                |
| 30007                                                                   | P01105 B          | 751224           | 05150              | ENGINE-OTHER PARTS<br>69 045 PONTIAC DIVISION   | A3 BONNEVILLE                      | 28 C                    | 000000                | 19802003       |
| OIL PRESSURE SWITCH INOPERATIVE-POSSIBLE LEAK AT BASE                   |                   |                  |                    |                                                 |                                    |                         |                       |                |
| 30007                                                                   | P01104 B          | 751224           | 05150              | ENGINE-OTHER PARTS<br>70 045 PONTIAC DIVISION   | A3 BONNEVILLE                      | 32 C                    | 000000                | 19802003       |
| OIL PRESSURE SWITCH LEAKS OIL-NO EVIDENCE OF METAL CRACKS-CAUSE UNKNOWN |                   |                  |                    |                                                 |                                    |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0067

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                        | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                      | MAKE-MODEL                    | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|----------------------------------------------------------------------|---------------|--------|------------------|--------------------|--------------------------------------------------------|-------------------------------|-------------------------|-----------------------|----------------|
| 30017                                                                | P01246        | B      | 760203           | 05150              | ENGINE-OTHER PARTS<br>73 045 PONTIAC DIVISION          | C3 CATALINA                   | 08 C                    | 021220                | 80910024       |
| DEFECT AT O RINGSEAT - SLIGHT CRACKS ON INSIDE OF ALUMINUM HOUSING   |               |        |                  |                    |                                                        |                               |                         |                       |                |
| 20004                                                                | P00453        | B      | 750721           | 05150              | ENGINE-OTHER PARTS<br>72 045 PONTIAC DIVISION          | 02 GRAND PRIX                 | 57 D                    | 051280                | 027105003      |
| VALVE LIFTER WORE EXCESSIVELY                                        |               |        |                  |                    |                                                        |                               |                         |                       |                |
| 30005                                                                | P01068        | B      | 751206           | 05150              | ENGINE-OTHER PARTS<br>73 045 PONTIAC DIVISION          | 03 PONTIAC                    | 57 C                    | 051312                | 33528027       |
| CAM SHOWS EXCESSIVE WEAR ON HALF OF LOBE, 2 EXTREME WEAR-HEAT DAMAGE |               |        |                  |                    |                                                        |                               |                         |                       |                |
| 30001                                                                | P01220        | B      | 760123           | 05150              | ENGINE-OTHER PARTS<br>71 163 FIAT S.P.A.               | 02 FIAT 850 SPIDER            | 03 C                    | 005230                | 67211009       |
| CRANKSHAFT BROKE ON MAIN BODY BETWEEN MAIN AND ROD BEARINGS          |               |        |                  |                    |                                                        |                               |                         |                       |                |
| 30023                                                                | P01289        | B      | 760214           | 05150              | ENGINE-OTHER PARTS<br>71 176 TOYOTA MOTOR CO LTD       | 02 TOYOTA COROLLA<br>2 TC     | 03 C                    | 110352                | 02140002       |
| CAMSHAFT BROKEN IN TWO - NEAR BEARING                                |               |        |                  |                    |                                                        |                               |                         |                       |                |
| 20013                                                                | P00942        | B      | 751024           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>00 000 UNKNOWN         | 00 UNKNOWN                    | 57 C                    | 000000                | 58626006       |
| TIMING GEAR WORN                                                     |               |        |                  |                    |                                                        |                               |                         |                       |                |
| 40003                                                                | P01358        | B      | 760329           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>00 010 AMERICAN MOTORS | 00 AMERICAN MOTORS<br>RAMBLER | 21 C                    | 085000                | 53140014       |
| TEETH ARE STRIPPED OFF TIMING GEAR                                   |               |        |                  |                    |                                                        |                               |                         |                       |                |
| 40003                                                                | P01363        | B      | 760329           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>73 010 AMERICAN MOTORS | 07 MATADOR                    | 51 C                    | 036000                | 53140014       |
| TIMING GEAR CHAIN POSS STRETCHED                                     |               |        |                  |                    |                                                        |                               |                         |                       |                |
| 40003                                                                | P01359        | B      | 760329           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>74 010 AMERICAN MOTORS | 07 MATADOR                    | 51 C                    | 048000                | 53140014       |
| TIMING CHAIN APPEARS NORMAL                                          |               |        |                  |                    |                                                        |                               |                         |                       |                |

# PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06

PAGE 0068

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                          | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                         | MAKE-MODEL        | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|-------------------|------------------|--------------------|-----------------------------------------------------------|-------------------|-------------------------|-----------------------|----------------|
| 40007                                                                  | P01414 C          | 760331           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>72 021 CHRYSLER DIVISION  | A1 NEWPORT        | 57 C                    | 043487                | 60626008       |
| TIMING CHAIN HAS EXCESSIVE WEAR                                        |                   |                  |                    |                                                           |                   |                         |                       |                |
| 40007                                                                  | P01414 B          | 760331           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>72 021 CHRYSLER DIVISION  | A1 NEWPORT        | 57 C                    | 043487                | 60626008       |
| 50002                                                                  | P01443 B          | 760401           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>74 031 FORD DIVISION      | D5 MUSTANG II     | 34 C                    | 042000                | 63111009       |
| PLASTIC COATING ON TEETH WORN AWAY-9 TEETH BROKEN EXCESS WEAR ON OTHER |                   |                  |                    |                                                           |                   |                         |                       |                |
| 40002                                                                  | P01339 B          | 760324           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>65 031 FORD DIVISION      | 03 FORD<br>500    | 57 C                    | 089000                | 92632025       |
| EXCESS WEAR ON PLASTIC COVERING OVER CAM GEAR TEETH                    |                   |                  |                    |                                                           |                   |                         |                       |                |
| 20013                                                                  | P00943 B          | 751024           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>C0 040 GENERAL MOTORS     | 00 GENERAL MOTORS | 03 C                    | 000000                | 60626008       |
| CAM GEAR WORN                                                          |                   |                  |                    |                                                           |                   |                         |                       |                |
| 1                                                                      | P00881 B          | 751008           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>69 041 BUICK              | A2 CENTURY 350    | 03 C                    | 063530                | 61107005       |
| PLASTIC PART OF CAMSHAFT SPROCKET BROKE                                |                   |                  |                    |                                                           |                   |                         |                       |                |
| 30002                                                                  | P01026 B          | 751119           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>67 042 CADILLAC DIVISION  | 01 CADILLAC       | 57 C                    | 075069                | 29611001       |
| PLASTIC GONE FROM CAM GEAR TIMING GEAR-TEETH EXCESSIVE WEAR-POOR LUBE  |                   |                  |                    |                                                           |                   |                         |                       |                |
| 20011                                                                  | P00882 B          | 751008           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>71 043 CHEVROLET DIVISION | C4 NOVA           | 03 C                    | 046464                | 61107005       |
| PLASTIC ON RIM OF CAMSHAFT BROKE OFF                                   |                   |                  |                    |                                                           |                   |                         |                       |                |
| 40001                                                                  | P01317 B          | 760320           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>73 043 CHEVROLET DIVISION | E0 PICK-UP MODELS | 57 C                    | 051000                | 95670006       |
| 1 GEAR DAMAGED-3 GEARS & 4 TENSIONERS SHOW EXCESS WEAR-2 CHAINS GOOD   |                   |                  |                    |                                                           |                   |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0069

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN NUMBER                                                             | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                         | MAKE-MODEL            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|-------------------|------------------|--------------------|-----------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 20011                                                                  | P00878 B          | 751006           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>70 043 CHEVROLET DIVISION | E3 IMPALA             | 03 C                    | 000000                | 19963104       |
| NYLON TOOTH STUCK IN CHAIN CAUSING LOCK KNOCK NOISE                    |                   |                  |                    |                                                           |                       |                         |                       |                |
| 20011                                                                  | P00879 B          | 751006           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>71 043 CHEVROLET DIVISION | 9A CHEVROLET TRUCK AN | 03 C                    | 044420                | 19963104       |
| CHIPPED TOOTH STUCK IN CHAIN CAUSING LOUD TAPPING NOISE                |                   |                  |                    |                                                           |                       |                         |                       |                |
| 50013                                                                  | P01537 C          | 760507           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>70 045 PONTIAC DIVISION   | B4 LE MANS            | 57 C                    | 050563                | 33604002       |
| SOME WEAR IN TIMING CHAIN                                              |                   |                  |                    |                                                           |                       |                         |                       |                |
| 50013                                                                  | PC1537 B          | 760507           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>70 045 PONTIAC DIVISION   | B4 LE MANS            | 57 C                    | 050563                | 33604002       |
| PLASTIC TEETH WORN FROM GEAR UNDERLYING MTL TEETH EXTREMELY WORN       |                   |                  |                    |                                                           |                       |                         |                       |                |
| 50013                                                                  | P01544 B          | 760507           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>68 045 PONTIAC DIVISION   | C3 CATALINA           | 57 C                    | 096285                | 54130001       |
| PLASTIC TEETH ON CAM GEAR WORN AWAY - WEAR ON UNDERLYING METAL         |                   |                  |                    |                                                           |                       |                         |                       |                |
| 40006                                                                  | P01396 B          | 760331           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>70 045 PONTIAC DIVISION   | C3 CATALINA           | 57 C                    | 060390                | 63301003       |
| PLASTIC COATING OF CAM GEAR WORN AWAY-ALUMINUM TEETH SHOW WEAR         |                   |                  |                    |                                                           |                       |                         |                       |                |
| 50013                                                                  | P01545 B          | 760507           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>68 045 PONTIAC DIVISION   | D3 EXECUTIVE          | 57 C                    | 098267                | 54130001       |
| 70 PCT OF PLASTIC TEETH WORN FROM GEAR-WEAR ON UNDERLYING MTL TEETH    |                   |                  |                    |                                                           |                       |                         |                       |                |
| 50021                                                                  | P01592 C          | 760607           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>68 045 PONTIAC DIVISION   | D3 EXECUTIVE          | 57 C                    | 084627                | 29611001       |
| CHAIN SHOWS SOME WEAR AND LOOSENESS                                    |                   |                  |                    |                                                           |                       |                         |                       |                |
| 50021                                                                  | P01592 B          | 760607           | 05151              | ENGINE - TIMING GEAR & CHAIN<br>68 045 PONTIAC DIVISION   | D3 EXECUTIVE          | 57 C                    | 084627                | 29611001       |
| PLASTIC WORN AWAY FROM GEAR-WEAR ON MTL TEETH, COATED W/ HARDND OIL DP |                   |                  |                    |                                                           |                       |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0070

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>MANUFACTURER                                                                                                    | MAKE-MODEL                       | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|--------|------------------|--------------------|--------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|-------------------------|-----------------------|----------------|
| 20013         | P00920        | B      | 751020           | 05210              | ENGINE COOLING SYSTEM-RADIATOR<br>74 043 CHEVROLET DIVISION                                                                          | 02 CHEVELLE                      | 59 C                    | 043887                | 93725039       |
| 40004         | P01367        | C      | 760329           | 05210              | COPPER FITTING SEPARATED BRASS BODY OF TRANS COLLER,POSSIBLE LEAK<br>ENGINE COOLING SYSTEM-RADIATOR<br>71 151 ADAM OPEL AG           | C1 OPEL 1900                     | 10 C                    | 033384                | 45406009       |
| 50013         | P01538        | C      | 760507           | 05220              | RADIATOR SUPPORT MOUNT SEPARATED AT RUBBER JOINT<br>ENGINE COOLING SYSTEM-HOSES<br>73 032 LINCOLN                                    | A2 MARK IV                       | 08 C                    | 039965                | 33604002       |
| 50021         | P01594        | B      | 760607           | 05220              | HOSE SPLIT 2 INCHES FROM END 1/2 INCH IN LENGTH<br>ENGINE COOLING SYSTEM-HOSES<br>73 174 NISSAN MTR CO LTD                           | 91 PICKUP TRUCK                  | 06 C                    | 065155                | 67501001       |
| 30008         | P01108        | B      | 751226           | 05230              | WORN EXCESS IN ONE SPOT ONE IN LONG- DOES NOT APPEAR WORN THROUGH<br>ENGINE COOLING SYSTEM-PUMP,WATER<br>73 022 DODGE                | 9A DODGE TRUCK AND VA<br>8300    | 21 C                    | 040576                | 68510002       |
| 40004         | P01368        | B      | 760329           | 05230              | PULLEY HUB CAME LOOSE-FAN WENT INTO THE RADIATOR<br>ENGINE COOLING SYSTEM-PUMP,WATER<br>73 031 FORD DIVISION                         | 9A FORD TRUCK AND VAN<br>LN-7000 | 08 C                    | 052162                | 45406009       |
| 50022         | P01604        | B      | 760607           | 05230              | RUBBER CAP ON WATER PUMP CRACKED ABOVE CLAMP REPL PART NOT AVAILABLE<br>ENGINE COOLING SYSTEM-PUMP,WATER<br>69 041 BUICK             | 07 SPECIAL                       | 33 C                    | 000000                | 12601051       |
| P00717        | B             |        | 750805           | 05230              | SHAFT HARD TO TURN POSS BEARING/BUSHING TURNING W/SHAFT INSIDE CASE<br>ENGINE COOLING SYSTEM-PUMP,WATER<br>00 043 CHEVROLET DIVISION | A2 CHEVELLE-MALIBU               | 57 C                    | 000000                | 055805004      |
| 30009         | P01130        | B      | 751228           | 05240              | HUB FELL OFF WATER PUMP SHAFT (EXCESSIVE WEAR)<br>ENGINE COOLING SYSTEM-FAN<br>72 010 AMERICAN MOTORS                                | 04 GREMLIN                       | 03 C                    | 057416                | 90027012       |

1 BLADE OF 5 BLADE FAN BROKE-1 BLADE CORNER BENT-MAJOR PORTION MISSING

## PARTS RETURN PROGRAM

76/07/06 PAGE 0071

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                   | MAKE-MODEL                    | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|---------------|-----------------------|--------------------|--------------------------------------------------------|-------------------------------|-------------------------|-----------------------|----------------|
| 30025                                                                  | P01261        | B 760306              | 05240              | ENGINE COOLING SYSTEM-FAN<br>71 022 DODGE              | 02 CHARGER                    | 08 C                    | 000000                | 63123002       |
| CRACK EXTENDS FROM UNDER BRACKET TO BLADE SURFACE - FLEX METAL BLADES  |               |                       |                    |                                                        |                               |                         |                       |                |
| 40002                                                                  | P01342        | B 760324              | 05240              | ENGINE COOLING SYSTEM-FAN<br>72 022 DODGE              | 9A DODGE TRUCK AND VA<br>200  | 28 C                    | 041000                | 92632025       |
| FAN CLUTCH FROZEN - ASSEMBLY INOPERATIVE                               |               |                       |                    |                                                        |                               |                         |                       |                |
| 30017                                                                  | P01237        | B 760203              | 05240              | ENGINE COOLING SYSTEM-FAN<br>75 022 DODGE              | 91 B1 VAN COMPACT<br>B100 VAN | 02 C                    | 033375                | 79605131       |
| FAN BLADE NICKED AND BENT                                              |               |                       |                    |                                                        |                               |                         |                       |                |
| 20015                                                                  | P00963        | B 751030              | 05240              | ENGINE COOLING SYSTEM-FAN<br>72 031 FORD DIVISION      | 08 TORINO                     | 03 C                    | 080364                | 044046005      |
| FAN BLADE BROKE-SUPPORT WHICH ATTACHED BLADE TO HUB-METAL SPLIT        |               |                       |                    |                                                        |                               |                         |                       |                |
| 50012                                                                  | P01530        | B 760507              | 05240              | ENGINE COOLING SYSTEM-FAN<br>73 031 FORD DIVISION      | 08 TORINO                     | 03 C                    | 000000                | 44132015       |
| ONE OF 5 BLADE METAL FLEX FAN BROKE-OFF-FLEX PART CRKD FROM END TO CTR |               |                       |                    |                                                        |                               |                         |                       |                |
| 30001                                                                  | P01004        | B 751118              | 05240              | ENGINE COOLING SYSTEM-FAN<br>74 031 FORD DIVISION      | 9D F-500<br>F500              | 03 C                    | 051146                | 91401026       |
| FAN BROKE AT RIVET & BOLT HOLE-BLADE ON OPPOSITE SIDE ALSO BENT        |               |                       |                    |                                                        |                               |                         |                       |                |
| 20003                                                                  | P00475        | B 750708              | 05240              | ENGINE COOLING SYSTEM-FAN<br>66 041 BUICK              | 05 RIVIERA                    | 03 C                    | 000000                | 098499007      |
| ENG. COOLING FAN ASSEN. BROKE AT CONNECTING BOLTS                      |               |                       |                    |                                                        |                               |                         |                       |                |
| 50008                                                                  | P01509        | B 760422              | 05240              | ENGINE COOLING SYSTEM-FAN<br>70 042 CADILLAC DIVISION  | B1 CADILLAC-DE VILLE          | 03 C                    | 060140                | 23701047       |
| BLADE BROKE OFF ARM OF FLEX FAN                                        |               |                       |                    |                                                        |                               |                         |                       |                |
| 30025                                                                  | P01254        | B 760306              | 05240              | ENGINE COOLING SYSTEM-FAN<br>71 043 CHEVROLET DIVISION | 09 VEGA                       | 03 C                    | 044071                | 022152094      |
| TWO BLADES OF FOUR MISSING REMAINING ARE CRACKED                       |               |                       |                    |                                                        |                               |                         |                       |                |

PARTS RETURN PROGRAM

76/07/06 PAGE 0072

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE | COMPONENT<br>CLASS | COMPONENT<br>NAME                                                                 | YR<br>MANUFACTURER | MAKE-MODEL              | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------|--------------------|-----------------------------------------------------------------------------------|--------------------|-------------------------|-------------------------|-----------------------|----------------|
| 40004         | P01367        | B 760329  | 05240              | ENGINE COOLING SYSTEM-FAN<br>71 151 ADAM OPEL AG                                  |                    | C1 OPEL 1900            | 03 C                    | 033384                | 45406009       |
|               |               |           |                    | PLASTIC FAN BLADE IS BROKEN                                                       |                    |                         |                         |                       |                |
| 20016         | P00975        | B 751108  | 05250              | ENGINE COOLING SYSTEM-BELTS<br>74 033 MERCURY                                     |                    | 04 MERCURY              | 37 C                    | 026716                | 63105001       |
|               |               |           |                    | EXCESSIVE WEAR AT BUSHING WHERE IDLER PULLEY TURNS ON SHAFT                       |                    |                         |                         |                       |                |
| 20013         | P00909        | B 751020  | 05260              | ENGINE COOLING SYSTEM-THERMOSTAT<br>74 033 MERCURY                                |                    | 04 MERCURY              | 53 C                    | 012546                | 22203030       |
|               |               |           |                    | THERMOSTAT STUCK OPEN                                                             |                    |                         |                         |                       |                |
| 40006         | P01395        | B 760331  | 05260              | ENGINE COOLING SYSTEM-THERMOSTAT<br>69 044 OLDSMOBILE                             |                    | C2 DELTA 88-ROYALE      | 03 C                    | 082752                | 63301003       |
|               |               |           |                    | BRACKET FOR SPRING BASE SEPARATED FROM MAIN BODY OF THERMOSTAT                    |                    |                         |                         |                       |                |
| 20007         | P00817        | B 750825  | 05260              | ENGINE COOLING SYSTEM-THERMOSTAT<br>73 044 OLDSMOBILE                             |                    | 06 98                   | 21 C                    | 018409                | 000000000      |
|               |               |           |                    | THERMOSTAT CAME APART AND LOCKED IN CLOSED POSITION                               |                    |                         |                         |                       |                |
| 40005         | P01383        | B 760330  | 06112              | FUEL TANK ASSEMBLY-PIPE,FILLER-NECK<br>69 031 FORD DIVISION                       |                    | 02 FALCON               | 08 C                    | 000000                | 94101002       |
|               |               |           |                    | FILLER NECK WEATHERED AND CRACKED AT 45 DEGREE BEND                               |                    |                         |                         |                       |                |
|               | P01497        | B 760421  | 06112              | FUEL TANK ASSEMBLY-PIPE,FILLER-NECK<br>72 043 CHEVROLET DIVISION                  |                    | 80 EL CAMINO            | 03 C                    | 000000                | 68510002       |
|               |               |           |                    | FILLER NECK BROKE OFF (NO PART SENT)                                              |                    |                         |                         |                       |                |
| 30011         | P01219        | B 760123  | 06112              | FUEL TANK ASSEMBLY-PIPE,FILLER-NECK<br>71 122 BRITISH LEYLAND MOTOR CO 50 TRIUMPH |                    |                         | 08 C                    | 022000                | 20009003       |
|               |               |           |                    | THREE CRACKS IN FUEL HOSE                                                         |                    |                         |                         |                       |                |
| 20008         | P00837        | B 750905  | 06112              | FUEL TANK ASSEMBLY-PIPE,FILLER-NECK<br>72 163 FIAT S.P.A.                         |                    | 01 FIAT 124 SPORTS COUP | 08 C                    | 031679                | 093702030      |
|               |               |           |                    | FUEL TANK FILLER-NECK CRACKED-FUMES & GAS LEAKED INTO TRUNK                       |                    |                         |                         |                       |                |

## PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06

PAGE 0073

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                       | MAKE-MODEL                      | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|----------------------------------------------------------------------|---------------------------------|-------------------------|-----------------------|----------------|
| 40009         | P01403 B      | 760331                | 06112              | FUEL TANK ASSEMBLY-PIPE,FILLER-NECK<br>68 163 FIAT S.P.A.            | 04 FIAT 124 SPYDER              | 08 C                    | 000000                | 20009003       |
|               |               |                       |                    | HOSE HAS SERIES OF CRACKS CAUSING FUEL LEAKAGE                       |                                 |                         |                       |                |
| 30011         | P01218 B      | 760123                | 06112              | FUEL TANK ASSEMBLY-PIPE,FILLER-NECK<br>71 163 FIAT S.P.A.            | 04 FIAT 124 SPYDER              | 08 C                    | 000000                | 20009003       |
|               |               |                       |                    | NUMEROUS CRACKS IN FUEL TANK FILTER HOSE                             |                                 |                         |                       |                |
| 20009         | P00836 B      | 750905                | 06112              | FUEL TANK ASSEMBLY-PIPE,FILLER-NECK<br>72 174 NISSAN MTR CO LTD      | 01 DATSUN<br>240Z               | 08 C                    | 053393                | 093702030      |
|               |               |                       |                    | FUEL TANK FILLER NECK CRACKED-GAS FUMES ENTER PASSANGER COMPARTMENT  |                                 |                         |                       |                |
| 20001         | P00483 B      | 750715                | 06112              | FUEL TANK ASSEMBLY-PIPE,FILLER-NECK<br>72 174 NISSAN MTR CO LTD      | 01 DATSUN                       | 08 C                    | 040560                | 092655004      |
|               |               |                       |                    | FUEL TANK FILLER NECK CRACKED-FUEL LEAKAGE                           |                                 |                         |                       |                |
| 30000         | P01051 B      | 751120                | 06113              | FUEL TANK ASSEMBLY-TANK<br>73 163 FIAT S.P.A.                        | 01 FIAT                         | 49 C                    | 024256                | 90027012       |
|               |               |                       |                    | TANK HAS GROUPS OF SMALL PIN HOLES ON BOTTOM,APPEARS TO HAVE RUSTED  |                                 |                         |                       |                |
| 30007         | P01109 B      | 751226                | 06121              | FUEL EMISSION CONTROL-LINES,VAPOR VENT<br>73 022 DODGE               | 9A DODGE TRUCK AND VA<br>D100   | 49 C                    | 045321                | 68510002       |
|               |               |                       |                    | EXTERIOR OF METAL VENT LINE CORRODED THRU-LINE RUSTED THRU PASS AREA |                                 |                         |                       |                |
| 20008         | P00828 B      | 750827                | 06131              | FUEL LINES,METALLIC<br>72 022 DODGE                                  | 9A DODGE TRUCK AND VA<br>CUSTOM | 49 C                    | 041763                | 068510002      |
|               |               |                       |                    | FUEL VENT LINE RUSTED CAUSING FUEL VAPORS TO ENTER CAB.              |                                 |                         |                       |                |
| 20007         | P00715 B      | 750805                | 06131              | FUEL LINES,METALLIC<br>66 023 PLYMOUTH                               | A4 FURY I                       | 49 C                    | 000000                | 055805004      |
|               |               |                       |                    | GAS LINE RUSTED THROUGH                                              |                                 |                         |                       |                |
| 20011         | P00892 B      | 751010                | 06131              | FUEL LINES,METALLIC<br>62 033 MERCURY                                | 04 MERCURY                      | 49 C                    | 090465                | 61107005       |
|               |               |                       |                    | FUEL LINE RUSTED/CORRODED                                            |                                 |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0074

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                         | YR | MAKE-MODEL                 | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|--------|------------------|--------------------|------------------------------------------------------------------------|----|----------------------------|-------------------------|-----------------------|----------------|
| 20007         | P00714        | B      | 750805           | 06131              | FUEL LINES,METALLIC<br>67 045 PONTIAC DIVISION                         |    | C3 CATALINA                | 49 C                    | 050128                | 055805004      |
|               |               |        |                  |                    | GAS LINES RUSTED AND LEAKED                                            |    |                            |                         |                       |                |
| 20004         | P00456        | B      | 750725           | 06132              | FUEL LINES,HOSES,NON-METALLIC<br>71 023 PLYMOUTH                       |    | A6 VALIANT-DUSTER          | 08 C                    | 052824                | 063301003      |
|               |               |        |                  |                    | FUEL PUMP HOSE SPLIT NEAR DISTRIBUTOR AREA CAUSING LEAKAGE             |    |                            |                         |                       |                |
| 20011         | P00893        | B      | 751008           | 06132              | FUEL LINES,HOSES,NON-METALLIC<br>69 023 PLYMOUTH                       |    | E4 FURY-SUBURBAN           | 32 C                    | 048539                | 01230005       |
|               |               |        |                  |                    | FUEL LINES LEAKS-CAR STOPPED OPERATING                                 |    |                            |                         |                       |                |
|               | P01049        | B      | 751112           | 06132              | FUEL LINES,HOSES,NON-METALLIC<br>76 043 CHEVROLET DIVISION             |    | 01 CAMARO                  | 09 C                    | 000000                | 22150084       |
|               |               |        |                  |                    | GAS LINE SEVERED FROM OBJECT IN RD. BOUNCING UP, STRIKING FUEL LINE    |    |                            |                         |                       |                |
| 20013         | P00967        | B      | 751030           | 06132              | FUEL LINES,HOSES,NON-METALLIC<br>71 045 PONTIAC DIVISION               |    | A4 TEMPEST/LEMANS GTO      | 06 C                    | 058642                | 90027012       |
|               |               |        |                  |                    | FUEL HOSE AT TANK-HOSE RUBBED AGAINSTS BRAKE CINE ON REAR END-LEAKS    |    |                            |                         |                       |                |
| 20007         | P00826        | B      | 750827           | 06132              | FUEL LINES,HOSES,NON-METALLIC<br>67 154 DAIMLER-BENZ AG                |    | 01 MERCEDES-BENZ           | 09 C                    | 075729                | 068510002      |
|               |               |        |                  |                    | FUEL HOSE CUT/TORN UNDER CLAMP                                         |    |                            |                         |                       |                |
| 20008         | P00835        | B      | 750905           | 06132              | FUEL LINES,HOSES,NON-METALLIC<br>67 174 NISSAN MTR CO LTD              |    | 01 DATSUN<br>SPL 311 1600  | 10 C                    | 074713                | 093702020      |
|               |               |        |                  |                    | FUEL LINE TO FUEL PUMP DETERIORATED FROM ACID-BATTERY MOUNTED OVERLINE |    |                            |                         |                       |                |
| DOT1          | P01194        | B      | 760118           | 06132              | FUEL LINES,HOSES,NON-METALLIC<br>71 174 NISSAN MTR CO LTD              |    | 06 DATSUN-510,PL510<br>510 | 32 C                    | 022676                | 90027012       |
|               |               |        |                  |                    | HOSE LEAKING-POSSIBLY DUE TO POSITION OF CLAMP                         |    |                            |                         |                       |                |
| 50007         | P01496        | B      | 760419           | 06136              | FUEL PUMP<br>63 631 FORD DIVISION                                      |    | 03 FORD                    | 03 C                    | 098209                | 68510002       |
|               |               |        |                  |                    | FUEL PUMP RETURN SPRING BROKE AND FELL OFF                             |    |                            |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0075

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER                                                          | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                          | MAKE-MODEL          | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|-------------------|------------------|--------------------|------------------------------------------------------------|---------------------|-------------------------|-----------------------|----------------|
| 40006                                                                  | P01400 B          | 760331           | 06136              | FUEL PUMP<br>72 043 CHEVROLET DIVISION                     | C4 NOVA             | 28 C                    | 016714                | 633C1CC5       |
| NO EXTERNAL DEFECTS DIAPHRAM ACTION IS GOOD POSS INTERNAL MALFUNCTION  |                   |                  |                    |                                                            |                     |                         |                       |                |
| 30017                                                                  | P01242 B          | 760203           | 06136              | FUEL PUMP<br>66 045 PONTIAC DIVISION                       | C3 CATALINA         | 32 C                    | 066740                | 198G20G3       |
| DIAPHRAM WEAK - POSSIBLY RUPTURED AND LEAKING                          |                   |                  |                    |                                                            |                     |                         |                       |                |
| 20007                                                                  | P00821 B          | 750827           | 06210              | CARBURETOR,UNKNOWN TYPE<br>74 174 NISSAN MTR CO LTD        | 01 DATSUN           | 26 C                    | 022675                | 090027012      |
| CARBURETOR FLOAT SINKS CAUSING ENGINE TO FLOOD                         |                   |                  |                    |                                                            |                     |                         |                       |                |
| 40007                                                                  | P01412 B          | 760401           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>74 023 PLYMOUTH      | E6 VALIANT-SCAMP    | 07 C                    | 030935                | 23513001       |
| FLOAT BROKEN-FLOAT MATERIAL HAS ABSORBED FUEL CAUSING FLOODING OF CARB |                   |                  |                    |                                                            |                     |                         |                       |                |
| 30012                                                                  | P01181 B          | 760107           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>70 023 PLYMOUTH      | 00 PLYMOUTH         | 32 C                    | 025817                | 85004002       |
| FLOAT LEAKS GAS TO INSIDE-SINKS,CAUSING FLOATING-POSSIBLE LEAK         |                   |                  |                    |                                                            |                     |                         |                       |                |
| 30010                                                                  | P01143 B          | 751229           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>74 031 FORD DIVISION | D5 MUSTANG II       | 07 C                    | 014000                | 97266002       |
| FLOATS ARE SOAKING UP GAS IN USE-PROBABLY WOULD SINK-CAUSING FLOODING  |                   |                  |                    |                                                            |                     |                         |                       |                |
| 30013                                                                  | P01200 B          | 760123           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>71 031 FORD DIVISION | G3 FORD-LTD         | 08 C                    | 042675                | 00000000       |
| DIAPHRAM RUPTURE CAUSING FLOODING AND EXCESSIVE FUEL CONSUMPTION       |                   |                  |                    |                                                            |                     |                         |                       |                |
| 30013                                                                  | P01198 B          | 760123           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>73 031 FORD DIVISION | G3 FORD-LTD         | 08 C                    | 022500                | 00000000       |
| DIAPHRAM RUPTURE CAUSING FLOODING AND HIGH FUEL CONSUMPTION            |                   |                  |                    |                                                            |                     |                         |                       |                |
| 30013                                                                  | P01199 B          | 760123           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>64 031 FORD DIVISION | H3 FORD-GALAXIE 500 | 08 C                    | 082460                | 00000000       |
| DIAPHRAM RUPTURE CAUSING FLOODING AND EXCESSIVE FUEL CONSUMPTION       |                   |                  |                    |                                                            |                     |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0076

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                     | MAKE-MODEL            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|-------------------|------------------|--------------------|-----------------------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 30021         | P01275 E          | 760207           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>00 031 FORD DIVISION            | 00 FORD DIVISION      | 28 C                    | 000000                | 84111015       |
|               |                   |                  |                    | NO VISIBLE DEFECT - SUSPECT VACUUM LEAK                               |                       |                         |                       |                |
| 30021         | P01275 C          | 760207           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>00 031 FORD DIVISION            | 00 FORD DIVISION      | 28 C                    | 000000                | 84111015       |
|               |                   |                  |                    | NO VISIBLE DEFECTS - SUSPECT VACUUM LEAK                              |                       |                         |                       |                |
| 30017         | P01245 B          | 760203           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>72 031 FORD DIVISION            | 06 PINTO              | 08 C                    | 038540                | 80910024       |
|               |                   |                  |                    | DIAPHRAM IS CRACKED AT ONE POINT                                      |                       |                         |                       |                |
| 30013         | P01201 B          | 760123           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>72 031 FORD DIVISION            | 9C F-250<br>F250      | 44 C                    | 041500                | 00000000       |
|               |                   |                  |                    | POOR PERFORMANCE FROM ECONOMIZER VALVE - ROUGH RUNNING - POOR MILEAGE |                       |                         |                       |                |
| 50019         | P01590 B          | 760607           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>00 041 BUICK                    | B6 SKYLARK GS         | 07 C                    | 000000                | 85364001       |
|               |                   |                  |                    | COMPOSITE STYROFOAM TYPE FLOAT SATURATED WITH GAS                     |                       |                         |                       |                |
| 30010         | P01135 B          | 751229           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>68 041 BUICK                    | 06 SKYLARK            | 44 C                    | 082000                | 91042007       |
|               |                   |                  |                    | FLOAT STICKS-CAUSES POOR GAS MILEAGE & HIGH CO READINGS-ABSORBS GAS   |                       |                         |                       |                |
| 30010         | P01133 B          | 751229           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>68 042 CADILLAC DIVISION        | A2 FLEETWOOD-ELDORADO | 26 C                    | 082000                | 91042007       |
|               |                   |                  |                    | CARB FLOAT SINKS CAUSING ENG TO FLOOD--POSSIBLY ABSORBS GAS           |                       |                         |                       |                |
| 50019         | P01587 B          | 760607           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>69 043 CHEVROLET DIVISION       | E0 PICK-UP MODELS     | 07 C                    | 042167                | 85364001       |
|               |                   |                  |                    | COMPOSITE STYROFOAM TYPE FLOAT-FULL OF GAS                            |                       |                         |                       |                |
| 30010         | P01134 B          | 751229           | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>68 043 CHEVROLET DIVISION       | E3 IMPALA             | 26 C                    | 042500                | 91042007       |
|               |                   |                  |                    | FLOAT SINKS CAUSES FLOODING, POOR OPERATION-POSSIBLY ABSORBS GASOLINE |                       |                         |                       |                |

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                            | MAKE-MODEL            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|-----------------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 30005         | P01071 B      | 751206                | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>68 043 CHEVROLET DIVISION | E3 IMPALA             | 07 C                    | 071125                | 809030015      |
|               |               |                       |                    | CARB FLOAT ABSORBED GASOLINE                                    |                       |                         |                       |                |
| 50019         | P01589 B      | 760607                | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>69 043 CHEVROLET DIVISION | E3 IMPALA             | 07 C                    | 010125                | 85364001       |
|               |               |                       |                    | COMPOSITE STYROFOAM TYPE FLOAT SATURATED WITH GAS               |                       |                         |                       |                |
| 40003         | P01357 B      | 760329                | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>73 043 CHEVROLET DIVISION | E3 IMPALA             | 28 C                    | 032000                | 53140014       |
|               |               |                       |                    | VACUUM OPERATED CHOKE PULL-OFF-NO VISABLE DEFECTS               |                       |                         |                       |                |
| 30012         | P01182 B      | 760107                | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>71 043 CHEVROLET DIVISION | 00 CHEVROLET DIVISION | 07 C                    | 060314                | 85004002       |
|               |               |                       |                    | FLOAT,STYROFOAM TYPE,SOAKED GAS-SINKS CAUSING FLOODING          |                       |                         |                       |                |
| 20008         | P00847 B      | 750912                | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>69 043 CHEVROLET DIVISION | 02 CHEVELLE           | 10 C                    | 082200                | 094303031      |
|               |               |                       |                    | CARB FLOAT ABSORBS GAS                                          |                       |                         |                       |                |
| 30005         | P01072 B      | 751206                | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>68 043 CHEVROLET DIVISION | 03 CHEVROLET          | 07 C                    | 049975                | 809030015      |
|               |               |                       |                    | CARB FLOAT ABSORBED GASOLINE                                    |                       |                         |                       |                |
| 20004         | P00728 B      | 750808                | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>69 043 CHEVROLET DIVISION | 03 CHEVROLET          | 28 C                    | 000000                | 085364001      |
|               |               |                       |                    | FLOAT INOPERATIVE CAUSING CARBURETOR TO FLOOD                   |                       |                         |                       |                |
| 20004         | P00727 B      | 750808                | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>69 045 PONTIAC DIVISION   | 03 PONTIAC            | 28 C                    | 061735                | 085364001      |
|               |               |                       |                    | FLOAT INOPERATIVE CAUSING CARBURETOR TO FLOOD                   |                       |                         |                       |                |
| 50019         | PC1588 B      | 760607                | 06213              | CARBURETOR,UNKNOWN TYPE-OTHER PART<br>76 049 GMC                | 9A GMC TRUCK<br>P-40  | 07 C                    | 011970                | 85364001       |
|               |               |                       |                    | COMPOSITE STYROFOAM TYPE FLOAT-FULL OF GAS                      |                       |                         |                       |                |

# PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06

PAGE 0076

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER                                                       | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>YR                          | COMPONENT NAME<br>MANUFACTURER | MAKE-MODEL | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------------------------------------------------------------|-------------------|------------------|--------------------|------------------------------------------|--------------------------------|------------|-------------------------|-----------------------|----------------|
|                                                                     | P01370 B          | 760330           | 06223              | CARBURETOR,<br>75 032 LINCOLN            | 00 LINCOLN<br>81               | 21 C       | 019500                  | 42301306              |                |
| NO PART-FUEL PLUG IN CARB FELL OUT CAUSING FUEL TO LEAK ON ENGINE   |                   |                  |                    |                                          |                                |            |                         |                       |                |
| 20001                                                               | P00470 B          | 750710           | 06223              | CARBURETOR,<br>68 043 CHEVROLET DIVISION | 02 CHEVELLE                    | 32 C       | 267119                  | 063105001             |                |
| CARBURETOR LEAKS AROUND BASE                                        |                   |                  |                    |                                          |                                |            |                         |                       |                |
| 20005                                                               | P00799 B          | 750813           | 06223              | CARBURETOR,<br>73 174 NISSAN MTR CO LTD  | 01 DATSUN<br>DL620             | 49 C       | 036614                  | 093702024             |                |
| RELAY CONTACTS RUSTED/CORRODED CAUSING CHOKE TO STAY ON             |                   |                  |                    |                                          |                                |            |                         |                       |                |
| 50006                                                               | P01487 B          | 760413           | 06233              | CARBURETOR,<br>73 031 FORD DIVISION      | A8 GRAN TORINO                 | 49 C       | 000000                  | 58201003              |                |
| EGR BLOCK FOR 28R CARB PARTIALLY EATEN AWAY CAUSING VACUUM LEAK     |                   |                  |                    |                                          |                                |            |                         |                       |                |
| 50013                                                               | P01540 B          | 760507           | 06233              | CARBURETOR,<br>73 031 FORD DIVISION      | B0 F-SERIES<br>F-350           | 04 C       | 041222                  | 68102003              |                |
| ALUMNM 28BL CARB SPACER PLATE BURNT THRU IN ONE CHANNEL AT 1 CORNER |                   |                  |                    |                                          |                                |            |                         |                       |                |
| 30013                                                               | P01197 B          | 760123           | 06233              | CARBURETOR,<br>73 031 FORD DIVISION      | 05 MUSTANG                     | 04 C       | 032400                  | 000000000             |                |
| EMISSION PORT AND CHANNEL BLOCKED BY DEPOSIT CAUSING DETERIORATION  |                   |                  |                    |                                          |                                |            |                         |                       |                |
| 30005                                                               | P01067 B          | 751206           | 06233              | CARBURETOR,<br>73 033 MERCURY            | 05 MONTEGO                     | 49 C       | 038807                  | 24017016              |                |
| CARB SPACER PLATE HAS EMISSION HOOK-UP HOLES-CLOGGED W/DEPOSITS     |                   |                  |                    |                                          |                                |            |                         |                       |                |
| 20005                                                               | P00803 B          | 750814           | 06233              | CARBURETOR,<br>73 043 CHEVROLET DIVISION | 03 CAPRICE                     | 02 C       | 017181                  | 076015012             |                |
| SECONDARY THROTTLE PLATES BENT                                      |                   |                  |                    |                                          |                                |            |                         |                       |                |
| 20013                                                               | P00916 B          | 751020           | 06243              | CARBURETOR,<br>00 000 UNKNOWN            | 00 UNKNOWN<br>TRUCK            | 00 C       | 000000                  | 54911016              |                |
| GASKETS & SPACER PLATE CRACKED                                      |                   |                  |                    |                                          |                                |            |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/05 PAGE 0079

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                                                                                                         | MAKE-MODEL            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|--------|------------------|--------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 40006         | P01393        | B      | 760331           | 06243              | CARBURETOR,FOUR-BARREL-OTHER PART<br>73 031 FORD DIVISION                                                                                                 | 07 THUNDERBIRD        | 49 C                    | 048734                | 00000000       |
| 30006         | P01090        | B      | 751224           | 06243              | ALUM CARB SPACER IN EGR PASSAGE BTWN PORTS & EDGE IS CORRODED<br>CARBURETOR,FOUR-BARREL-OTHER PART<br>69 043 CHEVROLET DIVISION                           | E3 IMPALA             | 26 C                    | 076779                | 90027012       |
| 30021         | P01274        | B      | 760207           | 06243              | CARBURETOR,FOUR-BARREL-OTHER PART<br>71 043 CHEVROLET DIVISION                                                                                            | 03 CHEVROLET          | 08 C                    | 004000                | 84111015       |
| 20008         | P00850        | B      | 750919           | 06243              | PLASTIC CHOKE PULLED OFF DIAPHRAM COVER-SPLIT AT SEAM-QUADRAJET CARB<br>CARBURETOR,FOUR-BARREL-OTHER PART<br>64 045 PONTIAC DIVISION                      | 03 PONTIAC            | 10 C                    | 000000                | 024017C16      |
|               | P01404        | B      | 760331           | 06327              | CARB FLOAT ABSORBS GAS-SINKS<br>FUEL INJECTION,ELECTRIC-INJECTOR<br>71 155 VOLKSWAGEN                                                                     | B3 SQUAREBACK SEDAN   | 32 C                    | 026832                | 20009003       |
| 30006         | P01078        | B      | 751224           | 06327              | NO PART-REPLACED 2 FUEL INJECTORS-FUEL LEAKAGE FROM FLEX HOSE<br>FUEL INJECTION,ELECTRIC-INJECTOR<br>72 181 AB VOLVO                                      | A1 VOLVO 142          | 32 C                    | 041502                | 67501001       |
|               | P01019        | B      | 751118           | 06327              | 4 FUEL INJECTORS LEAK-NO WEAR VISIBLE-NO SPECIFICS<br>FUEL INJECTION,ELECTRIC-INJECTOR<br>73 181 AB VOLVO                                                 | 01 VOLVO              | 32 C                    | 000000                | 67501001       |
|               | P01018        | B      | 751118           | 06327              | NO PART SENT-FUEL INJECTORS ARE REBUILT ITEMS ON EXCHANGE BASIS<br>FUEL INJECTION,ELECTRIC-INJECTOR<br>00 182 SAAB AKTIEBOLAG IN                          | A1 SAAB 99,99LE,99EMS | 32 C                    | 000000                | 675C1001       |
| 50009         | P01516        | B      | 760419           | 06430              | NO PART SENT-FUEL INJECTORS ARE REBUILT ITEMS ON EXCHANGE BASIS<br>THROTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>74 110 INTERNATIONAL HARVESTER 11<br>1/2 TON |                       | 08 C                    | 018000                | 51106004       |
|               |               |        |                  |                    | CRACK IN HOUSING BEFORE BRACKET WHERE CABLE BOLTS TO CARB                                                                                                 |                       |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0080

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                   | MAKE-MODEL          | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|------------------------------------------------------------------------|---------------------|-------------------------|-----------------------|----------------|
| 20008         | P00839        | B 750905              | 06430              | THROTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>70 010 AMERICAN MOTORS       | 05 HORNET           | 08 C                    | 041789                | 085004002      |
|               |               |                       |                    | THROTTLE CABLE FRAYED & SPLIT                                          |                     |                         |                       |                |
| 20011         | P00887        | B 751008              | 06430              | THROTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>70 010 AMERICAN MOTORS       | 05 HORNET           | 03 C                    | 035453                | 63123002       |
|               |               |                       |                    | CABLE FRAYED AND CAUSED THROTTLE TO STAY OPEN                          |                     |                         |                       |                |
| 30021         | P01267        | B 760207              | 06430              | THROTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>67 023 PLYMOUTH              | 00 PLYMOUTH         | 53 C                    | 000000                | 51106004       |
|               |               |                       |                    | PLASTIC CABLE BUSHING BROKEN AND BENT, RUST INSIDE CABLE HOUSING       |                     |                         |                       |                |
| 30015         | P01192        | B 760118              | 06430              | THROTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>71 023 PLYMOUTH              | 00 PLYMOUTH         | 03 C                    | 000000                | 85004002       |
|               |               |                       |                    | STRANDS OF CABLE CASING BROKE WHERE CABLE CONNECTS TO ACCELERATOR      |                     |                         |                       |                |
| 20016         | P00973        | B 751108              | 06430              | THROTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>69 031 FORD DIVISION         | E3 FORD-CUSTOM 500  | 03 C                    | 051980                | 8225011        |
|               |               |                       |                    | METAL STRANDS OF CABLE BROKE AT FITTING, UNWINDING CABLE STILL INTACT  |                     |                         |                       |                |
| 30005         | P01076        | B 751224              | 06430              | THROTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>72 031 FORD DIVISION         | G3 FORD-LTD         | 03 C                    | 019223                | 98126073       |
|               |               |                       |                    | THROTTLE CABLE FRAYED-ENDS SAME LENGTH-OTHER PARTS EXCELLENT CONDITION |                     |                         |                       |                |
| 50009         | P01515        | B 760419              | 06430              | THROTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>71 031 FORD DIVISION         | 04 MAVERICK         | 03 C                    | 045000                | 51106004       |
|               |               |                       |                    | THROTTLE CABLE SNAPPED AT ACCELERATOR CONNECTOR                        |                     |                         |                       |                |
| 30014         | P01202        | B 760123              | 06430              | THROTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>70 033 MERCURY               | E4 MERCURY-MONTEREY | 53 C                    | 069300                | 00000000       |
|               |               |                       |                    | CABLE IS FRAYED AT METAL FITTING AWAY FROM CARB                        |                     |                         |                       |                |
| 20011         | P00897        | B 751009              | 06430              | THROTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>69 043 CHEVROLET DIVISION    | 02 CHEVELLE         | 53 C                    | 057153                | 54911007       |
|               |               |                       |                    | THROTTLE CABLE STICKS, CAUSING FAST IDLE                               |                     |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06

PAGE 0081

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMSER | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                                                                                              | MAKE-MODEL                   | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|---------------|-------------------|------------------|--------------------|------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|-------------------------|-----------------------|----------------|
| 20013         | P00912 B          | 751020           | 06430              | THRUTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>70 044 OLDSMOBILE                                                                                    | 04 TORONADO                  | 53 C                    | 083266                | 54911C07       |
| 40005         | P01390 B          | 760330           | 06430              | THRUTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>70 045 PONTIAC DIVISION                                                                              | B4 LE MANS                   | 06 C                    | 000000                | 01904029       |
| 30015         | P01193 B          | 760118           | 06430              | ACCELERATOR LINKAGE CABLE BROKEN WHERE ATTACHED TO CARBURATOR<br>THRUTTLE LINKAGES,ACCELERATOR,FLEXIBLE<br>71 049 GMC                          | 9A GMC TRUCK                 | 03 C                    | 070834                | 850064002      |
| 30006         | P01085 B          | 751224           | 06500              | CABLE CASING SEPARATED FROM RUBBER GROMET - PLASTIC AROUND CABLE BROKE<br>EXHAUST/CRANKCASE EMISSION CONTROL DEVICE<br>71 022 DODGE            | 02 CHARGER                   | 28 C                    | 053418                | 63301003       |
| 30010         | P01142 B          | 751229           | 06500              | VALVE IN TWO PIECES-SPRING STILL STRONG-INSIDE DIRTY,OILY DEPOSITS<br>EXHAUST/CRANKCASE EMISSION CONTROL DEVICE<br>73 031 FORD DIVISION        | 9A FORD TRUCK AND VAN<br>VAN | 04 C                    | 042400                | 97266002       |
| 30011         | P01152 B          | 751229           | 06500              | METAL SPACER BLOCK BURNED FROM EXHAUST GASES-METAL BURNT-OUTLET CLOGGED<br>EXHAUST/CRANKCASE EMISSION CONTROL DEVICE<br>00 031 FORD DIVISION   | 9E BRONCO U100 4X4<br>BRONCO | 49 C                    | 043700                | 97266002       |
| 30011         | P01151 B          | 751229           | 06500              | EXHAUST HAS EATEN AWAY INTERIOR CHAMBER OF BLOCK-PIPE CLOGGED<br>EXHAUST/CRANKCASE EMISSION CONTROL DEVICE<br>73 031 FORD DIVISION             | 91 RANCHERO 500              | 49 C                    | 034453                | 97266002       |
| 50002         | P01439 B          | 760401           | 06530              | EXHAUST GASES HAVE CURRODED INTERIOR OF EGR SPACER BLOCK-METAL EATEN<br>EXHST/CRNKCASE EMISSION CNTRL-CHECK VALVE<br>74 043 CHEVROLET DIVISION | 01 CAMARO<br>2-28            | 32 C                    | 022536                | 03060006       |
| 20003         | P00706 B          | 750729           | 06610              | THERMO VACUUM SWITCH LEAKS-EGR CONNECTION BROKEN OFF<br>EXHAUST SYSTEM-KANIFOLD,ENGINE<br>73 010 AMERICAN MOTORS                               | A9 JEEP WAGONEER             | 03 C                    | 020861                | 000000000      |

HEAT CONTROL VALE BRUKE CAUSING EXHAUST FUMES TO ENTR PASS.COMPARTMENT

## PARTS RETURN PROGRAM

76/07/06 PAGE 0082

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN NUMBER | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME<br>YR MANUFACTURER                                      | MAKE-MODEL             | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|------------|------------|-----------------|-----------------|------------------------------------------------------------------------|------------------------|-------------------------|-----------------------|----------------|
| 40009      | P01437 B   | 760401          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE<br>72 022 DODGE                         | 05 DART                | 08 C                    | 043606                | 90027012       |
|            |            |                 |                 | MANIFOLD CRACKED ON EITHER SIDE OF HEAT COLLECTOR                      |                        |                         |                       |                |
| 50020      | P01563 B   | 760512          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE<br>73 022 DODGE                         | 05 DART                | 08 C                    | 022204                | 90027012       |
|            |            |                 |                 | EXH. MANIFOLD CRACKED ON BOTH SIDES WHERE COLLECTOR MEETS HEAT RISER   |                        |                         |                       |                |
| 50014      | P01553 B   | 760507          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE<br>75 022 DODGE                         | 9A DODGE TRUCK AND VAN | 08 C                    | 045690                | 79605131       |
|            |            |                 |                 | EXHAUST MANIFOLD CRACKED ACROSS CIRCUMFERENCE OF COLLECTOR-PORTS CONTM |                        |                         |                       |                |
| 50020      | P01560 B   | 760512          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE<br>71 023 PLYMOUTH                      | 06 VALIANT             | 08 C                    | 093926                | 90027012       |
|            |            |                 |                 | EXHAUST MANIFOLD CRACKED IN 2 ABOUT CIRCUM OF COLLECTOR BTWN PORTS 3-4 |                        |                         |                       |                |
| 30007      | P01098 B   | 751224          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE<br>69 031 FORD DIVISION                 | H3 FORD-GALAXIE 500    | 03 C                    | 049492                | 98944004       |
|            |            |                 |                 | RIGHT MANIFOLD BROKE IN MIDDLE-CRACK VISIBLE ON UNDERSIDE-RUST NOT CAU |                        |                         |                       |                |
| 30007      | P01096 B   | 751224          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE<br>69 031 FORD DIVISION                 | H3 FORD-GALAXIE 500    | 03 C                    | 049492                | 98944004       |
|            |            |                 |                 | LEFT MANIFOLD BROKE IN TWO-BREAK IS FAIRLY EVEN-STRAIGHT-RUST NOT CAUS |                        |                         |                       |                |
| 20016      | P00966 B   | 751030          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE<br>70 031 FORD DIVISION                 | 05 MUSTANG             | 08 C                    | 079472                | 90027012       |
|            |            |                 |                 | MANIFOLD SPLIT IN TWO                                                  |                        |                         |                       |                |
| 20016      | P00959 B   | 751031          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE<br>74 031 FORD DIVISION                 | 9C F-250               | 08 C                    | 019818                | 67421008       |
|            |            |                 |                 | EXHAUST MANIFOLD CRACKED BY EXHAUST HOOKUP                             |                        |                         |                       |                |
| 20013      | P00919 B   | 751020          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE<br>73 032 LINCOLN                       | A2 MARK IV             | 08 C                    | 024560                | 97404019       |
|            |            |                 |                 | EXHAUST MANIFOLD CRACKED IN TWO-BETWEEN 2ND & 3RD CYLINDER             |                        |                         |                       |                |

PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MIL YR

| BIN NUMBER                                                            | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT YR                      | COMPONENT NAME         | MAKE-MODEL                     | FAULT HAZ. CODE | MILEAGE AT FAILURE | SHIP NUMBER |
|-----------------------------------------------------------------------|------------|-----------------|-----------------|-----------------------------------|------------------------|--------------------------------|-----------------|--------------------|-------------|
| 20016                                                                 | P00968 B   | 751030          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE 73 | 032 LINCOLN            | AZ MARK IV                     | 08 C            | 035257             | 90027012    |
| MANIFOLD IS CRACKED                                                   |            |                 |                 |                                   |                        |                                |                 |                    |             |
| 30008                                                                 | P01120 B   | 751226          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE 72 | 042 CADILLAC DIVISION  | A2 FLEETWOOD-ELDORADO          | 08 C            | 052560             | 63105001    |
| RUST IS EVIDENT IN CRACK-MORE CRACKS NEAR MOUNTING HOLES              |            |                 |                 |                                   |                        |                                |                 |                    |             |
| 50007                                                                 | P01490 B   | 760419          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE 74 | 043 CHEVROLET DIVISION | A3 BELAIR                      | 03 C            | 099463             | 76901005    |
| EXHAUST MANIFOLD BROKE INTO THREE PIECES                              |            |                 |                 |                                   |                        |                                |                 |                    |             |
| 30027                                                                 | P01292 C   | 760214          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE 75 | 043 CHEVROLET DIVISION | C0 BLAZER BLAZER               | 03 C            | 028480             | 93705048    |
| CRACKED IN TWO BY #7 EXHAUST PORT AND PIPE HOOK-UP                    |            |                 |                 |                                   |                        |                                |                 |                    |             |
| 30027                                                                 | P01292 B   | 760214          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE 75 | 043 CHEVROLET DIVISION | C0 BLAZER BLAZER               | 03 C            | 028480             | 93705048    |
| CRACKED IN TWO BY #8 EXHAUST PORT AND PIPE HOOK-UP                    |            |                 |                 |                                   |                        |                                |                 |                    |             |
| 30004                                                                 | P01048 B   | 751122          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE 74 | 043 CHEVROLET DIVISION | E0 PICK-UP MODELS P.U. 1/2 TON | 03 C            | 012700             | 70601002    |
| LEFT SIDE OF V-8 ENG EXHAUST MANIFOLD CRACKED & SEPARATED AT 2 PLACES |            |                 |                 |                                   |                        |                                |                 |                    |             |
| 30004                                                                 | P01047 B   | 751122          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE 74 | 043 CHEVROLET DIVISION | E0 PICK-UP MODELS P.U. 1/2 TON | 03 C            | 012460             | 70601002    |
| RIGHT ENG EXHAUST MANIFOLD OF V-8 CRACKED & SEPARATED AT CENTER PORTS |            |                 |                 |                                   |                        |                                |                 |                    |             |
| 30028                                                                 | P01268 C   | 760207          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE 73 | 043 CHEVROLET DIVISION | 02 CHEVELLE                    | 03 C            | 000000             | 51106004    |
| EXHAUST PIPE BROKE NEAR PIPE CONNECTION AND NUMBER 8 EXHAUST PORT     |            |                 |                 |                                   |                        |                                |                 |                    |             |
| 20016                                                                 | P00958 B   | 751030          | 06610           | EXHAUST SYSTEM-MANIFOLD,ENGINE 72 | 043 CHEVROLET DIVISION | 03 CHEVROLET                   | 08 C            | 013476             | 67421008    |
| MANIFOLD SPLIT IN TWO PLACES                                          |            |                 |                 |                                   |                        |                                |                 |                    |             |

# PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06

PAGE 0084

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                             | MAKE-MODEL            | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|------------------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 50010         | P01512 C      | 760421                | 06610              | EXHAUST SYSTEM-MANIFOLD,ENGINE<br>75 043 CHEVROLET DIVISION      | 03 CHEVROLET          | 08 C                    | 021646                | 93705048       |
|               |               |                       |                    | MANIFOLD CRACKED AT BASE RUNNER ON #4 CYL                        |                       |                         |                       |                |
| 50010         | P01512 B      | 760421                | 06610              | EXHAUST SYSTEM-MANIFOLD,ENGINE<br>75 043 CHEVROLET DIVISION      | 03 CHEVROLET          | 08 C                    | 021646                | 93705048       |
|               |               |                       |                    | MANIFOLD CRACKED AT BASE OF RUNNER ON #1 CYL                     |                       |                         |                       |                |
| 30016         | P01186 B      | 760118                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>71 023 PLYMOUTH                   | 00 PLYMOUTH           | 08 C                    | 033505                | 68510011       |
|               |               |                       |                    | EXHAUST MANIFOLD FROM SIX CYLINDER IS CRACKED IN TWO PLACES<br>6 |                       |                         |                       |                |
| 20015         | P00964 B      | 751030                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>71 023 PLYMOUTH                   | 04 FURY               | 76 C                    | 044948                | 044646005      |
|               |               |                       |                    | INNER WALL OF DOUBLE WALLED EXHAUST PIPE COLLAPSED               |                       |                         |                       |                |
| 20002         | P00481 B      | 750711                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>71 023 PLYMOUTH                   | 90 PLYMOUTH TRUCK & V | 76 C                    | 000000                | 024153008      |
|               |               |                       |                    | EXHAUST PIPE COLLAPSED                                           |                       |                         |                       |                |
| 20005         | P00794 B      | 750812                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>71 031 FORD DIVISION              | H3 FORD-GALAXIE 500   | 76 C                    | 000000                | 037830002      |
|               |               |                       |                    | EXHAUST PIPE INNER LINER COLLAPSED                               |                       |                         |                       |                |
| 30025         | P01306 B      | 760306                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>73 031 FORD DIVISION              | 13 FORD-RANCH WAGON   | 76 C                    | 037070                | 54301057       |
|               |               |                       |                    | INNER WALL OF DOUBLE WALLED PIPE COLLAPSED                       |                       |                         |                       |                |
| 20013         | P00913 B      | 751020                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>70 031 FORD DIVISION              | 03 FORD               | 76 C                    | 034000                | 53215010       |
|               |               |                       |                    | EXHAUST PIPE COLLAPSES ON INTERIOR                               |                       |                         |                       |                |
| 50021         | P01597 B      | 760607                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>68 042 CADILLAC DIVISION          | B1 CADILLAC-DE VILLE  | 76 C                    | 081562                | 96126073       |
|               |               |                       |                    | INNER WALL OF DOUBLE WALLED EXHAUST PIPE COMPLETELY COLLAPSED    |                       |                         |                       |                |

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                 | MAKE-MODEL           | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|----------------------------------------------------------------------|----------------------|-------------------------|-----------------------|----------------|
| 50021         | P01596 B      | 760607                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>69 042 CADILLAC DIVISION              | B1 CADILLAC-DE VILLE | 76 C                    | 000000                | 98126073       |
|               |               |                       |                    | INNER WALL OF DOUBLE WALLED EXHAUST PIPE COLLAPSED                   |                      |                         |                       |                |
| 30008         | P01121 B      | 751226                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>71 042 CADILLAC DIVISION              | B1 CADILLAC-DE VILLE | 76 C                    | 000000                | 32809006       |
|               |               |                       |                    | INNER LINER COLLAPSED-BLOCKED EXHAUST-MOTOR WOULDN'T RUN-RUSTY       |                      |                         |                       |                |
| 40003         | P01350 B      | 760324                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>72 042 CADILLAC DIVISION              | B1 CADILLAC-DE VILLE | 76 C                    | 064000                | 52404002       |
|               |               |                       |                    | INNER WALL OF DOUBLE WALLED EXHAUST PIPE COLLAPSED                   |                      |                         |                       |                |
| 30022         | P01216 B      | 760214                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>68 042 CADILLAC DIVISION              | 01 CADILLAC          | 76 C                    | 068352                | 98126073       |
|               |               |                       |                    | INNER WALL OF DOUBLE EXHAUST PIPE COLLAPSED RESTRICTING EXHAUST FLOW |                      |                         |                       |                |
| 20004         | PC0713 B      | 750805                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>74 043 CHEVROLET DIVISION             | D3 CAPRICE           | 12 C                    | 043236                | 033604002      |
|               |               |                       |                    | INNER LINER OF EXHAUST PIPE COLLAPSED                                |                      |                         |                       |                |
| 30022         | P01268 B      | 760207                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>73 043 CHEVROLET DIVISION             | 02 CHEVELLE          | 76 C                    | 000000                | 51106004       |
|               |               |                       |                    | INNER WALL OF DOUBLED EXHAUST PIPE COLLAPSED RESTRICTING EXHAUST     |                      |                         |                       |                |
|               |               |                       |                    | EXHAUST SYSTEM-PIPE,EXHAUST<br>73 043 CHEVROLET DIVISION             | 02 CHEVELLE          | 06 C                    | 065452                | 68510002       |
|               |               |                       |                    | NO PART SENT-SHOP SAYS SHOCK MOUNT MORE HOLE ON LOWER R EXHST MNTING |                      |                         |                       |                |
| 20003         | P00488 B      | 750710                | 06620              | EXHAUST SYSTEM-PIPE,EXHAUST<br>72 043 CHEVROLET DIVISION             | 03 CHEVROLET         | 12 C                    | 030411                | 0271C1002      |
|               |               |                       |                    | EXHAUST PIPE COLLAPSED                                               |                      |                         |                       |                |
|               |               |                       |                    | EXHAUST SYSTEM-MUFFLER-RESONATOR<br>00 00C UNKNOWN                   | 00 UNKNOWN           | 44 C                    | 000000                | 64109015       |
|               |               |                       |                    | NO PART SENT-SHOP COMMENT IS MIDAS MUFFLER                           |                      |                         |                       |                |

PARTS RETURN PROGRAM

76/07/06 PAGE 0080

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN NUMBER | PRP I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                    | MAKE-MODEL        | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------|-------------------|------------------|--------------------|----------------------------------------------------------------------|-------------------|-------------------------|-----------------------|----------------|
|            | P01223 B          | 760123           | 06630              | EXHAUST SYSTEM-MUFFLER-RESONATOR<br>00 022 DODGE                     | 05 DART           | 49 C                    | 014000                | 63105001       |
|            |                   |                  |                    | REAR RESONATOR RUSTING OUT IN 225 CIO ENGINE-NO PART SENT            |                   |                         |                       |                |
| 30013      | P01210 B          | 760123           | 06630              | EXHAUST SYSTEM-MUFFLER-RESONATOR<br>00 023 PLYMOUTH                  | A6 VALIANT-DUSTER | 49 C                    | 000000                | 63105001       |
|            |                   |                  |                    | RUSTING OUT OF REAR RESONATOR-NO PART SENT                           |                   |                         |                       |                |
| 30011      | P01222 B          | 760123           | 06630              | EXHAUST SYSTEM-MUFFLER-RESONATOR<br>00 044 OLDSMOBILE                | 04 TORONADO       | 49 C                    | 000000                | 63105001       |
|            |                   |                  |                    | DETERIORATION IN REAR SECTION OF RESONATOR-NO PART SENT IN           |                   |                         |                       |                |
| 40004      | P01366 B          | 760329           | 06640              | EXHAUST SYSTEM-TAIL PIPE<br>71 043 CHEVROLET DIVISION                | E3 IMPALA         | 76 C                    | 000000                | 45406009       |
|            |                   |                  |                    | INNER LINING OF EXHAUST PIPE COLLAPSED                               |                   |                         |                       |                |
| 20001      | P00465 B          | 750708           | 07110              | POWER TRAIN CLUTCH ASSEMBLY-PEDAL<br>67 155 VOLKSWAGEN               | 01 TYPE I         | 03 C                    | 049636                | 063105001      |
|            |                   |                  |                    | CLUTCH PEDAL BROKE AT PIVOT CONNECTION PIN                           |                   |                         |                       |                |
| 40005      | P01374 B          | 760330           | 07110              | POWER TRAIN CLUTCH ASSEMBLY-PEDAL<br>69 155 VOLKSWAGEN               | 01 TYPE I         | 08 C                    | 052490                | 90027012       |
|            |                   |                  |                    | PEDAL IS CRACKED JUST BEFORE SLEEVE THAT ATTACHES TO LINKAGE         |                   |                         |                       |                |
| 30019      | P01252 B          | 760203           | 07120              | POWER TRAIN CLUTCH ASM-LINKAGE,FLEXIBLE<br>74 043 CHEVROLET DIVISION | 09 VEGA           | 09 C                    | 035888                | 029611001      |
|            |                   |                  |                    | CLUTCH CABLE FRAYED AND BROKE FOUR INCHES FROM EYELET END            |                   |                         |                       |                |
| 20005      | P00798 B          | 750813           | 07120              | POWER TRAIN CLUTCH ASM-LINKAGE,FLEXIBLE<br>72 181 AB VOLVO           | 01 VOLVO          | 03 C                    | 036345                | 093702023      |
|            |                   |                  |                    | CLUTCH CABLE BROKE APPROXIMATELY 1 INCH FROM END                     |                   |                         |                       |                |
| 40004      | P01365 B          | 760329           | 07130              | POWER TRAIN CLUTCH ASM-LINKAGE,RIGID<br>73 044 OLDSMOBILE            | 05 4-4-2          | 03 C                    | 026564                | 45406009       |
|            |                   |                  |                    | COLLAR ON THROW-OUT BRNG BROKEN                                      |                   |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0087

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>MANUFACTURER                                      | MAKE-MODEL            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|------------------------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 20003         | P00486 B      | 750711                | 07170              | PWR TRN CLUTCH ASM-PLATE,DRIVE,CLUTCH<br>74 031 FORD DIVISION          | 04 MAVERICK           | 04 D                    | 008000                | 019020002      |
|               |               |                       |                    | CLUTCH PRESSURE PLATE FINGER BROKE                                     |                       |                         |                       |                |
|               | P00457 B      | 750728                | 07170              | PWR TRN CLUTCH ASM-PLATE,DRIVE,CLUTCH<br>74 043 CHEVROLET DIVISION     | 09 VEGA               | 05 C                    | 002600                | 050265003      |
|               |               |                       |                    | CLUTCH DISC AND PRESSURE PLATE BURNT OUT                               |                       |                         |                       |                |
| 30001         | P01001 B      | 751114                | 07200              | POWER TRAIN TRANSMISSION,STANDARD-MANUAL<br>69 182 SAAB AKTIEBOLAG IN  | A1 SAAB 99,99LE,99EMS | 57 C                    | 052020                | 67501001       |
|               |               |                       |                    | GEAR TEETH SHOW EXCESSIVE WEAR-CHIPPING                                |                       |                         |                       |                |
| 20013         | P01052 B      | 751024                | 07240              | PWR TRN TRNS.-UNK.TYP-<br>67 023 PLYMOUTH                              | 04 FURY               | 08 C                    | 051404                | 60626008       |
|               |               |                       |                    | RUBBER BODY OF TRANS MCUNT SPLIT                                       |                       |                         |                       |                |
| 20015         | P00955 B      | 751024                | 07300              | POWER TRAIN TRANSMISSION,AUTOMATIC<br>00 000 UNKNOWN                   | 00 UNKNOWN            | 02 C                    | 000000                | 60626008       |
|               |               |                       |                    | ARM TO TRANSMISSION BENT                                               |                       |                         |                       |                |
| 30008         | P01118 B      | 751226                | 07300              | POWER TRAIN TRANSMISSION,AUTOMATIC<br>74 031 FORD DIVISION             | 05 MUSTANG            | 28 C                    | 027394                | 98036056       |
|               |               |                       |                    | ENG WILL START WHILE IN GEAR-SWITCH CLICKS-POSSIBLY POOR INTERNAL CONE |                       |                         |                       |                |
| 20003         | P00827 B      | 750827                | 07300              | POWER TRAIN TRANSMISSION,AUTOMATIC<br>72 031 FORD DIVISION             | 06 PINTO              | 57 D                    | 078148                | 068510002      |
|               |               |                       |                    | TRANSPAN & COOLER LINE RUBBING CAUSING HOLE IN COOLER LINE             |                       |                         |                       |                |
| 20008         | P00846 B      | 750912                | 07300              | POWER TRAIN TRANSMISSION,AUTOMATIC<br>70 033 MERCURY                   | 05 MONTEGO<br>MONTEGO | 03 C                    | 080500                | 094303031      |
|               |               |                       |                    | TRANS INTERMEDIATE BAND BROKE                                          |                       |                         |                       |                |
| 50011         | P01526 B      | 760501                | 07300              | POWER TRAIN TRANSMISSION,AUTOMATIC<br>75 041 BUICK                     | D2 CENTURY REGAL      | 08 C                    | 022000                | 19405087       |
|               |               |                       |                    | PLASTIC SERVO PISTON FROM T-350 TRANS. CRACKED ACROSS DIA.IN 2 PIECES  |                       |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06

PAGE 0088

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MIL YR

| BIN<br>NUMBER                                                              | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>MANUFACTURER                                       | MAKE-MODEL                       | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|----------------------------------------------------------------------------|---------------|-----------------------|--------------------|-------------------------------------------------------------------------|----------------------------------|-------------------------|-----------------------|----------------|
| 40010                                                                      | P01408 B      | 760331                | 07300              | POWER TRAIN TRANSMISSION, AUTOMATIC<br>74 043 CHEVROLET DIVISION        | 03 CHEVROLET                     | 57 C                    | 017982                | 30030021       |
| SOME CLUTCH & DISC SHOW BURN MKS, BUSHES SHOW WEAR, GEARS OK-FLUID PROBLEM |               |                       |                    |                                                                         |                                  |                         |                       |                |
| 30010                                                                      | P01129 B      | 751226                | 07300              | POWER TRAIN TRANSMISSION, AUTOMATIC<br>70 045 PONTIAC DIVISION          | 84 LE MANS                       | 21 C                    | 000000                | 63111009       |
| CABLE HOUSING SEPARATED FROM METAL CONNECTOR-CAUSE INTERNAL FRICTION       |               |                       |                    |                                                                         |                                  |                         |                       |                |
| 30006                                                                      | P01079 B      | 751224                | 07300              | POWER TRAIN TRANSMISSION, AUTOMATIC<br>00 176 TOYOTA MOTR CO LTD        | 00 TOYOTA MOTR CO LTD            | 03 C                    | 051728                | 67501C01       |
| REVERSE BAND EAR BROKEN OFF-APPARENTLY DUE TO INSUFFICIENT STRENGTH        |               |                       |                    |                                                                         |                                  |                         |                       |                |
| 20017                                                                      | P00990 B      | 751114                | 07350              | PWR TRN TRNS, AUTG-SWCH-SOLENOID, SHIFT, VAC<br>70 031 FORO DIVISION    | 98 F100 2DR CONV. PU<br>F100     | 28 C                    | 039629                | 80910024       |
| NO PHYSICAL DAMAGE TO CASING, GREASE EVIDENT-POSSIBLE INTERNAL DAMAGE      |               |                       |                    |                                                                         |                                  |                         |                       |                |
| 20013                                                                      | P00941 B      | 751024                | 07410              | POWER TRAIN DRIVELINE-UNIVERSAL JOINT<br>00 000 UNKNOWN                 | 00 UNKNOWN                       | 57 C                    | 000000                | 60626008       |
| EXCESSIVE WEAR OF BEARING ON U JOINT                                       |               |                       |                    |                                                                         |                                  |                         |                       |                |
| 50017                                                                      | P01569 B      | 760512                | 07410              | POWER TRAIN DRIVELINE-UNIVERSAL JOINT<br>65 010 AMERICAN MOTORS         | 02 AMERICAN                      | 03 C                    | 096569                | 90027012       |
| THREADED PART OF FLANGE BROKE IN 3- ONE CUP FROZEN IN U-JOINT FLANGE       |               |                       |                    |                                                                         |                                  |                         |                       |                |
| 30002                                                                      | P01021 B      | 751119                | 07430              | PWR TRN DRIVELINE-BRKT-SUPT., CENTER SHAFT<br>74 043 CHEVROLET DIVISION | EO PICK-UP MODELS<br>CHEYENNE    | 57 C                    | 026746                | 63105001       |
| BEARING DISINTEGRATED-RACES SHOW EXCESSIVE WEAR-SUPPORT CRACKED            |               |                       |                    |                                                                         |                                  |                         |                       |                |
| 40005                                                                      | P01382 B      | 760310                | 07450              | PWR TRN DRIVELINE-DIFFENTIAL UNIT<br>74 022 DODGE                       | 9A DODGE TRUCK AND VA<br>300 VAN | 07 C                    | 017521                | 43614003       |
| BEARINGS ARE CONTAMINATED-RACES SEVERLY PITTED                             |               |                       |                    |                                                                         |                                  |                         |                       |                |
| 30006                                                                      | P01084 B      | 751224                | 07450              | PWR TRN DRIVELINE-DIFFENTIAL UNIT<br>73 023 PLYMOUTH                    | 05 SATELLITE                     | 03 C                    | 085000                | 99134058       |
| PINION SHAFT BROKEN 6 INCHES FROM GEAR-POSSIBLY WEAK STEAL-NO SCORING      |               |                       |                    |                                                                         |                                  |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0069

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN NUMBER | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                                         | YR MANUFACTURER | MAKE-MODEL             | FAULT HAZ. CODE | HAZ. CAT.                          | MILEAGE AT FAILURE | SHCP NUMBER |        |           |
|------------|------------|-----------------|-----------------|------------------------------------------------------------------------|-----------------|------------------------|-----------------|------------------------------------|--------------------|-------------|--------|-----------|
| 30015      | P01234 B   | 760203          | 07450           | PWR TRN DRIVE-DIFFERENTIAL UNIT                                        | 75              | 043 CHEVROLET DIVISION | C4              | NOVA                               | 57                 | C           | 017201 | 43614003  |
|            |            |                 |                 | ROLLER BEARINGS BADLY WORN - BEARING RACE WORN ON INSIDE               |                 |                        |                 |                                    |                    |             |        |           |
| 20005      | P00804 B   | 750814          | 07452           | PWR TRN DRIVE-DIFFERENTIAL UNIT SNGL SP                                | 73              | 022 DODGE              | 9A              | DODGE TRUCK AND VA 7300 MOTOR HOME | 44                 | C           | 015545 | 045406001 |
|            |            |                 |                 | POOR PERFORMANCE OF BEARING (FAIL PART TAG ILLEGIBLE)                  |                 |                        |                 |                                    |                    |             |        |           |
| DCT1       | P01266 B   | 760207          | 07460           | POWER TRAIN AXLE ASSEMBLY                                              | 73              | 043 CHEVROLET DIVISION | 06              | CORVETTE                           | 03                 | C           | 052201 | 91401026  |
|            |            |                 |                 | REAR WH BEARING DISINTEGRATED, SHORT AXLE BROKEN AND BENT, R HUB BROKE |                 |                        |                 |                                    |                    |             |        |           |
| 50013      | P01533 C   | 760507          | 07460           | POWER TRAIN AXLE ASSEMBLY                                              | 74              | 049 GMC                | 9A              | GMC TRUCK 6000                     | 03                 | C           | 010285 | 33604002  |
|            |            |                 |                 | 8 LFT REAR AXLE FLANGE STUDS BROKE AT BASE OF COURSE THREADED SECTION  |                 |                        |                 |                                    |                    |             |        |           |
| 30015      | P01230 B   | 760203          | 07463           | PWR TRN AXLE ASSEMBLY-BEARING, AXLE SHAFT                              | 71              | 021 CHRYSLER DIVISION  | B1              | NEW YORKER                         | 08                 | C           | 049824 | 50702006  |
|            |            |                 |                 | OUTER BEARING RACE SPLIT AND WORN - ROLLER BEARINGS WORN AT CONTACT    |                 |                        |                 |                                    |                    |             |        |           |
| 50003      | P01460 C   | 760406          | 07463           | PWR TRN AXLE ASSEMBLY-BEARING, AXLE SHAFT                              | 71              | 031 FORD DIVISION      | E3              | FORD-CUSTOM 500                    | 57                 | C           | 024721 | 66510002  |
|            |            |                 |                 | SEALED TYP B1 BEARING & RACE EXCESS. WORN-REPL-BLA88128R WORN ALSO     |                 |                        |                 |                                    |                    |             |        |           |
| 50003      | P01460 B   | 760406          | 07463           | PWR TRN AXLE ASSEMBLY-BEARING, AXLE SHAFT                              | 71              | 031 FORD DIVISION      | E3              | FORD-CUSTOM 500                    | 57                 | C           | 024721 | 66510002  |
|            |            |                 |                 | SEALED TYPE BALL BEARING AND RACE EXCESSIVELY WORN                     |                 |                        |                 |                                    |                    |             |        |           |
| 20008      | P00840 B   | 750905          | 07463           | PWR TRN AXLE ASSEMBLY-BEARING, AXLE SHAFT                              | 71              | 031 FORD DIVISION      | 9A              | FORD TRUCK AND VAN F350            | 01                 | C           | 060551 | 085004002 |
|            |            |                 |                 | LOCK PLATE NOT BENT OVER R BEARING NUT-ALLOWED NUTS TO FALL OFF        |                 |                        |                 |                                    |                    |             |        |           |
| 30001      | P01002 B   | 751114          | 07463           | PWR TRN AXLE ASSEMBLY-BEARING, AXLE SHAFT                              | 00              | 033 MERCURY            | A1              | CAPRI 2000                         | 32                 | C           | 041850 | 67501001  |
|            |            |                 |                 | DOUBLE SEAL BEARING LEAKS GREASE                                       |                 |                        |                 |                                    |                    |             |        |           |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0090

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                    | MAKE-MODEL          | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|----------------------------------------------------------------------|---------------------|-------------------------|-----------------------|----------------|
| 50009         | P01514 B      | 760419                | 07470              | POWER TRAIN-OTHER PART<br>73 031 FORD DIVISION                       | H3 FORD-GALAXIE 500 | 03 C                    | 020069                | 51106004       |
|               |               |                       |                    | REVERSE BAND BROKE OFF AT RETAINER CLIP                              |                     |                         |                       |                |
| 40004         | P01369 B      | 760329                | 07470              | POWER TRAIN-OTHER PART<br>71 041 BUICK                               | 04 LE SABRE         | 08 C                    | 071076                | 45406009       |
|               |               |                       |                    | FLEX-PLATE CRACKED AROUND BOLT HOLES                                 |                     |                         |                       |                |
| 40004         | P01365 C      | 760329                | 07470              | POWER TRAIN-OTHER PART<br>73 044 OLDSMOBILE                          | 05 4-4-2            | 50 C                    | 026564                | 45406009       |
|               |               |                       |                    | INPUT SHAFT HOUSING IS SCORED AND GOUGED                             |                     |                         |                       |                |
| 50007         | P01498 B      | 760421                | 07470              | POWER TRAIN-OTHER PART<br>74 045 PONTIAC DIVISION                    | E4 GRAND AM         | 59 C                    | 035256                | 79605020       |
|               |               |                       |                    | WELD BROKEN AT CONNECTION BETWEEN TRANS-COOLER LINE&TANK(OIL COOLER) |                     |                         |                       |                |
| 30010         | P01128 B      | 751226                | 08120              | ELECTRICAL SYSTEM BATTERY-CABLE<br>73 043 CHEVROLET DIVISION         | E3 IMPALA           | 73 C                    | 033010                | 54911007       |
|               |               |                       |                    | NO VISIBLE SHORTS IN CABLE-POSSIBLE LOOSE CONNECTION                 |                     |                         |                       |                |
|               | P01343 B      | 760324                | 08210              | ELECTRICAL SYSTEM ALTERNATOR-GENERATOR<br>00 040 GENERAL MOTORS      | 00 GENERAL MOTORS   | 44 C                    | 000000                | 92632025       |
|               |               |                       |                    | SHP LETTER RE HIGH FAIL RATE OF GM ALTW/INTEGRAL REG-NO PART SENT    |                     |                         |                       |                |
| 50021         | P01594 C      | 760607                | 08210              | ELECTRICAL SYSTEM ALTERNATOR-GENERATOR<br>73 174 NISSAN MTR CO LTD   | 91 PICKUP TRUCK     | 28 C                    | 065155                | 67501001       |
|               |               |                       |                    | ALT BRUSHES WORN NO EXTERNAL DEFECTS-SHOP CLAIMS WATER DAMAGE        |                     |                         |                       |                |
| 50021         | P01594 D      | 760607                | 08210              | ELECTRICAL SYSTEM ALTERNATOR-GENERATOR<br>73 174 NISSAN MTR CO LTD   | 91 PICKUP TRUCK     | 28 C                    | 065155                | 67501001       |
|               |               |                       |                    | NO APPARENT EXT DEFECT SHOP CLMS DIODE SET DMGD BY WATER FROM HOSE   |                     |                         |                       |                |
| 20009         | P00868 B      | 750925                | 08220              | ELECTRICAL SYSTEM REGULATOR<br>00 023 PLYMOUTH                       | C4 FURY III         | 44 C                    | 000000                | 079601021      |
|               |               |                       |                    | POOR PERFORMANCE OF VOLTAGE REG-BATTERY BOILED-HI VOLTAGE-18 VOLT>   |                     |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0091

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                      | MAKE-MODEL        | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|--------|------------------|--------------------|------------------------------------------------------------------------|-------------------|-------------------------|-----------------------|----------------|
| 50021         | P01594        | F      | 760607           | 08220              | ELECTRICAL SYSTEM REGULATOR<br>73 174 NISSAN MTR CO LTD                | 91 PICKUP TRUCK   | 28 C                    | 065155                | 67501001       |
|               |               |        |                  |                    | EXT APPEAR NORM SHOP CLMS DAMAGED BY EXCESS LOAD FROM DMGD ALTERN      |                   |                         |                       |                |
| 50021         | P01594        | E      | 760607           | 08220              | ELECTRICAL SYSTEM REGULATOR<br>73 174 NISSAN MTR CO LTD                | 91 PICKUP TRUCK   | 28 C                    | 065155                | 67501001       |
|               |               |        |                  |                    | EXT APPEAR NORM SHOP CLMS DAMAGED BY EXCESS LOAD FROM DMGD ALTERN      |                   |                         |                       |                |
| 20007         | P00447        | B      | 750722           | 08230              | ELECTRICAL SYSTEM STARTER<br>72 010 AMERICAN MOTORS                    | 05 HORNET         | 57 D                    | 034643                | 094133032      |
|               |               |        |                  |                    | EXCESSIVE WEAR OF STARTER PINION GEAR                                  |                   |                         |                       |                |
| 20001         | P00479        | B      | 750708           | 08230              | ELECTRICAL SYSTEM STARTER<br>69 042 CADILLAC DIVISION                  | 01 CADILLAC       | 03 D                    | 068240                | 053140005      |
|               |               |        |                  |                    | STARTER HOUSING BROKE                                                  |                   |                         |                       |                |
| 50029         | P01605        | B      | 760601           | 08231              | ELECTRICAL SYSTEM STARTER MOTOR<br>74 043 CHEVROLET DIVISION           | 02 CHEVELLE       | 33 C                    | 009294                | 15697025       |
|               |               |        |                  |                    | SLIGHT WEAR ON STARTER DRIVE NO OTHER VISIBLE DEFECTS                  |                   |                         |                       |                |
| 30001         | P00997        | B      | 751114           | 08232              | ELECTRICAL SYSTEM STARTER SOLENOID<br>00 040 GENERAL MOTORS            | 00 GENERAL MOTORS | 28 C                    | 000000                | 19802003       |
|               |               |        |                  |                    | SOLENOID WORN-PROBABLE ELEC SHORT-NO DATA CARD                         |                   |                         |                       |                |
| 20007         | P00808        | B      | 750820           | 08233              | ELECTRICAL SYSTEM STARTER RELAY<br>73 021 CHRYSLER DIVISION            | 01 CHRYSLER       | 02 C                    | 002000                | 006120003      |
|               |               |        |                  |                    | CONTACTS BENT(SHOP STATES THAT RELAY WAS MISALIGNED WHEN INSTALLED)    |                   |                         |                       |                |
| 30011         | P01157        | B      | 760106           | 08240              | ELECT. SYS.-ALTRNTR,RGULTR,STRTR-OTHER PAR<br>71 031 FORD DIVISION     | 06 PINTO          | 03 C                    | 059332                | 085012004      |
|               |               |        |                  |                    | ALT.MOUNTING BRACKET BROKE NEAR ENG.-BROKE-BEFORE-WELDED-BROKE DIFF PL |                   |                         |                       |                |
| 30011         | P01158        | B      | 760106           | 08240              | ELECT. SYS.-ALTRNTR,RGULTR,STRTR-OTHER PAR<br>73 031 FORD DIVISION     | 06 PINTO          | 03 C                    | 000000                | 085012004      |
|               |               |        |                  |                    | UPPER ALT BRACKET BROKEN NEAR WHERE MOUNTED TO ENG-RUST NOT CAUSE      |                   |                         |                       |                |

# PARTS RETURN PROGRAM

76/07/06 PAGE 0092

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MOL YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | YEAR       | COMPONENT NAME<br>MANUFACTURER                              | MAKE-MODEL            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|---------------|-----------------------|--------------------|------------|-------------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 30011                                                                  | P01154        | B 760106              | 08240              | ELECT.     | SYS.-ALTRNTR,RGULTR,STRTR-OTHER PAR<br>73 031 FORD DIVISION | 06 PINTO              | 03 C                    | 000000                | 85012004       |
| ALTERNATOR PULLEY RIM BROKEN OFF ONE THIRD OF CIRCUMFERENCE-NO RUST    |               |                       |                    |            |                                                             |                       |                         |                       |                |
| 30011                                                                  | P01156        | B 760106              | 08240              | ELECT.     | SYS.-ALTRNTR,RGULTR,STRTR-OTHER PAR<br>69 044 OLDSMOBILE    | 00 OLDSMOBILE         | 03 C                    | 000000                | 085012004      |
| ALTERNATOR PULLEY BROKEN IN HALF WHERE 2 SIDES JOINED-INSUFF THICKNESS |               |                       |                    |            |                                                             |                       |                         |                       |                |
| 20010                                                                  | P00926        | B 751020              | 08240              | ELECT.     | SYS.-ALTRNTR,RGULTR,STRTR-OTHER PAR<br>72 044 OLDSMOBILE    | 05 4-4-2              | 08 C                    | 041000                | 60659011       |
| ALTERNATOR BRACKET CRACKED                                             |               |                       |                    |            |                                                             |                       |                         |                       |                |
| 20002                                                                  | P00474        | B 750716              | 08320              | ELECT.     | SYS.-WIRING-HARNES,REAR-UNDER DASH<br>00 041 BUICK          | 04 LE SABRE           | 73 C                    | 000000                | 019963106      |
| ELECT. WIRING HARNES SHORTED AND BURNT                                 |               |                       |                    |            |                                                             |                       |                         |                       |                |
|                                                                        | P00376        | B 750919              | 08340              | ELECT.     | SYS.-WIRING-OTHER PART<br>00 000 UNKNOWN                    | 00 UNKNOWN            | 00 C                    | 000000                | 031401020      |
| FAIL PART TAG SOAKED WITH FLUID-UNREADABLE                             |               |                       |                    |            |                                                             |                       |                         |                       |                |
|                                                                        | P00842        | B 750827              | 08340              | ELECT.     | SYS.-WIRING-OTHER PART<br>72 043 CHEVROLET DIVISION         | 00 CHEVROLET DIVISION | 10 C                    | 035655                | 068510002      |
| INSULATION USED IN WIRING-HARNES TOO THIN, ALLOWING METAL TO CUT       |               |                       |                    |            |                                                             |                       |                         |                       |                |
| 30006                                                                  | P01083        | B 751224              | 08500              | ELECTRICAL | SYSTEM-IGNITION<br>69 176 TOYOTA MOTR CO LTD                | 02 TOYOTA COROLLA     | 21 C                    | 044504                | 91720015       |
| COUNTER WEIGHTS IN DISTRIBUTOR CAUSING HIGH FRICTION-DIFFICULT ROTATIO |               |                       |                    |            |                                                             |                       |                         |                       |                |
| 30005                                                                  | P01074        | B 751223              | 08510              | ELECTRICAL | SYSTEM-IGNITION-SWITCH<br>70 023 PLYMOUTH                   | 04 SPORT FURY         | 73 C                    | 000000                | 63361003       |
| IGN SWITCH CONTACTS APPEAR OK-JUNCTION CASE,REDWIRE TO JUNCTION MELTED |               |                       |                    |            |                                                             |                       |                         |                       |                |
| DOT1                                                                   | P01043        | B 751112              | 08510              | ELECTRICAL | SYSTEM-IGNITION-SWITCH<br>69 031 FORD DIVISION              | 03 FORD-LTD           | 28 C                    | 081724                | 19020002       |
| 1 CONNECTION TO WIRING HARNES BENT,PLASTIC HOUSING AT HARNES BROKE     |               |                       |                    |            |                                                             |                       |                         |                       |                |

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                   | MAKE-MODEL               | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|------------------------------------------------------------------------|--------------------------|-------------------------|-----------------------|----------------|
| DOT1          | P01207 B      | 760123                | 08510              | ELECTRICAL SYSTEM-IGNITION-SWITCH<br>71 031 FORD DIVISION              | 03 FORD                  | 04 C                    | 053256                | 00C0C0C0C      |
|               |               |                       |                    | WIRE BURNED AT TERMINAL ON IGNITION SWITCH - GROUND WIRE LOOSE         |                          |                         |                       |                |
| 50009         | P01517 B      | 760419                | 08510              | ELECTRICAL SYSTEM-IGNITION-SWITCH<br>74 032 LINCOLN                    | 01 CONTINENTAL           | 04 C                    | 020C00                | 51106C0C4      |
|               |               |                       |                    | ONE WIRE IN STARTER SYSTEM IS MELTED                                   |                          |                         |                       |                |
| 30010         | P01127 B      | 751226                | 08510              | ELECTRICAL SYSTEM-IGNITION-SWITCH<br>65 043 CHEVROLET DIVISION         | E3 IMPALA                | 53 C                    | 055672                | 54911C07       |
|               |               |                       |                    | SHOP SAYS SWITCH STICKS IN START-STRONG RETURN SPRING-CK NOW           |                          |                         |                       |                |
| 20011         | P00898 B      | 751009                | 08520              | ELEC.SYS-IGNITION-SWITCH,NEUTRAL START<br>73 043 CHEVROLET DIVISION    | C4 NOVA                  | 28 C                    | 003800                | 03C6C0C0C      |
|               |               |                       |                    | DEFECTIVE NEUTRAL START SWITCH                                         |                          |                         |                       |                |
| 40003         | P01352 B      | 760329                | 08520              | ELEC.SYS-IGNITION-SWITCH,NEUTRAL START<br>72 049 GMC                   | 9A GMC TRUCK<br>2500 4WD | 28 C                    | 045000                | 52404-002      |
|               |               |                       |                    | NG APPARENT DEFECT - POSS INTERNALLY SHORTED                           |                          |                         |                       |                |
| 50015         | P01559 B      | 760512                | 08530              | ELEC.SYS-IGNITION-WIRING,PRIMARY & SECOND<br>69 021 CHRYSLER DIVISION  | A1 NEWPORT               | 44 C                    | 082713                | 01230C0C5      |
|               |               |                       |                    | 2NDARY IGNITN WIRING-POOR PERFORMANCE WHEN WET-CONTACTS NOT MAX PLIABL |                          |                         |                       |                |
| 30025         | P01294 B      | 760225                | 08530              | ELEC.SYS-IGNITION-WIRING,PRIMARY & SECOND<br>69 023 PLYMOUTH           | 05 SATELLITE             | 44 C                    | 035791                | 01230C0C5      |
|               |               |                       |                    | POSS HAIRLINE CRACKS IN INSULATION OIL ON COIL LEAD POOR PERF WHEN WET |                          |                         |                       |                |
| 20009         | P00867 B      | 750925                | 08530              | ELEC.SYS-IGNITION-WIRING,PRIMARY & SECOND<br>73 031 FORD DIVISION      | G3 FORD-LTD              | 44 C                    | 053675                | 001230C0C5     |
|               |               |                       |                    | ENG SKIPS IN WET OR RAINY WEATHER                                      |                          |                         |                       |                |
| 50016         | P01562 B      | 760512                | 08530              | ELEC.SYS-IGNITION-WIRING,PRIMARY & SECOND<br>72 031 FORD DIVISION      | 05 MUSTANG               | 44 C                    | 069490                | 01230C0C5      |
|               |               |                       |                    | 2NDARY IGNITION WIRE SET-POORLY PERFORMS WET-WIRES NOT VERY PLIABLE    |                          |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0094

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                                   | MAKE-MODEL         | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|------------------------------------------------------------------------|---------------|-----------------------|--------------------|----------------------------------------------------------------------------------------|--------------------|-------------------------|-----------------------|----------------|
| 30002                                                                  | P01024 B      | 751119                | 08530              | ELEC.SYS-IGNITION-WIRING,PRIMARY & SECOND<br>73 041 BUICK                              |                    | 44 C                    | 050423                | 01230005       |
| VARIOUS WIRE BRANDS USED FOR REPLACEMENT-1 WIRE IS CORRODED-WIRE TAPED |               |                       |                    |                                                                                        |                    |                         |                       |                |
| 30022                                                                  | P01166 B      | 760214                | 08540              | ELEC.SYS-IGNITION-ELECTRONIC CONTROL UNIT<br>74 110 INTERNATIONAL HARVESTER 22 TRAVALL |                    | 73 C                    | 018927                | 98126073       |
| UNIT IS SHORTED - NO SPECIFICS                                         |               |                       |                    |                                                                                        |                    |                         |                       |                |
| 30013                                                                  | P01224 B      | 760103                | 08550              | ELEC.SYS-IGNITION-OTHER PART<br>00 020 CHRYSLER MOTORS                                 | 00 CHRYSLER MOTORS | 03 C                    | 000000                | 55103001       |
| BALLAST RESISTOR IS AT FAULT IN NUMBER OF IGNITION PROBLEMS -BROKEN    |               |                       |                    |                                                                                        |                    |                         |                       |                |
|                                                                        | P01559 C      | 760512                | 08550              | ELEC.SYS-IGNITION-OTHER PART<br>69 021 CHRYSLER DIVISION                               | A1 NEWPORT         | 44 C                    | 082713                | 01230005       |
| CONTACTS ON INSIDE DISTRIBUTOR CAP SHOW WEAR-CRACKD CONTACT            |               |                       |                    |                                                                                        |                    |                         |                       |                |
|                                                                        | P01559 D      | 760512                | 08550              | ELEC.SYS-IGNITION-OTHER PART<br>69 021 CHRYSLER DIVISION                               | A1 NEWPORT         | 44 C                    | 082713                | 01230005       |
| CONTACTS OF DISTRIBUTOR ROTOR SHOW EXCESSIVE WEAR-POOR PERFORMANCE WET |               |                       |                    |                                                                                        |                    |                         |                       |                |
| 30012                                                                  | P01167 B      | 760106                | 08550              | ELEC.SYS-IGNITION-OTHER PART<br>73 021 CHRYSLER DIVISION                               | A1 NEWPORT         | 44 C                    | 043931                | 001230005      |
| PLUG WIRES APPEAR OK CONSIDERING NORMAL WEAR-ONE HAS BENT PLUG CONNECT |               |                       |                    |                                                                                        |                    |                         |                       |                |
| 50022                                                                  | P01603 B      | 760607                | 08550              | ELEC.SYS-IGNITION-OTHER PART<br>75 031 FORD DIVISION                                   | 04 MAVERICK        | 28 C                    | 000000                | 12601051       |
| NO VISABLE CRACKS IN CASE SOME OIL AROUND TOP E-TRONIC IG TYPE         |               |                       |                    |                                                                                        |                    |                         |                       |                |
| 50017                                                                  | P01570 B      | 760512                | 08550              | ELEC.SYS-IGNITION-OTHER PART<br>63 043 CHEVROLET DIVISION                              | E3 IMPALA          | 03 C                    | 079265                | 90027012       |
| DIST CAP BROKE INTO NUMEROUS PIECES WHEN ENGINE MOUNTS BROKE           |               |                       |                    |                                                                                        |                    |                         |                       |                |
| 20011                                                                  | P00899 B      | 751009                | 08550              | ELEC.SYS-IGNITION-OTHER PART<br>73 044 OLDSMOBILE                                      | 01 CUTLASS         | 08 C                    | 006285                | 03060006       |
| DISTRIBUTOR CAP CRACKED                                                |               |                       |                    |                                                                                        |                    |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0095

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                                                                                           | MAKE-MODEL                | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |           |
|---------------|---------------|--------|------------------|--------------------|------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|-------------------------|-----------------------|----------------|-----------|
| 30016         | P01241        | B      | 760203           | 08550              | ELEC.SYS.IGNITION-OTHER PART<br>73 044 OLDSMOBILE                                                                                        | 02 DELTA 88               | 08                      | C                     | 000000         | 19802003  |
| 20011         | P00903        | B      | 751008           | 09101              | COIL CASING CRACKED ON TOWER FOR DISTRIBUTOR WIRE CONN., AND DENTED<br>SWCH-BUTTON-RING-HIGH/LOW BEAM DIMMER<br>73 021 CHRYSLER DIVISION | 01 CHRYSLER               | 14                      | C                     | 034569         | 66607011  |
| 30010         | P01138        | B      | 751229           | 09101              | CIRCUIT BREAKER FAILS TO OPERATE PROPERLY ON HIGH BEAM<br>SWCH-BUTTON-RING-HIGH/LOW BEAM DIMMER<br>66 042 CADILLAC DIVISION              | 01 CADILLAC               | 21                      | C                     | 054000         | 91042007  |
| 50023         | P01611        | B      | 760601           | 09102              | PLASTIC SWITCH HELD IN PLACE BY ELEC CONTACTS-PLASTIC HOUSING FELL OUT<br>SWCH-BUTTON-RING-HEAD LIGHTS<br>68 010 AMERICAN MOTORS         | 08 REBEL                  | 73                      | C                     | 081002         | 54911007  |
| 20005         | P00800        | B      | 750813           | 09102              | EXTERNAL APPEARANCE NORMAL SUSPECT INTERNAL MALFUNCTION<br>SWCH-BUTTON-RING-HEAD LIGHTS<br>68 031 FORD DIVISION                          | G3 FORD-LTD               | 14                      | C                     | 000000         | 000000000 |
| 30021         | P01301        | B      | 760306           | 09102              | CIRCUIT BREAKER WEAK CAUSING HEAD LIGHTS TO OPERATE ERRATICLY<br>SWCH-BUTTON-RING-HEAD LIGHTS<br>75 031 FORD DIVISION                    | H3 FORD-GALAXIE 500       | 44                      | C                     | 043172         | 44312002  |
| 20005         | P00801        | B      | 750813           | 09102              | CONTACT TO PANEL LTS BENT POOR CONN. NO OTHER VIS DEFECTS<br>SWCH-BUTTON-RING-HEAD LIGHTS<br>74 031 FORD DIVISION                        | 9E BRONCO U100 4X4        | 14                      | C                     | 000000         | 000000000 |
| 40002         | P01349        | B      | 760324           | 09106              | CIRCUIT BREAKER WEAK CAUSING ERRATIC OPERATION OF HEAD LIGHTS<br>SWCH-BUTTON-RING-BRAKE LIGHTS<br>72 049 GMC                             | 9A GMC TRUCK<br>2500 4WDR | 28                      | C                     | 045000         | 52404002  |
| 40004         | P01398        | B      | 760331           | 09107              | SWITCH INOPERABLE-PROBABLE POOR CONNECTION, INTERNAL CONTACT<br>SWCH-BUTTON-RING-BACK-UP LIGHTS<br>75 031 FORD DIVISION                  | 06 PINTO                  | 28                      | C                     | 045923         | 63301003  |

INTERNAL MALFUNCTION ALL WIRES AND CONNECTIONS IN GOOD CONDITION

## PARTS RETURN PROGRAM

76/07/06 PAGE 0096

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>D RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                          | MAKE-MODEL     | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-------------------------|--------------------|---------------------------------------------------------------|----------------|-------------------------|-----------------------|----------------|
| 40000         | P01401 B      | 760331                  | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>00 000 UNKNOWN         | 00 UNKNOWN     | 44 C                    | 000000                | 63105001       |
| 30018         | P01258 B      | 760203                  | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>00 000 UNKNOWN         | 00 UNKNOWN     | 28 C                    | 000000                | 044107007      |
| 50014         | P01550 B      | 760507                  | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>67 010 AMERICAN MOTORS | 08 REBEL       | 28 C                    | 096893                | 29611001       |
| 40003         | P01355 B      | 760329                  | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>71 022 DODGE           | 00 DODGE       | 28 C                    | 063000                | 52404002       |
| 20011         | P00902 B      | 751008                  | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>70 022 DODGE           | 05 DART        | 28 C                    | 029593                | 66607011       |
| 30001         | P01003 B      | 751114                  | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>72 022 DODGE           | 06 MONACO      | 73 C                    | 026846                | 63105001       |
| 40004         | P01399 B      | 760331                  | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>68 023 PLYMOUTH        | C4 FURY III    | 28 C                    | 084124                | 63301003       |
| 20005         | P00802 B      | 750813                  | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>70 023 PLYMOUTH        | C4 FURY III    | 28 C                    | 000000                | 000000000      |
| 30018         | P01259 B      | 760203                  | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>00 030 FORD MOTORS     | 00 FORD MOTORS | 28 C                    | 000000                | 044107007      |

MOVABLE PORTION OF SWITCH MAKES POOR ELEC CONTACT - RESULT OF WEAR

PART OF PLASTIC T/S CONTACT ACTUATOR BROKE-OFF - PROBABLE POOR CONNECT

NO VISIBLE DEFECT - POSS INTERNAL OPEN

STOP LIGHT CIRCUIT INOPERATIVE

MOUNTING BRAKE LIGHT BUTTON BROKE-CAUSING SHORT-NO BRAKE LIGHTS

NO VISIBLE DEFECTS, WIRES & CONN IN GOOD COND-POSS SHORTED-UNIT MALF

TURN SIGNAL SWITCH INOPERATIVE-NO REAR SIGNALS

INOOPERATIVE - SUSPECT POOR CONTACTS

## PARTS RETURN PROGRAM

PAGE 0097

76/07/06

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>MANUFACTURER                                    | MAKE-MODEL          | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|----------------------------------------------------------------------|---------------------|-------------------------|-----------------------|----------------|
| 30023         | P01285 B      | 760214                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>72 031 FORD DIVISION          | D3 FORD-CUSTOM      | 28 C                    | 072132                | 83201004       |
|               |               |                       |                    | POSSIBLE POOR CONNECTION AT SOME POINT IN SWITCH ASSEMBLY            |                     |                         |                       |                |
| 30005         | P01070 B      | 751206                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>70 031 FORD DIVISION          | G3 FORD-LTD         | 28 C                    | 071340                | 92632037       |
|               |               |                       |                    | TURN SIGNAL SWITCH LOCATED IN STEERING COLUMN-PLASTIC-POSSIBLY WORN  |                     |                         |                       |                |
| 30018         | P01260 B      | 760203                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>71 031 FORD DIVISION          | G3 FORD-LTD         | 28 C                    | 000000                | 44107007       |
|               |               |                       |                    | INOPERATIVE-POOR CONTACT, ONE HORN CONTACT PLASTIC SUPPORT BROKEN    |                     |                         |                       |                |
| 30018         | P01260 C      | 760203                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>71 031 FORD DIVISION          | G3 FORD-LTD         | 28 C                    | 000000                | 44107007       |
|               |               |                       |                    | ONE RIVETED TERMINAL COVERED WITH MELTED PLASTIC                     |                     |                         |                       |                |
| 50018         | P01577 B      | 760521                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>71 031 FORD DIVISION          | G3 FORD-LTD         | 28 C                    | 057179                | 54130001       |
|               |               |                       |                    | NO VISIBLE PHYSICAL DAMAGE ALL CONTACTS IN GOOD COND POSS SHORT      |                     |                         |                       |                |
| 20011         | P00885 B      | 751008                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>00 031 FORD DIVISION          | H3 FORD-GALAXIE 500 | 28 C                    | 000000                | 54130001       |
|               |               |                       |                    | TURN SIGNALS & EMERGENCY SWITCH INOPERATIVE                          |                     |                         |                       |                |
| 30021         | P01278 B      | 760207                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>68 031 FORD DIVISION          | H3 FORD-GALAXIE 500 | 08 C                    | 087794                | 84111015       |
|               |               |                       |                    | PLASTIC HOUSING CRACKED ACROSS CENTER HOLE                           |                     |                         |                       |                |
| 30023         | P01296 B      | 760214                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>71 031 FORD DIVISION          | H3 FORD-GALAXIE 500 | 28 C                    | 055258                | 83201004       |
|               |               |                       |                    | POSSIBLE POOR CONTACT IN PART OF SWITCH - NO VISIBLE DEFECT          |                     |                         |                       |                |
| 50012         | P01534 B      | 760507                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>73 031 FORD DIVISION          | H3 FORD-GALAXIE 500 | 28 C                    | 048743                | 33604002       |
|               |               |                       |                    | ONE HORN BTN POST TERM, CRKD AT HSG-T/S CTACT ASSY CRKD-1/2 IS MISSG |                     |                         |                       |                |

# PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06 PAGE 0098

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME                                                      | YR | MANUFACTURER | MAKE-MODEL  | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|------------------|--------------------|------------------------------------------------------------------------|----|--------------|-------------|-------------------------|-----------------------|----------------|
| 20008         | P00849 B      | 750916           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>00 031 FORD DIVISION            |    |              | 03 FORD     | 28 C                    | 000000                | 022601028      |
|               |               |                  |                    | TURN SIGNAL SWITCH INOPERATIVE                                         |    |              |             |                         |                       |                |
| 30018         | P01256 B      | 760203           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>68 031 FORD DIVISION            |    |              | 03 FORD     | 28 C                    | 068700                | 044107007      |
|               |               |                  |                    | SHOP CLAIMS WIRE CONNECTOR MELTED IN PLASTIC                           |    |              |             |                         |                       |                |
| 30014         | P01208 B      | 760123           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>71 031 FORD DIVISION            |    |              | 03 FORD     | 28 C                    | 046844                | 000000000      |
|               |               |                  |                    | TURN SWITCH DOES NOT OPERATE ON RETURN                                 |    |              |             |                         |                       |                |
|               | P00726 B      | 750808           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>71 031 FORD DIVISION            |    |              | 03 FORD     | 28 C                    | 047220                | 065364001      |
|               |               |                  |                    | TURN SIGNAL INOPERATIVE FOR RIGHT TURN                                 |    |              |             |                         |                       |                |
| 30010         | P01140 B      | 751229           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>72 031 FORD DIVISION            |    |              | 03 FORD     | 28 C                    | 000000                | 22203030       |
|               |               |                  |                    | TURN SIGNALS INOPERATIVE-ELEC CONNECTIONS CLEAN & SECURE-NO BROKE PART |    |              |             |                         |                       |                |
| 30023         | P01302 B      | 760306           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>72 031 FORD DIVISION            |    |              | 03 FORD     | 28 C                    | 028167                | 44312002       |
|               |               |                  |                    | SUSPECT INTERNAL OPEN - NO VISIBLE DEFECT                              |    |              |             |                         |                       |                |
| 30011         | P01161 B      | 760106           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>00 031 FORD DIVISION            |    |              | 04 MAVERICK | 28 C                    | 054682                | 023513001      |
|               |               |                  |                    | NO BROKEN PARTS ON SWITCH-SWITCH DIRTY POSSIBLY HURTING CONNECTIONS    |    |              |             |                         |                       |                |
| 20009         | P00870 B      | 750925           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>73 031 FORD DIVISION            |    |              | 05 MUSTANG  | 28 C                    | 013206                | 079601021      |
|               |               |                  |                    | TURN SIGNALS INOPERATIVE                                               |    |              |             |                         |                       |                |
| 50022         | P01602 B      | 760607           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>73 031 FORD DIVISION            |    |              | 05 MUSTANG  | 28 C                    | 021500                | 12601051       |

SUSPECT INTERNAL MALFUNCTION OF 2-PRONG FLASHER TOTAL FAIL OF T SIGS

## PARTS RETURN PROGRAM

76/07/06 PAGE 0099

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, HDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                        | MAKE-MODEL     | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|-------------------------------------------------------------|----------------|-------------------------|-----------------------|----------------|
|               | P01287 B      | 760214                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>68 031 FORD DIVISION | 07 THUNDERBIRD | 28 C                    | 063026                | 83201C04       |
| 20009         | P00871 B      | 750925                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>70 031 FORD DIVISION | 07 THUNDERBIRD | 28 C                    | C57144                | 079601021      |
| 30021         | P01279 B      | 760207                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>00 031 FORD DIVISION | 08 TORINO      | 08 C                    | 041351                | 84111015       |
|               | P00454 B      | 750725                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>70 031 FORD DIVISION | 08 TORINO      | 28 C                    | C00000                | 0633C1G03      |
|               | P00455 B      | 750725                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>71 031 FORD DIVISION | 08 TORINO      | 28 C                    | 047769                | 063301G03      |
| 30018         | P01257 B      | 760203                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>72 031 FORD DIVISION | 08 TORINO      | 28 C                    | C00000                | 044107007      |
|               | P00712 B      | 750804                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>73 031 FORD DIVISION | 08 TORINO      | 28 C                    | 047725                | 091105033      |
| 30022         | P01280 B      | 760207                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>73 031 FORD DIVISION | 08 TORINO      | 08 C                    | 051044                | 84111015       |
| 30023         | P01303 B      | 760306                | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>73 031 FORD DIVISION | 08 TORINO      | 28 C                    | 048281                | 44312002       |

# PARTS RETURN PROGRAM

76/07/06 PAGE 0100

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMER                                                           | PRP<br>NUMBER | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                   | MAKE-MODEL                   | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |           |
|------------------------------------------------------------------------|---------------|------------------|--------------------|------------------------------------------------------------------|------------------------------|-------------------------|-----------------------|----------------|-----------|
| 20011                                                                  | P00686 B      | 751008           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>00 031 FORD DIVISION      | 96 F100 2DR CONV. PU<br>F100 | 28                      | C                     | 000000         | 54130001  |
| TURN SIGNAL SWITCH INOPERATIVE                                         |               |                  |                    |                                                                  |                              |                         |                       |                |           |
| 20009                                                                  | P00669 B      | 750925           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>70 032 LINCOLN            | 01 CONTINENTAL               | 73                      | C                     | 047417         | 079601021 |
| TURN SIGNAL SHORTED OUT CAUSING SIGNALS TO BE INOPERATIVE              |               |                  |                    |                                                                  |                              |                         |                       |                |           |
| 20013                                                                  | P00947 B      | 751024           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>69 033 MERCURY            | 03 COUGAR                    | 28                      | C                     | 020210         | 60626608  |
| TURN SIGNALS WOULD NOT WORK                                            |               |                  |                    |                                                                  |                              |                         |                       |                |           |
| 30011                                                                  | PC1162 B      | 760106           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>72 033 MERCURY            | 03 COUGAR                    | 28                      | C                     | 052086         | 023513001 |
| NO BROKEN PARTS IN SWITCH-GREASE ON CONTACTS COULD HAVE STOPPED CURRNT |               |                  |                    |                                                                  |                              |                         |                       |                |           |
| 30022                                                                  | P01284 B      | 760214           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>68 043 CHEVROLET DIVISION | A2 CHEVELLE-MALIBU           | 08                      | C                     | 059752         | 83201004  |
| PLASTIC SLIDE CONTACT HOUSING PICE CRACKED                             |               |                  |                    |                                                                  |                              |                         |                       |                |           |
| 40006                                                                  | P01391 B      | 760331           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>68 043 CHEVROLET DIVISION | A2 CHEVELLE-MALIBU           | 28                      | C                     | 044680         | 29611001  |
| CONNECTIONS ARE TIGHT & CLEAN-NO VISABLE DEFECTS--SHORT IN SWITCH      |               |                  |                    |                                                                  |                              |                         |                       |                |           |
| 20004                                                                  | P00721 B      | 750807           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>00 043 CHEVROLET DIVISION | A3 BELAIR<br>DELCO           | 28                      | C                     | 000000         | 052404002 |
| SWITCH INOPERATIVE WILL NOT CANCEL                                     |               |                  |                    |                                                                  |                              |                         |                       |                |           |
| 40003                                                                  | P01353 B      | 760329           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>66 043 CHEVROLET DIVISION | E0 PICK-UP MODELS<br>C-10 PU | 28                      | C                     | 000000         | 52404002  |
| POSS INTERNAL MALFUNCTION T/S SWITCH - NO VISABLE DEFECTS              |               |                  |                    |                                                                  |                              |                         |                       |                |           |
| 20008                                                                  | P00843 B      | 750911           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>69 043 CHEVROLET DIVISION | 9A CHEVROLET TRUCK AN<br>C50 | 53                      | C                     | 054000         | 084713018 |
| TURN SIGNAL WOULD NOT CANCEL-STICKS & BINDS                            |               |                  |                    |                                                                  |                              |                         |                       |                |           |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0101

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER                                                          | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                        | MAKE-MODEL               | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |           |
|------------------------------------------------------------------------|---------------|--------|------------------|--------------------|-----------------------------------------------------------------------|--------------------------|-------------------------|-----------------------|----------------|-----------|
| 50012                                                                  | P01535        | B      | 760507           | 09110              | SWCH-BUTTON-RING-TURN SIGNAL LIGHTS<br>68 045 PONTIAC DIVISION        | C4 TEMPEST               | 28                      | C                     | 000000         | 33604002  |
| INSULATION POOR UN SOME WIRES- SHOP CLAIMS WRONG REPL SWCH WAS INSTAL  |               |        |                  |                    |                                                                       |                          |                         |                       |                |           |
| 20002                                                                  | P00480        | B      | 750711           | 09111              | SWCH-BUTTON-RING-EMRG FLASH HZRD WARN-LIT<br>72 031 FORD DIVISION     | A8 GRAN TORINO           | 28                      | C                     | 000000         | 024153008 |
| EMRG. FLASH. HZRD. WARN. LIGHT SWITCH INOPERATIVE                      |               |        |                  |                    |                                                                       |                          |                         |                       |                |           |
| 20002                                                                  | P00482        | B      | 750711           | 09111              | SWCH-BUTTON-RING-EMRG FLASH HZRD WARN-LIT<br>72 031 FORD DIVISION     | G3 FORD-LTD              | 28                      | C                     | 000000         | 024153008 |
| EMRG. FLASH HZRD WARN LIGHT SWITCH FAIL TO OPERATE                     |               |        |                  |                    |                                                                       |                          |                         |                       |                |           |
| 20017                                                                  | P00989        | B      | 751114           | 09510              | COMMUNICATIONS-HORN ASSEMBLY-BUTTON-RING<br>71 031 FORD DIVISION      | H3 FORD-GALAXIE 500      | 73                      | C                     | 017009         | 80910024  |
| PLASTIC CRADLE ASSEMBLY CRACKED,INSULATOR MELTED,COPPER BANDS TWISTED  |               |        |                  |                    |                                                                       |                          |                         |                       |                |           |
|                                                                        | P01015        | B      | 751118           | 10100              | VISUAL SYSTEMS GLASS<br>72 033 MERCURY                                | 01 CAPRI                 | 21                      | C                     | 000000         | 90405016  |
| BONDING ON WINDOW LOCK PULLS APART,WINDOW FELL OUT-NO PART RECEIVED    |               |        |                  |                    |                                                                       |                          |                         |                       |                |           |
| 40002                                                                  | P01340        | B      | 760324           | 10311              | VISUAL SYS WINDSHIELD WIPER/WASHER SWITCH<br>65 022 DODGE             | C4 CORONET-440           | 28                      | C                     | 089769         | 92632025  |
| WIPER/WASHER SWITCH INOP-CONNECTIONS CLEAN & SECURE-INTERNAL PROB      |               |        |                  |                    |                                                                       |                          |                         |                       |                |           |
| 50002                                                                  | P01446        | B      | 760401           | 10311              | VISUAL SYS WINDSHIELD WIPER/WASHER SWITCH<br>69 042 CADILLAC DIVISION | 01 CADILLAC<br>AMBULANCE | 28                      | C                     | 000000         | 00000000  |
| INOPERATIVE-SUSPECT INTERNAL MALFUNCTION                               |               |        |                  |                    |                                                                       |                          |                         |                       |                |           |
| 20003                                                                  | P00467        | B      | 750708           | 10312              | VISUAL SYS WINDSHIELD WIPER,MOTOR<br>00 010 AMERICAN MOTORS           | 09 JEEP                  | 28                      | C                     | 034620         | 063105001 |
| WINDSHIELD WIPER MOTOR FAIL TO OPERATE                                 |               |        |                  |                    |                                                                       |                          |                         |                       |                |           |
| 30008                                                                  | P01124        | B      | 751226           | 10312              | VISUAL SYS WINDSHIELD WIPER,MOTOR<br>73 041 BUICK                     | A8 CENTURION             | 28                      | C                     | 030646         | 63105001  |
| WIPER MOTOR SUDDENLY QUIT-PLENTY OF LUBRICATION ON PARTS-INTERNAL FAIL |               |        |                  |                    |                                                                       |                          |                         |                       |                |           |

## PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

76/07/06 PAGE 0102

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER                                                         | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                   | MAKE-MODEL                     | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|-----------------------------------------------------------------------|---------------|--------|------------------|--------------------|---------------------------------------------------------------------|--------------------------------|-------------------------|-----------------------|----------------|
| 50010                                                                 | P01560        | B      | 760506           | 10312              | VISUAL SYS WINDSHIELD WIPER,MOTOR<br>74 045 PONTIAC DIVISION        | 05 VENTURA                     | 28 C                    | 024834                | 00000000       |
| DRIVING SHAFT ROTATION NORMAL-CON APPEAR NORM, POSS INTERNAL ELEC PRB |               |        |                  |                    |                                                                     |                                |                         |                       |                |
| 50011                                                                 | P01522        | B      | 760501           | 10313              | VISUAL SYS WINDSHLD WPR LNKG.-PIVOT,DRV AS<br>75 031 FORD DIVISION  | H3 FORD-GALAXIE 500            | 34 C                    | 049573                | 44312002       |
| SPLINED DRUM ONTO WHICH ARM MOUNTS IS LOOSE ON SHAFT TO TRANS LINKAGE |               |        |                  |                    |                                                                     |                                |                         |                       |                |
| 20004                                                                 | P00452        | B      | 750721           | 10314              | VISUAL SYSTEMS WINDSHIELD WIPER ARM<br>72 043 CHEVROLET DIVISION    | E3 IMPALA                      | 57 C                    | 018950                | 027105003      |
| WINDSHIELD WIPER ARM MORE EXCESSIVELY AT PIVOT CONNECTION             |               |        |                  |                    |                                                                     |                                |                         |                       |                |
| 40008                                                                 | P01406        | C      | 760331           | 10315              | VISUAL SYSTEMS WINDSHIELD WIPER BLADE<br>74 151 ADAM OPEL AG        | 01 OPEL                        | 57 C                    | 006171                | 12601050       |
| RUBBER INSERT WORN AT ENDS ONE END OF METAL BLADE IS BENT             |               |        |                  |                    |                                                                     |                                |                         |                       |                |
| 40009                                                                 | P01406        | B      | 760331           | 10315              | VISUAL SYSTEMS WINDSHIELD WIPER BLADE<br>74 151 ADAM OPEL AG        | 01 OPEL<br>KADET               | 57 C                    | 006171                | 12601050       |
| RUBBER IS 70 PERC SEPARATED ALONG PORTION WHICH MTS IN METAL GUIDE    |               |        |                  |                    |                                                                     |                                |                         |                       |                |
| 20017                                                                 | P00986        | B      | 751114           | 10321              | VISUAL SYSTEMS WINDSHIELD WASHER-MOTOR<br>69 043 CHEVROLET DIVISION | E0 PICK-UP MODELS<br>C10 TRUCK | 33 C                    | 034129                | 80910024       |
| CORROSION ON SPRING-ACTUATING MECHANISMS JAMMED-PLASTIC HOUSING CRACK |               |        |                  |                    |                                                                     |                                |                         |                       |                |
| 20008                                                                 | P00845        | B      | 750912           | 11100              | WATER-HEATER,DEFROSTER,DEFUGGER<br>72 023 PLYMOUTH                  | C4 FURY III<br>FURY II         | 08 C                    | 018472                | 088201019      |
| HEATER VALVE CRACKED                                                  |               |        |                  |                    |                                                                     |                                |                         |                       |                |
| 20007                                                                 | P00707        | B      | 750801           | 11100              | WATER-HEATER,DEFROSTER,DEFUGGER<br>73 044 OLDSMOBILE                | D1 CUTLASS-VSTA CRUSR          | 28 D                    | 000000                | 048910009      |
| HEATER CONTROL VALVE INOPERATIVE CAUSING LOSS OF COOLANT              |               |        |                  |                    |                                                                     |                                |                         |                       |                |
| 30016                                                                 | P01240        | B      | 760203           | 11101              | WATER-HEATK,DEFROSTR,DEFUGGR-CONTRL SWITC<br>62 044 OLDSMOBILE      | 02 DELTA 88                    | 32 C                    | 070000                | 19802003       |
| HEATER CONTROL VALVE LEAKS AT DIAPHRAM COVER,WATER PASSAGES CORRODED  |               |        |                  |                    |                                                                     |                                |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0103

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT<br>NAME<br>YR MANUFACTURER                                   | MAKE-MODEL          | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|------------------------------------------------------------------------|---------------------|-------------------------|-----------------------|----------------|
| 30015         | P01226        | B 760203              | 11102              | WATER-HEATER, DEFROSTER, FAN MOTOR SWITCH<br>75 031 FORD DIVISION      | 08 TORINO           | 04 C                    | 012141                | 22203030       |
|               |               |                       |                    | HEAVY RESISTOR COIL BURNED AND SEPARATED                               |                     |                         |                       |                |
| 20017         | P00988        | B 751114              | 11103              | WATER-HEATER, DEFROSTER, FAN MOTOR<br>74 031 FORD DIVISION             | A8 GRAN TORINO      | 33 C                    | 035640                | 80910024       |
|               |               |                       |                    | SHAFT TURNS IN MOTOR W/EXCESSIVE EFFORT-SOME RUST EVIDENT INSIDE MOTOR |                     |                         |                       |                |
| 20007         | P00830        | B 750828              | 11109              | WATER-HEATER, DEFROSTER, DEFROGGER-HOSE<br>75 045 PONTIAC DIVISION     | 00 PONTIAC DIVISION | 08 D                    | 006040                | 088001013      |
|               |               |                       |                    | BYPASS HEATER HOSE HAD BUBBLE WHICH BROKE AFTER 6040 MILES             |                     |                         |                       |                |
| 50009         | P01513        | B 760419              | 11110              | WATER-HTR, DEFROSTER, DEFROGGER-HOSE<br>70 021 CHRYSLER DIVISION       | A1 NEWPORT          | 08 D                    | 000000                | 51166004       |
|               |               |                       |                    | CRACK IN CASE - ONE LOOSE SCREW - LEAKS COOLANT                        |                     |                         |                       |                |
| 30019         | P01255        | B 760203              | 11606              | AIR CONDITIONER-HOSE REFRIGERANT HI/LO PR<br>75 043 CHEVROLET DIVISION | 06 CORVETTE         | 08 C                    | 017800                | 044107007      |
|               |               |                       |                    | HOSE IS SPLIT AROUND CIRCUMFERENCE ONE INCH FROM FITTING               |                     |                         |                       |                |
| 50018         | P01578        | B 760521              | 11608              | AIR CONDITIONER-EXPANSION VALVE<br>72 031 FORD DIVISION                | A8 GRAN TORINO      | 28 C                    | 071096                | 01230005       |
|               |               |                       |                    | PHYSICAL APPEARANCE OF VALVE NORMAL SUSPECT INTERNAL MALFUNCTION       |                     |                         |                       |                |
| 40001         | P01319        | B 760320              | 11609              | AIR CONDITIONER-COMPRESSOR<br>72 032 LINCOLN                           | A2 MARK IV          | 57 C                    | 030802                | 06120003       |
|               |               |                       |                    | CLUTCH PLATE UNIT DISASSEMBLED SOME WEAR ON FRICTION SURFACES-RUSTY    |                     |                         |                       |                |
| 30015         | P01227        | B 760203              | 11614              | AIR CONDITIONER-OTHER PART<br>73 033 MERCURY                           | 04 MERCURY          | 28 C                    | 029361                | 22203030       |
|               |               |                       |                    | ELECTRIC VACUUM SWITCH DOES NOT WORK PROPERLY                          |                     |                         |                       |                |
| 20003         | P00476        | B 750708              | 12310              | SEAT TRACKS AND ANCHORS<br>68 045 PONTIAC DIVISION                     | B4 LE MANS          | 03 A                    | 000000                | 098499007      |
|               |               |                       |                    | SEAT BELT ANCHOR BROKE ON IMPACT CAUSING DRIVER TO BE THROWN FORWARD   |                     |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06

PAGE 0104

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT, MODEL, MDL YR

| BIN NUMBER                                                             | PRP I<br>NUMBER | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                   | MAKE-MODEL                  | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|------------------------------------------------------------------------|-----------------|------------------|--------------------|------------------------------------------------------------------|-----------------------------|-------------------------|-----------------------|----------------|
| 50013                                                                  | P01539 B        | 760507           | 12410              | INSTRUMENT PANEL MATERIAL & PADDING<br>76 043 CHEVROLET DIVISION | D9 VEGA KAMMBACK            | 25 A                    | 000000                | 29405008       |
| BURNED PORTION OF PLASTIC DASH, PROBABLY PIECE SURROUNDING INST. CLUST |                 |                  |                    |                                                                  |                             |                         |                       |                |
| 30002                                                                  | P01025 B        | 751119           | 13110              | STRUCTURE-FRAME & MEMBERS(GIVE SIDE/END)<br>70 023 PLYMOUTH      | 01 BARRACUDA                | 09 C                    | 000000                | 63123002       |
| SHOCK MOUNTING HOLE TORN FROM CROSSMEMBER-OTHER MOUNT SPLIT-ELONGATED  |                 |                  |                    |                                                                  |                             |                         |                       |                |
| 50003                                                                  | P01451 B        | 760402           | 13110              | STRUCTURE-FRAME & MEMBERS(GIVE SIDE/END)<br>69 031 FORD DIVISION | H3 FORD-GALAXIE 500         | 21 C                    | 073000                | 48197006       |
| FRAME TORE AWAY AT IDLER ARM BRCKT MNTNG HOLES-IDLER ARM DOESN'T PIVOT |                 |                  |                    |                                                                  |                             |                         |                       |                |
| 40004                                                                  | P01372 B        | 760330           | 13110              | STRUCTURE-FRAME & MEMBERS(GIVE SIDE/END)<br>66 031 FORD DIVISION | 03 FORD SQUIRE              | 03 C                    | 073986                | 02140002       |
| FRAME ATTACHED TO IDLER ARM BRCKT MNTG BOLT BROKE AND RELEASED BRACKET |                 |                  |                    |                                                                  |                             |                         |                       |                |
| 40003                                                                  | P01345 B        | 760324           | 13110              | STRUCTURE-FRAME & MEMBERS(GIVE SIDE/END)<br>68 031 FORD DIVISION | 03 FORD                     | 03 C                    | 070795                | 02140002       |
| FRAME BROKE AT IDLER ARM BRACKET MOUNTING - EVIDENCE OF RUST           |                 |                  |                    |                                                                  |                             |                         |                       |                |
|                                                                        | P01016 B        | 751118           | 13110              | STRUCTURE-FRAME & MEMBERS(GIVE SIDE/END)<br>70 041 BUICK         | 04 LE SABRE                 | 59 C                    | 035132                | 90405016       |
| FRONT SUSPENSION CROSSMEMBER BROKE AT HORNS-POOR WELD-NO PART RECEIVED |                 |                  |                    |                                                                  |                             |                         |                       |                |
| 20008                                                                  | P00819 B        | 750827           | 13110              | STRUCTURE-FRAME & MEMBERS(GIVE SIDE/END)<br>68 044 OLDSMOBILE    | 01 CUTLASS                  | 49 A                    | 098000                | 004104003      |
| FRAME MEMBER RUSTED OUT CAUSING STEERING BOX TO BREAK LOOSE            |                 |                  |                    |                                                                  |                             |                         |                       |                |
| 50012                                                                  | P01533 B        | 760507           | 13420              | DOOR ASSEMBLY-HINGE & ATTACHMENTS<br>74 031 FORD DIVISION        | AC ECONOLINE SERIES<br>E200 | 03 C                    | 018000                | 33604002       |
| HINGE FASTENER FROM SLIDING SIDE DOOR BROKE-MADE OF LTWT CAST METAL    |                 |                  |                    |                                                                  |                             |                         |                       |                |
| 13720                                                                  | P01293 C        | 760204           | 13720              | HOOD ASSEMBLY-HINGE & ATTACHMENTS<br>70 030 FORD MOTORS          | 00 FORD MOTORS<br>FULL-SIZE | 14 C                    | 000000                | 13045014       |
| HOOD HINGES NEED LUBRICATION-CAUSING HOOD TO BREAK NEAR HINGE-NO PART  |                 |                  |                    |                                                                  |                             |                         |                       |                |

## PARTS RETURN PROGRAM

76/07/06 PAGE 0105

OFFICE OF DEFECTS INVESTIGATION  
CUMULATIVE PARTS RECEIVED INDEX  
AS OF 30 JUN 76

SORTED BY COMPONENT,MODEL,MDL YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                         | MAKE-MODEL                  | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|--------|------------------|--------------------|------------------------------------------------------------------------|-----------------------------|-------------------------|-----------------------|----------------|
| 30026         | P01299        | C      | 760301           | 13720              | HOOD ASSEMBLY-HINGE & ATTACHMENTS<br>72 031 FORD DIVISION              | G3 FORD-LTD                 | 76 C                    | 026000                | 53140017       |
|               |               |        |                  |                    | ONE ARM SLIGHTLY TORN NEAR PIVOT                                       |                             |                         |                       |                |
| 30026         | P01299        | B      | 760301           | 13720              | HOOD ASSEMBLY-HINGE & ATTACHMENTS<br>72 031 FORD DIVISION              | G3 FORD-LTD                 | 76 C                    | 026000                | 53140017       |
|               |               |        |                  |                    | ONE ARM BENT AT PIVOT                                                  |                             |                         |                       |                |
|               | P01293        | B      | 760204           | 13730              | HOOD ASSEMBLY-LATCHES<br>70 030 FORD MOTORS                            | 00 FORD MOTORS<br>FULL SIZE | 20 C                    | 000000                | 13045014       |
|               |               |        |                  |                    | INFO PERTAINING TO HOOD LATCH FAILURE-INSUFFICIENT LUBRICATION-NO PART |                             |                         |                       |                |
| 20015         | P00957        | B      | 751024           | 13730              | HOOD ASSEMBLY-LATCHES<br>74 044 OLDSMOBILE                             | 00 OLDSMOBILE               | 49 C                    | 000000                | 24017016       |
|               |               |        |                  |                    | CABLE EATEN THROUGH BY BATTERY ACID THIRD TIME                         |                             |                         |                       |                |
| 20016         | P00971        | B      | 751108           | 15501              | JACKS-BUMPER<br>74 045 PONTIAC DIVISION                                | C3 CATALINA                 | 59 C                    | 040000                | 48197006       |
|               |               |        |                  |                    | SPOT WELDS BROKE ON JACK STAND-WELDS HELD JACK SUPPORT TO BROAD BASE   |                             |                         |                       |                |
| 50010         | P01586        | B      | 760607           | 15503              | JACKS-STAND<br>00 300 EQUIPMENT MANUFACTURERS 1W WESTERN AUTO          |                             | 76 C                    | 000000                | 85364001       |
|               |               |        |                  |                    | TWO-TON JACK STAND COLLAPSED AT TOP OF TRI-POD UNDER 69 BELAIR         |                             |                         |                       |                |

## SECTION 4

### THE PRP NEWS

#### 4.0 General

One of the primary methods employed to both educate and motivate the PRP enrollees to submit failed parts is the newsletter. Our concern during the fifth year of operation has been to educate members in these areas; PRP objectives and operation, what parts are needed for the program, what a safety-related defect is, and what the PRP accomplishes for the NHTSA and highway safety. We have used the PRP Newsletter as the principle tool to accomplish this task.

Beyond educating members, we saw a need to communicate up to date information to attract the interest of our members. Service data on new models, descriptions of current investigations and recalls, and DOT news releases have been subjects of PRP newsletter articles in the past twelve months. Regular features include current levels of enrollment and participation as well as the names of contributing shops for the reporting period covered by the newsletter. These features and articles are intended to motivate non-contributing members to submit failed parts.

Shortly after receiving the contract award, we determined that there was a need for more communications between participants and KSI if we were to achieve a significant increase in the level of participation before the contract period ended.

It became apparent that many of those shops enrolled in the program knew little about the PRP objectives and operation. Many shops were not sure what their role in the program was or what type of parts qualified as safety-related. Many participants believed that if we had received one or two similar components from the same model vehicle, then we did not desire any more of these components. An example of this situation is broken motor mounts on Ford models with V-8 engines. Many parts had been received and articles had been published in the Newsletter for this particular problem. Some shops wrote notes to the contractor stating that they had removed many of these parts but since parts of this type had already been submitted in quantity, the shop believed the program did not need further input and the parts were thrown away. Considerable effort was required to change this attitude held by shop members.

4.1        Following this section we have provided a xeroxed copy of each of the 12 issues of the PRP News.



# NEWS PARTS RETURN PROGRAM NEWS

CONTRACT NO. DOT-HS-5-01166


U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Vol. 1, No. 12

June 1976

## AUTO JACK STANDS

The Parts Return Program has received a Western Auto Wizard Jack Stand Model A5030 from AC-CURATE AUTOMOTIVE ATTENTION, Yuma, Arizona. The jack stand reportedly collapsed while supporting a 1965 Chevrolet (see photo). A stand was also submitted from PRITZ'S FOREIGN CARS OF COLORADO, Colorado Springs, for evaluation. Mr. Pritzelwitz states that one of his stands, similar to the unit submitted, collapsed, and that he does not believe the stand will support its 3,000-pound rated capacity. The manufacturer is unknown; however, the unit appears to be a type of trailer-leveling jack.



In 1974, the National Highway Traffic Safety Administration (NHTSA) completed some survey-type testing of various jack stands purchased from retail stores. The testing program involved 40 different models; nine of the models failed test requirements. Testing consisted of statically loading each jack stand to the load rating on the label. Failure was defined as the inability of the jack stand to support the rated load, or deformation (compression) of 1/2-inch or more while the load was applied.

The nine jack stands that failed NHTSA requirements are as follows:

- Wizard A-5030 (Western Auto Stores).
- Drednaut 6-41601 (Auto Specialties).
- Riverside 61-5662 (Montgomery Ward).
- K-Mart 80511 (S. S. Kresge).
- Globe Fabricated JS-100.
- Globe Fabricated JS-200.
- Kar-Rite 1052.
- Pathfinder Auto Lamp Model 7224.
- Pathfinder Auto Lamp Model 8336.

Recall corrective action has been taken by the manufacturers of the jack stand models that are underlined above. However, the NHTSA is currently investigating the remaining four models which failed to meet their load ratings.

(Continued next page)

## AUTO JACK STANDS (CONT'D)

Because of the dangers involved in improper use of jack stands, the NHTSA strongly recommends following these guidelines when purchasing or using such devices:



- Use jack stands that are load rated by the manufacturer.
- Inspect these stands at the time of purchase and periodically during use. Look for cracks, deformation, missing welds, bent pins, etc.
- Know the load (weight) to be supported and don't overload.
- Use only in pairs.
- Support the vehicle under the axle or frame parts only. Center the load on the support plate.

- Use jack stands only on flat, level, hard surfaces.
- Use wheel chocks to prevent the vehicle from moving.
- Lower loads slowly onto stands.
- Keep bystanders away from the vehicle.
- Do not work under the vehicle with the tires removed.
- Do not use the stand if it has been mis-treated or is bent or corroded.

If any of our PRP members are aware of any other jack stand failures not the result of improper use or application, please let us know. Just place the failed stand in one of your return mailbags or send us a note describing the make/model of jack stand involved, the usage conditions, and the nature of the failure.

## SERVICE ALERT

Chevrolet's new model, the Chevette, may be equipped with optional full wheel covers that appear to be one piece. Actually, the cover is two pieces, a loose ring and the regular hub cap which holds the ring in place. When removing the cover, prying must be done at the edge of the hub cap or the costly ring could be damaged.



## AMC RECALLS PACERS FOR POSSIBLE REAR SEAT LATCH FAILURES

NHTSA RECALL NUMBER 76-0079

American Motors Corporation is recalling 19,581 Pacers. The Pacers involved are those 1976 models built from 4 December 1975 through 19 March 1976. The rivet securing the rear seat back latch lever to the seat back hinge arm has a shallow staking impression on some assemblies. During certain tests under NHTSA, Federal Motor Vehicle Safety Standard Number 207 (Seating Systems), the rivet could pull through the hinge arm and release the latch. Vehicle inspections and necessary corrections will be made at no cost to the owners of affected vehicles.

# **WANTED**

## **BADLY SCORED OR GROOVED DISK BRAKE ROTORS AND BRAKE DRUMS**

The Parts Return Program needs your help in obtaining scored or grooved discs and drums from 1970 to 1976 full size cars for use in an NHTSA test program.

We need parts that are damaged even from misuse, such as running with worn out pads or shoes (metal to metal).

Make, model, and year of the vehicle is very important, but we also need to know which wheel the parts came from (such as "left front" or "right rear").

### **HERE'S ALL YOU DO:**

- **FILL OUT DATA TAG AND ATTACH TO PART.**
- **PLACE IN CANVAS MAIL BAG, TIE THE CORD AND PUT IN MAIL BOX. POSTAGE IS PAID.**

**WE NEED MORE PARTS. WE NEED YOU. BECOME AN ACTIVE  
PARTICIPANT IN THIS PUBLIC SAFETY PROGRAM TODAY.**

**THANKS!**

## ITEMS OF INTEREST

- As we reported in our April newsletter, we have been in contact with Mr. Robert Schmidt of the Automotive Service Councils of Pennsylvania. We wish to thank the ASC of Pennsylvania for their PRP article in the Keystone Automotive Independent, June 1976.
- We have been in contact with the American Automobile Association (AAA) and are happy to report that the next issue of Let's Talk Road Service for Emergency Road Service Contractors will include an article about the PRP. We wish to thank the AAA for their support.
- In their newsletter, Let's Talk Road Service, the AAA has a suggestion that we think is worth mentioning again. Before installing a replacement part, such as a water pump, record your initials, the date of installation, and the initials of the part wholesaler with a pencil-type scribe on the part. Then cover the inscription with yellow paint. If the part is ever returned as defective, chip away the paint to reveal the inscription. This way, you can tell whether it is still under warranty and where it was purchased without having to refer to your invoices.
- Mr. Julius Meisner of BRANCH AUTO PARTS, Albany, New York, reports having difficulty with the braking system on his 1974 Ford Grand Torino. The vehicle has approximately 14,000 miles on it, and the brake pedal reportedly travels halfway to the floor before any braking effect occurs. The brakes must be pumped to obtain less travel. The condition has reportedly existed since the dealer turned the rotors to remove rust which had accumulated during storage. The repairs were performed after the pedal traveled to the floor on one occasion shortly after delivery.
- We have received a report from B. G. TANZIER'S AUTO REBUILD in Bellevue, Washington, concerning strut bar and frame bracket failures on two (1975 and 1976) Toyota Corolla Station Wagons. Upon impact in each case, the strut bar reportedly pulled through the frame bracket, allowing the front wheel to be driven through the firewall and into the passenger compartment near the occupant's feet. On the 1976 vehicle, the failure occurred on the right side, while on the 1975 model the left wheel was involved. Since no parts were available, the shop returned some excellent photographs.
- Ned Young of EUROPEAN MOTORS, Washington, D.C., reports replacing approximately six steering column couplers in 1971-1975 Mercury Capris. The coupler is made of metal with a rubber-like composite bonding the two plates together. In each case, the rubber reportedly separated from the metal resulting in steering looseness. Mr. Young also returned a rack and pinion steering gear assembly from a 1972 Capri. The bearing which locates the pinion on the rack had disintegrated, reportedly resulting in loss of steering control.
- Mr. C. M. Cochran of COCHRAN EQUIPMENT COMPANY, Middletown, Delaware, reports a severe shimmy in the front of nine Ford B700 school buses owned by the company. The condition occurs after driving over a bump or pothole and continues until the vehicle is brought to a near stop. The model years of the buses involved are 1970, and 1973 through 1975.

## OUTSTANDING SHOPS

Our outstanding shops are those shops that have sent into the PRP at least one part during the current month. A shop that sends in parts in consecutive months is identified by a number in parenthesis before the name. This number identifies the consecutive months the shop has sent in a part. New shops that have just become active in the PRP are identified with an asterisk before their name. During June 1976, eight shops became active participants in the PRP. Seven shops have sent in failed parts in consecutive months.

### REGION 0

- BABEL'S SERVICE  
Manchester, New Hampshire
- CAMBRIDGE BRAKE SERVICE  
Cambridge, Massachusetts
- (2) HARRY'S AUTO SERVICE  
Great Barrington, Massachusetts
- WORCESTER VOCATIONAL TECHNICAL H.S.  
Worcester, Massachusetts

### REGION 1

- BRANCH AUTO PARTS  
Albany, New York
- FERINO BROTHERS' EXXON  
Easterville, Pennsylvania
- KOLESNIK'S SERVICE STATION  
Rochester, New York
- LongBARD'S EXXON STATION  
Poughkeepsie, New York
- YOUNGWOOD EXXON  
Youngwood, Pennsylvania

### REGION 2

- AFRO-ENGINEERING  
Falls Church, Virginia
- (5) BEEA AUTO SERVICE  
Greenville, South Carolina
- (2) EUROPEAN MOTORS, LIMITED  
Washington, D.C.
- P AND J AUTOMOTIVE  
Falls Church, Virginia

### REGION 3

- AUTOMOTIVE MAINTENANCE, INC.  
Sarasota, Florida
- (2) SUNRAY OIL AND GAS  
Tampa, Florida

### REGION 4

- (2) EVAN'S BRAKE SERVICE, INC.  
Cleveland, Ohio
- LOUISVILLE AUTO SPRING AND BRAKE  
Louisville, Kentucky
- (2) TAYLOR'S GARAGE AND SERVICE STATION  
Akron, Ohio

### REGION 5

- FRENZ'S BRAKE SERVICE, INC.  
Minneapolis, Minnesota
- HERFEL 66 SERVICE  
Sioux City, Iowa
- JOE'S AUTO SERVICE  
Appleton, Wisconsin
- RICHFIELD WHEEL ALIGNMENT  
Minneapolis, Minnesota
- TOMMY'S AUTO REPAIR  
Sioux City, Iowa

### REGION 6

- (9) DICK JORDAN STANDARD SERVICE STATION  
Clayton, Missouri
- GENE'S AUTOMOTIVE SERVICE  
Garnett, Kansas
- TIM'S IMPORT SALES AND SERVICE  
Hutchinson, Kansas

### REGION 7

- HILL'S AUTOMOTIVE CLINIC  
Abilene, Texas

### REGION 8

- ACCURATE AUTOMOTIVE ATTENTION  
Yuma, Arizona
- BUZZ'S SKELLY SERVICE  
Colorado Springs, Colorado

### REGION 9

- DOYLE AUTOMOTIVE SERVICE  
Seattle, Washington

### REGION 9A


- DUANE'S TUNE-UP CLINIC  
Manteca, California
- LEE'S AUTO SAFETY CENTER  
Santa Ana, California
- RANCHO CORDOVA GARAGE  
Rancho Cordova, California
- VANOWEN BRAKE AND WHEEL  
North Hollywood, California

NOTE: We need more participating shops. If you know of an independent automotive repair facility in your area who you think might want to help out in this Program, please send their name and address to us. Thanks.

## CURRENT PRP PARTICIPATION

The graph below identifies the number of active shops within each Region. One hundred forty one shops have joined our active team and sent in a part. Keep up the good work. We still need many more shops on our active team and a lot more parts.

(As of 30 June 1976)



## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have any questions which need answers, or would like to pass on comments, please call us collect. Place your call to Bruce Beddow, Jonni Peizer, or Guy Whiddon at (703) 527-4500. We are Eastern Time and are normally available Monday through Friday from 8:30 a.m. to 5:30 p.m. Likewise, if you have a contribution or suggestion for the PRP News, please send it to Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention: Bruce E. Beddow.

## **NATIONAL PARTS RETURN PROGRAM** DESCRIPTION AND FUNCTION

- The PRP involves the voluntary submittal by independent repair shops of failed automotive components. Components are submitted to a representative (Kappa Systems, Inc.) of the National Highway Traffic Safety Administration (NHTSA).
- The purpose of the PRP is to gather information on these components to help the NHTSA identify the existence of safety-related, manufacturing defects in design, materials, construction, or performance of motor vehicles and motor vehicle equipment. Under the authority of the National Traffic and Motor Vehicle Safety Act of 1966, and Amendments to the Act in 1974, the NHTSA can require manufacturers to conduct safety defect notification campaigns when it has been determined that a defect relating to motor vehicle safety exists.
- The information obtained from these parts is also valuable in preparing Federal motor vehicle safety standards.

Your shop can help. The parts that you send in will give us vital information that cannot be obtained in any other way □

**PARTS RETURN PROGRAM**  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209



# NEWS PARTS RETURN PROGRAM NEWS

CONTRACT NO. DOT-HS-5-01166

U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Vol. 1, No. 11

May 1976

## CASE OF THE MONTH


ALLEGED FAILURES OF POWER STEERING, GEAR BOX SEALS AND STEERING TIE RODS ON 1975 PACERS MANUFACTURED BY THE AMERICAN MOTORS CORPORATION

(CASE C6-22)

This case was opened on April 14, 1976, based on owner complaints of tie rod failures prior to and subsequent to power steering gear box oil leakage repairs. Investigation was initiated to determine whether the alleged failures represent a potential safety-related defect within the meaning of the National Traffic and Motor Vehicle Safety Act of 1966.

The 1975 Pacer is equipped with a rack and pinion steering unit. This unit which is mounted transversely to the vehicle frame between the front wheels, has a short tie rod at each end which connects to its respective steering knuckle. Steering wheel motion turns the pinion which, in turn, moves the rack inside the steering gear box laterally to the left or right. The rack transmits steering motion through the tie rods to the front wheels. Please see the diagram below.

Allegedly, the tie rods either break or separate from the rack and pinion gear box, resulting in loss of steering control. Some owners have reported high steering effort or binding, or gear box oil leakage prior to failure. The NHTSA concern is whether failure of the rods or leakage of gear box oil occurs, as alleged, and, if so, whether either results in loss of vehicle control, property damage, or injury accidents.



## NHTSA ADMINISTRATOR'S AWARD

At the end of June, we will select those shops that have submitted at least 20 parts over the last year (since July 1, 1976) for the NHTSA Administrator's Award for outstanding participation. A Certificate of Appreciation will be provided to each qualifying member and a local newspaper will be notified that the participant has received the award. The shops that have already qualified for this year's award are listed below. Congratulations and many thanks!

| <u># of Parts</u> | <u>Shop Name</u>                                             | <u># of Parts</u> | <u>Shop Name</u>                            |
|-------------------|--------------------------------------------------------------|-------------------|---------------------------------------------|
| 49                | PARK AUTO REPAIR<br>Chicago, Illinois                        | 22                | BERT'S ARCO STATION<br>Wilmington, Delaware |
| 48                | ISE AUTOMOTIVE SERVICE<br>Hollywood, California              | 21                | DOYLE AUTOMOTIVE<br>Seattle, Washington     |
| 36                | DICK JORDAN STANDARD<br>SERVICE STATION<br>Clayton, Missouri | 20                | AUTO HOSPITAL<br>Lincoln, Nebraska          |

The following shops are close to the mark. We would like to have you receive the award; let us hear from you this month.

| <u># of Parts</u> | <u>Shop Name</u>                                                             | <u># of Parts</u> | <u>Shop Name</u>                                                               |
|-------------------|------------------------------------------------------------------------------|-------------------|--------------------------------------------------------------------------------|
| 11                | Mr. Stanley Adams<br>ADAM'S MOTOR SERVICE<br>Saint Charles, Missouri         | 11                | Mr. Harry Billings<br>HARRY'S AUTO SERVICE<br>Great Barrington, Massachusetts  |
| 17                | Mr. George Casper<br>AUTO BRAKE CORPORATION<br>Norfolk, Virginia             | 12                | Mr. Donald Kolesnik<br>KOLESNIK'S SERVICE STATION<br>Rochester, New York       |
| 19                | Mr. David Laskis<br>BEREA AUTO SERVICE<br>Greenville, South Carolina         | 11                | Mr. Laurence J. Smith<br>SMITH BROTHERS BRAKE AND WHEEL<br>Tujunga, California |
| 12                | Mr. Charles Nickerson<br>CAMBRIDGE BRAKE SERVICE<br>Cambridge, Massachusetts | 17                | Mr. Tim Foran<br>TIM'S IMPORT SALES AND SERVICE<br>Hutchinson, Kansas          |
| 12                | Mr. Randall D. Halblom<br>CEDAR RAPIDS AUTO SERVICE<br>Cedar Rapids, Iowa    | 11                | Mr. Thomas Lacugnato<br>TOMMY'S AUTO REPAIR<br>Sioux City, Iowa                |
| 17                | Mr. Floyd Hagan<br>HAGAN SERVICE CENTER<br>Gainesville, Georgia              | 16                | Mr. Bill Chisholm<br>VANOWEN BRAKE AND WHEEL<br>North Hollywood, California    |

## ITEMS OF INTEREST

- Mr. Ned Young of European Motors, Limited, in Washington, D.C., has encountered approximately 12 to 15 Fiat Model 128's with broken steering rack tube bushings on the right side. The plastic bushing, which centers the tie rod in the tube, is held in place by three ears or tabs. The locating tabs may break when the steering is in the far left position, and since the diameter of the bushing is smaller than the inside diameter of the tube, it may be pushed out. If the steering is turned to the right, the tie rod may break the bushing by forcing it against the end of the rack. The result is excessive play in the right wheel and clunking noises on bumps or turns. Mr. Young notes that vehicles in this condition will not pass District of Columbia inspections.

Mr. Young says the problem may be corrected if the bushing is found to be intact and in good condition. The bushing may be reinstalled and a locating screw can be fitted by drilling a hole in the rack tube. A clamp is then installed over the screw to prevent it from backing out.

- Mr. Ned Furr of the Motor Car in Bethesda, Maryland, has reported an erratic braking condition on two Datsun Pickup trucks, which are 1974 and 1976 model year vehicles owned by the company.

Mr. Furr states that the brakes pull severely, although not necessarily to the same side each time. He goes on to say that the 1974 truck, which has 37,000 miles on it, has had the wheel cylinders, drums, master cylinder, and six sets of shoes replaced, and still continues to pull to one side or the other. Furthermore, the dealer has reportedly been unable to determine the cause of the problem.

- In their estimated potential for saving lives and avoiding injury at relatively low cost, two highway safety countermeasures — mandatory safety belt use and the national 55 mph speed limit — stand out above all others analyzed in the National Highway Safety Needs Report. The report is in response to a directive by the Congress to provide the basis for evaluating the continuing highway safety programs authorized under Title 23 of the United States Code.

Findings indicate that the top ranking countermeasure, mandatory safety belt usage, has the potential to save 89,000 lives over the next 10 years, at a cost of \$45 million. It thus requires the expenditure of \$506 for each fatality forestalled. Increased enforcement of the national 55 mph speed limit is also ranked high, with the potential to save almost 32,000 lives at a cost of \$676 million — an expenditure of slightly over \$22,000 per life saved. (This does not include the costs of increased time for trips which formerly were made at higher speeds.)

- Accident investigators for the U.S. Department of Transportation have compiled a scientific sketch of the person most likely to cause a fatal highway accident involving excessive drinking.

Usually a 25 to 35-year old male, this driver is a heavy or problem drinker who often prefers beer to other alcoholic beverages. He probably has a high school education and drives an older car. Single, separated, or divorced, he displays overly aggressive drinking habits and poses the greatest threats to highway safety during the early morning hours on weekends.

## OUTSTANDING SHOPS

Our outstanding shops are those shops that have sent into the PRP at least one part during the current month. A shop that sends in parts in consecutive months is identified by a number in parenthesis before the name. This number identifies the consecutive months the shop has sent in a part. New shops that have just become active in the PRP are identified with an asterisk before their name. During May 1976, eight shops became active participants in the PRP. Six shops have sent in failed parts in consecutive months.

### REGION 0

- \*CLARK'S SERVICE STATION  
Westhaven, Connecticut
- FLANDER'S BRAKE AND ALIGNMENT  
SERVICE, INC.  
Hartford, Connecticut
- HARRY'S AUTO SERVICE  
Great Barrington, Massachusetts

### REGION 1

- (2)ARTIE'S SERVICE CENTER I  
LoGrangeville, New York
- \*COTTMAN TRANSMISSION  
Bridgeport, Pennsylvania
- \*DEITZEL BROTHERS, INC. GARAGE  
Harrisburg, Pennsylvania
- WALT'S GARAGE  
Kenmore, New York

### REGION 2

- (4)BEREA AUTO SERVICE  
Greenville, South Carolina
- EUROPEAN MOTORS, LIMITED  
Washington, D.C.
- (2)YON BROTHERS GARAGE  
Charleston, South Carolina

### REGION 3

- IKE'S AUTOMOTIVE MAINTENANCE  
Montgomery, Alabama
- SUNRAY OIL AND GAS  
Tampa, Florida

### REGION 4

- EVAN'S BRAKE SERVICE  
Cleveland, Ohio
- \*KORZUN AND CORLETTE GARAGE  
Euclid, Ohio
- TAYLOR'S GARAGE AND SERVICE STATION  
Akron, Ohio

### REGION 5

- DAY-NITE AUTO STATION  
Koukouno, Wisconsin

### REGION 6

- (8)DICK JORDAN STANDARD SERVICE STATION  
Cloyton, Missouri
- \*K AND B BRAKE SERVICE  
Omaha, Nebraska
- \*TROOSTWOOD GARAGE  
Kansas City, Missouri

### REGION 7

- ANCELL TEXACO  
Abilene, Texas

### REGION 8

- \*CAPITAL ALIGNMENT  
Boise, Idaho

### REGION 9A


- CALIFORNIA STATE AUTOMOBILE ASSOCIATION  
San Francisco, California
- (8)ISE AUTOMOTIVE SERVICE  
Hollywood, California
- \*LEONARD'S SERVICE  
Los Angeles, California
- RICHARD'S AUTOMOTIVE SERVICE  
Los Angeles, California

NOTE: We need more participating shops. If you know of an independent automotive repair facility in your area who you think might want to help out in this Program, please send their name and address to us. Thanks.

## CURRENT PRP PARTICIPATION

The graph below identifies the number of active shops within each Region. One hundred thirty three shops have joined our active team and sent in a part. Keep up the good work. We still need many more shops on our active team and a lot more parts.

(As of 31 May 1976)



## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have any questions which need answers, or would like to pass on comments, please call us collect. Place your call to Bruce Beddow, Jonni Peizer, or Guy Whiddon at (703) 527-4500. We are Eastern Time and are normally available Monday through Friday from 8:30 a.m. to 5:30 p.m. Likewise, if you have a contribution or suggestion for the PRP News, please send it to Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention: Bruce E. Beddow.

## CONSUMER INFORMATION PUBLICATIONS

Several publications are available free of charge from the Government Printing Office which may interest our members. Titles include Clean Air and Your Car 023D; Guide to Octane Ratings 005D; The Hazards of "Mixing" Tire Types 006D; Studded Tires 008D; Miles Per Gallon Ratings for 1975 Cars and Light-Duty Trucks 014D; Miles Per Gallon Ratings for 1975 California-Certified Cars and Light-Duty Trucks 015D; and Tips for Motorists 016D, a guide for improved gas mileage. No more than two copies of any single publication may be ordered due to limited supplies. To request copies, write to: Consumer Information, Public Documents Distribution Center, Pueblo, Colorado 81009. Include the title and document number of each item requested as well as the number of copies desired (one or two).

You may also request the Consumer Information Index which lists these and other publications, and includes an ordering blank for convenience.

PARTS RETURN PROGRAM  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209



# NEWS PARTS RETURN PROGRAM NEWS

CONTRACT NO. DOT-HS-5-01166

U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Vol. 1, No. 10

April 1976

## FAILED BRAKE HOSES

In the last six months, we have received many nonmetal brake hoses from AMC, Chrysler/Plymouth, Ford, and GMC vehicles, where the flexible hose has split, usually near one end, causing loss of brake fluid. The brake hose pictured below is representative of the types of parts we have received. The split occurred at the frame connection, but there is evidence of deterioration of the hose outer covering at the other end. Small cracks have developed across the surface at the curve near the connector, and cover approximately 1-1/4" of the hose.

Some of the contributing shops have reported that the failures occur because hoses are too short. We would like to hear from our members who have encountered this type of failure. If the part is not available for return, drop a note to us in your next bag of parts.

Special thanks to BERT'S ARCO STATION, Wilmington, DE; FOSTER'S SERVICE CORP., Seattle, WA; GORDIE'S AUTO SERVICE, West Chester, PA; HAGAN SERVICE CENTER, Gainesville, GA; ISE AUTOMOTIVE SERVICE, Hollywood, CA; KAHLER'S GARAGE, Williamsport, PA; KELLEY STREET GARAGE, Manchester, NH; KING CO. BRAKE SERVICE, Seattle, WA; KOLESNIK'S SERVICE STATION, Rochester, NY; MERRILL'S AUTOMOTIVE SERVICE, Salt Lake City, UT; MR. BRAKE, Salt Lake City, UT; PARK AUTO REPAIR, Chicago, IL; RICHFIELD WHEEL ALIGNMENT, Minneapolis, MN; SPORTS CAR SERVICE, Seattle, WA; and SUPERIOR WHEEL ALIGNMENT AND BRAKE SERVICE, Charlotte, NC.



## TIRE CONSTRUCTION

Since more and more tires have been introduced on the market, some confusion has arisen on the part of auto owners as to what type would best fulfill their needs. We hope that the following information will be useful in this respect.

There are three basic kinds of tire construction, or types, available to a U.S. vehicle owner. They are bias construction, bias-belted construction, and radial (or radial ply) construction. NHTSA does not endorse any one type as superior to the others. Each is considered by experts to have special advantages.

In a bias ply tire, the body plies or cord strips are arranged diagonally to the center line of the tread, from bead to bead. Alternate plies are reversed to cross at a 30 or 40 degree angle. The result is a uniformly firm body, satisfactory at moderate speeds, with sidewalls that can withstand curb bruises. In fast driving or hard turning, however, the tread elements squirm together then spring apart, producing heat that weakens the tire. The bias ply tire is the most inexpensive tire type to purchase. However, if highway driving or performance in curves will be required, another kind of tire may be more economical in the long run since the life-time in mileage with this type of construction will be decreased in these driving situations.

Belted bias tires have body plies which crisscross diagonally, like those of a bias tire, to ensure strong sidewalls. Between the body plies and tread, there are two or more cord strips that are cut on the bias, and alternated, herringbone fashion around the circumference of the tire. These belts strengthen the tire against impact and puncture damage, and help reduce squirm by stiffening the tread, thus reducing heat build-up.

Radial tires have body cords arranged perpendicularly to the center line of the tread (at right angles to the direction the tire rolls). The belt cords, which support the tread are arranged diagonally (on the bias) like a bias-belted tire. The radial body cords allow the sidewalls to flex so that the tread maintains maximum surface contact

with the road during turns, whereas the stiff sidewalls of a bias belted or bias tire would lift the tread. Radials perform well in high speed driving conditions but may produce roughness at low speeds as well as giving a stiffer ride. Radial tires roll more easily, so better fuel economy may be achieved under highway driving conditions. However, because of this same design feature, some sidewall strength is sacrificed, making this type of tire more susceptible to sidewall damage, particularly bruising.

Mixing types of tires on the same axle can be hazardous. Since the performance characteristics vary greatly between types of tires, especially radial ply tires, a vehicle with mixed tires on the same axle may handle erratically, possibly causing the driver to lose control.

The radial tire tends to keep its entire tread width on the road surface, even under cornering conditions where other types of tires might lift or slide laterally. Because of this, mixing radials on the front wheels and another type of tire on the rear wheels could produce a skid affecting vehicle control. Placing the two radials on the rear, while preferable to the front, is not the best solution either. Where wet or icy road conditions prevail, the front tires may skid causing the vehicle to pivot on the rear wheels and result in loss of steering control.



In the past, there has been a tendency to assume that high cost or high quality tires assured high speed capability. This is not necessarily so. For high speed operation, such as would be associated with police pursuit for example, tires designed for sustained high speed operation must be used.

The importance of making the proper tire selection becomes even more obvious when you consider that four sections of tread, each smaller than this page, are the only contact between the automobile and the road surface at any given instant.

Again, we hope that this information will be useful to you, and we plan to provide more information on tires in future articles.

# WANTED

## FAILED PARTS OR INFORMATION SUPPORTING CASE NO. C3-34



### ALLEGED REAR AXLE CONTROL ARM FAILURES ON 1966-1971 LIGHT DUTY TRUCKS MANUFACTURED BY THE GENERAL MOTORS CORPORATION

#### BASIS FOR INVESTIGATION:

This case was opened May 9, 1973, following receipt of correspondence from U.S. Department of Agriculture (USDA), Forest Service, of Albuquerque, New Mexico, dated January 26, 1973. The Forest Service reported the occurrence of cracks in the rear axle control arms in 15 Chevrolet  $\frac{1}{2}$  ton pickup trucks. An investigation was initiated to determine whether the alleged rear axle control arm failure is potentially a safety-related defect within the meaning of the National Traffic and Motor Vehicle Safety Act of 1966.

#### DESCRIPTION AND FUNCTION:

The rear axle control arm assembly as shown in Figures 1 and 2 is attached to the rear axle housing. The arm pivot points are rubber bushed. One end of the arm is connected to the housing, the other to the vehicle frame. The arm arrangement allows the rear axle housing to move up and down but limits fore-and-aft and side-to-side movements.

#### ANALYSIS OF THE ALLEGED PROBLEM:

Failure Mode: Cracking and eventual separation of the control arm reportedly occur as a result of metal fatigue.

Failure Symptoms: The vehicle operator may notice loud, unusual noises in the rear of the vehicle together with irregular handling characteristics. Cracks may be detected by visual examination. Initiation of the cracks occur in the vicinity of the "U" bolt attachment of the control arm assembly. Additionally, the two halves of the control arm may split where welded, permitting the "U" bolt to become disengaged.

Potential Safety-Related Concerns: Whether separation of the rear axle control arm occurs and, if so, whether it results in injury or property damage accident or other safety-related problems.

## ITEMS OF INTEREST

- MILLER'S AUTOMOTIVE in Fullerton, California, reports finding a very high rate of failure among some GM vehicles with alternators that are equipped with integral regulators. They also report having little success with replacement units, either new or rebuilt. They find that the most frequent problems are shorting, and not charging at the required rate.
- Mr. Carl Riegal of RIEGAL'S SERVICE, INC., Livonia, Michigan, has reported servicing two cases of cracked power steering gear housings. One case involved a 1972 Pontiac Catalina, mileage unknown, and the other a 1972 Cadillac De Ville with mileage of approximately 62,000. We have received some very good examples of this type of failure as a result of our January 1976 article, and would like to thank those shops again that have been looking out for these items. Your efforts are appreciated.
- Mr. Marvin Frerick of FRERICK'S GARAGE in Sioux City, Iowa, has written in response to Mr. Bill Chisholm's comments on after-market parts. Mr. Frerick states that in his opinion, rebuilt items such as carburetors, starters, and alternators have very poor quality control and are "outrageously" priced.
- We received a suggestion from a new enrollee, Mr. Emmy Sacco of BRIDGEPORT GARAGE in Bridgeport, Pennsylvania, to contact the Automotive Service Council of Pennsylvania, Post Office Box 3435, Harrisburg, Pennsylvania, for more information on new enrollees. We have contacted Mr. Robert Schmidt of that organization and would like to extend our thanks to Mr. Sacco for the tip.
- Mr. Bill Schmidt of BILL SCHMIDT'S GARAGE in Pittsburgh, Pennsylvania, reports removing a power steering gear box from a 1974 full size Chevrolet where the lower bearing and cup broke. He states that there was no loss of fluid, but a severe binding condition developed as a result. The part was not available since the dealer, which refunded the cost of repairs to the customer, retained it. This type of information can be very helpful in identifying the existence of safety-related defects.
- We have received an engine mount from a 1972 Dodge, presumably from the Winston-Salem, North Carolina, area. We have not been able to identify the shop. If you returned this part, please let us know. We have also received a bag from BRAKE-O-RAMA in New York. We have not been able to identify this number and we did not receive your address. Please call us so we can forward your certificate.

## OUTSTANDING SHOPS

Our outstanding shops are those shops which have sent into the PRP at least one part during the current month. A shop that sends in parts in consecutive months is identified by a number in parenthesis before the name. This number identifies the consecutive months the shop has sent in a part. New shops which have just become active in the PRP are identified with an asterisk before their name. During April 1976, 18 shops became active participants in the PRP. Eight shops have sent in failed parts in consecutive months.

### REGION 0

GLIDDEN AUTO SERVICE  
Nashua, New Hampshire

### REGION 1

- \* ARTIE'S SERVICE CENTER  
Lagrangeville, New York
- \* BOB SCHMIDT'S GARAGE  
Pittsburgh, Pennsylvania
- (4) KOLESNIK'S SERVICE STATION  
Rochester, New York

- (2) LONGBARD'S EXXON STATION  
Poughkeepsie, New York

- \* SASSAMAN & BURDEN  
Temple, Pennsylvania

### REGION 2

- (4) AUTO BRAKE CORPORATION  
Norfolk, Virginia

- (3) BERE A AUTO SERVICE  
Greenville, South Carolina

DODD'S AUTO SERVICE  
Portsmouth, Virginia

- \* THE MOTOR CAR  
Bethesda, Maryland

MYER'S GARAGE  
Winston Salem, North Carolina

PIONEER MOBILE STATION  
Springfield, Virginia

- \* YON BROTHERS GARAGE  
Charleston, South Carolina

### REGION 3

IKE'S AUTOMOTIVE MAINTENANCE  
Montgomery, Alabama

- (2) HAGAN SERVICE CENTER  
Gainesville, Georgia

RALPH CANNON AUTO SERVICE, INC.  
Atlanta, Georgia

- \* WAYNE TERRELL'S GARAGE  
Macon, Georgia

### REGION 4

- \* CHESTER BODY & REPAIR COMPANY  
Cleveland, Ohio

K & H TOTAL SERVICE  
Ypsilanti, Michigan

LEXINGTON BRAKE  
Lexington, Kentucky

RIEGAL'S SERVICE, INC.  
Livonia, Michigan

### REGION 5

DAVE McMILLEN'S AUTO REPAIR SERVICE  
Duluth, Minnesota

- \* DOC'S AUTO CLINIC  
Grand Forks, North Dakota

- \* ED & WALLY'S, INC.  
Kenosha, Wisconsin

- \* FRERICK'S GARAGE  
Sioux City, Iowa

K-S WHEEL ALIGNMENT SERVICE  
Waterloo, Iowa

- \* LARRY GAIDA'S SERVICE STATION  
Duluth, Minnesota

TOMMY'S AUTO REPAIR  
Sioux City, Iowa

### REGION 6

ATWELL AUTO REPAIR  
St. Louis, Missouri

AUTO HOSPITAL  
Lincoln, Nebraska

BILL NOBLE'S BRAKE SERVICE  
Pinelawn, Missouri

- (7) DICK JORDAN STANDARD SERVICE STATION  
Cloyton, Missouri

HUTT & STILES  
Skokie, Illinois

- \* MERWIN AUTOMOTIVE SERVICE  
Emporia, Kansas

- \* MIDAS MUFFLER  
Kansas City, Missouri

- \* RAY'S MOTOR SERVICE  
Topeka, Kansas

- \* SPRINGFIELD BRAKE COMPANY  
Springfield, Missouri

### REGION 7

- (2) HILL'S AUTOMOTIVE CLINIC  
Abilene, Texas

- \* LETOURNEAUX COLLEGE  
Longview, Texas

RED'S AUTOMOTIVE  
Abilene, Texas

TOMMY'S AUTOMOTIVE  
San Angelo, Texas

### REGION 8

DAVE KYLE'S GARAGE  
Phoenix, Arizona

### REGION 9

DOYLE AUTOMOTIVE SERVICE  
Seattle, Washington

FOSTER'S SERVICE CORPORATION  
Seattle, Washington

### REGION 9A

- \* BUD'S BRAKE & WHEEL SERVICE  
Bakersfield, California

- (7) ISE AUTOMOTIVE SERVICE  
Hollywood, California

- \* LEE'S AUTO SAFETY CENTER  
Santa Ana, California


VANOWEN BRAKE & WHEEL  
North Hollywood, California

WONG'S AUTOMOTIVE SERVICE, INC.  
Fresno, California

NOTE: We need more participating shops. If you know of an independent automotive repair facility in your area who you think might want to help out in this Program, please send their name and address to us. Thanks.

## CURRENT PRP PARTICIPATION

The graph below identifies the number of active shops within each Region. One hundred twenty nine shops have joined our active team and sent in a part. Keep up the good work. We still need many more shops on our active team and a lot more parts.



|          |    |    |    |    |    |    |    |    |    |    |
|----------|----|----|----|----|----|----|----|----|----|----|
| STATES { | CT | DE | DC | AL | IN | IA | IL | AR | AZ | AK |
|          | ME | NJ | MD | FL | KY | MN | KS | LA | CO | CA |
|          | MA | NY | NC | GA | MI | MT | MO | OK | ID | HI |
|          | NH | PA | SC | MS | OH | ND | NE | TX | NV | OR |
|          | RI |    | VA | TN |    | SD |    |    | NM | WA |
|          | VT |    | WV |    |    | WI |    |    | UT |    |
|          | PR |    |    |    |    |    |    |    | WY |    |
|          | VI |    |    |    |    |    |    |    |    |    |
|          |    |    |    |    |    |    |    |    |    |    |
|          |    |    |    |    |    |    |    |    |    |    |

## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have any questions which need answers, or would like to pass on comments, please call us collect. Place your call to Bruce Beddow, Jonni Peizer, or Guy Whiddon at (703) 527-4500. We are Eastern Time and are normally available Monday through Friday from 8:30 a.m. to 5:30 p.m. Likewise, if you have a contribution or suggestion for the PRP News, please send it to Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention: Bruce E. Beddow.

## RENAULT MODEL 17

Special public attention is directed to the Suspended Investigatory Case #C4-60, so that persons with experience or information they consider vital to this investigation may report the matter in detail to the National Highway Traffic Safety Administration.

|                           |                                                                                                                                                                                        |
|---------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <u>Manufacturer:</u>      | Renault                                                                                                                                                                                |
| <u>Model:</u>             | 17 Sports Coupe                                                                                                                                                                        |
| <u>Years:</u>             | 1971-1973                                                                                                                                                                              |
| <u>Component:</u>         | Bosch Fuel Injector                                                                                                                                                                    |
| <u>Possible Problems:</u> | Alleged fuel leakage from pressurized system onto engine exterior.                                                                                                                     |
| <u>Status:</u>            | Suspended June 24, 1975. No further investigatory effort will be expended on this case and it will be closed in the near future unless significant additional information is received. |

Investigations are currently being conducted to determine whether this condition represents a safety-related defect among certain 1970-1973 Volvo vehicles (Case #C4-58) and 1970-1972 Volkswagen vehicles, including Porsche (Case #C4-59). If you know of fuel leaks in any of the above vehicles we would like to know about them along with the results of the leaks.

PARTS RETURN PROGRAM  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209



# NEWS PARTS RETURN PROGRAM NEWS

CONTRACT NO. DOT-HS-5-01166

U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION


Vol. 1, No. 9

## BROKEN WIRE WHEEL

March 1976

Mr. Virgil Jones of DICK JORDAN'S STANDARD SERVICE STATION in Clayton, Missouri, has returned a wire wheel, removed from the right front of a 1975 Cadillac Coupe DeVille with a vehicle mileage of approximately 5,000. As indicated in the photograph at the right, the inner disc which attaches to the hub is cracked around 2/3 of its circumference. According to other information received by the Office of Defects Investigation, National Highway Traffic Safety Administration (NHTSA), the wheel is known as a Tru-Spoke and was manufactured by Wheel Specialties Co. of Anaheim, California. Failure reportedly occurred at a speed of approximately 20 mph and after the vehicle operator detected some front end vibration.

We would like our PRP members to be on the look out for failed wheels, whether original equipment or after market items. We would also like to hear from any shop which finds failed wheel adapters.



## AUTO SAFETY HOTLINE

The NHTSA's Office of Public Affairs and Consumer Services is now operating a new facility to aid motor vehicle owners who need help in solving safety-related vehicle problems or who have defect-related information to report.


The Hotline, instituted on October 15, 1975, is available toll-free to 10 states and the District of Columbia and has received approximately 5,000 calls since its creation.

Hotline staff are careful to avoid any judgment of consumer complaints as "defects" or dealer error, but instead refer all safety-related reports to the Office of Defects Investigation, NHTSA; at the same time sharing the reports with the involved vehicle manufacturer.

The 10-state area covered by the Hotline (800-424-0123) includes Maryland, Delaware, Virginia, West Virginia, Pennsylvania, North Carolina, New Jersey, Connecticut, the cities of New York, Long Island, Buffalo, and Rochester, and the 513 and 614 area codes of Ohio. The District of Columbia and surrounding metropolitan areas are covered by 426-0123. Those wishing to contact the Hotline from outside these areas may call 212-426-0123, if they want to pay for the call.

## BASIC TRAFFIC SAFETY LAWS ENACTED - 1966

The following is an excerpt from "Traffic Safety '74, A Digest of Activities of the National Highway Traffic Safety Administration."



Automotive transportation has been marked by accidents, injuries, and fatalities from its inception. In 1895, when there were only four gasoline-powered vehicles in the United States, two of them collided in St. Louis—seriously injuring both drivers. Nine years later, traffic had picked up and a 10-year-old girl was struck by a bakery truck, to become the first motor vehicle traffic death in the Nation's capital.

During the ensuing years, the number of motor vehicles proliferated, as did the roads on which they were driven, the drivers who operated them, and the miles they traveled. So also did traffic accidents, injuries, and deaths—until 1966, when Congress determined that a national traffic safety

effort, aimed at reducing the number of highway crashes and the resultant injuries and deaths, should be established. That year highway deaths exceeded 50,000, registered vehicles and licensed drivers hovered around 100 million, and mileage approached the trillion-mile-per-year level. The fatality rate per 100 million miles driven stood at 5.6. That was a high price for society to pay—even for a flexible, convenient form of transportation.

A program was launched to carry out the Congressional mandate through uniform standards governing highway use, design, and maintenance, safer cars, and better trained, more prudent drivers. Federal Motor Vehicle Safety Standards (FMVSS) were drawn up and published, to be adhered to by the automobile manufacturers. Similarly, national highway safety standards were issued, to be complied with by the States in planning and executing their highway safety programs. In 1968, a goal was established to reduce the fatality rate one-third by 1980 (from 5.3 in 1968 to 3.5).

The fatality rate has declined steadily since that time, as seen below:

**Table 1**  
**Mileage Death Rate**

| (Deaths per 100 million vehicle miles) |      |
|----------------------------------------|------|
| 1966                                   | 5.58 |
| 1967                                   | 5.36 |
| 1968                                   | 5.27 |
| 1969                                   | 5.11 |
| 1970                                   | 4.78 |
| 1971                                   | 4.50 |
| 1972                                   | 4.35 |
| 1973                                   | 4.20 |
| 1974                                   | 3.56 |


The basic laws enacted by the Congress in 1966 are the National Traffic and Motor Vehicle Safety Act and the Highway Safety Act. The motor vehicle safety law is administered by the National Highway Traffic Safety Administration (NHTSA). The Federal standards issued under the highway safety statute are administered largely by NHTSA, in part by the Federal Highway Administration (FHWA), and in part jointly by these two Department of Transportation agencies.

This illustrated, 38-page document is available free of charge to our PRP members, and we think you will find it well worth the time it takes to read. Subjects covered by the report include Safer Motor- ing, Crash Survivability, Crash Avoidance, a summary of the Federal Motor Vehicle Safety Stan- ards, and others.

This publication can be requested from the National Highway Traffic Safety Administration, General Services Division, Room 5202, Washington, D.C. 20590.

# WANTED

## FAILED PARTS OR INFORMATION SUPPORTING CASE NO. C4-34



### FUEL FILLER HOSES AND THREE-WAY CONNECTORS

Possible fuel leaks in the vicinity of the three-way connector and the filler hose of the 1969-1971 Datsun Models 510 and 1200.

### DESCRIPTION

Fuel filler hose and the three-way connector both are alleged to contain holes or cracks.

### FAILURE SYMPTOMS

Allegedly, the filler hose was improperly manufactured and contained holes. Improper installation in some cases is also alleged. The three-way connector is alleged to have cracks.

### POTENTIAL SAFETY RELATED CONSEQUENCES

Failure of these parts would permit the release of the fuel and fuel vapor which may penetrate into the passenger compartment. Such fumes may present an explosion hazard.

### PROBLEM SYMPTOM

The alleged failure could be detected by fuel vapor and leaking fuel. Visual inspection of the system might reveal wet fuel or fuel stains. It should be noted that a one-time occurrence of the smell of gasoline does not specifically indicate a fuel system malfunction. But a continued smell of fuel might indicate the need for a close visual inspection.

## CASE NO. C4-34

**SUBJECT:** Possible Fuel Leaks in the Vicinity of the Three-Way Connector and the Filler Hose on the 1969-1971 Datsun Models 510 and 1200

The case was opened on the basis of information obtained from the Outraged Consumer Action Committee (OCAC), Inc., of Whittier, California. Allegedly, fuel leaks from the plastic three-way connector in the fuel vent system and from the fuel filler hose. The purpose of the investigation is to determine if the alleged problems represent a potential safety related defect within the meaning of the National Traffic and Motor Vehicle Safety Act of 1966.

The fuel filler hose is a large diameter rubber hose used to connect the fuel filler cap assembly to the fuel tank neck. The plastic three-way connector is used to intersect the ventilation line of the fuel tank and the line that vents directly into the atmosphere. Please see diagram on reverse side.

Allegedly, the filler hoses were improperly manufactured and contain holes. Improper installation in some cases is also alleged. The three-way connector is alleged to have cracks.

Failure of these parts would permit the release of the fuel and fuel vapor which may penetrate into the passenger compartment. Such fumes may present an explosion hazard.

The alleged failure could be detected by fuel vapor and leaking fuel. Visual inspection of the system might reveal wet fuel or fuel stains. It should be noted that a one-time occurrence of the smell of gasoline does not specifically indicate a fuel system malfunction. But a continued smell of fuel might indicate the need for a close visual inspection.

## ITEMS OF INTEREST

- In meeting our objective of "spreading the word" about the PRP we are continuing to contact many automotive service industry associations. We are pleased to announce that the Automotive Services Council (ASC), Inc., has released an article, "Your Support is Needed" in their "Shop Notes," February 1976, page 8. This article describes the PRP and asks for more volunteers. We know that many of our PRP participants are ASC members and we thank the ASC for their support. We have received several requests to participate in the PRP as a result of this support.
- In addition, we have discussed with officials of the National School Transportation Association, ways in which their members — principally contract school bus fleet operators — might support the PRP. These discussions are continuing.
- If any of our existing members know of an independent automotive repair facility or automotive association that might be interested in learning more about the Program, send us their name and address.
- HARPER'S GARAGE in Midland, Texas, reports turn signal switches often warp due to heat build-up in vehicles. This reportedly results in rear brake light and turn signal failure. In addition, they report that the turn signal flasher control in some cases is located such that the driver may contact it accidentally, causing turn signal failure. Finally, they report finding many headlights out of adjustment which they attribute to poorly designed headlight adjuster nuts. The headlights reportedly become misaligned when contacted by small stones, etc.
- We would like to hear from any shops that are having difficulty getting answers to technical questions or solving service problems. We may be able to help. Please drop us a line explaining the problem and give the make, model, and year in question as well as any information you feel is pertinent.
- Mr. Charles S. Nickerson of CAMBRIDGE BRAKE SERVICE, INC., in Cambridge, Massachusetts, reported having difficulty with the local Post Office accepting our PRP mail bags. We would like to remind our members to make sure the failed part fits in the bag as your Post Office may refuse the bag otherwise. If you run into difficulties with the mail service, please contact us.
- Since the inception of the National Traffic and Motor Vehicle Safety Act of 1966 through December 1975, some 48.9 million vehicles have been recalled in 1,941 campaigns; 7.7 million (16% of the total) vehicles and 359 campaigns involved foreign vehicles.

## OUTSTANDING SHOPS

Our outstanding shops are those shops which have sent into the PRP at least one part during the current month. A shop that sends in parts in consecutive months is identified by a number in parenthesis before the name. This number identifies the consecutive months the shop has sent in a part. New shops which have just become active in the PRP are identified with an asterisk before their name. During March 1976, 16 shops became active participants in the PRP (our second highest month for shop participation). Ten shops have sent in failed parts in consecutive months.

### REGION 0

- BEN-SAL AUTO SERVICE CENTER, INC.  
Hartford, Connecticut
- (2) CAMBRIDGE BRAKE SERVICE  
Cambridge, Massachusetts
- \* FLANDER'S BRAKE & ALIGNMENT SERVICE  
Hartford, Connecticut
- \* GENE CASEY ARCO STATION  
Lynn, Massachusetts
- \* GEOFFREY SERVICE STATION  
Lowell, Massachusetts
- \* KELLEY STREET GARAGE  
Manchester, New Hampshire
- (2) WORCHESTER BOYS TRADE HIGH SCHOOL  
Worcester, Massachusetts

### REGION 1

- (2) BERT'S ARCO STATION  
Wilmington, Delaware
- \* BUSS KAHLER'S GARAGE  
Williamsport, Pennsylvania
- JOHN'S BODY SHOP  
Binghamton, New York
- (3) KOLESNIK'S SERVICE STATION  
Rochester, New York
- \* LONGBARD'S EXXON STATION  
Poughkeepsie, New York
- \* NEW YORK AUTO REPAIR & ALIGNMENT, INC.  
Poughkeepsie, New York

### REGION 2

- (3) AUTO BRAKE CORPORATION  
Norfolk, Virginia
- (2) BEREIA AUTO SERVICE  
Greenville, South Carolina
- EUROPEAN MOTORS LTD  
Washington, D.C.

### REGION 3

- AUTO SPRING & BRAKE SERVICE, INC.  
Montgomery, Alabama
- HAGAN SERVICE CENTER  
Gainesville, Georgia
- \* SALTER'S GARAGE  
Decatur, Georgia

### REGION 4

- \* EVAN'S BRAKE & TIRE SERVICE  
Cleveland, Ohio
- (2) HEATHERDOWN'S AUTOMOTIVE SERVICE  
Toledo, Ohio
- PAUL'S GARAGE  
Dayton, Ohio
- \* PEDLEY'S GARAGE  
Owensboro, Kentucky
- TAYLOR'S GARAGE & SERVICE STATION  
Akron, Ohio

### REGION 5

- BELOIT FRAME & AXLE CO.  
Beloit, Wisconsin
- \* CEDAR RAPIDS AUTO SERVICE  
Cedar Rapids, Iowa
- \* CENTRAL PARK SERVICE STATION  
Kenosha, Wisconsin
- \* EISENMAN & GALE  
Green Bay, Wisconsin
- \* HESSEFORT SERVICE  
Kenosha, Wisconsin
- \* NELSON'S AUTOMOTIVE  
Milwaukee, Wisconsin

### REGION 6

- ADAM'S MOTOR SERVICE  
St. Charles, Missouri
- (6) DICK JORDAN'S STANDARD SERVICE STATION  
Clayton, Missouri
- GENE'S AUTOMOTIVE SERVICE  
Garnett, Kansas
- JERRY MCCLAIN'S AUTO REPAIR  
St. Louis, Missouri
- PARK AUTO REPAIR  
Chicago, Illinois
- \* STONER'S TRIANGLE AUTO SERVICE  
Rockford, Illinois

### REGION 7

- \* HILL'S AUTOMOTIVE CLINIC  
Abilene, Texas

### REGION 9

- SHARPS AUTOMOTIVE  
Seattle, Washington


### REGION 9A

- CALIFORNIA STATE AUTO ASSOCIATION  
San Francisco, California
- (6) ISE AUTOMOTIVE SERVICE  
Hollywood, California
- MAURICE'S AUTOMOTIVE  
Hollywood, California
- MILLER'S AUTOMOTIVE  
Fullerton, California
- PRECISION AUTO REPAIR  
San Francisco, California
- (2) RANCHO CORDOVA GARAGE  
Rancho Cordova, California

NOTE: We need more participating shops. If you know of an independent automotive repair facility in your area who you think might want to help out in this Program, please send their name and address to us. Thanks.

## CURRENT PRP PARTICIPATION

The graph below identifies the number of active shops within each Region. One hundred and eleven shops have joined our active team and sent in a part. Keep up the good work. We still need many more shops on our active team and a lot more parts.



## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have any questions which need answers, or would like to pass on comments, please call us collect. Place your call to Bruce Beddow, Jonni Peizer, or Guy Whiddon at (703) 527-4500. We are Eastern Time and are normally available Monday through Friday from 8:30 a.m. to 5:30 p.m. Likewise, if you have a contribution or suggestion for the PRP News, please send it to Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention: Bruce E. Beddow.

## NATIONAL PARTS RETURN PROGRAM DESCRIPTION AND FUNCTION

- The PRP involves the voluntary submittal by independent repair shops of failed automotive components. Components are submitted to a representative (Kappa Systems, Inc.) of the National Highway Traffic Safety Administration (NHTSA).
- The purpose of the PRP is to gather information on these components to help the NHTSA identify the existence of safety-related, manufacturing defects in design, materials, construction or performance of motor vehicles and motor vehicle equipment. Under the authority of the National Traffic and Motor Vehicle Safety Act of 1966, and Amendments to the Act in 1974, the NHTSA can require manufacturers to conduct safety defect notification campaigns when it has been determined that a defect relating to motor vehicle safety exists.
- The information obtained from these parts is also valuable in preparing Federal motor vehicle safety standards.

Your shop can help. The parts that you send in will give us vital information that cannot be obtained in any other way.

PARTS RETURN PROGRAM  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209



# NEWS PARTS RETURN PROGRAM NEWS

CONTRACT NO. DOT-HS-5-01166

U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION


Vol. 1, No. 8

February 1976

## BROKEN FAN BLADES

Recently, we received from Mr. Jim Durbin of KINGS PARK EXXON in Springfield, Virginia, a broken cooling fan removed from a 1971 Vega with 44,071 miles. According to Mr. Durbin, the vehicle's engine was vibrating badly and the radiator had been damaged by one of the separated blades. The picture at right shows the cracks in the remaining blades. This type of failure may be extremely hazardous to an individual who is initially inspecting a vehicle while the engine is running.

In reviewing our records of the past 6 to 7 months we find we have received several broken fans, removed from AMC, Ford, and GM products, where one or more of the blades have separated from the fan hub. The shops who sent in these parts were ISE AUTOMOTIVE SERVICE, Hollywood, California; KALLEN'S GARAGE, Van Nuys, California; DOYLE'S SERVICE, Massillon, Ohio; B & E AUTOMOTIVE, Tacoma, Washington; and MCLAIN'S AUTO REPAIR, St. Louis, Missouri.



Although many fans may be too large for the mail bags, we would like to hear from our members who have encountered this type of failure. The information you can give us may be as valuable as the part.

## AMC RECALL NHTSA CAMPAIGN NO. 76-0021

American Motors Corporation is conducting a recall campaign on 1974-75 model year Matadors. There are 3,134 vehicles involved. Among these suspect vehicles, there are approximately 700 power brake boosters that may contain a defect which can cause separation of the power brake booster, section shells. This potential for separation results from a lack of full crimp overlap. Separation may occur during application of high pedal force, such as a panic stop.

Field corrective action will consist of inspection of each vehicle, and replacement of all power brake booster units with the relevant date code. Inspections and any replacements will be made without charge to the vehicle owners.

## WALL POSTERS AND CHARTS MULTIPIECE WHEELS

In the near future each shop enrolled in the National Parts Return Program will be receiving two posters and two charts concerning multipiece wheels. The posters and charts have been prepared and issued by the National Highway Traffic Safety Administration (NHTSA), and are part of a continuing campaign to alert truck and bus service personnel to the hazards involved in working with such wheels. These wheels consist of two pieces (a rim base and a side ring), or three pieces (rim base, side ring or flange, and lock ring).

NHTSA officials have pointed out that, of a total of 129 reported accidents involving the handling of all types of multipiece wheels, 104 resulted in crippling or fatal injuries. Investigation of these accidents indicates that they occurred in most cases because tires were inflated before side rings, or lock rings, were fully seated. As a result the wheel parts were blown apart with explosive force, inflicting serious injury to nearby service employees or bystanders.

The two posters dramatize the safety precautions for service personnel working with multipiece wheels, while one of the two charts details the correct mounting/demounting procedures and safety precautions for servicing tube type truck and bus tires. The second chart lists the accepted interchangeability known to exist between the various wheel makes and parts. The NHTSA noted in an earlier investigation a significant number of mismatched parts, probably the result of lack of knowledge in this area.

We would like to receive more input on this problem from our PRP members.

## SIGNIFICANT CASES INVESTIGATED DURING 1974

A recent report to the Congress of the United States in September 1975 by President Ford contained briefs of cases investigated by the Office of Defects Investigation, NHTSA, during the calendar year 1974. One such brief is presented below for your review. This text was taken in total from "A Report on Activities Under the National Traffic and Motor Vehicle Safety Act of 1966 and the Motor Information and Cost Saving Act of 1972," U.S. Department of Transportation Document No. DOT-HS-801-700, page 37.

### Automotive Jack Stand Inadequacy

This investigation resulted from an NHTSA survey of jack stands commonly available in the marketplace. Tests indicated that a number of models would not bear their rated load. Recalls, based on apparent capacity overrating, were initiated for 400,760 Pathfinder Auto Lamp Company auto jack stands and 17,860 Auto Specialties Manufacturing Company stands. The Pathfinder Model 7224, rated at 4,000 pounds, and Model 8336, rated at 5,000 pounds, manufactured during the first 6 months of 1974, were downgraded to 3,000 and 4,000 pounds respectively. The Auto Specialties models 41601 and 41603, rated at 5,000 pounds, were downgraded to 3,000.

## ITEMS OF INTEREST

- We are pleased to report that the PRP News receives wide distribution. In our November issue we conveyed the comments of Mr. D. Foran of TIM'S IMPORT SALES & SERVICE, Hutchinson, Kansas, concerning brake proportioning valves on import vehicles.

Subsequently, we were reminded by the people of Renault in France, through their U.S. representative, that the Renault R-10 is equipped with four wheel disc brakes, rather than disc/drum as our newsletter implied. Thanks for bringing this to our attention.

- The National Highway Traffic Safety Administration has received a variety of vehicle owner reports concerning catalytic converters. If your shop encounters any problems on vehicles equipped with catalytic converters, such as excessive heat build up, please let us know.
- Mr. K. Katon of KATON'S GARAGE, Lead, South Dakota, points out that sending in parts is not always the answer. Mr. Katon states that he has encountered Jeep Wagoneer brake failures at 30,000 miles resulting in damage to the brake drums, as well as heater core leaks which can cause the windshield to be obstructed. Mr. Katon goes on to say that these parts are usually repaired. Mr. Katon also mentions finding Wagoneers frequently having cracked fuel tanks.
- Mr. T. C. Duff of BELOIT FRAME AND AXLE CO., Beloit, Wisconsin, has asked whether a shop identification card would be helpful to the PRP in getting participation from other service establishments. We will look into this, and we welcome any comments our members have.
- Mr. Bill Chisholm of VANOWEN BRAKE AND WHEEL, North Hollywood, California, has reported experiencing frequent failures with after-market parts. He mentions difficulty with water pumps, and states that often the failures occur after a few thousand miles.

We are still studying the best approach to initiate a quarterly reporting form suggested by Mr. Paul Lovely of PAUL'S GARAGE in Dayton, Ohio, to record problems with defective replacement parts. If any of you have suggestions on this subject send them in with your next part.

- This month one of our PRP members sent us two engine mounts from a 1969 Ford Fairlane station wagon in support of NHTSA Case C4-18. We have been unable to identify that shop. If you sent us these parts, please let us know. We have also received a brake master cylinder from a 1970 Ford Maverick. We have been unable to identify the contributing shop. If you sent us this part, please notify us.
- Ms. Jonni B. Peizer will be the new Region 2 and Region 4 representative. Ms. Peizer is located in our Arlington, Virginia, office and may be contacted weekdays at (703) 527-4500 between 8:00 a.m. and 5:00 p.m., Eastern Time.

## OUTSTANDING SHOPS

Our outstanding shops are those shops which have sent into the PRP at least one part during the current month. A shop that sends in parts in consecutive months is identified by a number in parenthesis before the name. This number identifies the consecutive months the shop has sent in a part. New shops which have just become active in the PRP are identified with an asterisk before their name. During February 1976, six shops became active participants in the PRP, and at this time 10 shops have sent in failed parts in consecutive months.

### REGION 0

CAMBRIDGE BRAKE SERVICE  
Cambridge, Massachusetts

(2) HARRY'S AUTO SERVICE  
Great Barrington, Massachusetts

HENNIKER AUTOMOTIVE  
Henniker, New Hampshire

WORCHESTER BOYS TRADE H.S.  
Worcester, Massachusetts

### REGION 1

BERT'S ARCO STATION  
Wilmington, Delaware

CRANE AUTO REPAIR  
Bricktown, New Jersey

FRANK'S SUNOCO  
Tolleyville, Delaware

(2) GORDIE'S AUTO SERVICE  
West Chester, Pennsylvania

(2) KOLESNIK'S SERVICE STATION  
Rochester, New York

\* YAMAN'S TRANSMISSION SERVICE  
Cortland, New York

### REGION 2

(2) AUTO BRAKE CORPORATION  
Norfolk, Virginia

(3) B & G AUTO SERVICE  
Arlington, Virginia

BEREA AUTO SERVICE  
Greenville, South Carolina

\* KINGS PARK EXXON  
Springfield, Virginia

### REGION 4

DEROMEDI'S AUTO SERVICE  
Lakewood, Ohio

GLENN PERRY GARAGE  
Indianapolis, Indiana

HEATHERDOWN'S AUTOMOTIVE  
Toledo, Ohio

LEXINGTON BRAKE  
Lexington, Kentucky

(2) MASTER TIRE CO.  
Evansville, Indiana

### REGION 5

DES MOINES AREA COMM. COLLEGE  
Ankeny, Iowa

K & S WHEEL ALIGNMENT  
Waterloo, Iowa

RICHFIELD WHEEL ALIGNMENT  
Richfield, Minnesota

TOMMY'S AUTO REPAIR  
Sioux City, Iowa

### REGION 6

(2) CASEY'S SPORT CAR SERVICE  
Wichita, Kansas

(5) DICK JORDAN'S STANDARD SERVICE STATION  
Cloyton, Missouri

TOMAN AUTO REPAIR CO.  
St. Louis, Missouri

### REGION 7

\* A & B BRAKE & ALIGN  
Tyler, Texas

ANCELL'S TEXACO STATION  
Ablene, Texas

BOB CHESTER'S AUTO SERVICE  
Arlington, Texas

\* FUSELIER'S AUTO SERVICE  
New Orleans, Louisiana

### REGION 8

\* ALAMEDA GARAGE  
Pocatello, Idaho

DAN'S AUTOMOTIVE SERVICE  
Colorado Springs, Colorado

(2) NATIONAL SAFETY CLINIC AUTO REPAIR  
Salt Lake City, Utah

### REGION 9

DOYLE AUTOMOTIVE SERVICE  
Seattle, Washington

(3) FOSTER'S SERVICE CORPORATION  
Seattle, Washington

### REGION 9A

(5) ISE AUTOMOTIVE SERVICE  
Hollywood, California

KALLEN'S GARAGE  
Van Nuys, California

MICHAEL SCELZI GARAGE  
Fresno, California

RANCHO CORDOVA GARAGE  
Roncho Cordova, California


\* WONG'S AUTOMOTIVE SERVICE  
Fresno, California

NOTE: We need more participating shops. If you know of an independent automotive repair facility in your area who you think might want to help out in this Program, please send their name and address to us. Thanks.

## CURRENT PRP PARTICIPATION

The graph below identifies the number of active shops within each Region. Ninety-two shops have joined our active team and sent in a part. Keep up the good work. We still need many more shops on our active team and a lot more parts.

(AS OF 29 FEBRUARY 1976)



|        |    |    |    |    |    |    |    |    |    |    |
|--------|----|----|----|----|----|----|----|----|----|----|
| STATES | CT | DE | DC | AL | IN | IA | IL | AR | AZ | AK |
|        | ME | NJ | MD | FL | KY | MN | KS | LA | CO | CA |
|        | MA | NY | NC | GA | MI | MT | MO | OK | ID | HI |
|        | NH | PA | SC | MS | OH | ND | NE | TX | NV | OR |
|        | RI |    | VA | TN |    | SD |    |    | NM | WA |
|        | VT |    | WV |    |    | WI |    |    | UT |    |
|        | PR |    |    |    |    |    |    |    | WY |    |
|        | VI |    |    |    |    |    |    |    |    |    |
|        |    |    |    |    |    |    |    |    |    |    |
|        |    |    |    |    |    |    |    |    |    |    |

## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have any questions which need answers, or would like to pass on comments, please call us collect. Place your call to Bruce Beddow, Jonni Peizer, or Guy Whiddon at (703) 527-4500. We are Eastern Time and are normally available Monday through Friday from 8:30 a.m. to 5:30 p.m. Likewise, if you have a contribution or suggestion for the PRP News, please send it to Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention: Bruce E. Beddow.

## **NATIONAL PARTS RETURN PROGRAM** **DESCRIPTION AND FUNCTION**

- The PRP involves the voluntary submittal by independent repair shops of failed automotive components. Components are submitted to a representative (Kappa Systems, Inc.) of the National Highway Traffic Safety Administration (NHTSA).
- The purpose of the PRP is to gather information on these components to help the NHTSA identify the existence of safety-related, manufacturing defects in design, materials, construction, or performance of motor vehicles and motor vehicle equipment. Under the authority of the National Traffic and Motor Vehicle Safety Act of 1966, and Amendments to the Act in 1974, the NHTSA can require manufacturers to conduct safety defect notification campaigns when it has been determined that a defect relating to motor vehicle safety exists.
- The information obtained from these parts is also valuable in preparing Federal motor vehicle safety standards.

Your shop can help. The parts that you send in will give us vital information that cannot be obtained in any other way.

**PARTS RETURN PROGRAM**  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209



# NEW PARTS RETURN PROGRAM NEW

CONTRACT NO. DOT-HS-5-01166


U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Vol., No. 7

January 1976

## CRACKED POWER STEERING GEAR HOUSING

In recent months the PRP has received two cracked power steering gear housings. The first was received from Mr. Webb of WEBB & ANDERSON in Solem, Oregon. It carries serial number 5687962. This crack, approximately 160° around the cir-



cumference of the gear housing end, caused steering problems due to loss of fluid through the 1/8" separation. The second cracked power steering gear was received from Mr. W. M. Boyd of DODD'S AUTO SERVICE in Portsmouth, Virginia. It carries serial number 7805525. This crack is very similar to the first one and runs approximately 180° around the circumference of the gear housing end. The photograph (left) depicts these cracked power steering gear housings. The first foiled component was removed from a 1972 Buick Estote Wagon with 59,292 miles, and the second one came from a 1974 Chevrolet Impala Station Wagon with 53,000 miles. If any of our PRP members know of similar failures, please let us know with full descriptions of the failure, including make/model and year of the vehicle.

## STEERING POWER ASSIST HOSE

In October 1975, Mr. Gil Martin of GIL'S AUTOMOTIVE SERVICE in Sioux City, Iowa, sent in a ruptured power steering hose. This failed hose was taken from a 1975 Ford F-250, three-quarter ton pickup truck with 11,083 miles. A two-inch section of the hose was ruptured, reportedly due to contact with a hot engine manifold. The photograph (right) shows the hose rupture, between the arrows. We would like to hear from your shop if you know of similar conditions on other motor vehicles.



## HIGHLY ACTIVE PRP SHOPS

For the first half of the current year (period beginning 1 July 1975 and ending 31 December 1975) there were nine PRP shops that contributed 10 or more failed parts to the Program. Our objective is to have at least 20 of our shops contribute at least 20 or more failed parts by the year ending 30 June 1976. We know this is a reasonable goal which can be achieved with your help.

The shops who are well on their way to meeting this Program objective are listed below in order of the number of parts they had submitted as of 31 December 1975 (ties are listed in alphabetical sequence). We appreciate the contributions these shops are making to this Program.

| <u>SHOP NAME</u>                                            | <u>NO. OF PARTS</u> |
|-------------------------------------------------------------|---------------------|
| PARK AUTO REPAIR<br>Chicago, Illinois                       | 27                  |
| BERT'S ARCO STATION<br>Wilmington, Delaware                 | 22                  |
| ISE AUTOMOTIVE SERVICE<br>Hollywood, California             | 21                  |
| DICK JORDAN'S STANDARD SERVICE STATION<br>Clayton, Missouri | 20                  |
| AUTO HOSPITAL<br>Lincoln, Nebraska                          | 14                  |
| HAGAN SERVICE CENTER<br>Gainesville, Georgia                | 14                  |
| TIM'S IMPORT SALES & SERVICE<br>Hutchinson, Kansas          | 12                  |
| SMITH BROTHERS BRAKE & WHEEL SERVICE<br>Tujunga, California | 11                  |
| ADE & BOB'S MUFFLER & BRAKE CENTER<br>St. Paul, Minnesota   | 10                  |

## ITEMS OF INTEREST

- Currently there are several geographic regions which have a very low level of PRP participation. One such region includes the states of Idaho, Montana, North and South Dakota, Wyoming, Utah, and Nevada. If any of our existing PRP members know of independent automotive repair facilities in these states that might want to participate in this Program please forward their names and addresses to us. Thanks.
- Over the past few months the PRP has received 42 failed parts and/or items of information which relate to existing NHTSA defect investigations or audits. We have prepared the following summary table for your review. Keep up the good work. Your contribution of a failed part may lead to a new investigation, so keep them coming in even though they are not on this list.

| <u>CASE NO.</u> | <u>COMPONENT</u>                                   | <u>QTY. RECEIVED</u> |
|-----------------|----------------------------------------------------|----------------------|
| 161             | Power Brake Vacuum Check Valve (GM, Chrysler, AMC) | 7                    |
| 212             | Front Lower Control Arm (Ford)                     | 4                    |
| 258.5           | Engine Mounts (GM)                                 | 5                    |
| C2-53           | Brake Master Cylinder (Ford)                       | 5                    |
| 266             | Ignition Switch (Ford)                             | 1                    |
| 282.            | 15 x 5.5 Single-Piece Wheel (Ford, Mercury)        | 1                    |
| C4-07           | Hood Latch (Ford)                                  | 1                    |
| C4-09           | Brake Proportioning Valve (Chrysler)               | 2                    |
| C4-44           | Carburetor Floats (GM)                             | 8                    |
| C4-57           | Bosch Fuel Injector (Saab)                         | 1                    |
| C4-58           | Bosch Fuel Injector (Volvo)                        | 2                    |
| C5-07           | Timing Gears (Pontiac)                             | 1                    |
| A2-58           | Engine Mounts (GM)                                 | 4                    |
|                 |                                                    | <b>42 Parts</b>      |

A more detailed description of these investigations is contained in your NHTSA Defect Investigatory Cases Report. The December issue will be mailed to you in the near future.

## SIGNIFICANT CASES INVESTIGATED DURING 1974

In keeping with our objective of providing information to our PRP participants we are providing from time to time excerpts of significant cases, some of which have led to NHTSA influenced Recall Campaigns. The following case brief was taken in part from "A Report on Activities Under the National Traffic and Motor Vehicle Safety Act of 1966 and the Motor Vehicle Information and Cost Saving Act of 1972," U.S. Department of Transportation Document No. DOT-HS-801-700, page 37.

### **GENERAL MOTORS ROCHESTER QUADRAJET FUEL INLET PLUG FAILURE**

Based on allegations of fuel inlet plug failures in 1965-66 Chevrolets, and 1966 Buicks equipped with Rochester Quadrajet Carburetors, NHTSA investigated and determined that a safety-related defect existed. In the majority of the fuel inlet plug failures reported to NHTSA, engine compartment fires resulted. The manufacturer and other interested persons were given an opportunity to express their views; after considering these inputs, the NHTSA instructed GM to recall those vehicles. Since GM disagreed with the NHTSA's findings, legal proceedings were initiated.

## RECALL CAMPAIGN-CHRYSLER CORPORATION

(CAMPAIGN NO. 75-0201)

Chrysler Corporation is recalling 2,619 1975 Plymouth Fury and Dodge Coronet police vehicles equipped with 400 or 440 CID engines and power steering. There is a possibility that the steering return hoses may fail due to heat deterioration. High exhaust manifold temperatures produced by extensive idle operation and high speed pursuit conditions in police service may cause cracks in the return hose, resulting in leakage of power

steering fluid. In addition to potential loss of power steering assist, engine compartment fire may result from exhaust manifold ignition of the leaking fluid. The Chrysler Corporation will correct this problem by replacing suspect hoses with hoses made of a more heat resistant material (Hypalon). If your shop encounters power steering hose failures, due to heat deterioration, in non-police vehicles, we would like to hear from you.

## GOODYEAR RECALL OF CUSTOM STEELGARD

(CAMPAIGN NO. 76Y-002)

Goodyear Tire and Rubber Company is recalling 12,500 tires after some test tires failed the Department of Transportation's high speed and endurance requirements of Federal Motor Vehicle Safety Standard No. 109. The tires are the BR70-13, load range B, radial ply tubeless type with

raised white letters and serial numbers starting with the letter MK, and ending in the numbers 015 through 185 and 304 through 524. The tires will be replaced and mounted free of charge within 60 days from the date the customer or dealer receives the recall notification.

## OUTSTANDING SHOPS

Our outstanding shops are those shops which have sent into the PRP at least one part during the current month. A shop that sends in parts in consecutive months is identified by a number in parenthesis before the name. This number identifies the consecutive months the shop has sent in a part. New shops which have just become active in the PRP are identified with an asterisk before their name. During January 1976, 15 shops became active participants in the PRP, and at this time six shops have sent in failed parts in consecutive months.

### REGION 0

HARRY'S AUTO SERVICE  
Great Barrington, Massachusetts

- \* VENDETTA BROS. AUTOMOTIVE SERVICE  
Cromwell, Connecticut

### REGION 1

GORDIE'S AUTO SERVICE  
West Chester, Pennsylvania

KOLESNIK'S SERVICE STATION  
Rochester, New York

W. & S. SERVICE INC.  
Wilmington, Delaware

- \* YOUNGWOOD ESSO  
Youngwood, Pennsylvania

### REGION 2

AUTO BRAKE CORPORATION  
Norfolk, Virginia

- (2) B & G AUTO SERVICE  
Arlington, Virginia

\* DODD'S AUTO SERVICE  
Portsmouth, Virginia

\* EUROPEAN MOTORS LTD.  
Washington, D.C.

GROSS'S UNION 76 SERVICENTER  
Salem, Virginia

### REGION 3

- (4) HAGAN SERVICE CENTER  
Gainesville, Georgia

\* RALPH CANNON AUTO SERVICE, INC.  
Atlanta, Georgia

### REGION 4

\* FARRIS AUTOMOTIVE, INC.  
Whiting, Indiana

MASTER TIRE CO.  
Evansville, Indiana

### REGION 5

- (3) ADE & BOB'S MUFFLER & BRAKE CENTER  
St. Paul, Minnesota

### REGION 6

CAPITAL AUTOMOTIVE  
Lincoln, Nebraska

- \* CASEY'S SPORT CAR SERVICE  
Wichita, Kansas

- (4) DICK JORDAN'S STANDARD SERVICE STATION  
Clayton, Missouri

LINCOLN SAFETY SERVICE CO.  
Lincoln, Nebraska

- \* STONERS TRIANGLE AUTO SERVICE  
Rockford, Illinois

### REGION 7

GENERAL BRAKE SERVICE  
New Orleans, Louisiana

### REGION 8

- \* BUD'S GARAGE  
Pueblo, Colorado

DAVE KYLE'S GARAGE  
Phoenix, Arizona

- \* NATIONAL SAFETY CLINIC AUTO REPAIR  
Salt Lake City, Utah

WILLIAMS TEXACO SERVICE  
Phoenix, Arizona

### REGION 9

- (2) FOSTER'S SERVICE CORPORATION  
Seattle, Washington

\* GENESSE AUTOMOTIVE SERVICE  
Seattle, Washington

\* HAL'S MOTOR CLINIC  
Seattle, Washington

\* KING CO. BRAKE SERVICE  
Seattle, Washington

NORMAN'S AUTO REPAIR  
Arlington, Washington


\* SPORTS CAR SERVICE  
Seattle, Washington

\* WEBB & ANDERSON  
Salem, Oregon

### REGION 9A

- (4) ISE AUTOMOTIVE SERVICE  
Hollywood, California

- (2) SMITH BROTHERS BRAKE & WHEEL SERVICE  
Tujunga, California



THE PARTS RETURN PROGRAM

NEEDS YOUR HELP IN RETURNING FAILED STEERING SYSTEM COMPONENTS  
THAT ARE NOT THE RESULT OF AN ACCIDENT OR NORMAL WEAR.

HERE'S ALL YOU DO:

- *FILL OUT DATA TAG AND ATTACH TO PART.*
- *PLACE IN CANVAS MAIL BAG, TIE THE CORD  
AND PUT IN MAIL BOX. POSTAGE IS PAID.*


WE NEED MORE PARTS. WE NEED YOU. BECOME AN ACTIVE  
PARTICIPANT IN THIS PUBLIC SAFETY PROGRAM TODAY.

THANKS!

## CURRENT PRP PARTICIPATION

The graph below identifies the number of active shops within each Region. Eighty-three shops have joined our active team and sent in a part. Keep up the good work. We still need many more shops on our active team and a lot more parts.

(AS OF 31 JANUARY 1976)



|        |    |    |    |    |    |    |    |    |    |    |
|--------|----|----|----|----|----|----|----|----|----|----|
| STATES | CT | DE | DC | AL | IN | IA | IL | AR | AZ | AK |
|        | ME | NJ | MD | FL | KY | MN | KS | LA | CO | CA |
|        | MA | NY | NC | GA | MI | MT | MO | OK | ID | HI |
|        | NH | PA | SC | MS | OH | ND | NE | TX | NV | OR |
|        | RI |    | VA | TN |    | SD |    |    | NM | WA |
|        | VT |    | WV |    |    | WI |    |    | UT |    |
|        | PR |    |    |    |    |    |    |    | WY |    |
|        | VI |    |    |    |    |    |    |    |    |    |
|        |    |    |    |    |    |    |    |    |    |    |
|        |    |    |    |    |    |    |    |    |    |    |

## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have questions which need answers, or would like to pass on comments please call us collect. Place your call to Bruce Beddow or Guy Whiddon at (703) 527-4500. We are on Eastern Daylight Savings Time and are normally available Monday through Friday from 8:30 a.m. to 5:30 p.m. Likewise, if you have a contribution or suggestion for the PRP News, please send it to Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention: Bruce E. Beddow □

## NATIONAL PARTS RETURN PROGRAM DESCRIPTION AND FUNCTION

- The PRP involves the voluntary submittal by independent repair shops of failed automotive components. Components are submitted to a representative (Kappa Systems, Inc.) of the National Highway Traffic Safety Administration (NHTSA).
- The purpose of the PRP is to gather information on these components to help the NHTSA identify the existence of safety-related, manufacturing defects in design, materials, construction, or performance of motor vehicles and motor vehicle equipment. Under the authority of the National Traffic and Motor Vehicle Safety Act of 1966, and Amendments to the Act in 1974, the NHTSA can require manufacturers to conduct safety defect notification campaigns when it has been determined that a defect relating to motor vehicle safety exists.
- The information obtained from these parts is also valuable in preparing Federal motor vehicle safety standards.

Your shop can help. The parts that you send in will give us vital information that cannot be obtained in any other way □

**PARTS RETURN PROGRAM**  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209



# NEW PARTS RETURN PROGRAM NEW

CONTRACT NO. DOT-HS-5-01166

U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Vol. 1, No. 6

## CASE OF THE MONTH

December, 1975

ALLEGED ENGINE MOUNT FAILURES IN 1965-1969 FORD FAIRLANE AND RANCHEROS, 1965-1969 MERCURY MONTEGOS, 1965-1970 FORD FALCONS, AND 1965-1970 MERCURY COMETS MANUFACTURED BY THE FORD MOTOR COMPANY.



This case was opened as a result of six separate consumer reports of engine mount failure involving Ford Fairlane and Mercury Montego automobiles. All reports indicated a sticking throttle due to the broken engine mounts. An investigation was initiated to determine whether the alleged condition is potentially a safety related defect.

Engine mounts serve to support the engine on the vehicle's frame and to absorb noise, vibration, and torque reaction forces generated during engine operation. Engine mounts under investigation can be described as a "sandwich" type in which a thick layer of rubber is bonded between two layers of formed sheet metal. The "sandwiched" layer of rubber can split in two or delaminate causing the outer two metal pieces to separate. Note the separation of the engine mount in the photographs below. The most recent submittal of

a failed engine mount was by Frank Rumford of FRANK'S SUNOCO in Talleyville, Delaware. The engine mount is from a 1967 Ford.

The NHTSA concern is whether engine mount failure occurs as alleged and if so whether such failure results in partial rotation of the engine within the engine compartment during acceleration, jamming the accelerator and/or gear shift linkages. A failed engine mount may be detected by a "thumping" sound immediately after let up of the accelerator pedal. This "thumping" is the sound of the engine dropping back onto its mounting supports after being raised due to engine torque.

We know that many of our team members have sent in failed engine mounts in the past. If you encounter any additional failures, we would like to know about them and whether they had any effects on the operation of the car.



## CASE OF THE MONTH - NOVEMBER 1975

### ALLEGED REAR WHEEL BEARING FAILURE ON 1963-1974 CHEVROLET CORVETTE (CASE NO. C5-01)

The following information is supplemental to our case of the month article which appeared in the November 1975 PRP newsletter. It is being provided as an aid to PRP members in servicing the subject vehicles.

Page 2 of the November 1973 Chevrolet Service News, in an article entitled "Corvette Rear Wheel End Play Adjustment and Inner Bearing Lubrication - 1963-1974 Corvette," gives the following information:

"Please refer to the 'Component Parts Replacement (Corvette)' section found on pages 4-16 through 4-19 of the 1974 Chevrolet Passenger Car Service Manual before performing service on any component of a 1963 through 1974 Corvette rear wheel spindle, bearing and/or support. The procedure outlined on the pages above utilizes the latest updated service tools available for removal and/or replacement of the spindle assembly without removing the rivets. A new shim selector tool J24626 has been made available for determining

spindle end play without repeated removal of the spindle/rotor assembly as in the past.

"Re-emphasizing the importance of proper maintenance and lubrication of the spindle bearings, an article entitled 'Lubrication of Rear Wheel Inner Bearings Corvette Models' appeared in the November, 1972 issue of the Chevrolet Service News. The procedure outlined in the above article may be utilized on 1963-74 Corvette models using J-24488 greaser.

"In the case of a new vehicle, the inner wheel bearings should be lubricated after the initial 12,000 miles and every 24,000 miles thereafter.

"On past models, a 24,000 mile interval is recommended."

The special "J" number tools referenced are available from the Service Tool Division, Kent-Moore Corporation, 1501 South Jackson Street, Jackson, Michigan 49203.

### ITEMS OF INTEREST

- Gay Coffman has replaced Sharon Chapman as our PRP Region 8 Representative. Gay's telephone number is (303) 597-1900.
- Mr. David Stein of NORTH MAIN GARAGE in Westport, Connecticut, reports numerous ply separation failures in Firestone 500 Steel Belted Radial tires. At the time of his report, he indicated recent failures in JR78-15, LR78-15, and HR78-14. He also recorded two identification numbers VKV2FNR024 and VDV4FNJ263.
- Mr. Virgil Jones of DICK JORDAN'S STANDARD SERVICE in Clayton, Missouri, reports the failure of a power steering pump on a 1975 Maverick at 12,700 miles. The sudden failure made the vehicle difficult to steer. The failed part is not available to the PRP but Virgil sent us a completed failed part tag along with another failed part in the mailbag.
- Mr. R. Crum of SUBURBAN AUTOMOTIVE in Lynwood, Washington, sent in a failed part tag and photograph on a cracked front wheel. The wheel is from a 1973 Dodge Van with 40,175 miles. The photograph shows a severe crack just outside the lug bolt holes on the ridge.
- Another brake master cylinder from a 1970 Dodge Dart Custom has been received. We cannot identify the shop who sent in the part. Please notify us if this is your part.
- Several positive comments have been received concerning the proposed PRP Directory (October issue of the PRP News).

## SIGNIFICANT CASES INVESTIGATED DURING 1974

A recent report to the Congress of the United States in September 1975 by President Ford contained briefs of cases investigated by the Office of Defects Investigation, NHTSA, during the calendar year 1974. One such brief is presented below for your review. This text was taken in total from "A Report on Activities Under the National Traffic and Motor Vehicle Safety Act of 1966 and the Motor Vehicle Information and Cost Saving Act of 1972," U.S. Department of Transportation Document No. DOT-HS-801-700, page 37.

### B.F. Goodrich Space Saver Tire Explosive Tire/Rim Separation

Based on allegations of the explosive separation of the tire from the rim during the initial inflation process, NHTSA conducted an investigation that led to the conclusion that the failure of the tire assembly constituted a safety defect. Testing and field investigation demonstrated that the tire could fail during inflation and, in fact, had failed, causing two fatalities and several serious injuries. B.F. Goodrich has instituted a recall campaign to correct the problem.

### NISSAN RECALL - 20,187 1971 DATSUN PL510 SEDANS

The Nissan Motor Corporation in the United States has announced a recall, involving their 1971 model PL510 vehicles sold in California, to fix a faulty fuel tank plug. The rubber plug, used to close off a return line at the fuel tank, can possibly be eaten away by air pollutants, causing a gasoline leak into the rear seat area.

All vehicles sold in California are to be corrected for this defect without cost to the owner.

### RADIAL TIRE PROBLEMS

In the October issue of the PRP News we published articles concerning alleged problems with radial tires. We subsequently received a report from Mr. R. D. Halblom of CEDAR RAPIDS AUTO SERVICE in Cedar Rapids, Iowa, which reinforces the earlier reports. In addition, Mr. Halblom states that they have noted no "in service" failures of these tires when run on the rear axle. He also stated that severe alignment setting changes would not compensate for the pulling effect that these tires provide.

Mr. Halblom also reports difficulty in convincing customers that the problem originates in the tires. He states that they have often found it necessary to install a complete set of new or used tires to prove a diagnosis. Once convinced, the customers then return to the original tire dealer. No reports of dealers not fulfilling their adjustment obligations have been received by Mr. Halblom.

## OUTSTANDING SHOPS

Our outstanding shops are those shops which have sent into the PRP at least one part during the current month. A shop that sends in parts in consecutive months is identified by a number in parenthesis before the name. The number identifies the number of consecutive months the shop has sent in a part. New shops which have just become active in the PRP are identified with an asterisk before their name. During December, 12 shops became active participants in the PRP, and at this time 9 shops have sent in failed parts in consecutive months.

The outstanding shops for December are:

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p><b>REGION 0</b></p> <p>CAMBRIDGE BRAKE SERVICE<br/>Cambridge, Massachusetts</p> <p>CURLEY'S AUTO REPAIR, INC.<br/>Warwick, Rhode Island</p> <p>*HENNIKER AUTOMOTIVE<br/>Henniker, New Hampshire</p> <p>WORCESTER BOYS TRADE HIGH SCHOOL<br/>Worcester, Massachusetts</p> <p><b>REGION 1</b></p> <p>(2) BERT'S ARCO STATION<br/>Wilmington, Delaware</p> <p>*CENTRAL CITY GARAGE<br/>Harrisburg, Pennsylvania</p> <p>(2) D &amp; Z ATLANTIC<br/>Cornwells Heights, Pennsylvania</p> <p>FRANK'S SUNOCO<br/>Talleyville, Delaware</p> <p>*SARANDREA'S ESSO SERVICENTER<br/>Cornwells Heights, Pennsylvania</p> <p><b>REGION 2</b></p> <p>B &amp; G AUTO SERVICE<br/>Arlington, Virginia</p> <p>BETZ GARAGE<br/>Baltimore, Maryland</p> <p>GARLICK'S GARAGE<br/>Roanoke, Virginia</p> <p>*LIPPY'S AUTO SERVICE<br/>Richmond, Virginia</p> <p>*SOUTHSIDE GARAGE<br/>Winston Salem, North Carolina</p> | <p><b>REGION 3</b></p> <p>CHUCK'S SUPER SERVICE<br/>Orlando, Florida</p> <p>*DUNEDIN GARAGE<br/>Dunedin, Florida</p> <p>(3) HAGAN SERVICE CENTER<br/>Gainesville, Georgia</p> <p><b>REGION 4</b></p> <p>LEXINGTON BRAKE<br/>Lexington, Kentucky</p> <p>WHEEL &amp; AXLE SERVICE<br/>Lexington, Kentucky</p> <p><b>REGION 5</b></p> <p>(2) ADE &amp; BOB'S MUFFLER &amp; BRAKE CENTER<br/>St. Paul, Minnesota</p> <p>CEDAR RAPIDS AUTO SERVICE<br/>Cedar Rapids, Iowa</p> <p>JOE'S AUTO SERVICE<br/>Appleton, Wisconsin</p> <p>ROEHLS BEE LINE BRAKE &amp; ALIGN<br/>Appleton, Wisconsin</p> <p><b>REGION 6</b></p> <p>ADAMS MOTOR SERVICE<br/>St. Charles, Missouri</p> <p>*ATWELL AUTO REPAIR<br/>St. Louis, Missouri</p> <p>AUTO HOSPITAL<br/>Lincoln, Nebraska</p> <p>(3) DICK JORDAN'S STANDARD SERVICE STATION<br/>Clayton, Missouri</p> <p>(2) TIM'S IMPORT SALES &amp; SERVICE<br/>Hutchinson, Kansas</p> | <p><b>REGION 8</b></p> <p>*ALPINE AUTOMOTIVE SERVICE<br/>Lakewood, Colorado</p> <p>(2) BOBBITT'S CAR CLINIC<br/>Colorado Springs, Colorado</p> <p><b>REGION 9</b></p> <p>BOB'S AUTO CLINIC<br/>Sunnyside, Washington</p> <p>*DOYLE AUTOMOTIVE SERVICE<br/>Seattle, Washington</p> <p>*FOSTER'S SERVICE CORPORATION<br/>Seattle, Washington</p> <p>*SHARP'S AUTOMOTIVE<br/>Seattle, Washington</p> <p>STOP &amp; GO BRAKE &amp; WHEEL SERVICE<br/>Portland, Oregon</p> <p>*SUBURBAN AUTOMOTIVE<br/>Lynnwood, Washington</p> <p><b>REGION 9A</b></p> <p>BAUGHMAN &amp; TURNER<br/>Fullerton, California</p> <p>ERNIE'S AUTOMOTIVE SERVICE<br/>Tempe City, California</p> <p>HAMMER AUTOMOTIVE &amp; TRANSMISSION<br/>Corona, California</p> <p>(3) ISE AUTOMOTIVE SERVICE<br/>Hollywood, California</p> <p>LEE RANDALL &amp; SON<br/>San Diego, California</p> <p>(2) SAM'S WHEEL &amp; BRAKE SERVICE<br/>Santa Monica, California</p> <p>SMITH BROTHERS BRAKE &amp; WHEEL SERVICE<br/>Tujunga, California</p> <p>WILKERSON BROTHERS SERVICE STATION<br/>San Francisco, California</p> |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

## HIGHLY ACTIVE PRP SHOPS

As in the previous issues of the PRP News, we will reserve this space to publish photographs and brief descriptions of our very active program participants. Only one shop sent us a photograph this month.

### ADAMS MOTOR SERVICE St. Charles, Missouri


Our PRP team members are (left to right) Stanley Adams (owner), Melvin Ruhr (mechanic), and James Norton (mechanic). Ruth Adams (secretary and bookkeeper) is missing from the photograph. Stanley Adams has been in the vehicle service business since 1948 and established his present location in 1963. Stanley is NIASE certified in four categories. In the period 1 July 1974 through 30 June 1975, ADAMS MOTOR SERVICE contributed 12 failed parts to the PRP.



## CURRENT PRP PARTICIPATION

The graph below identifies the number of active shops within each Region. Sixty-nine shops have joined our active team and sent in a part. Keep up the good work. We still need many more shops on our active team and a lot more parts.

(AS OF 31 DECEMBER 1975)



## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have questions which need answers, or would like to pass on comments please call us collect. Place your call to Bruce Beddow or Guy Whiddon at (703) 527-4500. We are on Eastern Daylight Savings Time and are normally available Monday through Friday from 8:30 a.m. to 5:30 p.m. Likewise, if you have a contribution or suggestion for the PRP News, please send it to Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention: Bruce E. Beddow □

## NATIONAL PARTS RETURN PROGRAM DESCRIPTION AND FUNCTION

- The PRP involves the voluntary submittal by independent repair shops of failed automotive components. Components are submitted to a representative (Kappa Systems, Inc.) of the National Highway Traffic Safety Administration (NHTSA).
- The purpose of the PRP is to gather information on these components to help the NHTSA identify the existence of safety-related, manufacturing defects in design, materials, construction, or performance of motor vehicles and motor vehicle equipment. Under the authority of National Traffic and Motor Vehicle Safety Act of 1966, and Amendments to the Act in 1975, the NHTSA can require manufacturers to conduct safety defect notification campaigns when it has been determined that a defect relating to motor vehicle safety exists.
- The information obtained from these parts is also valuable in preparing Federal motor vehicle safety standards.

Your shop can help. The parts that you send in will give us vital information that cannot be obtained in any other way □

### **PARTS RETURN PROGRAM**

**NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION**

**c/o KAPPA Systems, Inc.**

**1501 Wilson Blvd.**

**Arlington, Va. 22209**



# NEWS PARTS RETURN PROGRAM NEWS

CONTRACT NO. DOT-HS-5-01166

U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Vol. 1, No. 5

## CASE OF THE MONTH

November 1975

### ALLEGED REAR WHEEL BEARING FAILURE ON 1963-1974 CHEVROLET CORVETTE (CASE NO. C5-01)

This case was opened as a result of a consumer complaint on a 1971 Chevrolet Corvette alleging rear wheel bearing failure. An investigation was initiated to determine whether the alleged failure and its consequences represented a potential safety-related defect within the meaning of the National Traffic and Motor Vehicle Safety Act of 1966.

The rear wheel bearings (inner and outer) are part of the rear spindle and support in the Corvette independent three-link type rear suspension. Exploded and cross-sectional views of this rear spindle and support assembly support the wheel assembly and permit rotation of the wheel with a minimum of

friction. The assembly consists of spacer separated, tapered roller bearings which require precise end play adjustments and a specific high load capacity wheel bearing grease.





FIGURE 1 EXPLODED AND CROSS-SECTIONAL VIEW OF REAR SPINDLE

Loss of lubricant in the bearing results in increased friction between the rollers and races. The rollers or races may spall and become rough. Increased friction resulting from dry or spalled rollers and races may become sufficiently great to destroy the bearing surfaces and lead to progressive grinding up of the bearing, or binding or seizure.

Failure of the bearing may be accompanied by squeaking, grinding or howling noises along with a sensation of rear end sway. Also reported in connection with spindle bearing failure have been owner sensations of hot dragging brakes and excessive rear wheel camber.

Failure of the bearing has been reported to result in seizure and possible locking of the spindle to the housing with consequent deformation or breakage of some drive train or suspension components and potential problems of vehicle controllability.


We have received a failed rear wheel bearing assembly of a 1968 Corvette from one of the PRP team members, CAMBRIDGE BRAKE SERVICE, Cambridge, Massachusetts.

If any of our other PRP team members have experienced this problem or know of someone who has, we would like to know about it.

### SEVERED FUEL LINE—1976 CAMARO

The PRP was notified by Mr. John Clark of PIONEER MOBIL STATION in Springfield, Virginia, that he was going to splice a fuel line that had been severed by an obstruction in the roadway. The PRP was interested in determining how this accident occurred and arranged with the owner of the vehicle to have several photographs taken. The photograph below shows the section of the fuel line that was replaced with a flexible hose (looking in the photograph from front to the rear of the vehicle). This fuel line on a 1976 Chevrolet Camaro was severed upon striking a manhole cover that had not been fully placed in the correct position on the roadway.

The location of the impact on the fuel line is just to the rear of the door and where the fuel line crosses from the main frame member to the outside panel. This particular vehicle had a full tank of gas upon impact with the manhole cover but due to the rear spout of the severed section being pinched, very little gas leaked to the road surface.



SEVERED FUEL LINE - 1976 CAMARO

We would like to know if any of our other PRP members have experienced similar situations with severed fuel lines.

## ITEMS OF INTEREST

- The PRP received a letter from Mr. Louis Yaman of YAMAN'S TRANSMISSION SERVICE in Cortland, New York, in reference to Case No. C4-07 (Alleged Hood Latch Failures on 1970-71 Ford and Mercury Full Size Vehicles — September issue of PRP News). Mr. Yaman stated that many vehicles come into his shop with the hoods nearly impossible to open. Mr. Yaman attributes the majority of these failures to a lack of lubrication.
- Mr. D. Foran of TIM'S IMPORT SALES & SERVICE in Hutchinson, Kansas, reports finding many problems with the brake proportioning valve on import vehicles, especially the Renault R-10. He suggests that the use of a correct size brake shoe in relation to the vehicle's weight and size might eliminate the problem. Mr. Foran also reports that the Bosch fuel injectors available in his geographic location are rebuilt items sold only on an exchange basis. During the month of October he expected to replace six of these injectors.
- Mr. Paul C. Lovely of PAUL'S GARAGE in Dayton, Ohio, has sent in several suggestions for PRP operational improvements. First, he suggests filing the Newsletter in three-ring loose-leaf notebooks for easy reference and access. Second, he recommends establishing a reference file for vehicle make/model/year with a brief statement of suspect components for each vehicle. Mr. Lovely suggests this might be accomplished by use of a sticky label on the Newsletter containing the information that, when removed, could be attached to the appropriate vehicle card in the reference file. Finally, Mr. Lovely suggests initiating a means by which the shops can report the defective replacement parts they purchase.

We agree with Mr. Lovely's suggestions. We hope the Newsletter creates sufficient interest on the part of our members that they would want to keep it handy as a reference. As to the file for suspect components and the make/model/year of applicable vehicle, we thought the document "Defect Investigatory Cases Report," which will be sent to you each quarter, could meet this reference file suggestion. This report identifies each case by Case No., manufacturer, make/model/year, suspect component, and alleged failure description. In reply to Mr. Lovely's last suggestion, we encourage all our PRP members to report to the PRP problems with replacement parts (article in October issue of PRP News). Mr. Lovely also suggests a quarterly reporting form to be supplied by the PRP to all the PRP members. We think this suggestion is a good idea and we will study the problem to determine the best approach.

- There is a new telephone number for our Region 5 Representative, Collin Strange. The new number is (414) 468-8370.
- One of our PRP team members sent in a brake master cylinder during this month. The tag became separated from the component and it was not in a mailbag. We have no way of identifying the active shop. If you sent in this part please let us know.

## OUTSTANDING SHOPS

Our outstanding shops are those shops which have sent into the PRP at least one part during the current month. A shop that sends in parts in consecutive months is identified by a number in parenthesis before the name. The number identifies the number of consecutive months the shop has sent in a part. New shops which have just become active in the PRP are identified with an asterisk before their name. During November, 16 shops became active participants in the PRP, and at this time 10 shops have sent in failed parts in consecutive months.

The outstanding shops for November are:


|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p><b>REGION 0</b></p> <p>(3) HARRY'S AUTO SERVICE<br/>Great Barrington, Massachusetts</p> <p>*TUCK'S SERVICE CENTER, INC.<br/>Hudson, Massachusetts</p> <p><b>REGION 1</b></p> <p>*BERT'S ARCO STATION<br/>Wilmington, Delaware</p> <p>*BRUCE'S AUTO REPAIR<br/>Northfield, New Jersey</p> <p>D &amp; Z ATLANTIC<br/>Cornwells Heights, Pennsylvania</p> <p>FERINO BROTHERS EXXON<br/>Feasterville, Pennsylvania</p> <p>*FLETCHER MOTORS<br/>Ambler, Pennsylvania</p> <p>(2) IDEAL GARAGE<br/>Fords, New Jersey</p> | <p>(2) KOLESNIK'S SERVICE STATION<br/>Rochester, New York</p> <p>(2) VINS MOTOR SERVICE CORP.<br/>Brooklyn, New York</p> <p>*YOUNGWOOD ESSO<br/>Youngwood, Pennsylvania</p> <p><b>REGION 2</b></p> <p>*ACREDALE AUTO SERVICE, INC.<br/>Virginia Beach, Virginia</p> <p>*PIONEER MOBIL STATION<br/>Springfield, Virginia</p> <p>PRESTON'S GULF SERVICE<br/>Richmond, Virginia</p> <p><b>REGION 2A</b></p> <p>(2) BERA AUTO SERVICE<br/>Greenville, South Carolina</p> | <p><b>REGION 3</b></p> <p>(2) HAGAN SERVICE CENTER<br/>Gainesville, Georgia</p> <p>*POST STREET GARAGE, INC.<br/>Jacksonville, Florida</p> <p>PRANGE BRAKE &amp; WHEEL<br/>Orlando, Florida</p> <p><b>REGION 4</b></p> <p>*FATHER &amp; SON GARAGE<br/>Detroit, Michigan</p> <p>*GLEN PERRY GARAGE<br/>Indianapolis, Indiana</p> <p>K &amp; H TOTAL SERVICE<br/>Ypsilanti, Michigan</p> <p>(2) SAFETY FIRST ALIGNMENT &amp; BRAKE<br/>Indianapolis, Indiana</p> | <p><b>REGION 5</b></p> <p>ADE &amp; BOB MUFFLER &amp; BRAKE CENTER<br/>St. Paul, Minnesota</p> <p>*BELOIT FRAME &amp; AXLE CO.<br/>Beloit, Wisconsin</p> <p>BLUEMOUND AUTOMOTIVE SERVICE<br/>Wauwatosa, Wisconsin</p> <p><b>REGION 6</b></p> <p>(2) DICK JORDAN STANDARD SERVICE STATION<br/>Clayton, Missouri</p> <p>*LINCOLN SAFETY SERVICE<br/>Lincoln, Nebraska</p> <p>(2) MC LAIN'S AUTO REPAIR<br/>St. Louis, Missouri</p> <p>TIM'S IMPORT SALES &amp; SERVICE<br/>Hutchinson, Kansas</p> | <p><b>REGION 7</b></p> <p>*J &amp; G AUTO CLINIC<br/>Lake Charles, Louisiana</p> <p><b>REGION 8</b></p> <p>*BOBBITT'S CAR CLINIC<br/>Colorado Springs, Colorado</p> <p>*DAN'S AUTO SERVICE<br/>Colorado Springs, Colorado</p> <p><b>REGION 9A</b></p> <p>(2) JISE AUTOMOTIVE SERVICE<br/>Hollywood, California</p> <p>KALLEN'S GARAGE<br/>Van Nuys, California</p> <p>*MIDAS MUFFLER SHOPS<br/>Bakersfield, California</p> <p>SAM'S WHEEL &amp; BRAKE SERVICE<br/>Santa Monica, California</p> |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

## HIGHLY ACTIVE PRP SHOPS

In our October issue of the PRP News we highlighted our team members who over the past 12 months had contributed over 20 failed parts to the PRP and had received an award from the NHTSA Administrator. (Three shops that received the award have not sent in photographs as yet.) In the PRP we have many more shops that have contributed over 10 parts and we would like to present a couple of these shops to you now.


### AUTO BRAKE CORPORATION Norfolk, Virginia

Our PRP team members are (left to right) George Casper (owner), Hattie Neal Casper (secretary-treasurer), Craig Casper (shop foreman), David Rannigan, Gordon Rannigan, and Gary Rannigan (mechanics). George Casper has been performing Virginia state inspections on motor vehicles since 1945 and started his present business in 1960. AUTO BRAKE CORPORATION performs general repair work and they have contributed 12 failed parts to the PRP during the period 1 July 1974 through 30 June 1975.



### D & Z ATLANTIC Cornwells Heights, Pennsylvania

Our PRP team members are (left to right) Sigmund and Dennis Ziembra. Ziggy has 30 years experience in the automotive repair business while Denny has 12 years experience. D & Z ATLANTIC has been operating since 1950 and specializes in electronic tune-ups, exhaust emissions analysis and repair, and general automotive repairs. They are also a state inspection station, and they have contributed 14 failed parts to the PRP during the period 1 July 1974 through 30 June 1975.



THE PARTS RETURN PROGRAM

NEEDS YOUR HELP IN RETURNING FAILED BRAKE SYSTEM COMPONENTS  
THAT ARE NOT THE RESULT OF AN ACCIDENT OR NORMAL WEAR.

HERE'S ALL YOU DO:

- *FILL OUT DATA TAG AND ATTACH TO PART.*
- *PLACE IN CANVAS MAIL BAG, TIE THE CORD  
AND PUT IN MAIL BOX. POSTAGE IS PAID.*

WE NEED MORE PARTS. WE NEED YOU. BECOME AN ACTIVE  
PARTICIPANT IN THIS PUBLIC SAFETY PROGRAM TODAY.

THANKS!


4-54

171

## CURRENT PRP PARTICIPATION

The graph below identifies the number of active shops within each Region. Fifty-seven shops have joined our active team and sent in a part. Keep up the good work. We still need many more shops on our active team and a lot more parts.

(AS OF 30 NOVEMBER, 1975)



STATES

|    |    |    |    |    |    |    |    |    |    |
|----|----|----|----|----|----|----|----|----|----|
| CT | DE | DC | AL | IN | IA | IL | AR | AZ | AK |
| ME | NJ | MD | FL | KY | MN | KS | LA | CO | CA |
| MA | NY | NC | GA | MI | MT | MO | OK | ID | HI |
| NH | PA | SC | MS | OH | ND | NE | TX | NV | OR |
| RI |    | VA | TN |    | SD |    |    | NM | WA |
| VT |    | WV |    |    | WI |    |    | UT |    |
| PR |    |    |    |    |    |    |    | WY |    |
| VI |    |    |    |    |    |    |    |    |    |

## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have questions which need answers, or would like to pass on comments please call us collect. Place your call to Bruce Beddow or Guy Whiddon at (703) 527-4500.

## GM RECALLS TRUCKS, AVOIDING NEW TRIAL ON WHEEL SAFETY

The U.S. Department of Transportation announced on November 6, 1975, that the Federal Government and General Motors Corporation have settled the long-standing Kelsey-Hayes wheel case.

Under terms of the settlement, and with the consent of the U.S. District Court for the District of Columbia, General Motors has agreed to recall and replace, free of charge, all 15 x 5.50 Kelsey Hayes three-piece disc wheels installed on approximately 200,000 3/4-ton 1960-65 model year Chevrolet and GMC trucks. The wheels were manufactured by the Kelsey-Hayes Corporation of Romulus, Michigan, and then sold to GM.

Under the settlement, the case will continue, but only on the government's claim for a civil penalty against GM.

This case was initiated in late 1970 by the department's National Highway Traffic Safety Administration (NHTSA) when it determined that 1960-

65 3/4-ton Chevrolet and GMC trucks, when equipped with these wheels, contain a safety-related defect.

The NHTSA Administrator found that the wheels in question are subject to failure without warning by fracturing and breaking while the truck is in motion. When failure occurs, the driver may suffer immediate loss of air pressure from the tire, the tire may come off the wheel, the driver may lose control of the truck, and the truck may even turn over.

On November 4, 1970, the NHTSA Administrator determined that the wheel failures constitute an unreasonable risk of personal injury and property damage, and he ordered General Motors to issue defect notifications to the owners of the trucks.

General Motors initially refused to issue the notification, and was contesting the Administrator's order in court. However, the corporation has now agreed to recall the trucks under this settlement.

### **PARTS RETURN PROGRAM**

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209



# NEWS PARTS RETURN PROGRAM NEWS

CONTRACT NO. DOT-HS-5-01166

U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION


Vol. 1, No. 4

October 1975

## TOYOTA WHEEL

Ron Wolf of RON'S AUTOMOTIVE REPAIRS in Fresno, California, sent to the PRP the wheel pictured below. Ron reported that during a routine check-up of a 1970 Toyota Crown Station Wagon his customer complained about a cracking noise heard each time he made a right turn. Ron pulled the right front wheel and inspected it. He found cracks on the leading and trailing edges of three of the four spokes at the location of the joint. The photograph below highlights the cracks found on one of these spokes. Not satisfied with only inspecting one wheel, Ron proceeded to pull and inspect each of the other three wheels. He found that two more had similar cracks. The spare wheel was checked and found to be all right. (Of the four wheels in contact with the road surface, three wheels had severe cracks in more than one location.)

The vehicle's mileage at the time this potential hazard was uncovered was reported at 54,000 miles. Ron Wolf also reported that these wheels



Right Front Wheel -  
1970 Toyota Crown Station Wagon

were original equipment. The identification number of the wheels shown in the photograph is TOPY 6-69 Jx14S-3. These 14" wheels could also be used on Toyota pick-up trucks, but normally only 12" and 13" wheels are used on Toyotas other than the Crown model.

If any of you have information relative to these wheels, please let us know about it.

## NO-RETURN PARTS

During this past month we have had several inquiries from our team members concerning problems with faulty replacement or aftermarket parts. Questions have come about from the shop's receipt of failed parts which must be returned to the parts dealer or manufacturer to receive credit.

In cases such as these we encourage our team members to report to us in writing. Drop us a line or simply fill out a failed part tag and send it along with the other failed parts which you submit to the P. If you use the failed part tag approach please indicate on the tag that the part is not available as it was returned for credit.

In many cases this type of information can be as valuable as receiving the part.

## SIGNIFICANT CASES INVESTIGATED DURING 1974

A recent report to the Congress of the United States in September 1975 by President Ford contained briefs of cases investigated by the Office of Defects Investigation, NHTSA, during the calendar year 1974. One such brief is presented below for your review. This text was taken in total from "A Report on Activities Under the National Traffic and Motor Vehicle Safety Act of 1966 and the Motor Vehicle Information and Cost Saving Act of 1972," U.S. Department of Transportation Document No. DOT-HS-801-700, page 36.

### BUICK AND CADILLAC ENGINE MOUNT FAILURE

Investigation of alleged engine mount failures and resultant throttle jamming led to the conclusion that the failure of these components constituted a safety defect. Vehicle tests demonstrated that, when engine mounts fail under certain conditions, the vehicle throttle control could become jammed in the open position, causing the driver to lose control of his vehicle. At the conclusion of this investigation, an initial defect determination was sent to General Motors, in accordance with Section 113 (e) (2) — now Section 152(a) (2) — of the National Highway Traffic and Motor Vehicle Safety Act of 1966. At a formal Section 113 (152) Public Proceeding, the manufacturer presented his view that the alleged defect did not affect motor vehicle safety. Legal proceedings are being initiated.

### TIRE RESPONSES


We have received information from two team members concerning conditions with radial tires (steel and fabric belted).

Chuck Kopache of K&S WHEEL ALIGNMENT SERVICE in Waterloo, Iowa, reports several of these conditions: (1) Vehicle ill handling which may be caused by belts being off center or smaller in diameter on one side or the other; (2) wobble and/or vibration — in some cases a condition traced to radial tires with irregular belts; and (3) tread and/or cord separation — which may result in tire failure while the vehicle is in motion. Chuck reports that a solution for the first condition is switching and rotating tires until you have minimized the "lead or pull" effect. For the other conditions he indicates that a replacement of tires is necessary.

Jim Sebastian of ALINE RITE AUTO SERVICE in St. Louis, Missouri, has also reported the "lead and pull" condition among radial tires. Jim's solution is switching and rotating tires until a combination has been found that minimizes this abnormal handling effect. Jim also reported two instance bead failure when mounting steel radials onto rims. The tires had 10 to 15 pounds of air at the time of failure. Jim reports he was using a mounting "doughnut" and bead lubricant. He also has indicated that other shops have experienced the same kinds of problems.

## ABOUT OUR SPECIAL SHOPS


As reported in our September issue, six of our PRP Team Members received special awards from Dr. J. B. Gregory, the Administrator of the National Highway Traffic Safety Administration. We cannot say enough about these shops and their voluntary support of this public safety program. We would like to introduce these shops and the individuals who give of their time in support of the PRP. They are presented in alphabetical order.



**DICK JORDAN'S STANDARD SERVICE**  
Clayton, Missouri


Our team members pictured here, left to right, are Virgil Jones, Floyd Garner, Dick Jordan, Jeff Jordan, and Gregg Alexander (not present are Everett Goad and Noah Wimberly). Virgil Jones, our PRP Representative at Dick Jordan's, has done an outstanding job. Dick Jordan has 26 years experience in the automotive repair business and he has been at his present location for four years.

Three other team members received the NHTSA Administrator's award but we did not receive their photographs in time for this issue. When we receive their photographs we will print their picture in the following PRP News issue. Thanks again to these outstanding shops.



**DUANE'S TUNEUP CLINIC**  
Manteca, California

We do not have photographs of Duane Ploehn (owner and operator) or his employee, Myron Stogsdill, at this time; however, Duane tells us his business commenced operation 1 May 1963. Duane specializes in tune-up work, brake, and front end repairs. Duane Ploehn has 25 years of experience in the automotive repair business, seven of which were spent as a service manager for automobile dealers. Myron Stogsdill has been with Duane for over three years.



**ISE AUTOMOTIVE SERVICE**  
Hollywood, California

Our team members, front row left to right, Ise Kuromi (owner and operator), Timothy Clay, Conrad Halvorsen, back row left to right, Nelson Shifrin, Albert Del Gesso, and Frank Hawakami (manager). Not pictured are Mike Novikoff and Kriss Romeyn (secretary). Conrad Halvorsen is our PRP Representative at Ise Automotive. Again, an outstanding job has been performed by one who believes in safety on our highways. Ise Kuromi has been in business since 1947 and built his present facility in 1964.

## OUTSTANDING SHOPS

Our outstanding shops are those shops which send in to the PRP at least one part during the current month. A shop who sends in parts in consecutive months is identified by a number in parenthesis before his name. The number identifies the number of months the shop has consecutively sent in a part. New shops which have just become active in the PRP are identified with an asterisk before their name. During October, 19 shops became active participants in the PRP. Three shops have sent in parts in consecutive months. The PRP's best month yet.

The outstanding shops for October are:

|                                                                   |                                                         |                                                           |                                                 |
|-------------------------------------------------------------------|---------------------------------------------------------|-----------------------------------------------------------|-------------------------------------------------|
| <u>REGION 0</u>                                                   | <u>REGION 2A</u>                                        | <u>*HUNNICUTT'S STANDARD SERVICE STATION</u>              | <u>REGION 8</u>                                 |
| *GILDDEN AUTO SERVICE<br>Nashua, New Hampshire                    | BEREA AUTO SERVICE<br>Greenville, South Carolina        | Racine, Wisconsin                                         | *MR. BRAKE<br>Salt Lake City, Utah              |
| (2)HARRY'S AUTO SERVICE<br>Great Barrington, Massachusetts        | *CHANNEY'S GARAGE<br>Union, South Carolina              | JOE'S AUTO SERVICE<br>Appleton, Wisconsin                 | <u>REGION 9</u>                                 |
| <u>REGION 1</u>                                                   | (2)GARLICK'S GARAGE<br>Roanoke, Virginia                | *JOHNSON'S SPECIALIZED SERVICE<br>Appleton, Wisconsin     | *MAYER AUTO SERVICE<br>Marysville, Washington   |
| BELMONT GARAGE<br>Langhorne, Pennsylvania                         | <u>REGION 3</u>                                         | *K&S WHEEL ALIGNMENT SERVICE<br>Waterloo, Iowa            | *RIVIERA ARCO<br>Eugene, Oregon                 |
| BRAKE-O-RAMA, INC.<br>Lodi, New Jersey                            | *EDDIE'S GARAGE<br>Nashville, Tennessee                 | *TRIANGLE AUTO SERVICE<br>Milwaukee, Wisconsin            | <u>REGION 9A</u>                                |
| IDEAL GARAGE<br>Fords, New Jersey                                 | ED'S AUTOMOTIVE CENTER<br>Miami, Florida                | <u>REGION 6</u>                                           | *A&E AUTOMOTIVE SERVICE<br>Fresno, California   |
| KOLESNIK'S SERVICE STATION<br>Rochester, New York                 | HAGAN SERVICE CENTER<br>Gainesville, Georgia            | BILL NOBLE'S BRAKE SERVICE<br>Pine Lawn, Missouri         | *BAUGHMAN & TURNER<br>Fullerton, California     |
| *NACE BROTHERS ALIGNMENT & BRAKE SERVICE<br>Latrobe, Pennsylvania | <u>REGION 4</u>                                         | *B&L AUTO SERVICE<br>Beloit, Kansas                       | ISE AUTOMOTIVE SERVICE<br>Hollywood, California |
| VINS MOTOR SERVICE CORP.<br>Brooklyn, New York                    | DOYLE'S SERVICE<br>Massillon, Ohio                      | DICK JORDAN STANDARD SERVICE STATION<br>Clayton, Missouri |                                                 |
| *W. T. GRANT CO.<br>Williamsport, Pennsylvania                    | LOUISVILLE AUTO<br>Louisville, Kentucky                 | *J. GARTNER AUTO SERVICE<br>Chicago, Illinois             |                                                 |
| <u>REGION 2</u>                                                   | SAFETY FIRST ALIGNMENT & BRAKE<br>Indianapolis, Indiana | MCLAIN'S AUTO REPAIR<br>St. Louis, Missouri               |                                                 |
| *B & G AUTO SERVICE<br>Arlington, Virginia                        | <u>REGION 5</u>                                         | PARK AUTO REPAIR<br>Chicago, Illinois                     |                                                 |
| (2)MIKE'S SERVICE CENTER, INC.<br>Winchester, Virginia            | DAY-NITE AUTO STATION<br>Kaukauna, Wisconsin            | *STEELE AUTOMOTIVE SERVICE<br>Topeka, Kansas              |                                                 |
|                                                                   | *GIL'S AUTOMOTIVE SERVICE<br>Sioux City, Iowa           | STONER'S TRIANGLE AUTO SERVICE<br>Rockford, Illinois      |                                                 |


## ITEMS OF INTEREST

- We thought of publishing a Directory of shop names, addresses, principal PRP person to contact at each shop, and telephone numbers. This Directory would contain the names of all shops that have sent in a part to the PRP since 1 July 1974. We have had several requests for a Directory of this type from national associations. If you have a comment either for or against, drop us a note with your next failed part.
- Our recovery of PRP mailbags that have either General Environment's or Inland Testing's address has not been a huge success. We estimate that close to 3000 of these mailbags are still in the hands of our team members. If you have any of these mailbags, please drop them in the mail — preferably with a failed part. They will be forwarded to us by the U.S. Postal Service.
- We have been in touch with the National Association of Trade and Technical Schools headquartered here in Washington, D.C., to see if there is some interest on the part of their member schools in hearing about or participating in our program. The response so far has been very positive. If you have a trade or technical school in your area that you think might be interested in learning about the Parts Return Program and its objectives, send us the name and address.

## CURRENT PRP PARTICIPATION

The graph below identifies the number of active shops within each Region. Forty-one shops have joined our active team and sent in a part. That's great news — keep up the good work. We still need many more shops on our active team and a lot more parts.

(AS OF 31 OCTOBER, 1975)



## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have questions which need answers, or would like to pass on comments please call us collect. Place your call to Bruce Beddow or Guy Whiddon at (703) 527-4500. We are on Eastern Daylight Savings Time and are normally available Monday through Friday from 8:30 a.m. to 5:30 p.m. Likewise, if you have a contribution or suggestion for the PRP News, please send it to Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention: Bruce E. Beddow □

## NATIONAL PARTS RETURN PROGRAM DESCRIPTION AND FUNCTION

- The PRP involves the voluntary submittal by independent repair shops of failed automotive components. Components are submitted to a representative (Kappa Systems, Inc.) of the National Highway Traffic Safety Administration (NHTSA).
- The purpose of the PRP is to gather information on these components to help the NHTSA identify the existence of safety-related, manufacturing defects in design, materials, construction, or performance of motor vehicles and motor vehicle equipment. Under the authority of the National Traffic and Motor Vehicle Safety Act of 1966, and Amendments to the Act in 1974, the NHTSA can require manufacturers to conduct safety defect notification campaigns when it has been determined that a defect relating to motor vehicle safety exists.
- The information obtained from these parts is also valuable in preparing Federal motor vehicle safety standards.

Your shop can help. The parts that you send in will give us vital information that cannot be obtained in any other way □

PARTS RETURN PROGRAM  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209



# NEW PARTS RETURN PROGRAM NEW

CONTRACT NO. DOT-HS-5-01166

U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Vol. 1, No. 3

September 1975

## CASE OF THE MONTH

### ALLEGED HOOD LATCH FAILURES ON 1970-71 FORD AND MERCURY FULL SIZE VEHICLES (CASE NO. C4-07)

This case was opened as a result of consumer letters alleging that the hoods of the subject vehicles would fly open while the vehicles were in motion. Difficulty in closing the hood properly has also been alleged. An investigation was initiated to determine whether the alleged hazard is potentially a safety related defect within the meaning of the National Traffic and Motor Vehicle Safety Act of 1966.

The hood latch system (see Figure 1) consists of two hooks located on the upper grill area of the vehicle. These hooks engage the front of the hood to retain it in a closed position. The primary hook holds the hood in a secure position. The secondary hook is a backup system, designed to prevent the hood from opening in the event that the primary latch is not properly secured. The primary and/or secondary hood latch may fail to properly engage. If the latch is not positioned properly in the latch hole, it will not function.




Figure 1 Typical Ford-Mercury Hood Latch

The NHTSA's concern is whether, in the event of a hood latch failure on a moving vehicle, the wind will create sufficient force to bend the hood and cowl, break the windshield, or block the driver's forward vision, partially or completely.

If any of our PRP team members have experienced this problem or know of someone who has, we would like to know about it □

## ACTIVE CASE PARTS RECEIVED

Failed parts have been received recently from our PRP team members which may support several of our active cases. Three carburetor floats reported to have caused engine flooding due to loss of float buoyancy were received from ACCURATE AUTOMOTIVE ATTENTION, Yuma, Arizona; GARLICK'S GARAGE, Roanoke, Virginia; and TRAFFIC SAFETY RESEARCH CORPORATION, Palo

Alto, California. These carburetor floats, which may support Case C4-44, were removed from a 1964 Pontiac and two 1969 Chevrolets. One master brake cylinder reported to have failed due to corrosion was removed from a 1970 Falcon. It was sent to the PRP by the AUTO HOSPITAL in Lincoln, Nebraska. This brake master cylinder may support Case C2-53 □

## DATSUN FUEL TANK FILLER - NECKS CRACKED

The PRP has received four cracked fuel tank filler necks from Datsun vehicles. In each case the involved vehicle model is the 1972 Datsun 240Z. Two of these failed part tags did not contain mileage at failure. The other two were 40,560 and 53,393. These failed parts were received from the EUROPEAN AUTOMOTIVE SHOP, Fresno, California (2 filler necks), MIDWAY AUTO SERVICE, Midway City, California, and ISE AUTOMOTIVE SERVICES, Hollywood, California. One of the failed filler necks is shown in photograph (notice the position of the crack). In each case the cracked hose reportedly resulted in fuel leakage. We want all our PRP team members to be on the look out for this potential problem.




*Failed Fuel Filler Neck*

## CERTIFICATE OF PARTICIPATION

Any PRP team member who sends in at least one part receives a framed certificate for displaying where your customers can view it. This certificate highlights your shop as a contributor to improving safety on our highways. A reduced example of the certificate is below. The actual size is 8" x 10-1/2"

|                                                                                         |                                                                                            |
|-----------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|
|      | <b>U.S. DEPARTMENT OF TRANSPORTATION</b><br>NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION |
| .....                                                                                   |                                                                                            |
| <b>CERTIFICATE OF PARTICIPATION</b>                                                     |                                                                                            |
| THIS IS TO CERTIFY THAT                                                                 |                                                                                            |
| <i>Automotive Repair facilities</i>                                                     |                                                                                            |
| IS ACTIVELY PARTICIPATING TO IMPROVE<br>MOTOR VEHICLE SAFETY THROUGH COOPERATION IN THE |                                                                                            |
| <b>NATIONAL PARTS RETURN PROGRAM</b>                                                    |                                                                                            |
| FOR THE YEARS: 1975-1976                                                                |                                                                                            |
| ISSUED BY:                                                                              | CONTRACT NO. DOT-HS-5-01166                                                                |
| PROGRAM MANAGER                                                                         |                                                                                            |



THE PARTS RETURN PROGRAM

NEEDS YOUR HELP IN RETURNING FAILED BRAKE SYSTEM COMPONENTS  
THAT ARE NOT THE RESULT OF AN ACCIDENT OR NORMAL WEAR.

HERE'S ALL YOU DO:

- FILL OUT DATA TAG AND ATTACH TO PART.
- PLACE IN CANVAS MAIL BAG, TIE THE CORD  
AND PUT IN MAIL BOX. POSTAGE IS PAID.

WE NEED MORE PARTS. WE NEED YOU. BECOME AN ACTIVE  
PARTICIPANT IN THIS PUBLIC SAFETY PROGRAM TODAY.

THANKS!

4-65

## SHOPS RECEIVE SPECIAL AWARDS

Dr. James B. Gregory, Administrator of the National Highway Traffic Safety Administration, recently awarded a specially framed Certificate of Appreciation to six of our team members for their contribution to the PRP during the year ending 1 June 1975. Dr. Gregory also provided each of these shops with a related news release for their local newspapers. This annual award is given to those participants within the PRP who submit 20 or more failed parts over the period of one year. Of the almost 2000 current PRP enrollees, only these six shops qualified for the award this year. We congratulate these shops on their award and thank them for their voluntary support. The shops who received this special award were:

1. DICK JORDAN STANDARD SERVICE STATION, CLAYTON, MISSOURI
2. DUANE'S TUNEUP CLINIC, MANTECA, CALIFORNIA
3. HAGAN SERVICE CENTER, GAINESVILLE, GEORGIA
4. ISE AUTOMOTIVE SERVICE, HOLLYWOOD, CALIFORNIA
5. PARK AUTO REPAIR, CHICAGO, ILLINOIS
6. VANOWEN BRAKE AND WHEEL, N. HOLLYWOOD, CALIFORNIA

## CORRECTIONS TO REGIONAL REPRESENTATIVES

Mr. Collin Strange has replaced Mr. Don Heimlick as our Region 5 Representative. Collin's telephone number is (414) 468-9460.

Ms. Jeanette Cason, our Region 6 Representative, has left the company. Jeanette's replacement has not been named. Region 6 shops can call collect to Region 2 if you have a question.

In Region 9 ask for Mr. John Hickey if Mike Botkin is not there. John can be reached on the same number.

Our Region 9A Representative, Ms. Virginia Gore's telephone number was misprinted. It should be (408) 243-4796 not 7496.

## ITEMS OF INTEREST

Our Region 8 Representative, Sharon Chapman, suggests that our PRP team members might want to place or hang the Newsletter where your customers can get a chance to read or view it. Might stir some interest — good idea.

Tonilee Myre, our Region 2A Representative, reports that Mr. Brewer of SMITHS GARAGE in Winston-Salem, North Carolina, discusses the PRP in weekly meetings with his personnel. We need more interest like this.

## OUTSTANDING SHOPS

Our outstanding shops are those shops which send in to the PRP at least one part during the current month. A shop who sends in parts in consecutive months is identified by a number in parenthesis before his name. The number identifies the number of months the shop has consecutively sent in a part. New shops which have just become active in the PRP are identified with an asterisk before their name. We are pleased to announce that last month we had nine new active shops and this month we have 10 more □

The outstanding shops for September are:

### REGION 0

HARRY'S AUTO SERVICE  
Great Barrington, Maine

### REGION 1

\*JOE JERGE'S GARAGE  
Erie, Pennsylvania

### REGION 2

\*MIKE'S SERVICE CENTER, INC.  
Winchester, Virginia

### REGION 2A

\*SMITH AUTO SERVICE, INC.  
Richmond, Virginia

PRESTON'S GULF SERVICE  
Richmond, Virginia

\*GARLICK'S GARAGE  
Roanoke, Virginia

\*SUPERIOR WHEEL ALIGNMENT  
& BRAKE SERVICE  
Charlotte, North Carolina

### REGION 3

\*BECKTON AUTO REPAIR  
Savannah, Georgia

### REGION 4

MOBILE BRAKE SERVICE  
Columbus, Ohio

AKRON WHEEL ALIGNMENT  
Akron, Ohio

### REGION 7

\*J. D. CARTER GARAGE  
Abilene, Texas

### REGION 8

DAVE KYLE'S GARAGE  
Phoenix, Arizona

\*MCMILLEN AUTO SERVICE  
Roswell, New Mexico

\*TERRY MOTOR CO.  
Beaver, Utah

\*MERRILL'S AUTOMOTIVE SERVICE  
Salt Lake City, Utah

### REGION 9

B&E AUTOMOTIVE  
Tacoma, Washington

### REGION 9A

CALIFORNIA STATE AUTOMOBILE  
ASSOCIATION  
San Francisco, California


TRAFFIC SAFETY RESEARCH  
CORPORATION  
Palo Alto, California

JERRY HALL TIRE SERVICE  
Costa Mesa, California

EUROPEAN AUTOMOTIVE SHOP  
Fresno, California

## CURRENT PRP PARTICIPATION

The graph below identifies the number of active shops within each Region. Twenty-two shops have joined our active team and sent in a part. That's great news — keep up the good work. We still need many more shops on our active team and a lot more parts □



## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have questions which need answers, or would like to pass on comments please call us collect. Place your call to Bruce Beddow or Guy Whiddon at (703) 527-4500. We are on Eastern Daylight Savings Time and are normally available Monday through Friday from 8:30 a.m. to 5:30 p.m. Likewise, if you have a contribution or suggestion for the PRP News, please send it to Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention: Bruce E. Beddow □

## NATIONAL PARTS RETURN PROGRAM DESCRIPTION AND FUNCTION

- The PRP involves the voluntary submittal by independent repair shops of failed automotive components. Components are submitted to a representative (Kappa Systems, Inc.) of the National Highway Traffic Safety Administration (NHTSA).
- The purpose of the PRP is to gather information on these components to help the NHTSA identify the existence of safety-related, manufacturing defects in design, materials, construction, or performance of motor vehicles and motor vehicle equipment. Under the authority of National Traffic and Motor Vehicle Safety Act of 1966, and Amendments to the Act in 1974, the NHTSA can require manufacturers to conduct safety defect notification campaigns when it has been determined that a defect relating to motor vehicle safety exists.
- The information obtained from these parts is also valuable in preparing Federal motor vehicle safety standards.

Your shop can help. The parts that you send in will give us vital information that cannot be obtained in any other way □

### **PARTS RETURN PROGRAM**

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209



#### CASE OF THE MONTH (Cont'd)

Because the front disc brakes require greater line pressure to apply the brake pads against the rotor (disc) than the rear brakes require to force the brake shoes against the drum it is necessary to control the hydraulic pressure received by each.

The braking force on the front and rear wheels has to be varied in order to obtain the maximum braking, i.e., stopping within the shortest distance. An effective method is the use of the brake proportioning valve. By sensing the master cylinder pressure it proportions the proper amount

of pressure between the front and rear brakes, under various braking conditions.

One of our PRP team members, LEE RANDALL AND SON of San Diego, California, sent in a proportioning valve from a 1972 Dodge Dart that reportedly caused rear brake lock-up. If any of our PRP team members have information relative to this case, please forward it to the address printed on the back of this newsletter. Perhaps some of you have encountered this alleged problem and have suggestions as to the cause of rear wheel lock-up. If so, we would like to hear from you

#### CASE NO. C4 - 07

##### REPORTED HOOD LATCH FAILURES ON 1970 AND 1971 FORD AND MERCURY FULL SIZE VEHICLES

This case was opened on 24 July 1973 as a result of consumer complaint letters received in the Office of Defects Investigation, NHTSA, alleging that the hoods of the subject vehicles would fly open while the vehicles were in motion. In addition, difficulty in closing the hood properly has also been reported.

This reported hood latch problem has been selected as our case of the month for the September Newsletter. Anyone having information relative to this case, please send it to U.S. Department of Transportation, c/o Kappa Systems, Inc., 1517 Wilson Boulevard, Arlington, Virginia 22207. Attention: Mr. Bruce Beddow

#### WE WANT FAILED TIRE INFORMATION

Many of our Team Members have asked our Regional Representatives if we were interested in failed tire information. The answer is yes. It is not necessary to send the tire to our facility. Just record the failure and tire identification information on the sidewalls of the tire on the failed part tag and drop it into a mailbag along with another part and mail.

The information which is important to us includes:

1. The tire identification number molded on the tire. As an example: CEJCVPI033.
2. Tire size. As an example: 825 x 14.
3. Construction type such as Bias, Belted, or Radial.
4. Construction material such as Nylon, Rayon, Fiberglass, Steelbelts, etc.

5. Ply rating such as 4 or 8, etc.
6. Tire name molded on sidewall such as "Allstate Crusader."
7. The owner's name and address.
8. Mileage at failure.
9. Failure description such as tread separation, ply separation, blowout, etc.

The information requested in 1-6 above can be obtained from the tire. Record this information on the back of your failed part tag. Record the owner's name on the lower portion of the back side of this tag. Be sure to record the mileage at failure and the failure description in the appropriate spot on the front of the tag

## OUTSTANDING SHOPS

Our outstanding shops are those shops which send in to the PRP at least one part during the current month. A shop who sends in parts in consecutive months is identified by a number in parenthesis before his name. The number identifies the number of months the shop has consecutively sent in a part. New shops which have just become active in the PRP are identified with an asterisk before their name.

The outstanding shops for August are:

### REGION 0

- \* BOTHEL'S GARAGE  
Cape Elizabeth, Maine
- BEN-SAL AUTO SERVICE  
CENTER, INC.  
Hartford, Connecticut

### REGION 1

- WALT'S GARAGE  
Kenmore, New York
- SAFEWAY BRAKE & MUFFLER SHOP  
Albany, New York
- GORDIES AUTO SERVICE  
West Chester, Pennsylvania

### REGION 3

- \* PRANGE BRAKE & WHEEL ALIGNMENT  
Orlando, Florida
- ED'S AUTOMOTIVE CENTER  
Miami, Florida
- SUNRAY OIL & GAS #961-1507  
Tampa, Florida
- KELSO'S MOTOR TUNE-UP SERVICE  
Oak Ridge, Tennessee

### REGION 4

- \* LOTT'S REPAIR SERVICE  
Lansing, Michigan
- \* PAUL'S GARAGE  
Dayton, Ohio

### REGION 5

- \* DAVE McMILLEN'S AUTO REPAIR  
SERVICE  
Duluth, Minnesota
- CEDAR RAPIDS AUTO SERVICE  
Cedar Rapids, Iowa

### REGION 6

- CAPITAL AUTOMOTIVE  
Lincoln, Nebraska
- AUTO HOSPITAL  
Lincoln, Nebraska

### REGION 7

- \* GENERAL BRAKE SERVICE  
New Orleans, Louisiana
- \* TOM'S SOUTHSIDE ALIGNMENT AND  
REPAIR  
Arlington, Texas

### REGION 8

- A. & T. 66 SERVICE  
Las Cruces, New Mexico
- ACCURATE AUTOMOTIVE ATTENTION  
Yuma, Arizona

### REGION 9A

- (2) VANOWEN BRAKE & WHEEL  
North Hollywood, California
- \* WERK BROTHERS GARAGE  
Pasadena, California
- BIG BRAKE OF STOCKTON  
Stockton, California
- MICHAEL SCELZI GARAGE  
Fresno, California
- ISE AUTOMOTIVE SERVICE  
Hollywood, California

## REQUEST FOR OLD MAILBAGS

The continuing operation of the PRP depends, in a large part, on your returning the old mailbags (those that have as an address General Environment Corporation or Inland Laboratories) at the earliest possible time. If you still have some of these mailbags, we urgently request you drop them in the mail. This will be a major contribution towards keeping this worthwhile public safety program in high gear □

## CURRENT PRP PARTICIPATION STATISTICS

As a continuous article each month we would like to provide you with information relative to the active participation within each PRP Region. Active participation in the PRP as defined here means having sent in a part to the program some time during the period 1 July 1974 to the present.

The states are divided into Regions. To determine your Region, locate your state in the list below:

| <u>Region 0</u>   | <u>Region 2A</u>  | <u>Region 5</u> | <u>Region 8</u>  |
|-------------------|-------------------|-----------------|------------------|
| Maine             | Southern Virginia | Iowa            | Colorado         |
| New Hampshire     | North Carolina    | Wisconsin       | Wyoming          |
| Vermont           | South Carolina    | Minnesota       | Idaho            |
| Massachusetts     |                   | South Dakota    | Utah             |
| Connecticut       | <u>Region 3</u>   | North Dakota    | Arizona          |
| Rhode Island      | Tennessee         | Montana         | New Mexico       |
|                   | Georgia           | <u>Region 6</u> | Nevada           |
| <u>Region 1</u>   | Florida           | Illinois        | <u>Region 9</u>  |
| New York          | Alabama           | Missouri        | Oregon           |
| Pennsylvania      | Mississippi       | Kansas          | Washington       |
| New Jersey        | <u>Region 4</u>   | Nebraska        |                  |
| Delaware          | Kentucky          | <u>Region 7</u> | <u>Region 9A</u> |
| <u>Region 2</u>   | Ohio              | Louisiana       | California       |
| Washington, D.C.  | Indiana           | Arkansas        |                  |
| Maryland          | Michigan          | Oklahoma        |                  |
| Northern Virginia |                   | Texas           |                  |
| West Virginia     |                   |                 |                  |

Three figures are provided for each Region. They are as follows:

- Active Participants — Repair shops that have sent in at least one part since July 1974.
- PRP Members — The number of repair shops enrolled in the PRP. This number includes both active and nonactive members.
- Percent Active — The percent of active participation within the PRP Region.

The PRP Members figure of 879 used in this calculation does not represent all of the repair shops that are enrolled in the program at the present time. There are an additional 1100 repair shops that have been enrolled in the program but have not been active for several years. These 1100 shops will receive our special attention in the days ahead in order to seek their active participation.

The results of the active participating percentage calculation is as follows:

| Region | Active Participants | ÷ | PRP Members | = | Percent Active |
|--------|---------------------|---|-------------|---|----------------|
| 0      | 17                  |   | 34          |   | 50.0           |
| 1      | 24                  |   | 59          |   | 40.7           |
| 2      | 14                  |   | 67          |   | 20.9           |
| 3      | 16                  |   | 105         |   | 15.2           |
| 4      | 25                  |   | 96          |   | 26.0           |
| 5      | 15                  |   | 98          |   | 15.3           |
| 6      | 18                  |   | 95          |   | 18.9           |
| 7      | 10                  |   | 97          |   | 10.3           |
| 8      | 12                  |   | 110         |   | 10.9           |
| 9      | <u>42</u>           |   | <u>118</u>  |   | <u>35.6</u>    |
| Total  | 193                 |   | 879         |   | 22.0           |

We certainly would like to improve these figures. If we could enlist 247 more of you to actively participate in this program we would reach 50% active. This is not an impossible goal — we need your support □

### THE OFFICE OF DEFECTS INVESTIGATION (ODI) NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION (NHTSA)

As members of the Parts Return Program, you may be interested in the background of the Program and how it supports the mission of the Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA).

The Parts Return Program was developed by the ODI to assist in uncovering potential safety-related defects in motor vehicles and motor vehicle equipment. We are looking for any defect in the performance, construction, components, or material of a motor vehicle or item of motor vehicle equipment which subjects the public to unreasonable risk of accident, death, or injury. In uncovering potential safety-related defects the PRP contributes to the defect investigation cycle by helping to

- Identify new potential defects, and
- Provide supporting information on ongoing investigations.

The mission of the ODI within NHTSA is "to provide testing, inspection, and investigation necessary to the identification and correction of safety-related defects (other than those not in compliance with promulgated Federal Motor Vehicle Safety Standards) disclosed in foreign and domestic motor vehicles and associated equipment, and the safety-related defect notification requirements of the National Traffic and Motor Vehicle Safety Act of 1966, as amended." In carrying out the above mission the ODI conducts tests, inspections, and investigations necessary to uncover potential or confirm the existence of suspected or of alleged, safety-related defects in motor vehicles and related equipment. When investigations are opened by the ODI the PRP helps to support these investigations by supplying information and parts for testing and inspection □

### IN RESPONSE TO INQUIRIES

We are interested in receiving all parts which are considered to have a safety-related defect. This includes similar or identical "repeat parts." These repeat parts may provide important supporting information to cases under investigation or may lead to new areas for investigation.

For example, if you have several engine mounts from the same model vehicle, we want all of them. Likewise, if you read in the PRP News where one of our team members sent in a specific part and you have an identical part, we want yours also □

## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have questions which need answers, or would like to pass on comments please call us collect. Place your call to Bruce Beddow or Guy Whiddon at (703) 527-4500. We are on Eastern Daylight Savings Time and are normally available Monday through Friday from 8:30 a.m. to 5:30 p.m. Likewise, if you have a contribution or suggestion for the PRP News, please send it to Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention: Bruce E. Beddow □

## NATIONAL PARTS RETURN PROGRAM DESCRIPTION AND FUNCTION

- The PRP involves the voluntary submittal by independent repair shops of failed automotive components. Components are submitted to a representative (Kappa Systems, Inc.) of the National Highway Traffic Safety Administration (NHTSA).
- The purpose of the PRP is to gather information on these components to help the NHTSA identify the existence of safety-related, manufacturing defects in design, materials, construction, or performance of motor vehicles and motor vehicle equipment. Under the authority of the National Traffic and Motor Vehicle Safety Act of 1966, and Amendments to the Act in 1974, the NHTSA can require manufacturers to conduct safety defect notification campaigns when it has been determined that a defect relating to motor vehicle safety exists.
- The information obtained from these parts is also valuable in preparing Federal motor vehicle safety standards.

Your shop can help. The parts that you send in will give us vital information that cannot be obtained in any other way □

PARTS RETURN PROGRAM  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209

4-75

PRP NEWSLETTER



# NEWS PARTS RETURN PROGRAM NEWS

CONTRACT NO. DOT-HS-5-01166

U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Vol. 1, No. 1

July 1975

## CASE OF THE MONTH

### STEERING RACK AND PINION ASSEMBLY 1971-1972 FORD PINTO ALLEGED LOSS OF STEERING CONTROL


Case of the Month articles are intended to call your attention to important investigations currently being conducted by the U.S. Department of Transportation (DOT), National Highway Traffic Safety Administration. As you know, our Parts Return Program team members have made valuable contributions to many of these investigations of alleged safety related defects. We are now counting on our team members to provide failed parts and information which will help in this investigation.

The case featured this month was opened on the basis of consumer reports of steering failure on 1971 and 1972 Ford Pintos. These failures were said to have resulted in steering difficulty or loss of steering control. Information obtained by DOT suggests that the reported steering failures may have been caused by bending of the rack gear, due to impact.

As most of our team members know, the Pinto steering rack and pinion assembly consists basically of a rack gear and a pinion gear. The pinion gear is a part of the input shaft. A flexible shaft connects the input, or pinion, shaft to the upper steering shaft. The ends of the rack gear are connected to the tie rods and sealed with rubber bellows. Rotary motion of the steering wheel is transmitted through the steering shaft to the pinion shaft. The rack and pinion assembly

translates this rotary motion through the connecting rods to the front wheel spindles, to control vehicle steering.


Failed Pinto rack and pinion steering gear assemblies have already been sent in by two Parts Return Program shops. Mr. William Murley of Medley's Auto and Truck Alignment Service Inc. in Louisville, Kentucky, sent in a locked up steering assembly from a 1972 Ford Pinto. The rack gear was bent downward and slightly backward in a manner which caused the gear to jam in the housing. The driver complained to Mr. Murley that his steering system suddenly locked up and caused him to lose control of his vehicle. His car left the roadway before he was able to bring it to a stop in an adjoining field.



*Rack and pinion steering assembly from a 1972 Ford Pinto. The rubber boot on the drivers side of the assembly has been pulled back to expose the bent rack gear.*

#### CASE OF THE MONTH (Cont'd)

Mr. Joseph Pettinato of Pettinato's Body Shop Inc. in Sacramento, California, sent in the 1972 Ford Pinto steering assembly with the broken rack gear. Mr. Pettinato reported that this 1972 Ford Pinto ran off the roadway and into a field. He was uncertain as to whether the steering gear broke before or after the vehicle left the roadway.



*Broken rack gear on rack and pinion steering assembly from a 1972 Ford Pinto*

Reports of bent Pinto rack and pinion steering gear assemblies have also been received from some of our other team members. Mr. Glen Templeton of T&T Service Center in Detroit, Michigan, reported that he had encountered two Ford Pintos with bent rack gears. He noted that the rack gear was bent downward on both vehicles. In both instances this was purported to have been the result of the vehicle hitting a chuckhole. Other shops which have reported bent Ford Pinto rack gears include Frank's Auto Repair in West Middlesex, Pennsylvania, City Foreign Car Parts and Service in North Hollywood, California, and Mandt Brake Service in Rockford, Illinois.

Failures of this type, on Ford Pinto steering systems, are very important and we would like to obtain the failed parts and learn more about this problem. If the components are too large for a mailbag, please call us collect so that special shipping arrangements can be made □

#### CASE NO. C4-09

This case involves the investigation of alleged rear wheel lockup, under normal brake operation, on vehicles equipped with front disc brakes. The vehicles are 1967-1972 Plymouth Valiant and Dodge Dart models. You have probably seen this case listed on the monthly list of current National Highway Traffic Safety Administration defect investigations.

Case No. C4-09 has been selected as our case of the month for the August Newsletter. Anyone

having information relative to this case, please send it to U.S. Department of Transportation, c/o Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention Mr. Bruce E. Beddow.

Last month one of our PRP shops, Dave Kyle's Garage, Phoenix, Arizona, reported a serious accident, due to rear wheel lockup, which involved a 1974 Dodge Dart □

#### ADMINISTRATOR'S AWARD

Last year the Administrator of the National Highway Traffic Safety Administration awarded Certificates of Appreciation to 12 shops for their outstanding PRP participation over a period of one year (submittal of 20 or more safety-related, failed parts). This year there are six shops de-

serving of this award. These will be highlighted in an upcoming issue of the PRP News.

We are now into a new year — our goal is to triple the number of PRP shops that are worthy of the Administrator's Award. We can meet this goal only through your cooperation □

## OUTSTANDING SHOPS

In the past, only shops which have contributed a certain number of parts for a specific period of time were highlighted in this article. We want to approach this subject in a different manner by naming in our publication all shops which send in parts on a monthly basis. We anticipate in the near future the implementation of summaries by state and region which will indicate the level of participation in the PRP across the country. Other ideas are still in the planning stages, so if you have a comment, send us a note.

Our outstanding shops for the month of July are:

### REGION 0

WAYNE'S CITGO  
Shelburne, Vt.

### REGION 1

ALEX'S SERVICE CENTER, INC.  
Trenton, N.J.

SYSTEM BRAKE SERVICE  
Perth Amboy, N.J.

PHILADELPHIA MOTORS  
Philadelphia, N.Y.

FERINO BROTHERS EXXON  
Festerville, Penna.

D&Z ATLANTIC  
Cornwells Heights, Penna.

### REGION 2A (VA., N.C., & S.C.)

GROSS'S UNION 76 SERVICECENTER  
Salem, Va.

JACK STOLTZ'S GARAGE  
Winston-Salem, N.C.

MUSTEN AUTO SERVICE  
Winston-Salem, N.C.

### REGION 5

FELD GARAGE, INC.  
Kenosha, Wis.

JOE'S AUTO SERVICE  
Appleton, Wis.

ADE & BOB'S MUFFLER AND BRAKE  
CENTER  
St. Paul, Minn.

YEARIAN'S TIRE INC.  
W. Des Moines, Iowa

### REGION 6

DICK JORDAN  
STANDARD SERVICE STATION  
Clayton, Mo.

ADAMS MOTOR SERVICE  
St. Charles, Mo.

### REGION 7

ADOLPH'S GARAGE  
Corpus Christi, Texas

### REGION 8

HURLEY SUPER SERVICE STATION  
Pueblo, Colo.

### REGION 9

B&E AUTOMOTIVE  
Tacoma, Wash.

### REGION 9A (CALIFORNIA)

TONY'S AUTO REPAIR  
San Francisco, Calif.

VANOWEN BRAKE & WHEEL  
N. Hollywood, Calif.

MIDWAY AUTO SERVICE  
Midway City, Calif.

RON'S AUTOMOTIVE REPAIRS  
Fresno, Calif.

J&J MUFFLERS, INC.  
Inglewood, Calif.

## MAILBAGS TO BE READDRESSED

The transition of PRP operational support to Kappa Systems, Inc. (KSI), requires that the address currently on your mailbags be changed. KSI is in the process of accomplishing this task and your old mailbags are needed. Please expedite the return of the mailbags as requested in your NHTSA letter in order to prevent a slow down in the flow of failed parts □

## KAPPA SYSTEMS, INC.

Commencing 1 July 1975 Kappa Systems, Inc., of Arlington, Virginia, assumed responsibility for the operational support of the PRP. Kappa Systems, Inc. (KSI), is a diversified professional services company organized in 1963. KSI's only business is providing high quality consulting and support services to government, industry, national non-profit associations, and private community organizations. Prior to beginning work on the Parts Return Program, KSI personnel have had extensive experience over the past 6 years working with the Office of Defects Investigation and the Office of Standards Enforcement within the National Highway Traffic Safety Administration in the area of program development and operation.

KSI's main office is located at 1501 Wilson Boulevard, Arlington, Virginia, in the Rosslyn area just across the Theodore Roosevelt Bridge from the District of Columbia. Our Arlington office encompasses 24,000 square feet on two adjacent floors, approximately 80% of which is devoted to private offices for members of the professional


staff. It is in these offices that the KSI Parts Return Program team members are located.

KSI has Regional Offices in Pennsylvania, Illinois, Colorado, and Washington. Similarly, KSI maintains smaller branch offices in Maine, Florida, Georgia, Arkansas, Wisconsin, and California. In order to utilize this national distribution for PRP support, KSI divided the country into 10 geographic regions. In each region they have appointed a PRP Regional Representative.

The PRP Regions that have been established and their PRP Regional Representatives are identified on the map which follows. The objective of the Regional Representative concept for the PRP operations is to maintain an information feedback loop from you to us and back to you again.

These Regional Representatives will be calling you in the near future. If you have suggestions on how to improve the program, please pass on the information to these individuals □

# NATIONAL PARTS RETURN PROGRAM REGIONAL OFFICES



## TELEPHONE CALLS

If you have any problems regarding this program, are in need of additional mailbags, tags, etc., have questions which need answers, or would like to pass on comments please call us collect. Place your call to Bruce Beddow or Guy Whiddon at (703) 527-4500. We are on Eastern Daylight Savings Time and are normally available Monday through Friday from 8:30 a.m. to 5:30 p.m. Likewise, if you have a contribution or suggestion for the PRP News, please send it to Kappa Systems, Inc., 1501 Wilson Boulevard, Arlington, Virginia 22209, Attention: Bruce E. Beddow □

## NATIONAL PARTS RETURN PROGRAM DESCRIPTION AND FUNCTION

- The PRP involves the voluntary submittal by independent repair shops of failed automotive components. Components are submitted to a representative (Kappa Systems, Inc.) of the National Highway Traffic Safety Administration (NHTSA).
- The purpose of the PRP is to gather information on these components to help the NHTSA identify the existence of safety-related, manufacturing defects in design, materials, construction, or performance of motor vehicles and motor vehicle equipment. Under the authority of National Traffic and Motor Vehicle Safety Act of 1966, and Amendments to the Act in 1975 the NHTSA can require manufacturers to conduct safety defect notification campaigns when it has been determined that a defect relating to motor vehicle safety exists.
- The information obtained from these parts is also valuable in preparing Federal motor vehicle safety standards.

Your shop can help. The parts that you send in will give us vital information that cannot be obtained in any other way □

**PARTS RETURN PROGRAM**  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209





U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

INITIAL CONTACT  
ATTACHMENT 1

PARTS RETURN PROGRAM

REPLY TO:

U.S. Department of Transportation  
c/o KAPPA Systems, Inc.  
1501 Wilson Blvd.  
Arlington, Va. 22209  
(703) 527-4500

Date \_\_\_\_\_

SHOP QUESTIONNAIRE

Shop Name \_\_\_\_\_

Address \_\_\_\_\_

City & State \_\_\_\_\_ Zip Code \_\_\_\_\_

Phone No. Area Code \_\_\_\_\_

Owner or Manager \_\_\_\_\_

Number of Bays or Stalls \_\_\_\_\_

Brake Repair: Yes \_\_\_\_\_ No \_\_\_\_\_

Other systems which are repaired here: Steering \_\_\_\_\_ Suspension \_\_\_\_\_

Towing Service: Yes \_\_\_\_\_ No \_\_\_\_\_

Other Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Region # \_\_\_\_\_

Signed: \_\_\_\_\_

11



U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
WASHINGTON, D.C. 20590

JUN 27 1975

IN REPLY REFER TO:  
181.S:N41-62 wo

Dear Sir:

With this letter we would like to inform you that this office has recently employed the services of Kappa Systems, Inc., of Arlington, Virginia, to replace General Environments Corporation of Morton Grove, Illinois, as our primary contractor in support of the National Highway Traffic Safety Administration "Parts Return Program" (PRP).

During the next 30 days you will receive three (3) new parts return mailbags with Kappa's address imprinted on them. Please fill one bag with your older mailbags and return to Kappa, keeping two for returning parts. The older bags you send to Kappa will be returned to you shortly with the new address.

Kappa has appointed a local PRP representative for your geographic region. His name, address, and telephone number will be provided to you in the near future. Meanwhile, please contact (collect) Messrs. Bruce Beddow or Guy Whiddon at (703) 527-4500 if you need assistance.

We believe the PRP is a valuable tool in helping us to identify the existence of safety-related manufacturing defects in motor vehicles. The year ending this June 30, 1975, will be a success for the PRP in the number of parts returned. With your continued assistance and active participation, the year ending June 30, 1976, will be an even greater success.

Thank you for your patience in this transition. We are looking forward to your continued support in the program to help us improve motor vehicle safety.

Sincerely,

Andrew G. Detrick  
Director  
Office of Defects Investigation  
Motor Vehicle Programs



U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
WASHINGTON, D.C. 20590

JUL 07 1975

IN REPLY REFER TO:  
181.S:N41-62 WO

Dear Sir:

With this letter we would like to inform you that this office has recently employed the services of Kappa Systems, Inc., of Arlington, Virginia, to replace General Environments Corporation of Morton Grove, Illinois, as our primary contractor for the National Highway Traffic Safety Administration "Parts Return Program" (PRP).

In support of this transition we ask that you place all of your existing PRP mailbags into one of the bags, and then drop it in the mail. In this way the mailbags will be forwarded to Kappa Systems so that they can change the address that is imprinted on the bags. Once this has been accomplished they will return the mailbags to you with the new address. Your prompt response to this request will be greatly appreciated.

Kappa Systems has appointed a local PRP representative for your geographic region. His name, address, and telephone number will be provided to you in the near future. Meanwhile, please contact (collect) Messrs. Bruce Beddow or Guy Whiddon at (703) 527-4500 if you need assistance.

We believe the PRP is a valuable tool in helping us to identify the existence of safety-related manufacturing defects in motor vehicles. The year ending this June 30, 1975, will be a success for the PRP in the number of parts returned. We want to solicit your active participation in the program by sending in a possible safety-related and defective part. We believe that with your active support, the year ending June 30, 1976, will be an even greater success.

Thank you for your patience in this transition. We are looking forward to your active participation in the program to help us improve motor vehicle safety.

Sincerely,

Andrew G. Detrick, Director  
Office of Defects Investigation  
Motor Vehicle Programs



ATTACHMENT 3

U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
WASHINGTON, D.C. 20590

JUN 30 1975

IN REPLY REFER TO:  
181. S: N41-62 wo

Postmaster  
United States Post Office  
Morton Grove, Illinois 60053

Dear Sir:

This is to confirm the telephone conversation on June 24, 1975, between the Superintendent of your Post Office and Mr. Gary R. Woodford of my staff.

For the past several years General Environments Corporation of Morton Grove, Illinois, has been under contract with us to conduct our Parts Return Program. As you know, this program involves receipt of failed automotive components through the mail. The components are submitted voluntarily by independent repair shops, and the information gained from them helps us to identify the existence of safety-related, manufacturing defects in motor vehicles and motor vehicle equipment.

However, on June 30, 1975, our contract with General Environments Corporation expires. Effective July 1, 1975, our new contractor for this Program is Kappa Systems, Inc., of Arlington, Virginia. Accordingly, we request that the components and other mail that you receive after June 30, 1975, concerning our Parts Return Program, be forwarded to Kappa Systems, Inc. For your convenience we have listed below the new and old addresses effective July 1, 1975.

New Address

Old Address

Department of Transportation  
c/o Kappa Systems, Inc.  
1501 Wilson Boulevard  
Arlington, Virginia 22209

Department of Transportation  
c/o General Environments Corp.  
7845 Nagle Avenue  
Morton Grove, Illinois 60053

In the meantime, during this Program transition period, we would like to assure you that every effort will be made by Kappa Systems and us to notify the participating shops of this change immediately. Kappa Systems has already prepared a process for changing the General Environments Corporation address that is on the canvas mailbags used by shops to return failed components.

Thank you for your cooperation both now and over the past several years. If there are any questions concerning this matter, please contact Mr. Gary R. Woodford of my staff at (202) 426-2840.

Sincerely,

ORIGINAL SIGNED BY  
A. G. DETRICK

Andrew G. Detrick  
Director  
Office of Defects Investigation  
Motor Vehicle Programs

cc:

Mr. Herbert C. Wolf  
General Environments Corporation

✓ Mr. Bruce Beddow  
Kappa Systems, Inc.



**U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION**

\*\*\*\*\*

**CERTIFICATE OF PARTICIPATION**

**THIS IS TO CERTIFY THAT**

**IS ACTIVELY PARTICIPATING TO IMPROVE  
MOTOR VEHICLE SAFETY THROUGH COOPERATION IN THE**

**NATIONAL PARTS RETURN PROGRAM**

**FOR THE YEARS: 1975-1976**

**ISSUED BY:**

**PROGRAM MANAGER**

**CONTRACT NO. DOT-HS-5-01166**

PARTS RETURN PROGRAM

76/04/12 PAGE 0001

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
01 TO 31 MARCH 76

SORTED BY COMPONENT, MODEL, POL YR

| BIN NUMBER | PRP NUMBER | DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                                 | MAKE-MODEL            | FAULT HAZ. CODE CAT. | MILEAGE AT FAILURE | SHOP NUMBER |
|------------|------------|---------------|-----------------|----------------------------------------------------------------|-----------------------|----------------------|--------------------|-------------|
| 30025      | P01251 B   | 760306        | 01140           | STEERING COLUMN LOCKING-ANTI-THEFT DEVICE<br>69 155 VOLKSWAGEN | R3 SQUAREBACK SEDAN   | 03 C                 | C00000             | 94101002    |
| 30029      | P01304 B   | 760306        | 01220           | POWER STEERING GEAR BOX<br>72 C42 CHEVROLET DIVISION           | C4 NOVA               | 28 A                 | 033544             | 94101002    |
| 30021      | P01269 B   | 760306        | 01222           | POWER STEERING SHAFT-SECTOR<br>73 C42 CADILLAC DIVISION        | 02 FLEETW00D          | 03 B                 | 019939             | 63105001    |
| 40002      | P01333 B   | 760320        | 01330           | STEERING POWER ASSIST-HOSE,FLUID<br>65 C21 CHRYSLER DIVISION   | 01 CHRYSLER 4 D       | 32 C                 | 079444             | 30501001    |
| 30026      | P01300 B   | 760306        | 01330           | STEERING POWER ASSIST-HOSE,FLUID<br>67 C23 PLYMOUTH            | 01 BAPRACUDA          | 08 C                 | 061976             | 06120003    |
| 40006      | P01385 B   | 760330        | 01330           | STEERING POWER ASSIST-HOSE,FLUID<br>76 C33 MERCURY             | 04 MERCURY            | 21 C                 | 024000             | 19802003    |
| 40001      | P01332 B   | 760320        | 01510           | STEERING LINKAGES-APM,PITMAN<br>75 C23 PLYMOUTH                | 04 FURY<br>POLICE SPC | 57 C                 | 019168             | 01605008    |
| 50001      | P01435 B   | 760331        | 01530           | STEERING LINKAGES-APM, IDLER AND ATTACHMEN<br>CC C0C UNKNOWN   | 00 UNKNOWN            | 57 C                 | C0C000             | 60626008    |
| 50001      | P01433 B   | 760331        | 01530           | STEERING LINKAGES-APM, IDLER AND ATTACHMEN<br>00 C0C UNKNOWN   | 00 UNKNOWN            | 53 C                 | 000000             | 60626008    |

STIFF MOVEMENT IN BALL STUD SOCKET



## PARTS RETURN PROGRAM

76/04/12 PAGE 0002

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX

SORTED BY COMPONENT, MCOEL, FCL YR

01 TO 31 MARCH 76

| BIN NUMBER                                                             | PRP I<br>NUMBER | CATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                       | MAKE-MODEL            | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|------------------------------------------------------------------------|-----------------|------------------|--------------------|-------------------------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 50001                                                                  | P01434 B        | 760331           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>CC CCC UNKNCHN            | 00 UNKNCHN            | 53 C                    | 000000                | 60626008       |
| STIFF MOVEMENT IN BALL STUD SOCKET-TAG NOT READABLE                    |                 |                  |                    |                                                                         |                       |                         |                       |                |
| 40003                                                                  | P01371 B        | 760330           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>68 C31 FCRO DIVISION      | 03 FCRO               | 03 C                    | 062452                | C2140002       |
| IDLER ARM BRACKET PECKEN WPIRE IT ATTACHES TO FRAME                    |                 |                  |                    |                                                                         |                       |                         |                       |                |
| 40004                                                                  | P01373 B        | 760330           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>68 C31 FCRO DIVISION      | 03 FCRO               | 03 C                    | 074932                | 02140002       |
| IDLER ARM BRACKET IS BROKEN AT AREA WHERE ATTACHED TO FRAME            |                 |                  |                    |                                                                         |                       |                         |                       |                |
| 40002                                                                  | P01327 B        | 760324           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>74 C31 FCRO DIVISION      | 5A FCRO TRUCK AND VAN | 03 C                    | 025588                | 53511008       |
| BRACKET BROKE AT 90 DEGREE BEND, IRON PIECE CRACKED IN TWO-SHAFT CK    |                 |                  |                    |                                                                         |                       |                         |                       |                |
| 40001                                                                  | P01324 B        | 760320           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>65 043 CHEVROLET DIVISION | F3 IMPALA             | 21 C                    | 058000                | 06114008       |
| ARM SEPARATED FROM BRACKET, EXCESS WEAR, LITE RUST AT JOINT            |                 |                  |                    |                                                                         |                       |                         |                       |                |
| 40003                                                                  | P01346 B        | 760324           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>71 C42 CHEVROLET DIVISION | 02 CHEVELLE           | 08 C                    | 054640                | 66032002       |
| METAL CRACKED AT LOWER BODY HOLE ON MTG BRKT SOME WEAR AT IDLER JOINT  |                 |                  |                    |                                                                         |                       |                         |                       |                |
| 40001                                                                  | P01325 B        | 760320           | 01530              | STEERING LINKAGES-ARM, IDLER AND ATTACHMEN<br>65 043 CHEVROLET DIVISION | 03 CHEVROLET          | 21 C                    | 060000                | 06114008       |
| EXCESS WEAR AT JOINT NO EVIDENCE OF LUBE-IDLER ARM SEP FROM BRACKET    |                 |                  |                    |                                                                         |                       |                         |                       |                |
| 50001                                                                  | P01424 B        | 760331           | 01560              | STEERING LINKAGES-TIE ROD, END<br>CC CCC UNKNCHN                        | 00 UNKNCHN            | 57 C                    | 000000                | 60626008       |
| BALL STUD SOCKET ONLY BALL IS WORN APPAR SEP FROM TIE-ROD-BODY         |                 |                  |                    |                                                                         |                       |                         |                       |                |
| 50001                                                                  | P01422 B        | 760331           | 01560              | STEERING LINKAGES-TIE ROD, END<br>00 000 UNKNCHN                        | 00 UNKNCHN            | 57 C                    | 000000                | 60626008       |
| EXCESS WEAR IN BALL STUD SOCKET EVIDENCE OF LACK OF LUBE TAG NOT LEGBL |                 |                  |                    |                                                                         |                       |                         |                       |                |

# PARIS RETURN PROGRAM

76/04/12 PAGE 0003

OFFICE OF EFFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
01 TO 31 MARCH 76

SORTED BY COMPONENT, MODEL, YR

| BIN NUMBER | PRP I<br>NUMBER | CATF<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                       | MAKE-MODEL  | FALLT HAZ.<br>CCTE CAT. | MILEAGE<br>AT FAILURE | SHCP<br>NUMBER |
|------------|-----------------|------------------|--------------------|----------------------------------------------------------------------|-------------|-------------------------|-----------------------|----------------|
| 50001      | P01418 B        | 760331           | 01560              | STEERING LINKAGES-TIE ROD, FNC<br>00 CCC LAKNCWN                     | 00 UNKNCHN  | 57 C                    | 000000                | 60626008       |
|            |                 |                  |                    | VERY SLIGHT WEAR IN BALL STUD SOCKET TAG NOT READABLE                |             |                         |                       |                |
| 50001      | P01419 B        | 760331           | 01560              | STEERING LINKAGES-TIF ROD, FNC<br>00 CCC UNKNOWN                     | 00 UNKNCHN  | 57 C                    | 000000                | 60626008       |
|            |                 |                  |                    | SLIGHT WEAR IN BALL STUD SOCKET TAG NOT READABLE                     |             |                         |                       |                |
| 50001      | P01420 B        | 760331           | 01560              | STEERING LINKAGES-TIE ROD, FNC<br>CC C00 LAKNCWN                     | 00 UNKNCHN  | 57 C                    | 000000                | 60626008       |
|            |                 |                  |                    | EXCESS WEAR IN BALL STUD SOCKET EVIDENCE OF LACK OF LUBE TAG NOT LEG |             |                         |                       |                |
| 50001      | P01421 B        | 760331           | 01560              | STEERING LINKAGES-TIE ROD, FNC<br>CC C00 UNKNOWN                     | 00 UNKNCHN  | 57 C                    | 000000                | 60626008       |
|            |                 |                  |                    | WEAR IN BALL STUD SOCKET TAG NOT READABLE                            |             |                         |                       |                |
| 50001      | P01423 B        | 760331           | 01560              | STEERING LINKAGES-TIF ROD, FNC<br>CC C00 LAKNCWN                     | 00 UNKNCHN  | 57 C                    | 000000                | 60626008       |
|            |                 |                  |                    | EXCESS WEAR IN STUD SOCK TIE-ROD APPAR CUT W/TOUCH TAG NOT READABLE  |             |                         |                       |                |
| 40001      | P01329 D        | 760320           | 01560              | STEERING LINKAGES-TIF ROD, FNC<br>65 C23 PLYMOUTH                    | C4 FURY III | 57 C                    | 001823                | 66032002       |
|            |                 |                  |                    | SOCKET HAS SOME WEAR DUE TO CRACKED GREASE BOOT-PLUG STILL IN PLACE  |             |                         |                       |                |
| 40001      | P01329 C        | 760320           | 01560              | STEERING LINKAGES-TIE ROD, FNC<br>69 C23 PLYMOUTH                    | C4 FURY III | 08 C                    | 001823                | 66032002       |
|            |                 |                  |                    | SOCKET HAS SOME WEAR GREASE BOOT CRACKED-GREASE PLUG STILL IN PLACE  |             |                         |                       |                |
| 40001      | P01329 B        | 760320           | 01560              | STEERING LINKAGES-TIE ROD, FNC<br>65 C23 PLYMOUTH                    | C4 FURY III | 21 C                    | 001823                | 66032002       |
|            |                 |                  |                    | BALL STUD SEPARATED FROM SOCKET BOOT CRACKED NO LUBE EVIDENT         |             |                         |                       |                |
| 40001      | P01329 E        | 760320           | 01560              | STEERING LINKAGES-TIF ROD, FNC<br>65 C23 PLYMOUTH                    | C4 FURY III | 08 C                    | 001823                | 66032002       |
|            |                 |                  |                    | BALL STUD SOCKET HAS SOME WEAR GREASE BOOT SPLIT-PLUG STILL IN PLACE |             |                         |                       |                |

PARTS RETURN PROGRAM

OFFICE OF DEFENSE INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX

76/04/12 PAGE 0004

01 TO 31 MARCH 76  
SORTED BY CCMFCNENT,MODEL,POL YR

| BIT<br>NUMBER | PPP<br>NUMBER | I<br>DATE | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                                                   | MAKE-MODEL            | FAULT HAZ.<br>CCDE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------|--------------------|-------------------------------------------------------------------------------------|-----------------------|-------------------------|-----------------------|----------------|
| 40008         | P01338 B      | 760324    | 01580              | STEERING LINKAGES-KNUCKL-SFINDL-ARM<br>66 IIC INTERNATIONAL HARVESTER<br>LDSTAR1600 | 11 INTERNATIONAL TRUC | C3 C                    | C64000                | 98134058       |
| 30029         | P01308 P      | 760306    | 01580              | SPINDLE BECKE OFF NEAR BASE BOTH BEARING RACES LEFT WEAR MARKS CN SPIN              |                       | 03 C                    | 058674                | 03102004       |
| 50001         | P01425 B      | 760331    | 02132              | STEERING LINKAGES-KNUCKL-SFINDL-ARM<br>68 043 CHEVPOLET DIVISION                    | -E3 IMPALA            |                         |                       |                |
| 50001         | P01428 B      | 760331    | 02132              | SPINDLE BECKE ACROSS DIAMETER AT BEARING - WHEEL BEARING FRCZE                      |                       |                         |                       |                |
| 50001         | P01427 B      | 760331    | 02132              | SUSP.N.INCP.FT. CTRL ARM UNK TYP-BALL JCIN<br>00 CCC UNKNOWN                        | 00 UNKNOWN            | 57 C                    | 000000                | 60626008       |
| 50001         | P01426 B      | 760331    | 02132              | EXCES WEAR IN BALL STUD SOCK-NO LUBE EVIDENT-GREASE BOOT CRACKED                    |                       |                         |                       |                |
| 50001         | P01432 B      | 760331    | 02132              | SUSP.N.INCP.FT. CTRL ARM UNK TYP-BALL JCIN<br>00 CCC UNKNOWN                        | 00 UNKNOWN            | 57 C                    | 000000                | 60626008       |
| 50001         | P01429 B      | 760331    | 02132              | EXCESSIVE WEAR IN BALL STUD SOCKET-EXCESSIVE VERTICAL MOVEMENT                      |                       |                         |                       |                |
| 50001         | P01431 B      | 760331    | 02132              | SUSP.N.INCP.FT. CTRL ARM UNK TYP-BALL JCIN<br>00 CCC UNKNOWN                        | 00 UNKNOWN            | 57 C                    | 000000                | 60626008       |
| 50001         | P01426 B      | 760331    | 02132              | EXCESS VERTICAL MOVEMENT IN BALL STUD SOCKET TAG NOT READABLE                       |                       |                         |                       |                |
| 50001         | P01427 B      | 760331    | 02132              | SUSP.N.INCP.FT. CTRL ARM UNK TYP-BALL JCIN<br>00 CCC UNKNOWN                        | 00 UNKNOWN            | 57 C                    | 000000                | 60626008       |
| 50001         | P01428 B      | 760331    | 02132              | SLIGHT WEAR IN BALL STUD SOCKET-GREASE BOOT CRACKED                                 |                       |                         |                       |                |
| 50001         | P01429 B      | 760331    | 02132              | SUSP.N.INCP.FT. CTRL ARM UNK TYP-BALL JCIN<br>00 CCC UNKNOWN                        | 00 UNKNOWN            | 57 C                    | 000000                | 60626008       |
| 50001         | P01430 B      | 760331    | 02132              | EXCESSIVE VERTICAL MOVEMENT IN BALL STUD SOCKET                                     |                       |                         |                       |                |
| 50001         | P01431 B      | 760331    | 02132              | SUSP.N.INCP.FT. CTRL ARM UNK TYP-BALL JCIN<br>00 CCC UNKNOWN                        | 00 UNKNOWN            | 57 C                    | 000000                | 60626008       |
| 50001         | P01432 B      | 760331    | 02132              | EXCESSIVE PLAY IN BALL STUD SOCKET-EXCESS VERTICAL PLAY-NO EVIC CF LUB              |                       |                         |                       |                |
| 50001         | P01433 B      | 760331    | 02132              | SUSP.N.INCP.FT. CTRL ARM UNK TYP-BALL JCIN<br>00 CCC UNKNOWN                        | 00 UNKNOWN            | 57 C                    | 000000                | 60626008       |
| 50001         | P01434 B      | 760331    | 02132              | EXCESS WEAR IN BALL STUD SOCKET,VERTICAL PLAY-GREASE RET PCCT CRACKED               |                       |                         |                       |                |

## PARTS RETLRA PROGRAM

76/04/12 PAGE 0005

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
01 TO 31 MARCH 76

SORTED BY COMPONENT, MODEL, MCL YR

| RIN<br>NUMBER | PPF<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                          | MAKE-MODEL                     | FALLT HAZ-<br>CCCE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|-------------------------------------------------------------------------|--------------------------------|-------------------------|-----------------------|----------------|
| 50001         | P01430 B      | 760331                | 02132              | SUSP.N-INCF.FT. CTRL ARM UNK TYP-BALL JCINT<br>00 C00 UNKNOWN           | 00 UNKNOWN                     | 57 C                    | 000000                | 0626008        |
|               |               |                       |                    | EXCESS WEAR IN BALL STUC SOCKET, VERTICAL PLAY-GREASE RET BOOT CRACKED  |                                |                         |                       |                |
| 40003         | P01362 B      | 760329                | 02140              | SUSP.N-INCF.FT. CCNTRCL ARM, UPPER<br>71 C10 AMERICAN MOTORS            | 01 AMBASSADOR                  | 08 C                    | 058000                | 53140014       |
|               |               |                       |                    | BOIP SIDES OF CCNTRCL ARM CRACKED AT AREA CONNECTED TO FRAME            |                                |                         |                       |                |
| 40001         | P01326 B      | 760320                | 02142              | SUSP.N-INCF.FT. CTPL ARM UPPER-BALL JCINT<br>70 C22 PLYMOUTH            | 06 VALIANT                     | 21 C                    | 026000                | 06114008       |
|               |               |                       |                    | BALL STUC SEP FROM SOCKET FTM PLATE OF JCINT MISS - NO LUBE EVIDENT     |                                |                         |                       |                |
| 40009         | P01417 B      | 760331                | 02150              | SUSP.N-INCF.FT. CCNTRCL ARM-LCWER<br>00 C00 UNKNOWN                     | 00 UNKNOWN                     | 03 C                    | 000000                | 0626008        |
|               |               |                       |                    | LWR CCNTRCL ARM BROKE IN HALF ACROSS WIDTH-AC HEAVY RUST EVIDENT        |                                |                         |                       |                |
| 40005         | P01381 B      | 760330                | 02150              | SUSP.N-INCF.FT. CCNTRCL ARM-LCWER<br>74 C21 CHRYSLER DIVISION           | 02 IMPERIAL                    | 03 C                    | 035435                | 94117018       |
|               |               |                       |                    | CCNTRCL ARM BROKEN AT BALL JOINT-RELEASEING JCINT                       |                                |                         |                       |                |
|               | P01232 B      | 760306                | 02150              | SUSP.N-INCF.FT. CCNTRCL ARM-LCWER<br>69 045 PONTIAC DIVISION            | 84 LE MANS                     | 03 C                    | 000000                | 52205033       |
|               |               |                       |                    | PART NOT AVAIL - BALL JCINTS WERE REPLACED IN 6/75 POSS EXCESS STRESS   |                                |                         |                       |                |
|               | P01261 B      | 760329                | 02152              | SUSP.N-INCF.FT. CTRL ARM, LCWER-BALL JCINT<br>71 C10 AMERICAN MOTORS    | 06 JAVELIN                     | 57 C                    | 000000                | 53140014       |
|               |               |                       |                    | EXCESSIVE WEAR ON LCWER BALL JOINT                                      |                                |                         |                       |                |
| 40005         | P01360 B      | 760330                | 02152              | SUSP.N-INCF.FT. CTRL ARM, LCWER-BALL JCINT<br>69 042 CHEVROLET DIVISION | 01 CAMARO                      | 03 C                    | 030000                | 01851013       |
|               |               |                       |                    | THREADED SECTION OF BALL JOINT USED TO SECURE TO LCWER A FRAME BRCKE    |                                |                         |                       |                |
| 40002         | P01344 B      | 760324                | 02240              | SUSP.N-I BEAM, SLD, FT: SHOCK ABSORBER<br>74 C22 CCCGE                  | 9A CCCGE TRUCK AND VA<br>D-300 | 32 C                    | 002714                | 02140002       |
|               |               |                       |                    | SHOCK LEAKS FLUID                                                       |                                |                         |                       |                |

PARTS RETURN PROGRAM

76/04/12 PAGE 0006

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
01 TO 31 MARCH 76

SORTED BY COMPONENT, MODEL, YR

| BIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                    | MAKE-MODEL                                                                               | FAULT HAZ-<br>CODE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|---------------|---------------|-----------|--------------------|-------------------------------------------------------------------|------------------------------------------------------------------------------------------|-------------------------|-----------------------|----------------|
| 40010         | P01348 B      | 760324    | 02450              | SUSPN-SGL AXL R-SPRING, COILCATTACHMENTS<br>71 C31 FORD DIVISION  | H3 FORD-GALAXIE 500                                                                      | 02 C                    | 000000                | 36104001       |
| 40010         | P01407 B      | 760331    | 02450              | SUSPN-SGL AXL R-SPRING, COILCATTACHMENTS<br>74 C32 MERCURY        | COIL SPRING BROKE IN TWO PIECES NEAR CENTER OF COILS<br>05 MCNTEGG                       | 02 C                    | 011205                | 12601050       |
| 40010         | P01407 C      | 760331    | 02450              | SUSPN-SGL AXL R-SPRING, COILCATTACHMENTS<br>74 C32 MERCURY        | COIL SPRING BROKE AT END LIGHT LAYER OF RLST ON SPRING<br>05 MCNTEGG                     | 03 C                    | 011205                | 12601050       |
| 40010         | P01327 B      | 760320    | 02450              | SUSPN-SGL AXL R-SPRING, COILCATTACHMENTS<br>75 C41 BUICK          | CCIL SPRING BROKE AT END LIGHT LAYER OF RLST ON SPRING<br>04 LE SABRE                    | 03 C                    | 014692                | 36104001       |
| 40010         | P01335 B      | 760324    | 02620              | WHEELS, SINGLE<br>76 C42 CADILLAC DIVISION                        | REAR CCIL SPRING CRACKED AND BROKEN NEAR END<br>B1 CADILLAC-DE VILLE                     | 02 E                    | 000000                | 63105001       |
| 40001         | P01318 B      | 760320    | 03221              | BRKS-HYDRAULIC-PWR ASSIST-LINES, VACUUM<br>75 C1C AMERICAN MOTORS | CRACK AROUND 2/3 CIRC OF WIRE WHEEL CENTER DISCCRACK AT WELC AT 60MPH<br>0A PACER        | 04 C                    | 000000                | 90027113       |
| 40002         | P01341 B      | 760324    | 03221              | BRKS-HYDRAULIC-PWR ASSIST-LINES, VACUUM<br>65 C32 MERCURY         | 5116" PCSE-DETERIORATED AT ONE END<br>E4 MERCURY-MCINTEREY                               | 45 C                    | 056000                | 52632025       |
| 40004         | P01397 B      | 760331    | 03223              | BRKS-HYDRAULIC-PWR ASSIST-CHECK VALVE<br>67 C31 FORD DIVISION     | SCME DETECTION INSIDE POSE - PCSE SPLIT LENGTHWISE FOR INSPECTION<br>H3 FORD-GALAXIE 500 | 03 C                    | 067313                | 63301003       |
| 40007         | P01402 B      | 760331    | 03230              | BRKS-HYDRAULIC-PWR CYL<br>71 C1C AMERICAN MOTORS                  | SMALL CONNECTOR BROKEN OFF-LARGER HOSE IS INTACT, BLT HARD WITH AGE<br>06 JAVELIN        | 28 C                    | 044496                | 63105001       |

PRCEABLE INTERNAL MALFUNCTION-RESERVICIR DIRTY-CONTAMINATED-NO VISABLE

PARTS RETURN PROGRAM

76/04/12 PAGE 0007

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
C1 TO 31 MARCH 76

SORTED BY COMPONENT, MODEL, PCL YR

| BIN NUMBER                                                       | PPP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                                            | YR | MANUFACTURER | MAKE-MODEL         | FALLT HAZ. CCDE CAT. | HAZ. AT FAILURE | SPCP NUMBER     |
|------------------------------------------------------------------|------------|-----------------|-----------------|---------------------------------------------------------------------------|----|--------------|--------------------|----------------------|-----------------|-----------------|
| 40006                                                            | P01364 B   | 760331          | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>65 C21 CHRYSLER DIVISION                       |    |              | D1 300             | 44                   | C               | 061930 63105001 |
| PCSS INTERNAL LEAKAGE BTWN CYL WALL & PISTONS NO VISABLE DEFECTS |            |                 |                 |                                                                           |    |              |                    |                      |                 |                 |
| 40006                                                            | P01392 B   | 760331          | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>71 C23 FLYCUTH                                 |    |              | C5 RCJC FLANNER    | 45                   | C               | 000000 25611001 |
| SCPE CCFCSION IS PRESENT CN CYLINDER WALL CF MASTER CYLINDER     |            |                 |                 |                                                                           |    |              |                    |                      |                 |                 |
| 40006                                                            | P01386 B   | 760330          | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>72 C23 FLYCUTH                                 |    |              | P-4 FLY GRAN COLPE | 32                   | C               | 057641 15802003 |
| NO VISABLE DEFECTS, POSS INTERNAL BYPASS                         |            |                 |                 |                                                                           |    |              |                    |                      |                 |                 |
| 30026                                                            | P01307 B   | 760306          | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>65 C23 FLYCUTH                                 |    |              | 04 FURY            | 28                   | C               | 017713 79605020 |
| INTERNAL LEAK, RUSTED                                            |            |                 |                 |                                                                           |    |              |                    |                      |                 |                 |
| 40006                                                            | P01384 B   | 760330          | 03230           | BRKS-HYDRAULIC-MSTR CYL<br>72 C44 CLESMORILE                              |    |              | 02 DELTA 88        | 22                   | C               | 051954 23513001 |
| NO VISABLE DEFECT POSS INTERNAL BYPASS                           |            |                 |                 |                                                                           |    |              |                    |                      |                 |                 |
| 40001                                                            | P01321 B   | 760320          | 03241           | BRKS-HYDRAULIC-LINES, METALLIC<br>70 IIC INTERNATIONAL HARVESTER 12 SCOUT |    |              |                    | 45                   | C               | 065476 61108013 |
| STEEL LINES SEVERELY RUSTED                                      |            |                 |                 |                                                                           |    |              |                    |                      |                 |                 |
| 40001                                                            | P01323 B   | 760320          | 03241           | BRKS-HYDRAULIC-LINES, METALLIC<br>00 C0C UNKNOWN                          |    |              | 00 UNKNOWN         | 10                   | C               | 000000 61108013 |
| NO PARTS-SPCP COMMENTS ON DESIGN CF BRAKE TUBING                 |            |                 |                 |                                                                           |    |              |                    |                      |                 |                 |
| 40001                                                            | P01322 B   | 760320          | 03241           | BRKS-HYDRAULIC-LINES, METALLIC<br>63 C43 CHEVROLET DIVISION               |    |              | 84 CHEVY II        | 49                   | C               | 060630 61108013 |
| STEEL LINES SEVERELY RUSTED                                      |            |                 |                 |                                                                           |    |              |                    |                      |                 |                 |
| 40001                                                            | P01328 B   | 760320          | 03242           | BRKS-HYDRAULIC-LINES-HOSE, NCA-METALLIC<br>73 C22 C00CF                   |    |              | 05 DART            | 08                   | C               | 035489 17701024 |

HOSE CRACKED 3/8" FROM EACH FITTING - CRACKS ARE AROUND CIRCUMFERENCE

PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
C1 TO 31 MARCH 76

76/04/12 PAGE 0008

SORTED BY COMPONENT, MAKE, PCL YR

| BIN NUMBER                                                      | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                          | YR | MANUFACTURER | MAKE | PCL            | FALLT HAZ. CODE | HAZ. CAT. | MIILEAGE AT FAILURE | SHCF NUMBER |
|-----------------------------------------------------------------|------------|-----------------|-----------------|-----------------------------------------|----|--------------|------|----------------|-----------------|-----------|---------------------|-------------|
| 40001                                                           | P01328 C   | 760320          | 03242           | BRKS-HYDRAULIC-LINES-HOSE, NON-METALLIC | 73 | C22 CDDGE    | 05   | CART           | 08              | C         | C354E9              | 17701G24    |
| HOSE CRACKED AROUND CIRCUMFERENCE 3/8" FROM FITTING             |            |                 |                 |                                         |    |              |      |                |                 |           |                     |             |
| 40002                                                           | P01336 C   | 760324          | 03242           | BRKS-HYDRAULIC-LINES-HOSE, NON-METALLIC | 73 | C22 PLYMOUTH | A6   | VALIANT-DUSTER | 32              | C         | 037771              | 14607007    |
| HOSE SEVERED AT BOTH ENDS POSSIBLY DURING REMOVAL               |            |                 |                 |                                         |    |              |      |                |                 |           |                     |             |
| 40002                                                           | P01336 B   | 760324          | 03242           | BRKS-HYDRAULIC-LINES-HOSE, NON-METALLIC | 73 | C22 PLYMOUTH | A6   | VALIANT-DUSTER | 08              | C         | 037771              | 14607007    |
| HOSE CRACKED IN THREE PLACES 1/4"-1/2" FROM BRACKET END FITTING |            |                 |                 |                                         |    |              |      |                |                 |           |                     |             |
| 40002                                                           | P01334 B   | 760309          | 03242           | BRKS-HYDRAULIC-LINES-HOSE, NON-METALLIC | 72 | C22 PLYMOUTH | 06   | VALIANT        | 08              | C         | 086277              | 30501001    |
| RUBBER CRACKED AROUND CIRC. 1/2" FROM METAL JOINT-BOTH ENDS     |            |                 |                 |                                         |    |              |      |                |                 |           |                     |             |
| 40002                                                           | P01334 C   | 760309          | 03242           | BRKS-HYDRAULIC-LINES-HOSE, NON-METALLIC | 73 | C22 PLYMOUTH | 06   | VALIANT        | 08              | C         | 086377              | 30501001    |
| RUBBER SPLIT 360 DEG AROUND CIRC - 3/8" FROM METAL FITTING      |            |                 |                 |                                         |    |              |      |                |                 |           |                     |             |
| 30021                                                           | P01309 B   | 760306          | 03242           | BRKS-HYDRAULIC-LINES-HOSE, NON-METALLIC | 62 | C41 BLICK    | 04   | LE SPARE       | 44              | C         | C52524              | 03102004    |
| HOSE IS OLD & CRACKED - POSS INTERNAL BLOCKAGE                  |            |                 |                 |                                         |    |              |      |                |                 |           |                     |             |
| 30026                                                           | P01297 C   | 760301          | 03264           | BRKS-HYCR-SHCE AND CRUM SYSTEM-DRUM     | 70 | C22 CCCGE    | B5   | DART-SWINGER   | 21              | C         | 047347              | 53140017    |
| HUB SEPARATED FROM CRUM NC EXCESSIVE WEAR ON BEARING RACES      |            |                 |                 |                                         |    |              |      |                |                 |           |                     |             |
| 30027                                                           | P01297 B   | 760301          | 03264           | BRKS-HYCR-SHCE AND CRUM SYSTEM-DRUM     | 70 | C22 CCCGE    | B5   | DART-SWINGER   | 21              | C         | 047347              | 53140017    |
| HUB SEPARATED FROM CRUM MARKS AT INNER BRNG LOCATION ON PUE     |            |                 |                 |                                         |    |              |      |                |                 |           |                     |             |
| 40007                                                           | P01416 B   | 760231          | 03272           | BRKS HYDRAULIC-DISC-PADS AND SHCES      | 00 | 000 UNKNOWN  | 00   | UNKNOWN        | 57              | C         | 000000              | 60626008    |
| EXCESSIVE WEAR ON RIVETED PADS-TAG NOT RELEASABLE               |            |                 |                 |                                         |    |              |      |                |                 |           |                     |             |

FARTS RETURN PROGRAM

76/04/12 PAGE 0009

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
01 TO 31 MARCH 76

SORTED BY COMPONENT, MODEL, PCL YR

| BIN NUMBER | PPP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME MANUFACTURER                                       | MAKE-MODEL        | FALLY HAZ. CCCC CAT. | MILEAGE AT FAILURE | SHOP NUMBER |
|------------|------------|-----------------|-----------------|-------------------------------------------------------------------|-------------------|----------------------|--------------------|-------------|
| 40001      | P01330 B   | 760320          | 03272           | BRKS HYDRAULIC-DISC-PADS AND SHCES 74 C22 LINCOLN                 | A2 PARK IV        | 21 C                 | C23600             | 44110013    |
|            |            |                 |                 | LINING SEPARATED FROM PLATE-LINING CRACKED AT ONE RIVET OTHERS OK |                   |                      |                    |             |
| 40005      | P01379 B   | 760330          | 03272           | BRKS HYDRAULIC-DISC-PADS AND SHCES 73 176 TCYCTA MCTR CO LTC      | 02 TCYCTA COROLLA | 57 C                 | 017000             | C1904029    |
|            |            |                 |                 | PADS WORN TO METAL-CLUTCHPAD IS SCURED ON ONE END                 |                   |                      |                    |             |
| 40005      | P01379 C   | 760330          | 03273           | BRKS HYDRAULIC-DISC-ROTOR-FISC MUR 72 176 TCYCTA MCTR CO LTC      | 02 TCYCTA COROLLA | 50 C                 | C17000             | 01504029    |
|            |            |                 |                 | ROTOR IS SCURED SEVERELY, POSSIBLY RESULT OF WORN PADS            |                   |                      |                    |             |
| 40007      | P01415 B   | 760331          | 05110           | ENGINE MOUNTS 72 021 CHRYSLER DIVISION                            | 81 NEW YORKER     | 03 C                 | 057479             | 60626000    |
|            |            |                 |                 | RUBBER PORTION SEPARATED FROM METAL                               |                   |                      |                    |             |
| 30024      | P01296 B   | 760301          | 05110           | ENGINE MOUNTS 65 C31 FCRD DIVISION                                | C3 FCRD-CUSTOM    | 08 C                 | 041054             | 29611001    |
|            |            |                 |                 | RUBBER SEPARATED FROM METAL                                       |                   |                      |                    |             |
| 40001      | P01331 B   | 760320          | 05110           | ENGINE MOUNTS 70 C31 FCRD DIVISION                                | G3 FCRD-LTD       | 21 C                 | 054823             | 06120003    |
|            |            |                 |                 | RUBBER PORTION OF MOUNT SPLIT AT METAL BASE                       |                   |                      |                    |             |
| 30027      | P01305 C   | 760306          | 05110           | ENGINE MOUNTS 65 C31 FCRD DIVISION                                | 01 FAIRLANE       | 08 C                 | 060000             | 00000000    |
|            |            |                 |                 | RUBBER CRACKED AT BASE WHERE IT MEETS METAL                       |                   |                      |                    |             |
| 30027      | P01305 B   | 760306          | 05110           | ENGINE MOUNTS 65 C31 FCRD DIVISION                                | 01 FAIRLANE       | 03 C                 | 060000             | 00000000    |
|            |            |                 |                 | RUBBER SEPARATED FROM METAL - FAN DAMAGED RADIATOR                |                   |                      |                    |             |
| 40003      | P01347 B   | 760324          | 05110           | ENGINE MOUNTS 68 031 FCFC DIVISION                                | 03 FCRD SUB       | 03 C                 | 068206             | 12601031    |
|            |            |                 |                 | RUBBER PORTION OF MOUNT SEPARATED NEAR JOINT WITH METAL BASE      |                   |                      |                    |             |

PARTS RETLFA PROGRAM

76/04/12 PAGE 0010

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
01 TO 31 MARCH 76

SORTED BY COMPONENT, MODEL, YR

| BIN NUMBER                                                   | PPP I DATE<br>NUMB:R C RECEIVED | COMPONENT CLASS | COMPONENT NAME<br>YR MANUFACTURER          | MAKE-MODEL              | FALLT HAZ.<br>CCCE CAT. | MILEAGE<br>AT FAILURE | SHOP<br>NUMBER |
|--------------------------------------------------------------|---------------------------------|-----------------|--------------------------------------------|-------------------------|-------------------------|-----------------------|----------------|
| 40001                                                        | P01320 B 760320                 | 05110           | ENGINE MOUNTS<br>65 C22 MERCURY            | 04 MERCURY              | 21 C                    | 000000                | 13501005       |
| RUBBER SEPARATED FROM METAL PORTION OF MOUNT                 |                                 |                 |                                            |                         |                         |                       |                |
| 40005                                                        | P01378 B 760330                 | 05110           | ENGINE MOUNTS<br>70 C42 CADILLAC DIVISION  | B1 CADILLAC-DE VILLE    | 03 C                    | 057478                | 25611001       |
| RUBBER SEPARATED FROM METAL (RIGHT SIDE)                     |                                 |                 |                                            |                         |                         |                       |                |
| 40005                                                        | P01378 C 760330                 | 05110           | ENGINE MOUNTS<br>70 C42 CADILLAC DIVISION  | B1 CADILLAC-DE VILLE    | 03 C                    | 057478                | 25611001       |
| RUBBER SEPARATED FROM METAL (LEFT SIDE)                      |                                 |                 |                                            |                         |                         |                       |                |
| 40003                                                        | P01356 B 760329                 | 05110           | ENGINE MOUNTS<br>72 C43 CHEVROLET DIVISION | A2 CHEVELLE-MALIBU      | 03 C                    | 032000                | 53140014       |
| METAL SEPARATED FROM RUBBER                                  |                                 |                 |                                            |                         |                         |                       |                |
| 30022                                                        | P01273 B 760306                 | 05110           | ENGINE MOUNTS<br>71 C43 CHEVROLET DIVISION | B0 EL CAMINO            | 03 C                    | 064572                | 30501001       |
| TWO-THIRDS SEPARATION OF METAL & RUBBER                      |                                 |                 |                                            |                         |                         |                       |                |
| 40005                                                        | P01377 B 760330                 | 05110           | ENGINE MOUNTS<br>71 C43 CHEVROLET DIVISION | C4 NOVA                 | 03 C                    | 002033                | 50027012       |
| RUBBER SEPARATED FROM METAL (RIGHT SIDE)                     |                                 |                 |                                            |                         |                         |                       |                |
| 40005                                                        | P01377 C 760330                 | 05110           | ENGINE MOUNTS<br>71 C43 CHEVROLET DIVISION | C4 NOVA                 | 03 C                    | 002033                | 50027012       |
| RUBBER SEPARATED FROM METAL (LEFT SIDE)                      |                                 |                 |                                            |                         |                         |                       |                |
| 40005                                                        | P01375 B 760330                 | 05110           | ENGINE MOUNTS<br>65 C43 CHEVROLET DIVISION | EC PICK-UP MODELS<br>PU | 03 C                    | 078564                | 50027012       |
| RUBBER SEPARATED FROM METAL ON MOTOR MOUNTS                  |                                 |                 |                                            |                         |                         |                       |                |
| 30024                                                        | P01295 B 760301                 | 05110           | ENGINE MOUNTS<br>70 C43 CHEVROLET DIVISION | E3 IMPALA               | 08 C                    | 065549                | 25611001       |
| RUBBER PARTIALLY SEPARATED FROM METAL A2-58 (RECALL 71-0235) |                                 |                 |                                            |                         |                         |                       |                |

PARTS RETURN PROGRAM

76/C4/12

PAGE 0011

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
01 TO 31 MARCH 76

SORTED BY COMPONENT, PCDL, PDL YR

| BIN NUMBER | PRP NUMBER | I DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                         | YR MANUFACTURER | MAKE-MODEL                 | FALLT HAZ. CODE CAT. | MILEAGE AT FAILURE | SHOP NUMBER |
|------------|------------|-----------------|-----------------|--------------------------------------------------------|-----------------|----------------------------|----------------------|--------------------|-------------|
| 40008      | P01495 C   | 760331          | 05110           | ENGINE MOUNTS<br>71 C42 CHEVROLET DIVISION             |                 | 02 CHEVELLE                | C3 C                 | 000000             | 20009003    |
|            |            |                 |                 | RUBBER SEPARATED FROM METAL                            |                 |                            |                      |                    |             |
| 40008      | P01405 B   | 760331          | 05110           | ENGINE MOUNTS<br>71 C43 CHEVROLET DIVISION             |                 | 02 CHEVELLE                | C3 C                 | 000000             | 20009003    |
|            |            |                 |                 | RUBBER PORTION OF MOTOR MOUNT SEPARATED FROM METAL     |                 |                            |                      |                    |             |
| 40003      | P01351 C   | 760329          | 05110           | ENGINE MOUNTS<br>72 C42 CHEVROLET DIVISION             |                 | 9A CHEVROLET TRUCK AN C-30 | 03 C                 | 050000             | 52404002    |
|            |            |                 |                 | RUBBER SEPARATED FROM METAL - MOTOR MOUNTS BROKE       |                 |                            |                      |                    |             |
| 40003      | P01351 B   | 760329          | 05110           | ENGINE MOUNTS<br>72 C43 CHEVROLET DIVISION             |                 | 9A CHEVROLET TRUCK AN C-30 | 03 C                 | 050000             | 52404002    |
|            |            |                 |                 | RUBBER SEPARATED FROM METAL - MOTOR MOUNTS BROKE       |                 |                            |                      |                    |             |
| 40005      | P01376 B   | 760330          | 05110           | ENGINE MOUNTS<br>70 C44 CLOSMOBILE                     |                 | 02 DELTA 88                | 03 C                 | 040673             | 50027012    |
|            |            |                 |                 | RUBBER SEPARATED FROM METAL ON MOTOR MOUNTS            |                 |                            |                      |                    |             |
| 40003      | P01364 B   | 760329          | 05150           | ENGINE-OTHER PARTS<br>72 C10 AMERICAN MOTORS           |                 | 00 AMERICAN MOTORS         | 08 C                 | 000000             | 53140014    |
|            |            |                 |                 | VALVE SEALS ARE CRACKED                                |                 |                            |                      |                    |             |
| 40003      | P01358 B   | 760329          | 05151           | ENGINE - TIMING GEAR & CHAIN<br>00 C10 AMERICAN MOTORS |                 | 00 AMERICAN MOTORS         | 21 C                 | 005000             | 53140014    |
|            |            |                 |                 | TEETH ARE STRIPPED OFF TIMING GEAR                     |                 | RAPIDLY                    |                      |                    |             |
| 40003      | P01363 B   | 760329          | 05151           | ENGINE - TIMING GEAR & CHAIN<br>73 C10 AMERICAN MOTORS |                 | 07 MATADOR                 | 51 C                 | 036000             | 53140014    |
|            |            |                 |                 | TIMING GEAR CHAIN PDS STRETCHED                        |                 |                            |                      |                    |             |
| 40003      | P01359 B   | 760329          | 05151           | ENGINE - TIMING GEAR & CHAIN<br>74 C10 AMERICAN MOTORS |                 | 07 MATADOR                 | 51 C                 | 048000             | 53140014    |
|            |            |                 |                 | TIMING CHAIN APPEARS NORMAL                            |                 |                            |                      |                    |             |

FACTS RETURN PROGRAM

76/04/12 PAGE 0012

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
C1 TO 31 MARCH 76

SORTED BY COMPONENT, MODEL, YR

| BIN NUMBER | PRP NUMBER | DATE RECEIVED | COMPONENT CLASS | COMPONENT NAME                                                         | MANUFACTURER               | MAKE-MODEL                    | FALLT HAZ. CODE CAT. | FILE#GE AT FAILURE | SPCF NUMBER |
|------------|------------|---------------|-----------------|------------------------------------------------------------------------|----------------------------|-------------------------------|----------------------|--------------------|-------------|
| 40007      | P01414 C   | 760331        | 05151           | ENGINE - TIMING GEAR & CHAIN                                           | 72 (21) CHRYSLER DIVISION  | AI NEWPCRT                    | 57 C                 | 042487             | 60626008    |
|            |            |               |                 | TIMING CHAIN HAS EXCESSIVE WEAR                                        |                            |                               |                      |                    |             |
| 40007      | P01414 B   | 760331        | 05151           | ENGINE - TIMING GEAR & CHAIN                                           | 72 (21) CHRYSLER DIVISION  | AI NEWPCRT                    | 57 C                 | 042487             | 60626008    |
|            |            |               |                 | PLASTIC COATING ON TEETH WORN AWAY-9 TEETH BROKEN EXCESS WEAR ON OTHER |                            |                               |                      |                    |             |
| 40002      | P01339 B   | 760324        | 05151           | ENGINE - TIMING GEAR & CHAIN                                           | 65 (31) FCRD DIVISION      | 03 FCRD 500                   | 57 C                 | C85000             | 92632025    |
|            |            |               |                 | EXCESS WEAR ON PLASTIC COVERING OVER CAM GEAR TEETH                    |                            |                               |                      |                    |             |
| 40001      | P01317 B   | 760320        | 05151           | ENGINE - TIMING GEAR & CHAIN                                           | 72 (42) CHEVROLET DIVISION | E0 FICK-LF MODELS             | 57 C                 | C51000             | 55670006    |
|            |            |               |                 | 1 GEAR CAM/FEC-3 GEARS & 4 TENSIONERS SPGW EXCESS WEAR-2 CHAINS ECCD   |                            |                               |                      |                    |             |
| 40006      | P01396 B   | 760331        | 05151           | ENGINE - TIMING GEAR & CHAIN                                           | 70 (45) FCNTIAC DIVISION   | C3 CATALINA                   | 57 C                 | 060350             | 63301003    |
|            |            |               |                 | PLASTIC COATING OF CAM GEAR WORN AWAY-ALUMINUM TEETH SPON WEAR         |                            |                               |                      |                    |             |
| 40004      | P01267 C   | 760329        | 05210           | ENGINE COOLING SYSTEM-RADIATOR                                         | 71 (51) ACAM OPEL AG       | C1 CPFL 1500                  | 1G C                 | C33384             | 45406009    |
|            |            |               |                 | RADIATOR SUPPORT MOUNT SEPARATED AT RUBBER JOINT                       |                            |                               |                      |                    |             |
| 40004      | P01368 B   | 760329        | 05220           | ENGINE COOLING SYSTEM-PUMP, WATER                                      | 72 (31) FCRD DIVISION      | 9A FORD TRUCK AND VAN LA-7000 | 08 C                 | 052162             | 45406005    |
|            |            |               |                 | RUBBER CAP ON WATER PUMP CRACKED ABOVE CLAMP REPL PART NOT AVAILABLE   |                            |                               |                      |                    |             |
| 30025      | P01261 B   | 760306        | 05240           | ENGINE COOLING SYSTEM-FAN                                              | 71 (22) ECCGE              | 02 CHARGER                    | CE C                 | CC0000             | 63123002    |
|            |            |               |                 | CRACK EXTENDS FROM UNDER BRACKET TO PLATE SURFACE ~ FLEX METAL BLADES  |                            |                               |                      |                    |             |
| 40002      | P01342 B   | 760324        | 05240           | ENGINE COOLING SYSTEM-FAN                                              | 72 (22) CCCGE              | 9A CODE TRUCK AND VA 200      | 28 C                 | C41000             | 52632025    |
|            |            |               |                 | FAN CLUTCH FROZEN - ASSEMBLY INOPERATIVE                               |                            |                               |                      |                    |             |

PARTS RETLFA PROGRAM

76/04/12 PAGE 0013

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
C1 TO 21 MARCH 76

SORTED BY COMPONENT, MAKE, MODEL, YR

| BIN NUMBER | PRP I DATE      | COMPONENT CLASS | COMPONENT YR                                                                                      | COMPONENT NAME                                                                                    | MAKE-MODEL          | FALLT HZ. CCCC CAT. | FILEAGE AT FAILURE | SHOP NUMBER |
|------------|-----------------|-----------------|---------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|---------------------|---------------------|--------------------|-------------|
| 40004      | P01367 B 760325 | 05240           | ENGINE COOLING SYSTEM-FAN<br>71 151 ACAP CPEL PG                                                  | ENGINE COOLING SYSTEM-FAN<br>71 151 ACAP CPEL PG                                                  | C1 CPEL 1500        | C3 C                | 032324             | 45406005    |
|            |                 |                 |                                                                                                   | PLASTIC FAN BLADE IS BROKEN                                                                       |                     |                     |                    |             |
| 40006      | P01395 B 760331 | 05260           | ENGINE COOLING SYSTEM-THERMOSTAT<br>69 044 CLESMOBILE                                             | ENGINE COOLING SYSTEM-THERMOSTAT<br>69 044 CLESMOBILE                                             | C2 DELTA 88-ROYALE  | 03 C                | 082752             | 63301003    |
|            |                 |                 |                                                                                                   | BRACKET FOR SPRING BASE SEPARATED FROM MAIN BODY OF THERMOSTAT                                    |                     |                     |                    |             |
| 40005      | P01363 B 760330 | 06112           | FUEL TANK ASSEMBLY-PIPE, FILLER-NECK<br>65 C21 FCPO DIVISION                                      | FUEL TANK ASSEMBLY-PIPE, FILLER-NECK<br>65 C21 FCPO DIVISION                                      | 02 FAICCN           | C8 C                | 000000             | 94101002    |
|            |                 |                 |                                                                                                   | FILLER NECK WEATHERED AND CRACKED AT 45 DEGREE BEND                                               |                     |                     |                    |             |
| 40009      | P01403 B 760331 | 06112           | FUEL TANK ASSEMBLY-PIPE, FILLER-NECK<br>68 162 FIAT S.P.A.                                        | FUEL TANK ASSEMBLY-PIPE, FILLER-NECK<br>68 162 FIAT S.P.A.                                        | 04 FIAT 124 SPYDER  | C8 C                | 000000             | 20005003    |
|            |                 |                 |                                                                                                   | HOSE HAS SERIES OF CRACKS CAUSING FUEL LEAKAGE                                                    |                     |                     |                    |             |
| 40006      | P01400 B 760331 | 06136           | FUEL FLMP<br>72 C42 CHEVROLET DIVISION                                                            | FUEL FLMP<br>72 C42 CHEVROLET DIVISION                                                            | C4 NCVA             | 28 C                | 016714             | 63301003    |
| 40003      | P01357 B 760325 | 06213           | NC EXTERNAL DEFECTS DIAGRAM ACTION IS GOOD POSS INTERNAL MALFUNCTION<br>73 C42 CHEVROLET DIVISION | NC EXTERNAL DEFECTS DIAGRAM ACTION IS GOOD POSS INTERNAL MALFUNCTION<br>73 C42 CHEVROLET DIVISION | E3 IMPALA           | 28 C                | 032000             | 53140014    |
|            |                 |                 |                                                                                                   | VACUUM OPERATED CHECKER FULL-CFF-NC VISIBLE DEFECTS                                               |                     |                     |                    |             |
|            | P01370 B 760330 | 06223           | CAREURFETCP, SINGLE-CTF-PART<br>75 C32 LINCCN                                                     | CAREURFETCP, SINGLE-CTF-PART<br>75 C32 LINCCN                                                     | 00 LINCCN<br>81     | 21 C                | 015500             | 42301006    |
|            |                 |                 |                                                                                                   | NC PART-FUEL PLUG IN CARE FELL OUT CAUSING FUEL TO LEAK ON ENGINE                                 |                     |                     |                    |             |
| 40006      | P01393 B 760331 | 06243           | CAREURFETCP, FCLP-BARREL-CTF-PART<br>73 C31 FCPO DIVISION                                         | CAREURFETCP, FCLP-BARREL-CTF-PART<br>73 C31 FCPO DIVISION                                         | 07 TRUNDERBIRD      | 49 C                | 046734             | 00000000    |
|            |                 |                 |                                                                                                   | ALLM CARB SPACER IN FOR PASSAGE BTWN PORTS & EDGE IS CORRODED                                     |                     |                     |                    |             |
|            | P01404 B 760331 | 06327           | FUEL INJECTION, ELECTRIC-INJECTOR<br>71 155 VOLKSWAGEN                                            | FUEL INJECTION, ELECTRIC-INJECTOR<br>71 155 VOLKSWAGEN                                            | E3 SQUAREBACK SEDAN | 22 C                | 026832             | 20009003    |
|            |                 |                 |                                                                                                   | NC PART-REPLACED 2 FUEL INJECTORS-FUEL LEAKAGE FROM FLEX HOSE                                     |                     |                     |                    |             |

PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
01 TO 31 MARCH 76

76/C4/12 PAGE 0014

SORTED BY COMPONENT, MODEL, PCL YR

| SIN<br>NUMBER | PRP<br>NUMBER | I<br>DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>MANUFACTURER                                          | YR | MAKE-MODEL                        | FAULT HAZ.<br>CCE CAT. | MILEAGE<br>AT FAILURE | SPOP<br>NUMBER |
|---------------|---------------|-----------------------|--------------------|-------------------------------------------------------------------------|----|-----------------------------------|------------------------|-----------------------|----------------|
| 40005         | P01380 B      | 760330                | 06430              | THROTTLE LINKAGES, ACCELERATOR, FLEXIBLE<br>70 C45 PONTIAC DIVISION     |    | P4 LE MANS                        | 06 C                   | 000000                | 01504025       |
|               |               |                       |                    | ACCELERATOR LINKAGE CABLE BROKEN WHERE ATTACHED TO CARBURATOR           |    |                                   |                        |                       |                |
| 30025         | P01306 B      | 760306                | 06620              | EXHAUST SYSTEM-PIPE, EXHAUST<br>72 C31 FORD DIVISION                    |    | I3 FORD-RANCH WAGON               | 76 C                   | 037070                | 54301057       |
|               |               |                       |                    | INNER WALL OF DOUBLE WALLED PIPE COLLAPSED                              |    |                                   |                        |                       |                |
| 40003         | P01350 B      | 760324                | 06620              | EXHAUST SYSTEM-PIPE, EXHAUST<br>72 C42 CADILLAC DIVISION                |    | B1 CADILLAC-DE VILLE              | 76 C                   | 064000                | 52404002       |
|               |               |                       |                    | INNER WALL OF DOUBLE WALLED EXHAUST PIPE COLLAPSED                      |    |                                   |                        |                       |                |
| 40004         | P01366 B      | 760329                | 06640              | EXHAUST SYSTEM-TAIL PIPE<br>71 C43 CHEVROLET DIVISION                   |    | E3 IMPALA                         | 76 C                   | 000000                | 45406005       |
|               |               |                       |                    | INNER LINING OF EXHAUST PIPE COLLAPSED                                  |    |                                   |                        |                       |                |
| 40005         | P01374 B      | 760330                | 07110              | POWER TRAIN CLUTCH ASSEMBLY-REAR<br>65 155 VOLKSWAGEN                   |    | 01 TYPE I                         | 08 C                   | 052450                | 50027012       |
|               |               |                       |                    | PEDAL IS CRACKED JUST BEFORE SLEEVE THAT ATTACHES TO LINKAGE            |    |                                   |                        |                       |                |
| 40004         | P01365 B      | 760329                | 07130              | POWER TRAIN CLUTCH ASM-LINKAGE, RIGID<br>72 C44 CHRYSLER                |    | 05 4-4-2                          | 03 C                   | 026564                | 45406005       |
|               |               |                       |                    | COLLAR ON THROCK-OUT BRNG BROKEN                                        |    |                                   |                        |                       |                |
| 40010         | P01408 B      | 760331                | 07300              | POWER TRAIN TRANSMISSION, AUTOMATIC<br>74 C43 CHEVROLET DIVISION        |    | 03 CHEVROLET                      | 57 C                   | 017582                | 20030021       |
|               |               |                       |                    | SCME CLUTCH & DISC SPCH BUEN MKS, BUSHS SPCH WEAR, GEARS OK-FULL FRCBLM |    |                                   |                        |                       |                |
| 40005         | P01382 B      | 760310                | 07450              | PAR TRN DRIVE-LINE-DIFFERENTIAL UNIT<br>74 C22 DODGE                    |    | SA DODGE TRUCK AND VAN<br>300 VAN | 07 C                   | 017521                | 43614003       |
|               |               |                       |                    | BEARINGS ARE CONTAMINATED-RACES SEVERELY PITTED                         |    |                                   |                        |                       |                |
| 40004         | P01365 B      | 760325                | 07470              | POWER TRAIN-OTHER PART<br>71 C41 BUICK                                  |    | 04 LE SAERE                       | 08 C                   | 071076                | 45406005       |
|               |               |                       |                    | FLEX-PLATE CRACKED AROUND BELT HOLES                                    |    |                                   |                        |                       |                |



PARTS RETURN PROGRAM

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
C1 TO 31 MARCH 76

76/04/12 PAGE 0016

SORTED BY COMPONENT, MODEL, YR

| BIN NUMBER | PPR I<br>NUMBER | DATE<br>C RECEIVED | COMPONENT<br>CLASS | COMPONENT YR | COMPONENT NAME<br>MANUFACTURER                                         | MAKE-MODEL                   | FALLT HAZ.<br>CCE CAT. | HAZ. CAT.<br>AT FAILURE | MPLEAGE<br>NUMBER | SHCP<br>NUMBER |
|------------|-----------------|--------------------|--------------------|--------------|------------------------------------------------------------------------|------------------------------|------------------------|-------------------------|-------------------|----------------|
| 30023      | P01302 B        | 760306             | 09110              | 72           | SACH-BLITTON-RING-TURN SIGNAL LIGHTS<br>72 C21 FCRC DIVISION           | 03 FCRC                      | 2E                     | C                       | 020167            | 44312002       |
|            |                 |                    |                    |              | SUSPECT INTERNAL CFEA - AC VISIBLF DEFECT                              |                              |                        |                         |                   |                |
| 30023      | P01303 B        | 760306             | 09110              | 72           | SACH-BLITTON-RING-TURN SIGNAL LIGHTS<br>72 C31 FCRC DIVISION           | 08 TCRING                    | 2E                     | C                       | 040281            | 44312002       |
|            |                 |                    |                    |              | SUSPECT FCRC CONNECTION AC VISIBLE DEFECTS                             |                              |                        |                         |                   |                |
| 40006      | P01391 B        | 760331             | 09110              | 68           | SACH-BLITTON-RING-TURN SIGNAL LIGHTS<br>68 C43 CHEVROLET DIVISION      | A2 CHEVELLE-MALIBU           | 28                     | C                       | 044680            | 29611001       |
|            |                 |                    |                    |              | CONNECTIONS ARE TIGHT & CLEAN-NO VISIBLE DEFECTS-SHORT IN SWITCH       |                              |                        |                         |                   |                |
| 40003      | P01353 B        | 760329             | 09110              | 68           | SACH-BLITTON-RING-TURN SIGNAL LIGHTS<br>68 C43 CHEVROLET DIVISION      | E0 PICK-LF MODELS<br>C-1C PU | 28                     | C                       | 000000            | 52404002       |
|            |                 |                    |                    |              | PCSS INTERNAL MALFUNCTION 1/5 SWITCH - AC VISAPLE DEFECTS              |                              |                        |                         |                   |                |
| 40002      | P01340 B        | 760324             | 10311              | 65           | VISUAL SYS WINDSHIELD WIPER/WASHER SWITCH<br>65 C22 DCEGE              | C4 CCRONET-440               | 28                     | C                       | 065769            | 52632025       |
|            |                 |                    |                    |              | WIPER/WASHER SWITCH INCP-CONNECTIONS CLEAN & SECURE-INTERNAL PRCE      |                              |                        |                         |                   |                |
| 40008      | P01406 B        | 760331             | 10315              | 74           | VISUAL SYSTEMS WINDSHIELD WIPER BLADE<br>74 151 ACAM OPEL AG           | 01 CPEL<br>KACET             | 57                     | C                       | 000171            | 12601050       |
|            |                 |                    |                    |              | RUBBER IS 70 PERC SEPARATED ALONG FCRTION WHICH PTS IN METAL GUIDE     |                              |                        |                         |                   |                |
| 40008      | P01406 C        | 760331             | 10315              | 74           | VISUAL SYSTEMS WINDSHIELD WIPER BLADE<br>74 151 ACAM OPEL AG           | 01 CPEL                      | 57                     | C                       | 000171            | 12601050       |
|            |                 |                    |                    |              | RUBBER INSERT WORN AT ENCS ONE FNC OF METAL PLADE IS BENT              |                              |                        |                         |                   |                |
| 40001      | P01319 B        | 760320             | 11609              | 72           | AIR CONDITICKER-COMPRESSOR<br>72 C32 LINCOLN                           | A2 MARK IV                   | 57                     | C                       | 030802            | 06120003       |
|            |                 |                    |                    |              | CLUTCH PLATE UNIT DISASSEMBLED SCME WEAR ON FRICTON SURFACES-RUSTY     |                              |                        |                         |                   |                |
| 40004      | P01372 B        | 760330             | 13110              | 66           | STRUCTURE-FRAME & MEMBERS(CIVE SIDE/ENC)<br>66 C31 FCRC DIVISION       | 03 FCRC<br>SCLIRF            | 03                     | C                       | 073986            | 02140002       |
|            |                 |                    |                    |              | FRAME ATTACHED TO ICLEF ARM BROKT MNTG BOLT BROKE AND RELEASED BRACKET |                              |                        |                         |                   |                |

PARTS RETURN PROGRAM

76/04/12 PAGE 0017

OFFICE OF DEFECTS INVESTIGATION  
MONTHLY PARTS RECEIVED INDEX  
01 IC 31 MARCH 76

SORTED BY COMPONENT, MODEL, YR

| RIN<br>NUMBER                                                | PRE I<br>NUMBER D | DATE<br>RECEIVED | COMPONENT<br>CLASS | COMPONENT NAME<br>YR MANUFACTURER                              | MAKE-MODEL  | FAULT HAZ.<br>CODE CAT. | MILEAGE<br>AT FAILURE | SOP<br>NUMBER |
|--------------------------------------------------------------|-------------------|------------------|--------------------|----------------------------------------------------------------|-------------|-------------------------|-----------------------|---------------|
| 40003                                                        | P01345 B          | 760324           | 12110              | STRUCTURE-FRAME & MEMBERSHIP SICE/END)<br>68 031 FORD DIVISION | 03 FORD     | 03 C                    | 070755                | 02140012      |
| FRAME BRACE AT IDLER ARM BRACKET MOUNTING - EVIDENCE OF RUST |                   |                  |                    |                                                                |             |                         |                       |               |
| 30026                                                        | P01299 C          | 760301           | 13720              | HCCC ASSEMBLY-HINGE & ATTACHMENTS<br>72 031 FORD DIVISION      | 03 FORD-LTD | 76 C                    | 026000                | 03140017      |
| ONE ARM SLIGHTLY TOEN NEAR PIVOT                             |                   |                  |                    |                                                                |             |                         |                       |               |
| 30026                                                        | P01299 B          | 760301           | 12720              | HCCC ASSEMBLY-HINGE & ATTACHMENTS<br>72 031 FORD DIVISION      | 03 FORD-LTD | 76 C                    | 026000                | 03140017      |
| ONE ARM SEENT AT PIVOT                                       |                   |                  |                    |                                                                |             |                         |                       |               |

TL 242 .B33  
BEDDOW, B.  
NATIONAL PA  
PROGRAM /

Form DOT F 1720  
FORMERLY FORM DO

