

**Evaluation of Corrosion  
Resistant Steel Reinforcing in  
the Deck Slab of a Three-span  
Prestressed Concrete Girder  
Bridge**



# Objective and Scope

- Investigate and evaluate the field performance of new reinforcing steel and compare with conventional reinforcing steel
- Corrosion sensors embedded in deck slab to be monitored
- Data collected occasionally to assess performance in terms of corrosion resistance



# MMFX vs. Epoxy coated steel

- Micro-composite Multi-structural Formable Steel (MMFX)
  - Relatively new form of corrosion resistant material
- Epoxy coated steel (ECS)
  - Conventional black steel coated with epoxy



# Bridge Description



MMFX bridge




Epoxy bridge

- Twin 83.5m x 12m three-span prestressed concrete girder bridges constructed in May 2002, and open to traffic in Aug 2003
- Located in Grundy County, IA carrying relocated Highway U.S. 20
- Each bridge deck constructed with different types of reinforcing steel
  - East bound : MMFX steel (MMFX bridge)
  - West bound: Epoxy coated steel (Epoxy Bridge)




# Instrumentation

- Sensors on Ten bars in each bridge deck
- Negative bending moment region near the eastern drainage points



# Instrumentation (Detail C - MMFX Bridge)



# Instrumentation



- Lead wires run out of deck to measure voltage and electric current

Completed installation





# Monitoring Concept

- Increase in electric potential and internal voltage with presence of active corrosion
- DC voltage and DC current measured with a Voltmeter



Voltmeter




# Monitoring Concept


- Output dependent on conditions of concrete after placement
- Normal to expect high voltage levels with fresh and uncured concrete (could be over 1000 mV)
- Initial “spike” subsides back to within the “normal” range of less than 400 mV
- Corrosion indication
  - Electric Current above 0.100 mA (1000  $\mu$ A)




# Field Monitoring




MMFX bridge



Epoxy bridge



MMFX bridge



Epoxy bridge



# Overall to date

- In general, Readings on MMAX bridge lower than Epoxy bridge
- No significant active corrosion
  - Electric Current reading close to zero
- On-going investigation
  - More Data to be collected



# Acknowledgement

- Projects initiated by
  - Iowa Department of Transportation (Iowa DOT)
- Sponsored by
  - Federal Highway Administration (FHWA) through the Innovative Bridge Research and Construction (IBRC) program



# Questions?

