

# INTERSTATE COMMERCE COMMISSION

---

## REPORT OF THE CHIEF OF THE DIVISION OF SAFETY COVERING THE INVESTIGATION OF AN ACCIDENT WHICH OCCURRED ON THE CHICAGO, MILWAUKEE & ST PAUL RAILWAY AT OAKWOOD, WIS., ON JANUARY 30, 1915

APRIL 28, 1915

### *To the Commission*

On January 30, 1915, there was a derailment of a passenger train on the Chicago, Milwaukee & St Paul Railway at Oakwood, Wis., which resulted in the injury of 21 passengers. After investigation as to the nature and cause of this accident, I beg to submit the following report.

The train involved in this accident was westbound passenger train No. 5, en route from Chicago, Ill., to Minneapolis, Minn. It consisted of an engine, 1 mail car, 1 combination mail and express car, 1 baggage car, 3 coaches, 1 dining car, and 1 parlor car, and was in charge of Conductor Wood and Engineman Collins. It left Chicago at 8 30 a. m., and at 10 12 a. m. was derailed at a crossover frog a few feet east of the station at Oakwood while traveling at a speed estimated to have been about 55 miles per hour.

The entire train was derailed with the exception of the locomotive and first two cars, the baggage car coming to rest on its side, while the other cars remained practically upright and none was materially damaged. Illustration No. 1 is a view of the rear portion of the train, looking east.

This part of the Chicago, Milwaukee & St Paul Railway is a double-track line and is equipped with automatic block signals. At the point of accident the track is straight, laid with 100-pound steel rails, 33 feet in length, with about 19 oak ties under each rail, ballasted with 2 feet of gravel. At the time of the accident the weather was clear.

Examination of the equipment of the train showed that there was a broken wheel under the baggage car. The trucks under this car

were 6-wheel trucks, and the wheel which broke was the middle wheel on the right side of the forward truck. When the truck was examined pieces of a journal box, packing, and several small parts of the truck were found at a point about 2,300 feet east of the point of derailment. About five rail lengths west of this point was a broken rail, apparently broken as a result of the pounding of the broken wheel upon it. Nearly 850 feet west of the point where the parts of the journal box were found was a piece of the tire from the broken wheel, this piece being found at the foot of the embankment on the south side of the eastbound track. Nearly 650 feet west of this point a second piece of this tire was found, this piece being between the two main tracks. About 450 feet beyond the point of derailment a third fragment of the tire was found, while one other piece could not be located.


The night car inspector in the coach yard in Chicago stated that the baggage car arrived in Chicago on January 29 and on being brought to the coach yard was inspected by him. He found one pair of defective wheels on the same truck under which the broken wheel which caused the accident afterwards failed. The car was then sent to the wheel pit and a new pair of wheels was put under the car in place of the defective pair. After this had been done the car was again inspected by him, as well as by two car repairmen, but no other defects were found.

The investigation to ascertain the reason for the failure of this wheel was conducted by Mr. James E. Howard, engineer-physicist, tests being made in conjunction with representatives of the Chicago, Milwaukee & St. Paul Railway Co. at the shops of that company in Milwaukee, Wis. The report covering the results of this investigation follows:


#### REPORT OF THE ENGINEER PHYSICIST

The wheel the tire of which failed, apparently leading to the derailment of train No. 5, was one of a built-up type, which consisted of a cast-iron hub, or spider—so called—two rolled-steel cheek plates, and a rolled-steel tire. The several parts, during fabrication, were assembled by forced mechanical fits, to insure the proper unity of their action in the completed wheel. In a subsequent operation the plates, hub, and tire were drilled and were further secured to each other by through bolts. The usual number of bolts in wheels of this type is 39, of which 30 are three-fourths inch diameter and 9 are seven-eighths inch diameter. The smaller bolts form three concentric circles of the outer part of the wheel, the larger bolts are those of the inside circle at the hub, the heads of the latter being counter-sunk.

Figure No 2 shows the construction of this type of wheel, in a cross section, with cast-iron spider in place on the axle, inner and outer steel plates, and rolled-steel tire. The thickness of the tire here shown,  $1\frac{3}{8}$  inches in the plane of the outer plate, represents thickness at time of derailment.



No 2—Sectional view showing details of construction of built-up wheel consisting of cast iron hub, two  $\frac{7}{16}$ -inch steel plates and rolled steel tire



No 3—Side view of built-up wheel showing cast-iron spider with one  $\frac{7}{16}$ -inch steel plate and steel tire in place the outside  $\frac{7}{16}$ -inch steel plate removed

Figure No 3 is a side view of the wheel showing the cast-iron spider and the tire, with one of the plates, the outer one, removed

In machining these parts, for obtaining proper mechanical fits, the plates are made slightly over and under the diameters of the tire and the hub, respectively, the assembling then being done by forcing the plates over their seats with a hydraulic press. The mechanical fits thus secured are relied upon in lieu of assembling by shrinkage fits.

The outer circle of bolts clamp the check plates directly to the interior web of the tire. The bolts of the next circle, which are located just within the inner diameter of the tire, draw the plates toward each other. Since there is no direct support opposite this second circle of bolts the plates are bent slightly inward, in consequence of which any radial movement of the tire with reference to the plates tends to wear a shoulder where the inside faces of the plates are deflected against the corners of the web of the tire. The plates used are seven-sixteenths inch in thickness each.

The third circle of bolts clamps the plates to the lugs of the cast-iron spider and the fourth circle to the main web of the hub.

In wheels of this type the axle loads are transmitted to the tire through the two seven-sixteenth inch plates. The efficiency of the bearing surface, seven-eighths inch total width at the edges of the plates, is augmented in sustaining the axle load by the frictional resistance set up between the plates and the interior web of the tire.

The cast-iron spider shown in figure No 3 represents the pattern used in 33-inch wheels, the size which failed in the truck of baggage car No 522. In wheels of larger diameter cored spiders of greater size are used in order to provide for the desired distribution of the bolts over the flat surfaces of these plates of increased width.

The completed wheels are pressed on the axles in the usual manner of assembling, a forced fit being made between the hub and the wheel seat of the axle. Such are the constructive details of wheels of this type.

On the occasion of the derailment of tram No 5, the tire of the middle wheel of the forward truck of baggage car No 522, right-hand side of the tram, broke at four places, at each place separating the tire by radial lines of rupture. Each line of rupture passed through a bolt hole of the interior web of the tire. The smallest fragment comprised two-twelfths of the circumference. There were two fragments of intermediate size of three-twelfths each and one fragment of four-twelfths the circumference. Three of these fragments were recovered after the derailment, the smallest one not having been found.

An examination of the fractured surfaces showed that each line rupture had its origin at the inner diameter of the tire, thence passing through the metal in an outward direction to the surface of the tread and through the flange.

The thin sections of metal between the bolt holes of the inner web and the inner diameter of the tire were fractured at each bolt hole. These incipient fractures, however, did not extend beyond the thin sections, excepting at those places where the full cross section was separated in forming the four detached fragments.


The principal lines of rupture are shown on figure No. 4, marked "a," "b," "c," and "d," on which the incipient fractures at the bolt holes are also indicated. The initial line of rupture of the tire is believed to have occurred between fragments 1 and 4, on the line marked "a," followed by that marked "b," thereby detaching the short fragment which was not recovered. The indications are that the line of rupture next to occur was that marked "d," in the development of which one-half of the tire was detached from the plate. This half, in its flight, evidently came into collision with some object which caused it to break apart at the middle of its length, at the line marked "c," in this manner forming the two fragments numbered 2 and 3.

In the course of their flight fragments Nos. 2 and 3 crossed over to the left-hand side of the train, emerged therefrom and came to rest, one at the foot of an embankment about 850 feet from the place where the first evidence of damage to the truck was found, while the other fragment came to rest between the eastbound and the westbound tracks, 650 feet beyond the first recovered fragment. Fragment marked 4 remained with or in the vicinity of the train, at a further distance of 1,267 feet, making a total distance of 2,767 feet beyond the place where the first evidence of damage to the truck was found, and 440 feet beyond the place of derailment of the train at the crossover frog. This fragment was recovered in the vicinity of the rear coaches of the derailed train, where they came to rest.

The relation of the distance of fragment 4 to the crossover frog leads to the inference that this fragment played an important part in the derailment when the train encountered the frog in question. Although portions of the tire had been detached from the plates of the wheel for some distance to the rear, still the train remained on the rails until the crossover frog was reached, beyond which the train was derailed and the track destroyed. Up to the location of the frog no injury had been done to the track excepting the fracture of one rail which was located at a considerable distance to the rear.

This broken rail was on the side of the track of the broken wheel located at a distance of 2,177 feet from the place of derailment, and

150 feet beyond, in the direction the train was traveling, the place where first indications of damage to the truck appeared, the latter consisting of journal-box packing and a broken pedestal. The rail was a 100-pound A S C E section branded "10001 Illinois Steel Co South Wks X 1906," heat No 7889. It had a square break 27 inches from the receiving end and just beyond its seat upon a tie. The line of rupture started in the base, thence passing upward through the web and the head. There was a longitudinal seam at the center line of the base 11 inches long, the presence of which appeared to have led to this fracture.



No. 4.—Tire of built up wheel showing location of the four lines of rupture which were found at time of derailment separating the tire at bolt holes a b c and d. Incipient lines of rupture present at each of the other bolt holes of the recovered fragments.

It is of interest to note the conditions which were probably responsible for the fracture of this one rail. It was a case of streaked steel, seams or streaks in the base, which successfully endured the stresses of ordinary traffic but failed when subjected to an exceptionally severe stress, in this case incident to a broken wheel, from which a portion of the tire had probably just been detached. Evidence of the streaked state of the metal in this rail was presented at another place

along its length where a short strip of the flange was sheared off. No other rail was broken nor were any bent until the point of derailment was reached, 2,177 feet beyond.

The causes which led to the fracture of the wheel were looked for in the evidence furnished by the recovered fragments and in the condition of the mate of the fractured wheel. The inquiry was also extended to the examination of other wheels of this type, some of which had been removed on account of cracked tires and others by reason of having been worn down to the minimum thickness permitted.

In the ruptured wheel it was found that appreciable wear had taken place at the bearing between the rims of the plates and the inside diameter of the tire, that is, at the junction of the inside web and tread. The tire was grooved, in some places the groove reached a depth of three-hundredths of an inch. This grooving evinced that a movement had occurred between the tire and the plates during the time the wheel was in service, and which doubtless had an influence in promoting rupture.

The incipient cracks at the bolt holes furnished other evidence of local movement and bending of the tire when the wheel was in service. Some of the bolt holes in the recovered fragments were considerably distorted, a secondary occurrence, incidental to shearing the bolts when the fragments were detached from the plates.

Still another effect was noticed, the broken pieces of the tire assumed a radius of curvature slightly less than that which the intact diameter of the tire called for. This change in curvature resulted from the introduction of internal strains in the metal in the zone next below the surface of the tread and was due, it is believed, to the cold-rolling effect between the wheels and the head of the rail. Such internal strains correspond to stresses of considerable magnitude and are not negligible quantities when judging of the endurance of steel under the conditions of railway service. The presence of such internal strains was made manifest by the springing together of the ends of tires when they were cut apart radially, a matter to be referred to in a later part of this report.

The mate of the ruptured wheel was dismantled and the condition of its parts examined, previous to which, however, it was sounded with a hammer. Under the hammer test the wheel did not appear to be loose in any of its parts. In dismantling, the nuts of the plate bolts were removed and the bolts driven out. Those of the inner circle,  $\frac{7}{8}$  inch diameter, required hard driving in their removal. The  $\frac{3}{4}$ -inch bolts in general drove out easily, particularly those of the outer circle—those which passed through the web of the tire.

The outside plate of this wheel was removed, furnishing access to the surface next the tire and the spider, also permitting inspection of the seat of the plate in the tire and of the condition of the bolt holes

Grooving had taken place in the tire where the rims of the plates seated, although not to the same extent as that which was witnessed in the fragments of the broken wheel. Incipient cracks were found at each of the 12 bolt holes in this tire, across the thin sections between the bolt holes and the interior diameter of the web. None had extended to the metal on the opposite sides of the holes. When such extension occurs an early and complete failure of the tire would be expected, resulting in a cracked tire, visible at the tread. These incipient cracks, which were found to be comparatively numerous in wheels which were dismantled in quest of them, are not visible until the outer circle of bolts are taken out or one of the plates removed.

The thickness of the metal at this place is insufficient to afford substantial aid to the strength of the tire. The presence of such incipient fractures, however, is held to be significant that the wheel in service carried loads which successively bent and flattened the tire as it rotated.


The rupture of the metal is regarded as evidence of the effect of repeated stresses, endured in regular service, the fractures pointing to the place in which strength and rigidity seem deficient.

The lack of rigidity and unity of action was illustrated in the effects which the use of the wheel produced on the metal of the plates, as shown by the brightened annular surfaces surrounding the outer circle of bolt holes, and accompanied by the formation of perceptible shoulders on the faces of the plates where the corners of the web of the tire bore against them. Figure No. 5 is shaded to represent the places where these movements occurred. In some of the wheels examined, there was evidence of the movement of the plates having occurred as far down as the lugs of the spider, but in general the effects were not visible beyond that part of the plate covered by the outer two circles of bolts.

Structurally, a weak part of the wheel, at least in one with a worn tire, is thus shown to be in the vicinity of the rim, where these movements between the tire and the plates occur. The stresses which attend these alternate movements it would appear, eventually lead to rupture of the metal after the manner of repeated or fatigue tests. A direct measure of the magnitude of the stresses experienced in service does not admit of determination but the results of such stresses in causing rupture may be taken as indicative of their magnitude, and the frequency of their application.



Wheels of this type, which fail with cracked tires, commonly have their lines of fracture pass through the bolt holes, with their origin at the interior diameter of the tire, extending thence in an outward direction, nevertheless there are occasional exceptions to this manner of failure. There are instances in which the incipient places of rupture are located at the surface of the tread, at the corner of the rim, or at the flange. In such tires the lines of rupture travel in the opposite direction to those first described, that is radially inward instead of outward. Such fractures owe their origins to other and distinct causes from those above mentioned.



No. 5.—Plate of built up wheel. Evidence of movement between plate and tire found as indicated by the annular shaded zones around outer circle of bolt holes, the formation of shoulders on the face of plate by lines at the sides of the second circle of bolt holes.

Chemical analyses and tensile tests were made upon the metal of the ruptured tire, the results of which next follow

### Chemical analyses

[Results furnished by the Chicago, Milwaukee & St. Paul Ry. Co.]

Carbon	Manganese	Silicon	Sulphur	Phosphorus
	0.59 64 64	0.25 29 31	0.032 032 032	0.026 029 031

[Results furnished by the Railway Steel Spring Co.]

0.71	0.64	0.28	0.030	0.035
------	------	------	-------	-------

Independent check determination, carbon only, on chips taken from tensile test piece, gave carbon 73

### Tensile tests

[Specimens 0.505 inch diameter by 2 inches long]

Description	Elastic limit per square inch	Tensile strength per square inch	Elongation	Cont. of area
Tangential specimens	<i>Pounds</i>	<i>Pounds</i>	<i>Per cent</i>	<i>Per cent</i>
Outside part of tread	41 900	103 500	21.3	32.5
Center of tread	53 500	104 950	18.7	29.5
Near flange	40 750	102 500	21.5	29.5
Crosswise specimen				
Center of tread	66 300	104 700	11.0	16.1

[Results furnished by the Railway Steel Spring Co.]

	57 570	114 370	15.0	21.0
--	--------	---------	------	------


### Appearance of the fractures, granular

Figures Nos. 6 and 7 show the axle and wheels, one of which had the fractured tire. All of the fragments of the right-hand wheel were detached from the plates, as shown in figure No. 6, prior to the time the train came to rest. The left-hand wheel, shown in figure No. 7, which was otherwise intact was found upon examination to have incipient cracks at each of the bolt holes of the interior web of the tire. Heavy lines have been sketched on the cut to indicate more clearly the positions of these lines of rupture.

The total mileage of the wheel which failed under baggage car No. 522 was 276,396 miles, up to the end of December last. It was run in the trucks of different cars during its term of service as the accompanying table shows.

*Record of wheel which failed under baggage car No 522*

In service	Months	Days	Under car	Weight of car	Mileage of wheel	Ave load wh
				<i>Pounds</i>		<i>Pou</i>
Jan 7 to Jan 21 1912		14	Mail and baggage, 3510	118,700	6,874	
Jan 23 to Feb 29 1912	1	5	Baggage, 515	119,000	16,566	
Mar 14 to May 13 1912	1	29	Passenger, 612	135,000	26,245	1
June 14 to Nov 5, 1912	4	21	Baggage, 3031	129,160	66,160	1
Nov 18 1912 to May 3 1913	5	15	Mail and baggage, 518	118,700	75,611	
May 10 to Dec 2 1913	6	22	Mail and baggage, 3500	112,500	42,220	
Sept 25 to Dec 31 1914	3	5	Baggage 522	129,750	42,720	1
Total					276,396	



No 6 —Appearance of fractured wheel on axle as removed from truck after derailment. All fragments of tire were detached when train came to a rest.

Six-wheel trucks were used under each of the above cars

Actual time of wheel in service, 23 months, 21 days

The loads under which this wheel was run, were of moderate degree, not reaching the higher loads which are current in certain kinds of freight-car equipment

There were four kinds of wheels under train No 5, 18 of the type which fractured, as the following table shows



No 7—Wheel on opposite end of axle mate to fractured wheel Outside plate removed showing cast iron hub or spider steel tire and inside plate There were incipient cracks at each bolt hole of the tire as indicated in the cut

*Weight of cars and kinds of wheels used in train No 5 at time of derailment*

Car	Number	Weight of car	Average wheel load	Size of wheels	Number of wheels			
					Schoen	Standard	Paige	Chilled iron
		<i>Pounds</i>	<i>Pounds</i>	<i>Inches</i>				
Mail	518	118 700	9 890	33	4	4	4	
Mail and express	352	95 500	7 958	33				
Baggage	522	120 750	10 810	33	6	4	2	
Coach	667	131 980	11 000	33	8	4		
Do	608	135 000	11 250	33	6	2	4	
Do	604	135 000	11 250	33	6	4	2	
Diner	P	130 500	10 875	38	4	2	6	
Parlor	Mineola	140 000	11 667	36	12			
Total					46	20	18	

The number of incipient cracks which were disclosed at the bolt holes of the tires of the two wheels from baggage car No 522 led to a further examination of wheels of this type taken from other sources. Some of the additional wheels examined, as previously remarked, had tires which cracked in service and had been removed for that cause, while others had been removed on account of having been worn to the minimum thickness permitted.

The tires of 20 wheels were examined. Of this number 9 tires had incipient cracks at 56 of their bolt holes. In addition to these incipient cracks there were 13 lines of rupture which completely separated the metal of 5 tires, and 6 incipient cracks in the shoulder fragments of the tenth tire. In all, the total number of incipient and complete fractures at bolt holes in 10 tires was 75. In the other 10 tires of the 20 examined, no fractures at the bolt holes were found.

In the table following are given the results of this examination including in the tabulation the two wheels of baggage car No 522.

## STEEL-TIRED BUILT-UP WHEELS

*Incipient cracks in webs of tires, between bolt holes and interior diameter of tire, found in worn wheels when dismantled for examination*

Car	Diameter of wheel	Marks on tires	Number of incipient cracks	Remarks
	<i>Inches</i>			
Baggage No 522	33	Z215717 Latrobe	7	On fragments of broken tire
Do	33	999002-4 Latrobe	12	On mate of wheel with broken tire
Axle removed from truck	33	953983 Latrobe	9	
Do	33	A8965-2 Latrobe	0	Comby tread } Wheels from same axle
Do	33	998817-5 Latrobe	6	Tire cracked in service across bolt hole
Do	33	998852-3 Latrobe	2	
Sleeper Beaver Dam	38		1	Do
Do	38		6	
Sleeper detached wheel	36	A45382-4 Latrobe	7	Do
Do	36		6	
Total			56	

The incipient cracks which were found in the tires of wheels on an axle from sleeping car Beaver Dam are shown by figures Nos 8 and 9. These were 38-inch wheels, one of which developed a crack in service separating the tire at a bolt hole as shown by figure No 8. In this tire there was an additional fracture, an incipient crack at the fourth bolt hole from the line of rupture which separated the tire.

In the mate to this wheel there were six incipient cracks at bolt holes, the positions of which are shown on figure No 9. These two cuts represent the wheels with their outside plates removed, crosses sketched thereon indicating the positions of the fractures. Cored spiders are used on wheels of this diameter, as shown in these cuts.

The feature to which attention was next directed, was the state of internal strain which had been introduced into the metal below the treads of the tires by reason of the cold rolling action of the wheels upon the rails, alluded to in the remarks concerning the reduction in the radius of curvature of the fragments from the wheel of baggage car 522 and the springing of the tires when cut apart radially.

This cold rolling sets up strains both in the head of the rail and in the tread of the tire, parts which react upon and influence each other. The zones of metal immediately affected are next the surfaces of the treads of the tires and the running surfaces of the heads of the rails. Internal strains of compression are introduced at these places, which remain as permanent effects in the steel, unless the metal is subsequently annealed, by which treatment such strains may be removed.

The presence of and the kind of internal strains, whether of tension or compression, is made known by affording the metal an opportunity to assume a state of repose. When relieved from restraint, the direction of the resilient movement of the steel indicates the kind of strain which was in the metal, the magnitude of which is proportional to the amount the metal recovers in its length.

Internal strains of compression, immediately below the surface of the tread, tend to cause the tire to assume a larger diameter when the wheel is intact. In the case of a detached tire the effect of such strains is to cause the ends to spring toward each other when the tire




No 8 —38-inch built-up wheel from sleeper Beaver Dam. A. Removed from service on account of cracked tire. One additional crack at bolt hole shown when wheel was dismantled. Complete line of rupture of tire and incipient cracks indicated by crosses sketched on the cut.

is cut apart radially That is, a chord measurement on a tire decreases in length when a radial cut bisects it

The ends of these tires, as will appear, sprung together when cut radially, indicating the release of internal strains of compression in the metal next below the treads

Eight tires were slotted apart radially, and the relief to the metal thus afforded, was noted Included in this examination was a tire of a fused cast iron center coach wheel, that is, a steel-tired wheel which had a gray iron center cast or fused in place The fused wheel had had a large part of its rim broken off in service



No 9—38 inch built-up wheel from sleeper Beaver Dam B Mate of wheel A Six incipient cracks at bolt holes revealed when outside plate was removed and web of tire examined Position of cracks indicated by crosses sketched on the cut



The results obtained with these tires are shown on the table which follows

*Table showing the amounts the ends of steel tires sprung together when radial cuts were made*

Car	Diameter of wheel	Marks on tires	Amount ends sprung together	Remarks
Baggage 522	<i>Inch</i> 33	999002-4 Latrobe	<i>Inch</i> $\frac{11}{16}$	Mate of wheel that fractured at time derailment of train No 5
Sleeper Deaver	35	1955-3 Latrobe	$\frac{11}{16}$	This tire cracked in service across a bolt hole It was slotted at the crack
Do	33	995010-4 Latrobe	$\frac{11}{16}$	Mate of wheel next above Tire was intact excepting 6 incipient cracks at bolt hole
Detached wheel	33	Z 170938	$\frac{1}{16}$	$\frac{3}{16}$ -inch on a side was turned off the tread and flange of this tire before it was cut apart
Do	33	953983 Latrobe	0	Tire was annealed heated to a bright yellow and cooled over night in furnace then cut apart
Sleeper Vinara	36		$\frac{11}{16}$	The interior web of the tire was turned before cutting apart radially
Detached wheel	36	A 26765-5 Latrobe	$\frac{1}{2}$	Tire cracked in service Line of rupture $1\frac{1}{2}$ inches from bolt hole Incipient position of rupture, outside corner of tread
Sleeper Shasta	38	Cast iron center branded 'Railway Steel Spring Co. Feb 12 1907'	$\frac{1}{2}$	Steel tired gray iron fused center


As shown in the table, the ends of the tires when cut apart radially sprung together amounts normally appearing to range from eleven sixteenths to fifteen sixteenths inch

These results represent the state of initial strain existing in the tires of wheels which have been in service They are strains which are introduced chiefly by service conditions, and it is immaterial, far as dislodging them goes, whether the tire is cracked in service or not, the strains remain The second tire in the tabulation failed in service developing the crack which is shown in illustration No 10 but notwithstanding which, the ends sprung together fifteen sixteenths inch when removed from the plates and slotted across on the line of rupture Its mate, which had its rim intact, closed in the same amount, when cut apart radially The residual effect of cold rolling was the same in each tire

The direct effect of cold rolling is confined to a zone of metal near the tread Turning off the metal of the tread removes some of the metal which is in a state of initial compression, and lessens the distance which the ends spring together when a radial cut is made The fourth tire was turned off at the tread and flange three-sixteenths inch on a side This sprung together seven-sixteenths inch when cut radially Annealing the steel eliminates initial strains and will be noted in the case of the fifth tire that no closing in occurred

when cut apart, all measurable initial strains having been removed by the process of annealing

Figure No 10 shows a tire which had been cut apart radially. Two cuts in the slotter were made on this tire, each cut being 1 inch wide. After the first cut was made the ends sprung together, leaving an opening one-sixteenth inch wide. A second cut, 1 inch wide, was made which left the ends  $1\frac{1}{16}$  inches apart as shown in the illustration.




No 10.—Tire of built up wheel cut apart radially. Ends closed in  $\frac{1}{16}$  inch. Two inches width of metal was slotted out leaving the opening between the ends  $1\frac{1}{16}$  inches as shown in this illustration.

The first five tires of the table belong to one group of wheels. The sixth tire was the mate of a wheel which broke in service. The latter separated into six main fragments and five smaller ones, comprising parts of the tread and flange. The interior web of the sixth tire was turned off before slotting. The removal of this metal did not mate-

rially affect the amount of springing of the ends when slotted apart which closed in fifteen-sixteenths inch, an amount which seems abnormal in these tires

The seventh tire was from a detached wheel, which had been moved from service on account of a crack separating it. The failure of this tire differed from the others which were included in present examination, in respect to its passing through the full cross section between bolt holes. Furthermore, in its development it traveled in an opposite direction, starting from the outside or tread of the tire and extending across and radially inward.




No. 11.—Cross section of tire of built up wheel which fractured across full section of metal  $1\frac{1}{2}$  inches from a bolt hole. The line of rupture started at the corner of the outside face of the tire indicated by sketch on the illustration.

The incipient point of rupture was at the corner of the tread, the outside face of the tire. It was slotted along the line of rupture whereupon the ends closed in one-half inch. The appearance of the fractured surface of this tire is shown in figure No. 11, on which stars have been sketched to indicate the place where the line of rupture had its origin. This fracture had its origin at that part of the tire which is not exposed to cold rolling on the rail head, and only reached by the brake shoe. The metal appeared sound in that vicinity, but harder than at other parts of the tire. This illustrates a fracture occurring where increased hardness and brittleness of the steel has probably been induced by the action of the brake shoe, the severity of such action not having reached, however, a stage in which the

development of thermal cracks had formed. Evidence of heating of the tire if such had occurred was not present. It is of interest to determine the characteristics of these early changes in properties which culminate in rupture and make observations which will lead to their recognition, that danger zones may be made known.

Alternate heating and cooling through brake action induces loss of integrity by the development of thermal cracks. Examples of the kind furnished by the rupture of this tire lead to the query whether limiting stresses may not be received and rupture approached



No. 12.—Cross section of tire of built up wheel showing the darkened surface of an incipient crack in the thin section of metal at side of bolt hole of the web. Line of rupture extended outward radially from the bolt hole.

under service conditions unattended by outward, visible manifestations. The failure of this tire, excepting the local hardening of the metal, which was not extreme, bears a close resemblance to fatigue fractures, those resulting from repeated alternate stresses in which the approach to rupture is not heralded by outward signs. Wheels are, preeminently, good examples of material subjected to repeated stresses. The mileage of this particular wheel is not known, but that of baggage car No. 522 furnishes a convenient illustration. The mileage of the latter, ending with December last, was 276,396.

miles This calls for 170,000,000 rotations, in round numbers, at each rotation of which alternate stresses were received Blake-shoe action, which had not, however reached the stage in which the metal of the ~~tire~~ was actually ruptured, combined with repeated stresses were probably potential influences in the fracture of this tire

Figure No 12 is introduced to show a line of rupture which traveled in the opposite direction from that illustrated in cut No 11 This line of rupture traveled radially outward from the bolt hole to the surface of the tread and through the flange It represents also a section of tire in which an incipient crack had formed, shown by the darkened metal between the bolt hole and the inner diameter of the web

The eighth tire in the tabulation of results on those which were cut apart radially was taken from a steel-tired wheel which had a gray iron fused center Two pieces of the tread, each about 2 feet long, had been split off in service The steel tire was removed from the gray iron center by a circular cut in a boring mill after which it was cut apart radially, midway the side from which the two fragments were detached When the radial cut was made the ends closed in a distance of three-fourths inch

The springing of these tires, when cut apart, corresponds to the movement observed in steel rails when the heads of those which have been in service are detached from the webs The heads of such rails assume a curved shape, convex on the running surface, while these tires behave in a similar manner, increasing their convexity when allowed to do so The introduction of internal strains, in conjunction with the effects of repeated stresses, in the manner in which each are received in service are factors which affect the integrity of materials of this kind

The examination of the steel-tired, fused cast-iron wheel was carried along jointly with those of the type which failed under baggage car 522 The fused wheel did not cause a derailment It was on the middle axle of a 6-wheel truck One fragment of the rim was found 26 miles, and the other fragment 35 miles to the rear of the place where the injury to the wheel was discovered The axle had become considerably sprung at the time the train was stopped When this examination was made the axle, placed on dead centers, ran out at the middle of its length  $1\frac{1}{8}$  inches The journals and wheels were correspondingly out of true, the maximum and minimum distance between the inside faces of the wheels now being  $53\frac{1}{4}$  and  $52\frac{7}{16}$  inches, respectively, a difference of  $1\frac{5}{16}$  inches The two detached fragments covered nearly one-half the circumference of the tread, notwithstanding the loss of which and the bent condition which the axle eventually reached, the truck was not derailed The train was brought to a stop without injury

The fractured surface of the tire showed seamy metal, and in appearance resembled the surfaces witnessed in certain rails having split heads. Figure No. 13 shows a part of one of the seams in this tire, along the line of which one of the fragments was detached. The metal at the immediate surface of the tread was flaky, and at a stage prior to actual failure the wheel probably showed an increased width of tread. The fractures of the tire are attributed to the presence of the seams, one of which was 8 inches long, which were revealed on the surfaces which were brought into view. Lateral flow of the metal at the tread caused, it is believed, the enlargement of the seams which resulted in the detachment of the two fragments.



No. 13.—Steel tired fused cast-iron wheel. Fractured at a seam 8 inches long located  $\frac{1}{2}$  inch below the surface of the tread. Surface metal at tread exhibited a laminated appearance with evidence of lateral flow.

The metal in other parts of the tire was found to be seamy. Tension tests showed the metal to possess only limited elongation in a tangential direction, while taken crosswise the tread the metal in one test fractured at a seam without appreciable elongation. A supplementary crosswise test piece showed an elongation of 0.8 per cent. The results of the chemical analysis and tension tests next follow.

*Metal of steel tire of wheel with fused cast iron center*


CHEMICAL ANALYSIS

Carbon	0.69
Manganese	.58
Silicon	.32
Sulphur	.031
Phosphorus	.03

## TENSILE TESTS

Direction tested	Diameter	Sectional area	Elastic limit per square inch	Tensile strength per square inch	Elongation	Contraction of area	Appearance of fracture
Tangential	0.505	0.20	Pounds 52,150	Pounds 96,800	Per cent 2.3	Per cent 3.5	Granular
Supplementary crosswise specimen	.356	.10		97,740	8		Do

The display of a limited amount of extension or its entire absence in tensile test piece does not necessarily signify that the steel is devoid of the ability to flow under wheel pressures. There is a distinction to be made between the elongation which steel is capable of developing when extended by its own tensile strength and its malleability or the elongation which it may display under cold rolling pressures or by swaging. When deformed by an independent force steel admits of greater extension than witnessed in the tensile test. The fractured ends of the tangential test piece, which developed 2.3 per cent elongation



No. 14.—Fractured ends of tangential test piece. This specimen displayed 2.3 per cent extension in the tension test. Fractured ends subsequently cold swaged an additional extension of 16 per cent the metal still remaining intact tangentially.

tion, were swaged cold, and each given 16 per cent additional stretch. The swaging was discontinued when interior shearing fractures were developed, the metal still remaining intact as regards longitudinal extension.

Figure No. 14 shows the fractured ends of the tangential test piece after swaging. Lines are sketched across the stems indicating the amount of extension which was displayed in the tension test and the additional extension which was subsequently given the steel by the operation of swaging, representing its malleability.

Across the line of a streak or seam the malleability of the steel is impaired, whence it follows that split treads of steel tires necessarily result when in the lateral deformation of the metal interior defects of this kind are encountered. Split heads in rails are formed in a similar manner. The elimination of streaked or seamy metal is a matter of the highest importance to attain in steel that is used in situations in which there is exposure to overstrains normal to the direction of the seams.

Referring to the fracture of the built-up wheel which led to the derailment of train No. 5, and in summation of the results of this inquiry, it appears—

That this wheel and others of this type do not show unity of action in the component parts under service conditions as manifested in the evidence of movement between the tires and the plates, which in some cases pertained also to the relations between the plates and the spiders of the hubs.

That incipient cracks are developed in the tires separating the metal between the bolt holes and the interior diameter of the web.

That complete fractures of tires very frequently extend across the bolt holes, having their origins at the inner diameter of the webs or at the sides of the bolt holes, thence extending radially outward through the tread and flange.

That service conditions induce the formation of incipient cracks on one side of the bolt holes, and lead to their extension on the opposite side of the bolt holes, culminating in the complete fracture of the tire.

That the presence of incipient cracks does not admit of detection, without partially dismantling the wheel and giving access to the interior web of the tire or to the sides of the bolt holes.

That looseness of the tires under the wheel loads takes place, but does not admit of detection by hammer test or by external inspection of the wheels in the truck.

That internal strains are introduced in the metal of the tires by reason of the cold-rolling effect of the wheels on the rails, and that the combined strains from wheel loads and internal strains require to be



considered in judging of the ultimate effects of repeated loads in promoting rupture

### SUMMARY

The results of the investigation of this accident and the study of other wheels similar in type and construction to the wheel that failed in this instance, as set forth in Mr Howard's report, call into question the strength and durability of wheels of this type for modern railroad service

In this instance a tire broke in a wheel which had not been subject to loads as high as are frequently experienced in certain other branches of railway service. The loads carried by this wheel in fact are regarded as moderate loads for general equipment, since they ranged from 9,375 pounds to 11,250 pounds. The investigation revealed the presence of incipient cracks in a considerable number of wheels of this type. Out of 20 wheels examined, one-half were found to have incipient cracks in the interior web of the tire, 56 incipient cracks and 19 fully developed fractures were discovered. It is true that these wheels had been removed from service for cause, but the presence of these incipient cracks was not among the causes which led to their removal.

That wheels run for a length of time with incipient cracks in the tires is probable, and, obviously, cracks that have started in one part of a tire are liable to extend and cause the complete failure of the wheel. Those wheels which were removed from service, containing the 75 fractures, undoubtedly had such cracks in them for a time prior to their removal.

A sufficient number of wheels were included in this investigation to establish the general development of incipient cracks in this type of wheel, although the period of their formation is unknown.

The stresses to which the wheels are exposed do not admit of direct measurement, since the parts which are failing are inaccessible, but the development of incipient cracks in the thin sections between the bolt holes and the interior diameter of the web is taken to be evidence that disruptive strains are there found. The introduction of internal strains of magnitude in the metal of the tires immediately below the surface of the treads was found to be a common result of service conditions. All tires examined were so affected. The same results appear in this investigation in respect to the influence of cold rolling in the case of tires, as have been found in the case of rails. These two parts react upon each other and whatever has an influence upon one must affect the other. Conditions which attend the failure of rails have their counterpart in the case of tires.

In the light of this examination the details and design of this type of wheel seem inadequate for the wheel loads which are commonly

used in passenger service. The wear at the edges of the plates, the grooving of the tires at the plate seats, and the wear and shoulders formed on the inner faces of the plates all go to show a state of insufficient strength to meet present requirements.

There is but little strength in the thin sections in which the incipient cracks made their appearance, and it was noted that the drilling of the holes was made in such a manner that the sections were not of uniform thickness, further, that the thinner sections in the majority of cases were those in which incipient fractures were discovered. A state of uncertainty nevertheless exists which is brought out in this investigation and further data are required to remove the doubts which have arisen in respect to the present condition of wheels of this kind which are now doing service.

In the derailed train there were 18 wheels of the type which fractured. In the ordinary course of maintenance, wheels are removed, sent to the shop to be trued up, and are returned to service under different cars than those from which originally taken. It therefore follows that a mixed lot of wheels may be found under a given car. In the present instance there were four makes of wheels in the same train and three kinds in the trucks of the car which had the broken wheel.

If the wheels of this type are in a state of uncertainty as to strength, as inferred to be the case according to this investigation, then their distribution under different cars complicates the matter, for their presence may occur under any equipment and in any train, and incidentally they may be placed under high-speed trains quite as likely as under those of other classes.

Under the most diligent inspection and thorough tests that can be made with the wheel in the truck, those with incipient cracks might appear sound. The critical places in the construction of wheels of this type are obscured from view, and can be made visible and accessible only by the partial or complete dismantling of the wheel. Inspection, however critical it may be, will not reveal incipient cracks which are hid by bolts and plates. This feature of the case is a serious one, since there appears no way in which the condition of wheels when in service can be determined and those having incipient cracks in the tires discovered.

It is clearly established that the usual inspection of wheels of this type in service is not adequate to discover these incipient cracks and that no inspection which can be made of the wheel in the truck can detect the presence of a defect such as led to the failure of the wheel in this instance. It is understood that wheels of this type are not being used so extensively as formerly, although a very considerable number of them are in service at the present time. To determine

definitely whether or not wheels of this type now in use are in proper condition for service, the ordinary wheel inspection should be supplemented by inspection of the metal at the bolt holes as one of the methods of ascertaining the probability of approaching rupture

Respectfully submitted

H W BELNAP,  
*Chief, Division of Safety*