IN RS INVESTIGATE OF A MARKET STATE OF THE GRANT OF THE ANALYSIS AND A MARKET.

: etcher 29, 1919.

In Leptember 19, 1919, there was a regreend aciliston between two freight trains on the Great Northern Railway at arland, Sont.. which resulted in the death of I employee and I caretaker of stock and the injury of I employee. After investigation of this accident, the Chief of the Bureau of Safety reports as follows:

The district of the Great Northern deilway on which this accident occurred extends from bitefish, Mont., to Troy, Mont., a distance of 134 miles. It is a single-track line, over which train movements are reverned by time-table and train orders, no block signal system being in use. Truins of the same direction are spaced 10 minutes apart at telegraph stations. Deginning at the station board at Sarland and a prosching the point of sealdent from the cast there are 1.706 feet of tangent track followed by a 1-degree curve to the left 1,374 feet in length, them 3,718 feet of tangent track, a 1-degree ourse to the left 621 feet in length and 1,208 feet of tangent track & the point of accident. .. train standing at the point of accident my te seen by the engineers of a train approaching from the east for a distance of about 2.500 feet. The grade at the point of accident is lovel. The are d of freight trains over this line is restricted by time-card rule to 20 miles an hour.

Wes bound freight train extra 103, consisting of a locamotive.

17 loaded cars, 6. empty cars and a caboose, in charge of Conductor

Tykward and Angineman Jurham, left whitefish at 10.50 p.m., 'eptember 18, and arrived at Rexford at 6.50 a.m., extenser 19.

At Rexford, Lagineses burkes, on account of sickness, was relieved from duty by Traveling Engineer Shouf, and he went to the cab case to deadhead to froy. Axtra 5108 left Rexford at 9.05 e.m., with 16 cars and a caboose, after receiving train order \$0.234, which read as follows:

Order 1234.

47

3. A s. Axtra 5103 Fest Eng 3103 run extra Rexford to Troy meet extra 3059 dast at hexford. Has right over two extras 1754 and 1320 dast Rexford to Libby, but wait at tral 9.50 A.M. Volcour 10.00 s.d. Sarland 10.10 A.Y. Yearnell 10.25 A.M. Jennings 10.40 A.M. for two extras 1754 and 1320 dast.

The train passed Stonehill at 9.30 a.m.. Volumer at 10.22 a.m., and arrived at Farland, 31.56 miles west of Rexford, at 10.12 a.m., where it was stouped on account of the train order board being in the stop position. Extra 5105 had been standing at this point about 2 minutes when its rear and was struck by extra 1752.

September 19, with a locomotive and 16 loaded cars in charge of Conductor Hinds and Engineeran Lakenyon. At 8.40 s.m., this train arrived at Aexford where the crew received train order No. 236 reading as follows:

Crdor #238

C. A. Z. Axtra 1758 Vest
Lugineer 1752 run Axtra Mexford to Iro, meet extra
3059 dest at Rexford, has right ever two extra 1754
and 1550 east Rexford to Libby, but weit Ural 9.50
4.8. Velcour 10.00 A.E. Variand 10.10 A.M. Ferrall
10.25 A.M. Jennings 10.40 A.E. for two extras 1754
and 1320 hast.

Extra 1752 left dexford at about 3.50 a.m., passed stonehill at 9.46 a.m., 16 minutes behind extra 5165, and at 10.14 a.m., while running at a speed estimated to be about 15 miles an hour, collided with the caboose of extra 5105.

The cabocse of extra 3103 was of secten construction and was entirely described; the box car immediately sheed of the caboose was entirely destroyed and the self-ining car was also damaged.

The locomotive of extra 1752 turned ever on its left side. The persons killed were fireman the tout and a man who was in charge of live stock; both were riding in the caboose of extra 3103.

conductor Tykserd of extra 3102 stated that his train arrived at mexford at 6.50 a.m., on the serming of the section and seme time before leaving, extra 1752 arrived at that cint. He stated that he amilianductor Hinds of extra 1752 were at the telegraph effice at the same time asking for orders, but he did not see the orders received by Conductor Hinds, nor did Conductor Hinds see the orders he received. He stated further that his train arrived at Sarland at 10.12 a.m., and stopped on account of the train order board being in the stop position. Show the train stopped he started forward toward the head and of the train, while his flagman started back to flag. He said exactly two minutes clapsed from the time his train stopped until it was struck by extra 1752.

Rear Brakeman Scott of extra 3105 stated that upon arrival at Warland his train stopped and he started back immediately to flar and had gone about 4 or 5 pages when he saw extra 1752 approaching on the straight track west of the curve. He then got back on the caboose in order to warn the men who were in it, got off again and ran toward the approaching train with a red flar in his hand. He reached a point about 50 feet from his cabecse when the locomotive of extra 1752 passed him. He stated further

that he had not seen extra 1752 since leaving dexford and did not know it was following so of sely behin... He did not know that his train would stop at barland and had not thrown off fusion approaching that point.

Preveling Engineer shoof, of extra 3100, stated that his train left Rexford at 9.05 s.m., passed stonehill at 9.30 s.m., passed Velcour at 10.02 s.m., and arrived at 'arland at 10.12 s.m. He thought the average steed of his train between Rexford and tarland was 30 miles an hour and he estimated that about 2 minutes clapsed from the time he stopped to the time his train was struck by extra 1752.

firemen Christensen of a tra 5100 stated that he thought the everage speed of his train between mexford and warland was 26 miles an hour and he stated that the, did not stop at any point. He thought about 2 minutes elapsed between the time his train stopped at Warland and the time of the collision.

Conductor Hinds of extra 17-2 stated that his train arrived at Rexford at 8.40 a.m., and then he went into the office for orders, the conductor of extra 3102 was also in the office and both extra 3102 and his own train were figuring on leaving Rexford on the arrival of train No. 4. He did not see the orders received by Conductor 1, kward nor did Condo tor Tykward see the orders he received. He stated that train No. 4 arrived at Mexford at 9.05 a.m., and extra 3102 decorated soon thereafter, but he did not know the exact time. He stated that his own train left dexford not later than 9.25 or 3.27 a.m. He was riding in the cuphle of the caboose approaching the point of socident and he said that the gaves in the caboose showed 75 pounds train line pressure

at this time. He saw the caboose of extra 3103 at about the same time as his enginemen made an emergency application of the brakes. He estimated that the daboose of extra 3103 could be seen from a point about 50 car lengths distant. Conductor Rinds further stated that according to his judgment the speed of his train between Rexford and Warland was from 55 to 58 miles an hour, and while he know this was in excess of that allowed by the time-card rule, he thought it was a safe rate of speed and made no attempt to have it reduced. He also stated that it was customary for conductors on this line to allow enginemen to use their own judgment as to speed and to make up all the time possible.

Head Brakeman Spencer and Rear Brakeman Sloan of extra 1752 estimated the speed of their train between Reaford and Agriand at about 35 miles an hour. Brakeman Spencer saying it was no feater than is made every day. Both were riding in the emboose of entra 1752 and neither saw the caboose of extra 3103 until the engineman had made an emergency application of the air brakes.

Angineman Laminnyon of extra 1752 stated that he saw extra 3103 ahead of him at Rexford, but did not know what train it was. He then went in to eat broakfast and when he returned to his train, the train ahead had gone. He stated that his train left dexford between 9.20 and 9.25 a.m/, and that its speed between Rexford and Warland was 35 or 36 miles an hour. He and the fireman naw extra 3103 at Warland at mout the same instant, at which time the engine had received the straight track or about 1200 feet from the caboose and was running at a speed of about 30 miles an hour. The engineman stated that he immediately applied the brokes in emergency, but the brake valve worked

hard and required him to use both hands. We said the speed was reduced to about 7 or 8 miles an hour and he was unable to reduce the speed forther, the train running along at that rute of apead until it collided with the train sheed. He stated further that the braking power on his train was better than on many trains be had handled and that he had had no trouble in stoppily at any provious time; the brakes were not responsible for his not stopping in time. it was the short distance. Aith his train running at a speed of 35 miles an hour be thought be should be able to stop within a distance of 2,000 feet. ingineman Lakunyon attributes the accident to his not being informed of the fact that both his train and extra 2103 held orders containing the same waits, and he said that had he known extre blow was just ahead of his he woul: have entered arland under control. sise thought that if a fosee had been thrown off by extra 3105 he could have stopped in time to avoid the collision and is sure that if he had eighted of the 21)2 when 2 or 4 car lengths farther east, he could have stopped before striking it. He. also stated that all enginemen on this district exceed the enced limit of 30 miles an hour.

Fireman init of extra 1752 stated that a proaching arland the stoker had stoped and he was turning on steam; he outlinated that when he I oked up and saw the rear end of extra 5102 whead, his train was about the par congites from it. He called to agine can make myon who immediately a lied the brakes in emergency. He was the resular fireman on the capine and said that semotimes the brake valve handle would catch in the last notch before emergency and he thought that the eriod of time that

the handle would stick in that position would be long enough to destroy the emergency feature of the brakes. He did not know that the trouble had ever been reported.

Operator McCarthy on duty at Monchill stated that extra 3108 passed his station at 9.50 a.m., and extra 1702 at 9.66 a.m. He said both trains were going at a pretty high rate of speed but that the second was going considerably factor than the first.

Station Agent Randell at Warland stated that extra \$105 arrived at Warland at 10.12 a.m., and that the collision occurred at 10.14 a.m.

Cperator Grageon, on daty at Benford, stated that while he was preparing orders for Conductor Tykward of extra 3103. Conductor Hinds of extra 1752 came into the office and said "You might as well fix me up, we will be ready to go on the arrival of train No. 4 too". He stated that his records show extra 3103 as leaving Renford at 9.05 and extra 1752 as leaving at 9.30 a.m.

Dispatcher Depen on duty between 8.00 a.m., and 4.00 p.m., on the day of the accident stated that it is not ometomary to give one extra train copies of the orders received by a creating extra, and that the management has criticised the practice of verbally informing one train of the whereabouts of other trains. He said when he went on duty his instructions were to the effect that lecomotive 3103 was to tie up at Rexford and that lecomotive 1752 was to pick up both trains. Later he learned that Traveling Sugimeer Shoaf was to handle extra 3102 and could reach Tray within 16 hours providing he received through orders, or orders that would cause no delays. Therefore, in order to expedite

r ()

the movement of extra \$100. Mapatcher Jecow put out order ho.

254 to that train. At that time he thought extra 1762 would

not be ready to leave derived for some time, but shortly afterwards 'perator Jregoes informed his that estra 1752 was ready

to go and he then issued order So. 288 to extra 1752, which order

contained the same waits as order Bo. 284 issued to \$102. He

said that had he known that both extras were going to leave

derived near the same time, he rould have included both trains

on the same order.

This ecoident was osused by Engineens Lawrence of extra 1752 exceeding the appear limit and his Sailure to have his train under such control as to enable him to stop when he saw extra 2103. Hule 481 of the Great Northern Hailway Company reads as follows:

"Engineers of trains following other trains must approach stations with dare and with train under such control as will enable them to avoid collision with trains sheed."

The exact wise entra 1762 left dexford is dismited. The operator says it cleared at 9.20 a.m. and so he reported it. while the conductor mays the train started whead on the siding at 9.22 a.m., and that it was not later than 9.26 or 9.27 a.m., when the train tenched the main line and the switch had been The engineean mys the train started between 9.20 and 9.25 a.m. If the train left at 9.30 a.m., then it consumed only 44 minutes in traveling flow Rexford to carland, a distance of 31.55 miles, or an average rate of aread of about 43 miles an hour. If it left doctord at 9.25 c.m. then it consumed 49 minutes, with an average speed of nearly 39 miles them it is also considered that the fastest westbound an hour.

train on the road, a mail train, which does not stop either at Rexford or wriend, consumes all minutes between the two stations, it is clear that extra 1782 was being operated at an excessive rate of seed. Had the train been operated at a rate of speed within the limit permitted by the time-eard rule, and had inginement takingon been maintaining a proper lockout approaching harland, it is probable that he would have been able to stop his train in time to avoid the collision.

On the joy following the socident a test was made to ascertain the dictance from which an object at the point of accident could be seen. A tender was placed at the point where the caboose of extra 3103 stood at the time of the accident and was approached from the east on locometive 3110. It was found that without leaning very far out of the window of the locometive the engineers was able to see the tendergwhen 2,542 feet distant therefrom. The curvature approaching the point of specifient is slight, there are no trees or buildings to obstruct the view and no reason can be assigned for the failure of anginessan LaManyon to see an a justly long distance on the day of the accident.

a test was also made of the brake valve on the locamotive operated by anginessen Lawenyon on the last of the socident, but nothing wrong with it could be found. Two other tests were made of the brakes on the train and while two of the care showed li-inch viston travel and another a 4-inch piston travel, the brakes on the whole were in good condition.

Enrineman Lakenyon was employed as a fireman on this division in Aril, 1910, having previously worked eight years on other divisions and railroads as fireman. He was promoted to ensineman in

e e 🍅

Ţ

August, 1916. In July, 1917, he was given a 15-days suspension when it developed that he operated his train at a high rate of speed, knowing that emother train was ahead, which resulted in his train running into the rear of the preceding train.

At the time of the accident the erew of extra 1752 had been on duty less than 5 hours.

This accident serves to call attention again to the weaknesses of the train order systems of operation, under which a train moving at a high rate of speed may close up on a clower moving train without warning of the movements of the train shead with the result that it may at any time suddenly come in sight of that train and be anable to stop in time to avoid a collision, as went he case in this instance. Had an adequate block signal system been in use on this line, this accident would undoubtedly not have occurred.