In re Investigation of accident on the Lebigh Velley Bailroad, near Slatington, Pa., on July 27, 1913.

September 2, 1913.

On July 27, 1913, there was a rear-end callieion between the freight trains, and a passenger train ran into the wrockage, on the Lehigh Valley Railroad, near Slatington, Pa., resulting in the death of 1 cm, loyer and the injury of 27 passengers and 4 caployees.

After investigation of this accident the Chief Inspector of safety appliances submits the following report:

Where this accident occurred the Lehigh Valley Railroad is a double track road, operated under the automatic block signal system, dick signals being usel. At the point where the accident occurred there is a slight descending grade toward the east, and the track is on a thirty-foot fill. Approaching from the rect. signal No. 1072 can be seen for a distance of nearly a mile before it is reached. Proceeding eastward from this signal, there is a five-logred curve, 1460 feet in length, which is followed by a tangent of 1032 feet, and then there is a four-degree curve 750 feet in length, extending to signal No. 1062. The collision occurred about 100 feet east of this signal. At the time of the accident there was a hight mist rising from the river near by, but signal lights could be seen plainly.

Enstbound freight train Extra 1351, consisting of an engine, 46 cars and a caboose, with Conductor Mosppel and Engineman Miller in charge, left Mahoning yard at 11:15 p.m., July 86, on route to Easton, Pa. When this train approached signal No. 1062, about ten mile east of Mahoning yar, that signal was in the stop position and the train came to a stop as required by the rules. Extra 1681 then moved for and again came to a stop at 18:18 a.m., July 17, the caboose standing about 100 feet east of signal No. 1062. While standing at that point it was struck by extra 1684.

Eastbound freight train extra 1884, consisting of an engine, 20 cars and a cubocse, with Conductor Vitterline and Enginemen Malek in charge, left Mahening yard at 11:50 p.m., July 26, on route for Jersey City, N. J. When t is train approached signal No. 1072, that signal was in the caution position, indicating that the block shoot was occupied. Extra 1884 passed that signal, ran ever to terpedoes, parced the flagman of extra 1881, and signal No. 1082 which was in the danger position, and collided with the rear end of extra 1881 at about 12:22 a.m., July 27, while running to appeal of approximately 10 miles per hour. Consuctor Weepel the was in the cubocse of extra 1881 at the time of the collision was killed.

A refrigerator our an the cabose fouled the westbound track, and restbound massenger train No. 5 collided with the wrockuge of the care, not being maned of the danger in time to permit of a

material reduction of its speed. The passenger train consisted of an engine, I smoking car, I coach, I club car, 3 speeping cars and 3 coaches. This train was running at a speed of about 45 miles per hour when it collided with the wrockage, at about 12:24 a.m. The engine was derailed and the tender, smoking car and first coach were thrown down the embonkment.

Engine Miller of Extra 1381 stated that he brought his train to a stop just vest of signal No. 1062, which was in the stop position, and then started it ahead slowly, bringing it up nearly to a preceding train. Extra 1381 stood there about five minutes; just as he was ready to start the train, the air gauge showed that the precedure was falling; he thought a hose had bursted and he told the head brakeman to examine the hose. Just after the head brakeman started back, train No. 5 went past.

Flagman Eddinger of evtra 15% stated that when his train stopped for signal No. 1062 he placed one torpedo on the rail about one reil-length behind the coboose, and then the train started again he gut down another torpedo two r il lengths from the first one. The train moved up beyons signal 1082, the rear end being about have our lengths from that si mal when it stopped the second time, and the flagman started to walk back as soon as the train stopped. He thought be had sone back about 20 our lengths when extra 1684 come up. He stated that the enginemen did not acknowledge his signal until about the time the enginemen did not acknowledge his signal until about the time the enginement the torpedoes; he thought that steam had been shut off a en and when the engine passed him fire was flying from the driving heels, as if the brakes were set. The speed of the train at the time was about ten niles per hour. He say the brakes in jump off from the engine, the brakes noted him to go flag No. 5 and he started i mediately, but had gone only a short distance beyond the reak on No. 5 passed him.

Engineeran Walch of extra 1864 the det that on the night of the accident the air brakes as a property to be working on 27 of the 30 cars of his train; he is a constant of the running test of the brakes on leaving Mahaning yar, as a constant of by the rules, but expected to do so at Prescholer, a constant it hilles from Mahaning. He had no occasion so use the brakes of considering and the point where the collision occurred. The rules required that trains should not exceed a speed of 20 miles or have at a read crossing at Slatington, the last station act of be order of the accident. Engineeran Welck stated that he shut fill seem and let the engine drift at that point at a speed of about 15 stars per hour. He then began to use steem again, shutting off and first saw the caution signal; when the engine had passed sign 1 107% he made a 10 or 12 pound reduction; when the train has proceed a 1 or 20 car lengths beyond that signal his engine ran over to the continuous the danger signal, the flagman and the rear on it is 1381; he made a further resuction of from 12 to 15 pounds, and he saw the train was not going to be stooped in time of 11rd the brakes in emergency, without releasing, reversed to continue and used steam. He stated that the brakes 4id in the life or is angine was clogged up so that the sender could not be used. He of the brakes and sinder could not be used. He of the brakes and sinder

had operated properly the socident might have been averted. He made no examination of the brukes after the collision although the collision did not damage the brake equipment on his train.

Head Brakeman Ditterline of extra 1684 stated that he rede on the left side of the engine cab from Mahoning to the point where the accident occurred. Approaching that point he saw and called the coution signal, and the enginemen shut off steam. When the engine ran over the torpodoes which he thought were shout midway between the two block signals, he bgain called to the engineman, who applied the brakes. Soon afterwards he saw the rear end of extra 1381; he called to the engineman again, and as his train approached the stanling train he jumped off. After the callision occurred he say the flagman of extra 1381 and told him to go flag No. 5.

Conductor litterline of extra 1684 stated that as the train approached the point where the accident occurred he noticed that the engineers shut of stoom, the speed at that time being about 30 miles per hour, and soon afterwards the brakes were applied. He did not notice any further application of the brakes. He stated that he did not attempt to ascertain the reason for slowing down a trains ordinarily stooped for water at Rockdale, the next station, and it was not unusual to be delayed at that point. He thought the speed of his train at the time of the collision was 10 or 12 miles per hour.

Piroman Mothetein of ortra 1684 stated that just before the collision occurred he jumper off; he had a torch in his hand and he immediately started out to flag train No. 5.

Engineman Krumannocker of train No. 5 stated that as his train approached the scene of the accident he saw a man with a white light and a man with a torch signaling him to stop; he applied the brakes in emergency, but his train almost immediately collided with a car wich obstructed the pertound track. He stated that train No. 5 was running at about 45 miles per hour and that the brakes were in good condition.

Foreman Ditemer of the car inspectors at Mahoning year stated that then the brakes on a tr in have been examined a cyr is given to the engineman showing the number of brakes corking and the number not working. He stated that brakes are examined to see whether all of them are working and that the piston travel is projectly adjusted, and for looks. His report to the engineman of extra 1884 showed that there ere 50 cars in the train; on 27 the brakes ere sorking and on 3 they were not orking.

This accident was caused by failure of Engleman Walck to obey signal indications. But Enginees walck applied the brakes on his train in sime to insure that the train would be under complete controls it approaches signal No. 1062, the collision no doubt sould have

been everted. Enginemen Walck had ample warning in this case, as the caution signal could be seen for nearly a mile and that signal was located more than 3000 feet from the signal which indicated danger.

The rules of this railroad results that a running test of the brakes should be made when this train left Mohoning yard. Had such a test been male the engineers would have been informed regarding the efficiency of the brokes on his train and would have been better prepared to operate the brakes properly at the point where the collision cocurred. Rowever, in this case the brakes appear to have been in operating condition; the exemination made before this train left Mahaning yard showed that there were 27 brokes in the train which applied and released properly: and after the accident a further exemination of the brakes was made and then the train was hauled to its destination without any repairs to the brukes being made. It is believed, therefore, that had the enginoman used the brokes properly thore ould have been no difficulty in controlling the aread of the train and stopping the train before it passed the danger signal. It sy ears that the sand pipe on the engine wer elogged, but the engineers was aware of this fact as he had worked on this same wipe before leaving Mahoning yard, and he should have been prepared to stor sthout using sand.

Engineman Walck had been in the employ of this company for seven years as a firmum and for about one year as an engineman. His record was clear.