Chairman

IN RE INVESTIGATION OF AN ACCIDENT WHICH OCCURRED ON THE HASHVILLE, CHATTANOOGA & ST. LOUIS RAIL-WAY NEAR ESTILL SPRINGS, TRNN. ON AUGUST 1, 1919.

September 16, 1919.

On August 1, 1919, there was a rear-end collision between two freight trains on the Nashville, Chattanooga & St.

Louis Railway near Estill Springs, Tenn., which resulted in the death of 1 employee and the injury of 2 employees. After investigation of this accident, the Chief of the Bureau of Safety reports as follows:

The Chattanooga Division, on which this accident occurred, extends from Mashville, Tenn., to Chattanooga, Tenn., Estill Springs is located 77 miles a distance of 151 miles. south of Nashville and this railroad in the vicinity of Estill Springs is a single-track line, over which train movements are governed by time-table and train orders, no block signal system being in use. Approaching the point of accident from the south the track is tangent for about 2.348 feet. followed by a 1-degree ourve to the right 452 feet in length, a tangent 1.341 feet in length and then a 2-degree curve to the left 827 feet in length. The collision occurred on this last mentioned curve, 65 feet north of its south end, and 913 feet north of a bridge over Elk On the inside of the curve on which the accident occurred River. an embankment rises about 10 feet above the track and materially 11. Its the view of enginemen on approaching northbound trains. Approaching from the south the track is nearly level to within 900 feet of the point of accident, followed by a .97 per cent.

ascending grade to the point of accident.

On the day of the socident northbound freight train extra 402, in charge of Engineman W. H. Blessing and Jonductor Poe. left Cowan, Tenn. at 8.10 a.m., to do switching work between Cowan and Pullahoma; it arrived at Decherd. Tenn., at 8.20 a.m., and upon completion of the switching at that point departed at 11.54 a.m., consisting of locomotive 402, 16 cars and a caboose. Arriving at the south and of the Istill orrings passing track at 12.05 p.m., the caboose and 12 cars were left on the main track, while the locomotive and 4 cars were taken into the sand pit, about one-fourth mile distant, for the surpose of making a switching movement. At this time the conductor and flagman exchanged duties, the flagman going with the nead portion of the train to the sand pit, while the conductor remained to protect the rear portion. At 12.35mp.m., the locometive returned with 5 cars and had just coupled to the other 12 cars, when northbound freight train 1st No. 42 approached and collided with extra 402.

Northbound freight train 1st No. 42 was a test train operating for the purpose of determining the relative efficiency of hand and stoker-fired locomotives, and was in charge of angineman O'Donnell and Conductor Wiggs. This train, consisting of locomotive 653, 26 loaded cars, 4 empty cars and a caboose, left Chattancoga at 8.10 a.m., passed Decherd, the last train order office, at 12.27 p.m., and at 12.35 p.m., while traveling at a speed estimated to have been 10 or 12 miles an hour, collided with the rear end of extra 402 near Estill Springs.

The locomotive of train let No. 42 came to rest with its pilot and front end on the rear of a flat car of extra 402, with the cupols of the locomotive. Four terms of extra 402, including the caboose, were overturned and heally damaged. In train let No. 42, a wooden flat car was demolished while an adjacent car was derailed and another overturned. As a result of the collision Fireman Smith of train No. 42 was killed; J. C. Bleecing, local representative of the Brotherhood of Locomotive Fireman and Angineman who was riding on the locomotive of train No. 42, was injured and 4. No. Allies, mechanical draftsman, who was also riling on the locomotive of train No. 42 was slightly injured. At the time of the accident a drizzling rain was falling.

of his train at Latile porings, the locamotive and frost four cars were out off and he took this part of the train to the sampit where he left the four cars and picked up five others, returning then to the rear portion of the train. While his train was being coupled up, his fireman saw train No. 42 approaching from the south and called out to him, "Bill, I believe they are going to run into us." Then the angingman looked out and saw that a collision was inevitable, he counded the whistle to wern his brakeman who was between as a coupling up the air hose. Engineman Blessing said that he heard no torpeloes exploded nor any whistle sounded by train No. 42. He also said that about a minute elapsed between the time he first saw train No. 42 and the time of the collision and he was unable to pull his train out of the way.

Flagmen horvell of extra 402 stated that on leaving Decherd he asked his conductor whether they would leave the train on the main line at Estill borings while performing their duties in the sand pit or whether they would take the train on to the side track, at the same time suggesting to the conductor that, in order to s ve time, the train be left on the main track. He also made the suggestion to the conductor that the conductor protect the rear end of the tr. in while he attended to the switching in the He received instructions from his conductor which were sand oit. in conformity with his suggestions and upon a rival at estill borings he went to the sand oit with the locomotive and four cars. Within a malf-hour they returned to the main track with five cars and he was coupling them up with the balance of the train when the collision occurred. Flagman Norvell stated that he did not know how far Conductor ros went back to protect the train, but that if he had been doing the flagging he would have remained at the south end of Elk giver bridge until called in. He stated that the conductor had not been called in when the collision occurred.

Conductor fee of extra 402 stated that his train left
Decherd at 11.55 a.m. and that he had no information concerning
follo ing trains at that time. He stated that he had made arrangements with flagman harvell to go to the sand bit at Astill Jarings,
thinking that the flagman could handle the work there more
efficiently than he could. Then the train stooped at retill
barings, he started back with torpedoes and went back to mile post
78, about a nalf-mile distant, and there blaced two torpedoes on
the rail. He then came back to the south end of alk given bridge

from which point he could watch the locomotive of his train at work in the sand pit and there placed one torpedo on the rail. Then he saw his locomotive starting back to the main track with the 5 cars, he picked up the torpedo and started across the bridge He stated that the reason he started in as toward his train. soon as he did was so that he could get in promptly when called. Just before the hocomotive and five cars coupled to the standing ears, he saw train No. 42 coming around the curve, at which time he was about 20 per lengths from his caboose. He did not hear train No. 42 explode the torpedoes which he had left at mile post He stated that he started flagging the opmoaching train as soon as he saw it but the enginemen did not answer his signals. although he thought he had been seen, as when the train reached the south end of the bridget he saw dust and sand flying, indicating that the brakes had been applied in emergency. When the locomotive of train No. 42 passed him he yelled to the engine crew, but he Conductor roe stated further that he conreceived no response. siders 20 car lengths a sufficient distance to remain back to protect a train if the train is protected by tornedoes farther back, and he said he would not have re ained back farther to flag a passonger train. He also stated trat he knew of other instances when torpedoes mad failed to explode.

Engineman O'wonnell, of train No. 42, stated that the air brakes on his train were tested before leaving Chattanooga on the day of the additiont and all were found to be working properly.

After leaving Cowan he came down the mountain grade slowly, making about 3 applications of the brakes, and on each occasion the brakes

worked properly. At Deckerd he received a clear board and procoeded toward astill borings. At just about the tire he reached the worth end of the ...lk iver bridge and while running at a speed of about 25 miles an hour. J. C. Bles ing, who was standing beside him, called out to him, "look out, Jack," and at about the same time he grabbed hold of the brake valve handle, opened the sand lever and leaned out of the window. He saw the cabouse of extra 402 only 14 or 15 car lengths ahead and saw a man 4 or 5 car lengths south of the caboose, who he learned afterwards was Conductor : oe. He stated further that he reduced the speed of his train from 25 miles an hour at the time br. blessing spoke to him to 10 or 12 miles an hour at the time of the collision. Engineman o'Donnell stated he did not her any torpedoes or see the smoke of extra 402 as he approached astill Sorings, meither did he have any knowledge of extra 402 being ahead of him. stated that the time card authorizes extra trains to run shead of third class trains.

of train No. 42 and having charge of the fuel test being made, stated that approaching Estill Springs he noticed smoke near the passing track switch and remarked to .r. Blessing who was sitting behind him that if that train was on the main track, it looked near. As train no. 42 neared Estill Springs, he kept on looking shead, but failed to see anything of the caboose of extra 402 until the train had cassed over alk giver Bridge. At the time he saw th caboose he also say a man with a red flag; he immediately rushed to the right side of the locomotive and reversed

and opening the sand lever at the same time. He judged that the train was 14 or 15 car lengths from the same time. He judged that the the flagman of extra 402 and that the flagman was 14 or above; he estimated the above with in 10. 42 at that time to be 20 or 25 miles an hour. He further stated that he neard no torped see explode.

train No. 42 and assisting with the test, stated that the engineman did not exceed a speed of 30 miles an hour between Decherd and Estill Foring and that the speed was about 25 miles an hour across lik hiver bridge. Just before the caboose reached the bridge we felt the brakes go on an emergency and after the train had run a distance of not more than 15 car tenatus, he felt a second for which was caused by stalking the caboose of extra 402. he did not hear temporous and could not recall whether or not he heard a whistle signal of any kind as protein.

Conductor wiggs, of train No. 42, stated that he heard no torponces approaching actill Springs. He falt the application of the brakes in emergency 10 or 12 on lengths from the point of collision at which time the absence was about 25 miles an hour. He thought the speed had been reduced to about 15 miles an hour when the collision occurred. The stated that he did not see Conductor noe before the accident accurred and does not know where he was located.

Head Brakeman Moody, of train No. 42, stated that he had gone back to the catoose to est his lunch and was washing some

dishes when he felt the brakes applied in emer, ency. He stated that the train traveled a distance of 7 or 8 car lengths after the brakes were applied before the collision occurred. He estimated the speed of the train at 25 or 30 miles an hour at the time the brakes were applied.

Hear Brakeman Terry, of train 60. 42, stated that from the time the brakes were applied to the time the collision occurred. the train ran a distince of 6 or 7 car lengths. He further stated that he went back to protect the rear of his train immediately after the accident and saw no torpedoes on the track near mile post 78.

Mechanical Draftsman villis, who was inding on the locomotive of train 20. 42 in connection with the test, stated that his
first intimation of the impending accident was when he heard fir.
Blessing give warning and the brakes were a plied in emergency. He
stated he then swung out of the window, saw the corner of the caboose
of extra 402 just ahead, jumped off and was knocked unconscious. He
stated further that he id not see the conductor of extra 402 at the
tile he swung out of the window.

stated that on the day of the socident he came nome for dinner at 12.15 p.m. and noticed a flagman standing near the north end of the bridge. After he had some inside his house to eat it started to rain. A short time later he heard train No. 42 percaching and upon looking out saw the flagman running from the ceboose of the standing train toward the approaching train, and he judged the flagman was 5 or 6 car lengths from the caboose at that time. It

was his supposition that the flagmen he saw near the bridge at 12.15 p.m. went to the caboose for thelter when it started to rain.

4 i

Alvin Cook, employed at Heirens Gravel Bit, stated that he saw train No. 42 approaching the point of accident and noticed a flaman from extra 402 running toward the approaching train, being about 2 car lengths from the standing caboose when he first saw him.

This accident was caused by the failure of Conductor roe properly to protect the rear of his train, in accordance with rule 99 of the mashville. Chattancoga & St. Louis Parlroad book of Operating Jules, which reads in part as follows:

which it may be struck, the flagman must so back immediately with stop simple a sufficient distance to insure full protection, at which point no must place two torpedoes on the rail, two rail lengths apart, as a caution at mal. He may then return to such distance from his train as will admit of a stop signal being given to an approaching train by hand or torpedo in time to prevent accident, where he will place one torsedo on the rail. Then recalled, he may return to his train, first removing the single torpedo.

while the statements of Conductor foe and other witnesses conflict in regard to his location on the arrival of train No. 42. Conductor foe himself admitted that he had not been called in by the engine whistle when he started to return to his train, and that he was no ore than 20 car lengths from his caboose when he signalled the following train to stop. According to his own statement, therefore, he was not in position to furnish adequate protection for his train, and the fact that he returned nearly to his train before being called in indicates a wanton disregard for the elemental principles of train protection. The

weight of evidence is that he was considerably less than 20 car lengths from the rear end of his train when ho. 42 so proached. Had a block signal system been in overation on this line this accident might have been averted.

Conductor Poe entered the service of the Nashville.

Chattanooga & St. Louis Railrotd as brahenen in July, 1892, and

was promoted to conductor in 1897. His service record shows no

offense of any great magnitude standing against him.

None of the employees involved in this accident had been on duty in violation of the provisions of the fours of Service Law.