REPORT OF INVESTIGATION RELATIVE TO CAUSE OF ACCIDENT TO BALTIMORE & OFTO RAILROAD PALAGENGER TRAIN NO. 14 ON THE WALHINGTON TERMINAL COMPANY'S TRACKS, MAY BOTH, 1911.

From a personal investigation and interviews had with the Daltimore & Ohio and Wachington Terminal people we find as follows:

That train #14 left the Union Station bound for Baltimore, Mail, at 10: 54 p.m. and consisted of BAO Locamotive #2121, one mail, one baggage, three scaches and one parlor, making a total of six cars. The createst composed of S. Montgomery, Conductor; John Michael, Baggageman; B. Kinmell, Flagman; C. H. Burch, Enginemen; and Howard Cramblitt, Fireman.

Conductor Contgomery stated that the crew had not been on duty an excessive length of time, having left Cumberland, Md., at 8:52 p.m. after having had ten ours rest before leaving time of train.

At the frog in crossover treek near bridge "L", about 3300 feet north from where the to in started at Union Station train shed, the locomotive left the track and ran on the ground some two-hundred frot. The train did not break loose from the locomotive, neither did it leave the track, but a ntimued on the rails of the crossover track. The locomotive when it stopped was nearly diagonally across the tracks to the east of crossover track and the tender cromped around towards the right-hand side of the locomotive. When the locomotive left the track the firman was standing on the agron between the locomotive and tender and jusped off from the right- and side and stated that the train was running from eight to ten siles per our, that he did not fall or get

hurt and that then he jumped the engineers was getting off his beat in the cab but did not see him again until his body was found between the rails and partially under the for and trucks of the mail car.

The body did not seem to have been run over by the wheels but had been crushed by the brake rigging under the trucks. The shock caused by the stepping of the train was so slight that it was hardly noticed by the cassangers in the train. No one was injured in any way except the engineeran.

The toper on said the accident appened at 10:57 p.m. This being the case, in making the distance of 3300 feet in the per minutes, would indicate that the train had not exceeded any average rate of specu of 12% miles per hour.

It is impossible to state whether the engineers was thrown off or jumped. The scatements made by the fireman, with reference to observing the engineers gesting off the seat and what transpired on the locomotive after he left the track, cannot be fully relied upon as it was stated that to was decad and when interviewed later seemed excited and confused.

The steam on the locomotive was not shut off. The drivers consinued so turn rapidly for some five minutes after saving left the track and until the locomotive had damaged herself to such an extent that she had no power. It is thought that the engineman did not apply the so or brakes and that they were not applied until some brook secu red in the air connections by the dereilment causing the brakes at apply suscentically. If the engineman was thrown off that sould account for his not shutting off the steam and oplying the air.

From what we could observe and learn from others, the track, owitches and signals were all in good condition. The curve to crossover track is 12% degrees. The wheel base of the locamotive is 13 feet 2 inches.

It is our opinion that some obstruction may have been on the track or something may have fallen from the locomotive truck, derailing the same. The frog showed some irregular marks as if something scraped over same and a few feet north shows the first marks where the wheels left the rails. These marks were not very heavy and would indicate that they were made by the forward truck wheels. There the drivers left the track the rails were bent and torn up for some distance.

The fireman stated that he had fired for five years on freight and three years on passenger trains and that he had made six trips with locomotive #2121, also that the locomotive was in good condition, rode good, took all ourses nicely and nothing wrong with it which would account for its leaving the track.

There was no damage done to the cars in the train. There was an excessive strain on the dra heads between the tender and mail car caused by the cromped condition in which the cars were, which made it impossible to uncouple them at that time and as there was only a small amount of mail in the car the mail was transferred to the baggage car and balance of train taken back to Union Station.

From the d maged condition in w ich we found the lecomotive so many of its parts destroyed and missing, loose driving wheels, damaged trucks, broken boxes and brake rigging, in fact the locomotive (as the saying is) and stripped herself - it would be difficult for us to say that there had been anything wrong with the locomotive which would have caused the accident.

Later we attended the Coroner's inquest but there was no information brought out that we had not previously obtained.

The officials and employees of both the Beltimore & Chio Railroad and the Washington Terminal Company were very courteous and perfectly willing to render us all the assistance within their power in making the investigation, in fact, we received the thanks of the officials for our assistance in endervoring to locate the cause of the accident.

We attach hereto copies of statements from the employees which were interviewed in regard to the matter.

Respectfully submitted,