



SPEED AND ACCIDENTS. VOLUME II

Research Triangle Institute
Durham, North Carolina

26 June 1970





PB195017

RESEARCH TRIANGLE INSTITUTE

RTI PROJECT SU-409

SPEED AND ACCIDENTS
VOLUME II

RESEARCH TRIANGLE INSTITUTE

JUNE 26, 1970

FINAL REPORT

PREPARED FOR:

U.S. DEPARTMENT OF TRANSPORTATION
NATIONAL HIGHWAY SAFETY BUREAU
WASHINGTON, D.C. 20591

CONTRACT NO. FH-11-6965

RESEARCH TRIANGLE PARK, NORTH CAROLINA 27709

221

SPEED AND ACCIDENTS
VOLUME II

Prepared for:

National Highway Safety Bureau
U.S. Department of Transportation
Washington, D.C. 20591

26 June 1970

Prepared by:

Research Triangle Institute

Prepared for the U.S. Department of Transportation,
National Highway Safety Bureau, under Contract No. FH-11-6965

The opinions, findings and conclusions expressed in this
publication are those of the authors and not necessarily
those of the National Highway Safety Bureau.

FOREWORD

The Research Triangle Institute (RTI) and the Institute for Research in Public Safety of Indiana University have jointly performed a study to gather accident and speed information in order to better define the role that speed (primarily the speed deviation of accident-involved vehicles) plays as a contributing factor in vehicle accidents. This study was under contract number FH-11-6965 to the National Highway Safety Bureau (NHSB) of the Federal Highway Administration. Dr. Robert J. Taylor of the Mathematical Analysis Division under the direction of Mr. Donald Mela of the NHSB is the contract manager. The Research Triangle Institute is the prime contractor and the work is being performed in the Statistics Research Division (SRD) under the direction of Dr. A. L. Finkner. Dr. Herbert H. Hill is project leader and the following members have assisted in this study: S. B. White, Jr., J. W. Dunn, L. B. West, A. C. Nelson, Jr., R. L. Beadles, H. J. White, J. R. Batts, Mary J. Artz, and R. E. Kirk.

The Institute for Research in Public Safety is the subcontractor to RTI and has been primarily responsible for the data collection activity. This investigation has been under the direction of Dr. Kent B. Joscelyn and the following members have contributed to this report: G. H. Reinier, J. S. Merritt, T. H. Bryan, J. L. Shambach, S. P. Malak, J. R. Kinney, R. L. Chapman, R. G. Rockenbaugh, F. J. Connelly, R. N. Wolff, J. R. Treat, and K. J. Waymire.

The specific objectives of this study were to:

- A. Gather more reliable accident data by using trained accident investigators rather than relying on the usual police and insurance accident reports,
- B. Gather speed survey information over a selected representative sample of roadways in order to determine involvement rates in relation to miles traveled for different amounts of deviation from the average traffic speed, and

C. Determine the interaction between speed deviation and other factors precipitating accidents.

The authors wish to express their appreciation to Mrs. Patricia Daniel and Mrs. Linda Tingen for the typing of the tedious mathematical equations and tables, and to Mrs. Susan Bergeron for editorial assistance.

The report is contained in two volumes. Volume I is a summary report and contains the major results and conclusions along with examples of tables and figures from Volume II. Volume II contains the detailed information and analyses. In particular, the summary data for all of the accidents is contained in Volume II.

Many people have contributed to the success of this project. Immediate and accurate accident notification was furnished by the Bloomington Police Department, the Monroe County Sheriff's Department, and the Indiana State Police. Sheriff Clifford Thrasher and the deputies of the Monroe County Sheriff's Department deserve a special thanks for providing continuous communications support for the accident investigation teams. The excellent service provided by the staffs of Indiana Bell Telephone and Public Service of Indiana was particularly helpful during the implementation of the computer-sensor system. Finally, the Indiana State Highway Commission provided consistent support and, in particular, authorized the in-road installation of the detector hardware for the computer-sensor system.

ABSTRACT

In the last few years it has become the conviction of some investigators that, instead of blaming the absolute values of speeds for accidents, it may be more prudent to examine the extent to which accident-involved vehicles have deviated from the average speeds of surrounding traffic flow. The relationship between accident-involvement rate and the speed deviation of the accident-involved vehicle from the average of the surrounding traffic flow was investigated during this study. Accident and speed data were collected in Monroe County, Indiana by the Institute for Research in Public Safety of Indiana University. Based on these data it is concluded that a U-shaped relationship between involvement rate and speed deviation exists.

On approximately 20 miles of roadway magnetic loop vehicle detectors coupled on-line with a digital computer were used to record speed, effective length, and headway data for all detected vehicles on a full-time basis. The speeds of the accident-involved vehicles were estimated by means of accident investigation teams arriving at the scene of the accident as soon as is possible after notification of its occurrence and/or by speeds given by the computer-sensor system (CSS). The mean speed of the traffic in which the accident-involved vehicle was traveling was estimated by means of radar measurements taken both before and after the accident and under conditions as similar as possible to those surrounding the accident and/or by data from the CSS.

This volume contains a detailed description of the data collection procedures, the methods used in analysis, and a tabulation of the results. A complete summary of all the information provided by the computer-sensor system would require many volumes and this information is being retained on tape by either RTI or the Institute for Research in Public Safety of Indiana University. The computer-sensor system is described in some detail in Appendix C. The summary data for all of the accidents are given in Section 6. A summary of the results is presented in Section 2 with convenient references to the section containing more detailed results.


TABLE OF CONTENTS

	<u>Page Number</u>
FORWORD	ii
ABSTRACT	iv
LIST OF FIGURES	vif
LIST OF TABLES	ix
1. INTRODUCTION	1
1.1 Historical Background	1
1.2 Objectives	3
1.3 Plan of Research	3
2. SUMMARY	7
3. ACCIDENT INVOLVEMENT RATE ANALYSIS	15
3.1 Relationship Between Involvement Rate and Speed Deviation	15
3.2 Accident and Involvement Rates by Road and Time of Day	21
3.3 Estimating Vehicle Mileage	24
3.4 Tracking Vehicles Using the Computer-Sensor System . . .	26
3.5 Classifications of Accidents	35
4. SYSTEMS ANALYSIS	41
4.1 System Availability	43
4.2 System Accuracy and Repeatability	51
4.3 Analysis of Estimated Vehicle Lengths	52
5. TRAFFIC FLOW CHARACTERISTICS AND ANALYSIS	55
5.1 Volume-Time Relationship	55
5.2 Relationship Between Speed and Traffic Flow Characteristics	57
5.3 Speed Profiles	69
5.4 Speed Distributions	81

TABLE OF CONTENTS (Continued)

	<u>Page Number</u>
6. SPEED CHARACTERISTICS AND ACCIDENT DATA	83
7. REFERENCES	127
APPENDIX A - RADAR SPEED SAMPLING	A.1
A.1 Traffic Flow Profile	A.1
A.2 Post-Accident Radar	A.2
APPENDIX B - ACCIDENT INVESTIGATION PROCEDURES (PHASE I AND PHASE II)	B.1
B.1 Objectives and Format	B.1
B.2 Accident Investigation: Phase I	B.1
B.3 Accident Investigation: Phase II	B.4
APPENDIX C - COMPUTER-SENSOR SYSTEM	C.1
C.1 The Computer	C.1
C.2 Sensor System and Interface Equipment	C.4
APPENDIX D - ESTIMATING VEHICLE MILEAGE	D.1
APPENDIX E - TYPICAL ON-SITE ACCIDENT REPORT	E.1
APPENDIX F - SPEED ESTIMATION OF AIV USING DATA FROM COMPUTER- SENSOR SYSTEM	F.1
APPENDIX G - COMPUTER-SENSOR ACCURACY AND REPEATABILITY TEST DATA .	G.1
APPENDIX H - VOLUME-TIME RELATIONSHIP - HIGHWAY NO. 37 ALSO INCLUDES STATE ROADS 45, 46, 48	H.1

LIST OF FIGURES

	<u>Page Number</u>
2.1 Speed Distribution and Likelihood of Accident Involvement as a Function of Speed Deviation (ΔS_D)	11
3.4.1 Example of Vehicle Tracking (Accident 280)	33
3.5.1 Accident Locations - Monroe County	38
4.1.1 Percentage of Missing Hourly Summaries by Time of Day	49
4.1.2 Percentage of Hourly Summaries with BCC \geq 5% by Time of Day (Time Period 9/1/69 to 9/28/69)	50
5.2.1 Hourly Mean Speed Versus Hourly Volume Time For Loop 8	61
5.2.2 Hourly Mean Speed Versus Hourly Volume For Loop 0	66
5.3.1 Speed Profiles - Highway No. 37	70
5.3.2 Speed Profiles - Highway No. 37 North	71
5.3.3 Speed Profiles - Highway No. 37 South	72
5.3.4 Speed Profiles - Highway No. 46 East	73
5.3.5 Speed Profiles - Highway No. 46 West	74
5.3.6 Speed Profiles - Highway No. 45 East	75
5.3.7 Speed Profiles - Highway No. 45 West	76
5.3.8 Speed Profiles - Highway No. 48 West	77
5.3.9 Speed Profiles	78
5.3.10 Speed Profiles	78
5.3.11 Posted Speeds (mph) Shown in  For Monroe County State Roads	79
5.4.1 Speed Distribution - Station 203	82
6.1 State Roads in Monroe County, Indiana Showing Location of Sensor Sites and Road Segment Station Identification	84
6.2 Daytime (0600-1900) Mean Speed and Standard Deviation Versus Time	125

LIST OF FIGURES (Continued)

	<u>Page Number</u>
APPENDIX	
C.1 Installation of Wire Loops in Roadway	C.9
C.2 Installation of VEDET Detectors on Utility Pole	C.10
C.3 Location of Sensor Sites on State Highway 37	C.11
C.4 Plan View of Roadway Section for Site 0-4	C.12
C.5 Plan View of Roadway Section for Site 1-5	C.13
C.6 Plan View of Roadway Section for Site 2-6	C.14
C.7 Plan View of Roadway Section for Site 3-7	C.15
C.8 Plan View of Roadway Section for Site 8-12	C.16
C.9 Plan View of Roadway Section for Site 9-13	C.17
C.10 Plan View of Roadway Section for Site 10-14	C.18
C.11 Plan View of Roadway Section for Site 11-15	C.19
C.12 Location of Additional Sensor Sites on State Highway 37 North	C.22
C.13 Plan View of Roadway Section for Site 20-26	C.23
C.14 Plan View of Roadway Section for Site 21-27	C.24
C.15 Plan View of Roadway Section for Site 22-28	C.25
C.16 Plan View of Roadway Section for Site 23-29	C.26
C.17 Plan View of Roadway Section for Site 24-30	C.27
C.18 Plan View of Roadway Section for Site 25-31	C.28

LIST OF TABLES

		<u>Page Number</u>
3.1.1	Relationship Between Involvement Rate and Speed Deviation	17
3.1.2	Total Accidents and Number Associated With Turning Maneuver	18
3.1.3	Relationship Between Involvement Rate and Speed Deviation (Adjusted)	20
3.2.1	Number of Accidents, Number of Involvements and Associated Rates by Road and Time-of-Day	22
3.2.2	Observed and Expected Number of Daytime Involvements on Highway No. 37	23
3.2.3	Observed and Expected Number of Daytime Accidents on Highway No. 37	24
3.3.1	Estimated Vehicle Mileage (in Thousands of Miles)	25
3.4.1	Accident History	27
3.4.2	Comparison of Speed Estimates	29
3.5.1	Accidents Classified According to Type, Location, Environment, Driver and Vehicle Characteristics	36
3.5.2	Observed and Expected Number of Accidents by Year	37
3.5.3	Contributing Factors Versus Speed Deviation Category	39
4.1.1	System Availability (%)	46
4.1.2	Percentage of Hourly Reports With BCC \geq 5% Versus Loop Pair	51
4.3.1	Estimated Lengths (In Feet)	53
5.2.1	Regression Equations and R^2 for Four Locations Using Model I with Hourly Mean Speed as the Dependent Variable	59
5.2.2	Regression Equations and R^2 for Two Locations Using Model I with Hourly Standard Deviation of Speed as the Dependent Variable	60
5.2.3	R^2 for Selected Subsets of Regressions Using Model II with Hourly Mean Speed as the Dependent Variables	63
5.2.4	R^2 for Selected Subsets of Regressions Using Model III with Hourly Mean Speed as the Dependent Variable	68

LIST OF TABLES (Continued)

	<u>Page Number</u>
6.1 Accident Data	88
6.2 Speed Survey Data Summary	118
APPENDIX	
H.1 Volume-Time Relationship - Highway No. 37	H.1
H.2 Volume-Time Relationship for Other State Roads	H.9

1. INTRODUCTION

1.1 Historical Background

For many years investigators have believed that speed has a direct correlation with highway traffic accidents. In principle this cannot be refuted because, obviously, if the speeds driven by all drivers were reduced by half, certainly the number of serious accidents would be reduced. However, such a drastic reduction in speeds is not acceptable to the motoring public in the interest of highway safety. Thus it appears that the ground transportation system involving motor vehicles is destined to be one of relatively high speeds and correspondingly high rates of accidents, with their attendant property damage, injuries, and fatalities.

In recent years it has been observed that it is possible for traffic to move in a relatively safe manner at high speeds on freeways and other roadways designed for high speed. It is now the conviction of some investigators that instead of "blaming" accidents on absolute speeds, it is more prudent to examine the extent to which speeds of vehicles involved in accidents deviate from the average speed of the surrounding traffic.

Speed difference is a very important concept and one which is very difficult to measure in the field. This difficulty is due, primarily, to the problems involved in determining a vehicle's speed immediately prior to its involvement in an accident. After an accident has occurred, such speed quantifications are, at best, subjective estimates and considerable variation in the estimates of speed is to be expected.

As substantiation of the significance of the correlation between accidents and speed differences it has been reported [1] that:

1. The accident-involvement rates were highest at very low speeds, lowest at about average speed, and increased at very high speeds (i.e., the greater the deviation in speed of any vehicle from the average speed of all traffic, the greater its chance of being involved in an accident).

2. Passenger-car drivers involved in two-car, rear-end collisions were much more likely to be traveling at larger speed differentials than the average. For example, one-third of accident-involved drivers had speed differences of 30 miles per hour or more, compared to only one percent of pairs of cars selected at random.

This study was based on 10,000 accidents covering more than 600 miles of highways. It is clear that there is no simple increasing monotone accident risk with speed. The issue is much more complex.

In another study [2], the relationship between accident involvement and a function of acceleration noise was investigated. The accident involvement rate increased as the mean number of 2 1/2 mph speed deviations increased. This study utilized six roads ranging in design and volume characteristics from a "farm to market" type to an expressway.

It appears that the key to a successful analysis of the role of speed differences as a causative factor in accidents is the ability to determine accurately the deviation in speed of each vehicle involved in an accident from the average speed of the surrounding traffic flow. Measurement errors and their effects on involvement rate are discussed in [3]. It was shown that errors in estimating the speed of the accident-involved vehicle (AIV) results in an overestimate of the involvement rate for large deviations (positive and negative) and an underestimate of the rate at deviations near zero. For this reason it was necessary to develop an automated and continuous device to identify vehicles and to estimate their speeds at selected points along particular roadways. It was hoped that such an automated and refined system would provide the speed accuracy required in this project. A description of the computer-sensor system that was developed is described in Appendix C.

1.2 Objectives

The major objective of this project was to gather and analyze accident and speed data that would quantitatively define the relationship between speed (primarily speed deviation of accident-involved vehicles) and the frequency of occurrence of corresponding motor vehicle accidents. In order to accomplish this objective it was necessary to:

1. Gather reliable accident data using trained accident investigators,
2. Estimate the speeds of vehicles involved in accidents at the time immediately before the collision sequence began,
3. Estimate the speed distribution of traffic flow at the time and location of the occurrence of each accident investigated,
4. Using the speed data as found in 2. and 3. above, quantify the correlation between speed deviation and accident rates, and to determine interactions, if any, between speed deviation and other factors precipitating accidents, and
5. Analyze other related factors which appear to be important in describing the mechanisms of accidents.

1.3 Plan of Research

The Research Triangle Institute (RTI), acting as prime contractor, and the Institute for Research in Public Safety (IRPS) (formerly the Research Division of the Department of Police Administration, Indiana University) for the Indiana University Foundation, serving as subcontractor to RTI, contracted with the National Highway Safety Bureau, Department of Transportation, to provide the personnel, facilities, and special equipment to fulfill the direct objectives enumerated in Section 1.2. The responsibility for data collection was given to the IRPS, while RTI was assigned the tasks of analysis and evaluation.

All state highways and all the county roads in Monroe County, Indiana, with a speed limit of 40 mph or over - or where the mean speed was 40 mph or greater -

were included in the study. This involved approximately 70 miles of state roads, on which two hundred (200) accident investigations were completed during the 13 months of active investigation.

During the initial phase of the project, accident investigators were trained for on-site and post-crash accident investigation. Based on the physical documented evidence, witness reports, and driver interviews, a subjective estimate of the pre-crash (sequence) speeds was determined. Subsequently, a panel of project research personnel reviewed each accident report and arrived at independent speed estimates. Whenever possible and appropriate, the data from the computer-sensor system were integrated into the pre-accident speed estimation processes.

During the second phase of the project, the decision was made to expand the computer-sensor system from eight to fourteen detector locations, each monitoring two lanes of traffic on State Route 37, North and South of the City of Bloomington. At the same time the decision was made to expand the computer-sensor system, the on-site investigation was discontinued in favor of a follow-up scheme in which the speed estimates were based on the computer-sensor system output, the accident report of the investigating law enforcement agency, and statements of witnesses.

Tasks of Data Collection

The data collection process used to satisfy the objectives of this investigation was essentially threefold: (1) radar speed sampling, (2) at-the-scene and follow-up accident investigation, and (3) a computer-sensor system for continuously monitoring traffic characteristics (i.e. speed, headway, length) at selected points. Brief descriptions of these three efforts are presented below:

(1) Radar Speed Sampling

The state roads were divided arbitrarily into one-mile segments. Within each segment 15-minute radar spot speed measurements were taken at various times under varying environmental conditions. This provided a data base for constructing volume-time relationships and speed profiles for the network of roads included in the study.

Radar speed readings were also collected at each accident site. Efforts were made to duplicate time of day, day of week, location and environmental conditions surrounding each accident. For each accident, speeds were observed for a minimum of 200 vehicles with at least 50 vehicles traveling in the same directions as the accident vehicles. Post-accident radar collection of data was conducted from January 6, 1969 through December 31, 1969. The complete description of the details of techniques utilized in radar sampling is given in Appendix A.

(2a) At-the-Scene Accident Investigation

On-scene accident investigation began December 7, 1968, and continued through July 31, 1969. Primary and back-up investigators were placed on-call 24 hours a day. Notifications of accidents were obtained through the cooperation of the Bloomington City Police Department, the Monroe County Sheriff's Department, and the Indiana State Police. Each of these has accident investigation jurisdiction within Monroe County. The on-site investigation was concluded with a formal, written report that included the regular police report, accident scene diagrams, photographs, and various computer-compatible report forms. Engineering analyses were included wherever appropriate. This report was then reviewed before the speed estimates were made. The complete details are given in Appendix B.

(2b) Follow-up Accident Investigation

The character, design, and intensity of the accident investigation process changed August 1, 1969. Only those accidents which occurred on State Route 37 within the computer-sensor system were investigated. On-site coverage of accidents was discontinued, and the accident investigation funds were used to extend the time of computer-sensor data collection in hopes of obtaining more information about speeds of AIV's. Consequently, accident data were obtained by reviewing the computer-sensor data, the police accident report, and statements made by the witnesses and drivers. A ten-hour accident investigation seminar was conducted by the research team and selected faculty for Monroe County Sheriff's deputies, to up-grade the quality of accident reports.

Forty-eight accidents were investigated between August 1, 1969, and December 31, 1969.

(3) Computer-Sensor System

The collection of speed and headway data from eight computer-sensor sites, North and South of the City of Bloomington, on State Route 37 began on May 7, 1969.

Each sensor site consisted of two induction loops laid in each lane, at certain "strategic" points, North and South of Bloomington. The passage of a vehicle through the radio-frequency field was "sensed" by the loop detector. The resulting signal was then transmitted to an IBM 1800 computer system at IRPS.

Two coded words were produced by the computer from the sensor signals. These words identified time, individual velocity, vehicle length, interval between vehicles, and direction of travel. Thus, data descriptive of vehicle length, speed, time of day, direction, site location, and time headway were noted and stored on magnetic tape during the 24-hour-a-day operation. Whenever possible, State Route 37 accident investigations utilized the information collected by the system for speed estimates, traffic flow profiles and, in some instances, vehicle identification.

2. SUMMARY

The results of this study are summarized below under the three major headings: A. Accidents, B. Traffic Flow, and C. Computer-Sensor System. The references given in parentheses following each summary statement indicate the sections in this report where the reader may find more detailed information.

A. Accidents

1. Over a thirteen month period, 200 accidents, involving 353 vehicles were investigated on the state roads of Monroe County, Indiana. In addition, 94 accidents which occurred on county roads were investigated. These accidents are listed in this report but are not included in the involvement rate analysis because of insufficient volume-time information on county roads. (Section 3)

2. The results of this study indicate a U-shaped relationship between involvement rate and speed deviation. The following table gives the numerical values of the involvement rate as a function of speed deviation for all state roads in Monroe County, Indiana. These rates were obtained after eliminating those accidents which involved a turning maneuver. (Section 3)

<u>Speed Deviation Class Interval (mph)</u>	<u>Involvement Rate (No. Involvements per MVM)</u>
< -15.5	9.8
-15.5 to - 5.5	0.8
- 5.5 to + 5.5	0.8
+ 5.5 to +15.5	1.3
> +15.5	9.8

3. These results confirm the hypothesis that slow driving as well as fast driving increases the likelihood of being involved in an accident. However, the curvature of this U-shaped relationship is not nearly as pronounced as that given by Solomon [1] in a previous study. (Section 3)

4. Forty-four percent of all accidents (and 56% of the involvements) involved at least one vehicle which was either in a turning maneuver or influenced by another vehicle which was in the process of turning. (Section 3)

5. Thirty-nine (39) out of 183 drivers, or 21 percent, having seat belts available were using them. (Section 3)

6. The number of involvements for the several age groups and speed deviation categories are tabulated below. As expected, there is a speed deviation and age interaction, that is, the distribution of speed deviations is not the same for all age groups. This tabulation does not include the turning involvements. (Section 3)

Age Category	Speed Deviation Category			Totals
	$\Delta S_D < -15.5$	$-5.5 < \Delta S_D < 5.5$	$\Delta S_D > 15.5$	
≤ 19	2	12	12	26
20 - 24	2	13	14	29
25 - 29	3	11	4	18
30 - 34	1	5	1	7
35 - 39	0	6	1	7
≥ 40	12	25	1	38
Totals	20	72	33	125

7. Another useful breakdown of the types of accidents and roads is given below.

	Single	Multiple			Totals
		Head-on	Rear-End	Side	
Highway 37 North	17	10	22	16	65
Highway 37 South	14	5	17	13	49
All Other State Roads	36	9	38	20	103
Totals	67	24	77	49	217

The major point to be made relative to this table is that the percentage of multiple (single) vehicle involvements decreases (increases) as the traffic volume decreases. Even though Highway 37 North appears to a driver to be a safer highway than 37 South, the likelihood of being involved is greater due to the multiple vehicle accidents. (Section 3)

B. Traffic Flow

Utilizing radar and the computer-sensor system data, traffic flow characteristics (mean speed, speed variability, and volume) were examined for each of the roads included in the study. For Highway No. 37, these characteristics have been examined with respect to changes over time. Some general conclusions resulting from these analyses are:

1. Large differences in mean speeds exist among the various roads included in the study. This was anticipated in view of differences in road geometry, surface, type, width, topography, concentration of population, etc., existing within the road network. (Section 6)
2. Mean speeds at night and especially the early morning hours are consistently higher than daytime mean speeds. (Section 6)
3. Mean speeds are generally higher for dry roads than for wet roads. There were stations where wet roads exhibited mean speeds equal to or even greater than dry roads; however, this could be a situation where rain had just ended and there was good visibility, but the road was still wet. (Section 6)

4. Speed variability is relatively stable over the entire road network system. (Section 6)

5. Speed variability is generally greater, but by only a small amount, during night driving as compared to daytime driving. (Section 6)

6. Three multiple linear regression models consisting of 3, 6, and 15 variables were examined to determine those variables which account most for the variation in hourly mean speeds. Of all the variables studied, volume of vehicles in same direction is the most important single factor. (Section 5)


7. Speed distributions are adequately described by the normal distribution. (Section 5)

8. One approach for evaluating the effectiveness of countermeasures pertaining to speed deviations is described below. The step function describing the likelihood of being involved in an accident is nearly symmetrical and U-shaped, but is dependent on the road type. (See Section 3) For a symmetrical, U-shaped distribution, the overall likelihood of being involved in an accident can be reduced by:

- a. Reducing high speed deviations by one of many possible means,
- b. Enforcing minimum speeds, or
- c. Decreasing the likelihood of involvement over all speeds.

Given an estimate of the likelihood function $l(\Delta S_D)$ and the speed distribution, which is assumed to be normal, $\phi(\Delta S_D)$ say; one can estimate the portion of the overall likelihood L which is attributable to the high- and/or low-speed deviations. Consider the speed distribution and likelihood of involvement function given in Figure 2.1. For this example the values of $l(\Delta S_D)$ are taken from data in Table 3.1.3 for Highway No. 37 (see Section 3 of this volume). The speed distribution is assumed to be normal with a standard deviation of 8 mph. The calculation of L is made by summing the products of the likelihood of involvement by

Figure 2.1 Speed Distribution and Likelihood of Accident Involvement as a Function of Speed Deviation (ΔS_D)



the probability of a vehicle speed within the corresponding speed deviation interval, i.e.

$$\begin{aligned} L &= 6.3[.026] + 0.7[.219] + 0.8[.510] + 1.0[.219] + 6.9[.026] \\ &= 1.12. \end{aligned}$$

Thus the portion of L attributable to each of the five speed deviation categories is given in the following table.

Total	$\Delta S_D < -15.5$	$-15.5 < \Delta S_D < -5.5$	$-5.5 < \Delta S_D < 5.5$	$5.5 < \Delta S_D < 15.5$	$\Delta S_D > 15.5$
$L = 1.12$.164	.153	.408	.177	.179
Percent of L	14.6%	13.7%	36.4%	19.6%	16.0%
Maximum reduction of L possible in low- and high-speed deviation categories	.138 (12.3%)	- -	- -	- -	.153 (13.8%)

From the above results one can estimate the maximum reduction possible in overall likelihood (ignoring intersection-turning maneuver accidents) which can be achieved by particular countermeasure programs. The rates cannot be reduced to zero because any speed control, advisory, or enforcement program will only displace the driver-vehicle to another speed deviation category. In this example, the likelihood-involvement rate of unity is assumed for the minimum. This assumption yields 0.138 and 0.153, or about 12% and 14% respectively for the low- and high-speed deviation categories, as the estimated maximum reductions in L which can be attained. The effectiveness of a program to reduce the involvement rate must be considered relative to the maximum possible reduction, and then the potential value of a particular C/M program can be estimated. For example, if a program of law enforcement is able to reduce the number

of speed deviations exceeding 15.5 mph by half its estimated magnitude, i.e. from 0.026 to 0.013, the savings will be approximately 7% of involvements. For this high-speed category a significant reduction in fatalities would result. The cost of additional enforcement to accomplish this magnitude of reduction would be expected to be very costly. (Section 3)

9. An additional conjecture relative to speed limits is given below. There were not sufficient data available to allow a full analysis but it appears that this study reinforces the setting of speed limits at the 85th percentile speed. The standard deviation of the speed distribution is approximately 8 mph. Approximately 85 percent of the drivers drive at speeds below the mean plus one standard deviation. The drivers having speeds between the mean and one standard deviation above the mean are definitely in a low involvement group. The region between one and two standard deviations above the mean speed encompasses approximately 10 percent of the drivers and does not have a significantly greater involvement rate than at mean speed. Speeds at two standard deviations above the mean correspond to approximately the tolerance level allowed by police agencies. Thus the higher level of enforcement occurs when the $\lambda(\Delta S_D)$ function begins to increase significantly resulting in a more cost effective C/M.

If minimum speed limits are set, a similar argument would lead to the conclusion that the limit should be placed at about the 15th percentile speed with enforcement at about the 5th percentile.

C. Computer-Sensor System

1. The Computer-Sensor System (CSS) has provided data on speed, density, headways, and mix of vehicles on the roadway during the time of the accident in a very satisfactory manner. Data are now available that have not been previously collected regarding the overall traffic parameters in a traffic stream containing AIV's. (Section 4)

2. The CSS is capable of detecting either the AIV or the platoon of vehicles containing the AIV approximately 25 percent of the time with high confidence (Section 3). This capability is still dependent on some accident investigation which identifies the particular vehicles, location and time of the accident, and statements of witnesses concerning (unusual) speeds and relative positions of vehicles having extreme lengths (Section 4).

3. The standard deviations of the estimated vehicle speeds and lengths as recorded by the CSS are approximately 1 mph and 1 foot respectively. (Section 4)

4. The CSS has provided considerable data on vehicle speeds, lengths, and headways which can provide data for better understanding of traffic flow behavior. A detailed analysis of these data is costly and beyond the level of effort for this project. However, these data should be of value for future projects. To our knowledge no data on a two-lane road such as State Road No. 37 exists to the extent that they are available from this data collection effort. (Section 4)

5. For the 22 weeks beginning with June 23, 1969 through November 23, 1969, the weekly system availability ranged from about 57% to 96%, adjusting for scheduled maintenance of four hours per week. System availability is the proportion of up-time for the system to total time, in this case 164 hours per week. During this period of time considerable down-time was scheduled for system analysis, expansion, and improvements. During three weeks the availability exceeded 90% indicating that it is capable of high level performance.

3. ACCIDENT INVOLVEMENT RATE ANALYSIS

Contained in this section are the results of various analyses of speed and accident data which deal with the accident involvement rates observed on the network of state roads included in this study.

The results are grouped into five general areas of interest. These include:

Relationship Between Involvement Rate and Speed Deviation (Section 3.1)

Accident and Involvement Rates by Road and Time of Day (Section 3.2)

Estimating Vehicle Mileage (Section 3.3)

Tracking Vehicles Using the Computer-Sensor System (Section 3.4)

Classifications of Accidents (Section 3.5).

3.1 Relationship Between Involvement Rate and Speed Deviation

One of the primary objectives of this study is to determine the relationship between involvement rate and speed deviation from the mean traffic speed. The involvement rate, as used in this report, is a measure of the likelihood of being involved in an accident. Normally, this rate is expressed as the number of involvements per million vehicle miles.

The general consensus of opinion is that the involvement rate is a minimum at or near a speed deviation of zero. This means that both the slow and fast drivers are expected to experience a higher rate of involvement than those driving near the average traffic speed. Thus, it is not so much the absolute speed but rather the deviation from mean traffic speed that affects the probability of being involved in an accident. Of course, given that an accident has occurred, the severity of the injury is directly related to the absolute speed of the involved vehicle.

The relationship between the involvement rate and speed deviation may be empirically determined by dividing the speed deviation axis into arbitrary intervals and estimating the involvement rate within each interval. For this study, the

involvement rate, on a per mile basis, for a given speed deviation interval, ΔS_D , for a specified time period, T, is estimated as follows:

$$I_{\Delta S_D, T} = \frac{n_{\Delta S_D, T}}{L \times V_T \times P_{\Delta S_D}}$$

where

$I_{\Delta S_D, T}$ = Involvement rate for the interval ΔS_D for time T.

$n_{\Delta S_D, T}$ = Number of involvements with speed deviations within the interval ΔS_D occurring over time, T.

L = Length of road (miles).

V_T = Total number of vehicles over time T.

$P_{\Delta S_D}$ = Proportion of vehicles traveling within the interval, ΔS_D .

For example, for ΔS_D between 0 and +5 mph, the involvement rate is calculated as: number of accident-involved vehicles whose speed differential is between 0 and +5 mph divided by the total mileage generated by all vehicles with speed differentials between 0 and +5 mph.

The numerator, $n_{\Delta S_D, T}$, is obtained by calculating, for each involvement, the difference between the estimated speed of the accident-involved vehicle and the estimated mean traffic speed, then counting the number of differences that lie within the interval ΔS_D . A discussion of the procedures employed in calculating the denominator, $L \times V_T \times P_{\Delta S_D}$, which represents the total mileage driven by all vehicles with speed differentials within the interval ΔS_D is given in Appendix D.

For Highway No. 37, other state roads, and all state roads combined, Table 3.1.1 shows the number of involvements, total vehicle mileage and the corresponding involvement rate (per MVM) for five arbitrarily selected speed deviation intervals. In all three cases the rate is highest for large negative deviations, decreases to a minimum at or near zero speed deviations, and then starts increasing for large

Table 3.1.1 Relationship Between Involvement Rate and Speed Deviation

Highway No. 37 (North and South)

<u>Speed Deviation Class Interval (mph)</u>	<u>Number Involvements</u>	<u>Total Vehicle Mileage (MVM)</u>	<u>Rate (Involvements) per MVM</u>
< -15.5	80	1.890	42.3
-15.5 to - 5.5	37	16.243	2.3
- 5.5 to + 5.5	63	39.976	1.6
+ 5.5 to +15.5	20	16.243	1.2
> +15.5	16	1.890	8.5

Highway No.'s 46 (East and West),
45 (East and West)
and 48 (West)

< -15.5	52	.571	91.1
-15.5 to - 5.5	14	8.429	1.7
- 5.5 to + 5.5	37	23.621	1.6
+ 5.5 to +15.5	21	8.429	2.5
> +15.5	13	.571	22.8

Total (All State Roads In Monroe County)

< -15.5	132	2.461	53.6
-15.5 to - 5.5	51	24.672	2.1
- 5.5 to + 5.5	100	63.597	1.6
+ 5.5 to +15.5	41	24.672	1.7
> +15.5	29	2.461	11.8

positive speed deviations. The results are presented separately for Highway No. 37 (North and South) since the instrumentation of this road provided more complete and reliable vehicle speed and volume data on which the involvement rates are based. On the remaining state roads, radar was used to collect the necessary data.

The involvements occurring on Highway No. 37 totalled 216 and represented 114 accidents, for an average of 1.89 vehicles per accident. For the remaining state roads in Monroe County, there were 137 involvements in 86 accidents, for an average of 1.59 vehicles per accident. The average over all state roads was 1.77 vehicles per accident (200 accidents involving 353 vehicles).

Upon examining those involvements which exhibited large speed deviation (132 negative and 29 positive deviations) to determine perhaps some common factor or underlying mechanism, it became immediately apparent that many of the vehicles were either in the process of making some turning maneuver or influenced by another vehicle in the process of making a turn. The following table illustrates the degree to which this is present.

Table 3.1.2 Total Accidents and Number Associated with Turning Maneuver

	<u>Total No. Accidents</u>	<u>Total No. Involvements</u>	<u>Associated With Turning Maneuver</u>	
			<u>Number Accidents</u>	<u>Number Involvements</u>
Highway No. 37	114	216	56	132
Other State Roads	86	137	32	67
Total	200	353	88	199

From the above table, 44% (88 out of 200) of the total number of accidents had at least one vehicle directly involved in some turning maneuver or was directly influenced by another vehicle which was likewise involved in some turning maneuver. A similar statement can be made regarding 56% (199 out of 353) of the total involvement.

The use of involvements per million vehicle miles as a measure of risk is not applicable to intersections (or to any single point on the road) since the denominator of the involvement rate formula approaches zero as the length of the road, L, approaches zero. This problem is normally avoided by using involvements per volume of turning vehicles as a measure of risk at a given intersection. Data were not collected in this study to permit this type of analysis. Furthermore, it is extremely difficult to estimate the involvement rate over a finite length of road which encompasses an intersection because of the variation in the speed distribution parameters in the vicinity of the intersection. Hence, an adequate estimate of vehicle mileage in terms of speed deviation cannot be easily obtained.

In view of the above comments and the fact that such a large number of accidents occurred which possessed the common property of being associated with at least one vehicle involved in a turning maneuver, a decision was made to exclude these accidents in the involvement rate versus speed deviation analysis. By excluding these accidents, the resulting relationship between involvement rate and speed deviation is considered to be more valid. Table 3.1.3 shows the relationship between involvement rate and speed deviation for Highway No. 37, other state roads and for all state roads combined after eliminating all accidents involving at least one vehicle in a turning maneuver. It should be noted that in all cases the relationship is still U-shaped (involvement rate is a minimum near zero speed deviations and increases with deviation in speed regardless of sign). The involvement rates for large negative speed deviations are now comparable to the rates for large positive speed deviations which represents a significant change over the results previously given in Table 3.1.1. Based on the results from all the state roads in Monroe County, it appears that deviations in speed from the normal traffic flow by 15 mph in either direction increases the risk of being involved in an accident by an order of magnitude.

The elimination of accidents involving vehicles in turning maneuvers from the involvement rate versus speed deviation analysis does not, in any way, lessen the importance of these accidents and the valuable information they provide in the

Table 3.1.3 Relationship Between Involvement Rate
and Speed Deviation (Adjusted*)

Highway No. 37 (North and South)

<u>Speed Deviation Class Interval (mph)</u>	<u>Number Involvements</u>	<u>Total Vehicle Mileage (MVM)</u>	<u>Rate (Involvements per MVM)</u>
-15.5	12	1.890	6.3
-15.5 to - 5.5	11	16.243	.7
- 5.5 to + 5.5	32	39.976	.8
+ 5.5 to +15.5	16	16.243	1.0
> +15.5	13	1.890	6.9

Highway No.'s 46 (East and West), 45 (East and West)
and 48 (West)

< -15.5	12	.571	21.0
-15.5 to - 5.5	9	8.429	1.1
- 5.5 to + 5.5	22	23.621	.9
+ 5.5 to +15.5	16	8.429	1.9
> +15.5	11	.571	19.3

Total (All State Roads in Monroe County)

< -15.5	24	2.461	9.8
-15.5 to - 5.5	20	24.672	.8
- 5.5 to + 5.5	54	63.597	.8
+ 5.5 to +15.5	32	24.672	1.3
> +15.5	24	2.461	9.8

* Accidents involving at least one vehicle in a turning maneuver or influenced by another vehicle involved in the process of making a turn have been excluded.

formulation of programs to increase highway safety. On the contrary, the occurrence of such a large number of these accidents in this study clearly demonstrates the danger areas and confirms the need for safety programs involving separate turn lanes, more limited access roads, more grade crossings, etc. (i.e. any action which reduces the need for stopping or drastic reduction in speed within the main stream of traffic).

3.2 Accident and Involvement Rates by Road and Time of Day

Table 3.2.1 gives the number of accidents, number of involvements, and the associated rates by time of day for each section of state road extending from Bloomington to the Monroe County line. It is recognized that over the time period of this study, daylight hours varied considerably. However, for convenience and also to eliminate any inconsistency in the data collection activity relative to the determination of day versus night, day is defined as the time period between 6:00 A.M. to 7:00 P.M.

Table 3.2.1 provides a more detailed breakdown of the data than the volume of data actually warrants (i.e. 200 accidents split into 14 classes). Hence, the amount of data in some of the classes is insufficient for drawing conclusions. Even for the case where a statistical test rejects the null hypothesis the Type II error is very large for small sample sizes; consequently, misleading results may be obtained.

For those situations where sufficient data are available for making comparative analyses, the chi-square statistic may be used in making tests of significance. The following example illustrates how this test may be carried out. Suppose we wish to determine whether the daytime involvement rate for Highway No. 37 North (3.3 involvements per MVM) is significantly higher than the daytime rate for Highway No. 37 South (1.9 involvements per MVM). Table 3.2.2 is then constructed:

Table 3.2.1 Number of Accidents, Number of Involvements and Associated Rates by Road by Time-of-Day*

<u>Road</u>	<u>Time-of-Day</u>	<u>Number of Accidents</u>	<u>Number of Involvements</u>	<u>No. Acc. per MVM</u>	<u>No. Inv. per MVW</u>
No. 46 East	Day	8	14	1.2	2.1
	Night	5	8	2.5	3.9
	Total	13	22	1.5	2.5
No. 46 West	Day	20	36	2.2	4.0
	Night	5	7	2.0	2.8
	Total	25	43	2.2	3.7
No. 45 East	Day	14	22	5.4	8.4
	Night	5	5	6.8	6.8
	Total	19	27	5.7	8.1
No. 45 West	Day	18	35	2.1	4.0
	Night	4	8	1.7	3.4
	Total	22	43	2.0	3.9
No. 48 West	Day	6	9	1.0	1.6
	Night	1	1	.8	.8
	Total	7	10	1.0	1.4
No. 37 North	Day	48	105	1.5	3.3
	Night	17	29	1.7	2.9
	Total	65	134	1.6	3.2
No. 37 South	Day	30	51	1.1	1.9
	Night	19	33	2.2	3.8
	Total	49	84	1.4	2.4

* For Highway No. 37 the time period covered is December 7, 1968 through December 31, 1969. For all other State Roads the time period is December 7, 1968 through July 31, 1969.

Day is defined as the time period 6:00 A.M. to 7:00 P.M.

Table 3.2.2 Observed and Expected Number of Daytime Involvement on Highway No. 37

	<u>Observed No. Involvements</u>	<u>Expected No. Involvements*</u>	<u>(O - E)²</u>
	(O)	(E)	(E)
Highway No. 37 North	105	85	4.7
Highway No. 37 South	51	71	5.6
			<u>χ² = 10.3</u>

* Number of involvements expected under the null hypothesis that both roads have the same rate (i.e. rate averaged over both roads). The average rate times the vehicle mileage for a given road gives the expected number of involvements for that road.

Under the null hypothesis of no difference between the two involvement rates, a χ^2 value equal to or larger than $\chi^2 = 10.3$ would occur by chance less than one time in a hundred. Since our calculated value of $\chi^2 = 10.3$ represents an unlikely event, we reject the null hypothesis and conclude that the daytime involvement rate for Highway No. 37 North is greater than (or not equal to) that of Highway No. 37 South. In this case, our chance of being incorrect in drawing this conclusion is less than one in a hundred.

These two roads differ in many respects. For example, Highway No. 37 South as compared to the northern section is asphalt rather than concrete, contains more curves and grades, has lower speed limits, and shows a much higher degree of roadside development. In view of these differences, one may expect the daytime involvement rate to be higher on Highway No. 37 South, which is contrary to the results shown above. In this regard it is instructive to examine the accident rate for these two roads rather than the involvement rate, since multiple vehicle-accidents affect the latter rate but not the former. The following table provides the necessary data for comparing the daytime accident rates.

Table 3.2.3 Observed and Expected Number of Daytime Accidents on Highway No. 37

	<u>Observed No. Accidents</u>	<u>Expected No. Accidents</u>	<u>$(O - E)^2$ (E)</u>
	(O)	(E)	
Highway No. 37 North	48	42.5	0.71
Highway No. 37 South	30	35.5	0.85

$$\chi^2 = 1.56$$

This result ($\chi^2 = 1.56$ with 1 degree of freedom) indicates there is no evidence of a significant difference in accident rates for the two roads. What happened in this situation was that more 3, 4, and 5 vehicle accidents occurred on Highway No. 37 North so as to increase the involvement rate to a significantly high level. Higher speeds on Highway No. 37 North may have been a contributing factor to the increase in the number of 3, 4, and 5 vehicle accidents.

These analyses merely serve to illustrate the types of considerations one must keep in mind in drawing conclusions from the results based on a particular comparison. In-depth analysis is required in all comparisons of interest.

3.3 Estimating Vehicle Mileage

Table 3.3.1 gives the estimated total vehicle mileage of the state roads in Monroe County, Indiana included in the study. For State Roads 45, 46, and 48, the time period covered by these mileage estimates is December 7, 1968 through July 31, 1969. Speed and volume count information obtained through radar spot speed measurements provided the source data for the mileage estimates for State Roads 45, 46, and 48. On the other hand, the computer-sensor system provided the source data (speeds and volume counts) for estimating vehicle mileage for Highway No. 37. Because of the differences in the source data, the procedures for estimating vehicle mileage for State Roads 45, 46, and 48 and State Road 37 are discussed separately in Appendix D.

Table 3.3.1 Estimated Vehicle Mileage* (in thousands of miles)

Location		Speed Deviation Interval (mph)					Total
		<-15.5	-15.5 to - 5.5	- 5.5 to 5.5	5.5 to 15.5	>15.5	
No. 46 (East)	Day**	77	1,332	3,786	1,332	77	6,604
	Night	19	402	1,191	402	19	2,033
	Total	96	1,734	4,977	1,734	96	8,637
No. 46 (West)	Day	111	1,780	5,263	1,780	111	9,045
	Night	70	547	1,231	547	70	2,465
	Total	181	2,327	6,494	2,327	181	11,510
No. 45 (East)	Day	19	480	1,614	480	19	2,612
	Night	5	144	437	144	5	735
	Total	24	624	2,051	624	24	3,347
No. 45 (West)	Day	127	1,841	4,781	1,841	127	8,717
	Night	46	522	1,206	522	46	2,342
	Total	173	2,363	5,987	2,363	173	11,059
No. 48 (West)	Day	74	1,105	3,378	1,105	75	5,736
	Night	23	276	734	276	23	1,332
	Total	97	1,381	4,112	1,381	97	7,068
No. 37 (North)	Day	839	6,739	16,360	6,739	839	31,516
	Night	332	2,184	4,838	2,184	332	9,870
	Total	1,171	8,923	21,198	8,923	1,171	41,386
No. 37 (South)	Day	511	5,473	14,313	5,473	511	26,281
	Night	208	1,847	4,465	1,847	208	8,575
	Total	719	7,320	18,778	7,320	719	34,856
All Roads	Day	1,758	18,750	49,495	18,750	1,758	90,511
	Night	703	5,922	14,102	5,922	703	27,352
Grand Total		2,461	24,672	63,597	24,672	2,461	117,863

* For Highway No. 37 the time period covered is December 7, 1968 through December 31, 1969. For all other State Roads the time period is December 7, 1968 through July 31, 1969.

** Day is defined as the time period 6:00 A.M. to 7:00 P.M.

3.4 Tracking Vehicles Using the Computer-Sensor System

The Computer-Sensor System provides two main functions in the Speed and Accident investigation. These are:

1. To provide traffic flow characteristics of the traffic stream on Highway No. 37 (Described in Section 5),
2. To identify accident-involved vehicles and to give an estimate of the speed(s) of these vehicle(s).

The latter function is the most important one relative to the primary objective of this study. There are several factors which can be used in the identification of accident-involved vehicles. Some of these factors are directly a function of the computer-sensor system and others are a function of post-accident investigations. Some factors which aid in identifying accident-involved vehicles from the computer printout are:

1. Sudden decrease in traffic speeds at a nearby sensor,
2. Gaps in the traffic stream,
3. Failure of a vehicle to cross the next sensor, and
4. Extreme length or speeds of the accident-involved vehicle.

If the vehicle is of average length (17 to 19 feet), that of a passenger car, then its relative position to other vehicles in the traffic stream having extreme length and/or speeds is used in identifying the accident-involved vehicle.

The factors listed above are not always sufficient to identify accident-involved vehicles because very frequently accidents do not block the traffic lanes to a sufficient extent that the traffic flow pattern at the next sensor is disturbed. This is particularly true with the sensor sites located approximately 1 to 2 1/2 miles apart. Hence, it is necessary to use post-accident investigation to identify the time and position of the accident as accurately as is possible. Furthermore, the post-accident interview with the involved person(s) and/or witness(es) can aid in identifying the relative positions of vehicles in the traffic stream. The methodology for integrating the information from the CSS and the post-accident investigation is given in Appendix B.

A brief analysis of the capability of the system is presented below, along with a brief description of the computer program for tracking vehicles through the system, and the accompanying printout for a particular accident in which the probability of identification of the accident-involved vehicle(s) is extremely high. Table 3.4.1 presents a brief summary of the accident history for August 1, 1969 through December 31, 1969. The total number of accidents observed during this period was 48 and began with accident number 262.

Table 3.4.1 Accident History

<u>Observed Information</u>	<u>Number of Cases</u>
Total number of accidents -	48
Accidents within the Computer-Sensor System (CSS) -	36
Number of accidents for which the CSS speeds were used for at least 1 involved vehicle for estimating its speed -	23
Number of accidents in which AIV's were identified with high confidence (greater than 90% for the platoons containing the AIV's) -	14
1. Number of accidents subject to the above high confidence of identification and for which the estimated speeds given by the CSS are considered relevant	9
2. Other cases for which the speeds are not relevant because of the type of the accident (e.g., a rear-ender remote from the sensor)	5
The number of accidents within the "thick" CSS which was installed as of November 4, 1969 -	0
The number of accidents for which RTI has made a track of the AIV's -	5

In summary, the information given in the above table indicates that about 25% (9 out of 36) of the accidents within the Computer-Sensor System on Highway No. 37 can be tracked to the extent that an estimate of the speed of the accident-involved vehicle(s) is useful in this investigation; and furthermore, there is a high probability of identifying the accident-involved vehicle within a platoon of a few vehicles.

There is, however, the problem that the speed of an AIV at the last sensor site is not necessarily equal to its speed at the location of the accident due to the variation of the vehicle speeds from location to location as a function of the highway geometry, environment, and other factors. This variation is very clearly pointed out in the analysis of the traffic flow characteristics in Section 5.2 of this report. Hence, even with the Computer-Sensor System, one can estimate the speed of the accident-involved vehicle to within about six mph with 90% confidence.

Table 3.4.2 lists the accident numbers and the speeds as given by the computer-sensor system printout and the accident data sheet. It should be noted that the two speed estimates are nearly identical for many accidents, the only exceptions being the rear-end accidents and those accidents involving a passing maneuver in which a vehicle has speeded up after passing over the last sensor site. As of August 1, 1969 the accident investigation was purely a post-accident investigation of lesser depth than that used prior to August 1, 1969. Therefore, considerable dependence was placed upon the speed estimates obtained from the computer printout. Prior to August 1, 1969 the computer-sensor system was not yielding sufficiently precise and accurate data in order to attempt to track vehicles and compare the estimates of speeds with those given by an independent accident investigation. Thus, there is insufficient information to analyze the speeds provided by the accident investigation teams as compared with that of the computer-sensor system as the two estimates are not independent.

Utilization of the Several Sensors to Determine the Trajectory of a Vehicle Through the Test Section

The computer-sensor system provides output on a real-time basis which enables educated guesses to be made about vehicle trajectories. Each vehicle has speed and length computed from the sensor data.

A computer program was written which can, on a time increment basis, queue the vehicles by sensor into a time sequence. This sorted vehicle speed-length data is then printed with the time sequence down the page and the sensor distance spacing at

Table 3.4.2 Comparison of Speed Estimates

<u>Accident No.</u>	<u>Vehicle No.</u>	<u>Estimated Speeds of AIV's</u>	
		<u>Computer Printout</u>	<u>Accident Data Sheet</u> (Table 6.1)
263	1	57	40
264	1	57	55
265	1	61	75
268	1	31	26
	2	29	45
	3	28	45
	4	27	45
270	1	46	45
	2	50	50
275	1		
	2	59	59
279	1	54	55
	2	59	50
280	1	60	50
	2	40	40
282	1	40	40
290	1	41	41
291	1	55	55
297	1	64	75
303	1	51	50
305	1	-	-*
	2	(28 - 47)	45
307	1	65	65
308	1	74	72
	2	68	68
309	1	57	57
310	1	42	45
316	1	64	65
319	1	-	-*
	2	58	58
	3	60	60
327	1	58	58
332	1	-	-*
	2	-	-*
	3	61	61
335	1	-	-*
	2	-	-*
	3	57	57
340	1	39	40
342	1	-	-*
	2	45	40
	3	46	46
	4	49	49
344	1	34	34
	2	34	34
351	1	38	38
	2	21	21
352	1	42	42
355	1	-	-*

* Computer estimated speeds not relevant.

a predetermined scale across the page. This method of output provides an overview of the traffic flow at each of the sensors.

Certain vehicles (longer or shorter, faster or slower) are easily found when they pass a sensor. A line may then be drawn which connects these vehicles at each sensor. These "different" vehicles effectively break the vehicle stream up into segments which contain groups of vehicles. Within these smaller groups several events are possible:

1. All vehicles remain on the road and no new vehicles enter.
2. Some vehicles leave the road and no new vehicles enter.
3. All vehicles remain on the road and new vehicles enter.
4. Some vehicles leave the road and new vehicles enter.
5. Vehicle order remains the same.
6. Vehicle order changes (passing).

Because of the multitude of possible events which can occur, at this point vehicle tracking is more of an art than a science. The usual process of vehicle tracking is as follows:

1. Locate a vehicle which has either unique speed or length characteristics at several sensor locations.
2. Connect the unique vehicle-sensor-time points with straight lines.
3. Examine the vehicles which are bounded by the vehicles located in Steps 1 and 2 for speed, headway, length, and platoon characteristics.
4. Repeat Step 2.

The basic sequence just outlined can usually be repeated within the groups defined in Step 1 until most vehicle trajectories can be traced.

The use of proportional spacing for the queue-sensor enables a visual study to be made of the traffic flow. A change in the slope of the trajectory line indicates a speed fluctuation between the sensors.

Example of Vehicle Tracking

Accident 280 has been selected as a positive example of the use of the computer-sensor system (CSS). This accident has three primary identification points which are not found in the average case; first, one accident-involved vehicle was followed by two-tractor semi-trailer trucks, second, the other vehicle was a tractor semi-trailer truck, and third, traffic was blocked (i.e. stopped) from the accident location through a sensor location. With these three facts in mind the apparent trajectories are easily found. See Figure 3.4.1 for tracking the vehicles in Accident 280.


Loops 12, 13, 14

At time 16.5579 the first of two trucks crossed Sensor 12, followed 5.4 seconds by the second, which in turn is followed 3.6 seconds later by a vehicle traveling 4 mph faster than the trucks ahead. This sub-platoon of three vehicles can be found at Sensor 13 at 16.5785. The next vehicle to cross 13 does so 36 seconds later at 34 mph (15 mph below the apparent mean speed at this time). Succeeding vehicles slow to a crawl and eventually traffic disappears from the sensor. Sensor 14 carries its normal traffic until the "point in time" at which the above vehicles should have arrived, then traffic almost disappears from it. The vehicle which was traveling 4 mph faster than the trucks is hypothesized to be the automobile involved.

Loops 10, 9, 8

Traffic disappearance is a major factor in tracking vehicles here. Traffic flows from Sensor 10 to 9 to 8. Around 16.5410 a platoon of three vehicles crosses Sensor 10, at 16.5789 they crossed 9, and at 16.6019 they crossed 8. Traffic following this platoon continues to cross Sensor 10 but disappears from Sensors 9 and 8. This platoon is followed on Sensor 10 by a 37 foot vehicle which never arrives at Sensor 9 or 8. This vehicle is hypothesized to be the tractor semi-tractor truck involved.

SOUTHBOUND NORTH OF TOWN



NORTHBOUND NORTH OF TOWN




Figure 3.4.1 Example of Vehicle Tracking (Accident 280)

16.5944
 16.5950
 16.5955
 16.5959
 16.5964
 16.5964
 16.5969
 16.5974
 16.5980
 16.5984
 16.5989
 16.5994
 16.5999
 16.6005
 16.6010 59 18
 16.6014
 16.6019
 16.6019
 16.6024
 16.6030
 16.6035
 16.6039
 16.6039
 16.6044
 16.6049 10* >2.1>
 16.6055
 16.6060
 16.6064
 16.6069
 16.6074
 16.6080
 16.6085
 16.6089
 16.6094
 16.6099
 16.6104
 16.6110
 16.6114
 16.6119
 16.6124
 16.6129 64 15
 16.6135 65 18
 16.6140
 16.6144
 16.6149
 16.6154 61 14
 16.6160 63 17
 16.6160 62 16
 16.6165
 16.6169
 16.6174 63 18
 16.6179 63 15
 16.6185
 16.6190 63 13
 16.6194
 16.6199 62 19
 16.6204 62 16
 16.6210
 16.6215
 16.6219
 16.6224
 16.6229
 16.6234
 16.6240
 16.6244 63 44
 16.6249 62 17
 16.6249 62 11
 16.6254 10* >2.1>
 16.6259
 16.6265 65 18
 16.6270
 16.6274
 16.6279
 16.6284
 16.6290
 16.6295
 16.6299
 16.6304 81 18
 16.6315
 16.6320
 16.6324
 16.6329
 16.6334
 16.6339
 16.6345 65 15
 16.6345 53 18
 16.6349 38 6

LOOP 9 TRAFFIC DISAPPEARS

57 16
 58 18
 57 17

>1.3> 8* >1.9>

LOOP 8 TRAFFIC DISAPPEARS

9* >1.3> 8* >1.9>

LOOP 9 TRAFFIC DISAPPEARS

LOOP 8 TRAFFIC DISAPPEARS

16.5934
 16.5939
 16.5944
 16.5944
 16.5950 60 18
 16.5955 14*
 16.5959 60 18
 16.5964
 16.5969
 16.5974
 16.5980
 16.5980
 16.5984
 16.5989
 16.5994
 16.5999
 16.6005
 16.6010
 16.6014
 16.6014
 16.6019 60 13
 16.6024
 16.6030
 16.6035
 16.6039 65 17
 16.6044
 16.6049
 16.6055
 16.6060
 16.6064
 16.6069
 16.6074
 16.6080
 16.6085
 16.6089
 16.6094
 16.6099
 16.6104
 16.6110
 16.6114
 16.6119
 16.6124
 16.6129
 16.6135
 16.6140
 16.6144
 16.6149 54 12
 16.6154
 16.6160
 16.6160
 16.6165 14* <2.1<
 16.6169
 16.6174
 16.6179
 16.6185
 16.6190
 16.6190
 16.6194
 16.6199
 16.6204
 16.6204
 16.6210
 16.6215
 16.6219 52 15
 16.6224
 16.6224
 16.6229
 16.6234
 16.6240
 16.6244
 16.6249
 16.6249
 16.6254
 16.6259
 16.6265
 16.6265
 16.6270
 16.6274
 16.6279
 16.6284
 16.6290
 16.6295
 16.6299
 16.6304
 16.6309
 16.6315
 16.6320
 16.6324
 16.6329
 16.6334
 16.6339
 16.6345
 16.6345
 16.6349

LOOP 13 TRAFFIC DISAPPEARS

LOOP 13 TRAFFIC DISAPPEARS

LOOP 14 TRAFFIC DISAPPEARS

30 19
 27 15
 13* <1.3< 12* <1.9<
 63 16
 17 22 49 30
 49 13
 47 16
 16 21
 12 18
 62 15
 66 15
 56 17
 59 18
 53 15
 56 18
 0 0
 0 0
 12* <1.3< 12* <1.9<
 55 16
 52 10
 51 10
 55 17
 54 15
 62 16
 53 15
 61 13
 59 14
 50 27
 50 25
 49 10
 48 16
 47 16
 46 11

B

3.5 Classifications of Accidents

Included in Section 6 is a listing of each accident investigated along with certain accident data considered pertinent to this study. These accidents have been classified according to:

- a) Type of accident
- b) Location
- c) Day of occurrence
- d) Light conditions
- e) Seat belt usage
- f) Evidence of alcohol
- g) Weather condition
- h) Sex of driver
- i) Age of driver
- j) Year of vehicle.

The results of these categorizations are shown in Table 3.5.1, prepared primarily for informational purposes. It is difficult to draw conclusions from these data alone, since direct comparison of absolute numbers of accidents are, in most cases, invalid. Other information must be considered in making comparative analyses. For example, male drivers were involved in 368 accidents (73% of all involvements), whereas, female drivers were involved in 136 accidents (27% of all involvements). According to the 1960 U.S. Census data, the breakdown of the Monroe County driver-age population (ages 16-70) by sex shows an almost even split between males and females (50.4% and 49.6% respectively). If one is willing to assume that males and females drive an equal amount, then we could conclude from these data that males are more likely to be involved in an accident. However, the above assumption is invalid since the male population normally has greater exposure in terms of miles driven. Hence, information regarding miles driven by males and females is necessary in order to make a comparative analysis. As a second example, consider the breakdown of accidents by

Preceding page blank

Table 3.5.1 Accidents Classified According to Type, Location, Environment, Driver and Vehicle Characteristics

<u>(a) Type of Accident</u>		<u>(b) Location</u>	
Single	110	Highway #37 North	65
Multiple	184	Highway #37 South	49
Head-on	32	Highway #45 East	19
Rear-end	81	Highway #45 West	22
Side	71	Highway #46 East	13
		Highway #46 West	25
		Highway #48 West	7
		Other County Roads	94
<u>(c) Day of Occurrence</u>		<u>(d) Light Conditions</u>	
Weekday	188	Day	173
Weekend	106	Night	103
		Dusk	12
		Dawn	6
<u>(e) Seat Belt Usage</u>		<u>(f) Evidence of Alcohol</u>	
Used	39	Yes	40
Not Used	144	No	438
Not Installed	84	Unknown	34
Use Unknown	254		
<u>(g) Weather Conditions</u>		<u>(h) Sex of Driver</u>	
Clear	174	Male	368
Rain	59	Female	136
Snow	13	Not Identified	8
Ice	6		
Overcast	37		
Fog	5		
<u>(i) Age of Driver</u>		<u>(j) Year of Vehicle</u>	
< 19	102	1970	1
20 - 24	119	1969	56
25 - 29	59	1968	67
30 - 34	46	1967	60
35 - 39	28	1966	60
≥ 40	147	1965	66
Unknown	11	1964	50
		1963	44
		1962	37
		1961	11
		1960	12
		< 1960	37
		Unknown	11

year of vehicle. To illustrate how additional information may be utilized in making comparative analyses of model years the following table has been prepared.

Table 3.5.2 Observed and Expected Number of Accidents by Year


<u>Year</u>	<u>Observed No. Accidents</u>	<u>Expected No. Accidents*</u>
1969	56	45.4
1968	67	64.4
1967	60	63.4
1966	60	59.3
1965	66	52.8
1964	50	46.3
1963	44	42.1
1962	37	37.0
1961	11	29.2
1960	12	23.2

* The expected number of accidents was obtained by multiplying the proportion of vehicles for a given model year by the total number of accidents. Data on a national basis for proportion of vehicle by model year may be found in Automotive News 1969 Almanac.

A chi-square statistic may be used to determine whether the differences between the observed and expected number of accidents can be attributed to chance variation. In carrying out this statistical test, however, one must assume equal exposure for all model year vehicles which may not be completely valid. If data are available on exposure by model year then these should be used to obtain the expected number of accidents.

In addition, a map of the state highways in Monroe County is shown in Figure 3.5.1 with the locations of the accidents superimposed. Although the locations of accidents appear to be well dispersed throughout the county, there are indications of "danger" spots. Stations 102, 103, 203, 209, 305, 401, 603 and 609 appear to have experienced a proportionately high number of accidents. In analyzing Figure 3.5.1 one must recall that for Highway No. 37 the time period covered is December 7, 1968 through December 31, 1969. For the remaining State Roads the time period is December 7, 1968 through July 31, 1969.

Figure 3.5.1 Accident Locations - Monroe County



For each of the accidents on the state highways in Monroe County and involving at least one vehicle in the low-, medium-, and high-speed deviation categories, the most pertinent contributing factors were tabulated and the results are given in Table 3.5.3.

Table 3.5.3 Contributing Factors Versus Speed Deviation Category

Contributing Factors	Speed Deviation Category			
	$\Delta S_D < -15.5$		$-5.5 < \Delta S_D < 5.5$	$\Delta S_D > 15.5$
	No Turning Maneuver	Turning Maneuver		
1. Lost control	2	1	20	14
2. Too fast for road and weather conditions	1	0	8	10
3. Road surface slippery	5	6	21	8
4. Following too closely	5	14	21	3
5. Passing maneuver	2	9	8	3
6. Forced off road	0	1	6	2
7. Too slow for normal traffic flow	1	1	0	0
8. Vision obscured	3	9	10	4
9. Narcolepsy	0	0	0	1
10. Mechanical defect	1	5	6	1
11. Interaction with turning maneuver	0	26	15	2
12. Alcohol*	0	1	6	6
13. Wrong side of road	3	2	15	9
14. Inattention	2	10	8	1
15. Failure to yield right of way (primary factor)	0	13	5	1

* Those instances of alcohol involvement reported reflect the driver status as noted on the investigating officer's report. Neither strict guidelines nor legal aids exist in Indiana to provide for the identification of the drunk driver. Except in the extreme case where a blood-alcohol test was administered, most reported incidences of alcohol were based on the subjective judgement of the investigating officer.

4. SYSTEMS ANALYSIS

At the inception of this project it was intended that the computer-sensor system be able to provide data in a real time system in two basic areas:

1. To record traffic parameters as a function of time and sensor position on Highway 37; in particular, this includes the speed, density, headways, and mix of vehicles on the roadway during the time of an accident.
2. Identification of the accident-involved vehicles (AIV's) such that their speeds over the last sensor before the accident site could be determined.

The computer-sensor system was able to provide data in Area 1 very satisfactorily. In this respect, data are now available which have not been previously collected regarding the specific overall traffic parameters in the stream of flow containing the AIV's. These data are very important in determining the mean speeds of surrounding traffic flow, which are really half the speed data required for determining speed deviations of the AIV. In this respect the computer-sensor system has been valuable.

One of the most difficult tasks (Area 2) of this project was to estimate accurately the speeds of the AIV's. In general, only a small number of AIV's were identified with this system, i.e., in approximately 25% of the accidents was it possible to identify the specific AIV or the platoon of vehicles containing the AIV as they passed over the last sensor before the accident site. The 25% figure may seem low at first reading; however, the following rationalization may help to explain the figure and also indicate the additional number of sensor sites necessary to increase the figure to a relatively high percentage. The first eight sensor sites were dispersed over a section of road approximately 11.2 miles in length (not including the sections beyond the outer loops) or about 12.2 miles allowing one-quarter mile on each end of the two instrumented sections of Highway 37 North and South. The "sight" distances

Preceding page blank

vary from one loop site to another, but suppose that the area surrounding each site can be "observed" by an average distance of about one-quarter of a mile in each direction, then the eight sites "cover" approximately four miles or about 33% of the road. To yield a high percentage coverage would require two to three times as many loop sensors. They could be located so that the sight distance would be such that the occurrence of an accident anywhere on the road would result in an almost immediate disturbance in the traffic flow at one of the adjacent sensor sites. Since the additional sensor sites added in the later portion of this study are located within approximately this distance (i.e. six sites were added within the distance of two sites), it appears that data should become available to check the validity of these remarks.

Since the accuracy and precision of the computer-sensor system was assessed just prior to August 1, 1969, the intensive use of the CSS to provide the required speed data for each accident within the outer loops of the CSS began at that time. From this point until December 31, 1969, 36 accidents occurred on Highway 37 within the sensor system. Since, in approximately 9 cases the AIV's could be identified with a high degree of confidence, either as the individual vehicle or one member of a platoon, it appears that the cost per accident is quite high. In fact, if this were the only justification of the CSS the cost per accident exceeds that of a multidisciplinary accident investigation, the latter being about \$2,000 to \$2,500 per accident. If two to three times as many sensors could be added to the roadway and the additional cost increase by no more than 25% and if the percentage of detection of the AIV's could be increased to 90%, the cost could be reduced to about \$1,400 per accident. This tradeoff of cost needs to be evaluated for the potential value of such data in future highway safety programs.

However, as mentioned previously, the CSS has provided for this study the necessary characteristics of the traffic flow surrounding that of the accident. Without improved measures of individual and mean traffic speeds, standard deviation of speeds, and volumes, the precisions of the estimates of the involvement rates as

a function of speed deviation would have been reduced. Thus the use of the CSS as a means of providing pertinent traffic flow data is not easily converted to a cost figure for the primary purpose of this study.

4.1 System Availability

Individual observations of speed, length and headway for each vehicle crossing a pair of magnetic loop detectors are generated by the computer-sensor system and stored on magnetic tape. Through a series of data processing techniques, these individual observations are reduced to Hourly Summary Reports which, through various summary statistics, characterize the events of interest during one-hour periods at each loop site. The volume of traffic in each direction on Highway No. 37 is sufficiently high so as to insure that at least one vehicle per hour will cross each loop which is sufficient to generate an Hourly Summary Report. Hence, for each 24-hour day the complete system, composed of sixteen loops, should generate a total of $16 \times 24 = 384$ hourly reports. Based on the presence of these reports and the usability of data contained therein a system availability is calculated. System availability for a given time period is defined as the ratio of the number of hourly reports for the time period which contain usable data to the total possible hourly reports, expressed in percent. Four hours during each seven day period are normally scheduled for maintenance, thus the availability cannot exceed $100 \times 164/168 = 97.6\%$ unless the maintenance period is shorter than anticipated. The numerator of this ratio is affected by two factors. First, if the hourly report is missing then, naturally, the data for that report is not usable. Second, if the hourly report shows the bad car count (BCC) $\geq 5\%$ then the data for that report is considered unusable. The 5% is an arbitrary value. Frequently, the computer-sensor system will sense the passage of a vehicle over the sensor; however, the speed and length is recorded as zero - this constitutes a bad car count. A BCC of 5% infers that 5% of the total activations had speed and length of zero. Several possible causes of this phenomena are given below.

1. Improper lane usage.
2. One of the two Vedets per loop set can fail locking the relay open or shut.
3. The field strength of one of the VeDets may be less than its pair loop so that one loop detects (or fails to detect) when the other loop does not. This often occurs with trailer trucks with the body some distance from the road surface.
4. Loops 11 and 15 and 10 and 14 were multiplexed using a single phone line. We believe, but have been unable to document because of the intermittency, that the multiplex circuit equipment malfunctions sending multipulse signals that cause misinterpretation by the computer.

During July 1969 the problem of VeDet sensitivity to deal with 3. above was studied. It was discovered in loops 8-15, which were located in the concrete portion of North 37, that the interaction between the wire loops and the iron reinforcing rods contained in the concrete was sufficient to greatly alter the field above the loops. This resulted in insufficient detection, particularly of trucks. In mid-August and throughout September the power input of the northern detectors was raised in order to increase the field strength over the wire loops. At the same time the relays utilized in the output were altered in all units. Increasing the field strength did reduce the BCC but it also increased the sensitivity of the unit requiring more frequent tuning and making it more temperature sensitive.

The data involving BCC's can be divided into two types:

1. Non-continuous failure where intermediate data are accurate and may be viewed as a sample. Volume count would be affected but in some cases can be corrected.
2. Continuous failure where the data samples are not usable.

Normally, the change from type 1 to 2 is quite evident because usually the VeDet is either operational, accurate and missing only a relatively few vehicles or it is non-operational, missing almost all vehicles. If a detector were properly calibrated, it is expected that accurate speed data on the portion of vehicles counted would be provided even though BCC is as large as 15%. Situations have been observed where the BCC is almost 100% and the actual number of BCC recorded during an hour far exceeds the expected number of vehicles for that hour. Also, there is evidence that during these times the recorded speeds are grossly in error.

Beginning with June 23, 1969, weekly system availability percentages have been calculated for each of the loops and for all sixteen loops combined. Data are presented on paired loops because of the commonality in location and the similarity of the availability figures for loop pairs. The results are shown in Table 4.1.1 for the 22 week period from June 23, 1969 through November 23, 1969.

For the sixteen loops combined, the weekly system availability ranged from 54% to 93%. On a paired loop basis the weekly system availability ranged from 0% to 99%. With one exception (Loop No.'s 11 and 15) all paired loops had one or more weeks in which the system availability was 96% or higher. This alone demonstrates that the system is capable of high level performance. The overall level of performance measures the effects and interactions of many factors as listed above, for some of which an adequate solution may be simple, complex, expensive and/or time consuming. A detailed systems analysis is needed with regard to accuracy, repeatability, maintainability, the identification of problem areas (including causes and possible solutions), recommendations for improvement, and other areas of vital interest to potential users of such a system.

System availability as shown in Table 4.1.1 provides, on a weekly basis, an overall view of the system's operational characteristics. This does not, however, provide information to the detailed level required to attempt to identify or diagnose the underlying causes or problems. Some additional analyses have been made

Table 4.1.1 System Availability (%)*

Loop No.	Time Period													
	WEEK 1	WEEK 2	WEEK 3	WEEK 4	WEEK 5	WEEK 6	WEEK 7	WEEK 8	WEEK 9	WEEK 10	WEEK 11	WEEK 12	WEEK 13	WEEK 14
	6/23 - 6/29	6/30 - 7/6	7/7 - 7/13	7/14 - 7/20	7/21 - 7/27	7/28 - 8/3	8/4 - 8/10	8/11 - 8/17	8/18 - 8/24	8/25 - 8/31	9/1 - 9/7	9/8 - 9/14	9/15 - 9/21	9/22 - 9/28
	%	%	%	%	%	%	%	%	%	%	%	%	%	%
0 & 4	70	96	88	92	94	97	94	86	90	96	93	82	42	80
1 & 5	75	96	87	93	95	99	95	88	82	99	95	84	74	86
2 & 6	76	92	88	94	86	98	95	86	83	96	96	86	74	90
3 & 7	75	98	90	90	96	99	89	79	84	99	98	86	76	90
8 & 12	76	96	70	72	96	92	93	84	87	95	89	74	49	70
9 & 13	18	45	44	86	96	90	95	87	91	98	93	70	54	81
10 & 14	36	65	42	54	77	93	94	85	91	99	88	82	73	85
11 & 15	15	25	16	42	69	79	60	64	62	0	27	46	8	0
TOTAL (16 Loops)	55	77	66	78	89	93	89	82	84	85	85	76	56	73

* Scheduled maintenance time of four hours per week of 168 hours reduces the maximum value to 97.6%. Values exceeding 97.6% result from maintenance times shorter than anticipated.

Table 4.1.1 (Continued)

Loop No.	Time Period							
	WEEK 15	WEEK 16	WEEK 17	WEEK 18	WEEK 19	WEEK 20	WEEK 21	WEEK 22
	9/29 - 10/5	10/6 - 10/12	10/13 - 10/19	10/20 - 10/26	10/27 - 11/2	11/3 - 11/9	11/10 - 11/16	11/17 - 11/23
	%	%	%	%	%	%	%	%
0 & 4	68	75	72	70	65	75	80	71
1 & 5	71	78	72	72	68	74	79	90
2 & 6	73	25	52	74	67	72	58	75
3 & 7	73	79	76	75	68	76	58	62
8 & 12	33	0	50	72	63	75	63	66
9 & 13	71	76	72	73	69	76	74	0
10 & 14	63	67	63	62	64	76	70	63
11 & 15	24	31	53	67	61	70	49	64
TOTAL (16 Loops)	60	54	64	71	66	74	66	61

for the four week period of September 1st to 28th, 1969. This time period is almost four months after the system became operational and one month before the system was expanded to include six additional sets or loop pairs. During the month of September, program development for the expanded system as well as hardware implementation was on-going. In particular the 1:00 to 4:00 P.M. time period and the 12:00 to 6:00 A.M. time period were chosen for system shut down. This was done to maximize the chances of collecting data at high accident times.

Figure 4.1.1 shows, by time of day, the percentage of missing hourly summary reports. For each hour over a four week period there should be 448 hourly reports (28 hourly reports for each of the 16 loops). Figure 4.1.1 shows, for example, that for the hour ending at 2:00 A.M., 25% of 112 of the 448 reports are missing. The percentage of missing reports is slightly higher during the early morning hour (midnight to 6:00 A.M.) than during the remainder of the day, with the exception of the period from 2-4:00 P.M. During this period the high percentage of missing reports reflects deliberate down time in conjunction with system upgrade. Thus the percentages at times other than 12 to 6:00 A.M. and 1 to 4:00 P.M. provide a reasonable estimate of system performance with regard to missing reports.

Figure 4.1.2 shows, by time of day, the percentage of hourly summary reports in which the bad car count (BCC) \geq 5%. The 5% level is an arbitrary selection. The percentages of BCC during low volume hours (nighttime) are significantly higher than for the remaining hours. This would suggest that possibly trucks and improper lane usage represent problems to the system, since the percentage of trucks and improper lane usage is higher during low volume hours. These are system problem areas which should receive high priority in future research.

A comparison of the results in Figures 4.1.1 and 4.1.2 with those for November 1 to 24, 1969 indicates that no significant change in system performance with regard to missing reports but that the BCC's are reduced to about 4%.

Figure 4.1.1 Percentage of Missing Hourly Summaries by Time of Day
 (Time Period 9/1/69 to 9/28/69)





Figure 4.1.2 Percentage of Hourly Summaries with BCC \geq 5% by Time of Day
(Time Period 9/1/69 to 9/28/69)



The table below shows, by paired loops, the percentage of hourly summary reports in which the BCC \geq 5% along with some comments pertaining to the values for BCC's. These results enable direct comparisons to be made among the loop sites. Both "good" and "bad" loop sites exist, as evidenced by Pairs 3 & 7 and 11 & 15 respectively.

Table 4.1.2 Percentage of Hourly Reports With BCC \geq 5% Versus Loop Pair

<u>Loop Pair</u>	<u>Percentage of Hourly Reports with BCC \geq 5%</u>
0 - 4	5.7 ← probably best site but
1 - 5	2.3 high volume of improper
2 - 6	2.1 lane usage at low traffic
3 - 7 ← very low improper lane	0.6 volumes
8 - 12 usage due to road geometry	18.0
9 - 13	3.1
10 - 14	5.9
11 - 15	46.5 ← high interacting with reinforcing rods

System availability reflects both missing data and data discarded due to BCC \geq 5%. One may question the validity of discarding speed data for those cases where the BCC was \geq 5%. However, a very large quantity of data are available and this decision should minimize the error of biased estimates while maintaining sufficient data for performing the desired analyses.

4.2 System Accuracy and Repeatability

About three months after the computer-sensor system became operational, a speed check of accuracy and repeatability was made on the entire system. Each of the sixteen pairs of magnetic loop detectors (identified as Loop No.'s 0, 1, ..., 15) was checked for accuracy and repeatability of vehicle speed through the use of an RTI-supplied speed measuring device consisting of pressure sensitive tapes coupled to an extremely accurate electronic timer. When a vehicle traversed a loop, simultaneous readings of its speed were obtained from the "timer" and the "computer-sensor system." Appendix G contains the speed data collected for each of the sixteen loops. As a result of the method employed in calculating speed (truncation), the

computer is expected to read 0.5 mph below the timer speed. Hence, the expected difference is $\bar{d} = -.5$ when the bias is zero. Assuming the error associated with the timer is negligible, then s_d reflects the repeatability of the computer-sensor system.

From a total system standpoint, the computer-sensor system measures vehicle speed satisfactorily. Ten of the sixteen loops showed a bias less than .5 mph. The biases shown in the remaining six loops could be eliminated by "adjustments" to the computer programs. Loop 7 exhibited the largest bias, $\bar{d} = -4.6$ mph. From the standpoint of repeatability, only six of the sixteen loops showed standard deviations greater than 1.0 mph. These are:

<u>Loop No.</u>	<u>Standard Deviation (s_d)</u>
10	1.1
9	1.2
12	1.3
13	1.6
6	1.7
8	2.2.

A systems study should be made to determine how these loops differ from the remaining ten loops which showed standard deviations less than 1.0 mph. Also, it should be determined if there are economically justifiable ways of reducing the standard deviation to 1.0 mph or less.

All accuracy checks on these sixteen loops made prior to and subsequent to this test utilized radar as the standard or control.

4.3 Analysis of Estimated Vehicle Lengths

Several platoons of vehicles were followed through the Computer-Sensor System to determine the variation of the estimated lengths as given by the computer printout at various sites. As an example, the following data were selected from a printout for August 30, 1969 (Loops 6 and 7, SR 37 South).

TABLE 4.3.1 ESTIMATED LENGTHS (IN FEET)

Vehicle	Loop 7	Loop 6	Total
1	41	43	84
2	14	17	31
3	17	17	34
4	15	18	33
5	15	16	31
6	15	17	32
7	16	15	31
8	18	19	37
9	11	13	24
10	17	18	35
11	32	36	68
12	11	14	25
Total	222	243	465

An analysis of variance was performed on the above data to obtain the following information:

<u>Source of Variation</u>	<u>Degrees of Freedom</u>	<u>Mean Square</u>
Among Vehicles	11	164.01
Between Loops	1	18.37
Residual	11	1.01

The variation among vehicles is a function of the particular types passing through the sensor at the time of the study and is not of interest here. The variation between loops is a measure of the bias between the two sensors, that is Loop site 6 consistently gives results slightly greater than Loop site 7. The major value of this analysis is to estimate the residual variation in estimated lengths; that is, the capability of the system to yield consistent length measurements over the several loops. The variance estimate is approximately unity and the standard deviation in the estimated length is approximately one foot based on these results. The residual variation can be expressed as a measure of the inconsistency of the bias. That is, if one loop consistently measured lengths one foot greater than another loop, the

residual variation would be zero and this bias could be made zero by appropriate changes in the computer software. However, the variation in this difference of length measurements (bias) can only be corrected through improved hardware. Several analyses of this type were performed yielding values for the residual standard deviation as follows.

Date	Loop Sets	Number of Vehicles	Residual Standard Deviation
8/30/69	0, 1	5	0.59
8/30/69	1, 2	9	1.64
8/30/69	1, 2, 3	7	0.62
8/27/69	8, 9	12	1.06
8/27/69	9, 10	10	0.88

The average residual standard deviation of the length measurement for a total of 43 vehicles is 1.08.

In a recent study [4], involving the calibration and correction of magnetic loop detectors it was pointed out that errors in excess of ten percent in speed and length are not uncommon. This study concludes that through computer logic alone there is no obvious solution to the problem of misreading the length of high ground clearance vehicles.

5. TRAFFIC FLOW CHARACTERISTICS AND ANALYSIS

The hourly volume of traffic for a given location on a road is expected to vary significantly from hour-to-hour over any consecutive 24-hour period. This variation is relatively consistent from day-to-day, especially during weekdays when the normal pattern shows peak hourly rates during the morning and afternoon rush hours, low hourly rates during early morning hours, and intermediate hourly rates elsewhere. The weekend (or holiday) hourly volume rates may differ appreciably from the weekday pattern, but again, the variation is relatively stable from day-to-day.

Also, the hourly volume of traffic at a given time is expected to vary significantly from one location on a road to another. This difference may be attributable to one or a combination of many factors such as locations of private industries, residential areas, schools, and other highways.

The volume-time relationships are described in Section 5.1. The relationships between mean speeds and traffic flow and environmental effects are considered in Section 5.2. Three models of increasing degree of complexity are fitted to the observed data by means of the method of least squares. The adequacy of these models to predict the mean speed is given.

Section 5.3 contains the mean speed and the standard deviation of speed as a function of location on the state roads (expressed as distance from Bloomington) and the environmental effects (night versus day and dry versus wet road conditions). The adequacy of the normal distribution for describing the variation in vehicle speeds is contained in Section 5.4.

5.1 Volume-Time Relationship

Volume-time relationships were developed for all the state roads in Monroe County, Indiana. These results are given in Appendix H. For Highway No. 37 (North and South), the computer-sensor system provided the source data for calculating the average hourly volume rates for Monday through Thursday, Friday, Saturday and Sunday for each of the sixteen loops. Small day-to-day differences were noted during

each hour of the day. The hourly volume of vehicles on Friday morning followed very closely the observed rates for the other weekday mornings. However, beginning around noontime, Friday's rates begin to increase and are consistently higher than the other weekdays for the remainder of the day. Also, differences in ADT were noted for Saturday and Sunday. On Highway 37 North (Loops 8-15) the Sunday ADT is higher than Saturday, whereas on Highway 37 South the reverse is true. Volume count data generated by the computer-sensor system over the period June 23, 1969 through September 30, 1969, provided the source data for Appendix H. However, holiday periods surrounding July 4th, September 1st (Labor Day), and a football game day were excluded as being non-typical. Since the computer-sensor system downtime is unknown, the hourly volume count as given by the computer-sensor system cannot be used directly in calculating the volume-time relationship. Downtime causes the average hourly rate to be under-estimated. To avoid this bias, a minimum count for each hour, day-of-week, and loop was empirically established. Those hourly volume counts below the corresponding minimum counts were then discarded. In addition, hourly volume counts in which the bad car count (BCC) exceeded 50% were also excluded in the preparation of Appendix H. A listing of factors contributing to BCC's is given in Section 4.1. It is felt that when the bad car count reaches such a high level, the hourly volume count as given by the computer-sensor system is questionable.

Appendix H also gives the hourly volume rates for the remaining state highways in Monroe County. However, these rates were based on volume counts obtained from the 15-minute radar observation periods in which speed data were being recorded. Due to the manpower requirements, it was not economically feasible to obtain a sample hourly volume count for each direction of travel for each hour of the day, for each day of the week, at each station on these state highways in Monroe County. Based on the available speed survey data, it was necessary to ignore days of the week and direction of travel in order to have sufficient data for estimating hourly volume rates at most of the stations. On each highway, data from stations having similar

average daily traffic (ADT) were combined into one volume-time curve. As expected, each highway had the highest ADT in the areas adjacent to the city of Bloomington, and as the distance from Bloomington increased, the ADT decreased. Many of the volume-time curves did not show the typical early morning high volume rate because of the manner in which the data were combined as described above.

5.2 Relationship Between Speed and Traffic Flow Characteristics

The computer-sensor system provides speed and volume information continuously, by direction of travel, at a given point on the highway. Data collected in this manner provides an opportunity to statistically analyze the effect of volume rate (vehicles per hour) on the speed characteristics, mean and variability. Multiple regression techniques were employed in the evaluation of how speeds are affected by such factors as vehicles per hour in same direction, vehicles per hour in opposing lane, number of trucks per hour (based on length measurements), day effect, hour-within-day effect, and so on. Three linear models were considered:

a) Model I: $\hat{Y} = b_0 + b_1X_1 + b_2X_2 + b_3X_3$
 where \hat{Y} = Predicted hourly mean speed (or standard deviation) (mph)
 X_1 = Vehicles per hour in same direction (100's Veh.)
 X_2 = Vehicles per hour in opposite direction (100's Veh.)
 X_3 = X_1X_2 .

Model I is the simplest of all models examined in that it uses only volume information in each direction and their interaction as independent variables. The results of fitting this model to actual speed characteristics at four locations on Highway 37 North (Loop Nos. 8, 10, 12, and 14) are given in Tables 5.2.1 and 5.2.2. The data used in fitting this model were collected during Saturday and Sunday daylight hours (7 A.M. - 7 P.M.). Weekends were selected because of the vehicle per hour rate which ranged from 100 to 1,200 (one direction). In addition to fitting the full model, consisting of three variables (X_1 , X_2 , and X_3), all possible regression equations involving these three variables were evaluated and the results are given in Tables 5.2.1 and 5.2.2. From this, the effects of the variables taken singly or

in combinations can be easily ascertained from the R^2 values for each regression equation. R^2 is a measure of the goodness of fit of the regression in that it is the fraction of the total sum of squares of deviations of the observed Y (dependent variable) that is attributable to regression.

In Table 5.2.1, which treats hourly mean speed as the dependent variable, R^2 for Model I varies from .596 (Loop 14) to .842 (Loop 8). This says, in effect, that from approximately 60% to 84% of the hourly variation in speeds is attributable to variations in hourly volume counts. From the values of R^2 it is not necessary to include all of the variables X_1 , X_2 , and X_3 in the regression equation. For example, at Loop 8, R^2 for the full model is .842 whereas for the equation including only X_1 , R^2 was .840. Figure 5.2.1 shows a plot of the hourly mean speeds at Loop 8 versus the hourly volume (same direction). In general, for these four locations X_1 considered alone or X_1 and X_2 combined will provide essentially the same information as when X_1 , X_2 , and X_3 are used. As expected, for all four locations the coefficients of X_1 and X_2 taken separately or together are negative and, also, the magnitude of the X_1 coefficient is larger.

Table 5.2.2 gives the results of fitting Model I to a new dependent variable Y (hourly standard deviations in speed). As evidenced by the R^2 values, variables X_1 , X_2 , and X_3 do not account for a very large portion of the changes in speed variation. Hourly standard deviations of speed are not affected by hourly volumes to the extent that mean speeds are affected by the same variables.

$$b) \text{ Model II: } \hat{Y} = b_0 + b_1X_1 + b_2X_2 + b_3X_3 + b_4X_4 + b_5X_5 + b_6X_6$$

$$\text{where } \hat{Y} = \text{Predicted hourly mean speed (mph)}$$

$$X_1 = \text{Vehicles per hour in same direction (100's Veh.)}$$

$$X_2 = \text{Percent vehicles in same direction } > 22' \text{ (\%)}$$

$$X_3 = \text{Vehicles per hour in opposite direction (100's Veh.)}$$

$$X_4 = (X_1 - d)^2$$

$$X_5 = X_1X_3$$

$$X_6 = X_3X_4$$


Table 5.2.1 Regression Equations and R^2 for Four Locations
Using Model I with Hourly Mean Speed as the Dependent Variable

<u>Location</u>	<u>Regression Equation</u>	<u>Independent Variables</u>	<u>R^2</u>
Loop 8	$Y = 63.3 - 1.26X_1$	X_1	.840
	$Y = 57.9 - 0.17X_2$	X_2	.015
	$Y = 59.8 - 0.13X_3$	X_3	.274
	$Y = 63.4 - 1.25X_1 - 0.01X_2$	X_1, X_2	.840
	$Y = 63.4 - 1.23X_1 - 0.01X_3$	X_1, X_3	.841
	$Y = 58.4 + 1.28X_2 - 0.31X_3$	X_2, X_3	.556
	$Y = 63.1 - 1.17X_1 + 0.14X_2 - 0.04X_3$	X_1, X_2, X_3	.842
Loop 12	$Y = 56.4 - 0.65X_1$	X_1	.520
	$Y = 55.9 - 0.43X_2$	X_2	.233
	$Y = 56.4 - 0.13X_3$	X_3	.705
	$Y = 57.9 - 0.61X_1 - 0.36X_2$	X_1, X_2	.678
	$Y = 56.5 - 0.96X_1 - 0.12X_3$	X_1, X_3	.709
	$Y = 56.5 - 0.03X_2 - 0.13X_3$	X_2, X_3	.706
	$Y = 57.1 - 0.23X_1 - 0.14X_2 - 0.09X_3$	X_1, X_2, X_3	.719
Loop 10	$Y = 64.5 - 1.45X_1$	X_1	.644
	$Y = 58.7 - 0.26X_2$	X_2	.019
	$Y = 58.9 - 0.12X_3$	X_3	.130
	$Y = 65.0 - 1.44X_1 - 0.14X_2$	X_1, X_2	.650
	$Y = 64.4 - 1.47X_1 + 0.01X_3$	X_1, X_3	.645
	$Y = 59.0 + 0.78X_2 - 0.24X_3$	X_2, X_3	.193
	$Y = 66.2 - 1.75X_1 - 0.74X_2 + 0.14X_3$	X_1, X_2, X_3	.683
Loop 14	$Y = 60.8 - 0.64X_1$	X_1	.423
	$Y = 60.5 - 0.43X_2$	X_2	.207
	$Y = 60.7 - 0.13X_3$	X_3	.515
	$Y = 62.5 - 0.61X_1 - 0.38X_2$	X_1, X_2	.592
	$Y = 60.9 - 0.22X_1 - 0.10X_3$	X_1, X_3	.533
	$Y = 61.1 - 0.14X_2 - 0.12X_3$	X_2, X_3	.531
	$Y = 62.3 - 0.51X_1 - 0.33X_2 - 0.25X_3$	X_1, X_2, X_3	.596

Table 5.2.2 Regression Equations and R^2 for Two Locations
Using Model I with Hourly Standard Deviation of Speed as the Dependent Variable

<u>Location</u>	<u>Regression Equation</u>	<u>Independent Variables</u>	<u>R^2</u>
Loop 8	$Y = 8.5 - 0.24X_1$	X_1	.143
	$Y = 6.0 + 0.34X_2$	X_2	.279
	$Y = 7.0 + 0.02X_3$	X_3	.029
	$Y = 7.3 - 0.28X_1 + 0.38X_2$	X_1, X_2	.477
	$Y = 8.2 - 0.42X_1 + 0.06X_3$	X_1, X_3	.342
	$Y = 6.2 + 0.75X_2 - 0.09X_3$	X_2, X_3	.483
	$Y = 6.8 - 0.15X_1 + 0.60X_2 - 0.05X_3$	X_1, X_2, X_3	.506
Loop 10	$Y = 5.9 + 0.11X_1$	X_1	.059
	$Y = 6.8 - 0.11X_2$	X_2	.051
	$Y = 6.8 - 0.02X_3$	X_3	.061
	$Y = 6.3 + 0.12X_1 - 0.12X_2$	X_1, X_2	.119
	$Y = 6.1 + 0.22X_1 - 0.04X_3$	X_1, X_3	.228
	$Y = 6.8 - 0.04X_2 - 0.02X_3$	X_2, X_3	.063
	$Y = 5.6 + 0.31X_1 + 0.22X_2 - 0.08X_3$	X_1, X_2, X_3	.278

Figure 5.2.1 Hourly Mean Speed Versus Hourly Volume For Loop 8



Model II is simply the extension of Model I by the addition of three variables. The new variables are: the percent trucks (or vehicles with length greater than 22 feet as obtained from the sensor system) in the traffic stream, a quadratic term involving the X_1 variable, i.e. $X_4 = (X_1 - d)^2$, and the interaction of volume of vehicles in opposite directions (X_3) with X_4 . The quadratic term was added so as to make the model applicable over low hourly volumes (normally occurring at night) and high hourly volumes (daytime). Some preliminary analysis had indicated a need for a "squared" term. $X_4 = (X_1 - d)^2$ is used instead of $X_4 = X_1^2$ to avoid a high correlation between X_1 and X_4 . This approach, along with the formula for estimating the quantity, d , is discussed by Daniel [5].

Hourly speed data obtained from the computer-sensor system at loop 0 were used to evaluate Model II. Specifically, speed, volume and truck information were obtained for the hours ending at 0200, 0500, 0800, ..., 2300 for each day of a one week period (Monday - Sunday), for a total of $8 \times 7 = 56$ observations. The full model (all six variables) accounted for 82% ($R^2 = .820$) of the variation in hourly mean speeds as shown in Table 5.2.3. It is informative to examine models involving subsets of these six variables since some of the variables may not be significant, i.e. some variables may be dropped from the model without a significant loss in information. There are various procedures that may be employed in this type of analysis, such as step-wise regression (forward and backward). We have used the technique developed by Lamotte and Hocking [6] for selecting the "best" subset in regression analysis. This utilizes the "standardized total squared error" concept as the selection criterion which was first suggested by Mallows [7]. In addition to the full six variable model, Table 5.2.3 identifies, and gives the R^2 , for the "best" models of subsets of five variables, four variables, ..., one variable. All possible regression equations were not calculated for each subset size. For example, for subsets of three variables there are a total of $\binom{6}{3} = 20$ regression equations; however, only ten (the "best" ten) were calculated. It is apparent from Table 5.2.3 that a model with only X_1 and X_4 is almost as good a predictor of Y as

Table 5.2.3 R^2 for Selected Subsets of Regressions
Using Model II with Hourly Mean Speed as the Dependent Variables

<u>Subset</u>	<u>Independent Variables</u>						<u>R^2</u>	
Six Variables (Complete Model)	X_1	X_2	X_3	X_4	X_5	X_6	.820	
Five Variables	X_1	X_2	X_3	X_4		X_6	.820	
	X_1	X_2		X_4	X_5	X_6	.819	
	X_1	X_2	X_3	X_4	X_5		.812	
	X_1		X_3	X_4	X_5	X_6	.811	
		X_2	X_3	X_4	X_5	X_6	.808	
	X_1	X_2	X_3		X_5	X_6	.803	
Four Variables	X_1	X_2		X_4		X_6	.819	
	X_1			X_4	X_5	X_6	.811	
	X_1		X_3	X_4		X_6	.811	
	X_1	X_2	X_3	X_4			.808	
		X_2		X_4	X_5	X_6	.800	
	X_1	X_2		X_4	X_5		.800	
	X_1	X_2	X_3		X_5		.800	
			X_3	X_4	X_5	X_6	.799	
	X_1		X_3	X_4	X_5		.795	
	X_1	X_2	X_3			X_6	.786	
	Three Variables	X_1			X_4		X_6	.811
		X_1	X_2		X_4			.795
X_1			X_3	X_4			.792	
X_1				X_4	X_5		.788	
		X_2		X_4		X_6	.780	
				X_4	X_5	X_6	.773	
X_1		X_2	X_3				.768	
X_1			X_3		X_5		.767	
		X_2		X_4	X_5		.762	
			X_3	X_4		X_6	.755	

Table 5.2.3 (Continued)

<u>Subset</u>	<u>Independent Variables</u>						<u>R²</u>
Two Variables	X ₁			X ₄			.786
				X ₄		X ₆	.754
	X ₁					X ₆	.707
	X ₁		X ₃				.706
				X ₄	X ₅		.701
	X ₁	X ₂					.697
		X ₂			X ₅		.692
		X ₂	X ₃				.687
	X ₁				X ₅		.647
					X ₅	X ₆	.598
One Variable	X ₁						.644
					X ₅		.563
			X ₃				.455
		X ₂					.438
				X ₄			.140
						X ₆	.127

the full model with six variables ($R^2 = .786$ as compared to $R^2 = .820$). Note X_1 is the volume of vehicles in the same direction and $X_4 = (S_1 - d)^2$ is the quadratic term discussed previously. Figure 5.2.2 shows the hourly mean speeds at loop 0 versus the hourly volume (same direction). It is evident from this plot that the relationship between speed and volume is nonlinear for the range of values considered.

The variable representing the percentage of trucks (or vehicle lengths greater than 22 feet) does not explain any additional variation in hourly mean speeds over that already accounted for by variables X_1 and X_4 . This could be due to the relatively low percentage of trucks during high volume hours. The high percentage of trucks occurred during low volume hours and represented only a small volume in absolute numbers.

Model II was modified by defining X_2 as the number of trucks (vehicles with lengths greater than 22 feet) rather than percentage and a similar type analysis was conducted. The results were almost identical to those in Table 5.2.3 and are not included in this report. R^2 for the full model was .832.

c) Model III: $\hat{Y} = b_0 + b_1X_1 + \dots + b_{15}X_{15}$

where \hat{Y} = Predicted hourly mean speed (mph)

X_1 = Volume of vehicles per hour with length \leq 22 feet

X_2 = Volume of vehicles per hour with length $>$ 22 feet

X_3 = Volume of vehicles per hour in opposite directions

X_4 = Standard deviation of hourly mean speed

X_5 = Volume of vehicles per hour with headway $<$ 7 seconds

X_6 = Volume of vehicles per hour with headway \geq 30 seconds

X_7 = Day effect - linear

X_8 = Day effect - quadratic

X_9 = Day effect - cubic

X_{10} = Hour effect - linear

X_{11} = Hour effect - quadratic


X_{12} = Hour effect - cubic

X_{13} = Hour effect - quartic

X_{14} = X_8X_{11}

X_{15} = X_8X_{12}

Figure 5.2.2 Hourly Mean Speed Versus Hourly Volume For Loop 0



Model III expresses \hat{Y} (predicted hourly mean speed) as a linear function of fifteen variables which are identified above. The model was formulated in this manner primarily to examine the linear and higher order effects of days within week and similar effects of hours within days. Model III was fitted to the same set of data used for fitting Model II. This was discussed in the preceding section. R^2 for the full fifteen variable model is .809 as shown in Table 5.2.4. Actually, these fifteen variables accounted for slightly less variation in Y than did Model II where R^2 was .820. In addition to the full model, Table 5.2.4 gives the R^2 associated with the "best" models consisting of five variables, four variables, ..., one variable. It is apparent from Table 5.2.4 that there are subsets of four and five variables that do almost as well in explaining variations in Y as the fifteen term regression model. Also, of these four and five variable models, the variables involving day and hour-within-day effects occur so infrequently that one may conclude that these are relatively unimportant variables.

In summary, a series of multiple linear regression models were examined to determine those variables or factors which help to explain hourly changes in mean speeds. Of all the variables studied, volume (same direction) appears to be the most important single factor. Over low and high volume conditions (i.e. nighttime and daytime) it is necessary to include a second degree term involving volume in the model. As evidenced by the results at several locations on Highway 37, mathematical models can be constructed which will account for 60% to 84% of the hourly variation in mean speeds. This wide range probably reflects to some degree road geometry differences which should be included in the model.

Table 5.2.4 R^2 for Selected Subsets of Regressions Using Model III
With Hourly Mean Speed as the Dependent Variable

Subset	Independent Variables															R^2
	X_1	X_2	X_3	X_4	X_5	X_6	X_7	X_8	X_9	X_{10}	X_{11}	X_{12}	X_{13}	X_{14}	X_{15}	
Fifteen Variables (Complete Model)	X_1	X_2	X_3	X_4	X_5	X_6	X_7	X_8	X_9	X_{10}	X_{11}	X_{12}	X_{13}	X_{14}	X_{15}	.809
Five Variables	X_1		X_3	X_4	X_5					X_{10}						.795
	X_1		X_3	X_4	X_5							X_{12}				.793
	X_1		X_3	X_4	X_5									X_{14}		.792
	X_1		X_3	X_4	X_5										X_{15}	.791
	X_1		X_3	X_4	X_5						X_{11}					.790
	X_1		X_3	X_4	X_5				X_9							.789
Four Variables	X_1		X_3	X_4	X_5											.787
	X_1		X_3	X_4						X_{10}						.777
			X_3	X_4	X_5					X_{10}						.762
	X_1		X_3	X_4		X_6										.757
	X_1		X_3	X_4							X_{11}					.746
	X_1		X_3	X_4									X_{12}			.741
Three Variables	X_1			X_4	X_5											.758
	X_1		X_3		X_5											.733
	X_1		X_3	X_4												.730
	X_1				X_5									X_{14}		.716
	X_1			X_4		X_6										.715
	X_1				X_5	X_6										.711
Two Variables	X_1				X_5											.706
	X_1		X_3													.677
	X_1					X_6										.674
	X_1			X_4												.656
	X_1									X_{10}						.624
One Variable			X_3		X_5											.622
	X_1				X_5											.608
				X_3												.494
					X_5											.453
										X_{10}						.332
		X_2														.126
										X_{11}					.109	

5.3 Speed Profiles

Speed profiles are given in this section for the network of state roads included in this study. The profiles are for specified conditions and consist of mean speed and speed variability (standard deviation) plotted by sensor location and/or road segment.

Figure 5.3.1 shows the speed profile for Highway No. 37 (North and South) during the time periods 0-600, 0600-1900, and 1900-2400 hours. These curves are based on one full week of speed data (August 16-27) as obtained from the computer-sensor system. As expected, mean speeds were highest at all sensor sites during the early morning (0-0600 A.M.). Little differences exist between the periods 0600-1900 and 1900-2400. On Highway No. 37 South, the mean speeds increase with distance from Bloomington. This confirms what was anticipated. Highway No. 37 North exhibited higher mean speeds and less differences were noted between sensor sites. It is believed that speeds at Loops 11 and 15 as shown on Figure 5.3.1 are perhaps low, since these loops have shown some erratic behavior throughout the study period. Standard deviations throughout each period of the day and over all sensor sites appeared to be stable. The notable exception was the increase over Highway No. 37 North during the 0-0600 time period. Again, the value for Loops 11 and 15 may not be reliable.

Figures 5.3.2 - 5.3.8 provide speed profiles for all the state roads used in the study. Radar spot speed measurements provided the source data rather than the computer-sensor system. Two profiles were plotted on the same graph so that a visual comparison of the two conditions could be made directly. For example, a comparison of day and night mean speeds on Highway No. 46 East for vehicles traveling East during weekdays on dry roads can be made through a visual inspection of the plots in Figure 5.3.6. Figures 5.3.9 and 5.3.10 show mean speeds for various state roads plotted as a function of the distance (in miles) from Bloomington. The conditions under which these data were collected are shown on the graphs. It is obvious that large differences in mean speed exist over the network of roads included in the study. Figure 5.3.11 shows the posted speed limits over the network of state roads included in the study.

Figure 5.3.1 Speed Profile - Highway No. 37




Figure 5.3.2 Speed Profiles - Highway No. 37 North





Figure 5.3.3 Speed Profiles - Highway No. 37 South





Figure 5.3.4 Speed Profiles - Highway No. 46 East





Figure 5.3.5 Speed Profiles - Highway No. 46 West





Figure 5.3.6 Speed Profiles - Highway No. 45 East





Figure 5.3.7 Speed Profiles - Highway No. 45 West





Figure 5.3.8 Speed Profiles - Highway No. 48 West





Figure 5.3.9 Speed Profiles




Figure 5.3.10 Speed Profiles






Figure 5.3.11 Posted Speeds (mph) Shown In  For Monroe County State Roads



A review of these profiles resulted in the following general observations or conclusions:

- 1) Large differences in mean speeds exist among the various roads included in the study. This was anticipated in view of differences in road geometry, surface, type, width, topography, concentration of population, etc., existing within the road network.
- 2) Mean speeds at night and especially the early morning hours are consistently higher than daytime mean speeds.
- 3) Mean speeds are generally higher for dry roads than for wet roads.
- 4) Mean speeds, for any given condition, tend to increase as the distance from Bloomington increases. The one exception was Highway No. 45 East, where speeds tended to decrease - due to road geometry.
- 5) Speed variability is relatively stable over the entire road network system.
- 6) Speed variability is generally greater, but by only a small amount, during night driving as compared to daytime driving.


5.4 Speed Distributions

Many of the statistical techniques routinely used in the analysis of speed data require some assumption regarding the underlying distribution. More specifically, the assumption of a normal distribution is necessary to validate certain statistical tests applied to the observed or transformed observations. In order to verify the validity of the normality assumption, some sample speed distributions were examined and a statistical test for normality was applied.

Speed distributions on each of the seven state highways coming into Bloomington were examined. The cumulative speed distribution was calculated and then plotted on normal probability paper. The Kolmogorov-Smirnov (K.S.) test was applied to the cumulative distribution function to determine the acceptance or rejection of normality. The results of these analyses are given in [8]. Figure 5.4.1 illustrates the format with which the results are reported. In addition to the plot of the cumulative distribution function (which will plot as a straight line if the distribution is normal), each distribution is identified as to the location where the speed data were recorded, conditions under which the data were recorded, mean speed, standard deviation, sample size, speed limit, and results of the K.S. test.

Nine of the fourteen speed distributions examined were "accepted" by the K.S. test for normality ($\alpha = .01$). One of the remaining five was a borderline case with regard to acceptance or rejection by the K.S. test, and all five involved large sample sizes (ranging from 333 to 971). These results would indicate that the assumption of normality is probably "safe", especially in applying the t- and F-test for testing significance among mean speeds.

Figure 5.4.1 Speed Distribution - Station 203




6. SPEED CHARACTERISTICS AND ACCIDENT DATA

Included in this section are the accident data, speed data collected by radar, and speed data collected by the computer-sensor system. It is necessary to present these data in a reduced form because of the voluminous amount of raw data. For example, the number of actual speed observations collected via radar exceeds 100,000, and the complete file on any one of the 294 accidents investigated would cover several pages. The computer-sensor system continuously monitored the speed, length and headway of each vehicle at sixteen points on Highway No. 37 for more than six months, hence, literally hundreds of thousands of observations were collected. In the event it is necessary to check these raw data, individual speed observations collected by both the radar and loop detectors have been stored on magnetic tape. On an hourly basis, the data generated by the computer-sensor system were summarized for each pair of loop detectors. These hourly summaries are also available on magnetic tape. The complete file on each accident investigated is available from the Institute for Research in Public Safety, Indiana University.

Figure 6.1 shows the network system of state highways in Monroe County, Indiana which are included in this study. Each road has been divided into approximately one-mile segments and given a station number which identifies the location of the segment. The station identification numbers are also shown in Figure 6.1. Within each one-mile segment, a one-tenth mile code is used to further pinpoint on a highway the exact location of some event such as an accident or place where radar spot speeds were observed. For example, if an accident occurred on Highway 37 South about halfway within the segment identified as Station 204, the location of the accident would be identified as 204.5. Both the accident investigation teams and radar operators use this method of identifying the location where data are being collected. The locations of the magnetic loop detectors on Highway No. 37 (North and South) are also shown in Figure 6.1.

The accident investigation teams started operating officially on December 7, 1968. Accident investigation activity was not limited to the network of state

Figure 6.1 State Roads in Monroe County, Indiana Showing Location of Sensor Sites and Road Segment Identification



highways shown in Figure 6.1. Certain portions of Monroe County roads were included in the study (those roads or sections of roads where speeds of 40 mph or greater were anticipated). Accidents on these county roads were also investigated. However, insufficient volume-time data were available to warrant the inclusion of those accidents occurring outside the state road system in the calculation of accident or involvement rates.

In-depth investigation of accidents on all state and selected county roads continued until July 31, 1969. At this time, a decision was made to discontinue accident investigation on all roads except Highway No. 37 (North and South) where speeds were being monitored via magnetic loop detectors. This reduction in effort was used in extending the utilization of the computer-sensor system.

Table 6.1 provides a tabulation of data pertinent to this study for each of the 294 accidents. With the exception of the two columns identified as traffic characteristics, data in Table 6.1 were extracted directly from the accident files.

Traffic characteristics (mean speed and standard deviation) in Table 6.1 are estimates of the characteristics of all traffic at the time and location of the accident. This estimation of traffic flow conditions at the time and location of the accident utilized three sources of information: (1) post-accident speed data, (2) data in the speed survey master file which were collected by radar close to the scene of the accident and under conditions similar to those at the time of the accident, and (3) computer-sensor speed data at the nearest sensor site at the time of the accident.

During the course of the study some general guidelines or procedures for the collection of post-accident speed data were developed. These procedures evolved after reviewing some of the speed characteristics of the roads included in the study. The procedures are necessarily flexible to allow for maximum efficiency of radar operators' time under the constraint of a limited number of man-hours available per week. In general, the guidelines call for the collection of 200 speed readings at the accident site (including both directions of travel). Every effort was made

to obtain speed readings at the accident site under the same conditions as those present at the time of the accident (i.e. time-of-day, day-of-week, and environmental conditions). In order to maintain similar environmental conditions, it became necessary sometimes to vary time-of-day and/or day-of-week.

Within each one-mile segment of the complete network system, 15-minute radar spot speed measurements were made at varying times under varying environmental conditions. The radar spot speed data were collected during the period August 1968 through February 1969. Specifically, these data have been classified according to the following factors and factor levels.

- (1) Day of week - weekday, weekend
- (2) Light condition - day, night
- (3) Weather - dry, wet, ice & snow, fog
- (4) Direction of travel - north, south (or east, west).

These are $2 \times 2 \times 4 \times 2 = 32$ classes or combinations of the above factor levels. For each combination at each station, the mean speed and standard deviation (of individual speed observations) have been calculated. These statistics along with the sample sizes on which they were based are given in Table 6.2. There are many combinations for which speed data are not available. Most of these involve inclement weather conditions. In addition, it is difficult, and in some cases physically impossible, to obtain spot speeds at each station under adverse weather conditions.

As indicated previously, the computer-sensor system continuously monitored the speed, length and headway of each vehicle at sixteen points on Highway No. 37 for more than six months. For two months, twelve additional sites were being monitored. The raw data (individual observations), as collected by the system, have been stored on magnetic tape. In addition, hourly summaries for each sensor site have been prepared and are also available on magnetic tape. Further data reduction was made by combining hourly summaries into daily summaries. Programs have been written to reduce the data even further by generating weekly summaries for each sensor site.

Because of the voluminous amount of data produced by the system even in the reduced form, a complete presentation of the results, either in tabular or graphical form, cannot be given in this report. However, a sample of the results given in the daily summary reports is graphically portrayed in Figure 6.2. Daily mean speeds and standard deviations for 0600-1900 time period are given in Figure 6.2 for Loops 0 and 12 covering a three month period. Loop 0 is the first sensor site South of Bloomington and Loop 12 is the first sensor site North of Bloomington. In both cases the sensors are monitoring outbound traffic. The daily mean speeds at Loop 0 are quite stable at 40 mph, whereas, the mean speeds at Loop 12 are averaging about 55 mph and are more variable. Most likely, some of the variation at Loop 12 can be attributed to equipment performance and calibration adjustments.

Also shown on Figure 6.2 are the daily standard deviations in speed for Loops 0 and 12. As evidenced by the curves, speed variability is stable over time; however, there are consistent differences in speed variability between the two sites. Loop 0 shows a higher but more stable pattern of standard deviation. These standard deviations are inflated by hour-to-hour variation in speeds, hence, the values are somewhat higher than the within-hour speed variability mentioned elsewhere in the report.

Similar type data are available on each of the sixteen sensor sites (0000-0600) and late evening time periods (1900-2400).

TABLE 6.1. ACCIDENT DATA

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
001	304.9	12/7/68	0850	Rain	Day	Single	N.D.	65	V-1	E	N/A	N/A	Unk	Unk	Unk	Unk	M	1	Ramb	Unk	Unk	No	Decreased Visibility
002	305.2	12/7/68	0850	Rain	Day	Single	N.D.	65	V-1	E	N/A	N/A	Unk	Unk	Unk	Unk	M	1	Semi	Unk	Unk	No	Due to 001 off road braking--jackknife
003	305.4	12/7/68	1000	Rain	Day	Head-on	P.D.	65	V-1 V-2	E W	48 47	6.2 6.0	0 30	0 25	0 35	55 51	M M	1 2	Ford Ford	66 65	N.U. N.U.	No No	V-2 lost control Driving left of center
004	108.7	12/7/68	1005	Rain	Day	Single	P.D.	65	V-1	S	55	8.1	45	40	50	19	F	2	Ford	67	N.U.	No	Lost control on ice
005	1900 blk. of Curry Pike 2 mi. w. of city	12/7/68	1625	Clear	Day	Side Coll.	P.D.	30	V-1 V-2	N S	N/A N/A	N/A	50 05	45 03	55 08	22 51	M M	1 1	Pont Int. Dump	64 65	U. N.I.	No No	Speed V-1 V-2 turning
006	209.1	12/8/68	1750	Clear	Nite	Rear End	P.I.	55	V-1 V-2	N N	51 51	5.9 5.9	0 70	0 65	0 75	27 19	M M	2 2	Merc Chev	65 55	N.U. N.U.	No No	V-1 stopped to turn V-2 too fast to stop
007	207.2	12/7/68	1902	Clear	Nite	Rear End	P.I.	55	V-1 V-2	N N	50 50	5.5 5.5	0 35	0 31	0 38	18 72	M M	1 11	Merc Chev	66 55	N.U. N.I.	No No	V-2 faulty brakes V-1 turning
008	507.5	12/11/68	1311	Clear	Day	Head-on	P.I.	35	V-1 V-2	E W	30 29	5.8 6.2	40 30	35 25	45 35	19 19	M F	1 1	Ford Merc	64 60	N.U. U.U.	No No	V-1 driving left of center
009	Tapp & Leonard Springs Road	12/12/68	1300	Clear	Day	Side Coll.	P.D.	20	V-1 V-2	S W	N/A N/A	N/A	05 0	03 0	08 0	38 17	M F	1 1	Chev Trk Olds	68 67	U.U. U.U.	No No	V-1 turned too sharply
010	201.1	12/12/68	2200	Rain	Nite	Side Coll.	P.D.	40	V-1 V-2	E N	40 40	5.1 5.1	0+ 30	0+ 25	0+ 35	46 22	M F	1 2	Chev Chev	65 68	N.U. N.U.	No No	V-1 failed to yield right-of-way
011	204.3	12/14/68	0845	Snow	Day	Rear End	P.D.	55	V-1 V-2	N N	43 43	4.0 4.0	50 08	40 05	50 15	51 30	M F	1 1	Chev Ford	59 66	U.U. U.U.	No No	V-2 turning left V-1 saw no indicator signal, use unknown
012	603.1	12/17/68	2250	Clear	Nite	Single	P.D.	45	V-1	E	45	8.8	70	64	76	19	M	1	Dodge	68	U.U.	No	Speed--lost control on grade descent
013	107.1	12/17/68	1405	Over cast	Day	Side Coll.	P.D.	65	V-1 V-2	N S	55 55	8.0 7.8	70 55	68 50	78 60	46 62	M M	1 1	Olds Fd. Trk.	62 65	N.I. N.I.	Yes No	V-1 lost control excess speed

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
014	205.3	12/22/68	1245	Rain	Day	Single	P.D.	55	V-1	S	44	5.6	65	60	70	34	M	1	Merc	69	N.U.	No	Lost control in pass
015	Vernal Pike at woodyard	12/22/68	2230	Over cast	Nite	Single	P.D.	35	V-1	E	N/A	N/A	40	35	45	20	M	1	Ply	68	U.U.	Yes	Driver falling asleep
016	3420 Leonard Springs Road	12/24/68	0930	Clear	Day	Side Coll.	P.I.	40	V-1 V-2	E S	N/A N/A	N/A	35 02	30 01	35 03	40 50	F M	2 1	Ply Merc	63 60	N.U. N.U.	No Unk	V-2 failed to yield right-of-way
017	446-3696' S.	12/24/68	1600	Clear	Day	Single	P.D.	40	V-1	S	N/A	N/A	70	65	75	35	M	1	Pont	64	U.U.	Yes	Pass at excessive speed, lost control
018	109.8	12/24/68	1956	Clear	Nite	Side-swipe	P.D.	65	V-1 V-2	N S	61 58	7.4 7.7	55 65	53 Unk	60 Unk	53 Unk	M Unk	2 Unk	Ford Unk	59 Unk	N.I. U.U.	No Unk	V-2 driving left of center
019	304.5	12/24/68	2010	Over cast	Nite	Single	P.D.	45	V-1	E	46	6.7	50	45	55	54	M	1	Crys	58	N.I.	Yes	Failure to negotiate curve
020	Leonard Sprgs. & Tapp Road	12/25/68	1500	Clear	Day	Side Coll.	P.D.	20	V-1 V-2	S N	N/A N/A	N/A	05 60	03 54	10 60	18 30	M M	2 3	Ford Chev	58 62	N.I. N.I.	No No	V-1 did not see speeding V-2
021	Leonard Sprgs. 111' S. of Farington Dr.	12/26/68	1130	Freezing Rain	Day	Single	P.D.	20	V-1	S	N/A	N/A	25	25	35	58	M	1	Ramb	66	U.U.	No	Lost control on ice when brakes applied
022	107.6	12/26/68	1212	Snow Rain	Day	Single	P.I.	65	V-1	S	57	7.6	45	42	47	46	F	1	Ply	62	N.U.	No	Lost control on ice
023	208.1	12/28/68	2345	Clear	Nite	Single	P.D.	55	V-1	N	48	6.7	45	40	55	26	M	1	FdTk	67	U.U.	Yes	Lost control
024	603.4	12/29/68	0920	Clear	Day	Side Coll.	P.D.	45	V-1 V-2	E W	42 46	6.3 6.1	08 55	05 40	12 60	24 57	F M	1 1	Buick Chev	68 68	U.U. U.U.	No No	Failure V-2 to observe V-1
025	202.3	12/30/68	1423	Clear	Day	Rear End	P.D.	40	V-1 V-2	N N	42 42	5.1 5.1	10 35	05 35	15 40	30 46	F M	2 1	Ford Olds	65 67	N.U. N.U.	No No	Failure V-2 to observe V-1
026	104.2	12/30/68	1530	Sleet	Day	Single	P.D.	65	V-1	N	38	5.7	65	60	70	29	M	1	Ramb	67	U.	No	Slippery Road
027	102.4	12/30/68	1635	Rain Snow	Day	Single	P.D.	65	V-1	N	49	6.7	60	55	65	24	M	1	V.W.	68	U.	No	Slippery Road

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
028	Delap Rd. 1 1/4 mi W. of Union Valley	12/30/68	1955	Rain	Nite	Single	P.I.	not post- ed	V-1	E	N/A	N/A	30	25	35	29	F	1	Chev	59	N.U.	No	Slippery Road
029	404.7	12/31/68	1800	Clear	Nite	Forced Off Road	P.D.	50	V-1 V-2	W W	47 47	4.3 4.3	55 15	45 15	58 15	24 Unk	M Unk	2 Unk	Ford Unk	65 Unk	N.U. Unk	No Unk	V-2 signaled right then turned left
030	Old 37, .35 m. N. of Bethel L	1/1/69	0220	Clear	Nite	Single	P.I.	40	V-1	NE	N/A	N/A	85	80	100	19	M	1	Buick	63	N.I.	Yes	Excessive speed
031	202.3	1/1/69	2029	Over cast	Nite	Single	P.I.	45	V-1	S	43	5.0	70	65	75	24	M	1	Olds	57	N.I.	No	Lost control, speeding
032	S. Rogers & Hays Drive	1/6/69	1530	Clear	Dusk	Single	P.D.	Not Post- ed	V-1	S	N/A	N/A	60	56	65	16	F	1	Chev	69	N.U.	No	Lost control due to rise in roadway
033	102.5	1/5/69	1720	Over cast	Dusk	Rear End Multiple	P.D.	65	V-1 V-2 V-3 V-4 V-5	S S S S S	54 54 54 54 54	6.8 6.8 6.8 6.8 6.8	N/A 18 45 33 45	N/A 15 43 30 43	N/A 20 47 35 47	20 21 30 20 18	F M M M M	1 1 1 1 1	Olds Chev Chev Buick Olds	67 66 63 69 63	U.U. U.U. U.U. U.U. U.U.	No No No No No	V-1 slowing down for turning vehicle; other vehicles following too close
034	102.7	1/5/69	1725	Over cast	Dusk	Rear End Multiple	P.D.	65	V-1 V-2 V-3 V-4	S S S S	54 54 54 54	6.8 6.8 6.8 6.8	N/A N/A 40 50	N/A N/A 38 45	N/A N/A 42 53	19 18 18 54	M F F M	1 1 1 1	Chev Ford Ply Cadi	68 67 66 67	U.U. U.U. U.U. U.U.	No No No No	Acc#033-caused V-1 & V-2 to stop V-3 & V-4 following too close
035	104.1	1/5/69	1756	Over cast	Nite	Rear End	P.D.	65	V-1 V-2	S S	56 56	6.7 6.7	0 35	0 30	0 37	20 17	F M	1 2	Ford Chev	59 63	U.U. N.U.	No No	Faulty brakes V-2
036	105.1	1/5/69	1810	Clear	Nite	Rear End	P.D.	65	V-1 V-2 V-3	S S S	56 56 56	6.7 6.7 6.7	0 20 35	0 15 30	0 30 45	20 20 21	M F M	1 4 3	Chev Chev Ford	64 64 69	U.U. U.U. U.U.	No No No	Following too close
037	5700 block of S. Rogers	1/5/69	2115	Clear	Nite	Single	P.D.	30	V-1	N	N/A	N/A	80	75	85	19	M	1	Chev	63	N.U.	No	Speed

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification			Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
												Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
038	101.5	1/6/69	0929	Snow	Day	Side Coll.	P.I.	50	V-1 V-2	S N	45 47	6.6 7.7	40 40	35 45	44 60	F F	1	Ford Chev	47 61	U.U. U.U.	No No	Snow surface--V-2 lost control		
039	102.6	1/6/69	0945	Snow	Day	Single	P.D.	65	V-1	S	49	6.7	45	40	50	27	F	1	Chev	66	U.	No	Lost control slick surface	
040	609.8	1/6/69	1026	Snow	Day	Single	P.I.	65	V-1	W	44	4.9	45	40	47	20	F	1	Volvo	67	U.	No	Lost control passing on slick surface	
041	Handy Ridge Rd .7 m S.Moffet	1/6/69	1519	Snow	Day	Head-on	P.D.	30	V-1 V-2	E W	N/A N/A	N/A N/A	15 15	12 10	17 20	39 26	M F	1 1	Ford P/U Chev	65 58	N.U. N.I.	No No	Slick surface	
042	2729 S.Rogers	1/6/69	1616	Clear	Day	Rear End	P.D.	30	V-1 V-2	N N	N/A N/A	N/A N/A	05 25	03 20	07 27	23 25	F M	1 1	Chev Pont	64 66	N.I. N.U.	No No	Slick surface	
043	504.8	1/7/69	0900	Clear	Day	Single	P.D.	45	V-1	E	35	5.4	45	40	47	41	M	1	Ford	66	U.U.	No	Faulty brakes	
044	Hart Straight Rd. .1 m SE of 46W	1/8/69	0320	Clear	Nite	Single	P.D.	30	V-1	NW	N/A	N/A	30	25	35	18	M	1	Pont	67	N.U.	No	Lost control	
045	103.1	1/8/69	1600	Rain	Dusk	Off Road	P.D.	65	V-1 V-2	N S	41 41	6.9 6.9	55 57	55 55	60 60	20 28	M M	1 1	Opel Chev P/U	68 68	U.U. U.	No No	V-1 pulled out in front of V-2	
046	401.3	1/12/69	1800	Clear	Dusk	Rear End	P.I.	40	V-1 V-2	W W	42 42	7.6 7.6	45 0	40 0	50 0	23 26	F M	1 2	Buick Chev	62 68	U.U. N.U.	No No	V-2 stopped for turn	
047	406.1	1/9/69	0918	Clear	Day	Side Coll.	Fatal	40	V-1 V-2	E N	* *	*	40 35	35 30	42 40	51 62	M M	1 2	Ford Locomotive	65	N.I.	No	V-1 thru crossing (no gates) against signal (sun in eyes?)	
048	701.1	1/10/69	1612	Clear	Day	Rear End	P.D.	45	V-1 V-2	E E	40 40	5.0 5.0	35 35	33 33	38 40	22 38	M M	1 1	Dodge Ford	67 64	U.U. U.U.	No No	V-2 following too close	

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Conditions	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.	
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		No.	Make				Year
049	Moores Pike 1/2 mi. W. of Smith Road	1/8/69	1830	Clear	Dusk	Rear End	P.D.	35	V-1	E	N/A	N/A	0	0	0	20	M	2	Pont	67	N.U.	No	Illegally parked V-1 projecting on roadway V-2 struck V-1	
									V-2	E			20	20	30	17	M	1	Ramb	62	N.I.	No		
									V-3	E			Unk	Unk	Unk	Unk	Unk	Unk	Unk	Unk	Unk	Unk		Unk
050	2314 N. Walnut	1/10/69	1802	Clear	Nite	Rear End & Head-on	P.I.	40	V-1	S	N/A	N/A	30	35	25	16	F	1	Ford	65	U.U.	No	V-2 stopped; V-1 not aware of condition	
									V-2	N			0	0	0	31	M	1	Ford	66	U.U.	No		
									V-3	N			30	35	25	22	F	1	Olds	67	U.U.	No		
051	Moores Pike 520' W. Smith Road	1/10/69	1851	Clear	Nite	Head-on	P.I.	40	V-1	E	N/A	N/A	35	30	40	28	F	1	Chev	64	U.U.	No	Ice on roadway; V-1 lost control	
									V-2	W			30	27	35	49	M	1	Int. Scout	65	U.U.	No		
052	Bethel Lane 4000' S. of Hinnle Road	1/10/69	1945	Clear	Nite	Single	P.D.	40	V-1	E	N/A	N/A	35	25	40	17	M	1	Dodge	66	N.U.	No	Lost control	
053	304.9	1/12/69	0115	Clear	Nite	Rear End	P.D.	45	V-1	W	47	7.7	20	Unk	Unk	17	M	1	Chev	57	U.U.	Unk	V-1 too slow	
									V-2	W	47	7.7	45	Unk	Unk	19	M	1	Ford	69	U.U.	Unk		
054	404.3	1/14/69	1510	Clear	Day	Single	P.D.	50	V-1	E	43	6.1	50	Unk	Unk	44	M	1	Buick	67	U.U.	Unk	Lost consciousness	
055	704.9	1/14/69	2250	Clear	Nite	Single	P.I.	50	V-1	W	46	7.7	75	60	85	21	F	2	Chev	64	N.I.	Yes	Lost control on curve	
056	409.9	1/15/69	0654	Over cast	Nite	Single	P.I.	65	V-1	E	52	8.0	60	55	65	20	M	5	Nash	60	N.I.	No	Mech. (steering)	
057	306.5' E. of SR275 on SR46 By-pass	1/15/69	2055	Clear	Nite	Rear End	P.I.	45	V-1	E	N/A	N/A	0	0	0	48	M	1	Olds	64	U.U.	No	Intoxication V-2	
									V-2	E			35	30	40	27	M	1	Ply	68	U.U.	Yes		
058	603.5	1/16/69	0710	Over cast	Day	Side Coll.	P.I.	45	V-1	E	37	6.0	07	05	09	62	M	1	Ford Trk.	68	U.U.	No	V-1 did not observe V-2	
									V-2	E	37	6.0	20	18	25	40	M	1	Olds	62	U.U.	No		
059	403.9	1/16/69	1600	Rain	Day	Rear End Multiple	P.I.	50	V-1	E	46	5.3	N/A	N/A	N/A	22	F	2	Chev	65	N.U.	No	Rain decreased visibility vehicle travel too fast for conditions	
									V-2	E	46	5.3	N/A	N/A	N/A	27	F	1	Ford	66	U.	No		
									V-3	E	46	5.3	13	10	15	55	F	1	Chev	66	N.U.	No		
									V-4	E	46	5.3	42	40	47	18	M	1	Chev	65	N.U.	No		

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification		Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
									V-1	V-2		Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
060	Airport Rd. 632.4' W. of Kirby Road	1/17/69	2106	Rain	Nite	Rear End	P.D.	30	V-1	W	N/A	N/A	27	25	30	29	F	1	Buick	66	U.U.	No	Wet, slippery pavement V-2 skid into V-1	
									V-2	W			27	25	30	25	M	2	Opel	68	U.U.	No		
061	Moores Pike .2 mi. E. of Smith Road	1/18/69	2340	Over cast	Nite	Single	P.D.	30	V-1	E	N/A	N/A	60	55	65	17	M	3	Merc	65	N.U.	No	Lost control in avoiding slower car	
062	507.2	1/20/69	0724	Icing	Nite	Single	P.D.	30	V-1	W	32	7.3	45	35	45	29	M	1	Merc	68	N.U.	No	Lost control on ice patch	
063	401.5	1/21/69	1545	Wet	Day	Rear End	P.D.	40	V-1	S	**	**	05	03	07	33	M	2	Mac Trk.	65	U.U.	No	Failure to watch when backing	
									V-2	N	**	**	05	05	10	19	F	1	Ford	66	N.U.	No		
064	603.5	1/22/69	0715	Rain Fog	Nite	Rear End	P.D.	40	V-1	E	42	5.3	0	0	0	26	M	1	Pont	65	N.U.	No	V-2 following too close	
									V-2	E	42	5.3	40	35	45	44	M	1	Ford	67	N.U.	No		
065	102.1	1/23/69	1909	Rain	Nite	Rear End	P.D.	65	V-1	N	52	7.4	0	0	0	27	M	1	Chev Trk.	68	N.U.	No	V-1 & V-2 (wrecker w/car) stopped--V-3 obscured vision	
									V-2	N	N/A	N/A	0	0	0	(being towed)	Chev	67	N.U.	No				
									V-3	N	52	7.4	45	40	50	19	M	2	Chev	65	U.U.	No		
066	401.3	1/23/69	1925	Rain Fog	Nite	Single	P.D.	40	V-1	W	36	4.5	20	20	25	Unk	F	1	Pont	64	U.	No	Heavy rain & fog--unfami- liarity w/road	
067	408.4	1/23/69	2216	Rain Fog	Nite	Single	P.I.	65	V-1	W	45	6.7	55	50	60	35	M	1	V.W.	68	U.U.	No	Lost control on flooded roadway	
068	401.3	1/25/69	0746	Clear	Day	Single	P.D.	50	V-1	W	43	6.2	55	50	60	33	M	1	V.W.	64	U.U.	Unk	Lost control on curve	
069	401.3	1/25/69	1618	Clear	Day	Head-on	P.I.	40	V-1	E	44	4.7	40	38	45	50	M	1	Chev Trk.	60	U.U.	No	Sun blinded V-2	
									V-2	W	43	5.6	08	05	10	23	M	2	V.W.	68	U.U.	No		
070	201.4	1/25/69	1802	Clear	Nite	Head-on	P.D.	45	V-1	S	41	4.9	40	35	45	44	M	1	Ford Trk.	64	U.U.	No	V-2 left of center	
									V-2	N	43	5.6	20	18	25	26	M	1	Buick	63	U.U.	Yes		

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
071	109.7	12/24/69	1956	Clear	Nite	Rear End	P.I.	65	V-1	S	58	7.5	25	25	25	48	M	1	Diam.	68	N.I.	No	V-2 eyes off traffic rear ended slow V-1 climbing grade
									V-2	S	58	7.5	65	63	67	19	M	2	T.Trk. Ford	64	N.I.	No	
072	INSUFFICIENT DATA																						
073	609.8	1/30/69	0717	Rain	Dawn	Single	P.I.	65	V-1	E	48	6.1	68	65	70	40	F	1	Chev	67	N.U.	No	Excessive speed for conditions
074	609.9	2/1/69	0231	Rain	Nite	Single	P.D.	50	V-1	W	48	10.5	35	25	40	32	M	2	Int P/U	Unk	N.I.	Unk	Driver blinded by headlights
075	209.5	2/1/69	1622	Over cast	Day	Single	P.I.	55	V-1	S	52	3.8	55	50	60	46	M	1	Dodge	65	N.U.	No	Forced off road at lane change 1-2
076	306.0	2/2/69	0023	Icing	Nite	Single	P.I.	65	V-1	E	42	4.4	65	60	70	20	M	2	Ramb	63	U.U.	No	Lost control due to ice on roadway
077	603.7	2/3/69	0700	Clear	Day	Rear End	P.D.	45	V-1	W	46	7.2	0	0	0	17	F	1	Buick	65	U.U.	Unk	V-1 illegally parked protruding into roadway
									V-2	W	46	7.2	25	30	35	34	M	1	Ford	68	U.	Unk	
									V-3	W	46	7.2	35	35	40	20	M	1	Merc	61	N.U.	Unk	
078	601.2	2/3/69	0822	Clear	Day	Head-on	P.D.	45	V-1	E	36	5.7	30	30	40	25	M	1	Chev	66	N.U.	Unk	Soft shoulder--wheel off--lost control
									V-2	W	40	7.0	40	40	50	66	F	1	V.W.	64	N.U.	No	
079	1000' N. of Woodyrd on Smith Pike	2/3/69	0944	Ice	Day	Single	P.I.	35	V-1	N	N/A	N/A	40	30	45	17	M	1	Chev	59	N.U.	No	Ice on roadway
080	107.7	2/5/69	0716	Clear	Dawn	Rear End	P.I.	65	V-1	N	54	7.1	0	0	0	28	F	3	Ford	67	N.U.	No	V-1 stopped for school bus V-2 rear ended V-1
									V-2	N	54	7.1	55	53	58	69	M	4	Chev	69	N.U.	No	
081	405.6	2/5/69	1545	Clear	Day	Rear End	P.D.	50	V-1	E	45	7.4	0	0	0	53	F	1	Cadi	63	N.I.	No	V-1 stopped to turn
									V-2	E	45	7.4	50	45	56	49	F	1	Chev	65	N.U.	No	
082	446 (.5 mi S. of Moores Pke)	2/8/69	1745	Mist	Dusk	Single	P.I.	40	V-1	W	N/A	N/A	40	35	45	21	F	1	Ramb	58	N.U.	No	Too fast for curve
083	INSUFFICIENT DATA																						

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
084	203.9	2/8/69	2100	Snow	Nite	Side Coll.	P.I.	45	V-1	S	40	5.1	05	03	07	19	M	1	Ford	66	N.U.	No	V-1 turned in front of V-2
									V-2	N	40	5.7	25	20	30	18	M	3	V.W.	52	N.I.	No	
085	502.6	2/8/69	2122	Ice	Nite	Single	P.D.	45	V-1	E	33	4.4	35	33	38	37	F	1	Chev	57	U.U.	No	Icy road surface
086	202.9	2/10/69	1859	Clear	Nite	Side Coll.	P.D.	45	V-1	N	47	6.8	50	30	50	40	F	2	Olds	63	N.U.	No	V-2 not yielding right of way
									V-2	W	47	6.8	0 ⁺	0 ⁺	0 ⁺	26	M	2	Ford Trk.	50	N.I.	Unk	
087	205.2	2/10/69	1840	Over cast	Nite	Rear End	P.D.	55	V-1	S	48	6.9	50	48	52	20	F	1	Chev	63	U.U.	No	V-2 following too closely
									V-2	S	48	6.9	50	48	52	25	M	1	Int. Trk.	68	U.U.	No	
088	204.0	2/11/69	1514	Clear	Day	Rear End	P.D.	55	V-1	N	45	7.0	50	46	53	49	M	1	Ford	67	N.U.	No	V-2 following too closely
									V-2	N	45	7.0	50	47	54	73	M	1	Chev	64	N.U.	Unk	
089	506.1	2/11/69	2034	Over cast	Nite	Single	P.D.	45	V-1	E	38	7.3	50	48	54	19	M	1	V.W.	59	N.I.	No	Lost control due to speed and vehicle leaving road
090	701.2	2/13/69	0931	Clear	Day	Single	P.I.	45	V-1	E	42	5.9	45	42	48	22	M	1	Chev Dump	64	N.U.	No	Mech--Brakes failed
091	602.2	2/14/69	0736	Clear	Day	Side Coll.	P.I.	45	V-1	W	42	6.5	40	35	45	21	F	1	Ply	64	U.U.	No	V-2 not seeing V-1
									V-2	S	42	6.5	0 ⁺	0 ⁺	0 ⁺	25	M	2	Ford	69	U.U.	No	
092	Old 37 @ No. Dunn	2/14/69	1525	Clear	Day	Single	P.I.	30	V-1	E	N/A	N/A	35	30	40	28	M	1	Ford	62	U.U.	Yes	Lost control
093	S. Rogers at Monon Trks	2/15/69	1203	Clear	Day	Single	P.D.	30	V-1	S	N/A	N/A	30	25	35	72	M	1	Chev Trk.	64	N.I.	No	Wheel off road; lost control
094	S. Rogers & Country Club	2/18/69	1605	Clear	Day	Side Coll.	P.I.	30	V-1	N	N/A	N/A	30	27	35	17	M	1	Chev Trk.	50	N.I.	No	V-2 failed to yield right of way
									V-2	E			08	06	10	36	M	2	Ply	65	N.U.	No	
095	501.1	2/20/69	0823	Clear	Day	Side Coll.	P.D.	45	V-1	S	39	5.5	0 ⁺	0 ⁺	0 ⁺	48	F	1	Chev	68	U.	No	Failure V-2 to yield
									V-2	E	39	5.5	05	05	08	22	M	1	Ply	65	U.U.	No	

TABLE 8.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification		Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.	
									V-1	V-2	Direction	Mean Speed	Std. Dev.	Est.	Min.	Max.	Age		Sex	Make				Year
096	S. Rogers & That Rd.	2/20/69	1520	Clear	Day	Side Coll.	P.D.	35	V-1	N	N/A	N/A	30	25	30	52	M	1	Chev	65	N.U.	No	Improper turn by V-2	
									V-2	E			0	0	0	66	M	1	Chev	64	N.U.	No		
097	208.1	2/20/69	1625	Clear	Day	Rear End	P.I.	55	V-1	S	49	5.7	10	05	15	42	F	2	Ford	66	U.U.	No	V-1 attempting improper right pass on Berm	
									V-2	S	49	5.7	55	55	60	42	F	3	Ford	69	N.U.	No		
098	603.2	2/20/69	1630	Clear	Day	Side Coll.	P.D.	45	V-1	E	36	6.4	40	38	43	72	F	2	Cadi	68	N.U.	No	V-1 sun blinded	
									V-2	N	36	6.4	0†	0†	0†	32	F	1	Olds	60	N.U.	No		
099	Rockport at Graham Drug	2/22/69	0230	Clear	Nite	Single	P.I.	30	V-1	N	N/A	N/A	30	25	35	17	F	1	Stude	61	N.U.	No	Mech (power steering failed)	
100	105.7	2/22/69	2000	Rain	Nite	Side Coll.	P.D.	65	V-1	S	50	7.8	50	45	55	25	M	1	Chev	69	U.U.	No	V-2 left of center	
									V-2	N	49	4.8	65	65	70	21	M	1	V.W.	62	U.U.	No		
101	46 bypass at 10th Street	2/23/69	1346	Clear	Day	Single	P.D.	45	V-1	S	N/A	N/A	30	30	35	34	F	1	Pont	65	U.	No	Mech. (Brakes)	
102	203.9	2/23/69	1500	Clear	Day	Side Coll.	P.I.	45	V-1	E	42	5.0	0†	0†	0†	47	M	1	Pont	66	N.U.	No	V-1 not yielding intersection right of way	
									V-2	S	42	5.0	15	10	18	50	M	1	V.W.	62	N.U.	No		
103	108.2	2/25/69	1756	Overcast	Day	Rear End	P.D.	65	V-1	N	54	7.4	0	0	0	52	M	1	Chev	69	U.U.	No	V-2 following too close	
									V-2	N	54	7.4	45	43	48	18	M	1	Chev	65	U.U.	No		
104	Moores Pike 145'E of Valley Forge	2/26/69	0940	Clear	Nite	Side Swipe	P.I.	20	V-1	E	N/A	N/A	40	35	45	44	M	1	Ford	65	U.U.	Unk	V-1 & V-2 left of center	
									V-2	W			60	55	65	25	M	1	Ford	67	U.U.	Unk		
105	INSUFFICIENT DATA																							
106	110.6	2/27/69	1800	Clear	Dusk	Side Coll. Head-on	P.I.	65	V-1	N	57	6.3	70	65	75	44	M	1	Podge	66	U.U.	No	V-2 improper pass of V-3, V-1 speed	
									V-2	S	58	6.0	65	60	70	18	M	2	Ford	63	N.I.	No		
									V-3	S	58	6.0	60	55	65	36	M	1	Chev Trk	64	N.U.	No		

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
107	105.3	3/1/69	1240	Clear	Day	Rear End	P.D.	65	V-1 V-2	N N	49 49	6.9 6.9	15 10	10 5	20 15	31 19	M M	2 4	Olds Buick	62 63	UU NI	No No	V-1 attempting pass, pulled back into lane too soon.
108	504.1	3/4/69	2250	Clear	Nite	Single	P.D.	45	V-1	E	33	7.0	45	40	50	40	M	1	Chev	66	UU	Yes	Wheel off road - lost control
109	No Police Report																						
110	Harrodsburg Rd -Strain Ridge Rd.	3/5/69	1835	Clear	Dusk	Single	P.I.	30	V-1	N	N/A	N/A	30	25	30	20	F	1	Merc	64	NU	No	Lost control
111	No Police Report																						
112	604.5	3/6/69	1733	Clear	Day	Rear End	P.I.	50	V-1 V-2	W W	42 42	6.9 6.9	35 65	25 60	40 70	17 28	F M	3 1	Merc Mack	61 62	NI NI	No No	V-1 slowed; V-2 could not
113	303.1	3/7/69	1455	Clear	Day	Side	P.D.	45	V-1 V-2	W E	44 44	4.7 5.1	30 0	25 0	35 0	22 31	M M	1 1	M.G. Dodge	65 48	UU NI	No Yes	V-2 turned in front of V-1
114	201.9	3/7/69	1720	Clear	Day	Rear End	P.D.	45	V-1 V-2	S S	39 39	3.8 3.8	60 05	50 03	65 07	17 36	M F	1 1	Olds Ford	63 66	NI U	Yes No	V-2 slowing & making left turn; V-1 struck V-2 on right rear
115	Shuffle Gr. Rd 2000's South Shore Dr.	3/7/69	1900	Clear	Nite	Single	P.D.	30	V-1	N	N/A	N/A	65	60	70	49	M	1	Olds	69	UU	Yes	Lost control due to on-coming vehicle on his side of road
116	101.9	3/8/69	1245	Over cast Wet	Day	Rear End Side	P.I.	50	V-1 V-2 V-3	S W E	46 46 46	8.7 8.7 8.7	45 0 ⁺ 0 ⁺	40 0 ⁺ 0 ⁺	50 0 ⁺ 0 ⁺	30 27 33	M M F	7 3 1	MCI Bus Chev Tr. Dodge	68 68 68	UU UU U	No No No	V-2 turning; V-1 unable to stop; V-2 knocked in front of V-3

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification			Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
									V-1	V-2	V-3	Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
117	46 By-pass 20' South of SR 45	3/8/69	1550	Wet	Day	Rear End	P.I.	30	V-1	S										Chev	68	U	No	V-1 unable to stop.
									V-2	S	N/A	N/A	0	0	0	31	M	4	Ford	68	N.U.	No		
									V-3	S			5	0	5	20	F	2	Ford	68	U.U.	No		
118	405.6	3/20/69	0750	Wet	Day	Rear End Side	P.I.	50	V-1	S	47	6.1	0+	0+	0+	22	F	1	Chev	63	N.U.	No	V-1 on priv. dr., brakes failed; struck by V-2, impact forced V-1 into V-3.	
									V-2	W	47	6.1	25	20	40	22	M	1	Chev	68	N.U.	Unk		
									V-3	E	50	5.7	0	0	0	33	M	1	IntTk	58	N.I.	Unk		
119	110.9	3/8/69	2210	Rain Fog	Nite	Side	P.I.	65	V-1	N	54	6.5	50	45	55	17	M	2	VW	67	N.U.	Unk	V-2 turned in front of V-1.	
									V-2	S	50	8.7	10	7	12	56	M	3	Chev	62	N.U.	Unk		
120	Old 37 N. 52' South of Chambers	3/5/69	0810	Clear	Day	Single	P.D.	45	V-1	N	N/A	N/A	40	30	45	63	M	1	Nash	58	N.I.	No	Vehicle 1 left road in order to miss Vehicle X.	
121	Insufficient Data																							
122	306.5	3/16/69	0100	Clear	Nite	Side	P.I.	65	V-1	W	47	6.6	55	50	60	19	M	1	TR-3	60	N.U.	Yes	Vehicle 1 lost control. Bump on road.	
									V-2	E	50	7.0	45	45	50	18	M	5	Ramb	64	N.U.	No		

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification			Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.	
									V-1	V-2	V-3	Direction	Mean Speed	Std. Dev.	Est.	Min.	Max.	Age		Sex	Make				Year
123	106.3	3/16/69	1450	Clear	Day	Rear End	P.I.	65	V-1	N	43	9.5	0	0	0	19	M	2	Pont	65	U	No	Improper passing by V-2		
									V-2	N	43	9.5	55	50	60	28	M	4	Ford P.U.	62	N.I.	No			
124	102.5	3/20/69	0930	Clear	Day	Head-on Side	P.I.	65	V-1	S	56	5.0	65	55	70	21	M	1	Pont	66	Unk	No	Failure to yield right of way by V-2		
									V-2	N	55	6.2	15	10	20	21	M	1	Chev	66	N.U.	Yes			
									V-3	S	56	5.0	55	50	60	25	M	1	Semi	66	U.U.	Unk			
125	Rockport Road 3000' South of Country Club Road	3/21/69	1605	Clear	Day Dust Observed Complete	Head-on	P.D.	30	V-1	S	N/A	N/A	15	10	20	18	M	2	Olds	64	N.U.	No	100% obscured vision by lime dust.		
									V-2	N			15	10	20	34	M	2	Dodge	51	N.I.	No			
126	No Police Report																								
127	SR 446 1 1/3 South of SR 46	3/22/69	0111	Over Cast	Nite	Single	P.I.	40	V-1	E	N/A	N/A	50	45	55	19	M	2	Chev	62	N.U.	No	Lost control in middle of curve when tried to avoid left of center - oncoming vehicle		
128	Vernal Pike 3500' West of Curry Pike	3/23/69	0120	Clear	Nite	Single	P.I.	65	V-1	N	N/A	N/A	55	50	60	18	M	2	Ford	67	U	No	Too fast in curve		
129	College Mall & Rd. & Corenanter Drive	3/24/69	1925	Rain	Nite	Fatal Side swipe	F	65	V-1	N	N/A	N/A	40	35	45	16	M	1	Chev	63	U.U.	No	Pedestrian changing tire on roadway		
130	702.5	3/26/69	1630	Over cast	Day	Rear End	P.D.	45	V-1	W	37	4.3	0	0	0	37	M	2	Cry	66	N.U.	No	V-1 turning right, V-2 ran into rear		
									V-2	W	37	4.3	40	38	42	37	M	1	Ford	62	N.I.	No			
131	103.8	3/28/69	1235	Clear	Day	Multi-Rear End	P.I.	65	V-1	N	45	8.8	0	0	0	45	F	6	Ramb	66	N.U.	No	V-1 stopped W/O sig. V-2 rear-ended V-1; V-3 rear-ended V-2		
									V-2	N	45	8.8	45	42	48	22	M	1	Ford	68	U	No			
									V-3	N	45	8.8	45	42	48	22	M	5	Chev	67	N.U.	No			

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
132	108.2	3/29/69	0255	Light Rain	Nite	Side	P.I.	65	V-1 V-2	S N	59 56	5.8 6.5	55 10	50 8	65 13	44 32	F M	1 1	VW Chev	66 65	N.U. N.U.	Unk Unk	V-2 turned in front of V-1
133	101.9	3/29/69	1958	Clear	Nite	Side	P.I.	55	V-1 V-2	W S	52 52	7.4 7.4	0† 55	0† 50	0† 60	21 16	M M	2 1	Olds Ford	69 65	N.U. U.U.	No No	V-1 turned in front of V-2
134	506.1	4/4/69	1405	Over cast	Day	Head-on	P.I.	45	V-1 V-2	E W	37 36	6.1 5.5	35 25	30 20	40 30	17 21	M M	1 2	Ford P.U. Motor cycle Triumph	65 68	U.U. N.I.	No No	V-1 crested hill left of center
135	405.6	4/4/69	1730	Rain	Day	Rear End	P.I.	50	V-1 V-2	W W	42 42	4.6 4.0	0 45	0 40	0 50	21 16	F F	2 1	Chev P.U. Buick	65 64	N.I. N.I.	No No	V-1 stopped to make turn; V-2 rear-ended
136	SR 446, 2640' North of Knight Ridge Road	4/6/69	0130	Clear	Nite	Single	P.I.	40	V-1	S	N/A	N/A	40	35	45	19	M	2	Ford	63	N.I.	No	V-1 states that mule ran onto road in front of him. V-1 struck mule
137	102.6	4/6/69	1740	Clear	Day	Rear End	P.D.	65	V-1 V-2 V-3	S S S	56 56 56	4.4 4.4 4.4	N/A 0 35	N/A 0 30	N/A 0 40	21 22 19	M M M	2 3 3	Olds Chev Chry	66 69 66	U N.U. N.U.	No No No	V-1 & V-2 stopped; V-3 following too close - didn't stop
138	109.3	4/6/69	2330	Clear	Nite	Head-on	F	65	V-1 V-2	N S	58 57	5.4 5.6	55 65	50 55	60 70	26 24	M M	1 2	White Tk. Ford	69 62	U.U. N.I.	No No	V-2 forced off road by V-X; then lost control & hit V-1.
139	609.8	4/8/69	2030	Over cast	Nite	Side-swiped	P.I.	65	V-1 V-2	W W	50 50	8.7 8.4	25 60	20 57	30 65	16 24	F M	1 1	Chev Chev	68 67	U.U. U.U.	No No	V-1 slowing & making left turn; V-2 passed & struck V-1
140	409.3	4/9/69	1215	Over cast	Day	Rear End	P.D.	40	V-1 V-2	E E	47 47	6.1 6.1	0 30	0 28	0 33	75 23	M M	1 2	Ford Pont	69 68	N.U. U	No No	V-2 following too close

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
141	705.1	4/10/69	1420	Clear	Day	Single	P.I.	55	V-1	E	47	8.5	60	55	65	22	M	1	Buick	61	N.U.	No	Ran off road; lost control
142	405.9	4/11/69	0122	Fog	Nite	Single	P.I.	40	V-1	W	37	7.1	60	55	65	32	M	1	Pont	69	N.U.	Yes	Fell asleep
143	446 at 1846' South of Moores Pike	4/14/69	1955	Rain	Nite	Single	P.I.	40	V-1	N	N/A	N/A	45	40	48	27	M	2	Chry	60	N.I.	Yes	Lost control on wet curve
144	Country Club at Monon R.R.	4/17/69	1217	Clear	Day	Single	P.I.	30	V-1	E	N/A	N/A	30	25	35	18	M	1	Yama-ha	65	N.I.	No	Lost control on R.R. tracks
145	402.5	4/18/69	2345	Over cast	Nite	Side	P.D.	40	V-1 V-2	E S	43 43	6.7 6.7	45 0+	40 0+	50 0+	22 18	M M	1 1	Chev Buick	69 66	U.U. U.U.	Yes No	V-2 backed onto road; V-1 could not stop
146	508.1	4/19/69	0307	Rain	Nite	Single	P.I.	45	V-1	W	22	4.2	45	40	50	26	M	2	Ply	67	U.U.	No	Fell asleep
147	446 at 1 mile N. Moores Pike	4/19/69	0915	Clear	Day	Single	F	45	V-1	S	N/A	N/A	65	50	70	39	M	1	GMC P.U.	66	N.I.	Yes	Drunk; drove off road and struck tree
148	402.5	4/19/69	1300	Clear	Day	Rear End	P.D.	50	V-1 V-2	W W	41 41	4.8 4.8	25 25	20 20	30 35	41 17	F F	3 1	Chev Pont	66 65	U N.U.	No No	V-2 following too close
149	46 By-pass 300' S. SR45.	4/19/69	1301	Clear	Day	Rear End	P.I.	45	V-1 V-2 V-3	S S S	N/A	N/A	0 0 35	0 0 30	0 0 40	34 20 50	F M M	3 1 2	Chev Ford Int.Tk	62 65 69	N.I. U N.U.	No No No	V-1 & V-2 stopped; V-3 didn't
150	Mt. Tabor Rd. 2,000' North of Maple Grove Rd.	4/19/69	2238	Clear	Nite	Rear End	P.I.	35	V-1 V-2	N P	N/A	N/A	60 0	50 0	65 0	20 -	M -	1 0	Ford Chev	64 63	N.I.	Yes	Lost control due to speed; V-2 was parked.
151	603.4	4/22/69	0715	Clear	Day	Side	P.D.	45	V-1 V-2	E W	32 34	4.1 3.9	18 65	10 55	20 70	31 25	M M	1 1	VW Ply	67 69	N.U. U	No No	V-1 failed to see V-2 because of sun

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification		Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
									V-1	V-2	Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
152	503.8	4/25/69	1700	Clear	Day	Single	P.I.	35	V-1	W	33	4.8	60	58	61	19	M	3	Chev	60	U.U.	No	Lost control on curve
153	103.1	4/26/69	0525	Clear	Dawn	Head-on	P.I.	65	V-1	S	59	8.0	80	75	85	18	M	1	Pont	67	U.U.	Yes	V-1 reckless driving left of center
									V-2	N	56	9.8	65	60	70	18	M	1	Ford	66	U.U.	No	
154	Winslow Rd. at SR 37 S.	4/26/69	1250	Clear	Day	Rear End	P.D.	30	V-1	W	N/A	N/A	0	0	0	26	M	1	VW	66	U.U.	No	V-2 following too close
									V-2	W			5	3	7	54	F	1	Chev	63	U.U.	No	
155	104.3	4/26/69	1740	Clear	Day	Single	P.D.	65	V-1	S	54	6.2	60	55	65	29	M	1	VW	63	U	No	Aborted pass - oversteered - rolled
156	502.9	4/27/69	1140	Clear	Day	Head-on	P.I.	45	V-1	E	34	5.7	70	65	75	17	M	2	Chev	69	U.U.	No	Excessive speed for road condition
									V-2	W	34	7.6	5	0	10	69	M	1	Chev	62	N.I.	No	
157	207.4	4/30/69	0925	Clear	Day	Head-on	P.I.	55	V-1	N	50	6.7	10	7	15	27	F	3	Pont	59	N.I.	No	Foot feed of V-1 stuck
									V-2	S	52	6.9	55	50	60	33	M	1	Int.Tr	65	U.U.	No	
158	446: 1000' S. of Duke Road	4/30/69	1640	Clear	Day	Single	P.I.	40	V-1	W	N/A	N/A	45	40	50	16	M	1	Chev P.U.	69	N.U.	No	Speed too fast for curve
159	Old 37, 528' S. of Myers Rd.	5/1/69	0230	Clear	Nite	Single	P.I.	40	V-1	S	N/A	N/A	45	42	50	35	M	1	Chev	64	N.U.	Yes	Struck bridge in order to avoid another vehicle
160	No Police Report																						
161	109.9	5/2/69	1906	Clear	Day	Rear End	P.D.	55	V-1	N	50	8.3	0	0	0	27	F	1	Ford	63	N.U.	No	V-2 failed to see V-1 stopped for left turn
									V-2	N	50	8.3	40	40	45	20	M	3	Chev	66	N.U.	No	
162	109.3	5/2/69	2325	Clear	Nite	Single	P.I.	65	V-1	S	60	7.0	65	60	70	42	F	2	Chev	61	N.I.	Yes	Drunk; drive off rd.
163	303.0	5/5/69	2330	Clear	Nite	Side	P.I.	45	V-1	E	46	7.7	10	8	15	47	M	1	Dodge	68	U.U.	No	V-1 failed to yield right-of-way while turning left; V-2 speeding.
									V-2	W	42	6.4	60	50	65	19	F	2	SAAB	67	U.U.	No	

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
164	109.2	5/9/69	1400	Rain	Day	Rear End	P.I.	65	V-1	N	56	7.0	55	40	60	43	M	1	Ford	69	U.U.	No	V-1 speed too fast for conditions and following too close. V-1 struck V-2; V-2 struck V-3, and V-3 struck V-4.
									V-2	N	56	7.0	10	5	15	43	M	2	P.U. Chry	68	U.U.	No	
									V-3	N	56	7.0	0	0	0	20	F	1	Olds	63	U.U.	No	
									V-4	N	56	7.0	0	0	0	58	M	1	Chev	67	U.U.	No	
165	209.1	5/8/69	1800	Overcast	Dusk	Head-on	P.D.	55	V-1	N	50	4.8	45	40	50	21	M	1	Olds	69	U	No	V-1 driving left of center
									V-2	S	47	5.6	45	40	50	19	M	1	Ford	67	N.U.	No	
166	S. Rogers St. 1/10 mile S. of Rock Post Rd.	5/9/69	0709	Overcast	Dawn	Rear End	P.D.	30	V-1	N	N/A	N/A	10	5	15	52	F	2	Chev	64	N.I.	No	V-1 slowed; V-2 couldn't due to gravel on road & wet pavement.
									V-2	N			35	30	40	26	M	1	Olds	67	U.U.	No	
167	Curry Pike at Beasley Drive	5/9/69	0400	Rain	Nite	Single	P.I.	30	V-1	N	N/A	N/A	77	65	85	30	M	1	Ford	67	N.U.	Yes	Excessive speed & alcohol
168	Old SR 37 N. of Dunn St.	5/16/69	1910	Rain	Day	Head-on	P.I.	45	V-1	N	N/A	N/A	30	30	40	33	F	1	Ford	63	U	No	V-2 left of center in curve.
									V-2	S			40	40	50	17	F	3	Ramb	67	U.U.	No	
169	SR 46 By-pass at 17th St.	5/16/69	2200	Clear	Nite	Rear End	P.I.	45	V-1	N	N/A	N/A	0	0	0	16	M	2	VW	62	N.I.	No	Brake failure on V-2
									V-2	N			30	25	35	21	M	2	Saab	60	N.I.	No	
170	Curry Pike at Midland	5/17/69	0308	Rain	Nite	Single	P.D.	30	V-1	N	N/A	N/A	55	45	60	24	M	1	Ford	65	U.U.	Yes	Excessive speed & alcohol.
171	209.4	5/17/69	1000	Rain	Day	Single	P.I.	55	V-1	N	48	6.6	65	45	70	23	F	2	Olds	64	N.I.	No	Lost control due to poor traction & excessive speed
172	Bethel Lane at Hinkle Rd.	5/11/69	2345	Clear	Nite	Side	P.I.	30	V-1	N	N/A	N/A	0 ⁺	0 ⁺	0 ⁺	18	M	4	Pont	66	N.U.	Yes	V-1 failed to yield right of way to V-2
									V-2	E			40	35	45	22	M	3	Buick	67	N.U.	No	
173	Fairfax Rd. E. of SR 37	5/12/69	1240	Clear	Day	Single	P.I.	30	V-1	E	N/A	N/A	30	25	35	NA	F	1	Chev	61	N.I.	No	Leaned down to pick up purse & lost control

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification			Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
									V-1	V-2	V-3	Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
174	609.5	5/13/69	1435	Clear	Day	Side Swipe	P.D.	65	V-1	E	55	9.3	45	42	48	42	F	1	Ply	66	N.U.	No	Improper pass by V-3 Tried to pass V-2 while V-2 was Passing V-1.	
									V-2	E	55	9.3	55	50	55	41	M	1	ChevTk	67	N.U.	No		
									V-3	E	55	9.3	65	63	70	56	F	1	Ply	65	N.U.	No		
175	SR 43 at SR 48 Intersec- tion	5/13/69	1720	Rain	Day	Rear End	P.D.	55	V-1	W	N/A	N/A	40	35	45	18	M	1	Ford	63	N.I.	No	Traffic lane ob- structed by Road Closed sign visible at max. 280 ft.	
									V-2	W			0	0	0	45	M	1	Ford	62	N.I.	No		
176	705.1	5/14/69	1850	Clear	Day	Single	P.D.	50	V-1	W	47	11.1	60	55	65	19	M	3	Chev	50	N.I.	No	V-1 lost control while avoiding Veh. in front of him that was turning left.	
177	46 By-pass 176' East of 17th Street	5/15/69	1530	Clear	Day	Rear End	P.D.	45	V-1	E	N/A	N/A	0	0	0	43	F	2	Chev	66	U	No	V-1 stopped; V-2 didn't.	
									V-2	E			40	35	45	53	M	1	Ford	68	U	No		
178	204.5	5/17/69	1545	Over cast	Day	Side	P.D.	55	V-1	N	47	5.2	20	15	20	31	M	2	Pont	67	N.U.	No	V-2 was passing V-1. V-1 turned left (improper passing).	
									V-2	N	47	5.2	40	35	50	43	F	3	Chev	56	N.I.	No		
179	46 By-pass at Fee Lane	5/17/69	2350	Rain	Nite	Single	P.D.	45	V-1	W	N/A	N/A	40	35	45	21	M	2	Volvo	63	N.I.	No	V-1 forced off rd. by unknown veh.	
180	303.5	5/18/69	1315	Rain	Day	Rear End	P.D.	45	V-1	W	46	5.9	5	3	8	50	M	1	Ramb	68	U	No	V-1 slowed for traffic; V-2 follow- ing too close struck V-1; V-3 Also too close - struck V-2.	
									V-2	W	46	5.9	25	20	30	21	M	5	Ply	69	U.U.	No		
									V-3	W	46	5.9	30	25	35	27	M	2	Merc	64	U.U.	No		
181	101.1	5/18/69	1340	Rain	Day	Side	P.D.	40	V-1	E	49	7.9	10	5	15	21	F	1	Buick	68	U	No	Sbound V1 turned lt. on yel. lite., Nbound V3 hit V1 broadside, swung V1 180° into & on top of V2 stopped at intersection.	
									V-2	W	49	7.9	0	0	0	35	M	1	VW	63	U	No		
									V-3	N	49	7.9	40	30	45	47	M	3	Chev P.U.	64	N.I.	No		

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
182	Anderson Rd. 1.3 miles E. of Shilo	5/19/69	0005	Clear	Nite	Single	P.I.	65	V-1	E	N/A	N/A	45	30	50	22	M	1	Camaro	68	N.U.	No	Too fast for conditions - patches of water.
183	703.4	5/20/69	1700	Over cast	Day	Side	P.D.	45	V-1 V-2	W W	45 45	5.6 5.6	10 40	Unk 40	Unk 45	32 38	M M	2 3	Pont Ramb	64 66	N.U. N.U.	No No	V-1 slowed to make rt. turn; V-2 not able to stop; tried to pass on right.
184	Vernal Pike 224' N. of Adam	5/21/69	2340	Clear	Nite	Single	P.I.	30	V-1	S	N/A	N/A	40	35	45	40	M	1	Chry	67	N.U.	Yes	Speeding; lost control crossing RR tracks.
185	That Rd. 1000' W. of Rogers	5/22/69	0645	Rain	Dawn	Single	P.I.	30	V-1	W	N/A	N/A	30	25	35	62	M	1	Chev	61	N.I.	No	Lost control avoiding another veh.
186	609.1	5/22/69	0700	Rain	Dawn	Single	P.D.	45	V-1	E	51	7.8	45	45	50	42	F	1	Ford	67	N.U.	No	Lost control due to wet pavement.
187	502.4	5/22/69	1845	Clear	Nite	Single	P.D.	20	V-1	W	38	5.0	55	50	60	Unk	M	1	Chev	65	U.U.	Unk	Speed too fast for curve.
188	502.5	5/23/69	1550	Over cast	Day	Head-on	P.I.	45	V-1 V-2	E W	40 40	6.0 5.3	40 50	35 45	45 55	57 18	M M	1 1	Pont Pont	64 63	N.I. N.I.	No No	V-2 locked brakes to avoid other Veh., then lost control.
189	Rohner Rd. 2/10 mi. E. of SR 37	5/23/69	1710	Clear	Day	Side	P.I.	35	V-1 V-2	E E	N/A N/A	N/A N/A	7 40	5 36	10 44	34 20	F M	1 2	Dodge Honda	64 66	N.U. N.I.	No No	V-1 turning left & V-2 attempted to pass on left.
190	601.2	5/24/69	1200	Clear	Day	Rear End	P.D.	45	V-1 V-2	W W	37 37	6.2 6.2	10 50	Unk 45	Unk 55	42 22	M M	1 1	Ply Ford	68 65	N.U. U	No No	V-1 slowed to turn rt; V-2 didn't stop.
191	Curry Pike 5/10 mi. S. of Woodyard Rd.	5/19/69	1345	Over cast	Day	Single	P.I.	30	V-1	N	N/A	N/A	64	50	70	19	M	2	Chev	68	N.U.	No	Rt. front wheel left rd.; lost control.

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
193	102.8	6/1/69	1500	Clear	Day	Rear End	P.I.	65	V-1 V-2	S S	57 57	8.0 8.0	50 80	Unk Unk	Unk Unk	23 M	M Unk	Unk Unk	Cycle Unk	62 Unk	N.A. Unk	Unk Unk	Hit & Run. V-2 struck V-1 then left
197	602.2	5/20/69	1920	Clear	Day	Rear End	P.D.	45	V-1 V-2	E E	40 40	6.8 6.8	15 35	10 22	20 40	23 24	M M	3 1	Ford VW	65 62	U N.U.	No Yes	V-1 slowed; V-2 did not.
198	Weimer Rd. at Camp Rd.	5/30/69	1625	Clear	Day	Head-on	P.D.	65	V-1 V-2	S N	N/A N/A	N/A N/A	30 30	25 25	35 35	24 20	M M	5 1	Ford Chev	67 64	N.U. N.U.	No No	Unknown Veh. Crossed rd. forcing V-2 left of center.
199	305.1	6/1/69	1555	Clear	Day	Single	P.D.	45	V-1	E	46	6.3	35	30	40	45	F	2	Dodge	66	U.U.	No	Lost control of trailer due to wind.
200	306.1	6/1/69	1859	Rain	Day	Rear End	P.D.	55	V-1 V-2	W W	41 41	7.6 7.6	20 40	Unk 35	Unk 45	44 62	M M	2 4	Chev Ford	65 68	U.U. U.U.	No No	V-1 slowed to turn; V-2 following another veh. which avoided V-1, but V-2 struck.
201	Old 37 N. at Bethel Lane	6/3/69	0830	Clear	Day	Side	P.I.	30	V-1 V-2	E N	N/A N/A	N/A N/A	30 0 ⁺	25 0 ⁺	35 0 ⁺	17 26	F M	1 1	Pont Chev	67 64	U.U. U.U.	No No	V-2 failed to yield right-of-way.
202	Oard Rd. 3/10 mi. E. Vernal Pike	6/2/69	1509	Over cast	Day	Single	P.D.	35	V-1	W	N/A	N/A	35	30	40	49	M	3	Buick	53	N.I.	Yes	"Faulty Brake" claim
203	Hartstraight Rd. 2/10 mi. Ellettsville	5/26/69	1135	Clear	Day	Side	P.D.	35	V-1 V-2	N S	N/A N/A	N/A N/A	35 40	30 35	40 45	34 18	M M	1 1	Ford Dodge	64 63	U N.U.	No No	V-2 driving left of center; V-1 pulled left to avoid
204	Winslow Rd. 432' W. of High Street	6/8/69	0225	Clear	Nite	Single	P.I.	30	V-1	W	N/A	N/A	50	45	55	32	M	1	Dodge	65	N.I.	Yes	Driver intoxicated
205	Rockport Rd. 3.3 Mi. S. of Rogers	6/9/69	0700	Over cast	Day	Head-on	P.I.	30	V-1 V-2	N S	N/A N/A	N/A N/A	45 35	40 30	50 40	17 60	F F	1 1	Chev Chev	66 67	U.U. U.U.	No No	V-1 topped hill lt. of center.

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
207	Woodyard Rd. 112' W. Vernal Pike	6/11/69	2359	Clear	Nite	Single	P.D.	35	V-1	W	N/A	N/A	35	30	40	34	M	1	Chev PU	69	U.U.	Yes	Lost control in curve.
208	405.9	6/11/69	2245	Clear	Nite	Rear End	P.D.	55	V-1 V-2	W W	44 44	8.4 8.4	40 05	35 02	40 05	43 22	M M	5 2	Renault Buick	64 63	N.U. N.I.	No Yes	V-2 slowed to make left turn; V-1 didn't see in time to stop.
209	Curry Pike 6/10 mi. N. of 48	6/12/69	1400	Over cast	Day	Rear End	P.D.	30	V-1 V-2	N N	N/A N/A	N/A N/A	30 30	25 25	35 35	20 30	F F	1 1	Merc Chev	65 64	N.U. N.I.	No No	V-2 didn't see V-1 in time to stop.
210	Old 37 4/10 mi. N. of Bethel	6/12/69	1434	Rain	Day	Single	P.I.	40	V-1	S	N/A	N/A	45	35	50	20	F	1	Ford	63	U.U.	No	Failed to adjust speed to weather conditions.
211	501.2	6/12/69	1511	Rain	Day	Side	P.I.	45	V-1 V-2 V-3	W E S	41 39 41	7.6 5.0 7.6	40 40 0	35 35 0	45 45 0	41 43 23	F F F	1 2 2	Ford Buick Pont	65 66 63	U.U. U.U. U.U.	No No No	V-3 stopped at jct. with car in Wbound lane; V-1 pulled left of center to avoid V-3.
212	Hartstraight Rd. 4/10 mi. S. SR 46	6/12/69	1432	Rain	Day	Side	P.D.	35	V-1 V-2	N N	N/A N/A	N/A N/A	20 25	Unk 20	Unk 30	33 24	F M	1 1	Olds Chev	66 65	U.U. U.U.	No No	V-1 was making left turn; V-2 was not able to stop & turned with her.
213	504.1	6/13/69	1600	Over cast	Day	Rear End	P.D.	45	V-1 V-2	W W	28 28	5.8 5.8	30 30	25 25	30 30	41 55	F M	1 2	Ford Buick	67 69	N.U. U	No No	V-2 following too close.
214	202.9	6/14/69	1120	Over cast	Day	Side	P.D.	45	V-1 V-2	N N	36 36	7.6 7.6	35 15	30 Unk	40 Unk	16 49	M M	1 1	Chev Buick	55 66	N.I. U.U.	No No	V-2 turned left while V-1 passing on left.

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification		Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
									Direction	Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex	Make		Year				
215	209.6	6/14/69	1240	Rain	Day	Single	P.D.	55	V-1	N	52	5.2	55	50	60	22	F	1	Olds	68	N.U.	No	Lost control on rainslick curve.
216	Ahorer Rd. at Harrell Rd.	6/14/69	1643	Over cast	Day	Rear End	P.D.	35	V-1 V-2	W P	N/A N/A	N/A N/A	25 0	30 0	30 0	16 N/A	F N/A	6 -	Ply Olds	62 69	N.U. N.A.	No NA	V-2 parked with part of car on rd; V-1 crested rise & hit V-2.
217	602.2	6/15/69	1523	Clear	Day	Side	P.I.	45	V-1 V-2	E W	42 44	4.2 5.0	0 40	0 35	5 45	43 19	M M	1 1	Ford Honda	69 69	N.U. N.I.	Yes No	V-1 turned in front of V-2.
218	105.4	6/16/69	1850	Clear	Day	Single	P.I.	65	V-1	N	59	6.0	70	65	75	24	F	1	VW	64	N.U.	Yes	V-1 left rd & lost control.
219	404.1	6/17/69	0848	Clear	Day	Rear End	P.I.	50	V-1 V-2 V-3	W W W	42 42 42	11.0 11.0 11.0	N/A 0 50	N/A 0 45	N/A 0 55	69 31 31	M M F	2 1 1	Olds FordPU Chev	63 68 69	U.U. U.U. U.U.	No No No	V-1 & 2 stopped; V-3 didn't.
220	502.4	6/18/69	0826	Rain	Day	Single	P.I.	45	V-1	W	43	6.6	45	40	50	20	F	2	VW	65	N.U.	No	Lost control due to braking.
221	Mt. Tabor Rd, at Maple Grove Rd.	6/19/69	0702	Over cast	Day	Side	P.I.	35	V-1 V-2	E S	N/A N/A	N/A N/A	0 ⁺ 35	0 ⁺ 30	0 ⁺ 40	44 41	M M	1 1	Ford Chev P.U.	65 48	N.U. N.I.	No No	V-1 pulled into intersection & was hit by V2; No stop signs.
222	Tapp Rd. 374' W. of Rockport	6/21/69	1645	Clear	Day	Single	P.D.	40	V-1	W	N/A	N/A	40	35	45	44	M	1	Olds	66	N.U.	No	Lost control avoidg. on-coming traffic.
223	Union Valley Rd. 1 mi. N. of SR 46	6/21/69	2345	Clear	Nite	Single	P.D.	35	V-1	N	N/A	N/A	50	45	55	16	M	2	Chev	69	N.U.	No	Left ft. wheel locked.
224	103.7	6/22/69	1150	Rain	Day	Rear End	P.D.	65	V-1 V-2 V-3	N N N	54 54 54	8.6 8.6 8.6	8 15 40	5 12 35	10 18 45	44 49 33	F M M	4 4 2	Ford Cad. FordPU	68 67 68	Unk U.U. U.U.	No No No	V-1 making left turn V-2&3 unable to stop
225	46 By-pass at Jordan Ave.	6/22/69	1720	Rain	Day	Single	P.I.	35	V-1	S	N/A	N/A	45	40	50	20	M	2	Olds	63	N.U.	No	Lost control due to water on road.

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification		Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
									V-1	V-2	Direction	Mean Speed	Std. Dev.	Est.	Min.	Max.	Age		Sex	Make			
226	46 By-pass at Jordan Ave.	6/22/69	1045	Rain	Day	Rear End	P.D.	45	V-1 V-2	E E	N/A N/A	10 35	8 30	12 40	26 35	M M	1 3	Ford Chev	65 69	U.U. U.U.	No No	V-1 turning; V-2 pulling boat unable to stop.	
227	209.5	6/25/69	0720	Rain	Day	Single	P.D.	55	V-1	N	42	8.9	55	50	60	21	F	1	Pont	64	N.I.	No	Lost control on wet pavement.
228	446 on Causeway at Monroe Reservoir	6/25/69	2215	Over cast	Nite	Rear End	P.D.	40	V-1 V-2	N N	N/A N/A	45 0	40 0	50 0	67 38	M M	1 2	Chry Jeep Tk.	67 67	N.U. U.U.	No No	V-2 stopped on rd. with no lites on; V-1 did not see.	
229	Country Club Rd. & South Rogers St.	6/22/69	0825	Clear	Day	Side	P.D.	35	V-1 V-2	E N	N/A N/A	35 0 [†]	30 0 [†]	40 0 [†]	29 31	M M	1 1	Dodge Tk. Olds	67 69	U N.U.	No No	V-2 failed to stop for stop sign.	
230	46 By-pass at N. Dunn	6/27/69	1835	Clear	Day	Single	P.D.	45	V-1	E	N/A	N/A	45	40	50	18	M	1	Pont	69	N.U.	No	V-1 passing; Veh. in front turned left.
231	404.1	6/30/69	1400	Clear	Day	Side	P.I.	50	V-1 V-2	E W	40 44	9.7 5.5	30 50	25 45	35 55	54 28	M M	1 1	IntTk IntTk	68 63	N.U. U.U.	No No	V-2 braked to avoid another veh; brakes pulled him into V-1.
233	603.5	7/1/69	1720	Clear	Day	Head-on	P.I.	45	V-1 V-2	E W	44 32	5.1 11.5	30 10	25 5	35 15	23 22	M F	1 2	Triump Buick	68 67	N.I. U.U.	No No	V-2 failed to yield right-of-way to V-1
234	S. Rogers 3/10 mi. S. of Gordon P. La.	7/4/69	0332	Clear	Nite	Rear End	P.D.	30	V-1 V-2	N N	N/A N/A	60 25	55 20	65 30	20 21	M M	2 3	Chev Chev	68 64	N.U. N.U.	No No	V-1 speeding & improper overtaking.	
235	207.1	7/6/69	1345	Rain	Day	Single	P.I.	55	V-1	S	48	7.8	40	35	45	42	F	1	Merc	63	N.U.	Unk	V-1 hit puddle of water & lost contrl.
236	403.2	7/7/69	1000	Clear	Day	Single	P.D.	55	V-1	E	41	9.0	45	40	50	76	M	1	Stude	62	N.I.	No	Pulling trailer; no previous exp; braked hard; trailer j-knif
238	Rockport at Tapp Rd.	7/9/69	1645	Over cast	Day	Side	P.D.	40 30	V-1 V-2	E N	N/A N/A	35 0 [†]	30 0 [†]	40 0 [†]	28 19	M F	1 3	Ford Olds	65 53	N.U. N.I.	No No	V-2 didn't yield ROW to V-1.	

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification		Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
									V-1	V-2	Direction	Mean Speed	Std. Dev.	Est.	Min.	Max.	Age		Sex	Make			
239	Old 37 1/2 mi. N. of Bethel	7/10/69	0844	Rain	Day	Side	P.D.	40	V-1 V-2	S N	N/A N/A	35 35	30 30	40 40	49 39	F M	3 1	Merc Ford	58 68	N.I. U.U.	No No	V-2 lost control rounding curve & struck V-1 broadside	
240	405.2	7/11/69	1813	Over cast	Day	Side Swipe	P.D.	55	V-1 V-2	W W	45 45	9.2 9.2	10 30	8 25	15 35	18 36	M F	2 1	Chev Olds	68 64	U.U. U.U.	No No	V-2 improper pass on rt; V-1 signaled it - turned right.
241	Old 37 2/10 mi. N. of Bethel Lane	7/13/69	2205	Dry	Nite	Side	P.I.	35	V-1 V-2	S N	N/A N/A	40 55	35 50	45 60	25 23	M M	1 1	Fiat Chev	67 69	U.U. U.U.	No No	V-2 crossed center line & struck V-1	
242	407.2	7/14/69	1900	Clear	Day	Single	P.I.	50	V-1	E	46	6.1	50	45	55	22	F	3	VW	63	U.U.	No	Took eyes off rd. too long - left rd. and lost control.
243	501.6	7/19/69	1330	Clear	Day	Single	P.I.	45	V-1	E	37	4.6	35	30	40	18	M	1	Honda	69	N.I.	No	Forced off rd. by tk
244	103.2	7/19/60	1747	Clear	Day	Head-on	F	65	V-1 V-2	N S	54 57	6.8 4.9	70 55	65 55	75 60	18 40	M M	3 2	Olds Ford	59 67	N.I. U/NU	No No	V-1 left of center in passing; struck V-2 head-on.
245	That Rd .5 mi Wofclew Crk.	7/20/69	1045	Rain	Day	Single	P.D.	35	V-1	E	N/A	N/A	35	30	40	19	F	1	Chev	69	N.U.	No	Tried to avoid a dog lost control.
246	3110' S. of Leonard Spgs	7/20/69	1330	Rain	Day	Rear End	P.D.	30	V-1 V-2	S S	N/A N/A	N/A N/A	25 20	20 15	30 25	28 30	M M	5 5	Buick Chev	61 64	N.I. U/NU	No No	V-2 slowed for water on rd; V-1 struck in rear.
247	Old 37 2/10 mi. N. of Whisnand	7/20/69	1911	Over cast & wet	Day	Side	P.D.	35	V-1 V-2	S N	N/A N/A	N/A N/A	35 35	30 30	40 40	UNKNOWN NO POLICE REPORT						V-2 driving left of center & struck V-1.	
248	401.4	7/22/69	1731	Clear	Day	Rear End	P.I.	40	V-1 V-2	W W	45 45	10.1 10.1	0 40	0 35	0 40	21 60	F M	1 1	Olds Ford	62 69	N.U. N.U.	No No	V-1 stopped to make left turn;
250	503.5	7/26/69	1304	Clear	Day	Single	P.I.	45	V-1	W	38	4.7	45	40	50	21	M	2	Penn Ford	65	U.U.	No	Wheel off rd; lost control & rolled over

TABLE 6.1. Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
251	Airport Rd. 50' W. of End Wright	7/27/69	0810	Rain	Day	Head-on	P.I.	40	V-1	E	N/A	N/A	40	35	45	20	F	1	Dodge	63	U.U.	No	Both Veh. left of center.
								V-2	W			45	40	50	30	M	1	Ford	61	U.U.	No		
252	Union Valley Rd. 1000' N. of Maple Gr.	7/27/69	1355	Clear	Day	Head-on	P.I.	65	V-1	N	N/A	N/A	30	25	35	22	M	1	Ford	58	N.I.	No	V-1 crested hill; V-2 left of center.
								V-2	S			5	5	10	7	M	1	Bicycle	-	-	No		
253	SR 46 By-pass at Dunn	7/25/69	1415	Clear	Day	Side	P.I.	30	V-1	N	N/A	N/A	0+	0+	0+	14	M	1	Soapbox Derby Car	-	N.A.	No	V-1 disregarded stop & hit V-2.
								V-2	W			45	40	45	21	F	1	Ramb	59	N.I.	No		
254	2614 Leonard Springs	7/29/69	2200	Clear	Nite	Single	P.I.	20	V-1	S	N/A	N/A	35	30	40	33	M	1	FordTk	64	N.I.	No	Forced off rd. by on-coming vehicle.
255	501.3	7/31/69	2340	Clear	Nite	Single	P.I.	35	V-1	W	36	6.8	60	55	65	17	M	1	Chev	55	N.I.	No	Forced off rd. by on-coming vehicle - lost control.
257	102.1	7/4/69	0215	Clear	Nite	Single	P.I.	55	V-1	S	57	5.6	45	40	50	18	M	2	Volvo	69	U.U.	Yes	Drunk - lost control
258	210.2	7/7/69	2345	Clear	Nite	Rear End	P.D.	55	V-1	S	47	5.2	0	0	0	27	M	1	Merc	69	U.U.	No	V-1 stopped behind V-2; V-2 backed into V-1.
								V-2	S	47	5.2	5	3	7	67	M	1	Ford	61	U.U.	Yes		
259	SR 46 By-pass at Dunn St.	7/11/69	2220	Clear	Nite	Side	P.D.	45	V-1	W			35	30	40	20	M	1	Chev	66	U.U.	No	V-2 failed to yield ROW; hit by V-1 & forced into V-3.
								V-2	N	N/A	N/A	0+	0+	0+	16	M	1	Ramb	66	U.U.	No		
								V-3	S			0	0	0	44	M	1	VW Bus	65	U.U.	No		
260	602.4	7/16/69	1145	Clear	Day	Rear End	P.D.	30	V-1	W	39	6.3	20	15	25	51	M	1	FordTk	67	U.U.	No	V-2 following too close; hit V1 in rear.
								V-2	W	39	6.3	20	15	25	19	M	1	Chev	60	U.U.	No		

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification		Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
									V-1	V-2	Direction	Mean Speed	Std. Dev.	Est.	Min.	Max.	Age		Sex	Make			
261	604.1	7/16/69	1645	Clear	Day	Side	P.D.	45	V-1 V-2	E W	43 44	10.6 7.9	5 0	3 0	7 0	46 N/A	M N/A	1 0	IntTk Pont.	68 67	U.U. -	No -	V-1(Trac./Trail) turned too sharply.
262	103.2	8/1/69	1630	Clear	Day	Side	P.I.	65	V-1 V-2	S S	51 51	6.4 6.4	60 05	55 03	65 07	59 25	F M	Unk Unk	Buick Dodge	63 64	U.U. U.U.	No No	V-2 turned left in front of V-1.
263	203.9	8/2/69	0015	Clear	Nite	Side	P.I.	45	V-1 V-2	N S	39 41	7.4 8.0	08 40	05 35	11 45	24 19	M M	Unk Unk	Ford VW	66 69	U.U. U.U.	No No	V-1 making left turn; turned in front of V-2.
264	211.5	8/7/69	0750	Light Rain	Day	Single	P.I.	55	V-1	S	53	7.0	55	50	60	21	M	Unk	IHC	66	U.U.	No	Lost control on curve.
265	205.1	8/12/69	0120	Clear	Nite	Single	F	55	V-1	S	47	6.0	75	65	80	23	M	1	Chev	68	N.U.	Yes	Lost control; hit tree.
267	203.5	8/7/69	1115	Clear	Day	Rear End	P.D.	45	V-1 V-2	S S	39 38	6.5 5.5	10 0	8 0	12 0	57 22	M F	Unk Unk	Chev Olds	62 62	U.U. U.U.	No No	V-2 slowed for 2 veh. turning in ft. of him; V1 unable to stop.
268	103.7	8/9/69	1445	Clear	Day	Rear End	P.I.	65	V-1 V-2 V-3 V-4	N N N N	51 51 51 51	5.4 5.4 5.4 5.4	26 45 45 45	Unk 40 40 40	Unk 50 50 50	35 35 42 44	M M F M	Unk Unk Unk Unk	Dodge Chev Dodge Ford	69 68 65 69	U.U. U.U. U.U. U.U.	No No No No	V-1 was making lt. turn; Other veh. were unable to stop.
269	203.9	8/19/69	2020	Clear	Nite	Side	P.D.	45	V-1 V-2	N W	38 38	5.6 5.6	25 0+	20 0+	30 0+	22 43	M F	Unk Unk	Buick Ford	66 65	U.U. U.U.	No No	V-2 failed to yield ROW at intersection.
270	204.9	8/22/69	2230	Clear	Nite	Rear End	P.D.	55	V-1 V-2	S S	47 47	6.1 6.1	45 0	40 0	50 0	32 28	M F	Unk Unk	Ford Chev.	67 61	U.U. U.U.	No No	V-2 stopped to make left turn; V1 crested hill & was unable to stop.
271	302.1	6/11/69	1300	Clear	Day	Side	P.I.	45	V-1 V-2	E E	47 47	6.4 6.4	35 5	35 5	40 5	19 54	M F	1 1	VW Chev	66 62	N.U. N.U.	No No	V-2 stopped to make lt. turn; V1 about 5 cars back attempted to pass on left.

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
272	S. Rogers at That Rd.	6/11/69	1550	Clear	Day	Side	P.D.	30	V-1 V-2	S E	N/A N/A	70 00	60 00	75 03	16 68	M M	Unk 1	Ply Ford	64 62	U.U. U.U.	No No	V-2 pulled out of That Rd. in prep. for turn onto Rogers, V-1 unable to stop.	
273	205.8	8/27/69	2213	Clear	Nite	Side	P.D.	55	V-1 V-2	N S	53 49	5.2 4.8	40 50	35 48	45 52	45 24	M M	Unk Unk	ChevTk Ford	60 67	U.U. U.U.	No No	V-1 lost wheel; Wheel then hit V-2.
274	107.3	8/27/69	1445	Clear	Day	Side	P.D.	65	V-1 V-2	W S	56 56	6.8 6.8	0+ 45	0+ 35	0+ 50	26 18	M M	Unk Unk	Chev Ford	60 69	U.U. U.U.	No No	V-1 pulled out in front of V-2.
275	103.2	8/27/69	1015	Clear	Day	Rear End	P.D.	65	V-1 V-2	N N	56 56	8.3 8.3	0 59	0 Unk	0 Unk	61 69	F F	2 2	Cad. Volvo	68 68	N.U. U.U.	No No	V-1 stopping for flagman.
276	103.2	8/28/69	1840	Clear	Day	Side	P.I.	65	V-1 V-2	S S	57 57	5.6 5.6	30 50	20 40	50 60	76 29	M M	Unk Unk	Chev Olds	66 68	U.U. U.U.	No No	V-1 turning; V-2 attempted to pass.
277	203.2	8/30/69	0234	Fog	Nite	Rear End	P.I.	45	V-1 V-2 V-3 V-4	P S S S	43 43 43 43	6.0 6.0 6.0 6.0	0 20 70 48	0 15 60 43	0 30 75 53	No Driver 38 22 29	M M M	1 1 Unk	Semi FordTk Chev IntTk	60 Unk 69 68	N/A U.U. U.U. U.U.	N/A No No No	V-1 parked; V-2 hit by V3; V2 then hit V1; V4 unable to stop hit V-3.
279	106.1	9/2/69	1920	Rain	Nite	Side	P.D.	65	V-1 V-2	N S	56 61	8.2 6.2	55 50	50 45	60 55	26 65	M M	Unk Unk	Chev Olds	65 68	U.U. U.U.	No No	PU in front of V-2 stopping to turn; V-2 unable to stop - lost control.
280	103.8	9/10/69	1735	Clear	Day	Head-on	P.D.	65	V-1 V-2	N S	56 54	7.2 7.8	60 53	55 50	65 55	24 38	F M	Unk Unk	Pont IntTk	62 63	U.U. U.U.	No No	V-1 unable to stop in time to avoid veh stopped in ft; entered on-coming lane & was struck head-on by V-2.
281	204.1	8/30/69	1905	Clear	Day	Head-on	P.I.	55	V-1 V-2	S N	44 46	5.1 5.4	46 40	40 55	55 25	39 M	M Unk	Ford Van Chev	69 67	U.U. U.U.	No No	V-1 lost control on curve; crossed center & struck V-2.	

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification		Direction	Traffic Characteristics		Speed of Accident-Involved Veh			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
									V-1	V-2		Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
282	201.9	9/14/69	1248	Clear	Day	Side	P.D.	45	V-1 V-2	S E		42 42	5.0 5.0	40 0+	38 0+	42 0+	30 35	M M	Unk Unk	Chev Ply	64 62	U.U. U.U.	No No	V-2 entered the intersection in ft. of V-1; V-1 had ROW.
284	206.6	9/17/69	0300	Rain	Nite	Single	P.I.	45	V-1	S		48	6.2	70	60	80	22	M	Unk	Chev	69	U.U.	Unk	Lost control; Veh left road.
287	206.8	9/19/69	1605	Clear	Day	Rear End	P.D.	55	V-1 V-2	S S		48 48	10.4 10.4	0 45	0 35	0 55	19 49	F F	Unk Unk	Ply Chev	63 63	U.U. U.U.	No No	V-1 stopped for schoolbus; V-2 did not see V-1 in time to stop.
288	203.7	9/24/69	1910	Clear	Day	Rear End	P.D.	45	V-1 V-2	N N		40 40	4.9 4.9	7 50	5 35	10 65	26 21	M M	Unk Unk	Volvo Ply	58 69	N.I. U.U.	No No	V-1 slowed to turn left; V-2 unable to stop.
290	202.1	9/27/69	0026	Clear	Nite	Side	P.I.	45 35	V-1 V-2	S E		44 44	5.2 5.2	41 0+	39 0+	42 0+	22 23	M M	Unk Unk	Dodge Dodge	68 67	U.U. U.U.	No No	V-2 failed to stop at intersection & struck V-1.
291	204.4	10/4/69	0207	Clear	Nite	Single	P.D.	55	V-1	N		48	5.0	55	55	55	21	M	Unk	Merc	64	U.U.	No	D-1 fell asleep & ran off highway.
296	108.1	10/12/69	1015	Dry	Day	Rear End	P.D.	65	V-1 V-2 V-3	N N N		60 60 60	5.6 5.6 5.6	0 0 65	0 0 59	0 0 71	31 45 18	M M M	Unk Unk Unk	Pont Ford Ford	67 68 65	U.U. U.U. U.U.	No No NO	V-1&2 stopped for a turning Veh; V3 did not notice V-1&2 in time to stop.
297	104.5	10/14/69	1543	Clear	Day	Side	F	65	V-1 V-2	S S		60 60	7.2 7.2	75 40	65 36	82 44	53 58	M M	Unk 2	Pont VW	62 66	U.U. U.U.	No No	V-1 passing V-2; saw on-coming traf. (V-3) - pulls back into his lane & hit V-2.
303	106.7	10/12/69	2207	Rain	Nite	Single	P.D.	65	V-1	N		55	7.2	51	50	58	42	F	Unk	Ramb	69	U.U.	No	Deer ran in ft. of V-1 & was hit by V-1

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification	Direction	Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
											Mean Speed	Std. Dev.	Est.	Min	Max.	Age	Sex		Make	Year			
305	203.9	10/24/69	0717	Clear	Nite	Side	P.I.	45	V-1 V-2	W S	44 44	5.4 5.4	0+ 45	0+ 28	0+ 47	50 22	M M	Unk Unk	Buick Chev	66 67	U.U. U.U.	No No	V-1 pulled out in front of V-2 at an intersection.
307	106.1	10/25/69	0510	Dry	Nite	Single	P.I.	65	V-1	N	48	15.8	65	60	70	23	M	Unk	Ford	68	U.U.	Yes	V-1 left road & struck garage
308	103.8	10/25/69	0714	Dry	Nite	Side	P.D.	65	V-1 V-2	S N	56 55	6.6 6.7	72 68	70 65	74 68	Hit and 20	M	Run - Unk	Old School Bus Olds	69	U.U.	No	V-1 crossed center line & side-swiped V-2.
309	102.9	10/26/69	1845	Clear	Nite	Single	P.D.	65	V-1	N	54	6.1	57	40	60	55	F	Unk	Merc	65	Unk	No	Left front ball joint broken; D-1 lost control.
310	205.4	10/28/69	2230	Clear	Nite	Single	P.I.	55	V-1	S	48	7.2	45	45	65	16	M	Unk	VW	65	Unk	No	V-1 started to skid; D-1 lost control.
315	206.7	10/31/69	1730	Rain	Nite	Single	P.I.	55	V-1	S	47	7.6	45	40	50	23	M	Unk	Pont	65	Unk	No	D-1 stated that a truck forced him off road.
316	201.1	11/2/69	0247	Clear	Nite	Single	P.D.	45	V-1	N	38	5.4	65	60	70	22	M	Unk	Ford	65	Unk	Yes	D-1 lost control while passing other vehicle.
319	102.9	10/26/69	1845	Clear	Nite	Rear End	P.D.	65	V-1 V-2 V-3	N N N	58 58 58	6.9 6.9 6.9	10 58 60	Unk 40 40	Unk 63 65	20 36 46	M M F	Unk Unk Unk	Pont Olds Olds	62 67 68	Unk Unk Unk	No No No	V1 slowed for accident #309; V2 & 3 could not react in time to avoid rear-ending.
327	104.8	11/15/69	1325	Clear	Day	Single	P.I.	65	V-1	N	57	7.0	58	53	60	18	M	Unk	Dodge	59	Unk	No	V1 run off rd by on-coming vehicle.

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification		Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
									Vehicle Identification	Direction	Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
329	107.1	11/18/69	0157	Rain	Nite	Single	P.I.	65	V-1	N	58	6.9	55	49	61	38	M	1	Merc	69	U	No	Deer ran in ft. of V-1.
331	202.4	11/19/69	1815	Wet	Day	Rear End	P.I.	45	V-1	S	33	6.8	0	0	0	20	M	Unk	Chev	69	U.U.	No	V1 stopped to make left turn; V2 unable to stop.
									V-2	S	33	6.8	35	30	40	17	F	Unk	Ford	63	U.U.	No	
332	104.8	11/8/69	1000	Fog	Day	Rear End	P.D.	65	V-1	S	57	6.4	0	0	0	53	M	Unk	Merc	69	U.U.	No	V-1&2 stopped; V3 unable to stop.
									V-2	S	57	6.4	0	0	0	21	F	Unk	Ford	69	U.U.	No	
									V-3	S	57	6.4	61	59	63	19	F	Unk	Merc	68	U.U.	No	
333	104.8	11/8/69	1005	Fog	Day	Single	P.D.	65	V-1	S	56	6.5	Unk	Unk	Unk	50	M	Unk	Ford	64	U.U.	No	Traffic stopped for accident 332; V-1 unable to stop & took evasive action to the right.
335	108.2	11/24/69	1710	Clear	Day	Rear End & Head-on	P.D.	65	V-1	N	55	8.2	N/A	N/A	N/A	53	M	Unk	Olds	66	Unk	No	V-1&2 stopped; V3 unable to stop; attempted to pass but struck V4 in the process.
									V-2	N	55	8.2	5	0	10	23	M	Unk	Chev	63	Unk	No	
									V-3	N	55	8.2	57	49	70	26	M	Unk	Dodge Tk.	66	Unk	No	
									V-4	S	57	8.7	50	45	55	35	M	Unk	IHC	69	Unk	No	
340	205.9	12/8/69	0818	Clear	Day	Single	P.D.	55	V-1	S	47	6.6	40	40	45	35	M	Unk	VW	58	Unk	No	D-1 fell asleep & lost control.
341	209.5	12/14/69	1535	Clear	Day	Head-on	P.I.	55	V-1	S	51	6.5	55	49	61	36	F	Unk	Ford	62	Unk	Unk	V-2 turned in front of V-1 & was hit by V-1.
									V-2	N	51	7.0	10	9	11	41	F	Unk	Buick	65	Unk	Unk	
342	103.6	12/18/69	1407	Mist	Day	Rear End	P.I.	65	V-1	N	53	7.5	5	0	10	55	M	Unk	Linc	68	Unk	No	V-1 slowed for turning veh. V2,3,64 unable to avoid hit each other; V5 en-route opp. dir. hit V-3 as 3 crossed center of road.
									V-2	N	53	7.5	40	36	40	23	F	Unk	Ford	70	Unk	No	
									V-3	N	53	7.5	46	40	49	18	M	Unk	Chev	65	Unk	No	
									V-4	N	53	7.5	49	40	49	19	M	Unk	Fly	69	Unk	No	
									V-5	S	50	7.5	53	50	60	19	F	Unk	Buick	65	Unk	No	

TABLE 6.1. (Continued)

Accident Number	Location	Date	Time	Weather	Light Condition	Type	Damage	Speed Limit	Vehicle Identification		Traffic Characteristics		Speed of Accident-Involved Veh.			Driver		No. Occupants	Vehicle		Seat Belts	Alcohol	Contrib. Circum.
									V-1	V-2	Mean Speed	Std. Dev.	Est.	Min.	Max.	Age	Sex		Make	Year			
344	103.6	12/21/69	1650	Snow	Dusk	Head-on	P.D.	65	V-1	N	35	3.5	34	30	35	33	F	Unk	Ford	63	U.U.	No	D-1 lost control of his veh. due to snow; V-1 crossed over center line & struck V-2.
									V-2	S	39	5.7	34	30	40	52	M	Unk	Ford	65	U.U.	No	
346	102.1	12/21/69	2030	Snow	Nite	Side	P.D.	65	V-1	N	33	3.5	12	10	20	63	M	Unk	IntTk	67	Unk	No	V-2 lost control on snow & slid into highway truck.
									V-2	S	39	5.7	14	14	25	61	M	Unk	Buick	66	Unk	No	
348	108.9	12/21/69	1640	Snow	Day	Head-on	P.I.	65	V-1	S	33	6.1	30	27	33	58	M	Unk	Chev	67	Unk	No	V-1 crossed center line to avoid a veh stopped in his lane; V-1 hit by V2.
									V-2	N	40	4.7	30	27	33	36	M	Unk	Desoto	60	Unk	No	
351	105.9	12/23/69	1030	Snow	Day	Side	P.D.	65	V-1	S	40	4.7	38	30	40	30	M	Unk	Ford	63	Unk	No	D-1 lost control on snow; crossed center line; hit V2.
									V-2	N	33	6.1	21	20	25	26	M	Unk	Chev	62	Unk	No	
352	105.9	12/23/69	1106	Snow	Day	Single	P.D.	65	V-1	S	40	4.7	42	40	45	52	F	Unk	Ford	62	Unk	No	V-1 lost control due to snow.
355	206.7	12/30/69	1330	Clear	Day	Rear End	P.I.	55	V-1	N	48	6.5	10	5	15	33	F	Unk	Stude	65	U.U.	No	V-1 making right turn; V-2 (tractor/trailer) unable to slow in time.
									V-2	N	48	6.5	35	35	57	57	M	Unk	Dodge	68	U.U.	No	

N/A - Traffic characteristic not available or data not applicable due to secondary accident. (A secondary accident is defined as one in which the striking vehicle has just previously been involved in an accident.)

+ - Vehicle was crossing the stream of traffic of interest, hence speed is assumed to be 0 mph.

* - Accident #47 not included in involvement rate calculation since traffic speed is zero given that a train is crossing the highway.

** - Accident #63 not included in involvement rate calculation since both vehicles were crossing the stream of traffic of interest.

NOTE: In the "Accident Number" Column, missing numbers refer to reported accidents which were assigned a number but for one of several reasons were voided at a later date.

TABLE 6.2. SPEED SURVEY DATA SUMMARY

Station	WEEKDAY												WEEKEND													
	DAY						NIGHT						DAY						NIGHT							
	DRY		WET		ICE		FOG		DRY		WET		ICE		FOG		DRY		WET		ICE		FOG			
	N	S	N	S	N	S	N	S	N	S	N	S	N	S	N	S	N	S	N	S	N	S	N	S		
	<u>MEAN SPEED</u>																									
101	54							*	*	*	53															
102	54	55	49					57	57	53	52	48	52					54	51			63	56	53	56	
103	55	54	44					56	55	55	51	44	48					54	55			54	55	54	58	
104	55	55	55	35			38	59	58	55	53	*	53					54	56			60	57	56	59	
105	55	55	58					54	54	53	53							55	55			57	55	56	59	
106	56	56	58	56				57	60	56	55	47	45					55	56			54	52		51	
107	54	56	49	52				57	56	51	56							55	60			58	53	55	59	
108	55	57	58	55				58	57	*	61								59					59	58	
109	57	56	54	56				60	57	*	54								56					60	59	
110	56	57	51	57				59	59	*	58								57				54	57	56	60
	<u>STANDARD DEVIATION</u>																									
101	6.3							*	*	*	7.2															
102	6.6	6.2	6.7					6.8	7.3	6.0	6.8	4.6	12.4					6.2	14.3			7.2	6.7	6.8	7.3	
103	6.6	6.6	8.7					8.3	6.8	7.8	6.6	5.3	7.8					6.5	6.0			7.0	5.1	6.8	4.0	
104	6.4	7.0	7.5	4.5			5.7	8.2	7.6	7.9	6.8	*	8.7					6.4	5.7			12.2	6.2	7.4	7.0	
105	8.3	6.6	9.6					10.8	7.9	7.4	8.5							7.4	6.2			5.6	6.5	5.3	5.8	
106	7.8	6.6	5.3	4.2				8.6	8.1	8.5	7.5	6.7	5.4					10.8	7.9			9.0	6.0		5.4	
107	7.6	7.1	7.8	7.4				7.6	7.7	9.2	6.6							7.9	5.4			5.6	6.9	7.2	7.8	
108	7.2	7.6	6.9	8.1				8.1	7.6	*	6.8								6.1					3.7	7.5	
109	7.2	6.7	7.6	5.8				7.7	8.3	*	7.3								5.9					7.0	7.6	
110	8.1	6.6	7.0	6.3				7.6	7.2	*	9.1								6.8				5.5	5.6	5.9	8.8
	<u>SAMPLE SIZE</u>																									
101	57							5	2	1	13															
102	1212	823	66					162	152	87	118	21	17					427	477			43	75	161	93	
103	1521	1010	622					201	308	59	64	22	18					632	167			87	102	183	36	
104	952	1370	69	84			44	235	308	62	120	5	16					357	382			31	42	122	38	
105	1110	992	57					299	389	63	79							436	132			51	68	22	26	
106	774	959	113	31				208	211	47	71	17	21					475	203			67	54		65	
107	1076	1058	165	115				247	437	24	38							286	208			12	27	104	44	
108	1106	951	68	62				258	420	6	15								162					15	34	
109	856	644	95	145				262	266	9	18								195					45	40	
110	692	867	132	178				231	265	8	17								223				67	69	122	101

TABLE 6.2. Continued

	WEEKDAY														WEEKEND										
	DAY							NIGHT							DAY				NIGHT						
	DRY		WET		ICE		FOG	DRY		WET		ICE		FOG		DRY		WET		ICE		FOG			
	N	S	N	S	N	S	N	S	N	S	N	S	N	S	N	S	N	S	N	S	N	S	N	S	
	<u>MEAN SPEED</u>																								
201		28	38	42	40	39		40	42						41	43			36						
202	43	43	42	39	41	42		44	44	41	40				44	42	45	44			42	42			
203	40	40			40	40		41	43	*	41				40	44					40	43			
204	46	46	43	41	46	42		48	47	47	43				47	46	43	44			46	46			
205	51	47	48	41	48	46		52	50						53	50	44				48	50			
206	49	49			47	47		49	49						52	52			44						
207	48	51	51	49				52	52	*	*				50	53	50	50			51	51			
208	51	49						48	51				50	51	51	50	47	48			47	47			
209	49	51						47	52						50	52	50	52			50	50			
210	49	48						49	49	*	*				49	48	51	48			46	44			
211	53	51						53	53	*	50		*	*	54	51	53	46			54	53			
	<u>STANDARD DEVIATION</u>																								
201		6.6	6.0	4.3	3.7	4.1		6.5	5.6						4.6	3.8		4.3							
202	5.1	5.7	5.1	5.4	4.4	4.0		6.1	7.4	4.9	5.2				4.7	4.6	3.7	4.1			6.8	7.3			
203	7.2	7.6			5.7	5.1	10.5	5.9	*	7.4					7.4	6.7					5.6	5.3			
204	6.4	6.0	5.6	5.3	4.3	5.0	6.5	7.5	8.4	7.1					5.2	5.8	4.4	3.5			4.7	6.2			
205	5.6	6.7	5.5	5.7	5.1	4.9	7.9	7.5							5.6	4.8	6.2				5.8	6.3			
206	6.5	7.4			5.9	5.2	7.5	7.1							6.7	6.7		5.6							
207	7.1	7.9	7.5	7.0			7.1	7.5	*	*					6.0	6.5	5.0	4.6			5.4	7.2			
208	6.8	7.0					8.2	8.9					10.7	8.4	5.9	8.3	4.1	5.2			7.2	11.5			
209	6.6	5.5					10.4	5.8							6.7	6.2	5.6	4.9			4.8	5.3			
210	6.0	6.2					10.0	8.1	*	*					6.7	8.0	4.2	3.7			8.7	9.2			
211	6.4	5.6					7.6	9.7	*	5.5			*	*	6.0	7.2	5.4	5.0			8.0	6.9			
	<u>SAMPLE SIZE</u>																								
201		110	67	71	80	80		67	135						191	156		174							
202	829	876	59	89	73	68		233	295	34	112				247	220	47	51			66	47			
203	919	855			125	98		233	276	6	19				1313	403					113	65			
204	527	606	78	59	42	65		240	331	22	18				238	165	54	39			47	44			
205	532	523	24	28	48	53		168	289						110	741	54				34	40			
206	534	558			50	40		204	255						171	176		60							
207	891	579	16	15				143	205	4	3				239	237	51	38			66	80			
208	507	619						90	165				10	18	268	296	51	41			101	55			
209	412	563						90	100						300	328	98	80			110	90			
210	387	537						78	78	1	5				275	235	42	42			130	105			
211	306	611						53	43	4	20			2	1	221	176	42	27			128	117		

TABLE 6.2. Continued

	WEEKDAY										WEEKEND													
	DAY					NIGHT					DAY					NIGHT								
	DRY		WET		ICE	FOG	DRY		WET		ICE	FOG	DRY		WET		ICE	FOG	DRY		WET		ICE	FOG
	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W
	<u>MEAN SPEED</u>																							
301	37	36	37	34			38	36	39	35			37	37	37	35					40	42		
302	39	40	38	38	40		40	41	40	40			41	42	37	41			38	38	43	44	36	40
303	46	45	43	44			47	47	47	*			45	43	*	45					49	48	42	41
304	47	46	45	43			47	47	*	*			46	46	44	45	*	*			46	44	44	42
305	50	49	49	48			53	52	*	*			49	43	47	46	*	*			49	48	43	43
306	49	50	43	41			49	51	*	*			49	47	45	47	39	43			51	52	42	41
307	54	54	49	49			55	55	*				55	56	50	49	50	*			55	53	44	41
	<u>STANDARD DEVIATION</u>																							
301	5.0	4.8	6.0	6.4			5.5	5.3	5.9	5.8			5.7	4.6	4.8	3.6					6.0	7.2		
302	8.2	6.3	5.9	7.0	6.6		5.6	6.0	5.5	5.9			7.7	6.0	4.7	5.1			4.2	4.0	7.7	7.0	5.1	5.8
303	6.8	6.7	5.5	6.7			6.9	6.6	4.9	*			4.8	5.9	*	6.4					8.4	7.1	7.2	4.2
304	6.1	5.9	6.3	5.7			6.9	5.8	*	*			5.8	6.1	5.3	6.5	*	*			6.1	5.7	6.6	5.4
305	7.0	7.2	8.1	7.6			8.4	7.9	*	*			3.5	6.6	6.3	5.7	*	*			6.8	7.1	4.1	6.9
306	6.2	7.2	4.6	7.6			6.7	6.2	*	*			4.4	6.6	6.0	7.4	4.1	3.2			6.9	5.4	4.8	5.6
307	6.5	7.3	6.2	5.4			7.6	7.0	*				6.8	7.2	7.5	6.6	6.9	*			7.5	7.6	5.0	8.1
	<u>SAMPLE SIZE</u>																							
301	1184	982	331	436			651	368	114	114			173	329	40	298					92	76		
302	468	457	549	371	45		358	207	86	87			142	553	98	61			42	56	89	99	55	24
303	396	372	264	201			132	106	15	5			627	665	6	16					32	39	72	44
304	203	238	203	206			108	110	1	2			736	106	23	49	6	2			62	78	21	17
305	479	467	53	66			115	73	3	2			45	541	69	84	7	9			70	80	36	22
306	434	413	21	40			76	50	1	2			63	76	76	61	18	12			61	69	15	22
307	389	377	34	72			78	62	2				111	134	89	62	14	8			55	70	20	27

TABLE 6.2. Continued

	WEEKDAY										WEEKEND											
	DAY					NIGHT					DAY				NIGHT							
	DRY		WET		ICE	FOG	DRY		WET		ICE	FOG	DRY	WET	ICE	FOG	DRY	WET	ICE	FOG		
	E	W	E	W	E W	E W	E	W	E	W	E W	E	W	E W	E W	E	W	E	W	E W	E W	
	<u>MEAN SPEED</u>																					
401	36	37	39	36			39	42	35	37			40	43			38	35				
402	43	45	43	46			47	48					45	48			50	45	44	44		
403	46	41	43	43			50	48					50	46			48	44	41	40		
404	45	44	45	46			49	48	41	43			46	48			46	49				
405	45	44	47	47			46	50	41	39			47	46			47	44				
406	34	39																				
407	51	53					54	48	44	44			52	50			47	47				
408	52	51	51	55			50	51	45	45	45	45	52	52			54	55				
409	54	54					51	54	49	47	44	38	54	53			54	50				
	<u>STANDARD DEVIATION</u>																					
401	5.0	4.9	5.0	5.6			6.3	5.7	4.5	4.8			5.8	5.6			5.7	6.4				
402	5.3	4.9	7.1	4.5			6.3	6.5					6.0	7.9	4.8		8.8	6.0	6.0	5.5		
403	6.4	7.6	5.7	4.9			7.2	7.2					5.9	5.8			5.9	7.6	6.5	4.2		
404	6.1	6.3	4.2	5.5			8.1	6.1	8.4	6.6			6.0	6.1			7.5	6.2				
405	7.1	6.5	6.1	4.7			7.5	6.9	5.2	4.9			6.0	5.6			7.4	6.7				
406	4.9	4.6																				
407	6.2	7.5					7.7	8.8	5.1	7.2			6.6	7.5			7.8	8.0				
408	8.4	6.8	6.8	6.0			14.0	13.1	6.4	6.5	6.8	6.7	8.3	7.8			8.0	8.0				
409	8.0	6.6					8.7	9.4	7.0	8.5	13.8	9.7	7.9	7.6			7.9	9.2				
	<u>SAMPLE SIZE</u>																					
401	726	888	58	218			124	138	143	120			229	172			55	82				
402	509	614	113	48			159	163					193	58	539		33	49	62	84		
403	720	633	226	279			119	163					206	157			24	29	83	79		
404	1118	687	98	118			84	128	138	121			779	210			31	79				
405	593	471	69	54			88	110	78	104			198	298			72	100				
406	36	70																				
407	486	526					56	69	54	54			190	163			47	78				
408	550	629	22	21			23	39	45	45	18	44	176	143			14	19				
409	290	249					44	52	28	28	38	43	245	277			48	53				

TABLE 6.2. Continued

	WEEKDAY												WEEKEND											
	DAY						NIGHT						DAY						NIGHT					
	DRY		WET		ICE		FOG		DRY		WET		ICE		FOG		DRY		WET		ICE		FOG	
	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W
	<u>MEAN SPEED</u>																							
501	41	40	36	35				39	39	*	*			39	38	38	37	27	29			38	37	
502	40	41	37	38	32	33		41	41	38	36			42	42	40	40	33	32			48	47	
503	38	37	36	33	36	36		39	37	32	29			38	37							*	41	
504	35	35	29	29				35	37	*	*			33	34	31	27	23	23			33	33	
505	38	39	36	35	28	28		39	37	39	31			35	38	30	*	*	29			43	39	
506																								
507	30	30	29	28		*		30	33	30	30			31	29							*	*	
508	36	33	*	*	*	*		*	*	*	*			29	*							*	*	
509	*	36	*	*				*	*	*	*			30	35							*	*	
	<u>STANDARD DEVIATION</u>																							
501	4.5	5.8	5.6	4.6				5.2	6.2	*	*			5.4	4.9	5.0	5.6	4.9	6.3			6.8	5.4	
502	5.0	6.5	7.2	6.3	5.9	6.3		6.6	6.2	5.9	3.5			6.7	7.2	5.6	7.5	4.3	4.5			10.4	6.1	
503	7.1	6.8	5.8	5.7	8.6	4.2		6.7	4.4	3.7	4.7			5.2	4.8							*	6.4	
504	5.4	4.3	5.8	5.4				5.9	7.0	*	*			5.2	5.0	3.6	3.3	4.4	4.4			6.0	4.6	
505	6.4	6.7	6.9	6.2	4.6	5.6		7.3	6.1	4.8	8.1			7.1	6.9	6.3	*	*	5.4			8.4	7.6	
506																								
507	6.7	6.7	3.8	4.7		*		7.0	5.1	5.2	4.1			6.1	7.6							*	*	
508	4.2	4.4	*	*	*	*		*	*	*	*			5.0	*							*	*	
509	*	9.5	*	*				*	*	*	*			6.7	5.3							*	*	
	<u>SAMPLE SIZE</u>																							
501	256	169	130	141				207	117	8	2			161	209	61	59	10	29			21	13	
502	151	88	85	99	30	34		72	49	36	17			99	178	22	22	34	72			18	21	
503	119	91	87	90	16	15		86	70	20	15			93	119							9	12	
504	107	55	32	40				74	41	8	6			99	137	29	42	18	50			26	23	
505	126	98	12	14	14	15		68	55	20	11			113	124	13	3	6	16			12	15	
506																								
507	39	58	23	24		3		11	16	13	10			44	49							1	1	
508	17	14	1	3	4	4		8	2	2	3			13	9							2	2	
509	7	13	9	5				3	2	2	3			18	27							1	2	

TABLE 6.2. Continued


	WEEKDAY												WEEKEND											
	DAY						NIGHT						DAY				NIGHT							
	DRY		WET		ICE		FOG		DRY		WET		ICE		FOG		DRY		WET		ICE		FOG	
	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W	E	W
	<u>MEAN SPEED</u>																							
601	38	32																						
602	41	42	41	42	38	43	40	45	43	46	42	43					43	44			43	47		
603	41	43			30	33			45	44	44	40	*	*			45	46			46	46	*	*
604	45	45	42	42					50	46	46	43					48	47			47	44	*	45
605	48	47	44	44	48	44			51	50	47	45					48	47			53	50		51
606	49	49	49	42					52	52	52	*					49	49			52	49	*	*
607	50	50	51	48	46	46			54	54	51	50					54	54						
608	46	48	47	45	45	43	46	52	51	51	46	47					51	49			42	47		
609	50	47	48	47			41	44	56	52	48	51									54	50		
	<u>STANDARD DEVIATION</u>																							
601	4.3	6.0																						
602	6.0	6.7	5.6	6.5	4.6	4.0	4.4	5.1	5.4	6.8	5.4	4.1					5.5	6.4			7.0	6.2		
603	8.0	6.7			5.9	6.3			8.5	6.6	6.0	5.9	*	*			7.1	6.4			7.8	6.6	*	*
604	6.1	7.1	6.2	8.0					8.3	7.8	4.6	4.8					6.9	6.2			3.8	5.4	*	5.9
605	6.8	5.7	7.2	7.7	5.9	4.6			7.9	7.2	8.6	4.6					6.5	6.4			9.0	6.7		12.9
606	7.4	7.1	6.8	7.3					7.6	6.5	7.4	*					8.3	7.1			9.8	7.2	*	*
607	6.8	7.2	6.3	5.9	4.8	3.9			7.5	7.5	6.8	6.2					6.0	5.4						
608	7.1	7.9	6.7	8.2	6.1	5.9	6.0	6.6	7.6	7.8	5.5	9.2					5.9	6.1			9.9	7.7		
609	7.8	8.3	6.0	7.7			10.1	6.4	8.9	7.6	6.3	6.5									7.7	10.1		
	<u>SAMPLE SIZE</u>																							
601	109	75																						
602	619	885	169	270	50	30	37	20	100	153	97	184					127	55			47	64		
603	833	707			50	19			95	159	34	56	6	9			199	133			36	87	7	9
604	663	527	53	168					91	206	26	80					168	148			14	17	5	11
605	386	681	429	234	87	28			107	180	33	31					240	123			24	43		29
606	545	525	98	160					95	133	10	3					211	110			25	58	2	5
607	477	455	55	103	38	59			61	73	39	68					91	82						
608	432	447	35	71	29	39	18	13	57	83	39	66					52	56			32	46		
609	403	359	99	125			18	15	42	54	14	35									30	49		

TABLE 6.2. Continued

	WEEKDAY										WEEKEND													
	DAY					NIGHT					DAY					NIGHT								
	DRY		WET		ICE	FOG	DRY		WET		ICE	FOG	DRY		WET		ICE	FOG	DRY		WET		ICE	FOG
	E	W	E	W	E W	EW	E	W	E	W	E W	EW	E	W	E	W	E W	EW	E	W	E	W	E W	EW
											<u>MEAN SPEED</u>													
701	40	37	36	35			41	38	*	*			40	38		33		39	37	42	39			
702	39	40	37	40			41	41	38	39			38	40	34	37		36	38	43	41			
703	42	42	41	42			40	42	38	37			42	43	37	37		47	40	42	40	*	40	
704	39	43	41	43			43	47	*	*			42	42				*		41	42	46	*	
705	40	42	41	40			41	46	*	45			40	41	42	51		36	44	42	46		*	*
706	50	48	49	46			47	48	*	*			48	46	49	*		*	*	52	50	*	48	
707	45	46	32	*			47	46	33	31			40	42				*	*			*	*	
											<u>STANDARD DEVIATION</u>													
701	4.9	5.6	4.5	5.6			5.7	5.8	*	*			4.8	5.1		5.5		4.8	4.7	7.7	5.5			
702	5.6	5.4	4.5	5.1			6.1	6.1	8.7	4.2			5.5	5.2	6.5	5.0		5.6	5.8	5.8	5.3			
703	7.6	6.8	4.9	3.7			9.8	11.3	5.3	6.0			8.4	7.1	6.8	7.9		7.6	8.0	12.1	9.9	*	5.6	
704	6.9	6.8	7.5	6.5			8.0	6.8	*	*			5.9	6.3				*		7.4	7.4	6.9	*	
705	11.2	8.8	8.6	6.8			10.7	8.3	*	8.0			8.3	7.6	9.1	6.2		8.4	8.2	9.0	8.8		*	*
706	8.2	7.0	7.2	8.1			7.8	7.1	*	*			6.3	6.3	3.7	*		*	*	7.4	9.0	*	5.8	
707	8.0	7.9	5.0	*			7.2	6.2	8.1	12.1			5.6	7.3				*	*			*	*	
											<u>SAMPLE SIZE</u>													
701	1610	1549	58	165			242	433	6	5			160	184		14		120	85	38	52			
702	805	1100	518	332			312	399	47	49			317	286	101	64		65	46	16	34			
703	607	525	50	34			77	119	16	18			247	271	25	25		19	17	32	34	7	18	
704	517	541	137	72			61	94	3	4			138	171				6		30	40	12	5	
705	359	389	48	11			64	134	5	12			118	114	24	12		30	15	11	21		4	5
706	245	290	36	11			73	127	2	7			99	89	12	8			1	10	17		4	24
707	155	238	22	4			60	74	11	15			196	97				1	2				2	2

* Samples sizes are 9 or less.

Figure 6.2 Daytime (0600-1900) Mean Speed and Standard Deviation Versus Time



7. REFERENCES

- [1] Solomon, David, (1964) "Accidents on Main Rural Highways Related to Speed, Driver, and Vehicle," Bureau of Public Roads, July, 44pp.
- [2] Heimbach, C. L., (1968) "Developing Traffic Indices for the Detection of High Accident Potential Highways in North Carolina," Project ERD-110-67-6 - Part 1, January, 95pp.
- [3] White, S. B., Jr. and Nelson, A. C., Jr., (1970) "Some Effects of Measurement Errors in Estimating Involvement Rate as a Function of Deviation from Mean Traffic Speed," Accepted for publication in June issue of Journal of Safety Research.
- [4] Gazis, D. C. and Foote, R. S., (1969) "Calibration and Correction of Magnetic Loop Detectors," IBM Research, RC 2520 (#12140), Computer Applications, June 25, 1969, 9pp.
- [5] Daniel, C., et al, (1969) "Fitting Equations to Industrial Data with the Aid of a Computer," Unpublished book.
- [6] LaMotte, L. R. and Hocking, R. R., (1970) "Computational Efficiency in the Selection of Regression Variables," Technometrics, Vol. 12, No. 1, February, 1970, pp. 83-93.
- [7] Mallows, C. L., (1966) "Choosing a Subset Regression," Presented at the Joint Statistical Meeting, Los Angeles, California.
- [8] RTI and IRPS Staff Members, (1969) "Speed and Accidents - Phase I," Interim Report prepared for the National Highway Safety Bureau under Contract Number FH-11-6965, July 11, 1969, 138pp.

Appendix A

RADAR SPEED SAMPLING

A. RADAR DATA COLLECTION

This section deals with the problem areas and the general conduction of the radar collection effort as performed by the Institute for Research in Public Safety under conditions of the present study. The radar collection was undertaken to supply quantitative speed data which might be used in constructing a "Traffic Flow Profile". This profile is a data-set of the characteristics of speed, volume, types of vehicles, and groupings of vehicles for a given segment of highway during a specified time interval under specified weather conditions. Additionally, radar operations were utilized to supply post-accident information with regard to speed and density for a given time and date in order to facilitate the reconstruction of the conditions which existed at the time of the accident.

A.1 Traffic Flow Profile

This section discusses the process of development of the profile; it covers description, procedures, problem areas, and evaluation of effectiveness of the radar collection process itself.

Sample Size and Location

It was believed that a minimum of 400 accidents would be required for confident statistical predictions. An analysis of the accidents of Monroe County for 1966 and 1967 showed that it would be desirable to use all accidents on state highways within the county, plus those accidents which occurred on county highways on which vehicles would normally travel 40 mph or faster. The 40 mph determination is based upon the original RFP stipulation that the study should be pertinent to typical federal and state highways.

The state highways were arbitrarily divided into one-mile segments. Segments of this size were chosen initially because there was no way of knowing whether the profile of any one-mile segment would be sufficiently like that of the adjoining segment. The use of larger segments could not be made with confidence until readings

of smaller segments had been made. It was also estimated that a fifteen minute reading would be sufficient to establish the characteristics for any given hour (25 percent sample size).

A.2 Post-Accident Radar

This section directs itself to the process of development of the post-accident radar collection system.

Objectives

While the purpose of the Traffic Flow Profile was to establish a data base by which the speed estimates of the accident-involved vehicles might be compared, the purpose of the Post-Accident Radar operation was to refine this established base.

Not all the roadways under study were subjected to the profile activity; therefore, for those roads which were not under study, the post-accident activity formed the only normal-flow data available. Actual accident conditions were duplicated as much as was possible in the follow-up surveys. Platooning characteristics were also noted, so that a complete re-representation might be obtained.

Description

The purpose of post-accident radar collection was to reproduce, or simulate as closely as possible, the conditions surrounding the time of the accident. Post-accident radar data was collected for conditions as similar as possible to those existing at the time of the accident.

Since statistical significance is dependent on adequate samples, a minimum of 200 vehicles were recorded, with at least 50 vehicles traveling in the same direction(s) as the accident-involved vehicles. At least two visits to each accident site were required, to average out any unusual conditions influencing traffic on the collection day. Volume was read in both directions whenever possible.

When the accidents occurred during a low-volume time, adjustments in the collection methodology became necessary. The times for site visitation were adjusted to move towards higher volume-times, so that the 200 vehicles versus 2 hours criteria

could be met. All other parameters were kept constant, particularly, the day-night dichotomy. When the environmental conditions were difficult to duplicate (rain, ice or snow), the day of week was varied as necessary to match the accident's weather condition.

Vehicles were recorded as to type, direction of travel and speed, with a distinction being made between vehicles in a platoon and those traveling in a free flow condition.

Appendix B

ACCIDENT INVESTIGATION PROCEDURES

PHASE I AND PHASE II

B. ACCIDENT INVESTIGATION

B.1 Objectives and Format

Two different methodologies characterized the accident investigation activity. During Phase I, the accident investigation was conducted to estimate the speed(s) of accident-involved vehicle(s) in all accidents occurring in the state highways within Monroe County, as well as those occurring on county highways on which the normal rate of speed was 40 mph or greater. Factors from which the speed of the accident-involved vehicles could be determined were gathered by trained investigators who went to the scene as soon as possible after the accident had occurred.

In Phase II, follow-up investigations were made only of those accidents occurring on State Route 37. I.U. Institute personnel addressed their inquiries to the investigation officer and made use of his report and the data which were supplied by the computer-sensor system.

B.2 Accident Investigation: Phase I

The Phase I activity covered the period December 7, 1968, through July 31, 1969, and resulted in 250 accident reports. Following is a description of the activity in detail.

Procedures

The equipment used by the investigators was designed to assure their safety, as well as to expedite the gathering of the required data.

The investigators each had prior traffic accident investigation experience. Their experience was supplemented by training given by members of the Department of Forensic Studies (formerly the Department of Police Administration), Indiana University, covering such areas as the recognition, collection and preservation of physical evidence, scale drawing, the use of the traffic template, and skid mark measurements.

The definition of accidents to be investigated was based on Baker's "Traffic Accident Investigation Manual for Police" (page 10, paragraph 11.130, Motor-Vehicle-Accident). This defines a motor vehicle accident as any event that results in unintended injury or property damage attributable directly or indirectly to the motion of a motor vehicle or its load. For the purpose of the present study, the definition was expanded to include any situation in which a vehicle has deviated unintentionally from the normal traffic pattern.

To facilitate immediate notification of an accident, a prime investigator and a stand-by investigator were available 24 hours a day. In addition, third and fourth backup investigators were available when the volume of accidents was greater than that which could be handled by the first two. These situations generally occurred when ice and snow were present or when there was an extremely large volume of traffic.

Notification was accomplished by a special phone system that enabled the police agencies to call a single phone number at any time of the day or night. During the day, the phone was answered by the investigators in the office; during nights and weekends, it was answered by the Indiana University Safety Division. When the investigator was not on duty at the office, the I.U. Safety Division contacted him.

The investigators' cars were equipped with two-way radios which enabled them to be contacted directly through the Sheriff's Department. In addition, the investigators monitored the sheriff's radio on the fixed location receivers.

The investigation was conducted at the scene to permit the investigators to collect transitory or short term evidence, which included photographs of damaged vehicles, skid marks and other pertinent information as well as statements from involved parties and witnesses. Follow-up interviews were sometimes necessary when the information could not be obtained at the scene.

Two mechanical engineers were assigned to the investigators to assist in developing the accident data.

Reporting

The investigators engaged in two types of reporting. The first concerned their activities and the second concerned events. Activity reporting consisted of a daily report submitted by each investigator which outlined his activities during the previous 24-hour period.

Event reporting was accomplished by means of a series of forms developed for use by the investigators, both at the scene and for final data reporting. These forms are: (1) dispatch form, (2) letter of introduction, (3) field data collection guide, (4) interview guide, (5) accident summary, (6) conclusion sheet, and (7) data sheets.

The prime emphasis in the reporting process was to secure information on skid marks, vehicle damage and faults, road configuration, weather conditions, and the driver's condition. Subjective information was secured through statements from involved persons concerning his actions and the actions of other vehicles. A copy of one of the accident reports is included in this report as Appendix E.

Review

When the investigator had concluded the data gathering process and had prepared the report, it was submitted for review. The investigator was expected to draw conclusions regarding the elements contributing to the accident. The function of the review board was first to determine the consistency of the reports and secondly to independently examine the accident reports and supporting data, without reference to conclusions of investigators or other reviewers, and then form conclusions about the speed and contributing elements.

Engineering Analysis

As mentioned previously the engineers worked jointly with the accident investigators in the determinations of speeds of vehicles. To accomplish this, it was necessary to use formulas and concepts which had been developed in the field of traffic and vehicle engineering for reconstruction of the sequence of events and assignment of velocities within the sequence.

Approximately three months were utilized for the purpose of literature search, derivation of appropriate formulas, and documentation.

B.3 Accident Investigation: Phase II

Phase II transferred the investigation emphasis from the on-site scheme used in Phase I to a computer-sensor system follow-up approach. A late July meeting of Research Triangle Institute, National Highway Safety Bureau, and Institute for Research in Public Safety (IRPS) representatives reviewed the capability of the computer-sensor system to estimate the speeds of accident-involved vehicles. It was decided to reduce the accident investigation function to a follow-up approach and make use of the computer-sensor system to estimate speeds. With additional road sensors, and police officer accident investigation training, the accident study could continue without the expensive services of a project investigation team. Instead, IRPS personnel would address their inquiries to the investigation officer, his report, and use the data supplied by the computer-sensor system. This restricted the activity to within the boundaries defined by the sensor sites on State Road 37. This activity, which continued from August 1, 1969 through December 31, 1969, produced 48 accident reports. Following is a description of the activity in detail.

Preliminary Activity

As a preliminary to the full implementation of Phase II of the research effort, a five-session training seminar in accident investigation was held by I.U. Institute personnel for the deputy investigators of the Monroe County Sheriff's Department. Subjects of study included traffic and hazard control, scene preservation, photography, driver and witness interviewing, and speed estimation. Indiana State Police records personnel conducted a session on completing the accident report form. One two-hour session was devoted to skid tests and measurements, with each attendee receiving instructions in the use of the Northwestern Traffic Template.

The computer-sensor system was expanded from 8 to 14 sensor-sites in order that the data base for speed comparisons could be increased, along with the probability of accident-involved vehicle identification.

Accident Notification and/or Accident Selection

Before an accident became the subject of a Phase II report, several preliminary qualifications had to be satisfied. Institute personnel had daily contact with all three law enforcement agencies in the county. Each previous 24-hour radio-dispatch log was reviewed for traffic investigation communications, with the approximate locations being noted. All State Route 37 accidents were assigned an accident report number. These files were reported to project management and were held until some decision could be made concerning the accident's Phase II usability.

Each week, a research person of the IRPS visited the three agencies and obtained copies of all the accident reports which had been received since the last survey was made. A record of the resulting reports, as well as the reports themselves, was maintained by the Institute. This file was examined concerning the report numbers assigned from the daily contact.

Each report was examined as to whether the accident location fell within the confines of the computer-sensor system. If it did, a printout of vehicle speeds and lengths at all relevant computer-sensor system locations was obtained. At the same time, a statement of time, day of week, weather conditions and location was given to the field radar operator for post-accident radar scheduling for the accident site.

Computer-Sensor System Printout Analysis

When an accident report for a usable accident was received, the time of the accident was noted and checked for consistency with the time of notification and the time of arrival at accident scene. The times were then compared with the entries made in the dispatcher's logbook and with any statements which were available from witnesses.

The police report provided the precise location at which the accident occurred, and from this the loop pairs bracketing the accident site were identified. Data were obtained from the computer printout for these two pairs of sensors for a period of one-half hour prior to the accident to one-half hour after the accident. The computer printout of data for both loops was placed juxtaposition on a page to allow a more

thorough examination of the data. This matching was generally accomplished by picking a distinctive occurrence; i.e., a large semi-truck or large headway passing the first loop, then aligning it with the same sequential event at the second loop.

Once this was done, the traffic was examined at the first and second loops to identify any changes in the traffic flow. Of particular interest were large time gaps or cessations of traffic at the second loop, while traffic at the first loop continued in a normal manner. This was sometimes evidenced by a gap in the flow followed by a large platoon which was not present in the traffic at the prior loop.

Depending upon the distance of the accident site from either the first or second sensor, a large reduction in vehicle speeds is often observed, indicating a traffic slowdown and/or eventual stoppage behind the accident at the first loop.

The reports of witnesses often are quite helpful in locating the accident-involved vehicle (AIV) within the traffic flow. The characteristics of the AIV as listed on the police report (make, year, type, estimated prior speed) were also of great value, especially if any of the vehicles were unusually small or large.

Any vehicle which was suspected to be an AIV was then marked at the first loop. Using the speed at this loop and assuming constant speed was maintained, the time of arrival at the second loop could then be predicted. The vehicle which thus was identified at the second loop was then checked, using the average of the speeds from first and second sensors to validate elapsed time between loops. The vehicle length and position within the traffic pattern (headways in front of and behind vehicle, length of adjacent vehicles) were examined for further correlation and verification.

All vehicles, including suspected AIV's, could be traced through the sensor system in this way. Normally, the AIV was seen to disappear from the system between the two loops. Once such a vehicle(s) was found, it was possible to project the time of arrival at the accident site by using the speed at the first loop and the distance from that loop to the accident site. Using this time and the average speed

for the flow of the traffic in the opposing direction, an estimate could be made for the time of arrival at the first loop for any AIV(s) traveling in the opposite direction of the first vehicle(s) identified.

All vehicles crossing the first loop for the opposing direction within an interval around this estimated time were examined. The AIV from this opposing direction also failed to cross the second loop as expected. The suspected AIV in this direction was then verified using the police report, witness statements, and physical characteristics of the vehicle.

Once the AIV(s) had been identified by means of the sensor system data, speed estimates were made for these vehicles to show both speed prior to accident and speed at impact.

The estimate of speed prior to the accident was made using the following data and considerations: (1) depending upon the proximity of the accident site to the sensor location, the sensor data was considered, (2) the prior speeds as given by the police report, when available, were considered valid within ± 10 percent, (3) witness statements were used to strengthen the estimate if they correlated with the other data, (4) the characteristics of the roadway - condition, type, grade, speed limit, etc., and (5) weather and general traffic conditions.

The impact speed was derived in basically the same manner, with a few additional considerations such as skid marks, rest position relative to impact, statements of witnesses, and vehicle characteristics. A sample Phase II accident report appears in Appendix E.

Fifteen-Minute Summary

For the Phase II accidents, the standard deviation and mean of the speeds and headways for the fifteen minutes preceeding the accident were retrieved from the raw data tape. The vehicle count and the eighty-fifth percentile (a common speed limit determination parameter) were also included.

Appendix C

COMPUTER-SENSOR SYSTEM

C. THE COMPUTER-SENSOR SYSTEM

One of the difficulties with the traffic measuring devices in common use is the influence the device exerts on the very thing it is measuring. Obtrusive methods such as radar and speed tapes tend to interject bias into the data because of their visibility to the driver.

As an integral portion of the present study, the Institute for Research in Public Safety undertook the development of an unobtrusive traffic measuring system in which loop detectors were connected via telephone lines to a process control computer.

Eight locations along State Route 37, North and South of the City of Bloomington, Indiana, were monitored 24 hours a day during Phase I of the study. This number was expanded to fourteen during Phase II.

The unobtrusive instrumentation at each site relayed two signals which were interpreted by the IBM 1800 computer to yield the vehicle's speed, length, location, lane of travel, direction, headway (the time differential between the preceding vehicle and the vehicle being monitored), and time of transit.

One of the chief attributes of the computer-sensor system is its ability to collect, array, and store data without outside intervention. No human judgment (or error) became a factor in the data assimilated by the system. Other than the weekly calibration and a replacement of magnetic tape on a five day cycle, no personnel are involved in the system operation.

C.1 The Computer

The computer system developed for the present project has as its core an IBM 1800 system. An IBM traffic control system program was modified by project personnel to the special needs called for when measuring vehicle velocities data. The requirements of the project contemplated the use of the computer as a portion of an information system which would provide data for decision-making purposes.

The decision-making process contemplated in these projects was more analytical in nature; however, the system could also be adapted for tactical decision-making.

Hardware

During Phase I, the IBM 1800 system was composed of the following components:

- (1) 1802 Central Processing Unit (16K, 4mics.)
- (2) 2401 Magnetic Tape Unit
- (3) 1442 Card Read Punch
- (4) 1810 Disk Storage (250,000 words)
- (5) 1826 Data Adaptor
- (6) 1816 Printer Keyboard
- (7) 1802 Process Controller.

Twelve interrupt levels are necessary for a minimal system. The system also has a 1053 character printer which is used for data retrieval, while the other printer (1816) maintains a printed record of system status. In order to receive the vehicle information from the highway, four digital input strips with sixteen points each are mounted in the computer interfacing.

System Software

The basic system software used in the system design is IBM's 1800 O.S. Time Sharing Executive (TSX), Version 3, Modification Level 7. Through a series of programmed interrupts, queued programs and non-process programs, as well as optimizing alterations in the systems director, the facility has been adapted to the specific requirements of traffic study. Non-process programs can be run during low traffic volume periods without disturbing data collection.

Program PILOP, an incore subroutine, scans the digital input points every 5 milliseconds to check the status of each vehicle detector. A shift in voltage caused by a vehicle passing over a magnetic loop detector will be recorded along with the time as indicated on a 30.000 second clock. This, and the return to normalcy which accompanies the passage of the vehicle, are recorded for two wire

loops, as both are necessary to calculate the vehicle's velocity, length, direction, headway and time of passage. PILOP senses these times, and stores them in the appropriate buffer in INSKEL COMMON.

Program IR001, an interrupt core load, checks the INSKEL COMMON buffers for each loop set and dumps any full buffers to the appropriate disk files. Two 25 vehicle buffers are allotted for each loop set, so that one may be storing data while the other is being written to disk. If IR001 senses that a disk file is full, it queues up PC002.

Program PC002, a queued program, checks the disk files and dumps the full files to magnetic tape. The disk files are then reset, and the magnetic tape is checked to see if it is almost full. In this fashion, the system monitors traffic 24 hours a day without operator intervention.

Many non-process operations may be conducted utilizing the collected data, and other computer analysis functions may be performed while the system is monitoring traffic. A series of non-process programs have been developed to allow the users to care for the collection activity while engaged in other activity. Many of these programs provide for the maintenance of the computer-sensor system files and its calibration. The time-sharing capability of the IBM 1800 TSX provides for seemingly coincidental data collection and analysis activity.

Program NC003 establishes the disk files, initializes the tape and allows for parameter entry. When the loop sets are calibrated (by radar), adjustments in velocity and length are accomplished by means of modification in one of the conversion factors within the program which calculated these items from the four times provided by PILOP.

Programs NC004, NC005, and NC006 allow the operator to turn the loop sets on and off, and to enter the Data Input (Interface) time sense base, day of week, weather and special conditions. The traffic at a given site may be examined on a real time basis if desired.

Program NC007 writes all the disk files onto magnetic tape. In this fashion, the disk unit may continue to collect and store vehicle data for a period of three to four hours (depending on traffic density) before requiring a tape backup. During this time, previously completed tapes may be re-examined for retrieval of old data (Program NC012), analysis or any other task which may require the assistance of a magnetic tape unit.

Program NC011 replaces the tape removed by NC007. To regain the computer for any analysis requiring the tape unit, the NC007-NC011 sequence may be rerun as often as necessary, up until midnight when Program ENDDAY computes the daily totals and reinitializes the system with the new date.

From the signals received from each loop set, vehicle speed, length, direction and lane of travel are calculated. Also recorded is the time of day and the time between the vehicle in the set and the previous vehicle. In this manner, the system yields lane usage information as well as speed relationship data.

C.2 Sensor System and Interface Equipment

The sensor consists of an RCA Vehicle Detector Unit which is connected to a loop of wire placed into the roadway. The vehicle detector senses the presence of a vehicle in the loop and closes a relay in the detector amplifier. The relay is connected to a phone line which terminates in an interface system specially developed for this project by Indiana University Institute for Research in Public Safety personnel. The interface system interrogates the relay by means of an electrical signal and reports the relay state to the computer in digital input form.

By combining the sensors in groups of four, it is possible to monitor traffic in two directions and to determine the speed and length of each vehicle passing through the loop set. Inasmuch as the events are time related, traffic densities as well as information on traffic flow composition may also be determined.

Description of Loop Installation

At each site, four loop detectors are installed in the configuration shown in Figure C.1. The cuts are 1/8 inch wide, and originally 2 inches deep for the loop wires. The wire depth, and the loop dimensions have been subject to some minor variance in order to optimize response. After the cutting operation, the wire (19 strand, 14 gauge TW) is placed in the cuts, making three turns per loop, and all leads are brought out to the edge of the road. When the wire installation is completed, the cuts are filled with a quick-setting hydraulic cement.

At the edge of the roadway, each pair of loop wires is spliced to a pre-twisted shielded cable, which is buried up to a service pole.

The Service Pole

Mounted on each telephone pole is an equipment cabinet and an electric power meter. The cables from the loops come up the pole in a piece of conduit and into the equipment cabinet, where they terminate on a terminal strip. On this strip the loops are connected to the detector amplifiers and the detector output (relay closure) is connected to the telephone lines, which in turn run to the computer room of the Institute (Figure C.2). 115V service is provided to the pole by Public Service of Indiana for the operation of the Vehicle Detectors.

The Vehicle Detector

The RCA Multi-Pak Vehicle Detector was designed primarily as an intersection traffic control device. Its solid state circuitry detects a phase shift in the loop impedance whenever a metallic vehicle crosses the wire loops embedded in the roadway. Since each loop at the site requires its own circuitry and relay, the standard package contains a power supply and four detector modules, grouped together in a 4-Pak configuration.

To adapt the Ve-Det to the special usages demanded by the research activity, several modifications were required. The original relays were replaced by faster mercury wetted relays, and at some sites, the tuning board gain has been increased by changing two resistors. This may become necessary where the cuts are deep or

the roadway has steel reinforcing. At some installations, the loop inductance was so great as to require the addition of external capacitance (0.012 mf, in parallel with the loop) to achieve a tuning peak within the range of the Ve-Det's variable capacitance. Occasional tuning is required, as the loop sensitivity experiences minor fluctuations with time and weather.

The Computer Interface Circuit

An IBM 1800 Computer with digital voltage input has two input conditions:

<u>Voltage at input</u>	<u>Computer reads</u>
-1 to +30 volts	1
-6 to -30 volts	0
-1 to - 6 volts	indeterminant .

The Detector returns a -25 volts signal (sent to the site via one telephone wire) to the computer digital input point when no car is in the loop. When a vehicle enters the loops, the relay change at the Detector causes the digital input point to be connected to the computer ground (zero volts). With this information the computer is able to compute vehicle speed, length, number of vehicles per hour, and so forth.

The interface connections system used is of nominal cost (\$200) and replaces a system now in general use, which requires mechanical relays and costs in excess of \$2,500.

Sensor Sites: Phase I

Each sensor site has two loop "sets" - so called because a set of two wire loops is required in each lane to gather the necessary information. Two lanes are monitored at each site, and this configuration is named a loop "pair". During Phase I, sixteen loop sets were being monitored on North and South State Route 37, for a total of eight locations, i.e., two lanes of travel at eight spots. For reasons of programming, these sets are numbered from zero through fifteen. The additional sites created for Phase II will be discussed in the following section.

Loop sets 0-7 are located on State Route 37 South, with sets zero through three monitoring southbound traffic, and sets four through seven monitoring northbound traffic. The sequence of numbering is such that ascending numbers move away from Bloomington.

Pair 0-4 is located in a 45 mph zone, on a blacktop section of Highway 37. It is approximately 75 feet North of an intersection with a stop street. For southbound traffic, there is a negative slope of -5.2%. This is a main artery leading into Bloomington, and some rather high rush hour traffic may be experienced (rate of 900+/hour). Loop set zero monitors southbound traffic, and loop set four monitors northbound traffic.

Pair 1-5 is located in a 55 mph zone, enough South of the speed change from 45 mph to 55 mph to be unaffected by the former speed limit. The site is in the middle of a short straight stretch which acts as the connector for two curves in a general "S" configuration. The road is 22' blacktop, and the site is in a no passing zone. Set one monitors southbound; five monitors northbound.

Pair 2-6 is located in a 55 mph zone, in a 22' blacktop section of Highway 37. Traffic from the North has good visibility to the site, and its path is straight and effectively level. 130' South of the site, traffic experiences a gradual curve to the right. Set two monitors southbound traffic; six monitors northbound traffic.

Pair 3-7, the southernmost site, is located just beyond the bottom of a long hill, with good straight visibility in both directions. The road is 22' blacktop, and the speed limit is 55 mph. Set three monitors southbound and set seven monitors northbound traffic.

Loop sets eight through fifteen were installed on State Route 37 North, with sets of eight through eleven monitoring southbound traffic, and sets twelve through fifteen monitoring northbound traffic.

Pair 8-12 is located in a 65 mph zone, approximately 0.2 miles North of a flat curve with a speed limit of 55 mph. The geometry is such that speed would be

expected to have normalized to the 65 mph zone by the time northbound vehicles arrive at the site. Southbound vehicles have been in a 65 mph zone for over 15 miles. The road is concrete, 24' wide. Set eight monitors southbound traffic, and set twelve monitors northbound traffic.

Pair 9-13 is located at the northern end of the straight-away from Pair 8-12, in a long flat curve. The full expanse of the South straight-away is not fully visible at this site. The speed limit on this concrete, 24' wide portion of the roadway is 65 mph. Seven hundred feet to the North lies a small bridge on the same curve. Set nine monitors southbound traffic; set thirteen monitors northbound traffic.

Pair 10-14 borders the northern end of a long straight uphill section (for northbound traffic) which contains a passing zone for northbound traffic. It lies midway through a long curve which terminated in the hill section just mentioned. The road is 24' concrete, and the speed limit is 65 mph. Set ten monitors southbound traffic; set 14 monitors northbound traffic.

Pair 11-15 borders the northern end of a long level straight-away, and the southern end of a long level curve. The road is concrete, and the speed limit is 65 mph. Set eleven monitors southbound traffic and set fifteen monitors northbound traffic.


Roadway Diagrams - Sensor Sites: Phase I

Figure C.3 shows the location of the sensor sites on State Highway 37. Figures C.4 through C.11 show plan views of the roadway along Route 37 North and South which contain the above described sensor sites. Included in these sketches are vertical profiles and curvature information as indicated.


System Expansion: Phase II

In late July, 1969, a meeting of project officials, including those from the National Highway Safety Bureau, the Research Triangle Institute, and the Institute for Research in Public Safety, reviewed the system's capability as an instrument of traffic data collection. At that time, the system had a demonstrated capability of speed measurements to within +1.0 mph and length measurements to within +2.0 feet.


Top View of Cuts
in Roadway



Cross-sectional View
of Roadway



NOTE: At the southernmost location where the wires cross the roadway, there must be a minimum of 18' of clearance between the wires and the road.



- (A) Meter Trough and Meter.
- (B) 24" x 16" x 12" Equipment Cabinet, Supplied by I.U.
- (C) Grounding Stake, or Butt Ground at Bottom of Pole May be Used.

Figure C.3 Location of Sensor Sites on State Highway 37




Figure C.4 Plan View of Roadway Section for Site 0-4




Figure C.5 Plan View of Roadway Section for Site 1-5




Figure C.6 Plan View of Roadway Section for Site 2-6




Figure C.7 Plan View of Roadway Section for Site 3-7




Figure C.8 Plan View of Roadway Section for Site 8-12




Figure C.9 Plan View of Roadway Section for Site 9-13




Figure C.10 Plan View of Roadway Section for Site 10-14





Figure C.11 Plan View of Roadway Section for Site 11-15



Phase II called for post-accident follow-up and the use of the system as the accident data collection approach. To aid in this data collection and system evaluation, the system was expanded. Six additional sensor sites were located on State Route 37 North, with the computer software being rewritten to monitor these new sites. The installation and the computer software were completed November 4, 1969. These changes are discussed below.

Six loop pairs were added; five were placed in between Loops Pairs 8-12, and 9-13 and one (Set 20-26) was placed 0.2 miles South of 8-12. Sets 20 through 25 are monitoring southbound traffic, and Sets 26-31 are monitoring northbound traffic. (See diagrams at the end of this section for spacing and locations of these new sites.)

The same basic computer hardware which monitored 16 loop sets was utilized for the expanded system. The only addition came in the interfacing, with four digital input strips being utilized, instead of two. The 16K of core did prove to be sufficient after modification of the system software. Also, while the overall logic remained the same, interrupt levels and core allocations were reduced to accomodate the load levied on the system by the additional input. IBM-furnished TSX up-dates arrived out of sequence, causing some delay until the system could be built up under Version 3, Modification level 7, but the expanded system came on-line on November 4, 1969.

In order that the 1800 could monitor the almost twice as many loops as before, core work areas were preserved. Whereas in Phase I each loop set had two 50-vehicle in-core buffers to store vehicle data until it could be written to disk, in Phase II each was reassigned to two 25-vehicle buffers. Addresses, previously stored in core, in Phase II were calculated by program PILOP. Also, without requiring a rewiring operation, all unnecessary interrupt levels were stripped of their in-core work areas, saving 100 words for each of the four deleted levels. The retained interrupt levels were pared down to their absolute minimum necessary work areas. Some of these core-saving measures resulted in longer execution times, but the basic five millisecond interrupt was undisturbed. All fifty-six digital input points were still scanned every five milliseconds.

Roadway Diagrams - Added Sensor Sites: Phase II

Figure C.12 shows the location of the six additional sensor sites on Highway 37 North. The loop sets are numbered 20 through 31 inclusive. Figures C.13 through C.18 show plan views of the roadway sections along Route 37 North which contain the six additional sensor sites. Pertinent roadway geometry is indicated on each figure as required.

Figure C.12 Location of Additional Sensor Sites on State Highway 37 North




Figure C.14 Plan View of Roadway Section for Site 21-27




Figure C.15 Plan View of Roadway Section for Site 22-28




Figure C.16 Plan View of Roadway Section for Site 23-29




Figure C.17 Plan View of Roadway Section for Site 24-30





Figure C.18 Plan View of Roadway Section for Site 25-31



Appendix D

ESTIMATING VEHICLE MILEAGE

D. ESTIMATING VEHICLE MILEAGE

State Roads 45, 46, and 48

Step 1

Each road was divided into approximately one-mile segments and each segment given a station number (see Figure 6.1 of Section 6). Nighttime and daytime volumes were calculated for each station from the volume-time curves given in Appendix H. Because of insufficient data, these volume-time curves cover both directions of travel seven days a week.

Step 2

Using the information on speed variability given in Table 6.2 of Section 6, standard deviations for nighttime speeds and daytime speeds were calculated for each station. These standard deviations were obtained from variances in speeds observed during weekdays on dry roads averaged for both directions of travel. A more precise approach would have required separate standard deviations calculated for each station for weekday and weekend speeds (day and night); however, this would have required weekday and weekend volume-time curves which are not available. In view of the general stability of the speed variances, the use of weekday, dry road speed variances, pooled over both directions of travel, appears adequate for estimating total vehicle mileage.

Step 3

Using the daytime standard deviation calculated in Step 2 and assuming a normal distribution of speeds, the proportions of vehicles within the various speed deviation intervals of interest were calculated for each station. Similar calculations were made using nighttime standard deviations.

Step 4

For each speed deviation interval, the daytime volume for a given station, as found in Step 1, was multiplied by the daytime proportion calculated in Step 3 for that station. The product is the daytime miles for one day for each of the speed

deviation intervals. The mileage for one day is then multiplied by the number of days in the time period covered by the study (i.e., December 7, 1968 through July 31, 1969). Similar calculations are made using nighttime volumes and proportions.

Step 5

The daytime and nighttime totals calculated in Step 4 are summed to give the total mileage for each speed deviation for each station for the entire study period. These totals are then summed over all stations on a given road to give the total mileage for each speed deviation interval for that road.

Highway No. 37

The general procedure for estimating vehicle mileage on Highway No. 37 follows closely the procedure previously outlined for the other state roads. However, since the computer-sensor system monitors the traffic characteristics continuously, more refined techniques were utilized to obtain more accurate mileage estimates. For example, separate volume-time curves were developed for Monday through Thursday, Friday, Saturday, and Sunday for each direction of travel.

Step 1

Each lane of Highway No. 37 was divided into segments of varying lengths. Each segment contained one pair of magnetic loop detectors located, as nearly as possible, in the center of the segment. Nighttime and daytime volumes, by days of the week, were calculated for each segment from the volume-time data given in Section for that loop which represented a given segment.

Step 2

Standard deviations for nighttime and daytime speeds for Monday through Thursday, Friday, Saturday, and Sunday were calculated for each loop. These standard deviations represent the average within-one-hour standard deviations in speeds for nighttime and daytime driving. As such these standard deviations are not affected by hour-to-hour changes in mean traffic speed.

Step 3

Using the standard deviation calculated in Step 2 and assuming a normal distribution of speeds, the proportions of vehicles within the various speed deviation intervals of interest were calculated for each segment.

Step 4

The product of the volume of vehicles obtained in Step 1 and the proportion, for a given speed deviation interval, corresponding to the same segment, day-of-week and time period within-a-day, obtained in Step 3 times the length of the segment gives the daily vehicle mileage for that segment for the particular speed deviation interval. The mileage for one day is then multiplied by the number of days in the time period covered by the study (i.e., December 7, 1968 through December 31, 1969). This type of calculation was made for all speed deviation intervals for each segment.

Step 5

Total vehicle mileage for some given condition is obtained by summing over the appropriate mileage values calculated in Step 4. For example, the total mileage for a particular speed deviation interval is obtained by summing the mileage for a particular speed deviation interval is obtained by summing the mileage for the given interval over all segments.

Appendix E

TYPICAL ON-SITE ACCIDENT REPORT

E. TYPICAL ON-SITE ACCIDENT REPORT

Accident Report No. 073-B
PI 1/30/69 0717 Thursday

Investigator arrived at the scene at 0740 about 20 minutes after the accident had occurred. Monroe County Sheriff's Department was on the scene until arrival.

V-1 (vehicle number 1) was on its top in a ravine on the South side of the highway for eastbound traffic and was a distance of 26.4 feet South of the traveled portion of the roadway. There were three injuries involved in the accident.

D-1 (driver of vehicle 1) was interviewed at the Bloomington Hospital by the investigation officer from the Sheriff's Department. D-1 stated at that time that she was eastbound on SR 45 at a speed of 55 to 60 mph. As she rounded the curve to the right, she was temporarily blinded by the headlights from westbound vehicles and misjudged the curvature of the roadway. She left the roadway and dropped over an embankment and struck a tree on the South side of the roadway.

Physical evidence consists of tracks on the right shoulder for eastbound traffic, 27.0 feet in length. At this point, the vehicle became air-borne and traveled over an embankment where it struck a tree located 26.4 feet South of the traveled portion of the roadway. The vehicle struck the tree 4.8 feet above ground level. The vehicle then proceeded 15.3 feet where it struck a second tree, uprooting it. The vehicle then ricocheted off of the second tree and struck the embankment 10.2 feet beyond the second tree, at which time the vehicle flipped onto its top and came to rest 15.3 feet from the second tree. The front of the vehicle came to rest 26.4 feet from the traveled portion of the roadway and the rear of the vehicle was 32.4 feet South of the roadway. The distance traveled by the vehicle after it became air-borne on the South shoulder to the point where it impacted with the first tree was a distance of 52.8 feet. Engineers' calculations based on the trajectory of the vehicle using the vehicle weight and the distance that it dropped in 52.8 feet estimates the speed of the vehicle when it left the roadway to be 67 mph.

Vehicle damage consisted of the front of the vehicle in its entirety, windshield, left front door, right front door, left rear fender, top, frame, undercarriage. The transmission, differential, and motor were all ripped from the vehicle.

All three occupants in the vehicle received injuries in the accident. D-1 was thrown from the vehicle on impact with the first tree and received bruises on the right leg and hip. P-2 (passenger) received cuts and abrasions and a broken clavical. P-5 received severe cuts and abrasions and a broken back.

P-2 stated to the investigating deputy that she believed the vehicle was traveling approximately 65 mph when it left the roadway.


P-5 also stated to the investigating deputy that he believed the vehicle was traveling approximately 65 mph when it left the roadway.

Investigator drove to the scene at 55 to 60 mph with no difficulty and other traffic on the roadway seemed to be moving at a normal pace. The accident occurred at dawn; visibility was somewhat limited due to extremely heavy rain. Roadway was wet; temperature was slightly above freezing; there was no icing on the roadway. Both Monroe County Sheriff's Department Deputy and Bloomington Police Ambulance responded to the call with red lights and sirens and indicated no difficulty at speeds of 65 mph.

Traffic flow count was not obtained.

Seat belts were not used by any of the occupants.

Cause of the accident is attributable to the fact that the roadway was wet; vision was somewhat obscured by rain on the windshield and the drivers' ability to see the roadway was impaired by blinding headlights of on-coming traffic.



ACCIDENT # 073-B
 Scale Drawing
 1" = 30'

MONROE COUNTY ACCIDENT STUDY
ACCIDENT REPORT

Accident Number: 073-B Type PT
Date/Time/Group: 30 January 1969 0717 Thursday
AGENCY: Reporting S/O Investigating S/O Other _____
Location S.R. 45 West, 240.2 Ft. from Green Co. Line

ROAD DESCRIPTION

Type Blacktop, 2 lane
Speed limit 65 MPH
Weather Raining (hard), temperature in high 30's, Roadway wet.
Time: Dawn
Visibility Poor due to heavy rain and dawn
Volume Not taken at time of accident. Reading 0705-0720, Thursday,
13 February was 83 Eastbound @ average of 47.253 MPH and
Flow Speed 28 Westbound @ 48.607 MPH

INVOLVED VEHICLES

V-1
V-2
V-3
V-4

Type

1967 Chevrolet Station Wagon

Parties

1-D
1-P2
1-P5

Location

Driver V-1
R.F. V-1
R.R. V-1

Injury

Bruise on R. Hip
Broken Clavical
Broken Back

Summary:

V-1 was eastbound on S.R. 45, 240.2 ft. east of the Monroe-Green Co. Line. V-1 left
the road on the right side, went air-borne and struck a tree 4'8" above the ground.
V-1 then proceeded to a second tree and uprooted this tree and then came to rest on
its top.

FORM 107

Accident No. 0 7 3 B	<input checked="" type="checkbox"/> Driver <input checked="" type="checkbox"/> Owner	(Last)	(First)	(Middle)	Sex F M	Age 40	Veh. No. 0 1
Address City: Springville State: Indiana Springville Indiana					Drivers License <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Type OP.	Dob 1/9/29	
State Ind. Number C516-29049							

Vehicle Make Chevrolet	Year 67	Type S/W	State Lic. No. 28A3720	State Ind.	Year 68	Trailer Lic. No.—State—Year
----------------------------------	-------------------	--------------------	----------------------------------	----------------------	-------------------	-----------------------------

<input checked="" type="checkbox"/> Moving <input type="checkbox"/> Stopped <input type="checkbox"/> Parked	Azimuth 0 7 0	Roadway: S.R. #45 240.2' E. of Green Co. Ln.	Odometer 40130	Speedometer (If Jammed)
---	----------------------	--	--------------------------	----------------------------

Identification No.—(or any other factor)	Towed To: By: Cy Gyger - Wrecker	Posted Speed Limit 65	Estimate of Vehicle Speed 67
--	--	---------------------------------	--

Vehicle Defects	Body Damage Severity	Severity Code																																				
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Undeterminable <input type="checkbox"/> See Narrative Type	<table border="1"> <tr> <td>3.</td><td>4.</td><td>5.</td><td>6.</td><td>7.</td><td>8.</td> </tr> <tr> <td>3</td><td>3</td><td></td><td></td><td></td><td></td> </tr> <tr> <td>3</td><td>3</td><td>1</td><td></td><td></td><td></td> </tr> <tr> <td>1.</td><td>3</td><td>17</td><td>18</td><td>19</td><td></td> </tr> <tr> <td>16.</td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td>20.</td><td>3</td><td>3</td><td>2</td><td></td><td>2</td> </tr> </table> <p style="text-align: center;">Under Carriage</p>	3.	4.	5.	6.	7.	8.	3	3					3	3	1				1.	3	17	18	19		16.						20.	3	3	2		2	1. Slight or Minor 2. Moderate 3. Severe or Extreme 4. Fire Damage I—Induced Damage C—Contact Damage → Arrow Length Depth of Severity (Drawn into Diagram)
3.	4.	5.	6.	7.	8.																																	
3	3																																					
3	3	1																																				
1.	3	17	18	19																																		
16.																																						
20.	3	3	2		2																																	

Driver Had Been Drinking <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Other (Drugs)	Police Determinate of Influence <input type="checkbox"/> Minor Test Results <input type="checkbox"/> Moderate <input type="checkbox"/> Major	Citation or Arrest Charge: None
--	---	---

Occupants Positions Prior and After Accident		Pass. Position (WT)	Skid Marks
PRIOR	AFTER (Post)	D=Driver P1=CF P2=RF P3=LR P4=CR P5=RR	Right Front Left Front Right Rear Left Rear
		If 3 Seated Use P6=LC P7=CC P8=RC	Not Distinguishable Total 0
		Tread Depth	
		Recap	

Seat Belts	Oper(D)	P1	P2	P3	P4	P5	Code	<input type="checkbox"/> Yes <input type="checkbox"/> No.....RF <input type="checkbox"/> Yes <input type="checkbox"/> No.....LF <input type="checkbox"/> Yes <input type="checkbox"/> No.....RR <input type="checkbox"/> Yes <input type="checkbox"/> No.....LR
Lap Belt	NU		NU			NU	U=Used NU=Not Used NI=Not Installed F=Failure UU=Use Unknown	Gear Shift Position
Diagonal Belt	NU		NU			NU		Light Switch <input type="checkbox"/> HB <input checked="" type="checkbox"/> LB <input type="checkbox"/> Pk. Position <input checked="" type="checkbox"/> On <input type="checkbox"/> Off
Combination	NU		NU			NU		
Child Restrainter	NU		NU			NU		
Other	NU		NU			NU		
Radio/Stereo <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	1. ON 2. OFF 3. NI 4. UU							Motorcyclist: Req. Equip. Used <input type="checkbox"/> All—Items Not Used—

1-4 Acc#		5-10 Date		11-14 Time		15 Acc involved:		3 Veh / Ped		Tot		Tot		Tot				
01713B		013095		0717		Two or more M.V.		4 Veh / Obj		16-17 Veh		18-19 Inj		20-21 Dead				
01713B		013095		0717		One M.V. (Non-col)		5 Other		0 1		0 3		0 0				
22-33 Location Matrix				34-36 Temp		Din Vel. 37-39 Wind		40 Weather			5 Light		8 Fog		41 Light		42 Dawn	
				+ 5 4				1 Clear & Bright			3 Light Rain		6 Heavy Snow		9 Smoke		1 Day	
								2 Overcast			4 Heavy Rain		7 Snow Sleet		0 Other		2 Night	
																	4 Dusk	
																	5 Moon-light	
42 County		43-44 Twp		Refrence (Milepost/Inters)				Dist & Dir		45 Other Damage				Owner (Names & Add)				
2		0 6								Obj Struck & extent of damage								
46-48 Rd #1		ROADWAY OF VEHICLE				62-64 Rd #2		ROADWAY OF VEHICLE										
Ref No		S.R. #45 240.2' E. of				Ref No												
		Green Co. In.																
49 Condition		50 Type/Surface		51 Rd #1 Curvature		65 Condition		66 Type/Surface		67 Rd #2 Curvature								
1 Holes, ruts, bumps		1 Concrete		1 None		1 Holes, ruts, bumps		1 Concrete		1 None								
2 Loose surface		2 Blacktop		2 222'		2 Loose surface		2 Blacktop		2								
3 Obj. on road		3		3		3 Obj. on road		3		3								
4 Soft shoulder		4		4		4 Soft shoulder		4		4								
5 Const/repair		5		5		5 Const/repair		5		5								
				0 Max.						0 Max.								
52 Weather Surface—Rd #1		53 Grade—Rd #1		68 Weather Surface—Rd #2		69 Grade—Rd #2												
1 Dry		5 Packed snow		1 None		1 Dry		5 Packed snow		1 None		5						
2 Wet		6 Ice		2 -.01		2 Wet		6 Ice		2		6						
3 Loose snow(<6")		7 Flooded		3		3 Loose snow(<6")		7 Flooded		3		7						
4 Loose snow(>6")		8 Other		4		4 Loose snow(>6")		8 Other		4		8		Max.				
54 Obstructed Vision Rd #1		55 Temp. Change in Flow Dir. Rd #1		56 Temp. Change in # of Lanes Rd #1		70 Obstructed Vision Rd #2		71 Temp. Change in Flow Dir. Rd #2		72 Temp. Change in # of Lanes Rd #2								
1 Yes		1 Yes		1 Reduction in # of Lanes		1 Yes		1 Yes		1 Reduction in # of Lanes								
2 No		2 No		2 Reduction in Lane Width		2 No		2 No		2 Reduction in Lane Width								
				3 Increase in # of Lanes						3 Increase in # of Lanes								
				4 Increase in Lane Width						4 Increase in Lane Width								
57 Traffic Controls Rd #1		58 # of Lanes Rd #1		59-61 Direction of Travel (Azimuth)		73 Traffic Controls Rd #2		74 # of Lanes Rd #2		75-77 Direction Travel (Azimuth) Rd #2								
1 None		1 (1)				1 None		1 (1)										
2 Stop Sign		2 (2)				2 Stop Sign		2 (2)										
3 Yield		3 (1)/(2)				3 Yield		3 (1)/(2)										
4 Red Blinker		4 (2)/(1)				4 Red Blinker		4 (2)/(1)										
5 Yellow Blinker		5 (2)/(2)				5 Yellow Blinker		5 (2)/(2)										
6 Red		6 (3)/(2)				6 Red		6 (3)/(2)										
7 Green		7 (2)/(3)				7 Green		7 (2)/(3)										
8 Yellow		8 (3)/(3)				8 Yellow		8 (3)/(3)										
9 Unknown		9 Other				9 Unknown		9 Other										
0 Manual				7 0		0												
78 Photos		X Research		Number of Research Pictures				Specify Type										
2 Police		3 Both		Polaroid 6				Instamatic				Other 16 35 mm.						
Agencies Notified By Police		Name				Agency				Monroe Co. Sheriff's Dept.								
		Reason for Notification				Unit No. and Name												
		Name				Agency Accident Report No.												
		Reason for Notification																

DRIVER/PASSENGER

Accident No. 0 7 3 B		1=Bleeding Wound, Distorted Members, or Victim carried away 2=Bruises, Abrasions, Swelling 3=Complaint of Pain, No Visible Sign or Momentary Unconsciousness			
Name (Last) (First) (Middle)		Sex	Age	Vehicle No.	
		F	40	01	
Address (Street) (City) (State)			Tele.No.	<input checked="" type="checkbox"/> Driver <input type="checkbox"/> Passenger <input type="checkbox"/> Pedestrian	
Springville, Indiana					
If Passenger Position Class.		Fatal 1 } <input checked="" type="checkbox"/> 2 } Non-Fatal 3 }		<input type="checkbox"/> No Injury	
First Aid: <input checked="" type="checkbox"/> Given By: Bloomington <input type="checkbox"/> Refused: Police Dept.		Taken To: Bloomington Hospital		By: Police Ambulance	
Nature of Injuries: Bruise on right hip					
Name (Last) (First) (Middle)		Sex	Age	Vehicle No.	
		F	59	01	
Address (Street) (City) (State)			Tele.No.	<input checked="" type="checkbox"/> Driver <input type="checkbox"/> Passenger <input type="checkbox"/> Pedestrian	
Springville, Indiana					
If Passenger Position Class.		Fatal 1 } <input checked="" type="checkbox"/> 2 } Non-Fatal P2 3 }		<input type="checkbox"/> No Injury	
First Aid: <input checked="" type="checkbox"/> Given By: Bloomington <input type="checkbox"/> Refused: Police Dept.		Taken To: Bloomington Hospital		By: Police Ambulance	
Nature of Injuries: Abrasion and broken clavical					
Name (Last) (First) (Middle)		Sex	Age	Vehicle No.	
		M	21	01	
Address (Street) (City) (State)			Tele.No.	<input checked="" type="checkbox"/> Driver <input type="checkbox"/> Passenger <input type="checkbox"/> Pedestrian	
Springville, Indiana					
If Passenger Position Class.		Fatal 1 } <input checked="" type="checkbox"/> 2 } Non-Fatal P5 3 }		<input type="checkbox"/> No Injury	
First Aid: <input checked="" type="checkbox"/> Given By: Bloomington <input type="checkbox"/> Refused: Police Dept.		Taken To: Bloomington Hospital		By: Police Ambulance	
Nature of Injuries: Abrasions - cuts and broken back					

INVESTIGATORS CONCLUSION

TRAFFIC FLOW BEHAVIOR

VOLUME EB-83, WB-28
SPEED (EB) Average 47.3 (WB) Average 48.6 MPH Speed limit 65 MPH

ACCIDENT INVOLVED VEHICLES

SPEED PRIOR	V-1	EST	<u>65</u>	MIN	<u>60</u>	MAX	<u>67</u>
	V-2	EST	<u> </u>	MIN	<u> </u>	MAX	<u> </u>
	V-3	EST	<u> </u>	MIN	<u> </u>	MAX	<u> </u>
	V-4	EST	<u> </u>	MIN	<u> </u>	MAX	<u> </u>
SPEED IMPACT	V-1	EST	<u>60</u>	MIN	<u>58</u>	MAX	<u>63</u>
	V-2	EST	<u> </u>	MIN	<u> </u>	MAX	<u> </u>
	V-3	EST	<u> </u>	MIN	<u> </u>	MAX	<u> </u>
	V-4	EST	<u> </u>	MIN	<u> </u>	MAX	<u> </u>

SPEED A FACTOR IN ACCIDENT (YES OR NO) NO

COMMENTS:

The trajectory calculations indicate that the vehicle was traveling at about
speed limit. In the opinion of the investigator, the accident would have
occurred even if the vehicle had been traveling up to 15 mph slower. The
condition of being blinded by oncoming traffic during heavy rain was independent
of the speed deviance from the average as indicated above.

DO NOT CIRCULATE

Appendix F

SPEED ESTIMATION OF AIV USING DATA FROM
COMPUTER SENSOR SYSTEM

MONROE COUNTY ACCIDENT STUDY
ACCIDENT REPORT

Accident Number: 280-J Type PD
Date/Time/Group: 10 Sept. 1969 1735 Wednesday
AGENCY: Reporting ISP Investigating ISP Other _____
Location SR 37N (300 ft. south of Kinser Pike)

ROAD DESCRIPTION

Type 2 Lane - 1 SB, 1 NB, Concrete
Speed limit 65 mph
Weather Clear, Dry pavement, daylight
Visibility unobscured
Volume SB 16.328 - 107; NB 16.327 - 159
Flow Speed SB - 56 NB - 55

INVOLVED VEHICLES

Type

V-1 1962 Pontiac 4 dr. sedan
V-2 1963 International truck (semi)
V-3 _____
V-4 _____

Parties

Location

Injury

<u>V-1-D</u>	<u>LF</u>	<u>None</u>
<u>V-2-D</u>	<u>LF</u>	<u>None</u>
_____	_____	_____
_____	_____	_____

Summary:

Accident 280

Date: September 10, 1969

Time: 1735 hours

Location: SR 37 N, 300 feet south of Kinser Pike

Weather: Clear and dry

V-1, a 1962 Pontiac, was enroute north on SR 37N at 1735 hours on Wednesday, 10 September, 1969. D-1 noticed several vehicles stopped in the northbound lane at Kinser Pike and braked sharply to avoid a rear-end collision with these stopped vehicles. V-1 skidded across the centerline and into the southbound lane of SR 37N. V-1 was struck head-on by V-2, a southbound 1963 International combination truck (tractor and trailer). Both vehicles came to rest against the side railing of an iron bridge in the northbound lane of SR 37N.

The accident site is bracketed by loop pair 9-13 on the south and 10-14 on the north. Loops 13 and 14 monitor northbound traffic in sequential order while loops 10 and 9 monitor southbound traffic. The distance between these loop pairs is 2.3 miles. The accident occurred approximately .2 miles north of loop pair 9-13. (The data for these loops between 1600 hours and 1730 hours was retrieved from computer tape storage. A portion of this data has been reproduced on the following pages.)

From the police report it is determined that V-1 was a northbound, 1962 Pontiac 4-door sedan, traveling at approximately 65 mph. Witness statements further indicate that V-1 was followed by two consecutive semitrucks.

By examining the data for loop 13 two items are immediately noticed: (1) at 16.590 traffic begins to slow and eventually stops at 16.683 and (2) two semitrucks (A & B) pass thru loop 13 in succession at 16.579. Using the witness reports, the vehicle preceding the trucks is tentatively identified as V-1. At a constant speed of 50 mph, this vehicle should have arrived at loop 14, 151 seconds later or 16.620. At the time that V-1 should arrive at loop 14 an eight minute gap occurs in the traffic flow and V-1 has disappeared from the system. The length of this vehicle is 18 feet which is as expected for V-1.

Using this vehicle's time of crossing loop 13 as a base the time of accident may now be predicted. At 50 mph, V-1 would have reached the accident site at 16.582. The average speed for southbound traffic between 1600 and 1730 hours is 52 mph. Using this speed we then project back from the accident site to loop 10. To arrive at the accident site at 16.582 traveling at 52 mph a vehicle would have to have crossed loop 10 at 16.546, 130 seconds earlier.

Examining the data for loop 10 at 16.546 a large vehicle is observed traveling south at a speed of 53 mph. The two vehicles immediately preceding this truck (C & D) cross loop 9 as expected at 16.579 but the truck fails to cross loop 9. Instead there appears a three minute and 50 second gap in the flow which was not apparent at loop 10. This vehicle is then identified as V-2. Its speed coincides with the police report estimate and its length lends additional credence to the identification.

Now that the vehicles have been identified a speed estimate may be made. The posted speed limit is 65 mph. The police report gives 65 mph and 50 mph as the prior speed estimates for V-1 and V-2 respectively. These may be considered valid within $\pm 10\%$. The printout indicates a speed of 53 mph for V-2 lending support to the police estimates; however, V-1 printout speed is only 50 mph. Since the accident occurred only .2 miles north of the sensor this speed would normally be

given greater consideration in making the estimate; however, in an interview at the accident scene with the investigating officer it was learned that V-1 was accelerating. D-1 was anticipating passing the vehicle preceding him after they crossed the bridge on which the accident occurred. The accident diagram indicates that V-1 skidded 110 feet and V-2 125 feet prior to impact. This data can be used to estimate the impact speeds for V-1 and V-2 as 41 mph and 15 mph respectively using prior speeds of 60 mph and 53 mph respectively.

	MIN	<u>PRIOR</u> <u>EST</u>	MAX	MIN	<u>IMPACT</u> <u>EST</u>	MAX
V-1	50	60	65	15	41	45
V-2	53	53	55	10	15	15

LOOP 13

LOOP 14

DIR	SPEED	LEN	HEADWAY	TIME		DIR	SPEED	LEN	HEADWAY	TIME
0	60	17	19084	16550	*	0	65	20	3733	16577
0	62	18	1160	16550	*	0	60	18	0	16595
0	51	18	28673	16558	*	0	60	18	4205	16596
0	50	17	905	16558	*	0	62	15	14825	16600
0	55	18	8892	16561	*	0	66	15	3410	16601
0	53	14	9247	16563	*	0	60	13	3442	16602
0	57	15	10298	16566	*	0	65	17	8220	16604
0	51	18	7293	16568	*	0	54	12	0	16615
0	52	16	807	16569	*	0	52	15	26247	16622
0	51	18	2054	16569	*	0	74	17	0	16756
0	55	14	21636	16575	*	0	67	16	0	16785
0	51	17	5209	16577	*	0	54	14	0	16825
0	45	16	1949	16577	*	0	57	13	1652	16825
0	47	17	2076	16578	*	0	45	17	0	16839
0	45	18	898	16578	*	1	71	21	0	16890
0 V-1	50	18	2043	16578	*	0	51	12	0	16927
0 A	49	47	1224	16579	*	0	64	12	0	16950
0 B	52	47	2796	16580	*	0	62	17	9465	16952
0	50	16	1628	16580	*	0	17	25	0	16964
0	34	12	0	16590	*	0	47	13	0	16982
0	30	19	14346	16593	*	0	65	18	0	17010
0	27	15	5433	16595	*	0	56	13	0	17023
0	17	22	10570	16598	*	0	64	15	2643	17023
0	16	21	3969	16599	*	0	68	15	1106	17024
0	12	18	3399	16600	*	0	64	17	7231	17026
0	3	28	0	16660	*	0	49	38	11753	17029
0	8	20	0	16680	*	0	49	39	1964	17029
0	8	19	5468	16681	*	0	51	17	2192	17030
0	9	21	7257	16683	*	0	49	17	1873	17030
0	0	0	0	16836	*	0	48	15	2237	17031
0	3	21	0	16847	*	0	58	26	0	17041
0	0	0	0	16903	*	0	59	17	9167	17043
0	6	45	873	16903	*	0	65	15	2238	17044
0	9	38	0	16924	*	0	65	18	1968	17044
0	7	22	12004	16927	*	0	59	13	3497	17045
0	0	0	0	16949	*	0	60	15	2444	17046
0	0	0	4347	16950	*	0	62	17	1492	17046
0	2	33	0	16961	*	0	63	17	2536	17047
0	0	0	15821	16965	*	0	66	13	1818	17047
0	0	0	6941	16967	*	0	66	16	1493	17048
0	0	0	0	16983	*	0	63	17	2199	17049

LISTING IS FOR LOOPS 9 10 BETWEEN 16000 AND 17500 ON 9/ 10

LOOP 9					LOOP 10				
DIR	SPEED	LEN	HEADWAY	TIME	DIR	SPEED	LEN	HEADWAY	TIME
0	62	12	2417	16471 *	0	66	36	0	16521
0	92	14	11477	16474 *	0	75	19	2638	16521
0	79	17	0	16492 *	0	60	17	0	16531
0	76	18	1905	16492 *	0	57	17	988	16531
0	57	19	17381	16497 *	0	59	12	2918	16532
0	61	19	13760	16501 *	0	54	13	0	16541
0	60	18	2082	16501 *	0 C	64	16	3685	16542
0	60	18	846	16501 *	0 D	68	15	3501	16542
0	62	19	3155	16502 *	0 V-2	53	37	14246	16546
0	61	15	2244	16503 *	0	55	8	1155	16547
0	61	11	3158	16504 *	0	56	17	1193	16547
0	54	16	10442	16507 *	0	53	17	1020	16547
0	71	17	11158	16510 *	0	53	11	1490	16548
0	64	19	24371	16517 *	0	61	16	1777	16548
0	65	16	1494	16517 *	0	60	11	2500	16549
0	53	13	18923	16522 *	0	58	17	4839	16550
0	55	11	3655	16523 *	0	53	25	0	16561
0	59	16	1573	16524 *	0	53	43	2399	16561
0	59	18	1660	16524 *	0	57	12	1017	16561
0	53	16	1950	16525 *	0	56	15	4690	16563
0	49	14	1165	16525 *	0	58	17	2419	16563
0	49	17	2442	16526 *	0	55	18	3118	16564
0	50	17	2050	16526 *	0	57	15	939	16565
0	48	15	4138	16527 *	0	57	17	1338	16565
0	50	16	3128	16528 *	0	66	11	7536	16567
0	48	16	12800	16532 *	0	62	18	2306	16568
0	58	18	12992	16536 *	0	61	21	0	16577
0	42	12	20910	16541 *	0	61	18	1468	16577
0	74	37	0	16551 *	0	61	20	2317	16578
0	76	18	6161	16552 *	0	61	11	2182	16578
0	41	11	14792	16556 *	0	62	9	3154	16579
0	59	17	456	16557 *	0	65	14	2272	16580
0	58	18	915	16557 *	0	73	19	0	16592
0	61	12	1550	16557 *	0	59	18	0	16601
0	54	15	0	16579 *	0	64	15	0	16613
0 C	59	17	1513	16579 *	0	65	18	1965	16613
0 D	54	16	1017	16579 *	0	61	14	7986	16615
0	10	12	0	16643 *	0	63	17	1280	16616
0	0	0	0	16658 *	0	62	16	1075	16616
0	0	0	1581	16658 *	0	63	18	4664	16617
0	15	12	17147	16663 *	0	63	15	1933	16618
0	18	8	0	16675 *	0	63	13	2829	16619
1	5	5	21482	16680 *	0	62	19	4067	16620
0	11	14	7731	16683 *	0	62	16	1554	16620
0	30	16	0	16713 *	0	63	44	15571	16624
0	36	15	11892	16716 *	0	62	17	1228	16625

Accident No. 2 8 0		Driver (Last) (First) (Middle) Owner Same			Sex F	Age 24	Veh. No. 0 1	
Address Indianapolis Ind.				Drivers License <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Type OP				
State Ind. Number G-550-44508								
Vehicle Make Pontiac	Year 62	Type 4 Dr. Sed	State Lic. No. 71F 5387	State Ind.	Year 69	Trailer Lic. No.—State—Year		
<input checked="" type="checkbox"/> Moving <input type="checkbox"/> Stopped <input type="checkbox"/> Parked	Azimuth North		Roadway: S.R. #37 North		Odometer	Speedometer (If Jammed)		
Identification No.—(or any other factor)				Towed To: By: Hay's Gulf		Posted Speed Limit 65	Estimate of Vehicle Speed	
Vehicle Defects	Body Damage Severity					Severity Code		
<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Undeterminable <input type="checkbox"/> See Narrative Type	3.	4.	5.	6.	7.	8.	1. Slight or Minor 2. Moderate 3. Severe or Extreme 4. Fire Damage I—Induced Damage C—Contact Damage → Arrow Length Depth of Severity (Drawn into Diagram)	
Driver Had Been Drinking <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Other (Drugs)		Police Determinate of Influence <input type="checkbox"/> Minor <input type="checkbox"/> Moderate <input type="checkbox"/> Major			Test Results			Citation or Arrest Charge:
Occupants Positions Prior and After Accident								
PRIOR		AFTER (Post)			Pass. Position (WT)		Skid Marks	
					D=Driver P ₁ =CF P ₂ =RF P ₃ =LR P ₄ =CR P ₅ =RR If 3 Seated Use P ₆ =LC P ₇ =CC P ₈ =RC		Right Front Left Front Right Rear Left Rear Not Distinguishable Total 110'	
Seat Belts		Oper(D)	P ₁	P ₂	P ₃	P ₄	P ₅	
Lap Belt		U.U.						
Diagonal Belt								
Combination								
Child Restrainter								
Other								
Radio/Stereo <input type="checkbox"/> <input type="checkbox"/>		Code			<input type="checkbox"/> Yes <input type="checkbox"/> No.....RF <input type="checkbox"/> Yes <input type="checkbox"/> No.....LF <input type="checkbox"/> Yes <input type="checkbox"/> No.....RR <input type="checkbox"/> Yes <input type="checkbox"/> No.....LR			
1. ON 2. OFF 3. NI 4. UU		U=Used NU=Not Used NI=Not Installed F=Failure UU=Use Unknown			Gear Shift Position Light Switch <input type="checkbox"/> HB <input type="checkbox"/> LB <input type="checkbox"/> Pk. Position <input type="checkbox"/> On <input type="checkbox"/> Off			
Motorcyclist: Req. Equip. Used		<input type="checkbox"/> All—Items Not Used—						

1-4	Acc#	5-10	Date	11-14	Time	15	Acc involved:	3	Veh / Ped	Tot		Tot		Tot					
			Day Week				Two or more M.V.	4	Veh / Obj	16-17	Veh	18-19	Inj	20-21	Dead				
	2 8 10	0 9 1 10 9 4		1	7 3 5	2	One M.V. (Non-col)	5	Other	0	2	0	0	0	0				
22-33	Location Matrix			34-36	Temp	37-39	Wind	40	Weather	5	Light Snow	8	Fog	41	Light	3	Dawn		
									Clear & Bright	3	Light Rain	6	Heavy Snow	9	Smoke	4	Day	4	Dusk
									Overcast	4	Heavy Rain	7	Other	0	Other	2	Night	5	Moon-light
42	County	43-44	Twp	Reference (Milepost/Inters)			Dist & Dir	45	Other Damage	Owner (Names & Add)									
	2	1	0 5	S.R. 37 N. (300 Ft. South of Kinser Pike)					Obj Struck & extent of damage										
									1 Yes										
									2 No										
46-48	Rd #1	ROADWAY OF VEHICLE 1					62-64	Rd #2	ROADWAY OF VEHICLE 2										
	Ref No	S.R. 37 North						Ref No	S.R. 37 North										
49	Condition	50	Type/Surface	51	Rd #1 Curvature	65	Condition	66	Type/Surface	67	Rd #2 Curvature								
1	Holes, ruts, bumps	X	Concrete	X	None 6	1	Holes, ruts, bumps	X	Concrete	X	None 6								
2	Loose surface	2	Blacktop	2	7	2	Loose surface	2	Blacktop	2	7								
3	Obj. on road	3		3	8	3	Obj. on road	3		3	8								
4	Soft shoulder	4		4	9	4	Soft shoulder	4		4	9								
5	Const/repair	5		5	0 Max.	5	Const/repair	5		5	0 Max.								
52	Weather Surface—Rd #1			53	Grade—Rd #1		68	Weather Surface—Rd #2			69	Grade—Rd #2							
X	Dry	5	Packed snow	X	None	5	X	Dry	5	Packed snow	X	None	5						
2	Wet	6	Ice	2	6	2	2	Wet	6	Ice	2	6	2						
3	Loose snow (<6")	7	Flooded	3	7	3	3	Loose snow (<6")	7	Flooded	3	7	3						
4	Loose snow (>6")	8	Other	4	8 Max.	4	4	Loose snow (>6")	8	Other	4	8 Max.	4						
54	Obstructed Vision Rd #1	55	Temp. Change in Flow Dir. Rd #1	56	Temp. Change in # of Lanes Rd #1	70	Obstructed Vision Rd #2	71	Temp. Change in Flow Dir. Rd #2	72	Temp. Change in # of Lanes Rd #2								
1	Yes	1	Yes	1	Reduction in # of Lanes	1	Yes	1	Yes	1	Reduction in # of Lanes								
X	No	X	No	2	Reduction in Lane Width	X	No	X	No	2	Reduction in Lane Width								
57	Traffic Controls Rd #1	58	# of Lanes Rd #1	3	Increase in # of Lanes	73	Traffic Controls Rd #2	74	# of Lanes Rd #2	3	Increase in # of Lanes								
X	None	1	(1)	4	Increase in Lane Width	X	None	1	(1)	4	Increase in Lane Width								
2	Stop Sign	X	(2)	59-61	Direction of Travel (Azimuth)	2	Stop Sign	X	(2)	59-61	Direction of Travel (Azimuth)								
3	Yield	3	(1)/(2)	Northbound		3	Yield	3	(1)/(2)	Southbound									
4	Red Blinker	4	(2)/(1)			4	Red Blinker	4	(2)/(1)										
5	Yellow Blinker	5	(2)/(2)			5	Yellow Blinker	5	(2)/(2)										
6	Red	6	(3)/(2)			6	Red	6	(3)/(2)										
7	Green	7	(2)/(3)			7	Green	7	(2)/(3)										
8	Yellow	8	(3)/(3)			8	Yellow	8	(3)/(3)										
9	Unknown	9	Other			9	Unknown	9	Other										
0	Manual					0													
78	Photos	1	Research	Number of Research Pictures				Specify Type											
2	Police	3	Both		Polaroid		Instamatic		Other										
Agencies Notified By Police	Name		Agency																
	Reason for Notification		ISP																
	Name		Unit No. and Name																
	Reason for Notification		Patrick																
		Agency Accident Report No.																	

Accident No. 2 8 0		Driver (Last) (First) (Middle) Owner			Sex M	Age 38	Veh. No. 0 2
Address City: Indianapolis, Ind. Indianapolis, Ind.				Drivers License <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Type Chaf. State Ind. Number 5-240-30459			
Vehicle Make International 63	Year 63	Type Truck (tractor)	State Lic. No. 2887 L	State Ind.	Year 69	Trailer Lic. No.—State—Year	
<input checked="" type="checkbox"/> Moving <input type="checkbox"/> Stopped <input type="checkbox"/> Parked	Azimuth South	Roadway: S.R. 37 North			Odometer	Speedometer (If Jammed)	
Identification No.—(or any other factor)				Towed To: By: Drive Away		Posted Speed Limit 65	Estimate of Vehicle Speed
Vehicle Defects	Body Damage Severity				Severity Code		
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Undeterminable <input type="checkbox"/> See Narrative Type	3.	4.	5.	6.	7.	8.	1. Slight or Minor 2. Moderate 3. Severe or Extreme 4. Fire Damage I—Induced Damage C—Contact Damage → Arrow Length Depth of Severity (Drawn into Diagram)
	2.					9.	
	1.	15.	14.	13.	12.	10.	
	16.	20.	Under Carriage				
Driver Had Been Drinking <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Other (Drugs)		Police Determinate of Influence <input type="checkbox"/> Minor Test Results <input type="checkbox"/> Moderate <input type="checkbox"/> Major			Citation or Arrest Charge: None		
Occupants Positions Prior and After Accident							
PRIOR		AFTER (Post)				Pass. Position (WT)	Skid Marks
						D=Driver	Right Front
						P ₁ =CF	Left Front
						P ₂ =RF	Right Rear
						P ₃ =LR	Left Rear
						P ₄ =CR	
						P ₅ =RR	
						If 3 Seated Use	Not Distinguishable
						P ₆ =LC	Total 125'
						P ₇ =CC	Tread Depth
						P ₈ =RC	Recap
Seat Belts	Oper (D)	P ₁	P ₂	P ₃	P ₄	P ₅	<input type="checkbox"/> Yes <input type="checkbox"/> No.....RF
Lap Belt	U.U.						<input type="checkbox"/> Yes <input type="checkbox"/> No.....LF
Diagonal Belt							<input type="checkbox"/> Yes <input type="checkbox"/> No.....RR
Combination							<input type="checkbox"/> Yes <input type="checkbox"/> No.....LR
Child Restrainter							Gear Shift Position
Other							
Radio/Stereo <input type="checkbox"/> <input type="checkbox"/>						Motorcyclist: Req. Equip. Used	
1. ON 2. OFF 3. NI 4. UU						<input type="checkbox"/> All—Items Not Used—	
						Light Switch <input type="checkbox"/> HB <input type="checkbox"/> LB <input type="checkbox"/> Pk. Position <input type="checkbox"/> On <input type="checkbox"/> Off	

(8) TYPE _____ (9) SOURCE _____ (10-11) ANALYSIS _____ (12-13-14-15) LOSS _____ (16) LOCATION _____ (17-21) ACCIDENT NO. **280**

(17-18) DATE OF ACCIDENT September 10, 1969 (19-20) DAY OF WEEK Wednesday (21) TIME OF DAY 5:35 AM PM

(25-26) PLACE WHERE ACCIDENT OCCURRED: COUNTY Monroe CITY OR TOWN _____ (27) _____ (28-29) _____ (30-31) _____
 If accident occurred outside of city limits, indicate distance from nearest city or town limits, using two directions, if necessary.
 Occurred within corporate limits. MILES NORTH. _____ MILES SOUTH. _____ MILES EAST. _____ MILES WEST OF. _____
 Occurred outside corporate limits. LIMITS OF Bloomington
 (32-33-34) ROAD ON WHICH ACCIDENT OCCURRED SR 37 (35-36) City or Town _____ (37-38-39-40) _____
 AT ITS INTERSECTION WITH _____
 Name of Street or No. of Highway (US or STATE). If no No., use name. Name and Number of Intersecting Street or Highway.
 IF NOT AT INTERSECTION 300 FEET (N S E W) OF Kinser Pike
 Show nearest intersection, house number, or other identifying landmark.

VEHICLE NUMBER 1: (41) (42-43)
 YEAR 62 MAKE Pontiac TYPE 4 dr. Sed.
 Sedan, Truck, Bus, etc.
 LICENSE PLATE 7LF 5387 Ind. 1969
 Number State Year
 DRIVER (Print) Last Name First Middle _____
 ADDRESS (Print) Street or R.F.D. _____ (45-46) _____ (47) _____
 City and State DATE 12-23-44 AGE 24 SEX
 DRIVER'S LICENSE G 550-44800 Ind. OP.
 Number State Type (49)
 OWNER Same as above
 Last Name First Middle _____
 ADDRESS _____ Street or R.F.D. _____ City _____ State _____
 PARTS OF VEHICLE DAMAGED TOTAL--front end, motor, frame
 ESTIMATE OF REPAIR \$ 1100.00
 VEHICLE REMOVED TO Ray's Golf BY Wrecker

~~1~~ (53-54) (55)
 NAME (Print) Last Name First Middle _____ AGE _____ SEX _____
 ADDRESS _____ (56) Street or R.F.D. _____ City _____ (57) _____ State _____
 DRIVER _____ PASSENGER _____ IN VEHICLE NUMBER _____
 PEDESTRIAN _____ Other (EXPLAIN) _____
 NATURE AND EXTENT OF INJURIES _____

VEHICLE NUMBER 2: (41) (42-43)
 YEAR 63 MAKE International TYPE Truck
 Sedan, Truck, Bus, etc.
 LICENSE PLATE 2887 L Ind. 1969
 Number State Year
 DRIVER (Print) Last Name First Middle _____
 ADDRESS (Print) Street or R.F.D. _____ (45-46) _____ (47) _____
 City and State DATE 11-19-30 AGE 38 SEX
 DRIVER'S LICENSE S 240-30459 Ind. Chauff.
 Number State Type (49)
 OWNER _____ Last Name First Middle _____
 ADDRESS _____ Indianapolis, Ind. _____ Street or R.F.D. _____ City _____ State _____
 PARTS OF VEHICLE DAMAGED front bumper, left front of tractor
 ESTIMATE OF REPAIR \$ 300.00
 VEHICLE REMOVED TO Driven BY Driver

~~1~~ (53-54) (55)
 NAME (Print) Last Name First Middle _____ AGE _____ SEX _____
 ADDRESS _____ (56) Street or R.F.D. _____ City _____ (57) _____ State _____
 DRIVER _____ PASSENGER _____ IN VEHICLE NUMBER _____
 PEDESTRIAN _____ Other (EXPLAIN) _____
 NATURE AND EXTENT OF INJURIES _____

1. _____	2. _____	3. _____	4. _____
Died as result of accident.	Visible signs of injury, as bleeding wound, distorted limb or had to be carried away.	Other visible injuries, as bruises, swelling, abrasions, limping, etc.	No visible injuries, but complaint of pain or momentary unconsciousness.

DAMAGE TO OTHER PROPERTY: NONE
 Name of Object (s) _____ Owner's Name and Address _____ Nature of Damages _____
 ESTIMATE OF REPAIR \$ _____

Driver 1 2 Ped. (Check one)

0 No test offered.

1 Test offered but refused.

2 Breath test given.

3 Blood test given.

4 Urine test given.

(61) ARREST—(Check one)

Driver

0 Not arrested.

1 Arrested for D. U. I.

2 Arrested for other violation.

(61) SPEED LIMIT 65 MPH

(62) SPEED BEFORE ACCIDENT

Veh. 1 65 MPH Veh. 2 50 MPH

(63) CONTRIBUTING CIRCUMSTANCES INDICATED

Driver 1 2

1 Speed too fast.

2 Failed to yield right-of-way.

3 Drove left of center.

4 Improper overtaking.

5 Passed stop sign.

6 Disregarded traffic signal.

7 Followed too closely.

8 Made improper turn.

9 Other improper driving.

10 Inadequate brakes.

11 Improper lights.

12 Had been drinking.

(64) VEHICLE DEFECTS

Driver 1 2

0 No defects.

1 Brakes defective.

2 Lights defective.

3 Defective steering.

4 Puncture or blowout.

8 Other defects.

(65) VISION OCCURRED

Driver 1 2

0 Not obscured.

1 By building/s.


2 By embankment.

3 By signboard.

4 Trees, crops, etc.

5 By animal.

8 (Specify other)



DESCRIBE WHAT HAPPENED: Veh. 1 enroute north on SR37 was coming into an ifon bridge approaching Kinser Pike when suddenly traffic in front slowed for a veh. that was turning off of SR37 onto Kinser Pike. Veh. 1 braked sharply and skidded approx. 110 ft. and went across the center line to avoid a rear end collision & was hit headon by veh. 2 as it was southbound on SR37. Veh. 2 skidded 125 ft. before impact in the south bound lane & after impact went antoher 44 ft. into the bridge on the east side of the road. Veh. 1 was wedged under the tractor trailer at this time. Opinion: cause of acc. was veh. 1 being left of center with other traffic present & not having veh. under control to avoid a collisi

WHAT DRIVERS WERE GOING TO DO BEFORE ACCIDENT:

(63)

Driver No. 1 was headed N S E W on SR#37 (Name or number of street or highway.)

Driver No. 2 was headed N S E W on SR#37 (Name or number of street or highway.)

(Check applicable items for each driver.)

Driver 1	Driver 2	Driver 1	Driver 2
0 <input type="checkbox"/> Passing.	2 <input type="checkbox"/> Backing.	5 <input type="checkbox"/> Start from parked position.	6 <input type="checkbox"/> Avoiding veh. abn. Pcd.
1 <input type="checkbox"/> Turn right.	3 <input type="checkbox"/> Slow or stop.	7 <input type="checkbox"/> Skidded before applying brakes.	8 <input checked="" type="checkbox"/> Skidded after applying brakes.
1 <input type="checkbox"/> Turn left.	4 <input checked="" type="checkbox"/> Going straight ahead.	8 <input checked="" type="checkbox"/> Skidded after applying brakes.	9 <input type="checkbox"/> Parked.
1 <input type="checkbox"/> Make U turn.	5 <input type="checkbox"/> Start in traffic lane.	9 <input type="checkbox"/> Parked.	

CONDITION OF DRIVERS AND PEDESTRIANS (Check one)

(66) (70)

Driver 1 2 Ped.

0 Had NOT been drinking.

1 Obviously drunk.

2 Ability impaired.

3 Ability not impaired.

4 Unknown if impaired.

(67) (71)

11 Apparently normal.

0 Eyesight defective.

1 Hearing defective.

2 Other defects.

3 Illness.

4 Fatigued.

5 Apparently asleep.

6 Attention diverted.

7 Advanced senility.

8 Other handicaps.

(Specify other handicaps)

WHAT PEDESTRIAN WAS DOING BEFORE ACCIDENT

(67)

Pedestrian was going N S E W along across or into Street or Highway

From (N. E. corner to S. E. corner or from West side to East side, etc.) to

(Check one)

0 Not in roadway.

1 Walking in roadway with traffic.

2 Walking in roadway against traffic.

3 Pushing or working on vehicle.

4 Getting on or off vehicle.

5 Standing in roadway.

6 Other working in roadway.

7 Playing in roadway.

8 Other (Specify actions)

11 Crossing or entering not at intersection.

12 Crossing or entering at intersection.

(72) TRAFFIC CONTROL	(73) CHARACTER	(74) SURFACE	(75) CONDITION	(76) WEATHER	(77) LIGHT	(78) KIND OF LOCALITY
Driver 1 2	(Check two)	(Check one)	(Check one)	(Check one)	(Check one)	(Check one to show that area adjacent to roadway for 300' was primarily:)
0 <input type="checkbox"/> Police officer.	1 <input checked="" type="checkbox"/> Straight.	1 <input checked="" type="checkbox"/> Concrete.	1 <input checked="" type="checkbox"/> Dry.	1 <input checked="" type="checkbox"/> Clear.	1 <input checked="" type="checkbox"/> Daylight.	1 <input type="checkbox"/> School or playground.
1 <input type="checkbox"/> Automatic signal.	2 <input type="checkbox"/> Curve.	2 <input type="checkbox"/> Blacktop.	2 <input type="checkbox"/> Wet.	2 <input type="checkbox"/> Raining.	2 <input type="checkbox"/> Dark.	2 <input type="checkbox"/> Industrial or business.
2 <input type="checkbox"/> Yield right-of-way sign.	1 <input checked="" type="checkbox"/> Level.	3 <input type="checkbox"/> Sand or dirt.	3 <input type="checkbox"/> Snow/ice.	3 <input type="checkbox"/> Snowing.	3 <input type="checkbox"/> Dawn or dusk.	3 <input type="checkbox"/> Residential.
3 <input checked="" type="checkbox"/> Center line marked.	2 <input type="checkbox"/> On grade.	4 <input type="checkbox"/> Gravel.	4 <input type="checkbox"/> Other	4 <input type="checkbox"/> Fog.		4 <input checked="" type="checkbox"/> Open country.
	3 <input type="checkbox"/> Millcrest.	8 <input type="checkbox"/> Other		8 <input type="checkbox"/> Other		

(68) ROAD DEFECTS

1 Foreign material on surface.

2 Loose sand, gravel, etc.

3 Holes, ruts, dips, bumps, etc.

4 Defective curbsiders.

5 Obstruction not lighted or signaled.

6 Standing water, landslide, etc.

7 Obstructed by previous acc.

8 All other defects.

WITNESSES

Name _____ Address _____ Location northbound on 3

Name _____ Address _____ Location northbound on 3

POLICE ACTION

ARRESTS: Name _____ Charge _____

Name _____ Charge _____

INVESTIGATION: Time notified of accident _____ AM 5:40 PM Time of arrival at the scene _____ AM 5:45 PM

Where else was investigation made? _____ Is investigation complete? Yes No

(Have photographs taken?) Yes No

*SIGNATURE John D. ... Department ISP Post 7A Date of report 9-10-69

Appendix G

COMPUTER-SENSOR ACCURACY AND REPEATABILITY TEST DATA

G. COMPUTER-SENSOR ACCURACY AND REPEATABILITY TEST DATA

The first column of data within a given loop number gives the speed (mph) of the vehicle as recorded by the "timer." The second column gives the speed for the same vehicle as recorded by the "computer." The third column is the difference, d , in speeds, calculated as (computer speed-timer speed). The average difference, \bar{d} , and the standard deviation of the difference, s_d , are given at the bottom of the third column. \bar{d} represents the bias associated with the computer-sensor system.

Loop No. 0

Timer a	Computer b	Diff. d=b-a
43.6	44	.4
40.8	40	-.8
27.9	28	.1
45.6	46	.4
42.6	42	-.6
40.9	40	-.9
43.6	43	-.6
29.6	29	-.6
39.5	39	-.5
45.0	45	0
42.1	42	-.1
43.3	43	-.3
40.6	41	.4
41.1	40	-1.1
38.1	38	-.1
42.6	43	.4
43.6	43	-.6
37.4	36	-1.4
34.2	34	-.2
47.4	48	.6
48.4	48	-.4
29.7	30	-.3
38.0	37	-1.0
45.6	46	.4
42.7	43	.3
43.9	44	.1
48.0	48	0
25.2	25	-.2
42.6	42	-.6
46.4	46	-.4

$$\bar{d} = -0.3$$

$$s_d = 0.5$$

Loop No. 1

Timer a	Computer b	Diff. d=b-a
46.6	44	-2.6
44.1	42	-2.1
45.2	43	-2.2
47.6	46	-1.6
46.8	45	-1.8
46.8	44	-2.8
49.0	47	-2.0
43.6	41	-2.6
44.6	42	-2.6
47.2	44	-3.2
47.7	46	-1.7
47.6	45	-2.6
41.4	39	-2.4
29.9	27	-2.9
27.6	25	-2.6
35.2	33	-2.2
46.6	43	-3.6
38.6	36	-2.6
46.9	44	-2.9
47.0	45	-2.0
47.6	45	-2.6
40.0	37	-3.0
43.4	41	-2.4
37.0	35	-2.0
32.2	30	-2.2
40.2	38	-2.2
39.0	37	-2.0
50.2	48	-2.2
48.8	46	-2.8

$$\bar{d} = -2.4$$

$$s_d = 0.5$$

Loop No. 2		
Timer a	Computer b	Diff. d=b-a
47.1	47	- .1
44.5	44	- .5
47.0	46	-1.0
45.8	45	- .8
41.2	40	-1.2
37.2	36	-1.2
50.1	49	-1.1
41.0	40	-1.0
42.3	42	- .3
41.3	40	-1.3
35.1	34	-1.1
53.6	52	-1.6
44.8	45	.2
41.6	40	-1.6
50.1	49	-1.1
51.8	51	- .8
41.9	41	- .9
36.6	36	- .6
43.2	42	-1.2
36.9	36	- .9
40.1	40	- .1
33.8	33	- .8
46.1	46	- .1
44.0	44	0
45.5	44	-1.5
48.0	47	-1.0
46.0	45	-1.0
47.6	47	- .6
47.6	46	-1.6
41.7	41	- .7
49.1	48	-1.1
		$\bar{d} = -0.9$
		$s_d = 0.5$

Loop No. 3		
Timer a	Computer b	Diff. d=b-a
54.7	54	- .7
33.8	34	.2
62.4	62	- .4
62.0	62	0
51.9	52	.1
58.6	58	- .6
53.4	54	.6
50.3	50	- .3
45.3	45	- .3
56.9	56	- .9
53.9	54	- .1
51.4	51	- .4
56.6	55	-1.6
54.0	54	0
51.5	52	.5
56.9	56	- .9
60.7	60	- .7
49.4	50	.6
47.3	47	- .3
62.4	62	- .4
48.5	48	- .5
63.5	63	- .5
55.0	54	-1.0
52.5	53	.5
51.7	51	- .7
31.1	31	- .1
54.8	55	.2
50.6	50	- .6
69.1	68	-1.1
67.0	68	1.0
		$\bar{d} = -0.3$
		$s_d = 0.6$

Loop No. 4

Timer a	Computer b	Diff. d=b-a
38.5	39	.5
23.6	24	.4
41.6	42	.4
42.4	43	.6
37.4	38	.6
35.4	36	.6
36.8	38	1.2
37.1	38	.9
49.2	50	.8
40.8	42	1.2
44.6	45	.4
39.9	40	.1
39.8	40	.2
39.9	41	1.1
22.7	23	.3
40.6	42	1.4
51.6	52	.4
21.4	22	.6
35.0	36	1.0
27.5	28	.5
36.5	38	1.5
40.0	41	1.0
42.6	44	1.4
40.6	41	.4
44.2	45	.8
47.1	48	.9
17.1	17	-.1
37.1	37	-.1
41.7	43	1.3
42.6	44	1.4
39.4	40	.6

$$\bar{d} = 0.7$$

$$s_d = 0.5$$

Loop No. 5

Timer a	Computer b	Diff. d=b-a
49.5	48	-1.5
42.3	41	-1.3
50.0	49	-1.0
50.4	51	.6
47.3	46	-1.3
43.3	42	-1.3
38.4	36	-2.4
44.1	43	-1.1
47.1	46	-1.1
53.3	55	1.7
46.2	45	-1.2
48.0	47	-1.0
43.2	42	-1.2
44.0	44	0
40.4	39	-1.4
38.5	37	-1.5
46.9	35	-1.9
41.2	40	-1.2
38.7	37	-1.7
45.0	44	-1.0
43.1	41	-2.1
39.9	38	-1.9
45.2	44	-1.2
48.4	47	-1.4
43.4	43	-.4
46.1	45	-1.1
43.7	43	-.7
54.7	55	.3
47.0	47	0
42.4	41	-1.4

$$\bar{d} = -1.0$$

$$s_d = 0.8$$

Loop No. 6

Timer a	Computer b	Diff. d=b-a
40.3	38	-2.3
44.0	43	-1.0
34.5	31	-3.5
36.6	34	-2.6
37.6	35	-2.6
35.0	32	-3.0
42.2	40	-2.2
51.1	52	.9
44.0	44	0
42.5	42	-.5
43.5	42	-1.5
40.8	39	-1.8
52.2	51	-1.2
51.6	51	-.6
48.4	48	-.4
43.5	42	-1.5
56.1	57	.9
54.7	56	1.3
52.5	53	.5
60.0	64	4.0
54.2	53	-1.2
52.3	53	.7
54.2	56	1.8
54.5	56	1.5
46.9	46	-.9
46.4	45	-1.4
42.9	41	-1.9

$$\bar{d} = -0.7$$

$$s_d = 1.7$$

Loop No. 7

Timer a	Computer b	Diff. d=b-a
47.9	44	-3.9
55.4	50	-5.4
58.4	53	-5.4
52.5	48	-4.5
57.4	52	-5.4
59.5	54	-5.5
52.3	48	-4.3
65.1	60	-5.1
59.1	54	-5.1
49.1	44	-5.1
47.8	44	-3.8
46.9	43	-3.9
52.1	47	-5.1
50.9	46	-4.9
27.8	25	-2.8
42.3	38	-4.3
42.6	39	-3.6
46.9	42	-4.9
56.3	52	-4.3
56.6	52	-4.6
58.3	54	-4.3
48.8	44	-4.8
53.5	48	-5.5
51.9	48	-3.9
49.4	45	-4.4
46.9	42	-4.9
44.3	40	-4.3
53.9	49	-4.9
53.6	49	-4.6
52.3	48	-4.3

$$\bar{d} = -4.6$$

$$s_d = 0.6$$

Loop No. 8

Timer a	Computer b	Diff. d=b-a
57.7	56	-1.7
54.4	53	-1.4
58.7	57	-1.7
62.2	58	-4.2
63.5	60	-3.5
56.6	54	-2.6
54.0	54	0
50.4	50	- .4
51.7	51	- .7
53.0	52	-1.0
55.1	54	-1.1
43.9	44	.1
38.2	41	2.8
53.0	53	0
52.3	52	- .3
60.3	57	-3.3
55.3	53	- .3
58.8	57	-1.8
52.0	53	1.0
59.4	58	-1.4
48.4	49	.6
57.0	56	-1.0
64.0	61	-3.0
61.9	58	-3.9
60.7	57	-3.7
62.0	60	-2.0
41.1	43	1.9
33.0	36	3.0
60.5	55	5.5

$$\bar{d} = -0.8$$

$$s_d = 2.2$$

Loop No. 9

Timer a	Computer b	Diff. d=b-a
52.2	52	- .2
52.5	52	- .5
55.0	56	1.0
48.5	46	-2.5
49.6	50	.4
44.5	44	- .5
47.9	46	-1.9
56.2	55	-1.2
52.2	50	-2.2
46.5	46	- .5
51.4	50	-1.4
53.5	53	- .5
54.5	54	- .5
57.5	59	1.5
52.1	52	- .1
53.0	53	0
58.1	58	- .1
59.2	59	- .2
36.6	34	-2.6
61.0	61	0
44.3	41	-3.3
51.0	50	-1.0
51.9	53	1.1
59.4	59	- .4
56.4	57	.6
43.4	41	-2.4
53.4	53	- .4
53.1	53	- .1

$$\bar{d} = -0.6$$

$$s_d = 1.2$$

Loop No. 10

Timer a	Computer b	Diff. d=b-a
45.2	48	2.8
47.6	50	2.4
50.2	52	1.8
51.6	53	1.4
65.6	64	-1.6
55.6	58	2.4
56.2	59	2.8
61.1	63	1.9
58.8	61	2.2
70.7	71	.3
48.0	50	2.0
63.8	64	.2
57.0	54	3.0
54.0	56	2.0
49.0	51	2.0
58.4	60	1.6
56.6	58	1.4
54.2	56	1.8
63.0	64	1.0
54.4	57	2.6
47.6	48	.4
45.0	48	3.0
47.5	48	.5

$$\bar{d} = 1.6$$

$$s_d = 1.1$$

Loop No. 11

Timer a	Computer b	Diff. d=b-a
17.6	15	-2.6
41.7	39	-2.7
40.0	37	-3.0
50.0	46	-4.0
55.2	53	-2.2
33.6	30	-3.6
46.0	43	-3.0
52.3	49	-3.3
49.1	47	-2.1
50.6	47	-3.6
63.5	63	-.5
62.7	61	-1.7
51.1	47	-4.1
55.6	54	-1.6
59.7	56	-3.7
53.6	51	-2.6
54.7	52	-2.7
56.7	54	-2.7
51.6	49	-2.6
51.1	48	-3.1
45.9	43	-2.9
49.0	47	-2.0
56.1	54	-2.1
56.6	54	-2.6
50.0	47	-3.0
50.0	46	-4.0
49.1	46	-3.1
48.0	45	-3.0
46.6	44	-2.6
46.6	44	-2.6
57.6	55	-2.6
59.4	58	-1.4
56.1	53	-3.1

$$\bar{d} = -2.7$$

$$s_d = 0.8$$

Loop No. 12

Timer a	Computer b	Diff. d=b-a
43.6	44	.4
42.1	43	.9
48.4	48	- .4
44.8	46	1.2
43.2	44	.8
50.8	51	.2
50.8	50	- .8
50.0	50	0
60.4	59	-1.4
57.9	57	- .9
46.0	47	1.0
53.6	54	.4
39.1	40	.9
51.1	50	-1.1
56.0	55	-1.0
40.3	43	2.7
44.1	46	1.9
51.9	52	.1
53.4	51	-2.4
50.6	51	.4
58.6	55	-3.6
56.4	55	-1.4
43.6	45	1.4
56.6	56	- .6
58.0	57	-1.0
39.4	41	1.6
55.7	55	- .7
56.5	55	- .5
55.8	55	- .8
47.5	48	.5

$$\bar{d} = -0.1$$

$$s_d = 1.3$$

Loop No. 13

Timer a	Computer b	Diff. d=b-a
52.0	55	3.0
53.3	51	-2.3
55.3	51	-4.3
46.3	46	- .3
50.0	49	-1.0
57.3	54	-3.3
62.1	58	-4.1
45.3	45	- .3
49.6	49	- .6
43.2	43	- .2
56.4	54	-2.4
44.7	44	- .7
38.3	39	.7
49.7	47	-2.7
50.5	49	- .5
49.6	49	- .6
51.0	49	-2.0
54.1	53	-1.1
53.5	51	-2.5
52.7	61	-1.7
51.5	50	-1.5
52.2	51	-1.2
43.4	43	- .4
50.4	48	-2.4
52.2	51	-1.2
60.3	58	-2.3
60.4	56	-4.4
58.0	56	-2.0

$$\bar{d} = -1.5$$

$$s_d = 1.6$$

Loop No. 14

Timer a	Computer b	Diff. d=b-a
58.4	58	- .4
59.8	58	-1.8
54.2	53	-1.2
55.1	55	- .1
64.8	63	-1.8
57.1	58	.9
62.6	63	.4
59.4	58	-1.4
57.6	56	-1.6
52.3	52	- .3
52.8	51	-1.8
55.7	55	- .7
50.6	51	.4
59.5	59	- .5
60.5	60	- .5
49.3	49	- .3
43.6	42	-1.6
57.3	55	-2.3
60.8	60	- .8
60.4	59	-1.4
64.0	64	0
65.1	63	-2.1
50.5	50	- .5
41.0	40	-1.0
51.1	50	-1.1
		$\bar{d} = -0.9$
		$s_d = 0.8$

Loop No. 15

Timer a	Computer b	Diff. d=b-a
46.0	45	-1.0
50.6	51	.4
56.6	56	- .6
62.0	62	0
55.7	54	-1.7
56.1	56	0
44.0	42	-2.0
57.0	58	1.0
55.2	53	-2.2
45.4	44	-1.4
43.4	41	-2.4
43.4	43	- .4
33.0	32	-1.0
44.0	43	-1.0
		$\bar{d} = -0.9$
		$s_d = 1.0$

Appendix H

VOLUME-TIME RELATIONSHIP - HIGHWAY NO. 37

ALSO INCLUDES STATE ROADS 45, 46, 48

Table H.1 Volume-Time Relationship - Highway No. 37

Hour Ending	LOOP #0				LOOP #1			
	Mon.- Thur.	Fri.	Sat.	Sun.	Mon.- Thur.	Fri.	Sat.	Sun.
1	75	92	172	194	39	46	98	94
2	48	54	112	137	26	32	61	60
3	44	54	98	81	27	36	60	39
4	20	27	51	48	11	15	34	29
5	21	24	38	34	12	13	23	19
6	31	35	48	26	18	18	26	14
7	117	116	74	41	89	88	46	20
8	199	204	153	72	123	127	84	43
9	211	205	208	113	123	110	128	79
10	247	257	327	212	151	152	200	165
11	293	305	418	280	177	178	240	203
12	334	345	508	379	177	180	286	250
13	370	390	557	415	193	198	311	282
14	336	365	492	386	179	204	299	283
15	349	399	454	379	208	233	285	284
16	418	471	463	387	244	260	286	281
17	594	651	473	388	407	421	291	288
18	575	662	458	393	329	405	274	270
19	351	493	384	363	205	298	248	242
20	309	476	371	337	167	280	233	220
21	308	490	385	315	157	292	226	203
22	304	448	387	249	148	273	216	133
23	206	312	282	188	89	177	135	89
24	111	192	235	103	48	93	102	55
Total ADT	5,871	7,067	7,148	5,520	3,347	4,129	4,192	3,645

Table H.1 (Continued)

Hour Ending	LOOP #2				LOOP #3			
	Mon.- Thur.	Fri.	Sat.	Sun.	Mon.- Thur.	Fri.	Sat.	Sun.
1	59	71	126	106	54	62	117	101
2	29	35	69	69	26	34	67	70
3	40	51	78	43	36	43	68	41
4	14	17	36	31	12	16	31	26
5	17	18	28	20	15	16	24	18
6	24	25	33	16	23	23	30	14
7	95	94	52	22	98	96	51	21
8	126	133	87	45	117	119	80	41
9	131	122	130	84	120	115	126	81
10	153	159	198	180	148	148	188	181
11	179	170	231	220	167	169	219	210
12	177	192	300	268	167	183	260	249
13	194	206	331	308	174	181	287	276
14	186	212	314	308	170	193	268	283
15	217	242	300	300	190	218	252	275
16	277	320	318	315	261	307	272	286
17	568	614	332	320	517	543	295	298
18	365	448	299	305	312	389	257	285
19	230	315	274	277	199	298	238	256
20	185	307	269	259	159	279	230	231
21	176	331	277	221	137	240	179	176
22	167	287	253	171	122	199	150	130
23	110	203	160	109	89	174	127	96
24	56	119	120	57	48	97	109	56
Total ADT	3,775	4,691	4,615	4,054	3,361	4,142	3,925	3,701

Table H.1 (Continued)

Hour Ending	<u>LOOP #4</u>				<u>LOOP #5</u>				
	Mon.- Thur.	Fri.	Sat.	Sun.	Mon.- Thur.	Fri.	Sat.	Sun.	
1	54	60	118	153	34	38	65	90	
2	41	45	112	138	28	32	63	88	
3	20	22	61	86	14	12	25	35	
4	24	24	40	43	15	14	17	15	
5	39	34	36	24	29	23	21	12	
6	88	82	62	29	59	49	37	15	
7	335	338	151	52	216	218	89	32	
8	597	573	250	81	336	335	141	47	
9	376	383	325	111	209	204	174	64	
10	323	327	422	233	178	180	216	124	
11	310	321	490	282	173	181	262	177	
12	337	368	496	339	168	182	245	235	
13	340	375	410	376	172	186	219	263	
14	336	363	410	381	177	198	231	268	
15	331	351	394	401	189	184	233	298	
16	362	418	407	447	213	230	244	333	
17	392	437	423	507	232	252	241	387	
18	343	428	405	522	193	228	231	375	
19	341	420	412	507	176	242	238	360	
20	330	399	417	469	161	241	234	306	
21	270	358	378	383	124	184	206	244	
22	235	292	336	281	107	134	172	176	
23	163	247	249	205	74	112	136	134	
24	88	169	182	108	44	83	95	62	
Total ADT	6,075	6,834	6,986	6,158		3,321	3,742	3,835	4,140

Table H.1 (Continued)

Hour Ending	LOOP #6				LOOP #7			
	Mon.- Thur.	Fri.	Sat.	Sun.	Mon.- Thur.	Fri.	Sat.	Sun.
1	39	42	72	111	28	32	51	70
2	31	37	73	106	17	17	33	44
3	15	15	32	44	13	11	22	28
4	16	15	19	17	15	15	17	16
5	34	28	26	14	33	26	24	13
6	66	58	43	18	60	53	39	16
7	435	426	130	39	437	430	117	34
8	467	452	162	50	392	381	135	44
9	216	200	179	70	185	180	153	62
10	182	182	225	149	162	160	194	127
11	174	190	263	192	159	178	224	180
12	175	182	248	251	154	159	214	233
13	171	184	222	290	157	166	201	272
14	183	201	234	285	170	178	207	264
15	209	223	250	315	195	209	221	307
16	237	249	263	368	205	233	227	350
17	247	267	251	418	220	250	219	388
18	205	255	252	418	188	225	225	397
19	188	258	251	400	168	233	226	362
20	168	247	247	343	142	226	222	316
21	132	189	220	270	115	172	203	257
22	119	148	192	203	104	129	169	183
23	86	126	159	149	75	100	128	140
24	47	91	109	75	39	57	81	53
Total ADT	3,842	4,265	4,122	4,595	3,433	3,820	3,552	4,156

Table H.1 (Continued)

Hour Ending	LOOP #8				LOOP #9			
	Mon.- Thur.	Fri.	Sat.	Sun.	Mon.- Thur.	Fri.	Sat.	Sun.
1	68	72	128	158	67	70	123	154
2	48	46	103	101	47	45	104	98
3	27	28	66	57	26	27	64	56
4	23	23	48	37	23	21	47	37
5	24	24	44	31	23	24	43	30
6	41	41	81	39	39	40	83	38
7	207	202	128	65	207	201	123	58
8	334	307	177	87	329	311	173	86
9	318	285	292	143	314	274	271	147
10	321	273	381	257	313	266	365	252
11	319	288	418	353	303	278	412	350
12	306	291	456	471	301	287	438	478
13	301	302	413	506	293	288	404	497
14	294	313	408	504	284	297	386	490
15	289	316	387	488	282	296	383	467
16	303	349	403	441	286	323	380	416
17	338	379	401	437	325	368	390	416
18	368	484	381	440	359	466	366	410
19	311	484	364	422	299	470	338	389
20	230	470	330	385	228	455	308	359
21	180	382	272	338	175	376	262	323
22	155	281	227	287	149	276	215	274
23	122	235	170	222	122	227	161	212
24	80	156	139	144	80	150	157	132
Total ADT	5,007	6,031	6,217	6,413	4,874	5,836	5,996	6,229

Table H.1 (Continued)

Hour Ending	<u>Loop #10</u>				<u>LOOP #11</u>			
	Mon.- Thur.	Fri.	Sat.	Sun.	Mon.- Thur.	Fri.	Sat.	Sun.
1	59	58	113	138	61	58	116	150
2	40	39	85	90	42	43	87	91
3	23	21	57	49	23	21	56	50
4	20	18	46	33	21	20	44	35
5	21	23	39	28	21	25	44	29
6	35	36	79	40	35	35	80	39
7	191	182	110	61	190	184	108	59
8	277	257	157	79	275	246	157	80
9	264	236	243	132	268	226	245	133
10	276	228	326	235	279	232	328	227
11	276	249	346	328	262	224	365	328
12	262	259	408	435	266	277	409	472
13	260	248	360	470	280	233	361	477
14	253	277	369	452	276	295	393	492
15	263	278	354	445	281	310	375	408
16	268	306	352	410	266	312	380	437
17	297	310	356	401	297	342	387	412
18	333	418	341	392	336	437	370	395
19	267	474	335	380	266	433	356	380
20	189	422	294	346	192	399	296	338
21	148	357	226	310	147	325	238	301
22	139	255	194	265	128	242	193	253
23	106	212	144	203	107	192	145	210
24	71	132	130	124	73	138	138	128
Total ADT	4,062	5,295	5,464	5,846	4,392	5,249	5,671	5,924

Table H.1 (Continued)

Hour Ending	LOOP #12				LOOP #13			
	Mon.- Thur.	Fri.	Sat.	Sun.	Mon.- Thur.	Fri.	Sat.	Sun.
1	57	59	99	116	57	59	102	116
2	37	38	57	76	38	38	57	77
3	28	32	45	49	29	32	45	50
4	24	25	33	30	24	24	34	30
5	36	32	32	23	35	34	32	23
6	84	75	58	25	83	74	56	25
7	200	192	108	50	205	195	108	47
8	258	243	125	72	252	235	128	70
9	233	225	182	114	233	231	179	114
10	243	240	261	205	237	243	258	206
11	247	258	318	275	248	256	320	274
12	269	319	338	333	265	311	344	334
13	291	380	383	386	290	380	378	391
14	310	411	403	448	311	417	406	445
15	323	395	369	473	327	372	364	491
16	342	415	378	550	335	428	382	582
17	423	493	365	652	433	451	374	679
18	364	457	373	665	371	477	366	691
19	239	320	350	632	242	325	341	651
20	182	251	317	538	181	255	328	562
21	167	236	290	446	166	236	280	453
22	157	217	238	328	157	215	238	326
23	126	160	202	226	126	161	200	231
24	72	110	155	114	73	113	161	117
Total ADT	4,712	5,583	5,479	6,726	4,718	5,562	5,481	6,985

Table H.1 (Continued)

Hour Ending	LOOP #14				LOOP #15			
	Mon.- Thur.	Fri.	Sat.	Sun.	Món.- Thur.	Fri.	Sat.	Sun.
1	51	51	94	106	52	57	100	98
2	34	34	49	69	35	34	56	68
3	27	29	40	44	26	25	40	42
4	21	24	32	27	20	24	31	25
5	32	29	30	20	32	28	29	21
6	78	67	52	23	79	73	53	22
7	191	181	99	44	197	182	103	52
8	204	194	121	67	204	195	124	71
9	209	202	166	100	206	202	169	101
10	214	216	236	193	213	215	237	197
11	224	234	297	253	224	245	279	255
12	236	273	338	325	247	293	310	309
13	250	330	373	372	261	361	345	360
14	269	370	389	429	280	411	362	406
15	304	356	351	448	294	378	335	469
16	299	368	365	548	292	399	349	537
17	395	400	357	611	379	407	327	650
18	314	423	327	646	321	412	333	606
19	222	271	270	544	219	301	311	625
20	155	224	302	533	160	222	316	559
21	150	227	271	437	141	223	270	437
22	144	200	226	321	134	197	227	336
23	114	148	183	225	114	142	178	234
24	62	113	133	100	70	112	142	124
Total ADT	4,199	4,964	5,101	6,485	3,806	5,138	5,026	6,604

Table H.2 Volume-Time Relationship for Other State Roads

Time Period	No. 46 East		No. 46 West		No. 45 East		No. 45 West		No. 48 West		
	301- 302	303- 307	401- 405	406- 409	501- 504	505- 509	601- 603	604- 609	701- 702	703- 704	705- 707
1 A.M.	252	37	117	69	56	17	126	98	114	34	32
2	42	56	36	48	21	11	127	42	67	24	14
3	72	42	58	32	17	4	44	56	20	24	21
4	102	18	24	19	12	6	46	19	44	10	10
5	65	15	31	21	7	8	22	23	56	10	9
6	28	25	53	15	16	6	56	53	86	16	8
7	168	96	229	148	48	21	560	368	174	254	24
8	518	142	339	91	107	23	460	238	622	204	81
9	539	204	248	128	104	38	396	161	342	172	60
10	505	188	296	156	125	30	262	199	588	146	59
11	526	195	324	231	164	29	332	174	425	148	61
12	457	256	376	216	137	45	309	176	706	151	76
1 P.M.	528	225	489	204	197	73	343	177	712	159	75
2	564	226	394	210	167	41	347	229	595	154	71
3	505	206	431	206	151	50	315	261	618	174	76
4	638	208	535	282	168	60	532	338	960	212	129
5	884	268	636	405	239	103	764	420	1,046	236	142
6	758	314	688	287	315	100	526	362	924	154	116
7	532	197	400	252	170	52	402	254	480	164	84
8	466	139	343	138	140	32	346	147	465	111	79
9	331	132	257	148	92	36	220	141	333	76	53
10	415	133	233	134	121	10	224	132	320	84	51
11	406	95	204	83	72	12	170	114	189	59	42
12	245	56	118	51	61	21	131	66	126	18	33
Total	9,540	3,473	6,859	3,574	2,707	828	7,060	4,248	10,012	2,794	1,406

6.H

