## Montana Department of Transportation Research Programs Helena, Montana

## **Annual Experimental Final Evaluation Report**

(Informal)

Project: Fairfield North & South, STPP 3-1(15)18; Teton County

Location: Highway 89 (P-3); C000003, MP 19-28

Evaluation Date: October 2007

Date Constructed: Fall 2001

Project Description: 60 mm Cold In-place Recycle, CMS-2 – 60 mm Plant Mix

Bituminous Surface

Report Origin: Craig Abernathy

Experimental Project Manager

## Evaluation

This project was constructed in the fall of 2001. This is the fifth and final annual inspection. Information reported is rut depth in each lane wheelpaths and visual distress mapping spaced at every milepost for 300 ft. (91.4 m). The test section starts at mile point 19 and ends a mile point 28. The base data for this project is as follows:

Average transverse cracking per mile has increase from 47 cracks-per-mile (CPM) to 56 CPM, with a standard deviation of 1.26. The majority of the cracks were sealed. The additional cracking since the fall of 2006 is low severity in nature. Little additional rutting was observed during this evaluation. Estimated average rut is around 6 millimeter on both lanes. Average IRI for both lanes is rated as fair (60).

Overall, surface appearance of the project is tight and uniform. Based on the crack and rut data, this project has been rated as performing well. Additional information on this project is available at the MDT Research website:

http://www.mdt.mt.gov/research/projects/fairfield.shtml

The following images are at each data location point, ten sites total.



















