
DISPLAY COPY DO NOT REMOVE





MODIFICATION AND EVALUATION of SENTRE IMPACT ATTENUATION DEVICES





MARCH, 1990

RESEARCH AND DEVELOPMENT DIVISION

OKLAHOMA DEPARTMENT OF TRANSPORTATION

TE228 .W25 1990 OKDOT Library

TECHNICAL REPORT STANDARD TITLE PAGE

1. REPORT NO. FHWA 90 (02)	2. GOVERNMENT ACCESSION NO.	3. RECIPIENT'S CATALOG NO.	
4. TITLE AND SUBTITLE "Modification and Eva	aluation of SENTRE	5. REPORT DATE	
Impact Attenuation I	Devices"	6. PERFORMING ORGANIZATION CODE Item No. 2719	
7. AUTHOR(S)		8. PERFORMING ORGANIZATION REPORT 10. WORK UNIT NO.	
Gary G. Williams, P.	E.		
9. PERFORMING ORGANIZATION AND ADI			
Oklahoma Department of Transportation Research & Development Division 200 N.E. 21st Street, Room 2A2		11. CONTRACT OR GRANT NO.	
Oklahoma City, Oklah		13. TYPE OF REPORT AND PERIOD COVERED	
12. SPONSORING AGENCY NAME AND ADDRESS		Final Report 1985 to 1988	
		14. SPONSORING AGENCY CODE	
15 SUDDI EMENTADY NOTES			

Done in cooperation with the Federal Highway Administration.

16. ABSTRACT

This report covers a study of SENTRE Impact Attenuation Devices, done to identify potential design or installation improvements, to make these improvements, and evaluate performance of the devices once the indicated modifications were made.

During the study, a total of 21 SENTRE devices were installed on I-40 in Oklahoma City. Ten accidents involving SENTREs were documented. Analysis of these accidents led to modifications in amount of torque applied to anchor bolts, type of clips holding posts to base plates, and depth of topsoil covering the redirecting cable.

The limited number of SENTRE installations, and the even more limited number of accidents precluded a statistical comparison of accidents involving SENTREs to those with exposed guardrail ends or other types of impact attenuation. In all of the accidents occurring after the modifications were made, the SENTRE units performed as the designers intended, suggesting that they were effective in reducing impact severity.

17. KEY WORDS Impact Attenuation De End Treatment, Guardr Terminals	18. DISTRIBUTION STATEME No restricti		
19. SECURITY CLASSIF. (OF THIS REPORT) None.	Assif. (Of this page) None。	21. NO. OF PAGES	22. PRICE

This publication was printed and issued by the Oklahoma Department of Transportation as authorized by Neal A. McCaleb, Director. 125 copies have been prepared and distributed at a cost of \$0.60 each.

The contents of this report reflect the views of the author who is responsible for the facts and the accuracy of the data presented herein. The contents do not necessarily reflect the offical views of the Department of Transportation or the Federal Highway Administration. This report does not constitute a standard, specification, or regulation. While company and product names are used in this report, it is not intended as an endorsement.

EXECUTIVE SUMMARY

The SENTRE impact attenuation device was evaluated by the Oklahoma Department of Transportation with two separate objectives. The first objective of the study was to determine if the devices were operating as their designers intended, to reduce accident severity when struck by vehicles, and if not, make the modifications necessary to "make the SENTRE's work".

As units were struck, their performance was analyzed, and areas where improvement was needed were identified. Modifications in installation procedure or unit design were then made to improve their performance. Modifications made under this objective included: changing torque requirements on anchor bolts, adding reinforcing clips to post bases, and specifying the amount of cover required over redirecting cables.

The second objective consisted of evaluating SENTRE performance, once necessary modifications were made. A total of 10 accidents involving the SENTRE units were documented during the study. The first five accidents included situations where performance of the units indicated the need for design or installation changes. The remaining five accidents were cases where the units performed as intended, suggesting that they were effective in reducing the accident severity.

TABLE OF CONTENTS

	Page
INTRODUCTION	1
INSTALLATION. Site Preparation	6 6
MODIFICATIONS	
COLLISIONS INVOLVING SENTRES	15
ACCIDENT STUDY	18
CONCLUSIONS	20
RECOMMENDATIONS	21
REFERENCES	22
APPENDICES Appendix A. Captioned Photographs	B-1 C-1

LIST OF ILLUSTRATIONS

- LEGIC NO.		1 age
1.	SENTRE Unit	2
2.	SENTRE Unit Locations	5
3.	SENTRE Unit, Straight and Flared	6
4.	Types of Posts	7
5.	"EASI" Remnforcing Clips	9
6.	MP3 Anchor Installation	10
	LIST OF TABLES	
Table No.		Page
I.	SENTRE Unit Locations	4
2 •	Accident Statistics	12
3.	Collisions Involving SENTRE Units	13
4.	SENTRE Component Costs	16
5.	Replacement Components Used	17

6.

Guardrail Accidents......18

INTRODUCTION

The Insurance Institute for Highway Safety reports that in 1988, 1,229 deaths could be attributed to collisions with guardrails mid. With the trend toward smaller cars, untreated guardrail ends pose a very serious threat.

Energy Absorption System's SENTRE end treatment had been tested under federal standards for impacts by light and heavy cars before ODOT's investigation began. ODOT's investigation was conducted with the intent of satisfying two objectives:

(1) identifying any design or installation characteristics which could be modified to achieve better unit performance, making these modifications, and (2) evaluating SENTRE performance under actual roadway conditions

A typical SENTRE unit installation is illustrated in Figure 1. The SENTRE reduces impact severity using a system of telescoping panels connected to the exposed end of a guardrail or barriern* The system gently slows an impacting vehicle while a redirecting cable guides the panels and the vehicle sideways, away from the guardrail "hard spot". Posts supporting the SENTRE unit are on slip bases which allow them to slide with the impact when hit. Also, SENTRE units have plastic sand containers

^{*}NOTE: This evaluation began in 1985. At that time, SENTRE units were used for protection on ends of both barriers and guardrail, with different transition rails used between the units and the protected structures. Since then, Energy Absorption Systems has developed the TREND unit to be used on barriers, while SENTRE units are now used only as end protection on guardrails.

mounted on the first three posts facing the traffic. These rupture during impact, which helps to dissipate the collision energy.

A total of 21 SENTRE units were installed on I-40 in Oklahoma City, at the locations shown in Table 1. Bid price per unit, which included installation by the contractor was \$4,100 each (\$86,100 total). This amount could probably be lowered somewhat on projects where larger numbers of SENTREs were installed.

Maintenance and repair of the units has been done by the ODOT Interstate Maintenance Unit, 2901 East Reno, Oklahoma City.

Figure 1. SENTRE Unit.





Table 1. SENTRE Unit Locations

SENTRE Units on I-40 Eastbound

- 1. Entrance ramp onto eastbound I-40 from northbound I-44.
- 2. Immediately west of May Avenue Underpassn
- 3. Immediately east of May Avenue Underpass.
- 4. Agnew/Villa Avenue exit rampa
- 5. Immediately west of Agnew/Villa Avenue Underpassn
- 6. Agnew/Villa Avenue entrance ramp to eastbound I-40.
- 7. Immediately west of Pennsylvnia Avenue Underpassn
- 8. Virginia Avenue entrance ramp to eastbound I-40.
- 9. Immediately west of Western Avenue Underpass.
- 10. Western/Reno Avenue exit ramp (north side of ramp)n
- 11. Western/Reno Avenue exit ramp (south side of ramp)n
- 12. Reno Avenue entrance ramp to eastbound I-40.

SENTRE Units on I-40 Westbound

- 13. Immediately east of Western Avenue Underpassn
- 14. Immediately west of Sheridan Avenue ramp to westbound I-40.
- 15. Immediately east of Virginia Avenue underpass.
- 16. Pennsylvania Avenue entrance ramp to westbound I-40.
- 17. Immediately east of Agnew/Villa Avenue Underpass.
- 180 Agnew/Villa entrance ramp to westbound I-40.
- 19. May Avenue exit rampn
- 20. Immediately east of May Avenue underpass.
- 21. Exit ramp from westbound I-40 to northbound I-44.



PROJECT LENGTH = 2.224 MI.

5

INSTALLATION

Site Preparation

The appropriate location for a SENTRE guardrail/barrier end treatment includes an area extending forward from the end of guardrail or barrier, (see Figure 3 below) in the direction of oncoming traffic, for a distance of 20 feet. The site area should be level and free of obstruction. Any guardrail or posts extending into the site area should be removed.

Figure 3. Straight and Flared SENTRE Unit Locations.

Rear anchor

Front anchor

Front anchor

Front anchor

Offset from edge of roadway

Offset from edge of roadway

Flared Unit

Edge of roadway

Edge of roadway

Edge of roadway

Pad Construction

Each SENTRE unit is constructed on a 4'-0" x 18'-0" x 0'-7" design is illustrated reinforced concrete pad. Pad Appendix B. The first 3'-0" on the exposed end of the pad 3'-0" thick, the purpose of the thickened section is to furnish the weight and physical shape necessary for the pad to resist the specified the Special Provisions, collision forces in (Appendix F). Also, one end of the redirecting cable is anchored in the thickened section. Reinforcing steel must be placed accurately, (as shown in Appendix B), to avoid interference with concrete anchor bolts.

Rear Cable Anchor Unit


The rear cable anchor is located as shown in Figure 1. Although the original plans (Appendix B) show this embedded anchor set in concrete in a rectangular hole, this was later modified. The anchor unit hareware remains the same, but it is embedded in concrete poured in a four foot diameter augered hole. The additional concrete furnishes greater mass, since depth remains the same. Also, the hole can be augered, where the rectangular hole originally called for, had to be dug by hand.

Slip Base and Cable Anchor Installation

The SENTRE unit may be installed on either straight guardrail or on guardrail that has been flared away from the traffic (see Figure 3).

Two different types of slip bases are specified for SENTRE units (Figure 4). The slip bases for posts 1 and 2 have flared slots, allowing for easier slip if hit at an angle. Posts 3, 4, and 5 have straight slots.

During installation, the bases are arranged next to the proper post locations before proceeding to the anchoring process. The slip bases should be installed so that the ramp ends touch the slab.



MODIFICATIONS

Anchor Footing Elevations

During the evaluation period, some SENTRE units failed to operate properly because the posts did not slide along the directing cable as the designers intended. Investigation determined that this was due to the rear footings of many units being installed at improper elevations, leaving the cable buried under one foot or more of soil.


This problem resulted from footings being poured to existing shoulder elevations at the time they were constructed. Later, as shoulders and slopes were "dressed" to their final elevations, the footings and cables were buried with whatever depth of soil was needed to shape the slope. Experience during the study, (after corrections were made), indicated that one to three inches of cover would not affect the performance of the units. To prevent the cables from interfering with maintenance mowing operations, this depth of cover should be provided.

Retro-fitting

Early in the evaluation period, many of the collisions involving the SENTRE units resulted in a failure of the anchor bolts to hold the base plates to the concrete pad. This was eliminated by a design change, made by the manufacturer. The "Molly Wedge" anchor bolts originally used, were replaced with Hilti MP3 anchors set in drilled holes, with "C-10" a two-part epoxy system. "EASI" reinforcing clips were installed on the

slip bases at the same time the MP3 anchors were installed. "EASI" clips, and instructions for their installation, are shown in Figure 5 on the following page. All SENTRE units being evaluated received these modifications. Instructions for installing MP3 anchors are reproduced in Figure 5. Another factor which contributed to unit failures early in the evaluation period, was that pinch bolts were frequently over-torqued by the installation crews, making it impossible for the slip bases to function as intended. Pinch bolts should have been torqued to between 60 and 70 ft-lbs. In most cases, they were uniformly torqued to 125 ft-lbs. This was corrected during the retro-fit phase. This effect can be seen from the collision listing, Table 3, page 13.

Figure 5. TypicadeNTRE Reinforcing Clip Installation.



Step 1: Thoroughly clean area surrounding posts to expose a flat concrete surface and post base plate.

Step 2: Remove nuts and washers on the (4) existing expansion anchors through base plate. (Do not remove slip base bolts.)

3: Position reinforcing clips over the edges of the plate so that the slotted holes fit over the existing expansion anchor studs then push the clips as close to the base plate as possiblee and


Step 4: If possible, replace the expansion anchor washers nuts and torque them down to hold the clips firmly in positione

Step 5: Using a rotary impact concrete drill with a depth drill through the large holes in the clips a of 6 +/- 1/4" as measured from the surface of the concrete. Drill the holes at an angle to avoid interfering the existing fender panels and sandboxes. The holes must obeh drilled to a depth of 5 3/4" minimum, cutting rebar may be required.


Step 6: Throroughly blow out the concrete dust from the hole, brush the hole and then blow it outagain. Install stals 7 1/2" long 3/4" diameter Grade 5 HD galvanized with the polyester chemical, carefully following the instructions on the package. Under no circumstances should the study project more than 2" above concrete surface.

Step 7: When the polyester chemical has cured (see package instructions) torque the anchors to 125 +/- 5 ft/lbs to firmly secure the reinforcing clips.


Step 8: Conduct steps 1-7 for all posts on the ENTRE.




CAUTION: 1) to not allow contact with the skin or eyes (wear protection). Use in well wentilated area, 2) in hot weather, over 90 deg. F, keep kit cool until immediately before use, 3) in cold temperatures, below 60 deg. F, keep kit warm until immediately before use (pot life at 90 deg. F = 15 min, at 75 deg. F = 30 min, at 61 deg. F = 60 min, at 45 deg. F = 130 min)




Pour MP3 MIX down into the clean hole through the part to be aichored, fill the hole approximately 1/3 - 1/2 full. Do not over or under fill.




Position the part to be anchored according to the plans supplied with the unit. Drill the holes to the correct size and depth (1/8" larger than anchor diameter) following the recommendations on the plans. (NOTE; denot use a diamond drill as full strength may not be achieved). Check to be sure all the holes line up with the part to be anchored.




Force the stud through the part being anchered down into the grouted hole leaving enough stud exposed to attach the nut and washer. Give the stud several twists to wet the threads.




IMPORTANT: Brush the hole with a stiff bristled brush and blow it clean with oil-free compressed air to remove the concrete dust.



Remove the lids from the MP3 part A - Resin and part B - Hardener containers. Pour part B - Hardener into part A - Resin then mix vigorously and thoroughly for 30 seconds. (An anchor stud makes a suitable stirring rod)



Place a flat washer onto the stud then thread a nut on until it is flush with the top of the stud. Do not disturb the stud until the material has hardened.



Once the material has hardened, torque the nut to the values indicated in the plans.

Figure 6. How to Use MP3 Anchors.

COLLISIONS INVOLVING SENTRES

Individual collisions in which SENTRE units were hit during the study are listed on Table 3, page 13. Observations regarding the accidents and performance of the units, which led to corrective actions taken during the retro-fit phase, are included, as are actions taken.

Statistics regarding the ten accidents occurring during the study are listed in Table 2 below. It is the opinion of the author that dollar amounts for damages to attenuators could be lowered with installation of a greater number of units.

Table 2. Accident Statistics - Damages Due to Vehicle Impacts

	ESTIMATED DAMAGE TO IMPACTING VEHICLE (1)	DAMAGE TO ATTENUATOR (2)	TOTAL DAMAGE	
Average	\$3,800	\$ 950	\$4,750	
Median	\$5,000	\$ 566	\$4,165	
Minimum	\$1,150	\$ 169	\$1,669	
Maximum	\$8,000	\$2,665	\$8,300	

⁽¹⁾ Estimated by Oklahoma Highway Patrol Trooper investigating accident.

NOTE: Average, Median, Minimum and Maximum damages to vehicle and attentuator did not occur during the same accidents.

⁽²⁾ From ODOT Maintenance Crew records. Includes labor.

Table 3. Collisions Involving SENTRE Units

DATE	DESCRIPTION	SENTRE PERFORMANCE	CORRECTIVE MEASURES
4-26-85	Unit at Virginia St. & I-40 (east bound) hit.	Posts did not come off slipbases as intended. Pinch bolts were overtorqued.	Manufacturer had anchor bolts on all units torqued to 65 ft-lbs.
12-13-85	Unit at May & I-40 (eastbound) hit.	Posts did not come off slipbases. 1st post was torn off anchor plate.	None. This was considered to be due mainly to the angle of the collision.
8-25-85	Unit at Air Depot & I-40 (eastbound) hit.	Posts did not come off slipbases. Anchor plate was pulled out of concrete pad.	Manuafacturer was notified that earlier corrections didn't solve the problem.
8-17-86	Unit at Engle Rd. & I-40 (eastbound) hit.	Anchor bolts failed.	Manufacturer notified. They decided to retrofit at this point.
4-26-87	Unit at Klein & I-40 (eastbound) hit.	Slipbases performed as intended, but cable was buried too deeply for posts to slide down it.	ODOT Mainten. crew will raise cables when their workload allows.
5-12-87	Unit at Klein & I-40 (eastbound) hit.	Car hit unit on nose & rolled down backslope. Only the 1st two posts came off the slipbasesc Both posts were bent.	None. Angle of impact appears to be the reason unit performed as it did.
7-4-87	Unit at Virginia Ave. & I-40 (east bound) hit.	Unit was hit on nose. Car rolled over after hitting it. Uni collapsed as intended Front 2 posts bent, but did slide off bases. Six anchor bolts pulled out.	t

Table 3. Collisions Involving SENTRE Units (Continued)

DATE	DESCRIPTION	SENTRE PERFORMANCE	CORRECTIVE MEASURES
8-24-87	Unit at Sunnylane Rd. & I-40 (east bound) hit.	Unit collapsed as intended. Two posts were bent.	None.
12-15-87	Unit at Reno & I-40 (westbound) hit.	Unit collapsed as intended. Two posts were bent.	None.
12-15-87	Unit at Klein & I-40 (eastbound) hit.	Unit collapsed as intended. Three posts were benta	Nonec

Repairs After Collisions

When the evaluation began, it was thought that maintenance costs might be lowered with the use of SENTRE units. This was based on the assumption that most principal components could be repositioned and reused after most impacts. According to the ODOT maintenance crew who did the repair work after collisions involving the units, and their records, their experience did not show this.

Except for the pad, redirecting cable, and cable anchor which were not damaged during any of the accidents, all components actually involved in the collisions had to be replaced with new parts. Essentially, the only reuseable parts were those located far enough from the point of impact (i.e. Post 5, when first impact occurred on the nose), so that they were not affected.

Typically, fender panels and posts bend, even when they do telescope and come off slip bases as designed.

Also, a crew of three to five men is required for repairs, which in our experience, took approximately half a day. This amount of time is required because units must be disassembled for repairs, then reassembled with new componenents replacing those which are damaged.

Repair Costs

Components of a single SENTRE unit, and their cost, as of April 21, 1988, the date of ODOT's last replacement parts order, are listed in Table 4 on the following page. Nuts, bolts, washers, etc. are not listed. For a complete listing, including all hardware, see Appendix B.

Table 4. SENTRE Component Costs

NO.	COMPONENT	UNIT COSTS	TOTAL COSTS
1	Nose Cover	\$ 65.00 ea.	\$ 65.00
1	Post, No. 1	\$ 95.00 ea.	\$ 95.00
1	Post, No. 2	\$ 85.00 ea.	\$ 85.00
1	Posts, No. 3, 4 & 5	\$ 65.00 ea.	\$ 195.00
5	Blockouts	\$ 20.80 ea.	\$ 104.00
4	Sand Containers, 100 lb.	\$ 45.50 ea.	\$ 182.00
2	Sand Containers, 150 lb.	\$ 58.50 ea.	\$ 117.00
2	Base Plates, No 1 & 2	\$ 31.50 ea.	\$ 63.00
3	Base Plates, No. 3, 4 & 5	\$ 19.50 ea.	\$ 58.50
5	Bolt Keeper Plates	\$ 11.70 ea.	\$ 58.50
1	Redirecting Cable, 25' (threaded both ends)	\$299.00 ea.	\$ 299.00
5	Thrie Beam Fenders	\$279.50 ea.	\$1,397.50

NOTE: Based on prices as of April 21, 1988.

Numbers of individual components actually used for replacement during the study (other than nuts, bolts and washers), are tabulated on page 12. Note that 14 nose covers and hazard markers were used when only 10 collisions were reported. Also, some of the sand containers replaced were damaged by vandalism in addition to those damaged by vehicle impacts.

Table 5. Replacement Components Used

NUMBER USED	COMPONENT
33	100 lb. Sand Containers
12	150 lb. Sand Containers
23	Blockouts
14	Nose Covers
14	Hazard Markers
11	Fender Panels
10	Post No. 1
6	Post No. 2
8	Posts No. 3, 4, & 5
2	Base Plates

ACCIDENT STUDY

In an attempt to compare accident history prior to installation of the SENTRE devices to that after installation, a study of fixed object accidents covering the area where the SENTREs were installed was requested from the ODOT Traffic Engineering Division. Time periods used in compiling this information were: April 25, 1982 through April 25, 1985, and April 26, 1985 through April 26, 1988. This represented roughly three years before SENTRE installation, and three years after. These tabulations are shown in Appendix E.

Information regarding guardrail accidents, extracted from this study, is summarized in Table 6, below.

Table 6. Guardrail Accidents

TIME PERIOD	TOTAL NO. OF GUARDRAIL ACCIDENTS	TOTAL PROPERTY DAMAGE	NO. OF ACCIDENTS W/INJURIES	NO. OF ACCIDENTS W/FATALITIES
4-25-82 to 4-25-85	64	\$220,675	23 (35.9%)	2 (3.1%)
4-26-85 to 4-26-88	21	\$ 70,565	11 (52.4%)	0

It should be noted that construction was in progress during most of the 1985 - 1988 study period, on various parts of the study area. Speeds were lowered on some sections, some exits were closed, and some traffic was rerouted. These factors contributed to less traffic, and less accident exposure over much of the

second half of the study period. These factors are the likely reason for the marked reduction in property damage, injuries, and fatalities.

As can be seen from Table 6, the percentage of the guardrail accidents resulting in injuries actually increased, although the number of accidents decreased.

The first five accidents involving SENTRE units ocurred during the phase of the study when the units were being developed, and modifications discussed earlier, were made after accidents ocurred. The next five accidents ocurred after all modifications had been made and no corrective action was required. Although the accident study could not show this statistically, it is the opinion of the author, that the SENTRE's did reduce accident severity. During the last five accidents (those ocurring after modifications), the units operated as the designers intended during every impact.

CONCLUSIONS

The modifications to the installation procedure, discussed earlier, are now addressed in the current version of the manufacturer's installation manual. The changes in the type of anchor bolts and reinforcing clips used are now standard features.

It is an important point that pinch bolts must be torqued to between 60 and 70 ft-lbs, or slip bases will not function properly. This has also been addressed in the current installation manual.

Although the number of collisions occurring after modifications was limited, SENTRE unit performance during those collisions suggests that the SENTREs do contribute to reducing accident severity.

Repair of the units, once a collision has occurred, can be expected to require approximately four hours, for a three to five-man crew. Also, repairs done during the study indicate that any components actually involved in the collision must be replaced. With the exception of the pad, redirecting cable, and cable anchor, the only reuseable parts are those located far enough from the point of impact so that they are not affected. To repair a SENTRE, the entire unit must be disassembled, the damaged parts replaced, then the unit must be reassembled.

RECOMMENDATIONS

- Consideration should be given to using SENTRE units on future projects where guardrail end protection is desired.
- 2. Installation of SENTRE units should be planned, and then checked by construction inspectors, to insure that the redirecting cable anchors are placed at the proper elevation, so that the cable has 1 to 3 inches of cover.
- 3. A torque wrench should be used during installation of slip bases. Nuts holding slip bases should be tightened to between 60 and 70 ft - lbs torque. This should be checked by inspectors during construction.
- 4. Maintenance forces attempting to estimate numbers of components for repair stockpiles should consider:
 - a. Nose covers and hazard markers can be expected to require replacement in 100% of the accidents involving SENTREs.
 - b. Sand containers may be damaged by vandalism as well as by vehicle impacts.
 - c. Components placed toward the end of the unit facing traffic are more likely to sustain damage, and require replacement than those on the "transition" end.

REFERENCES

- 1. IIHS Facts 1989, Insurance Institute for Highway Safety, July, 1989.
- SENTRE (Safety Barrier End Treatment), NCHRP 230 Certifications Report, Energy Absorption Systems, Inc., May, 1983.
- 3. SENTRE Guardrail End Treatment, Installation Manual, Energy Absorption Systems, Inc., 1984.
- 4. Drawing Number 80-04-03, Concrete Pad Detail, Energy Absorption Systems, Inc., 1980.
- 5. MP3 Anchor Instructions, Hilti Corporation. 1984

APPENDIX A PHOTOGRAPHS



Figure 1. SENTRE unit after installation on guardrail end.




Figure 2. SENTRE unit after installation on barrier end.



Figure 3. Drilling holes for "MP-3" anchors during retrofit.




Figure 4c Placing 'MP-3" anchors after cleaning hole - retrofit phase.

* 0



gure 5. Reinstallation of slip base, retrofit phase.






Figure 7. After collision - unit functioned as intended.




Figure 8. Unit after collision - unit functioned as intended.



Figure 9. After impact, first three slip bases performed as intended.



Figure 10. SENTRE unit after impact. Slip bases failed to work due to over-torqued pinch bolts.




Figure 11. Slip base after impact, base did not perform.



Figure 120 SENTRE unit after impacto unit generally performed as intended, but anchor bolts were pulled out of slabo

APPENDIX B
SENTRE PLANS





12: A

PARTS LIST


TORQUE BUT TO 100 St-Lia














b linear Unless Otherwise Noted 11044 --

80000-01


č" '~


V4'. 1'.0"

181 6.


IJ

Motorial









APPENDIX C ACCIDENT STUDY

ANALO10. PRINT

ACCIDENT CONCENTRATION LISTING FOR IN-HOUSE USE COUNTYO (55) OKLAHOMA I-40 MAINLINE FIXED OBJECT ACCIDENTS FROM I-44 EAST TO SUNNYLANE

04-26-85 THRU 04-26-88

	LEINE TALE OBOL	٠.	~00	IULI	113 1 100	' • T	4 CAST TO SOIWITT	CAITC	`	J4 - 20 ·	-05	INKU (14-26-)
CS INT MI DIAG LOCATION	SPECIAL INT			W	PEOPLE	PROP	TYPE	CAUSE OF	CONDI	TIONS		
CITY # # POST CODE DESCRIPTION			D2		IN-FAT		ACCIDENT	ACCIDENT	LIGHT		SEV	DATE
						J.,,	200106111	ACCIDENT	LIGHT	NOAD	36.	UAIC
70 68 00 0029 00000 NOCANADIAN RI B	RO DGE NO	NW	NW	2		1650	F-O(BR POST)	UNSAF-SPD	DARK	IC-S	PD	12-10-85
70 68 00 0029 00000 N. DANADIAN RI B		Ε		2			F-O(RETN WALL)		DYLGT			02-08-86
70 68 00 0029 00000 N. CANADIAN RI B				1			F-O(RETN WALL)		DARK	WET		05-24-86
70 68 00 0029 00000 N. CANADIAN RI B				1			F-O(BR RAIL)	UNSAF-SPD	DARK	WET		09-29-86
70 68 00 0029 00000 N. CANADIAN RI B	RIDGE NO	W	W	2			F-O(RETN WALL)		DYLGT			09-30-86
70 68 00 0029 00000 N. CANADIAN RI B	RIDGE NO			1	1		F-O(RETN WALL)		DARK			10-05-86
(70) OKLAHOMA CITY I-40		ι T.				505		0.134, 3.0	UAIN	"".	1110	10 03 00
70 68 00 0030 00000	NO	E		1		700	F-O(RETN WALL)	INATT	DYLGT	DRY	PD	04-29-85
70 68 00 0030 00000	NO NO			1	1		F-O(GD-RAIL)	DEF-VEH	DYLGT			07-15-85
70 68 00 0030 00000	NO			- 1	1		F-C(RETN WALL)		DAWN			02-07-87
(70) OKLAHOMA CITY I-40		1.7						0.000	J		•	01 0, 0,
70 68 00 0037 00000	NO	F		1	*	2500	FT-O(RETN WALLO	IINSAF-SPD	DARK	IC-S	PN	12-03-86
(70) OKLAHOMA CITY I-40		- 5						J. J. J.	U A III I	., ,	٠٠	12 03 00
70 68 00 0038 00000	NO	_ _F _	1111	1		2500	F-O(RETN WALL)	LINSAF-SPD	DARK	WET	PD	09-28-86
70 68 00 0038 00000	NO			1			F-O(RETN WALL)		DARK	IC-S		02-16-87
70 68 00 0038 00000	NO NO			1			FIXED-O(OTHER)					03-24-88
(70) OKLAHOMA CITY I-40						1200	TALD O(OTTICK)	NO THE ACT	U.C.	UKI	FU	03 24 00
70 68 51 0042 00000		- _F -	. 1	1		2500	F-O(RETN WALL)	LINGAE - SPO	DARK	WET	חם	11-19-85
(70) OKLAHOMA CITY I-40						2300	T OUNCELL WALLY	ONSAL SLID	UAKK	75'	FU	1, 13 63
	ONSTRUCTION NO	Ε-	Е	2		675	F-O(RETH WALLO	FOL-CLOSE	DARK	DRY	PΠ	08-23-85
70 68 51 0048 00000	NO			1			F-O(RETN WALL)		DAWN	WEOT		11-727-85
(70) OKLAHOMA CITY I-40								3.7.	Dawit		, 0	11127 03
70 68 51 0051 00000	NO	- _w -		1		2675	F-O(RETN WALL)	UNSAF-SPD	DYLGT	DRY	PN	02-14-86
(70) OKLAHOMA CITY I-40	발길 하루 살아 되는 사람이 되고							3.13.27	0.00.	J.,,		ŭ
70 68 51 0058 00000	NO.	_ _w _		1		5050	FIXED-O(GTHER)	UNSAF-SPD	DARK	DRY	PD	09-07-85
(70) OKLAHOMA CITY I-40								3.0	•			
70 68 51 0059 00000	NO	_w_	100	1		125	F-O(RETN WALL)	NO-IMP-ACT	DYLGT	DRY	PD	03-10-86
(70) OKLAHOMA CITY I-40						177			7 1 7 7			, , , , , , , , , , , , , , , , , , ,
70 68 51 0068 00000	NO	-w	W	2		850	F-O(RETN WALLT	LINSAF - SPD	DYLGT	IC-S	ΡN	02-07-86
70 68 51 0068 00000	NO			1			F-O(RETN WALL)		DYLGT			02-07-86
70 68 51 0068 00000	NO.			1			F-O(RETN WALL)		DYLGT			02-07-86
70 68 00 068 00000	NO			•			FIXED-D(OTHERT)		DARK			02-16-87
70 68 51 0068 00000	NO			2			F-O(RETN WALL)					03-18-87
(70) OKLAHOMA CITY I-40						3300	F O(REIN WALL)	NO-TIME - ACT	DILGI	DKI	FU	03-16-67
70 68 51 0069 00000			<u> </u>	1	1	600	F-O(RETN WALLT	OTUED	DVLCT	DDV	TALL	12-18-85
(15) DEL CITY I-40	G	. "				600	F-U(REIN WALL)	UINER	DILGI	UKI	1140	12-10-65
15 68 00 0078 00000		- _w	<u> </u>	1		2200	F-O(RETN WALL)	LINICACOCOO	DVICT	IC-C	0.0	10 20 07
	11 / 12 / 13 / 14 / 15 / 15 / 15 / 15 / 15 / 15 / 15					2300	F-U(REIN WALL)	UNSAFOSPU	UTLGI	10-3	PU	12-28-87
(15) DEL CITY I-40		-w-				E400	5 0(CD 0ATL)	LINICAE - COD	DVICT	WET	7 8 1 1	44 07 07
	,	W		. 1	1	5400	F-O(GD-RAIL)	UNSAF-SPD	DYLGI	WEI	INO	11-27-87
(15) DEL CITY I-40	NO					5500	FIXED-O(OTHERT)	LINICA E - COO	DVLCT	DOV	DO	04-10-00
15 68 00 0080 00000 (15) DEL CITY I-40	Nº,			. 1		2500	LIYED-O(DIHEKI)	UNSAF-SPU	DYLGT	DRY	PU	04-19-88
15 68 00 0083 00000	NO						F-O(DETAL WALL)	O - W - 1	DVLCT	DDV	T & 1 I	06-20-86
	NU	2		1	1	400	F-O(RETN WALL)	U-#-1	DYLGT	UKI	TIAO	05-20-86
(15) DEL CITY I-40 15 68 00 0088 00000	NO	e				900	F-O(RETN WALL)	HAISAEDEDD	DVLCT	10-5	TAL	12-11-85
15 68 00 0088 00000	NO NO			1	1		F-O(RETN WALL)					04-17-86
15 68 00 0088 00000	NO NO											
	NU	₩.		1	1	10/5	F-O(GD-RAIL)	ONZAL - 2HO	DIEGI	WEI	TINO	06-04-86
	NO			-		700	C-O(DETN WALL)	NO THO ACT	DARK	0.7	0.0	00 12 05
15 68 00 0095 00000	NU	_		1		100	F-O(RETN WALL)	MO-IMP-ACI	DAKK	UI	טי	09-12-85
(15) DEL CITY I-40			-									

OKLAHOMA DEPARTMENT OF TRANSPORTATION ANALO10.PRINT

HIGHWAY TABULATION ACCIDENT CONCENTRATEON LISTING FOR IN-HOUSE USE COUNTYG (55) OKLAHOMA I-40 MAINLINE FIXED OBJECT ACCIDENTS FROM I-44 EAST TO SUNNYLANE

04-26-85 THRU 04-26-88

TRAFFIC ENGINEERING DIVISION

CS INT MI DIAG LOCATION SPECIAL CITY # # POST CODE DESCRIPTION FEATURES	INT REL		D2		PEOPLE IN-FAT		TYPE ACCRDENT	CAUSE OF ACCIDENT	CONDR 1		SEV	DATE
(70) OKLAHOMA CITY I-35			<u> </u>									
70 15 00 0613 00000 (70) OKLAHOMA CITY I-35	NO.		T. F		. 1	3125	F-O(GD-RAILC	UNSAF-SPD	DYLGT	IC-S	INJ	02-08-86
70 15 00 0614 00000 MILE 127	NO		ILE	12/		1400	5-0(CD-DAIL)	UNSAF-SPD	DARK	DRY	00	02-07-87
(70) OKLAHOMA CITY 1-35	140	-				1400	F-O(GO-RAIL)	UNSAF-SPU	DARK	UKT	PU	02-07-87
70 15 00 0616 00000	NO	_N_		1	1	600	F-O(BARRIER)	UNSAF-SPD	DARK	DRY	TMJ	11-03-86
(70) OKLAHOMA CITY I-35								3.13.1	J	J., .	0	03 30
70 15 00 0621 00000	NO	W	W	2		3450	FR-0 (CRETN WALL)	UNSAF-SPD	DARK	IC-S	PD	12-03-86
(70) OKLAHOMA CITY I-35				111		<u> </u>						
70 15 00 0641 00000	NO			1				NO-IMP-ACT				
70 15 00 0641 00000 CONSTRUCTION	NO	W		1	1	490C	FRO(RETN WALL)	D-W-I	DYLGT	DRY	INJ	06-27-87
(70) OKLAHOMA CITY I-35 70 15 00 0659 00000	10						5 0/50 0444 0					
(70) OKLAHOMA CITY I-35	NO	w		1		2000	F-O(GD-RAILR	UNSAFESPD	DYLGT	DRY	PD	08-30-87
70 15 00 0661 00000	NO	- _F -		1		2500	FIXED-O(OTHER)	∩-W-T	DARK	DRY	Pη	09-14-85
70 15 00 0661 00000 CONSTRUCTION				1			F-O(RETN WALL)		LIGHT	WET		11-25-86
70 15 00 0661 00000 CONSTRUCTION	NO	W		1			FGO (ORETN WALL)		DYLGT	DRY		11-06-87
(70) OKLAHOMA CITY I-35		<u> </u>		<u> 1911.</u>		<u> </u>						
70 15 00 0665 00000	NO	E	3.55	1		3450	FO(RETN WALL)	UNSAF-SPD	DYLGT	DRY	PD	07-19-86
(70) OKLAHOMA CITY I-35		<u> </u>	<u> 11111</u>			<u> </u>						
70 15 00 0670 00000	NO	W		1	1	1250	F-O(GD-RAIL)	INATT	DYLGT	DRY	INJ	12-19-85
(70) OKLAHOMA CITY I-35						<u> </u>						
70 15 00 0672 00000	NO			1			F-O(RETN WALL			WET		04-29-85
70 15 00 0672 00000	NO	E		1		2500	F-O(RETN WALL)	UNSAF-SPD	DYLGI	DRY	PU	07-24-85
(70) OKLAHOMA CITY I-35 70 15 00 0673 00000 CONSTRUCT®ON	NO	<u>.</u>		1		750	F-O(RETN WALL)	ENI -CLOSE	DVDCT	DRY	0.0	04-22-87
(70) OKLAHOMA CITY I-35		"				730	F-U(REIN WALL)	FUL CLUSE	UTRGI	UKT	PU	04-22-67
70 15 00 0674 00000	NO	_ _F _		1		1000	F-O(GD-RAIL)	NO-IMP-ACT	DYLGT	WET	PD	07-17-87
70 15 00 0674 00000	NO		Ε		1		FIXED-0(OTHER)					07-17-87
(70) OKLAHOMA CITY I-35												
70 15 00 0678 00000	NO	Ε_		1		700	F-O(RETN WALL)	UNSAF-SPD	DYLGT	WET	PD	06-05-85
(70) OKLAHOMA CITY I-35		<u> </u>										
70 15 00 0681 00000	NO			1			F-0(RETN WALL)					09-09-85
70 15 00 0681 00000	NO		W	2			F-O(RETN WALL)					03-07-86
70 15 00 0681 00000	NO		W	2			F-O(RETN WALL)					04-03-86
70 15 00 0681 00000	NO				1		F-O(GD-RAILR	NO-IMP-ACT				05-19-86
70 15 00 0681 00000 CONSTRUCTION	NO	W		1		400	F-O(RETN WALL	MO-IMP-ACT	DYLGI	WET	PD	07-17-87
(70) OKLAHOMA CITY I-35	NO			- 1		2000	C 0/00 0100)	UNCAE - COD	LICUT	DDV	- A -	07-29-86
70 15 00 0691 00000 70 15 00 0691 00000 CONSTRUCTION				1	1 1		F-O(BR PIER) F-O(RETN WALL)	UNSAF-SPD				12-19-86
70 15 00 0691 00000	NO			1			F-O(GD-RAILR	NO-IMP-ACT				1.2-02-87
			ENO		R OP *:		1 O(GD KAILK	1.0 1 25.	01.23.	UNI		02 0.
70 15 52 0699 00000 REND AVEC OP BRIDGE	NO				1	and observed to	F-O(GD-RAILR	UNSAF-SPD	DARK	WET	INJ	10-30-87
70 15 52 0699 00000 RENO AVEC OP BRIDGE	NO			1			F-O(RETN WALL)		DARK			12-13-87
(70) OKLAHOMA CITY I-35												
70 15 11 0721 00000	NO	_w_		1		2500	F-O(GD-RAIL)	NO-IMP-ACT	DARK	WET	PD	12-15-86
(70) OKLAHOMA CITY I-40			. CAN	IDA	AN RIVE	BRR						
70 68 00 0029 00000 N.CANADIAN RI BRIDGE	NO			- 1			F-O(GD-RAIL)	INATT	DARK	DRY		05-04-85
70 68 00 0029 00000 NRCANADIAN RI BRIDGE	NO			1			F-0(RETN WALL					05-04-85
70 68 00 0029 00000 N. CANADIAN RI BRIDGE	110	W		1		900	F-O(RETN WALLE	UNSAF-SPD	DYLGT	IC-S	PD	11-27-85

OKLAHOMA DEPARTMENT OF TRANSPORTATION ANALO10.PRINT

HIGHWAY TABULATION

ACCIDENT CONCENTRATION LISTING FOR IN-HOUSE USE COUNTYO (55) OKLAHOMA I-40 MAINLINE FIXED OBJECT ACCIDENTS FROM I-44 EAST TO SUNNYLANE

04-2	C-05	THOLL	04-26	00
U4 2	0 00	THING	04-26	-00

TRAFFIC ENGINEERING DIVISION

CS INT MI DIAG	LOCATION SPECIAL DESCRIPTION FEATURES	INT REL [)1 D2		PEOPLE IN-FAT		TYPE ACCCDENT	CAUSE OF ACCIDENT	CONDI LIGHT		SEV	DATE
15 68 00 0097 00000		NO E		1		700	F-0(RETN WALL)	UNSAF-SPD	DYLGT	WET	PD	03-11-86
	-40											
15 68 00 0103 00000		NO E		1		3500	F-0 (RETN WALLO	D-W-I	DARK	DRY	PD	01-16-88
	<u>0-40</u>		-									
15 68 00 0104 00000		NO V	1	1		2500	FIXED-O(OTHER)	UNSAF-SPD	DYLGT	WET	PD	02-05-86
	-40											
15 68 00 0108 00000		NOON	1	1		2500	F-O(RETN WALL)	UNSAF-SPD	DARK	IC-S	PD	12-13-85
15 68 00 0008 00000	CONSTRUCTOO	N NO E		1		2500	F-OQRETN WALL)	UNSAF-SPD	DYLGT	DRY	PD	04-24-86
	-40											
15 68 00 0169 00000		NO V	1	1	2	4500	F-O(RETN WALL)	UNSAF OSPD	DYLGT	DRY	INJ	06-30-87
	-40		-									
15 68 00 0128 00000	CONSTRUCTION	NO E		1		2500	F-0(BETN WALLO	OTHER	DAWN	DRY	PD	08-23-85
	-40											
15 68 00 0152 00000	CONSTRUCTION	NO0N	1	1		2500	F-O(RETN WALLO	UNSAF-SPD	DYLGT	WET	PD	03-11-86
15 68 00 0152 00000		NO V	,	. 1		3000	F-O(RETN WALL)	UNSAF-SPD	DUSK	WET	PD	03-02-88
(15) DEL CITY I	-40											
15 68 50 0162 00000		N00 V	1	. 1		760	FICED-0(OTHER)	DEF-VEH	CYLGT	DRY	PD	02-09-88
(55) MIDWEST CITY I	-40											
55 68 50 0201 00000		NO W	1	1		700	F-O(RETN WALL)	UNSAFOSPD	DYLGT	WET	PD	05-10-86
(15) DEL CITY I	-40											
15 68 50 0203 00000		NO V	/	1	1	10500	F-0(RETN WALLO	UNSAF-SPD	DYLGT	IC-S	INJ	03-03-88
(70) OKLAHOMA CITY I	-40											
70 69 00 0579 00000		NO E		. 1	2	1700	F-0(BETN WALLO	OTHER	DARK	ORY	INJ	03-23-88
(70) OKLAHOMA CITY I	-40		12.1									
70 69 00 0584 00000		NO E		1		8620	F-O(GD-RAILD	D-W-I	DARK	WET	PD	02-26-87
(70) OKLAHOMA CITY I	-40											
70 69 00 0587 00000	CONSTRUCTION	N NO E		1	1	1350	FIXED-O(OTHER)	OTHER	LIGHT	DRY	INJ	10-03-87
(70) DKLAHOMA CITY I	-40											
70 69 00 0596 00000	CONSTRUCTION	NO E		1		4250	F-0(RETN WALLO	UNSAF-SPD	LIGHT	DRY	PD	09-07-87
(70) OKLAHOMA CITY I				AVE	. O.P.*							
70 69 00 0597 00000	MAY AVE. O.P. BRIDGE	NO E		1	1	600	F-O(RETN WALL)	DEF-VEH	DYLGT	WET	INU	10-21-86
(70) OKLAHOMA CITY I	-40											
70 69 00 0598 00000		NO E		1			F-0(RETN WALL)		DYLGT			06-22-86
70 69 00 0598 00000		NOOW	1	. 1	1	3000	F-O(RETN WALLO	D-W-I	DYLGT	DRY	INJ	02-04-88
(70) OKLAHOMA CITY I	-40		-									
70 69 00 0607 00000		NO V	1	1		900	F-O(RETN WALLO	UNSAF-SPD	DYLGT	WET	PD	08-04-85
(70) OKLAHOMA CITY 1	-40											
70 69 00 0617 00000		NO V	1	1		2850	F-O(RETN WALL)	UNSAF-SPD	DYLGT	DRY	PD	01-03-88
(70) OKLAHOMA CITY I	-40			1.5								
70 69 00 0637 00000		NO V		2	1 1		F-O(RETN WALLO		DYLGT			12-29-85
70 69 00 0637 00000	CONSTRUCTION	NO E		1.		3000	FIXED-O(OTHER)	UNSAF-SPD	DYLGT	DRY	PD	05-04-87
(70) OKLAHOMA CITY I	-40											
70 69 00 0643 00000		NO E		1			F-O(RETN WALL)		DUSK	WET		07-25-85
70 69 00 0643 00000		NO W	1	. 1		1500	F-O(RETN WALL)	UNSAF-SPD	DYLGT	IC-S	PD	01-17-87
(70) OKLAHOMA CITY I	-40											
70 69 00 0654 00000		NO E		1			F-0(RETN WALLD					02-08-86
70 69 00 0654 00000		N00 E		1	1	2600	F-O(RETN WALL)	NO-IMP-ACT	DYLGT	DRY	INJ	07-30-86
(70) OKLAHOMA CITY I	-40											
70 69 00 0663 00000 70 69 00 0663 00000		NOOW		1			F-O(RETN WALL)					
		NO E			1		F-O(RETN WALL)					

TRAFFIC ENGINEERING DIVISION

ANALO10 PRINT

ACCIDENT CONCENTRATION LISTING FOR IN-HOUSE USE COUNTY: (55) OKLAHOMA I-40 MAINLINE FIXED OBJECT ACCIDENTS FROM I-44 EAST TO SUNNYLANE

04-26-85 THRU 04-26-88

CS INT MI DIAG LOCATION SPECIAL CITY N N POST CODE DESCRIPTION FEATURES	INT REL	D 1			PEOPLE IN-FAT		TYPE ACCIDENT	CAUSE OF ACCIDENT	CONDIT		SEV	DATE
(70) OKLAHOMA CITY 1-40												
70 69 00 0669 00000	NO	W		1	1	2600	F-0(RETN WALL)	NO-IMP-ACT	DYLGT	DRY	INJ	08-26-85
(70) OKLAHOMA CITY I-40			<u> </u>			<u> </u>						
70 69 00 0673 00000	NO			1	1		F-0(RETN WALL)					08-25-85
70 69 00 0673 00000	NO			1			F-0(RETN WALL)					
70 69 00 0673 00000	NO	W	W	2	3	2850	F-0(RETN WALL)	IMP-LN-CHG	DYLGT	DRY	INJ	09-19-86
(70) OKLAHOMA CIOTY I-40												
70 69 00 0683 00000	NO	W		1		2500	F-O(RETN WALL)	UNSAF-SPD	DARK	WET	PD	10-17-85
(70) OKLAHOMA CITY 1-40												
70 69 00 0684 00000	NO			1			F-O(RETN WALL)			DRY		06-11-85
70 69 00 0684 00000	NO	E		1		750	FIXED-O(OTHER)	NO-IMP-ACT	DAWN	DRY	PD	09-02-87
(70) OKLAHOMA CITY I-40		—										
70 69 00 0694 00000	NO		W	2			F-O(RETN WALL)		DYLGT			09-13-85
70 69.00 0694 00000	NO			1			F-O(RETN WALL)					12-10-85
70 69 00 0694 00000	NO			1	1		F-O(RETN WALL)					03-23-86
70 69 00 0694 00000	NO			1			F-0(RETN WALL)		DARK			04-19-86
70 69 00 0694 00000	NO			1	1		F-O(RETN WALL)					12-03-86
70 69 00 0694 00000	NO			1	1		F-O(RETN WALL)					12-03-86
70 69 00 0694 00000	NO	Ł		. 1		1500	FIXED-O(OTHER)	DEF-VEH	DYLGT	DRY	PO	12-04-87
(70) OKLAHOMA CITY I-40				ببنين							• • • •	
70 69 00 0698 00000	NO	W		1	1	800	F-O(RETN WALL)	NU-IMP-ACT	DYLGI	10-5	INU	11-19-87
(70) OKLAHOMA CITY I-40	NO		<u> </u>	4		<u> </u>	T 0(DETH WALL)	LINCAE COD				04 00 00
70 69 00 0703 00000	NU	W				300	F-O(RETN WALL)	UNSAF-SPU	DAWN	WET	PU	04-02-86
70 69 00 0708 00000	NO			1		2500	F-O(RETN WALL)	LING A E - CDO	DVLCT	DRY	200	07 20 05
(70) OKLAHOMA CITY I-40	140		TOCI		RR OP*		F-U(REIN WALL)	ONSAL-250	DYLGT	UKT	PU	07-30-85
70 69 00 0717 00000 VIRGINA/RR OP BRIDGE	NO		IKGI	INA/	RR UP-		F-O(RETN WALL)	LINEAE - SDD	DYLGT	DRY	00	04-27-87
(70) OKLAHOMA CITY I-40	140	•		٠.'		1000	F-U(REIN WALL)	UNSAL SPU	DILGI	UKI	PU	04-21-61
70 69 00 0718 00000	NO			1		125	F-O(RETN WALL)	NO-IMP-ACT	DVICT	DRY	B D	03-28-86
(70) OKLAHOMA CITY I-40	140	•				123	F-U(REIN WALL)	INO-IMP-ACI	Olcai	URI	PU	03-28-66
70 69 00 0724 00000	NO	- _w		1		2000	F-O(RETN WALL)	NO-IMP-ACT	LICHT	WET	D.D.	03-02-88
(70) OKLAHOMA CITY I-40	140	•				3000	P U(REIN WALL)	NO-IMP-ACI	LIGHT	WEI	PU	03-02-68
70 69 00 0728 00000	NO	-		1		900	F-O(RETN WALL)	NO-TMP-ACT	DVLCT	DRY	DO.	02-04-86
(70) OKLAHOMA CITY I-40	140					300	F U(REIN WALL)	NO THE ACT	DILGI	UKI	FU	02-04-86
70 69 00 0737 00000	NO	- w		1		2500	F-O(RETN WALL)	DEE-VEH	DYLGT	DRY	ρŊ	02-25-86
70 69 00 0737 00000	NO			1			F-O(RETN WALL)		DYLGT	DRY		11-07-86
(70) OKLAHOMA CITY I-40	.,,					•••	· O(NEIN WALL)	J.,	Ditai	UK.	, ,	1, 0, 55
70 69 00 0745 00000	NO	-w-		1		2000	F-O(RETN WALL)	TNATT	DARK	DRY	PO	03-22-87
(70) OKLAHOMA CITY I-40						2000			DAKK	J.	٠٠	30 22 3 .
70 69 00 0747 00000	NO	-w				2500	F-O(RETN WALL)	NO-IMP-ACT	DYLGT	WET	PD	11-04-86
70 69 00 0747 00000 CONSTRUCTION	NO	N		1	3		F-O(GD-RAIL)	1-W-D				07-04-87
70 69 00 0747 00000	NO			1			F-O(RETN WALL)					12-26-87
70 69 00 0747 00000	NO			1			F-O(RETN WALL)					12-26-87
(70) OKLAHOMA CITY I-40												
70 69 00 0757 00000	NO	-w		1		2675	F-O(RETN WALL)	NEG-DRVING	DYLGT	DRY	PO	05-30-86
(70) DKLAHOMA CITY 1-40												
70 69 00 0765 00000	NO	E		1		4000	F-O(RETN WALL)	D-W-I	DARK	DRY	PD	01-06-87
(70) OKLAHOMA CITY I-40									~	J		- 0
70 69 00 0775 00000	ON	w-		1		2500	F-O(RETN WALL)	NO-IMP-ACT	DYLGT	DRY	PD	07-18-86
(70) OKLAHOMA CITY I-40												
				-								

TRAFFIC ENGINEERING DIVISION

HIGHWAY TABULATION ANALO10.PRINT ACCIDENT CONCENTRATION LISTING FOR IN-HOUSE USE COUNTYN (55) OKLAHOMA I-40 MAINLINE FIXED OBJECT ACCIDENTS FROM IN-44 EAST TO SUNNYLANE

04-26-85 THRU 04-26-88

CS INT MI DIAG LOCATION SPECIAL	INT			PEOPLE		TYPE	CAUSE OF	CONDIT	TIONS			
CITY # # POST CODE DESCRIPTION FEATURES	REL	D1 D2	٧E	IN-FAT	DMG	ACCIDENT	ACCIDENT	LIGHT	ROAD	SEV	DATE	
70 69 00 0785 00000	NO				2500	C 0(80 0411)	NO 1NO 101	041.07	004	20	07 44 05	
70 69 00 0785 00000	NO		1	1		F-O(BR RAIL) F-O(RETN WALLN	NO-IMP-ACT				07-11-85	
70 69 00 0785 00000	NO		1			F-O(RETN WALL)					02-14-86	
70 69 00 0785 00000	NO			1		F-O(GO-RAIL)	UNSAF-SPD				12-27-87	
(70) OKLAHOMA CITY I-40	110			*75		1 O(GO KATE)	ONTAL SED	LIGHT	10 3	1110	12 27 07	
70 69 00 0791 00000 RAMP 0.P. *75 BRIDGE	NO			1		F-O(GD-RAIL)	D-W-I	LIGHT	DRY	TNJ	04-26-87	
(70) DKLAHOMA CITY I-40									J. T.	1110	0. 20 0.	
70 69 00 0795 00000	NO	W	1		2500	FNO(NETN WALL)	NO-IMP-ACT	OYLGT	DRY	PD	08-23-85	
70 69 00 0795 00000	NO	W	1		125	F-O(RETN WALL)	UNSAF-SPD	DYLGT	WET	PD	11-13-85	
70 69 00 0795 00000 CONSTRUCTION	N NO	W E	2	5	39500	F-O(RETN WALL)	UNSAF-SPD	DYLGT	WET	INJ	05-24-87	
70 69 00 0795 00000	NO	W	1		900	F-O(RETN WALLIN	UNSAF-SPD	DYLGT	WET	PD	05-27-87	
70 69 00 0795 00000 CONSTRUCTION	NO NO	W	1		1550	F-D(RETN WALLC	UNSAF-SPD	DYLGT	WET	PD	06-09-87	
70 69 00 0795 00000 CONSTRUCTION	NO NO	W	1		12000	F-O(RETN WALL)	UNSAF-SPD	DYLGT	WET	PD	06-19-87	
70 69 00 0795 00000 CONSTRUCTION	NO NO	W	1.		100	FIXED-O(OTHER)	NO-IMP-ACT	DARK	WET	PD	07-29-87	
70 69 00 0795 00000	NO	W	1		2100	F-O(RETN WALL)	UNSAF-SPD	DYLGT	IC-S	PO	12-27-87	
(70) OKLAHOMA CITY I-40		_										
70 69 00 0798 00000	NO	Ε	. 1		8000	F-O(GD-RAIL)	UNSAF-SPD	DARK	DRY	PD	05-12-87	
(70) OKLAHOMA CITY I-40												
70 69 00 0801 00000 CONSTRUCTION			1	1		F-O(RETN WALLN		DYLGT			05-21-87	
70 69 00 0801 00000 CONSTRUCTION	NO NO		. 1			F-0(RETN WALL)	UNSAF-SPU	DARK	WET	PD	05-28-87	
(70) OKLAHOMA CITY I-40	110			EVATIO		C 0/MCTN WALL N	LINEAE COD	DVLOT	004	200	10 07 96	
70 69 00 0802 00000 BEGIN ELEVATI (70) OKLAHOMA CITY IG40	NO	E .	1		300	F-O(MRETN WALLIN	UNSAF-SPU	DYLGI	DRY	טיי	10-07-86	
70 69 00 0806 00000 CONSTRUCT®0	NO NO	-w-	1	2	5700	F-O(RETN WALL)	D-W-T	DARK	nev	T.N. t	07-23-87	
(70) OKLAHOMA CITY IG40	1 110			•	3700	I O(KEIN WALL)	•	DAKK	UKI	1140	07 23 37	
70 69 00 0815 00000	NO	-E	1		2300	F-O(RETN WALL)	UNSAF-SPD	DYLGT	WET	PD	03-17-87	
(70) OKLAHOMA CITY I-40												
70 69 00 0820 00000	NO	E	1		2500	F-O(RETN WALL)	UNSAF-SPD	DYLGT	WET	PD	05-26-86	
(70) OKLAHOMA CITY I-40												
70 69 00 0835 00000	NO	_E	1		700	F-O(RETN WALL)	NO-IMP-ACT	DYLGT	DRY	PD	07-23-86	
(70) OKLAHOMA CITY I-40												
70 69 00 0836 00000	NO	W	1		900	F-O(RETN WALLIN	DEF-VEH	DYLGT	DRY	PD	05-18-86	
(70) OKLAHOMA CITY I-40												
70 69 00 0840 00000	NO		. 1			F-O(RETN WALL)			DRY		04-19-86	
70 69 00 0840 00000	NO		1			F-O(RETN WALL)						
70 69 00 0840 00000 CONSTRUCT NO			1	1		FIXED-ONOTHERN						
70 69 00 0840 00000	NO		. 1 	1	1000	F-O(RETN WALL)	UNSAF-SPU	DAWN	10-5	INO	11-19-87	
(70) OKLAHOMA CITY I-40 70 69 00 0850 00000 WALKER O.P. BRIDGE	NO	_WALK	ERI	j.P.	1000	F-O(RETN WALL)	LINGAE COD	DYLGT	WET	00	06-09-87	
70 69 00 0850 00000 WALKER 0.P. CONSTRUCTION			1			F-O(RETN WALL)		DARK	DRY		10-15-87	
70 69 00 0850 00000 WALKER 0.P. CONSTRUCTION			1			F-O(RETN WALL)					11-14-87	
(70) OKLAHOMA CITY I-40								J. L.J.	J.C.	٠٠		
70 69 00 0852 00000	NO	-ε	1		2500	F-O(RETN WALL)	UNSAF-SPD	DYLGT	DRY	PD	09-10-86	
70 69 00 0852 00000	NO		1			F-O(RETN WALL)					01-24-88	
70 69 00 0852 00000	NO	Ε	1	1		F-O(RETN WALL)					03-11-88	
(70) OKLAHOMA CITY I-40												
70 69 00 0853 00000	NO	W	1	5.35.55	2200	F-O(RETN WALL)	NO-IMP-ACT	OYLGT	IC-S	PD	12-31-87	
(70) OKLAHOMA CITY I-40												
70 69 00 0854 00000	NO	E	1		500	F-O(RETN WALL)	UNSAF-SPD	DYLGT	WET	PD	07-25-85	
70 69 00 0854 00000	NO	Ε	1		800	F-O(RETN WALL)	UNSAF-SPD	DYLGT	IC-S	PD	11-19-87	

TRAFFIC ENGINEERING DIVISION

COUNTYE (55) OKLAHOMA

ACCIDENT CONCENTRATION LISTING FOR IN-HOUSE USE
I-40 MAINLINE FIXED CBUECT ACCIDENTS FROM I-44 EAST TO SUNNYLANE

04-26-85 THRU 04-26-88

CS INT MI DIAG # PEOPLE PROP LOCATIFON SPECIAL INT TYPE CAUSE OF CONDITIONS CITY # # POST CODE DESCRIPTION FEATURES REL D1 D2 VE IN-FAT DMG **ACCIDENT** LIGHT ROAD SEV DATE ACCIDENT (70) OKLAHOMA CITY 1-40 70 69 00 0859 00000 NO E 800 F-0 (RETN WALL) UNSAF-SPD DYLGT IC-S PD 11-19-87 (70) OKLAHOMA CITY I-40 70 69 54 0875 00000 NO E 500 F-0(RETN WALL) NO-IMP-ACT DYLGT DRY PD 08-20-86 70 69 54 0875 00000 CONSTRUCTION NO E 1 1 2000 F-O(RETN WALL) NO-IMP-ACT DYLGT: WET INU 02-05-87 70 69 54 0875 00000 Ť NO E 1050 F-0(RETN WALL) UNSAF-SPD DYLGT DRY PD 03-31-87 (70) OKLAHOMA CITY I-40 70 69 54 0876 00000 NO W 2675 F-0(RETN WALL) UNSAF-SPD LIGHT WET INJ 04-29-85 70 69 54 0876 00000 NO W 1 2 2600 F-0(RETN WALL) D-W-I DARK DRY INJ 12-31-85 70 69 54 0876 00000 NO W 1450 F-O(RETN WALL) UNSAF-SPD DYLGT IC-S PD 02-07-86 2 69 54 0876 00000 NO W 2500 F-0(RETN WALLA UNSAF-SPO DYLGT DRY PD 10-31-86 70 69 54 0876 00000 NO W 500 F-0(RETN WALL) DEF-VEH DYLGT WET PD 11-17-86 69 54 0876 00000 NO W 1500 F-0(RETN WALL) UNSAF-SPO DAWN IC-S PD 02-07-87 69 54 0876 00000 NO E 3000 FIXED-0(OTHER) UNSAF-SPD DARK IMPACT ATNUS WET PD 02-16-87 1 70 69 00 0876 00000 150 F-O(RETN WALL) NO-IMP-ACT DYLGT DRY INU 07-02-87 NO W 1 1 70 69 54 0876 00000 NO W 1500 F-0(RETN WALL) UNSAF-SPO DYLGT WET PD 11-18-87 2 2 70 69 00 0876 00000 NO W 1200 F-0(RETN WALL) UNSAF-SPD DYLGT IC-S INJ 02-02-88 70 69 00 0876 00000 NO W 2000 F-0 (RETN WALL) UNSAF-SPD DYLGT WET PD 04-17-88 (70) OKLAHOMA CITY I-40 US-77 ROBINSON O.P. F77* 70 69 54 0879 00000 ROBINSON O.P. BRIDGE 2050 F-0(RETN WALL) UNSAF-SPD DARK IC-S INJ 12-28-87 NO E 1 1 (70) OKLAHOMA CITY I-40 2 1 70 69 00 0886 00000 NO W W 3400 F-0 (RETN WALL) UNSAF-SPD DARK IC-S INJ 03-03-88 (70) OKLAHOMA CITY I-40 70 69 00 0920 00000 NO E 1 2 800 F-C (RETN WALLE UNSAF-SPD LIGHT IC-S INJ 01-15-88 (70) OKLAHOMA CITY I-40 NO W 70 69 00 0929 00000 1000 F-0(RETN WALL) UNSAF-SPD DARK IC-S PD 02-07-87 (70) OKLAHOMA CITY I-40 NO E 70 69 00 0949 00000 2600 F-0 (RETN WALL F DEF-VEH DYLGT DRY INJ 10-13-86 70 69 00 0949 00000 CONSTRUCTION NO E 1750 F-O(BARRIERF) UNSAF-SPD DARK DRY PD 06-22-87 (70) OKLAHOMA CITY I-40 70 69 00 0971 00000 NO W 400 F-0(RETN WALL) UNSAF-SPD DARK IC-S PO 12-25-87 (70) OKLAHOMA CITY 1-40 CONSTRUCTION NO E 70 69 00 0980 00000 1500 F-0 (RETN WALL) UNSAF-SPD LIGHT DRY INJ 05-12-87 (70) OKLAHOMA CITY I-40 70 69 53 0989 00000 NO E DYLGT ORY 675 F-O(GD-RAIL) DEF-VEH PD 07-16-86 (70) OKLAHOMA CITY 1-40 70 69 53 0998 00000 NO W PD 02-09-86 900 F-0(RETN WALL) D-W-I DARK IC-S PD 02-13-87 CONSTRUCTION NO W 8000 F-0(RETN WALL) D-W-I DARK DRY 70 69 00 0991 00000 (70) DKLAHOMA CITY I-40 DRY INJ 06-09-86 70 69 10 0994 00000 CONSTRUCTION NO W. 2850 FIXED-0(OTHER) DEF-VEH DYLGT ORY INJ 09-01-87 CONSTRUCTION DARK 70 69 10 0994 00000 NO E 1 2 6400 F-0 (RETN WALL) D-W-I MILE 151 (70) OKLAHOMA CITY I-40 CONSTRUCTION NO W 3070 F-0(GD-RAIL) UNSAF-SPD DYLGT WET INJ 06-19-87 70 69 00 0999 00000 MILE 151 (70) DKLAHOMA CITY 1-40 70 69 00 1002 00000 NO E E DARK WET PD 08-23-85 2850 F-OCRETN WALL) UNSAF-SPD (70) OKLAHOMA CITY I-40 CONSTRUCTION NO E 2000 FIXED-0(OTHER) D-W-I DARK DRY INJ 06-22-87 70 69 00 1012 00000 (70) OKLAHOMA CITY I-40 CONSTRUCTION NO E 1000 F-0 (RETN WALL) UNSAF-SPD DYLGT WET PD 07-17-87 70 69 00 1020 00000 1

CIC

OKLAHOMA DEPARTMENT OF TRANSPORTATION

HIGHWAY TABULATION

TRAFFIC ENGINEERING DIVISION

ANALO10. PRINT

ACCIDENT CONCENTRATION LISTING FOR IN-HOUSE USE COUNTY: (55) OKLAHOMA I-40 MAINLINE FIXED OBJECT ACCIDENTS FROM I-44 EAST TO SUNNYLANE

04-25-82 THRU 04-25-85

Cooler, (Co) Greations		00000			VI 5 1 NO					J - 13	· • • •	0.7 _	_
CS INT MI DIAG LOCATION CITY # # POST CODE DESCRIPTION	SPECIAL FEATURES	INT REL ()1 D2		PEOPLE IN-FAT		TYPE ACCIDENT	CAUSE OF ACCIDENT	CONDI LIGHT			DATE	
(70) OKLAHOMA CITY I-40													
70 69 53 0986 00000		NO E	•	1	1	875	F-O(GD-RAIL)	NO-IMP-ACT	DARK	DRY	INJ	07-11-83	ı i
(70) OKLAHOMA CITY I-40	<u> </u>	<u> </u>	-			<u> </u>							
70 69 00 0989 00000		NO A	١	. 1		700	F-O(RETN WALLO	UNSAF-SPD	LIGHT	WET	PD	05-17-83	
(70) OKLAHOMA CITY 1-40													
70 69 00 0994 00000		NO E	:	1	1	2600	FIXED-O(OTHER)	D-W-I	DARK	DRY	LNJ	02-04-84	ř.
70 69 00 0994 00000		NO V	1	1		2500	F-O(RETN WALLE	UNSAF-SPD	LIGHT	DRY	PD	03-29-84	Ċ.
(70) DKLAHOMA CCTY I-40	<u> </u>	<u> </u>											
70 69 00 0998 00000		NO V	V	1		500	F-O(RETN WALL)	UNSAF-SPD	DYLGT	IC-S	PD	12-04-83	j
(70) OKLAHOMA CITY I-40				<u> 1886</u>		<u> </u>							
70 69 00 1001 00000		NO E		1		3050	F-O(GD-RAIL)	UNSAF-SPD	DYLGT	DRY	PD	03-10-84	Ċ.

TABULATION OF ACCIDENT DATA FROM 04-26-85 TO 04-26-88

RUN DATEA 01/19/89

I-40 MAINLINE FIXED OBJECT ACCIDENTS FROM I-44 EAST TO SUNNYLANE

PERSONS

STUDY LENGTH : .00

AC	CII	DEN	T S	EV	ERI	TY

		1	985			1	986			1	987			1	988			_1	989	
	FAT	INJ	P-D	TOTAL	FAT	INJ	P-D	TOTAL	FAT	INJ	P-D	TOTAL	FAT	INJ	P-D	TOTA L	FAT	INU	P-D	TOTAL
ACCIDENTS	1	9	31	41	1	16	49	66	1	24	44	69	100	7	9	16_	200		15.5	
PERSONS	1	11		12	1	20		21	<u>.: '- 1</u>	34		35		10	1	10		10 20 1	1. 1. 1.	
							S	TUDY TO	TAL (SE	VERIT	Υ)									
						FATAL			INJUR	Υ		PROPERTY	DAMA	GE	3	TOTAL				
		ACC	IDENTS	S		3			5	6	1	<u> </u>	33			192				

ACCIDENT TYPE & DAMAGE CAUSED

COLLISION		1	985			1	986	1 1 1 1 1 1		1	987			1 1	988			. 1	989	
TYPE	FAT	INJ	P-D	TOTAL	FAT	INJ	P-D	TOTAL	FAT	INJ	P-D	TOTAL	FAT	INU	P-D	TOTAL	FAT	LNJ	P-D	TOTAL
OVR-TRN(AN-RD)		5.5. N. L.					1.2 1.1	33.33			100		1. No. 1. 1.	7.11	5 5 5	18 18 18 18 18 18 18 18 18 18 18 18 18 1	1 1 1 1	11111	1 1 - 1	
PEDESTRIAN			4.55	4.5	3.7			3.10	11.11	1 2 1			100 B	2.2	3 5 5 5		1 1 1 1	3, 5,	5 T F	
PARKED-VEHICLE	T. 18	55,2	- (1-), F		11111	11.1	31 E 1		1.17	2.50			3.5	1.5	2.57			1.1	2.5	
RAILROAD-TRAIN		F 1.7	1.5				7.1	4, 4, 4			. 1 . 1	25 50 6 6	19.33	1 1 1	2010	tar filter	1.5	3.75		
ANIMAL	- 77	1.7.3.			- 1-11	11 / 1	1 1 1						250	1 1 1	1 1 1 1			11.5	1575	
FIXED-OBJECT	1 1	9	31	41	() (1)	16	49	66	√ . j. 1	24	44	69	400	i 7	: 9	16		5 - 1 - 2	2,53	<u> </u>
RAN-OFFAROAD		3.5	14.50		7 1 7		-1-1				11.5	10000	2.111	1 5 5 5	15 - 15	1 1 2 2 2		414.1	2 + 2 +	
S-S(SAME-DIR)		1.00	2.00							200	3.5	1 4 5 2 2	1 1.15	19.5	200		1000	100	19.7 (
REAR-END	V 40.3	5.1.2.5				1. 1. 1			1.5			5 to <u>1</u> 2 2	1.5 5 5	1000	1.1	4 1 1 4 1 4 1 A	12.5	11.1	4, 5	alian para pagaman na sana di selembra di sensi angalan sa sana sa
HEAD-ON I		:	1 + 21 - 1	1.00	5.5 5.5		J 1.		5 (5)		100		F-5-525	7.7	1.1	et en ge	10.60	3 1 1 1	200	
S-S(OPP-DIR)		1.1.7	12.1	1 - 1 - 1		1 1 2 1 2	100	- 100	Jul 1997	. 1. 1. <u>1</u>	100			17.5	19.00	1.5	13.75	3.5	5.7	<u> 1999 - 1999 - 1999</u>
ANGLE (TURN) I	14 / 1	1 1	11.			1 1 1		51 1 52	\$10.00		13.50	6 3 5 5 6		100	100	8 2 1 8 9	1111/11	' :	- 1:	
ANGLE (ATURN) NI	3 - 3 - 1			1 - 1 - 1			1 1				100		3.5	1.5	100	1 1 7 1 1	100	5.5	1.7	1,7,7,5,5,7,7
ANGLE(I)			1.1			2.1.1	14 (14)		J. 44		100	5 4 3 5 5 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5 (1)	1 1 1 1		1 1 2	1111		1 + 1 + 1 + 1 + 1 <u>+ 1</u>
ANGLE (NIA)	3 5 5 5	1.70	2 - 1					100	<u> </u>		1		3 1 7	1.1	1.11	7 7 7 1	-111 1 E	1 2 2	1 - 1 -	
OTHER	111111	3.7							1.7	100	100		1 1 1	1 - 1	1.		100	1 P. 1	11.5	
TOTAL (P.D.A	- 1111	\$79	, 275			\$137	,875			\$208	,990		1 1 1 1	\$34	. 5 10	3 7 1 2 2				

STUDY TOTAL (ACCIDENT TYPEA

	FATAL	PERCENT	INJURY	PERCENT	PROPERTY DAMAGE	PERCENT	TOTAL	PERCENT
OVR-TRN(IN-RD)								
PEDESTRIAN	A Francisco de la co							
PARKED-VEHICLE	A X CARREST		In a service of			On Assign to A		
RAILROAD-TRAIN		Territoria de la compansión de la compan	The state of the first			pela est a artir 🔝		<u>. 18 </u>
ANIMAL		Tarakanan Tara <u>k</u>				Targéran atau		
FIXED-OBJECT	3 - 3	100.0	56	100.0	133	100.0	192	100.0
RAN-OFF-ROAD		The state of the first of		1.15/10/10/10				<u> </u>
S-S(SAME-DIR)								
REAR-END								
HEAD-ON								
S-S(OPP-OIR)				100000000000000000000000000000000000000				
ANGLE (TURN) I						ta degrada e		
ANGLE (TURN)NI				ing the figure of the		<u> </u>	3 4 13 4 4 3 4 3 4 3	
ANGLE(I)								
ANGLE (NIA)								
OTHER								
TOTAL	3	100.0	56	100.0	133	100.0	192	100.0

SPEED CONDITIONS

TYPE OF				OP	ERATING S	SPEED						
VEHICLE	0-9	10-19	20-29	30-39	40-49	50-59	60-69	70-79	80+	UNKNOWN	TOTAL	PERCENT
SINGLE UNIT (NORMAL)	5	11	17	23	52	59	15	3	1		186	88.1
SINGLE UNIT (LARGE)	1	1	2		1 1	1			19.79		6	2.8
DUAL UNIT			1 1 1 1 1	3	6	9			N 2 3 3		19	9.0
OTHER			1 2 2 2 2 2 2			1 1 1 1			5 7 5			
TOTAL	6	12	20	26	59	69	15	3	1		211	100.0
PERCENT	2.8	5.6	9.4	12.3	27.9	32.7	7.1	1.4	. 4		100.0	

ACCIDENT OCCURRENCE

													HOU	JR OF	THE	DAY												
	- (DAY	<					AM						> <						-PM-						->	5 (5.5)	
П			1	2	3	4	5	6	7	8	9	10	111	12	1	2	3	4	5	6	7	8	9	10	1 1	12	TOTAL	PERCENT
	- 1	MON	1	1 : -		1.1	2	2	2	1	1	1	1	1	100	1	1	3	100	4	1	1	100		1	1	25	13.0
	F	TUE	1		1		1	3	1	4	1	1	1	1.		1	3	5	1	•	1	2	2	2	1.5		31	16.1
Έ.		WED	11.1	1	1		100	7	1 1	2	2		1 1	1	- 1, 1	3	6	:	2	1	1	2		12.1	100		29	15.1
		THU			1	1	100	1	3	4	1	1	1	3	3.00		1	1	2	100	3	1.1	100	2	1	1	27	14.0
	1	FRI			1:		1	4		3	3	2.2	4	1	2	3	2	1	6	1	11.			2	2		36	18.7
	1	SAT		2	2		1	1	2	1	1	2	1 1		1		1		1		2	1	3 t	2	2	1	24	12.5
		SUN	1	2		1	1	100			2	3	2	1	1			2			1		1		2		20	10.4
			EARL	Y MC	RNIN	G-SU	NRIS	E MO	RNIN	G PE	AK N	ID	MORN]	NG-M	ID A	FTER	NOON	AFT	ERNO	ON F	PEAK	EVEN	ING-	LATE	NIG	HT	TOTAL	100.0
	T	OTAL			3	17	1 - 1 - 1			35				53						30				37			192	
	PER	CENT			19.	2	1 7 1, 1		18	. 2				27.6					15	. 6			11	9.2		- 1	100	

POTENTIAL INFLUENCING CONDITIONS

ROADWAY							
CONDITIONS	DAYLINGHT	DARKNESS	TWILIGHT	LIGHTED	UNKNOWN	TOTAL	PERCENT
DRY	66	23	3	5		97	50.5
WET (NWATERIN	33	13	4	4		54	28.1
WET (NICE OR SNOW)	18	14	6	2		40	20.8
MUDDY							
NOT REPORTED		1				1	. 5
TOTAL	117	51	13	11		192	100.0
PERCENT	60.9	26.5	6.7	5.7		100	

WEATHER CONDITIONS	TOTAL	PERCENT	
CLEAR	63	32.8	٦
PARTLY CLOUDY	48	25.0	٦
OVERCAST	23	11.9	٦
RAINING	44	22.9	٦
OTHER	14	7.2	7
TOTAL	192	100.0	7

TABULATION OF ACCIDENT DATA FROM 04-26-85 TO 04-26-88

RUN DATE: 01/19/89

3

56

29.1

3

1.5

12

6.2

2

1.0

3

1331

69.2

6

192

1,00

3.1

100.0

I-40 MAINLINE FIXED OBJECT ACCIDENTS FROM I-44 EAST TO SUNNYLANE OFFENDING DRIVERS CONDITION CAUSE ALCOHOL INVOLVED ACCIDENT SEVERITY **OF** APPARENTLY ABILITY ODOR SLEEP PHYSICAL OTHER ACCIDENT NORMAL IMPAIRED DETECTED SUSPECTED DEFECT CONDITION FAT INJ P-D FAT INU P-D TOTAL | PCT F-Y DELD F-STOP F-SIGNAL IMP-TURN IMP-START IMP-STOP IMP-BACK IMP-PARK IMP-PASS IMP-LN-CHG 1 2 2 1.0 L-CENTER FOL-CLOSE 2 2 2 1.0 25 67 9 56.7 3 3 28 80 UNSAF-SPD 1 109 8 D-W-I 2 8 2 9 8 19 9.8 3 2.0 INATT 1 1 1 1 NEG-DRVING 1 . 5 DEF-VEH 4 7 1 4 8 12 6.2 WRNG-WAY NO-IMP-ACT 7 2 9 28 37 19.2 26 1

1

5

1

3

1.5

1

5

OTHER

TOTAL

PERCENT

1

38 106 |

19.7 55.2 1.0

3

2

8

4.1 4.6

9

. 5

5

2.6

4

2.0

APPENDIX D

ODOT SPECIAL PROVISION
March 282 1984

OKLAHOMA DEPARTMENT OF TRANSPORTATION SPECIAL PROVISIONS

FOR

EXPERIMENTAL SAFETY BARRIER END TREATMENT (SENTRE)

ON

FEDERAL AID PROJECT IR-40-4(304)147
OKLAHOMA COUNTY

These Special Provisions revise, amend, and where in conflicto supersede applicable Sections of Standard Specifications

for Highway Construction of 1976.

DESCRIPTIONO The SENTRE unit shall consist of interlocking collapsible thrie beam fender panelso wide flange posts, slip baseso sand containerso and a redirecting cableo These components shall form a crashworthy end treatment which shall meet the minimum test requirement specified in the National Cooperative Highway Research Program (NCHRP) report 2302

1. Impact at 25 degrees into the beginning of length of need (i.e.o beginning of tensioned guardrail and/or concrete parapet) at 60 mph with a 4500 lb. caro

Impact at 0 degrees into center nose of the device (0"
offset from centerline of vehicle) at 60 mph with a 4500

lbo caro

3. Impact at 15 degrees into side of the device midway between nose and beginning of length of need at 60 mph with an 1800 lb. caro

4. Impact at 0 degrees into nose of the device (with 1.25 fts offset from centerline of vehicle) at 60 mph with an 1800 lbg car.

When hit head-on, the unit shall be capable of simultaneously collapsing and moving laterally to re-direct an impacting vehicle away from the end of the downstream traffic barrier.

The redirecting cable shall be anchored at both ends with anchors that are capable of withstanding a minimum pullout force

of 50,000 lbs.

The base plate of each SENTRE post shall be rigidly held in place by anchors that are capable of withstanding a 15,2000 lbso shear and 26,500 ft-lbs moment in the longitudinal axis of the SENTRE and 27,2000 lbso of shear and 49,500 ft-lbs of moment in the lateral axis of the SENTRE.

MATERIALSo (a) General. All SENTRE components shall be assembled in accordance with the manufacturer's standards and

requirecentso

1. Fender Panelso The fender panels shall be fabricated from 10 gauge steel triple corrugated guardrail sections which meet AASHTO Guide M-180 specificationso Each fender panel shall

be drilled and slotted in accordance with the manufacturer's specificationss. When assembled in the field, all fender panels shall be bolted to a break away post by means of two boltss. The back end of each triple corrugated fender panel shall overlap and be connected to the fender panel of the next bay by means of a bolt and mushroom washer which fits through the long horizontal slot in the forward fender panel and the short vertical slot in the underlying panels. This connection method shall permit movement, front to back, of one set of fender panels relative to the panels in the underlying section.

2. Redirecting Cables The front post of the SENTRE shall have one 7/8" diameters 6 x 19 galvanized steels wire rope passing through it. The wire rope material shall be made from

improved plow steel with a minimum load limit of 712000 lbs.

3. Sand Containerss The front three posts shall be fitted with sand containers which hold either 100 or 150 pounds of sand. Two small (100 pound) sand containers shall be fastened to each of the front two postss Two large (150 pound) sand containers shall be fastened to the third posts The sand containers shall be molded from a black plastic having sufficient U.V. stabilizers and anti-oxidants to provide good weatherabilitys Each sand container shall have a hinged plastic lid which snaps firmly in place after the containers have been filled with sand. Sand mass for the containers shall meet the requirements of Subsection 701.05 and shall contain not more than two percent moisture by dry weight of the aggregate at the time of placement.

4. Nose Cover. The front of the SENTRE shall be fitted with a grey plastic "bull nose"s The nose shall be molded from a plastic having sufficient U.V. stabilizers and anti-oxidants to provide good weatherability. The nose shall interface to the front triple corrugated fender panel. The nose shall have a flat surface on its forward section which shall be suitable for

mounting reflective sheeting.

5. Fastenerss All bolts, nuts, and washers used to assemble the SENTRE shall be zinc coated, commercial quality "American

National Standard" unless otherwise specified.

6. Metal Work. All metal work shall be fabricated from either M1020 Merchant Quality or ASTM A-36 steel. After fabrication, all metal work shall be hot dipped galvanized in accordance with ASTM A-123. All welding shall be done by or under the direction of a certified welder.

(b) Materials Certification. A type "D" Materials Certification shall be required in accordance with Subsection 106.12.

CONSTRUCTION METHODS. Installation of the SENTRE shall be accomplished by experienced workmen in accordance with the recommendations of the manufacturer. As a replacement supplys the Contractor shall furnish a spare parts package. The quantity and materials of this package will be as shown on the Planss These unassembled materials will become the property of the Oklahoma

SPECIAL(c) 3-28-84

Department of Transportation and shall be delivered to the

Department Warehouse designated by the Engineers

METHOD OF MEASUREMENTO Each SENTRE installation will be measured by the unit for each installation as shown on the Planss Replacement packages will be measured by the unit delivered to the designated warehouse in accordance with these Specificationss

BASIS OF PAYMENTS Accepted SENTRE and replacement packages, measured as provided aboves will be paid for at the contract unit

price fors

SPs SAFETY BARRIER END TREATMENT (SENTRE) EA.

SPO SAFETY BARRIER END TREATMENT (SENTRE) & REPLACEMENT PACKAGE) EA.

which shall be full compensation for furnishing all containers, guardrails, posts, and all other materials, equipment, labor and incidentals to complete the work as specified.