

**EROSION CONTROL
AND REVEGETATION TECHNIQUES
USING MECHANICALLY
STABILIZED EARTH SLOPES**

COLORADO TRANSPORTATION INSTITUTE

**William R. Schiebel
Design Engineer
Colorado Department of Transportation**

**Albert C. Ruckman
Consultant in MSB Design and Construction
Denver, Colorado**

**Robert K. Barrett
Manager of Geotechnical Research
Colorado Transportation Institute**

**Jeff Rodencal
National Sales Manager, Drainage and Erosion Products
Tensar Earth Technologies, Inc.**

REPORT DOCUMENTATION PAGE			FORM APPROVED OMB NO. 0704-0188	
Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.				
1. AGENCY USE ONLY (Leave Blank)	2. REPORT DATE April, 1996	3. REPORT TYPE AND DATES COVERED Final Report, 2 years		
4. TITLE AND SUBTITLE Erosion Control and Revegetation Techniques Using Mechanically Stabilized Earth Slopes			5. FUNDING NUMBERS	
6. AUTHORS(S) William R. Schiebel, Albert C. Ruckman, Robert K. Barrett, Jeff Rodencal				
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(S) Colorado Department of Transportation 4201 E. Arkansas Ave. Denver, Colorado 80222			8. PERFORMING ORGANIZATION REPORT NUMBER CDOT/CTI-96-4	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(S) Colorado Department of Transportation 4201 E. Arkansas Ave. Denver, Colorado 80222			10. SPONSORING/MONITORING AGENCY REPORT NUMBER CDOT/CTI-96-4	
11. SUPPLEMENTARY NOTES Prepared in Cooperation with the U.S. Department of Transportation, Federal Highway Administration				
12a. DISTRIBUTION/AVAILABILITY STATEMENT No Restrictions: This report is available to the public through the National Technical Information Service. Springfield, VA 22161			12b. DISTRIBUTION CODE	
13. ABSTRACT (Maximum 200 words) Revegetation and erosion control techniques on reinforced one-to-one slopes were monitored and reported. Two 15 foot high embankments were constructed with reinforced one-to-one slopes. These four slopes were each finished with six revegetation test sections. The test section characteristics provided a broad range of aesthetic and economic examples. The test sections were monitored for vegetation success and eroded material. The study was conducted in a semiarid climate. It is concluded that: 1. Irrigation commensurate with evapotranspiration rates and precipitation will be necessary in semiarid climates. 2. Slope orientation will have an impact on revegetation success. 3. Any of the studied revegetation test sections offer excellent erosion control. And 4. Vegetated one-to-one can offer the designer an aesthetic and economic alternative to vertical retaining walls.				
14. SUBJECT TERMS Revegetation Erosion Control Steep slopes Mechanically Stabilized Geosynthetic Reinforcement			15. NUMBER OF PAGES	
			16. PRICE CODE	
17. SECURITY CLASSIFICATION OF REPORT Unclassified	18. SECURITY CLASSIFICATION OF THIS PAGE Unclassified	19. SECURITY CLASSIFICATION OF ABSTRACT Unclassified	20. LIMITATION OF ABSTRACT	

ACKNOWLEDGMENTS

Ralph Trapani, CTI President, and Rich Griffin, CDOT Research Coordination Engineer, provided oversight and funding that enabled us to complete this milestone MSB research project.

CDOT Maintenance personnel, under the direction of Al Kline, provided the site, equipment, materials and manpower. This support was critical to the success of this project. We are greatly indebted to them.

Steve Foster and Steve Hieber, CDOT Region 3, were construction supervisors.

Mike Banovich, CDOT Staff Landscape Architect, contributed his knowledge of local conditions, planting requirements, and survey methods by providing crucial technical assistance and recommendations.


Dave Woodham, CDOT Research Engineer, provided important technical expertise and experience in construction and monitoring of weather station systems.

CONTENTS

Introduction.....	p. 1
Construction and Materials.....	p. 1
Vegetation.....	p. 6
Instrumentation and Measurement.....	p. 8
Results and Discussion.....	p. 9
Conclusion.....	p. 16
Appendix A - Irrigation Schedule.....	p. 21

INTRODUCTION

This report summarizes a study of commonly used erosion control and vegetation techniques on Mechanically Stabilized Earth (M.S.E.) slopes in the semiarid climate of Denver, Colorado. Two geogrid reinforced embankments were constructed to provide test slopes of a 1:1 grade (i.e., 45 degree slopes). The embankments were oriented to provide slope exposure to the north, south, east and west. Each of the four slopes contained six revegetation test sections with an erosion collection bin at the base of each section. A weather station installed at the site monitored weather conditions during the study period. The site was monitored from June of 1994 to August of 1995.



CONSTRUCTION and MATERIALS

Two embankments were constructed at the Colorado Department of Transportation's Commerce City Maintenance Yard to study the characteristics of M.S.E. slopes and mechanically stabilized backfill (M.S.B.) walls. The M.S.B. walls are the focus of a separate study and report. The embankments were approximately 65 feet long with a bottom width of 40 feet and a height of 15 feet. M.S.E. slopes were constructed at one-to-one slope so that the berm width at the top was 10 feet. One berm was oriented from the north to the south and the other was oriented from the east to the west. This directed the four test slopes to the four compass directions. Primary and intermediate slope reinforcement was provided by Tensar geogrids. See Figure A.

The revegetation test sections that were built are labeled and described as "Section 1" through "Section 6" in Figure A and Figure B. Each test section was subjected to North, South, East and West exposure.




Figure A

Erosion collection bins (See Figure A) were constructed of 2" x 6" pine board frames and specially fabricated impermeable 30 mil plastic linings. The collection bins were built to provide each test section with a 10' x 4.5' rectangular bin at it's base to contain all eroded material for measurement.

A Case W14 front-end loader placed and compacted the embankment material. Topsoil was compacted with an eight horsepower vibrating plate compactor.




Figure B

Table 1 details the composition of the embankment material. **Table 2** gives the Topsoil test results. The topsoil used on the slopes is typical of topsoil used with native seeding on Colorado Department of Transportation projects.

<u>Sieve Analysis</u>			In-Place Moisture	4.35 %
Passing #4	87%		Liquid Limit	23
#10	79%		Plastic Limit	18
#40	57%		Plasticity Index	5
#200	25%			
Gravel	21%			
Coarse Sand	22%		<u>Classification</u>	
Fine Sand	32%		AASHTO	A-2-4(40)
Fines	25%		Corps. of Engrs.	Silty Gravelly Sand

Table 1 - embankment

<u>Sieve Analysis</u>			pH	7.250
Passing #4	97%		Cl	< 8.0 ppm
#10	95%		SO ₄	194 ppm
#40	86%		Organics	5.03 %
#200	57%		Resistivity	89,100 ohm-cm
Gravel	5%			
Coarse Sand	9%		<u>Classification</u>	
Fine Sand	29%		AASHTO	A-6(8)
Fines	57%		Corps. of Engrs.	Sandy Clay

Table 2 - topsoil

According to Tensar Earth Technologies, Incorporated, the manufacturer of the majority of the geosynthetics used in this study, **Table 3** provides the cost factor of each vegetation test section including the cost of plantings, seed, materials and labor. The least expensive is Section 2 with a cost factor of one. A standard modular block facade, including labor, would compare with a 3.0 to 3.5 cost factor.

Factored Cost of Each Vegetation Test Section	
Test Section Number	Cost Factor
#2	1.0
#3	1.05
#4	1.15
#5	1.5
#6	3.0

Table 3

The cost comparisons shown in **Table 3** represent only the cost of slope treatment. None of the items necessary to construct an M.S.E. slope are included. M.S.E. slopes are an alternative to vertical structures where construction site constraints permit. In most fill situations, an M.S.E. slope with the standard vegetation treatment (Section 3) will generally cost 30 to 50 percent less than a vertical M.S.B. structure. The more expensive slope treatments in this study offer visual alternatives to the designer. Hand planted woody vegetation is the most expensive component of these slope treatments whereas the vertical M.S.B. structure has the wall facing as its most expensive item. Where project spacial restrictions will allow and where aesthetic options are needed the vegetated M.S.E. slope should be considered.

VEGETATION

The six revegetation test sections were constructed on the North, South, East and West facing slopes (See Figure A and B above). Following is the vegetation planted on the individual test sections.

Section 1: Control section - No treatment.

Section 2: No topsoil, seeded and covered with erosion blanket. See Table 4a and 4b.

Section 3: Topsoiled, seeded and covered with erosion blanket. See Table 4a and 4b.

<i>Seed mix and fertilizer applied May 15, 1994.</i>		
<u>COMMON NAME</u>	<u>BOTANICAL NAME</u>	<u>PLS/ACRES (lbs.)</u>
BLUE GRAMA V. HACHITA	BOUTELOUA GRACILIS	1.5
SLENDER WHEATGRASS V. PRYOR	ELYMUS TRACHYCAULUS	5
WESTERN WHEATGRASS V. ARriba	PASCOPYRUM SMITHII	10
LITTLE BLUESTEM V. PASTURA	SCHIZACHYRIUM SCOPARIUM	2
BUFFALO GRASS V. TEXOKA	BUCHLOE DACTYLOIDES	10
SIDEOATS GRAMA V. VAUGHN	BOUTELOUA CURTIPENDULA	6
BLANKET FLOWER	GAILLARDIA ARISTATA	2
BLUE FLAX	LINUM PERENNE	1
PRAIRIE CONEFLOWER	RATIBIDA COLUMNIFERA	0.25
YARROW	ACHILLEA MILLEFOLIUM	0.2
	TOTAL	37.95
<u>COMMERCIAL FERTILIZER</u>	<u>ANALYSIS (%)</u>	<u>LBS./ACRE AVAILABLE</u>
NITROGEN	18	45
PHOSPHORUS	46	115
POTASSIUM	0	

Table 4a

Seed mix applied September, 1994. No fertilizer applied.

<u>COMMON NAME</u>	<u>BOTANICAL NAME</u>	<u>PLS/ACRES (lbs.)</u>
BLUE GRAMA V. HACHITA	BOUTELOUA GRACILIS	1.5
SLENDER WHEATGRASS V. PRYOR	ELYMUS TRACHYCAULUS	5
WESTERN WHEATGRASS V. ARRIBA	PASCOPYRUM SMITHII	10
LITTLE BLUESTEM V. PASTURA	SCHIZACHYRIUM SCOPARIUM	2
BUFFALO GRASS V. TEXOKA	BUCHLOE DACTYLOIDES	10
SIDEOATS GRAMA V. VAUGHN	BOUTELOUA CURTIPENDULA	6
BLANKET FLOWER	GAILLARDIA ARISTATA	2
BLUE FLAX	LINUM PERENNE	1
PRAIRIE CONEFLOWER	RATIBIDA COLUMNIFERA	0.25
YARROW	ACHILLEA MILLEFOLIUM	0.2
CANADA BLUEGRASS V. RUEBES	POA COMPRESSA	0.5
SHEEP FESCUE	FESTUCA OVINA	12
	TOTAL	50.45

Table 4b

Section 4: Topsoiled, covered with erosion blanket and sodded with buffalo grass sod.
Sod placed on June 2, 1994.

Section 5: Topsoiled, covered with landscape fabric and planted with 3 gallon plants.

Section 6: Terraced at 18 inch intervals and planted with 1 gallon container plants.

Following are the one and three gallon plantings placed in Sections 5 and 6.

<u>COMMON NAME</u>	<u>BOTANICAL NAME</u>
Rocky mountain sumac	Rhus glabra cis-montana
Rabbitbrush	Chrysothamnus nauseosus
Potentilla	Potentilla fruticosa

Rabbitbrush was planted on the bottom third of each section while Sumac and Potentilla were planted on the upper two thirds.

The site was irrigated using a sprinkler system and water tanker truck for portions of the study period. Table 5 shows the amounts of water applied to the site. See Appendix A for the detailed irrigation schedule.

INCHES OF WATER APPLIED TO SITE IN 1994	
June	4.27
July	3.03
October	6.23
<i>First seeding May, 1994</i>	
<i>Second seeding September, 1994</i>	

Table 5

INSTRUMENTATION and MEASUREMENT

The one-to-one M.S.E. slopes were not instrumented to record mass movement. Evaluation was made of vegetation survival and slope erosion. Bins at the base of each of the revegetation sections were built to contain all eroded material. This material was periodically collected and weighed. Determination of vegetation success was based on measurements of either vegetation density or plant survival. Soil temperatures were measured for each revegetation test section.

A weather monitoring station, constructed on the top center of the north-south test embankment and consisting of a three meter pivoting tower with guy wires, grounding rod, instrumentation and data recording devices, recorded weather data during the slope revegetation study. The data was recorded and downloaded with a Campbell Scientific Inc. (CSI) CR21 Micrologger and cassette tape recorder. The weather sensors used are listed below:

- ▶ CSI Model 101b Temperature Probe to measure north slope soil temperature. (°C)
- ▶ CSI Model 101b Temperature Probe to measure south slope soil temperature. (°C)

- ▶ CSI Model 101 Temperature Probe to measure level ground soil temperature. (°C)
- ▶ CSI Model 201 Temperature/Relative Humidity (RH) Probe to measure air temperature (°C) and relative humidity (%)
- ▶ Qualimetrics Silicon Cell Pyranometer Model 3120 to measure solar radiation. (W/m²)
- ▶ Met-One Model 024A Wind Direction Sensor to measure wind direction (in degrees with north equal to zero degrees)
- ▶ Met-One Model 014A Wind Speed Sensor to measure wind speed (m/s)
- ▶ CSI Model TE525 Tipping Bucket Rain Gage to measure rainfall (mm)

The sensors were sampled every ten seconds by the CR21 Micrologger and data values were computed and recorded every six hours (6:00 am, 12:00 pm, 6:00 pm, 12:00 am).

The air and soil temperature probes had maximum, minimum and average temperatures computed for each six hour period. The Temperature/RH probe and Pyranometer recorded average percent relative humidity and average solar radiation over the same periods. A wind vector program computed mean wind speed, mean wind vector magnitude, mean wind vector direction and standard deviation using the wind direction and wind speed sensors. The tipping bucket gage recorded time of rainfall events and total rainfall over the six hour period. Micrologger identification number and battery voltage were also recorded to monitor the status of the recording device. The recorded data were converted from Micrologger format on the cassette tape to ASCII file format for interpretation and storage.

Data from existing local weather stations operated by the Denver Water Department was used in addition to the on-site weather station data.

RESULTS AND DISCUSSION

Erosion Control

Eroded material was collected and weighed twice during the study period. The eroded soil collected was essentially dry except for that from Section 1. This section had a large amount of material which tended to be moist throughout. Moisture contents were determined and used for Section 1 samples to compute dry weight. Table 6 shows factored values for total eroded material collected during the study period.

A large amount of erosion occurred in the untreated control test sections (Section 1). Slope treatment by any one of the methods used in the study will reduce erosion by a factor between 6.5 and 230.

SLOPE EROSION - Factored Dry Wt. Of Collected Material						
Slope Facing Direction	Sect. 1	Sect. 2	Sect. 3	Sect. 4	Sect. 5	Sect. 6
North	368.9	1.6	2.3	3.4	8.0	3.2
South	155.3	1.6	1.4	1.0	9.8	*12.3
East	244.5	3.0	1.6	3.4	7.0	1.8
West	101.5	1.4	1.1	1.3	14.8	3.8

SEE FIGURE B FOR TEST SECTION DESCRIPTIONS.

Lowest weight of material becomes FACTOR 1.0.

* Visual inspection showed that the majority of material in South-6 was washed in from the adjacent untreated end of the berm.

Table 6

Sections 2 and 3 eroded similarly and generated the least amount of eroded material of the five vegetation test sections. Section 6 followed these two with a slightly higher weight of material. Section 5 had the most material eroded from its face. The large openings cut into the landscape fabric for placement of the three-gallon plants were not adequately stabilized by the wood chip bedding. The wood chips used on the terraces in Section 6 likely provided inadequate soil stabilization in that section as well. Section 4 eroded similar weights to Section 6, however, the almost immediate death of the sod in this section make comparison to this section of little use. The North facing slope experienced the greatest amount of erosion.

Soil Temperatures

Soil temperatures were recorded at the top and bottom of each test section as well as on either end of the top of both berms three times during the study period. **Figures C.1, C.2, and C.3** show slope temperature relationships.

SOIL TEMPERATURES
June 20, 1994 10:30 am




Figure C.1

SOIL TEMPERATURES
Aug. 17, 1994 12:00 noon




Figure C.2




Figure C.3

Vegetation

Slope vegetation was quantified in two ways: vegetation density estimates and planting surveys. Vegetation density was determined by a visual estimate of the percent of slope covered by living plant material. Consideration of plant species was not made and two observers were used for each of the estimates. Invasive weeds were the primary plant inhabiting the slopes at the time of the first vegetation density estimate. Large numbers of weeds were living on Sections 5 and 6 at the time of the first estimate. For this reason, Sections 5 and 6 were included in the first vegetation density estimate, however, the plantings surveys were the primary method used to determine the success of these two sections. All invasive weeds were removed from the slopes after the first estimate was recorded to allow the second seeding to grow unhindered. The buffalo grass sod in section 4 was dead by the time of the first vegetation density estimate. This section was included in both density estimates because it contained invasive weeds. During the second vegetation density estimate it was noted that the majority of plants in Sections 1, 2 and 3 were of the seeded species. Table 7 shows slope vegetation densities.

A survey of the plantings placed in sections 5 and 6 was made at two times during the study period. Tables 8a and 8b show the results of the plant surveys.

SLOPE VEGETATION DENSITY
In Percentage of Slope Covered

Slope Facing Direction	Sect. 1	Sect. 2	Sect. 3	* Sect. 4	Sect. 5	Sect. 6
<i>August 17, 1994</i>						
North	5	10	25	40	30	40
South	0	0	0	5	20	10
East	20	5	55	15	25	65
West	10	10	35	15	25	50
<i>June 26, 1995</i>						
North	7.5	62.5	75	25		
South	1	5	10	5		
East	12.5	22.5	30	7.5		
West	5	17.5	35	5		

SEE FIGURE B FOR TEST SECTION DESCRIPTIONS.

* The buffalo grass sod in section 4 is dead. All values represent invasive weed coverage. The seeded slopes during the first survey August 17, 1994, had very few of the seeded species growing on them. Invasive weeds dominated the slopes. The seeded species were dominant at the second survey.

Sections 4, 5 and 6 are recorded for information only.

Table 7

SURVEY OF PLANTINGS IN SECTIONS 5 AND 6
AUGUST 17, 1994

Slope facing Direction	Plant Type	SECTION 5 3 gallon Planted	5 plants Living	SECTION 6 1 gallon Planted	6 plants Living
North	RMS	6	4	13	13
	POT	6	4	11	1
	RB	6	6	14	14
South	RMS	6	4	12	4
	POT	6	0	13	1
	RB	6	6	14	13
East	RMS	6	5	12	9
	POT	6	1	14	0
	RB	6	6	13	1
West	RMS	6	6	14	10
	POT	6	3	12	3
	RB	6	6	14	13

SEE FIGURE B FOR TEST SECTION DESCRIPTIONS.

PLANT TYPE:

RMS = Rocky Mountain Sumac

POT = Potentilla

RB = Rabbitbrush

Table 8a

SURVEY OF PLANTINGS IN SECTIONS 5 AND 6
JUNE 26, 1995

Slope facing Direction	Plant Type	SECTION 5 3 gallon Planted	5 plants Living	SECTION 6 1 gallon Planted	6 plants Living
North	RMS	6	3	13	5
	POT	6	2	11	0
	RB	6	6	14	14
South	RMS	6	0	12	1
	POT	6	0	13	0
	RB	6	6	14	9
East	RMS	6	0	12	1
	POT	6	0	14	0
	RB	6	4	13	0
West	RMS	6	1	14	0
	POT	6	0	12	0
	RB	6	6	14	10

SEE FIGURE B FOR TEST SECTION DESCRIPTIONS.

PLANT TYPE:

RMS = Rocky Mountain Sumac

POT = Potentilla

RB = Rabbitbrush

Table 8b

CONCLUSION

Evapotranspiration Rates

Plant growth is largely a function of temperature and available moisture. Inadequate moisture will prevent seed germination and lead to wilting. Adequate temperature for seed germination and plant growth is necessary while excessive temperatures lead to high evapotranspiration (ET) rates. As plant ET increases, so does the need for available moisture to the plant in the form of precipitation or irrigation. Temperature's affect on plant ET can be seen in the Blaney-Criddle Formula as described below:¹

$$u = kf$$

$$\text{where } u = ET$$

$$k = \text{Empirical ET coefficient for a month} \\ = k_t \times k_c.$$

With

$$k_t = 0.0173t - 0.314$$

$$k_c = \text{plant growth stage coefficient}$$

$$f = (t \times p) \div 100$$

$$t = \text{Average monthly temperature} \\ \text{and}$$

$$p = \text{Monthly percentage of daylight hours in the year,}$$

$$ET = \frac{0.0173t^2k_cp - 0.314tk_cp}{100}$$

This relationship between temperature and ET was used to compute the on-site ET values shown in Table 9. This method of computing ET is less realistic than the method used by the Denver Water Department in computing ET rates.² Denver Water Department ET rates are based on solar radiation, air temperatures, relative humidity and wind conditions. Since the seed mix used on the study slopes required at least 30 percent less water than the alfalfa crop upon which the Denver Water Department ET rates are based, the factored off-Site ET rates shown in Table 9 are 70 percent of the Denver Water Department rates.

¹U. S. Department of Agriculture, Soil Conservation Service, Engineering Division, Technical Release No. 21 (Rev. 2), April 1967, Revised September 1970.

²Denver Weather Station Information, compiled by the Denver Water Department and posted on the Galaticomm Bulletin Board System at (303)628-6365, Denver Water Department, Denver, Colorado.

The plant growth stage coefficient is assumed to be a constant value of 1.0 when computing on-site ET rates. The air temperature just above the ground will likely be very similar to the temperature of the soil. Young and small plants will exist in this area just above the soil surface and soil temperature is thereby justified in computing on-site ET rates. The on-site rates are intended to show that slope orientation will influence ET and

		Monthly On-Site E.T. Rates				FACTORED	Irrigation (I)	Precip. + (P)
	Month	Air	North slope	South slope	Level ground	ET from Off-Site Data		
1994	JUNE	7.36	8.56	9.63	8.11	6.24	4.27	0.12
	JULY	7.41	8.85	10.39	8.79	5.78	3.03	0.01
	AUG.	6.88	6.96	8.69	8.33	4.89		0.57
	SEPT.	4.84	4.42	7.09	5.99	4.24		0.27
	OCT.	2.36	1.83	3.97	2.40	2.51	6.23	0.73
1995	APRIL					2.85		2.12
	MAY					3.05		4.72
	JUNE	5.20	6.05	6.81	5.73	4.41		2.62
	JULY	7.40	8.84	10.38	8.78	5.78		0.85
	AUGUST	5.71	5.78	7.21	6.91	4.06		0.33
'(I+P)-E.T.								
	Month	Air	North slope	South slope	Level ground	Off-Site Data		
1994	JUNE	-2.97	-4.17	-5.24	-3.72	-1.85		
	JULY	-4.37	-5.81	-7.35	-5.75	-2.74		
	AUG.	-6.31	-6.39	-8.12	-7.76	-4.32		
	SEPT.	-4.57	-4.15	-6.82	-5.72	-3.96		
	OCT.	4.60	5.13	2.99	4.56	4.45		
1995	APRIL					-0.73		
	MAY					1.67		
	JUNE	-2.58	-3.43	-4.19	-3.11	-1.79		
	JULY	-6.55	-7.99	-9.53	-7.93	-4.93		
	AUGUST	-5.38	-5.45	-6.88	-6.58	-3.73		

☞ Values are averaged from three Denver Water Dept.(DWD) Weather stations in the vicinity of the study site.

☞ Unreliable on-site weather data made the computation of on-site 1995 ET rates impossible. A monthly factor was determined between 1994 on-site air and off-site ET rates and used to estimate 1995 on-site air ET from 1995 off-site. The 1995 estimated on-site air was then used to determine 1995 North, South and Level based on 1994 relationships between them. Estimation of April and May ET rates was not possible by this means. Note the off-site values for these two months.

+ On-site precip. values for 1995 were unreliable. The averaged values from three D.W.D. weather stations were used.

Table 9

therefore required available water. The semiarid climate of this study requires irrigation on the North, South, and level ground exposures to establish plant growth. The South facing slopes will require the most irrigation water. See **Figures C.1, C.2 and C.3** above for additional illustration of the relationship between slope orientation and temperature.

The negative values for (I+P)-ET show that there was not enough water for plant growth after the first seeding and planting in June of 1994. According to *Climatological Data Annual Summary* the period following the first seeding and planting was drier and hotter than the normal.³ This fact was accentuated on the South and East slopes which were typically warmer than other exposures. The second seeding in October was well irrigated and lost less water to ET. This aided the seed germination but was too late to benefit the plantings placed in June. The mild, wet spring that followed was very beneficial to the seeded slopes as is evidenced in **Table 7** detailing the second vegetation density survey.

Another factor which influenced the success of the slope vegetation was slope grade. In comparison to flatter slopes, a forty-five degree slope will allow for a much higher rate of surface runoff and therefore allow less incident water to be used by vegetation. It was apparent during vegetation surveys that much of the water that fell on the smooth slopes (test sections 1 to 4) had settled at the slope base in that vegetation densities were typically greater at the slope bases.

Vegetation Survival

The buffalo grass sod planted in test sections 4 was dead within approximately one month of its placement. Successful plots of buffalo grass sod under the study site's weather conditions generally require daily watering for the first month followed by every other day watering for half of the second month. The irrigating schedule did not supply nearly the water required for the sod to establish itself. The sod pieces were placed on an erosion blanket in order stabilize the soil/root interface and to prevent the sod from sliding down the slope. However, due to the arid climate, this system likely prevented early root-soil bonding and allowed the sod root systems to dry out.

The plantings experienced mixed success as shown in **Tables 8a and 8b**. The *Potentilla* were quickest to dry out and die. The vast majority of the one-gallon *Potentilla* on all slopes and the 3-gallon *Potentilla* on the warmer East and South slopes were dead by the first survey. The one-gallon likely lost root moisture sooner than the 3-gallon. All *Potentilla* were dead at the second surveying except two 3-gallon plants on the North facing slope which was the coolest and was therefor likely the most moist. The Rocky Mountain Sumac were more resistant to drought but still showed large numbers of dead plants of the one-gallon size at the first survey on the South and East slopes. By the

³U. S. Department of Commerce, National Oceanic and Atmospheric Administration, Climatological Data Annual Summary, Colorado, 1994, Volume 99, Number 13, 1994, Asheville, North Carolina.

second survey essentially all Rocky Mountain Sumac were dead except for approximately half of the 3-gallon and one third of the one-gallon on the North slope. The Rabbitbrush were by far the most successful plantings on all slopes except the East. Sixty-four percent remained alive on the South slope, seventy-one percent survived on the West slope and all plants on the North slope were alive. At the time of the first survey, all but one of the East slope Rabbitbrush were dead. The reason for the high mortality of the Rabbitbrush on the East slope is uncertain. The relative success of the Rabbitbrush could be due to one or both of two factors. First, the species requires the least water for survival of the three plantings used on the site. Second, placement of the Rabbitbrush at the bottom of all slopes resulted in a greater supply of water due to slope runoff. It is likely a combination of these two factors that resulted in the success of the Rabbitbrush plantings.

Two test sections were seeded with a seed mix that has proven successful in use on many Denver area highway projects. As was noted earlier, the first seeding was largely unsuccessful due to inadequate water supply following seed application. The second seeding was given enough water by irrigation to promote seed germination and strong early grass growth. This seeding was successfully applied to the slopes by spraying the grass seed directly through the erosion blanket. Mild Fall and Spring weather further encouraged grass success on the seeded test sections. The South facing slope fared least well with rather low grass density. This was likely due to the higher temperatures experienced on this slope. The East and West slopes saw similar success while the North slope had by far the most complete slope coverage. Those slopes which received no topsoil before seeding generally had much lower grass coverage. The greater success of the topsoiled test sections is likely due to the topsoil's greater nutrient supply and greater ability to retain water than embankment material alone.

Buffalo grass sod requires a large amount of irrigation water to ensure that it will become established on a steep slope. The high irrigation cost and the relatively high cost of sod will likely make its use uneconomical on most large scale projects. Use of the erosion blanket underneath buffalo grass sod in semiarid climates should be avoided. One-gallon plantings should not be used if three-gallon plantings are available. Three-gallon Rabbitbrush is the best choice of the three in this study. Careful attention to plant bedding will minimize the erosion that is seen when wood chips are used as bedding. Of the two sections with plantings Section 6 is more costly but more aesthetically pleasing. If budget will permit and plantings are the desired slope treatment, the terraces as in Section 6 planted with three-gallon Rabbitbrush would be the most successful and appealing revegetation choice. Sections 2 and 3 are the most cost effective of the treatments and will erode the least. Topsoil before seeding is worth the additional cost. Watering commensurate with evapotranspiration is necessary until the plot is established.

Recommendations

The cost to construct a one-to-one M.S.E. slope is much less than the cost to construct either a concrete cantilever wall or a mechanically stabilized backfill (MSB) wall. Cantilever walls can be 50 to 75 percent more expensive and MSB walls can be 30 to 50 percent more expensive than an M.S.E. slope with topsoil, erosion blanket and seed. Where project spacial restrictions will allow and where aesthetic options are needed the vegetated M.S.E. slope should be considered assuming irrigation can be provided to suppliment precipitation as necessary to establish plant growth. The type of slope vegetation treatment will largely be a function of project budget and desired visual effect.

Selection of M.S.E. slopes in semiarid areas ($< 15"$ annual rainfall) should be limited to plantings with native grass species on East, West or North facing slopes with temporary irrigation used for initial plant establishment. Ornamental plantings on M.S.E. slopes should be limited to low height East, West, and North facing slopes where permanent irrigation is available. Sediment loss from the test slopes was controlled in all test sections regardless of the success of vegetation. The erosion control systems described in this study were effective in reducing soil loss on one-to-one slopes to a negligible amount.

APPENDIX A - IRRIGATION SCHEDULE

June 1994						
S	M	T	W	T	F	S
			1	0.356" 2	3	4
5	0.356" 6	7	0.356" 8	9	0.356" 10	11
12	0.356" 13	14	0.356" 15	16	0.356" 17	18
19	0.356" 20	21	0.356" 22	23	0.356" 24	25
26	0.356" 27	28	0.356" 29	30		
Total of 4.27 inches of water applied in June, 1994						

July 1994						
S	M	T	W	T	F	S
					0.356 1	2
3	0.356 4	5	0.356 6	7	0.356 8	9
10	11	0.267" 12	13	0.267" 14	15	16
17	18	0.267" 19	20	0.267" 21	22	23
24	0.267" 25	0.267" 26	27	28	29	30
31						
Total of 3.026 Inches applied in July, 1994						

APPENDIX A - IRRIGATION SCHEDULE

October 1994						
S	M	T	W	T	F	S
						0.356" 1
0.267" 2	0.267" 3	0.267" 4	0.267" 5	0.267" 6	0.267" 7	0.267" 8
0.267" 9	0.267" 10	0.267" 11	0.267" 12	0.267" 13	0.267" 14	0.267" 15
16	0.267" 17	18	0.267" 19	20	0.267" 21	22
0.267" 23	24	0.267" 25	26	0.267" 27	28	0.267" 29
30	0.267" 31					
All watering by Maintenance crew. Total of 6.23" in Oct., 1994						