

**CHANGE**

AC NO: 150/5345-12A CHG 1

DATE: 19 Mar 71



# ADVISORY CIRCULAR

## DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

**SUBJECT:** CHANGE 1 TO AC 150/5345-12A, SPECIFICATION FOR L-801  
BEACON

1. PURPOSE. This advisory circular change transmits paragraph changes to the subject advisory circular.
2. EXPLANATION OF CHANGES. The requirement for the total motor input power required to maintain rotation at normal speed at an ambient temperature of +70° F. has been increased. Also, the requirement for an automatic lampchanger arranged to burn a spare lamp upon failure of the first lamp with a telltale circuit to indicate failure of the first lamp has been changed to an optional requirement.
3. PAGE CONTROL CHART.

Remove Page	Dated	Insert Page	Dated
3 & 4	5/12/67	3	3/19/71
		4	5/12/67

A handwritten signature in cursive script, reading "Clyde W. Pace, Jr.", is located below the page control chart.

CLYDE W. PACE, JR.  
Acting Director, Airports Service