

AC NO: 150/5360-4

DATE: May 20, 1976



ADVISORY CIRCULAR

DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

SUBJECT: GUIDELINES FOR FEDERAL INSPECTION SERVICES FACILITIES AT
INTERNATIONAL AIRPORTS OF ENTRY AND AT LANDING RIGHTS AIRPORTS

1. PURPOSE. This advisory circular announces the availability of more current information on the requirements for Federal Inspection Services at airports of entry and at landing rights airports.
2. CANCELLATION. Advisory Circular 150/5360-3, Federal Inspection Service Facilities at International Airports, dated April 1, 1966, is cancelled.
3. REFERENCES.
 - a. Advisory Circular (AC) 00-2, Advisory Circular Checklist and Status of Federal Aviation Regulations, updated triannually, contains the listing of all current issuances of advisory circulars and changes thereto. It explains the circular numbering system and gives instructions for ordering advisory circulars that are for sale as well as those distributed free of charge.
 - (1) The following free advisory circulars may be obtained from the Department of Transportation, Publications Section, TAD-443.1, Washington, D. C. 20590:
 - (a) AC 00-2, Federal Register, Advisory Circular Checklist and Status of Regulations.
 - (b) AC 150/5000-3, Address List for Regional Airports Divisions and Airports District Offices.
 - (c) AC 150/5360-2, Airport Cargo Facilities.

b. The following publications may be purchased from the sources indicated:

- (1) Airport Terminals Reference Manual, Fifth Edition, Assistant Director General-Technical, International Air Transport Association, 1155 Mansfield Street, Montreal, Quebec, Canada H3D 4A4.
- (2) International Standards and Recommended Practices Annex 9 (Facilitation) to the Convention on International Civil Aviation Organization. International Civil Aviation Organization, Attention: Distribution Officer, P.O. Box 400, Succursale: Place de l'Aviation Internationale, 1000 Sherbrooke Street West, Montreal, Quebec, Canada H3A 2R2.

NOTE: Both the P.O. box and street address are necessary.

- (3) The Apron & Terminal Building Planning Report, dated July 1975, AD No. A018120. National Technical Information Service, 5285 Port Royal Road, Springfield, Virginia 22161.

4. BACKGROUND. Advisory Circular 150/5360-3, Federal Inspection Service Facilities at International Airports, dated April 1, 1966, contains material that describes and illustrates recommended facilities for inspection of passengers, baggage, and cargo entering the United States through airports designated by the U. S. Customs Service as international airports. However, the current inspection requirements have outgrown that guidance and persons with a need for current guidelines should contact the U. S. Customs Service office nearest them for assistance.

5. AVAILABILITY OF INFORMATION ON REQUIREMENTS FOR FEDERAL INSPECTION SERVICE FACILITIES.

- a. Until new design requirements for Federal Inspection Services facilities have been published, information on an interim basis is available at the following U. S. Customs Service Regional Offices:

U.S. Customs Service

Region I

100 Summer Street, Suite 1819
Boston, Massachusetts 02110

U.S. Customs Service

Region II

U.S. Customs House
Room 716, 6 World Trade Center
New York, New York 10048

U.S. Customs Service

Region III

U.S. Customs House
40 S. Gay Street
Baltimore, Maryland 21202

U.S. Customs Service

Region IV

Suite 300
7370 N.W. 36th Street
Miami, Florida 33166

U.S. Customs Service

Region V

701 Loyola Avenue
New Orleans, Louisiana 70113

U.S. Customs Service

Region VI

Suite 1240
500 Dallas Street
Houston, Texas 77002

U.S. Customs Service

Region VII

P.O. Box 2071
300 N. Los Angeles Street
Los Angeles, California 90053

U.S. Customs Service

Region VIII

450 Golden Gate Avenue
San Francisco, California 94102

U.S. Customs Service

Region IX

Suite 1501
55 E. Monroe Street
Chicago, Illinois 60603

- b. Refer to appendix 1 for a map of states covered by the various U.S. Customs Service regions.

6. HOW TO OBTAIN ADDITIONAL COPIES OF THIS CIRCULAR. Additional copies of this advisory circular may be obtained free of charge from the Department of Transportation, Publications Section, TAD-433.1, Washington, D. C. 20590.



WILLIAM V. VITALE

Director, Airports Service

APPENDIX 1. U. S. CUSTOMS SERVICE REGIONS



U. S. CUSTOMS SERVICE

