

TAD-494.4
AC NO: AC 150/5360-4A

DATE: October 7, 1977



ADVISORY CIRCULAR

DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

ANNOUNCEMENT OF AVAILABILITY--

SUBJECT: GUIDELINES FOR FEDERAL INSPECTION SERVICES FACILITIES AT
INTERNATIONAL AIRPORTS OF ENTRY AND AT LANDING RIGHTS AIRPORTS

1. PURPOSE. This advisory circular announces the availability of the booklet "Airports Within the United States - Guidelines for Federal Inspection Services Facilities."
 2. CANCELLATION. Advisory Circular 150/5360-4, Guidelines for Federal Inspection Services at International Airports of Entry and at Landing Rights Airports, dated May 20, 1976, is cancelled.
 3. REFERENCES. Advisory Circular (AC) 00-2, Advisory Circular Checklist and Status of Federal Aviation Regulations (FARs), updated triannually, contains the listing of current issuances of advisory circulars and changes thereto. It explains the circular numbering system and gives instructions for ordering advisory circulars that are for sale as well as those distributed free of charge. AC 00-2 also gives instructions for ordering the Federal Aviation Regulations. This checklist and the following advisory circulars may be obtained free of charge from the Department of Transportation, Publications Section, TAD-443.1, Washington, D.C. 20590:
 - a. AC 150/5360-6, Airport Terminal Building Development with Federal Participation.
 - b. AC 150/5360-7, Planning and Design Considerations for Airport Terminal Building Development.
 4. DESCRIPTION OF BOOKLET. This booklet contains guidance material on the design of airport terminal building facilities to accommodate the Federal Inspection Services (FIS) required for the processing of international traffic within the United States. The physical characteristics of the FIS area are discussed and delineated in terms of passenger and baggage flow and terminal buildings space utilization. Inspection facilities at international airports of entry and at landing rights airports are required in order to carry out the responsibilities
-

Initiated by: AAP-502

of the U. S. Customs Service of the Department of Treasury; the Immigration and Naturalization Service of the Department of Justice; the Animal and Plant Health Inspection Service of the Department of Agriculture; and the Public Health Service of the Department of Health, Education, and Welfare.

5. AVAILABILITY OF BOOKLET. A copy of "Airports Within the United States - Guidelines for Federal Inspection Services Facilities" can be obtained free of charge by writing to:

Director, Logistics Management Division
U. S. Customs Service
1301 Constitution Avenue, N. W.
Washington, D. C. 20229
Attn: Engineering Section

6. FACILITY APPROVAL AND ADDITIONAL INFORMATION.

- a. Additional information and details concerning FIS facility requirements may be obtained from the National Headquarters of the Federal Inspection Services listed below:


- (1) Associate Commissioner, Management
Immigration and Naturalization Service
425 I Street, N.W.
Washington, D.C. 20536
Attn: Chief, Engineering Branch
- (2) Foreign Quarantine Program
Public Health Service
Center for Disease Control
Atlanta, Georgia 30333
- (3) Commissioner of Customs
U. S. Customs Service
1301 Constitution Avenue, N.W.
Washington, D.C. 20229
Attn: Director, Logistics Management
Division
- (4) Plant Protection and Quarantine Programs
Animal and Plant Health Inspection Service
Department of Agriculture
Federal Building
Hyattsville, Maryland 20782
Attn: Chief, Port Operations Development
Staff

- b. Space and area planning approval is the joint responsibility of the Immigration and Naturalization Service, the U.S. Customs Service, and the Department of Agriculture (Immigration approves for itself and for the Public Health Service). Approving authority for Immigration and Agriculture is located in their national headquarters at the addresses given above. The U.S. Customs Service has delegated approval authority for new facilities to its nine regional offices. Addresses and a map of the states covered by the various U.S. Custom Service regions are given in appendix 1.
7. HOW TO OBTAIN ADDITIONAL COPIES OF THIS CIRCULAR. Additional copies of this advisory circular may be obtained free of charge from the Department of Transportation, Publications Section, TAD-433.1, Washington, D.C. 20590. FAA field personnel may obtain copies from their respective regional Distribution Officers.



WILLIAM V. VITALE
Acting Assistant Administrator
Office of Airports Programs

APPENDIX 1. U. S. CUSTOMS SERVICE REGIONS.



ADDRESSES OF U. S. CUSTOMS SERVICE REGIONS

Region I

U.S. Customs Service
100 Summer Street, Suite 1819
Boston, Massachusetts 02110

Region II

U.S. Customs Service
U.S. Customs House
Room 716, 6 World Trade Center
New York, New York 10048

Region III

U.S. Customs Service
U.S. Customs House
40 S. Gay Street
Baltimore, Maryland 21202

Region IV

U.S. Customs Service
99 SE 5th Street
Miami, Florida 33131

Region V

U.S. Customs Service
1440 Canal Street
New Orleans, Louisiana 70112

Region VI

U.S. Customs Service
Suite 1240
500 Dallas Street
Houston, Texas 77002

Region VII

U.S. Customs Service
P.O. Box 2071
300 N. Los Angeles Street
Los Angeles, California 90053

Region VIII

U.S. Customs Service
211 Main Street
San Francisco, California 94105

Region IX

U.S. Customs Service
Suite 1501
55 E. Monroe Street
Chicago, Illinois 60603