



U.S. Department
of Transportation
**Federal Aviation
Administration**

AC 20-36R

DOT LIBRARY
10A SECTION
REGULATIONS AND DATA
FEDERAL AVIATION ADMINISTRATION
Sept 19, 1991

ADVISORY CIRCULAR

**INDEX OF ARTICLES (MATERIALS, PARTS,
PROCESSES, AND APPLIANCES) CERTIFIED
UNDER THE TECHNICAL STANDARD ORDER
SYSTEM**

JUNE 1991



U.S. Department
of Transportation
**Federal Aviation
Administration**

Advisory Circular

Subject: INDEX OF ARTICLES (MATERIALS,
PARTS, PROCESSES, AND APPLIANCES)
CERTIFICATED UNDER THE TECHNICAL
STANDARD ORDER SYSTEM

Date: 6/28/91
Initiated by: AVN-113

AC No: 20-36R
Change:

1. PURPOSE. This Advisory Circular provides a list of manufacturers and articles produced by them under a Technical Standard Order (TSO) Authorization or letter of Technical Standard Order Design Approval. These articles are eligible for use on U.S. type certificated products.

2. CANCELLATION. AC 20-36Q, Index of Articles (Materials, Parts, Processes, and Appliances) Certified Under the Technical Standard Order System, dated July 16, 1985, is cancelled.

3. DISCUSSION.

a. TSO Authorizations are issued for articles (materials, parts, processes, or appliances) produced by manufacturers who comply with the requirement to submit quality control system data in addition to certifying that their designs comply with the pertinent TSO. TSO authorizations may be issued for articles manufactured outside the United States if the Administrator finds that the location of the manufacturer's facilities places no undue burden on the FAA in administering applicable airworthiness requirements.

b. The FAA also issues letters of TSO Design Approval for appliances manufactured in foreign countries with which the United States has an agreement for the acceptance of these appliances. These approvals are limited to appliances as defined in pertinent bilateral airworthiness agreements. Such approvals do not require submittal of quality control data and are issued when the appropriate foreign civil air authority certifies that the appliance has been examined, tested, and found to meet the applicable TSO or other performance standards specified in Federal Aviation Regulations (FAR) 21.617. Foreign manufactured appliances may be eligible for use on U.S. type certificated products when accompanied by a Certificate of Airworthiness for Export issued by the civil airworthiness authority of the country of manufacture under the provisions of FAR 21.502 or 21.617.

c. An FAA TSO Authorization (domestic) or letter of TSO Design Approval (foreign) does not convey installation approval. Accordingly, installation approval in a manner acceptable to the Administrator must be obtained for each particular product on which the article is to be installed.


William H. Williams, Jr.

Acting Director, Aviation Standards
National Field Office, AVN-1

**AC 20-36R
INDEX OF ARTICLES
(MATERIALS, PARTS, PROCESSES,
AND APPLIANCES) CERTIFIED
UNDER THE
TECHNICAL STANDARD ORDER SYSTEM
JUNE 1991**

**PREPARED BY:
DOT/FEDERAL AVIATION ADMINISTRATION
AVIATION STANDARDS NATIONAL FIELD OFFICE
ENGINEERING & MANUFACTURING BRANCH, AVN-110
P.O. BOX 26460
OKLAHOMA CITY, OKLAHOMA 73125**

HOW TO OBTAIN TECHNICAL STANDARD ORDERS

To obtain a copy of a Technical Standard Order (TSO) write to: U.S. Department of Transportation, Utilization and Storage Section (M-443.2), Washington, D.C. 20590.

To obtain a copy of a proposed TSO write to: Department of Transportation, Federal Aviation Administration, Aircraft Certification Service, Aircraft Engineering Division, (AIR-120), 800 Independence Avenue, S.W., Washington, D.C. 20591. Telephone (202) 267-9546.

Advisory Circular 20-110(), Index of Aviation Technical Standard Orders, contains a list of TSO's which have been issued and a list of proposed TSO's which FAA anticipates will be issued within 12 succeeding months. Copies of the Advisory Circular may be obtained from the U.S. Department of Transportation, Utilization and Storage Section (M-443.2), Washington, D.C. 20590.

INFORMATION REGARDING USE AND INSTALLATION OF APPLIANCES PRODUCED BY FOREIGN MANUFACTURERS

- NOTE 1: Each appliance manufactured in a foreign country and identified with a TSO marking under the provisions of an FAA TSO Design Approval (FAR 21.617) must be accompanied by a Certificate of Airworthiness for Export required by FAR 21.617(c), issued by the Civil Aviation Authority of the country of manufacture. The Certificate of Airworthiness may be in any form, e.g., certificate, tag, memo, etc. These appliances may be eligible for use on U.S. type certificated products, under the provisions of FAR 21.502, when accompanied by such certifications and when the installation (reference Note 2) has been approved by the FAA.
- NOTE 2: Neither the FAA issued letter of TSO Design Approval nor the Certificate of Airworthiness for Export from the country of manufacture convey installation approval. Accordingly, installation approval in a manner acceptable to the Administrator must be obtained for each particular product on which the article is to be installed. Approval for return to service must be performed by a person authorized in FAR Part 43, Maintenance, Preventive Maintenance, Rebuilding and Alteration.

PREFACE

This publication lists those manufacturers who hold a Technical Standard Order (TSO) Authorization or a letter of TSO Design Approval. The requirements for obtaining an authorization or letter are prescribed in Part 21, Subpart O of the Federal Aviation Regulations.

The page layout is arranged as follows:

- Column 1 - Lists the specific TSO number. A letter F in this column denotes foreign manufacturers.
- Column 2 - Identifies the person to whom the approval was issued.
- Column 3 - Lists the FAA region which issued the authorization or letter of approval.
- Column 4 - Shows the TSO descriptive title. This title appears one time at the beginning of each group of TSO holders meeting the requirements of a specific TSO.
- Column 5 - Lists the model or part number of the article approved.

Anyone desiring further information on an article listed herein should contact the TSO holder or the FAA region which issued the authorization or letter of approval.

TECHNICAL STANDARD ORDER INDEX

| TSO NO. | TSO SUBJECT | PAGE |
|---------|--|------|
| TSO-C1 | Cargo and baggage compartment smoke detection instruments | 1 |
| TSO-C2 | Airspeed indicator (pitot static) | 2 |
| TSO-C3 | Turn-and-slip indicator | 5 |
| TSO-C4 | Bank and pitch instruments (indicating gyro-stabilized type) (gyroscopic horizon, attitude gyro) | 12 |
| TSO-C5 | Direction instrument, nonmagnetic, gyro stabilized type (directional gyro) | 24 |
| TSO-C6 | Direction instruments, magnetic (gyro-stabilized type) | 28 |
| TSO-C7 | Direction instrument, magnetic, non-stabilized type (magnetic compass) | 40 |
| TSO-C8 | Rate of climb indicator, pressure actuated (vertical speed indicator) | 41 |
| TSO-C9 | Automatic pilots | 46 |
| TSO-C10 | Aircraft altimeter, pressure actuated, sensitive type | 60 |
| TSO-C11 | Fire detectors (thermal sensing and ionization sensing types) | 66 |
| TSO-C12 | Life rafts (twin tube) | 73 |
| TSO-C13 | Life preservers | 73 |
| TSO-C14 | Aircraft fabric, intermediate grade; external covering material | 77 |
| TSO-C15 | Aircraft fabric, grade A; external covering material | 77 |
| TSO-C16 | Air-speed tubes (electrically heated) | 78 |
| TSO-C17 | Fire resistant aircraft sheet and structural material | 79 |
| TSO-C18 | None | |
| TSO-C19 | Portable water-solution type fire extinguishers | 79 |
| TSO-C20 | Combustion heaters | 80 |
| TSO-C21 | Special aircraft turnbuckle assemblies and/or turnbuckle safetying devices | 82 |
| TSO-C22 | Safety belts | 83 |
| TSO-C23 | Parachutes | 93 |
| TSO-C24 | None | |
| TSO-C25 | Aircraft seats and berths (Type I transport, 6g forward load) | 99 |
| TSO-C26 | Aircraft wheels and brakes | 104 |
| TSO-C27 | Twin seaplane floats | 123 |
| TSO-C28 | Aircraft skis | 125 |
| TSO-C29 | None | |
| TSO-C30 | Aircraft position lights | 126 |
| TSO-C31 | High frequency (HF) radio communication transmitting equipment operating within the radio frequency range of 1.5 to 30 megacycles | 127 |
| TSO-C32 | High frequency (HF) radio communication receiving equipment operating within the radio frequency range of 1.5 to 30 megacycles | 130 |
| TSO-C33 | Position light flashers, single-circuit (for non-air carrier aircraft) | 133 |
| TSO-C34 | Airborne ILS glide slope receiving equipment | 133 |
| TSO-C35 | Airborne radio marker receiving equipment | 141 |
| TSO-C36 | Airborne ILS localizer receiving equipment | 145 |
| TSO-C37 | VHF radio communications transmitting equipment operating within the radio-frequency range of 118-136 megacycles | 154 |
| TSO-C38 | VHF radio communications receiving equipment operating within the radio-frequency range of 118-136 megacycles | 161 |
| TSO-C39 | Aircraft seats and berths | 167 |
| TSO-C40 | VOR radio receiving equipment operating within the radio-frequency range of 108-118 megacycles (for air carrier aircraft) | 226 |
| TSO-C41 | Airborne radio receiving and direction finding equipment operating within the radio frequency range of 200-415 kilocycles (for air carrier aircraft) | 235 |
| TSO-C42 | Propeller feathering hose assemblies (rubber and wire braid construction) | 240 |
| TSO-C43 | Temperature indicators | 243 |

TECHNICAL STANDARD ORDER INDEX - CONTINUED

| TSO NO. | TSO SUBJECT | PAGE |
|---------|--|------|
| TSO-C44 | Fuel flowmeters | 249 |
| TSO-C45 | Manifold pressure indicating instruments | 253 |
| TSO-C46 | Maximum allowable airspeed indicator systems | 254 |
| TSO-C47 | Pressure instruments - fuel, oil, and hydraulic | 258 |
| TSO-C48 | Carbon monoxide detector instruments | 263 |
| TSO-C49 | Electric tachometer: magnetic drag (for air carrier aircraft) | 263 |
| TSO-C50 | Aircraft audio and interphone amplifiers | 268 |
| TSO-C51 | Aircraft flight recorder | 273 |
| TSO-C52 | Flight directors | 274 |
| TSO-C53 | Fuel and engine oil system hose assemblies (rubber or tetrafluoroethylene tube and wire braid construction) | 285 |
| TSO-C54 | Stall warning instruments | 301 |
| TSO-C55 | Fuel and oil quantity instruments (for reciprocating engine aircraft) | 302 |
| TSO-C56 | Engine-driven direct current generators for aircraft certified under Part 25 | 304 |
| TSO-C57 | Aircraft headsets and speakers (for air carrier aircraft) | 306 |
| TSO-C58 | Aircraft microphones (for air carrier aircraft) | 308 |
| TSO-C59 | Airborne selective calling equipment (for air carrier aircraft) | 309 |
| TSO-C60 | Airborne Loran A receiving equipment operating within the radio-frequency range of 1800-2000 kilocycles (for air carrier aircraft) | 310 |
| TSO-C61 | Portable aircraft emergency communications equipment (for air carrier aircraft) | 313 |
| TSO-C62 | Aircraft tires | 314 |
| TSO-C63 | Airborne weather radar equipment operating within the radio-frequency bands of 5,350 to 5,470 Mc. and 9,300 to 9,500 Mc. | 360 |
| TSO-C64 | Oxygen mask assembly, continuous flow, passenger (for air carrier aircraft) | 367 |
| TSO-C65 | Airborne doppler radar groundspeed and/or drift angle measuring equipment (for air carrier aircraft) | 367 |
| TSO-C66 | Airborne distance measuring equipment (for air carrier aircraft) | 368 |
| TSO-C67 | Airborne radar altimeter equipment (for air carrier aircraft) | 375 |
| TSO-C68 | Airborne automatic dead reckoning computer equipment utilizing aircraft heading and doppler obtained groundspeed and drift angle data (for air carrier aircraft) | 376 |
| TSO-C69 | Emergency evacuation slides | 376 |
| TSO-C70 | Liferafts (nonreversible) | 379 |
| TSO-C71 | Airborne static ("DC to DC") electrical power converter (for air carrier aircraft) | 380 |
| TSO-C72 | Individual flotation devices | 380 |
| TSO-C73 | Static electrical power inverter | 390 |
| TSO-C74 | Airborne ATC transponder equipment | 391 |
| TSO-C75 | Hydraulic hose assemblies | 397 |
| TSO-C76 | Fuel drain valves | 412 |
| TSO-C77 | Gas turbine auxiliary power units | 412 |
| TSO-C78 | Crewmember demand oxygen masks | 413 |
| TSO-C79 | Fire detectors (radiation sensing type) | 414 |
| TSO-C80 | Flexible fuel and oil cell material | 414 |
| TSO-C81 | None | |
| TSO-C82 | None | |
| TSO-C83 | None | |
| TSO-C84 | Cockpit voice recorder | 416 |
| TSO-C85 | Survivor locator lights | 417 |

TECHNICAL STANDARD ORDER INDEX - CONTINUED

| TSO NO. | TSO SUBJECT | PAGE |
|----------|---|------|
| TSO-C86 | None | |
| TSO-C87 | Airborne low-range radio altimeter | 418 |
| TSO-C88 | Automatic pressure altitude digitizer equipment | 420 |
| TSO-C89 | Oxygen regulators, demand | 425 |
| TSO-C90 | Cargo pallets, nets and containers | 425 |
| TSO-C91 | Emergency locator transmitters | 436 |
| TSO-C92 | Ground proximity warning equipment | 439 |
| TSO-C93 | Airborne interim standard microwave landing system converter equipment (ISMLS) | 441 |
| TSO-C94 | Airborne omega receiving equipment | 441 |
| TSO-C95 | Mach Meters | 445 |
| TSO-C96 | Anticollision lights system | 445 |
| TSO-C97 | Lithium sulfur dioxide batteries | 445 |
| TSO-C98 | None | |
| TSO-C99 | Protective breathing equipment | 446 |
| TSO-C100 | Child restraint systems | 446 |
| TSO-C101 | Over speed warning instruments | 446 |
| TSO-C102 | None | |
| TSO-C103 | None | |
| TSO-C104 | Microwave landing systems (MLS) airborne receiving equipment | 447 |
| TSO-C105 | Optional display equipment for weather and ground mapping radar indicators | 448 |
| TSO-C106 | Air data computer | 448 |
| TSO-C107 | None | |
| TSO-C108 | None | |
| TSO-C109 | Airborne navigation data storage system | 448 |
| TSO-C110 | Airborne passive thunder-storm detection system | 449 |
| TSO-C111 | None | |
| TSO-C112 | Airtraffic control radar beacon system mode select (ATCRBS/MODE S) airborne equipment | 450 |
| TSO-C113 | Airborne Multipurpose electronic display | 452 |
| TSO-C114 | Torso restraint systems | 453 |
| TSO-C115 | Airborne area navigation equipment using multi-sensor inputs | 453 |
| TSO-C116 | Crewmember protective breathing-equipment | 456 |
| TSO-C117 | None | |
| TSO-C118 | None | |
| TSO-C119 | Traffic alert and collision avoidance system (TCAS) airborne equip., TCAS II | 456 |
| TSO-C120 | None | |
| TSO-C121 | Underwater locating devices (acoustic) (self-powered) | 457 |
| TSO-C122 | None | |
| TSO-C123 | None | |
| TSO-C124 | None | |

SUBJECT INDEX

| ALPHABETICAL LIST | TSO NO. | PAGE |
|--|----------|---------|
| Airborne area navigation equipment using multi-sensor inputs | C115 | 453 |
| Airborne ATC transponder equipment | C74 | 391 |
| Airborne interim standard microwave landing system converter equipment (ISMLS) | C93 | 441 |
| Airborne multipurpose electronic display | C113 | 452 |
| Airborne navigation data storage system | C109 | 448 |
| Airborne omega receiving equipment | C94 | 441 |
| Airborne passive thunder-storm detection system | C110 | 449 |
| Air data computer | C106 | 448 |
| Air-speed tubes, electrically heated | C16 | 78 |
| Airtraffic control radar beacon system mode select (ATCRBS/MODE S) airborne equipment | C112 | 450 |
| Altimeters: Pressure actuated | C10 | 60 |
| Radar | C67 | 375 |
| Low range radio | C87 | 418 |
| Amplifiers: Audio and interphone | C50 | 268 |
| Anticollision lights system | C96 | 445 |
| Automatic pilots | C9 | 46 |
| Bank and pitch instruments | C4 | 12 |
| Batteries, lithium | C97 | 445 |
| Belts, safety | C22 | 83 |
| Berths and seats | C25, C39 | 99, 167 |
| Brakes and wheels | C26 | 104 |
| Cargo pallets, nets and containers | C90 | 425 |
| Child restraint systems | C100 | 446 |
| Cockpit voice recorder | C84 | 416 |
| Converter, static electrical power | C71 | 380 |
| Crewmember protective breathing - equipment | C116 | 456 |
| Digitizer, altitude, automatic pressure | C88 | 420 |
| Direction instruments: Nonmagnetic, gyro stabilized | C5 | 24 |
| Magnetic, gyro stabilized | C6 | 28 |
| Magnetic, non-stabilized | C7 | 40 |
| DME, distance measuring equipment | C66 | 368 |
| Doppler dead reckoning computer equipment | C68 | 376 |
| Doppler radar ground speed and/or drift angle equipment | C65 | 367 |
| Emergency evacuation slides | C69 | 376 |
| Fabric: Aircraft exterior covering, intermediate grade | C14 | 77 |
| Exterior covering, Grade A | C15 | 77 |
| Fire detectors: Thermal and ionization sensing | C11 | 66 |
| Radiation sensing | C79 | 414 |
| Fire extinguishers - portable | C19 | 79 |
| Fire resistant sheet and structural material | C17 | 79 |
| Flight director | C52 | 274 |
| Flight recorder | C51 | 273 |
| Floats, twin seaplane | C27 | 123 |
| Floation devices, individual | C72 | 380 |
| Fuel and oil cell material, flexible | C80 | 414 |
| Fuel and oil quantity instruments | C55 | 302 |
| Fuel drain valves | C76 | 412 |
| Fuel flowmeters | C44 | 249 |

SUBJECT INDEX - CONTINUED

| ALPHABETICAL LIST | TSO NO. | PAGE |
|---|---------|------|
| Gas turbine auxiliary power units | C77 | 412 |
| Generators: Engine driven direct current | C56 | 304 |
| Headsets and speakers, air carrier | C57 | 306 |
| Heaters - combustion | C20 | 80 |
| Hose assemblies: Propeller feathering | C42 | 240 |
| Fuel and engine oil system | C53 | 285 |
| Hydraulic | C75 | 397 |
| Indicators: Airspeed, pitot static | C2 | 2 |
| Turn-and-slip | C3 | 5 |
| Rate of climb | C8 | 41 |
| Temperature | C43 | 243 |
| Airspeed, maximum allowable | C46 | 254 |
| Instruments: Smoke detection, cargo and baggage compartment | C1 | 1 |
| Manifold pressure | C45 | 253 |
| Fuel, oil and hydraulic pressures | C47 | 258 |
| Carbon monoxide detector | C48 | 263 |
| Stall warning | C54 | 301 |
| Fuel and oil quantities | C55 | 302 |
| Inverters: Static electrical power | C73 | 390 |
| Life preservers | C13 | 73 |
| See also "Flotation devices, individual" | C72 | 380 |
| Life rafts: Twin tube | C12 | 73 |
| Nonreversible | C70 | 379 |
| Lights: Position | C30 | 126 |
| Survivor locator | C85 | 417 |
| Light flashers: Non - air carrier | C33 | 133 |
| Mach meters | C95 | 445 |
| Microphones, air carrier | C58 | 308 |
| Navigation equipment: Microwave landing system | C93 | 441 |
| Omega | C94 | 441 |
| Optional display equipment for weather and ground mapping radar indicator | C105 | 448 |
| Over speed warning instrument | C101 | 446 |
| Oxygen mask: Passenger, continuous flow (air carrier) | C64 | 367 |
| Crewmember, demand | C78 | 413 |
| Oxygen regulator, demand | C89 | 425 |
| Parachutes | C23 | 93 |
| Position light flashers: Non - air carrier | C33 | 133 |
| Protective breathing equipment | C99 | 446 |
| Radio altimeter, low range | C87 | 418 |
| Radio equipment: HF transmitting | C31 | 127 |
| HF receiving | C32 | 130 |
| ILS glide slope receiving | C34 | 133 |
| Radio marker receiving | C35 | 141 |
| ILS localizer receiving | C36 | 145 |
| VHF transmitting | C37 | 154 |
| VHF receiving | C38 | 161 |
| VOR receiving | C40 | 226 |
| Direction finding (ADF) | C41 | 235 |
| Loran A receiving | C60 | 310 |
| Portable emergency | C61 | 313 |

SUBJECT INDEX - CONTINUED

| ALPHABETICAL LIST | TSO NO. | PAGE |
|--|---------|------|
| Weather radar | C63 | 360 |
| Emergency locator transmitter (ELT) | C91 | 436 |
| Ground proximity warning | C92 | 439 |
| MLS airborne receiving equipment | C104 | 447 |
| Recorders: Flight | C51 | 273 |
| Cockpit voice | C84 | 416 |
| Restraint systems | C100 | 446 |
| SELCAL, selective calling equipment | C59 | 309 |
| Skis | C28 | 125 |
| Speakers and headsets | C57 | 306 |
| Survivor locator lights | C85 | 417 |
| Tachometers: Electric, magnetic drag | C49 | 263 |
| Temperature indicators | C43 | 243 |
| Tires | C62 | 314 |
| Torso restraint systems | C114 | 453 |
| Traffic alert and collision avoidance system (TCAS) airborne equip., (TCAS II) | C119 | 456 |
| Transmitters: HF transmitting equipment | C31 | 127 |
| VHF transmitting equipment | C37 | 154 |
| ELT, emergency locator transmitters | C91 | 436 |
| Transponder equipment, Airborne ATC | C74 | 391 |
| Turn-and-slip indicator | C3 | 5 |
| Turnbuckle assemblies and/or devices | C21 | 82 |
| Underwater locating devices (acoustic) (self-powered) | C121 | 457 |
| Wheels and brakes | C26 | 104 |

INDEX OF MATERIALS, PARTS, AND APPLIANCES CERTIFIED
UNDER THE TECHNICAL STANDARD ORDER SYSTEM

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|--|---|
| TSO-C1a | Pyrotector, Inc. Hingham, MA 02043 | NE | CARGO AND BAGGAGE COMPARTMENT SMOKE DETECTION INSTRUMENTS | 230 30-303A-2 30-231 30-303A-3 30-231-4 30-303A-4 |
| TSO-C1b | Autronics Corporation 180 N. Vinado Ave. Pasadena, CA 91109 | NM | CARGO AND BAGGAGE COMPARTMENT SMOKE DETECTION INSTRUMENTS | 2156() Series |
| TSO-C1b *F | Cerberus Guinaid Rue Fourny B.P. 20 78530 BUC, France | EU | | CG7P(X)-(XX) CG7G(X)-(XX) CG7PO()() CG7GO()() KTA2400(X) |
| TSO-C1b *F | Ets 10 rue de l'Abbe Glatz 92270 - Bois Colombes France | EU | | FR21()() FR22()() FR32()() |
| TSO-C1b | Fenwal, Inc. 400 Main Street P.O. Box 309 Ashland, MA 01721 | NE | | 72-11XXX1-X00 72-12XXX1-X00 72-11XXX1-X0X 72-12XXX1-X0X 72-130001-XXX |
| TSO-C1b | Japan Aircraft Maint. (America), Inc. 8227 - 44th Avenue West Mukilteo, WA 98275 | NM | | PU90-1 |
| TSO-C1b | Pyrotector, Inc. 333 Lincoln St. Hingham, MA 02043 | NE | | 30-231-() 30-284-() 30-303E-3 30-303E-10 30-326-() |
| TSO-C1b | Systron Donner Safety Systems Div. 2731 Systron Dr. Concord, CA 94518-1355 | NM | | 601 |
| TSO-C1c *F | CERBERUS GUINARD 617 rue Fourny 78530 BUC France | EU | CARGO AND BAGGAGE COMPARTMENT SMOKE DETECTION INSTRUMENTS | KTA 2400(x) |
| TSO-C1c *F | L'HOTELLIER 10 rue de l'Abbe Glatz 92270 Bois Colombes France | EU | | FR 212 (X)-(X) FR 222 (X)-(X) FR 312 (X)-(X) FR 322 (X)-(X) |
| TSO-C1c | Systron Donner 2731 Systron Drive Concord, CA 94518-1355 | NM-L | | Model 601:8550-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|--------------|--|------|--|--|---|--|
| TSO-C2 *F | Aeritalia, S.p.A. Merviano (Milan), Italy | EU | AIRSPEED INDICATOR (PITOT STATIC) | 11030() 8.039.003 8.039.508 8.039.703 8.039.503 8.039.508.1 8.039.808.1 8.038.808.1.02 8.039.808.1.03 8.039.808.1.04 | 11050() 8.039.008 8.039.603 8.039.708 8.039.008.1 8.039.608.1 8.039.808.1.01 | 8.039.408 8.039.608 8.039.808 8.039.408.1 8.039.708.1 |
| TSO-C2 | Bendix Instrument & Life Support Div. Hickory Grove Rd. Davenport, IA 52802 | CE-W | | 1453 | | |
| TSO-C2 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 5802-() G1212 | 22-695() | 22-697() |
| TSO-C2 | Lear Siegler, Inc. Instrument Division 4142 Eastern Ave. S.E. Grand Rapids, MI 49508 | CE-C | | B0152() | B0203() | |
| TSO-C2 | Production Research Corp. Cummings & Sander 6426 San Francisco Rd. Glendale, CA 91209 | NM | | SP-52() SP5148-() | SP5103-() | SP5104-() |
| TSO-C2 | Rockwell International Collins Avionics Division 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | DU-1000:622-7484-411 | | |
| TSO-C2 *F | Tokyo Acft. Instrument Co. 1600 Izumi, Komae-chi, Kitatama-gun, Tokyo, Japan | NM | | SA-4 SA-40-1LB SA-46-1RB | SA-40-1RC SA-45-1RB SA-46-1LB | SA-40-1RB SA-45-1LB |
| TSO-C2a | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | AIRSPEED INDICATOR (PITOT STATIC) | S-15() | | |
| TSO-C2a | AMETEK/U.S. Gauge 900 Clymer Ave. Sellersville, PA 18960 | NE | | AW-2 3/4-158TF37 | | |
| TSO-C2a | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | 1426-6H-B17 1426-29H-B17 1426-29F-B17 1426-47G-B17 1426-1AK-B1 | 1426-29K-B17 1426-29G-B17 1426-47H-B17 1426-6K-B17 1426-1AF-B1 | 1426-29J-B17 1426-29D-B17 1426-47J-B17 1426-1AH-B1 1426-12G-B1 |
| TSO-C2a | Karnish Instrument Inc. 210 Third Ave. Lock Haven, PA 17745 | NE | | AC-118A AC-131A | AC-129A | AC-130A |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-------------------------|--|--|--|
| TSO-C2b *F | Aeritalia, S.p.A. Nerviano (Milan), Italy | EU | AIRSPEED INSTRUMENTS | 11000() 11051() 8.042.003.1 8.042.508.1 8.042.703.1 8.042.508.2 8.042.703.2.02 | 11010() 11020() 8.042.008.1 8.042.603.1 8.042.708.1 8.042.608.2 | 11031() 11024() 8.042.503.1 8.042.608.1 8.042.008.2 8.042.708.2 |
| TSO-C2b | Aero Mechanism Inc. 20327 Nordhoff Street Van Nuys, CA 91405 | NM | | 8059() | 8502-() | |
| TSO-C2b | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | | H-15-K S-25-K-10 20015() 20925() | S18-() S-25-KA() 20025() 20515() | S-15-KA-() S-40-KA() 20040() 20018() |
| TSO-C2b | Acft. Inst. & Dev., Inc. 317 E. Lewis St. Wichita, KS 67202 | CE-W | | 11-10()-() | | |
| TSO-C2b | ALCOR, Inc. P. O. Box 32516 San Antonio, TX 78284 | SW | | TS-27 TS-27-001-53 TS-27-001-56 CTS-2753 | TS-27-001-51 TS-27-001-54 CTS-2751 CTS-2754 | TS-27-001-52 TS-27-001-55 CTS-2752 CTS-2755 |
| TSO-C2b | AMETEK/U.S. Gauge 900 Clymer Ave. Sellersville, PA 18960 | NE | | AW2821AJ01 AW2812A005 AW2837()()() | AW2812AJ02 AW2823()()() | AW2812A004 |
| TSO-C2b *F | Badin-Crouzet Aerodrome Toussus le Noble P. O. Box 17, 78530 Buc France | EU | | 38 399-000 38 399-390 | 38 399-050 | 38 399-090 |
| TSO-C2b | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | EA-5171 EA-5174 | EA-5172 EA-5175 | EA-5173 EA-5176 |
| TSO-C2b | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Systems Div. P.O. Box 21111 Phoenix, AZ 85036-1111 | NM | | HG280D-() | HG280D80-() | HG4808() |
| TSO-C2b | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 No. 19th Ave. Phoenix, AZ 85027 | NM | | 2594621-() HG280D-() | 2594466-() | 403891-() |
| TSO-C2b | Instrument Specialties Co. P. O. Box 365 Euless, TX 76039 | SW | | 5802-() | | |
| TSO-C2b | Instrument Technology Corp. P. O. Box 20478 Dallas, TX 75229 | SW | | 90-1000(7) | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-------------------------|---|---|----------------------------------|
| TSO-C2b | Kollzman/IDC Avionics Group 170 Coolidge Ave. P.O. Box 81 Englewood, NJ 07631 | NE | | 24779-() 36950-() | 32760-() 38610-() | 34090-() 38620-() |
| TSO-C2b | Karnish Instruments Inc. 210 Third Ave. Lock Haven, PA 17745 | NE | | AC-118A | AC-130A | AC-131A |
| TSO-C2b *F | Kollsman Industries, Ltd. Southampton, Hampshire England | EU | | L-8305()-() ()-() () () | | |
| TSO-C2b | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Hwy. So. Merrimack, NH 03054 | NE | | 1296U-0194 1296U-0215 A29297-10-006 A29297-10-007 A32707-10-006 B12961-0218 B25685-10-006 ()36157-()-() | 1296U-0197 1296U-0218 A29297-10-004 A32707-10-001 A34823-04-003 B25685-10-002 B25685-10-007 | 1296U-0214 1296U-0219 |
| TSO-C2b | MacLeod Instrument Corp. Sub. of Aerosonic Corp. P. O. Box 5163 Clearwater, FL 33518 | CE-A | | 230-() | 2030-() | |
| TSO-C2b *F | Smiths Industries, Ltd. Aviation Division Bishops Cleeve Cheltenham Gloucestershire, England | EU | | 246AS() WL271AS() | WL101AMS() WL280AS() | WL102AMS() |
| TSO-C2b | Teledyne Avionics P. O. Box 888 Charlottesville, VA 22092 | NE | | Type A, SLZ () | | |
| TSO-C2b *F | Thompson-CSF 31 rue Camille Desmoulins 92131 Issy-les-Maulineaux, France | EU | | 64-040-5()() 64-042-1()() 64-050-8()() | | 640-40-8()() 64-050-2()() |
| TSO-C2b *F | Tokyo Acft. Instrument Co. 1600 Izumi, Komae-machi Kitatama-gun, Tokyo, Japan | NM | | SA-40-11() | SA-45-11() | SA-46-11() |
| TSO-C2b | United Instruments, Inc. 2415 S. Glendale Wichita, KS 67210 | CE-W | | 8000()() 8100()() 8135()() | 8025()() 8125()() | 8030()() 8130()() |
| TSO-C2c | Aero Systems, Inc. P.O. Box 20478 Dallas, TX 75220 | SW | AIRSPEED INSTRUMENTS | | | |
| TSO-C2c | Bendix/King General Aviation Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | KAI 487:066-3079-10, -11, -12, -13, -14 20, -21, -22, -23 KDC 481:065-0082-02, -04 KAI 486 KAI 487 KDC-481 | | |
| TSO-C2c | Evergreen Systems, Inter'l. 31336 Via Colinas, #103 Westlake Village, CA 91362 | NM | | 581 | | |
| TSO-C2c | Honeywell, Inc. Sperry Commercial Flight | NM | | SG-820:4057800-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|-------------------------|--|-------------|-------------|
| | Systems Division Air Transport Facility 21111 N. 19th Avenue Phoenix, AZ 85306-1111 | | | | | |
| TSO-C2c | Intercontinental Dynamics Corporation 170 Coolidge Ave. P.O. Box 81 Englewood, NJ 07631 | EA | | 45760-() | | |
| TSO-C2c | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | ADC-85:622-8051-002 ADM-85:622-8692-002, -003, -004, -005, -006, -011 ARP-86:622-9227-002 DU-1000:622-7484-411 ADC-850 ADM-850 ARP-86 DCP-1000 | | |
| TSO-C2c *F | Smiths Industries Bishops Cleeve Cheltenham, Gloucestershire England | EU | | 290AS() | | |
| TSO-C2d | Avionix Corporation 8 Romanelli Avenue South Hackensack, NJ 07606 | NE | AIRSPEED INSTRUMENTS | 2A110 (XXXXXX) | | |
| TSO-C2d | Instrument and Flight Research 2716 George Washington Blvd. Wichita, KS 67210 | CE-W | | 1FR 20-15, 20-20, 20-25, 20-30, 20-75 | | |
| TSO-C3 *F | Aeritalia, S.p.A. Nerviano (Milan), Italy | EU | TURN-AND-SLIP INDICATOR | 26240() | 26340() | |
| | | | | 8.042.003.1 | 8.042.008.1 | 8.042.503.1 |
| | | | | 8.042.508.1 | 8.042.603.1 | 8.042.608.1 |
| | | | | 8.042.703.1 | 8.042.708.1 | 8.042.008.2 |
| | | | | 8.042.508.2 | | 8.042.608.2 |
| | | | | 8.042.703.2.02 | | 8.042.708.2 |
| TSO-C3 | R. C. Allen, Inc. Instrument Division 678 Front Ave., N. W. Grand Rapids, MI 49501 | CE-C | | A1400 | 1600 | A2200-5 |
| | | | | A2310 | A2450-1 | A2450-2 |
| | | | | A2450-3 | A2450-4 | A2450-5 |
| | | | | A2450-6 | A2450-7 | A2450-8 |
| | | | | A2450-9 | A2450-10 | A2550-5 |
| | | | | A2570 | A2670-1 | A2670-2 |
| | | | | A2670-3 | A2670-4 | A2670-5 |
| | | | | A2670-6 | A2670-7 | A2670-8 |
| | | | | A2670-9 | A2670-10 | A2840 |
| | | | | A2941 | M3540-1 | |
| | | | | MC-4A | MD-1A | MD-1B |
| | | | | MD-4 | MD-8 | MD-8A |
| | | | | M5910 | MS28024-2 | MS28024-3 |
| | | | | RCA-2 | RCA-2W | RCA-12 |
| | | | | RCA-28 | RCA-212R | RCA-212F |
| | | | | RCA-212W | RCA-228R | RCA-228F |
| | | | | RCA-412F | RCA-412R | RCA-412W |
| | | | | RCA-428F | RCA-428R | RCA-428W |
| | | | | 28P61-D28 | 28F65-E18S | 29P65-E1S |
| TSO-C3 | ANSCO, Division of General Aniline and Film Corp. Binghamton, NY 13902 | NE | | E-1217 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|--------------|---|------|--------------------------------|--|--|---|
| TSO-C3 *f | Apparatebau Gauting, GmbH Ammerseestr. 31 8035 Gauting 2, Germany | EU | | WZ 402 | | |
| TSO-C3 | Bendix Inst. & Life Support Div. Hickory Grove Rd. Davenport, IA 52802 | CE-W | | 3907 3922 3929 | 3919 3924 3934 | 3920 3927 |
| TSO-C3 | Brittain Industries Div. Narco Scientific Ind. Commerce Dr. Fort Washington Ind. Park Fort Washington, PA 19034 | NE | | TC12-1() | TC100() | |
| TSO-C3 | Collins Radio Co. 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | 329B-() 329B-7F 329B-8() 329B-8F 522387003 772-5005-001 | 329B-7() 329B-7J 329B-8A 329B-8G 522443003 7771224001 | 329B-7A 329B-7/8G 329B-8B 522387001 527-4529-001 7771224004 |
| TSO-C3 | FL Aerospace Corp. General Design/Janitrol Aero Division 8600 Lankershim Blvd. Sun Valley, CA 91352 | NM | | 2800() | | |
| TSO-C3 | Lear Siegler, Inc. Instrument Division 4141 Eastern Ave., S. E. Grand Rapids, MI 49508 | CE-C | | 4005T | | |
| TSO-C3 | Production Research Corp. Cummings & Sander 6426 San Francisco Rd. Glendale, CA 91209 | NM | | SP13057-1() SP5407-() | SP-5300-1-() SP-5300-2-() | |
| TSO-C3 | Western Machine Works, Inc. Wichita, KS 67202 | CE-W | | W2-B12 W2-C24 | W2-B24 W3 | W2-C12 |
| TSO-C3a | R. C. Allen, Inc. Instrument Division 678 Front Ave., N. W. Grand Rapids, MI 49501 | CE-C | TURN-AND- BANK INDICATOR | A1610 A1725 A2475-1 A5758 B4050-01 B4050-04 G4000 G4003 M3075 M3500-3 M3500-6 M3520-1 M3520- MD-4A RCA-30 RCA-92B-1 12P61-A2A 12F65-A2S 12W2-E1A 28P61-A2A 28P65-D2S 28W2-D2S | A1715 A1730 A2475-2 B4050-02 G4001 M3500-1 M3500-4 M3500-7 M3520-2 M3520-5 RCA-40() RCA-120 12F65-A1A 12F65-D2S 12W2-A2A 28F65-A1A-A2A 28F65-A1A-A2S 28F65-A1A-D2S | A1720 A2420 Series A2475-3 B4050-03 G4002 M3500-2 M3500-5 M3500-8 M3520-3 M3520-6 RCA-80B RCA-121 12F65-A2A 12W2-D2S 12W2-E1S |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|--|------|-----------|--|-----------------------------------|------------------------|
| ===== | | | | | | |
| | | | | 28W2-E1A 28W2-C1A | 28W2-A2A | 28W2-E1S |
| TSO-C3a | ANSCO, Division of General Aniline and Film Corp. Binghamton, NY 13902 | NE | | AP 7000 | | |
| TSO-C3a | Bendix Eclipse-Pioneer Division Teterboro, NJ 07608 | NE | | 1722 Series 3907 Series | 3906 Series 3932 Series | |
| TSO-C3a | Brittain Industries, Inc. 3266 N. Sheridan Road Tulsa, OK 74115 | SW | | TC-100() | | |
| TSO-C3a | Brittain Industries, Inc. P. O. Box 12248 Houston, TX 77017 | SW | | TC100() | | |
| TSO-C3a | Century Flight Systems, Inc. P.O. Box 610 Mineral Wells, TX 76067 | | | 52069 | 52075-() | |
| TSO-C3a | Clifton Precision Instrument & Life Support Div. 2734 Hickory Grove Road Davenport, IA 52808 | CE-W | | 3932 | 3934 | |
| TSO-C3a | Collins Radio Co. 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | 329B-7R | 345A-7() | FD-109H |
| TSO-C3a | Edo-Aire Mitchell P. O. Box 610 Mineral Wells, TX 76067 | SW | | 52069 52075-4 52069() | 52075() 52075-5 1C497-6 | 52075-3 52075-6 |
| TSO-C3a | FL Aerospace Corp. General Design/ Janitrol Aero Division 8600 Lankershim Blvd. Sun Valley, CA 91352 | NM | | 3600() | | |
| TSO-C3a | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | 2588264 AD-200 HZ-4() | 2588424-() 2588369() HZ-6 | 2588424-901 HZ-6() |
| TSO-C3a | Schwieb Engineering Co. Van Nuys, CA | NM | | B3 B11 | B3A 27200 | B4 |
| TSO-C3a | Smiths Industries SLI Avionics Systems Corp. 4141 Eastern Avenue S.E. Grand Rapids, MI 49518-8727 | CE-C | | 4005T:140100-01-01 4005T1:140100-03-01 4005AC:142640-01-01 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|--------------------------------|--|-------------------------|------------|
| TSO-C3b *F | Aeritalia, S.p.A. Nerviano(Milan), Italy | EU | TURN- AND-SLIP INDICATOR | 20220() 27221() | 26220() 27241() | 26320() |
| TSO-C3b | Aeronetics - Withdrawn Div. of AAR Corp. 2100 Touhy Ave. Elk Grove Village, IL 60007 | | | | | |
| TSO-C3b | Aerosonic Corporation P.O. Box 4627 Clearwater, FL 33518 | CE-A | | 71002-() ANS-70 | ANS-80 | ANS-82 |
| TSO-C3b | Aerosonic Navigation Sys. 3312 Wiley Post Road Carrollton, TX 75006 | SW | | ANS-50() ANS-80() | ANS-51() ANS-82() | ANS-70() |
| TSO-C3b | Aircraft Instrument & Development, Inc. 535 S. Topeka Wichita, KS 67202 | CE-W | | RCA30-() RCA83A-() RCA56-():056-0023-08 | RCA56-() | RCAB2A-() |
| TSO-C3b | R.C. Allen Instruments, Inc. Aircraft Instruments and Development, Inc. 535 S. Topeka Wichita, KS 67202 | CE-W | | RCA 30-() RCA 80B-() RCA 83A-() | RCA 56-1 RCA 82A-() | |
| TSO-C3b | R. C. Allen, Inc. Instrument Division 678 Front Ave., N. W. Grand Rapids, MI 09550 | CE-C | | RCA-92B-1 | RCA-120 | RCA-121 |
| TSO-C3b *F | Astronautics C.A. Ltd. of Israel 8 Hayarkon Street Bnei Brak, Israel | EU | | 117800-(7) | | |
| TSO-C3b | Astronautics Corporation of America 4116 North Teutonia Ave. Milwaukee, WI 53209 | CE-C | | 117800-() | 130530 | |
| TSO-C3b | Astronautics Corporation of America 2416 Amsler St. Torrance, CA 90505 | NM | | P1-TC() | P2-TC() | TC-M() |
| TSO-C3b | Aviation Instrument Manufacturing Corp. 817 Dessau Road Austin, TX 78753 | SW | | TS200-() TS300-() | TC-110() TS400-() | TC120-() |
| TSO-C3b | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | FGS-70 | | |
| TSO-C3b | Bendix General Aviation P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | CP-103F | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|-----------|--|
| TSO-C3b | Bendix/King Air Transport Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33309 | CE-A | | EFS-10 SG-101A:3614311-1004 SG-101B:3614335-1004, -1005, -1006, -1007, -1008, -1010, -1011, -1012, -1013 |
| TSO-C3b | Collins Avionics Division Rockwell International 400 Collins Road NE Cedar Rapids, IA 52406 | CE-W | | 329B-8Y() 344-7() ADI-44V:CPN622-5139-001 ADI-55V-1 ADI-70:622-4913-001 ADI-77:622-4423-001 ADI-84():787-6173-001, 201, 202, 203, 204, 205, 206, 207, 208, 211, 212, 213, 214, 215, 216, 217, 218 ADI-85:622-4423-001 ADI-85A:622-4808-001/002/003/004 DPU-84:622-9682-001 DPU-85:622-6022-002, -012, -006 DPU-85A:622-7244-001, -002 DPU-85B:622-7245-001 DPU-85C:622-7448-001 DPU-85H DPU-85L:622-8022-001 DPU-85M:622-8444-001 DPU-85N:622-8678-002, -003 DPU-85U:622-9965-001 DPU-86A:622-7247-001, -002 DPU-86C:622-7248-003 DPU-86D:622-7249-001 DPU-86H:622-7711-002 DPU-86K:622-7713-001, -003 DPU-86L DPU-86N:622-8713-002, -003 DPU-86S:622-9285-002 DPU-86U:622-9930-001 EFD-85:622-6020-001/-002/-011/-012/ -021/-022 EFD-85A:622-6464-011, 012, -021, -022 EFD-86:622-6342-011/-012/-013/-014 EFD-86A:622-6535-011/-012/-021/-022/ -023/-024 EFIS-86D(2) KFD-85:622-6020-011, -012 KFD-85A:622-6464-001, -011, -012 KFD-86 KFD-86A:622-6020-011, -012 MPU-84:622-9684-001 MPU-85:622-6091-002, -012 MPU-85A:622-7250-001, -002 MPU-85B:622-7251-001 MPU-85C:622-7454-001 MPU-85H MPU-85L:622-8023-001 MPU-85M MPU-85N:622-8679-002, -003 MPU-85U:622-9966-001 MPU-86A:622-7253-001, -002 MPU-86C:622-7254-003 MPU-86D:622-7255-001 MPU-86H:622-7716-002 MPU-86K:622-7718-003 MPU-86L |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|-----------|--|
| | | | | MPU-86N:622-8714-002, -003 MPU-86S:622-9286-002 MPU-86U:622-9967-001 3298-8R 3298-8U 3298-8Y 3298-9L 3298-8J:772-5005-012 |
| TSO-C3b | Electric Gyro Corporation State Road 909 KM.2 P. O. Box 614 Humacao, Puerto Rico | CE-A | | 1234T100 1234T100-5() 1234T100-7() 1394T100() 1394T100-3() |
| TSO-C3b | General Design/ Janitrol Aero Div. 8600 Lankershim Blvd. Sun Valley, CA 91352 | NM | | 5400() 5560() 5550() 7125() |
| TSO-C3b | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Systems Div. P.O. Box 21111 Phoenix, AZ 85036-1111 | NM | | AD-300B AD-350 AD-600 ED2600/800:7003110-(), 7003400-() 703420-(), 7003430-(), 7004123-() GG2479AA03 GG2479AB GG2499AB04 HZ-6F:2590281-901, -907, -908, -909 2588624-902 2591411-() 4020550-() 4020917-() 4046401-() 4048501-() 4049210-() 4049214-() 4050201-() 4070749-() 7000466-() |
| TSO-C3b | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 5353 W. Bell Road Glendale, AZ 85308 | NM | | DC-800:7003420-965, -966 DC-811:7012977-761, -763, -764, -767 ED-600 ED-800 RG-204:7007453-() SG-600/800 SG-603:7003400-624, -824 SG-803:7003400-624, -824 SC-800:7004123-327, -328 |
| TSO-C3b | JET Electronics and Technology, Inc. 5353 52nd St. P.O. Box 8239 Grand Rapids, MI 49508-0239 | SW | | TS 300-() TC120-() TS200-() TS 400-() TC110-() |
| TSO-C3b | Mid-Continent Instrument Company, Inc. 7706 E. Osie Wichita, KS 67207 | CE-W | | 1234T100-() 1394T100-() 1394T100-1() 1394T100-3() |
| TSO-C3b | Smiths Industries SLI Avionic Systems Corp. 4141 Eastern Avenue S.E. Grand Rapids, MI 49518-8727 | CE-C | | 4058AC/A:149150-01-01 4058AC/B:149155-01-01 4058AC/D:149150-01-02 4058AC/E:149155-01-02 |
| TSO-C3b | S-TEC Corporation Route 3, Building 945 Walters Industrial Complex Mineral Wells, TX 76067 | SW | | 6405-() 6407-() |
| TSO-C3b *F | Tokyo Acft. Instrument Co. 1600 Izumi, Komae-shi Tokyo, Japan | NM | | TE-71-1B |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|--------------------------------|---|
| TSO-C3b | United Instruments, Inc. 3625 Comotara Avenue Wichita, KS 67210 | CE-W | | 9000:90()() 95()-() |
| TSO-C3c | Acft. Instrument & Development, Inc. R.C. Allen Inst. Div. 535 South Topeka Wichita, KS 67202 | CE-W | TURN AND SLIP .NSTRUMENT | RCA58-11 RCA59-01 |
| TSO-C3c *F | Aerodrome de Villacoublay B.P. 59, 78141 Velizy - Villacoublay, France | EU | | H140JLM() |
| TSO-C3c | Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505 | NM | | P3-TC() G300A():303880 303560 |
| TSO-C3c | Astronautics Corp. of America P.O. Box 523 Milwaukee, WI 53201-0523 | CE-C | | TC-M():303560 TC-M():303990 A/P G300A |
| TSO-C3c | Clifton Precision 5050 State Road Drexel Hill, PA 19026 | NE | | 79800000-() |
| TSO-C3c | Collins Avionics Division Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | 8ZL-871 DPU-86L DCP-1000 DU-1000:622-7484-411 MPU-86L |
| TSO-C3c | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Business & Commuter Avn. Systems Division 5353 West Bell Road Glendale, AZ 85308 | NM | | AB600:7003360-() AH600:7003360-932, 940, -941, -944 AC800, AC801: 7004545-() DC-810:7005819-747 thru -758, -763, -764, -767, -768, 765, -766, -933, -934 DC-811:7012977-747 thru -758, -763, -764, -765, -766, -767, -768, -933, -934 DC-820 ED2-605/805 MG-800:7007062-701, -702, -721, -722, 833, -834, -933, -934 MG-603:7007061-624, -824 MG-605:7011673-606 MG-605/805:7011673-605, -607, -805, -807, Mod F MG-611:7007321-512 MG-800:7007062-833, -834, -933, -934, 7007061-902 MG-800:7007062 MG-800:7007061-902 MG-803:7007061-624, -824 MG-810:7007301-() MG-815:7011675-315 MG-816:7011674-216 MG-816:7011675-216 MG-817:7011675-() MG-820:7009289-() SC-610/810:7004544-() SC-800 SG-605/705/805:7011672-605, -705, |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|--------------|--|------|--|--|
| | | | | -805, Mod F SG-605:7011672-606 SG-605/805:7011672-605, -607, -805, -807 SG-605/805:7011673-605, -607, -805, -807 SG-611:7004544-512 SG-705:7011672-705, -707 SG-806:7013788-807 SG-816:7013788-807 SG-811:7004544-712 SG-815:7011674-117, -315 SG-816:7011674-216 SG-611 SG-817 SG-820 7013788-() |
| TSO-C3c | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Division 21111 N. 19th Avenue Phoenix, AZ 86036-1111 | NM-L | | MD-80:4055900-(), 4056510-(), 4056512-(), 4056511-(), 4056513-() |
| TSO-C3c | King Radio Corporation 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | KAV-485 |
| TSO-C3d | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Business & Commuter Avn. Systems Division 5353 West Bell Road Glendale, AZ 85308 | NM-L | TURN AND SLIP INSTRUMENT | EDZ-600/800:4066300-(), 4066192-(), 4066191-(), 4066190-() |
| TSO-C3d | Honeywell, Inc. Air Transport P.O. Box 21111 Phoenix, AZ 85036-1111 | NM-L | | BAe146:4066300-(), 4066192-(), 4066191-(), 4066190-() |
| TSO-C3d | Rockwell International Collins Avionics Div. 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | EFD-84:622-9681-001, -002, -011, -012 |
| TSO-C4 *F | Aeritalia, S.p.A. Nerviano (Milan), Italy | EU | BANK AND PITCH INSTRUMENTS (INDICATING GYRO STABI- LIZED TYPE) (GYROSCOPIC HORIZON, ATTI- TUDE GYRO) | 36100() 8.044.003 8.048.003 8.048.503 8.048.008.1 8.048.008.1.01 |
| TSO-C4 | Aeronetics Div. of AAR Corporation 2100 Touhy Ave. Elk Grove, IL 60007 | | | 2137 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|--------------|--|------|-----------|---|---|--|
| TSO-C4 | Astronautics Corporation of America 907 S. First St. Milwaukee, WI 53204 | CE-C | | ARU-20/A ACA | 109090-() | |
| TSO-C4 | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | RA1S-60 | 19905() | |
| TSO-C4 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | 14168() 18773() 19912() 1903712-() | 17826() 1925756-() 1978179() | 17827() 1978121-() 1990529-() |
| TSO-C4 | Bendix South Montrose Div. South Montrose, PA 18843 | NE | | 17810-() | 18300-() | 1964771-() |
| TSO-C4 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 327B-1 327B-2W 329B-2 329B-2AW 329B-4AX 329-7A 329-8A 329-8J 329B-8R 332D-6A 344C-1 344C-1E 344C-1H 345A-2 345E-1A 1NS-60B 522-4529-001 | 327B-1W 329B-() 329B-2A 329B-4A 329B-6D 329-7F 329-8F 329B-7/8G 331A-6A 332D-9 344C-1B 344C-1F 344C-1K 345A-2A 444A-1 1NS-61B 522-4430-003 | 327B-2 329B-1 329B-2W 329B-4B 329B-7 329B-7R 329-8G 329B-8() 332D-5 332D-11 344C-1D 344C-1G 344C-1P 345E-1 916S-1 VG-204 |
| TSO-C4 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 500() 646040 | 5000() 656768 | 23-1276 661062 |
| TSO-C4 | Honeywell, Inc. Sperry Comm. Ft. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | F-3 H-3 HZ-3 2589201-() 2586137-() 1509589-903 | H-1 H-6B GH-101 2588533-() 1783867-() | H-1A HZ-1 GH-102 2594816 614937-() |
| TSO-C4 | Jet Electronics & Technology 5353 52nd St. Grand Rapids, MI 49508 | CE-C | | VG-302 | | |
| TSO-C4 | Lear Siegler, Inc. Instrument Division 4141 Eastern Ave., S.E. Grand Rapids, MI 49508 | CE-C | | 4005T 139602-01-() 4058AC/B 139001-01 7650B | 4055C 4058AC/A 149155-01 5000BU 140180-01 | 4055K 149150-01 4060P 5513B |
| TSO-C4 *F | Litton Systems Division 25 Cityview Dr. Rexdale, Ontario, Canada HGW 5A7 | NE | | LTN-51 | | |
| TSO-C4 | Minneapolis-Honeywell | CE-C | | GG17B | GG53A-1 | GG74A |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|---|------|--|--|--|--|
| | Regulator Company Aeronautical Division Minneapolis, MN 55401 | | | JC7003A JG7044A-57 | JG7044A-37 | JG7044A-55 |
| TSO-C4 | Production Research Corp. Cummings & Sander 6426 San Francisco Rd. Glendale, CA 91209 | NM | | SP-5002-2-() SP-5300-()-() SP-5300-2-() SP-7581-() | SP-5300-1-() | |
| TSO-C4b | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | BANK AND PITCH INSTRUMENTS (INDICATING GYRO STABI- LIZED TYPE) (GYROSCOPIC HORIZON, ATTI- TUDE GYRO) | 14603 Series RAIS200 RAIS300 19903() | 14606 Series 14610 Series 17830() 19905() | 14608 Series 15901 Series 17832() |
| TSO-C4b | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | RAIS200 19913() | RAIS300 19917() | 19911() |
| TSO-C4b | Bendix General Aviation Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | SG-101A | SG-101B | |
| TSO-C4b | Castleberry Instruments & Avionics, Inc. 817 Dessau Road Austin, TX 78753 | SW | | 251 | 643 | |
| TSO-C4b | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | HZ-4 | | |
| TSO-C4b | Karnish Instrument, Inc. 210 Third Ave. Lock Haven, PA 17745 | NE | | AN5736-1 | | |
| TSO-C4b | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 5525 | | |
| TSO-C4b | Smiths Industries SLI Avionic Systems Corp. 4141 Eastern Avenue S.E. Grand Rapids, MI 49518-8727 | CE-C | | 2159R:134107-01 4003F:131400-01 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|--|---|---|--|
| TSO-C4c *F | Aeritalia S.p.A. Nerviano (Milan), Italy | EU | BANK AND PITCH INSTRUMENTS (INDICATING GYRO STABI- LIZED TYPE) (GYROSCOPIC HORIZON, ATTI- TUDE GYRO) | 36101() 38300() | 37304() | 38200() |
| TSO-C4c | Aeronetics Division of AAR Brooks & Perkins Corp. 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | | RVG-801C:520-8012-() () () RVG-801D:520-8013-() () () RVG-801E:520-8014-001 RVG-801() | | |
| TSO-C4c | Aeroquip Corporation Aeroquip Aerospace Div. 300 South East Avenue Jackson, MI 49203 AND Aero Hardware & Supply, Inc. Miami Springs, FL 33166 AND Aerotech World Trade Corp. Purchase, NY 10577 AND Cooper Airmotive Van Nuys, CA 91408 AND VanDusen Aircraft Engineering, Inc. Kansas City, KS 66100 AND Boeing Comm. Airplane Co. Auburn, WA 98002 | CE-C | | AR1417-12 AR1520-12 | AR1418-12 | AR1519-12 |
| TSO-C4c | Aerosonic Navigation Systems SW 3312 Wiley Post Road Carrollton, TX 75006 | | | ANS-30() | | |
| TSO-C4c | Aircraft Instrument and Development, Inc. R.C. Allen Instruments 535 S. Topeka Wichita, KS 67202 | CE-W | | RCA268K() RCA22-() RCA26C() | RCA26AK() RCA 11A-() | RCA26CM-() RCA 15BK-() |
| TSO-C4c | Aircraft Instruments, Inc. 420 Lincoln Rd. Miami Beach, FL 33139 | CE-A | | AI-701-1A | | |
| TSO-C4c *F | Aircraft Radio AG Flughafenstrasse 22 8302 Kloten Switzerland AND Merag, Switzerland | EU | | G213() | 135140-() | |
| TSO-C4c | R. C. Allen, Inc. Instrument Division 678 Front Ave. Grand Rapids, MI 49501 | CE-C | | K3995 K4119-02 K4209-02 102-0002 RCA25C-() RCA23-() | K4119 K4209 RCA-21-() RCA26C-() RCA26BK() RCA26AK-() | K4119-01 K4209-01 25() RCA22-() RCA26CM-() RCA29BK-() |
| TSO-C4c | Astronautics C.A. Ltd. | EU | | 111303 - () | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|-----------|---|---|--|
| *F | of Israel 8 Hayarkan Street Bnei Brak, Israel | | | | | |
| TSO-C4c | Astronautics Corporation of America 4116 North Teutonia Avenue Milwaukee, WI 53209 | CE-C | | ARU-28/A ACA 102630-() 111303-() 117800-() | 102379-() 102550 112090-() 129160-() | ARU-13/A ACA 111300-() 112090(-2) 130530 |
| TSO-C4c *F | Badin Crouzet Toussus le Noble P. O. Box 17 78530 BUC France | EU | | 950:35870 960:34005 | 955:34000 38221() () | |
| TSO-C4c | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | 310 Series | RAIS100 | |
| TSO-C4c | Bendix Flight & Eng. Instr. Div. South Montrose, PA 18843 | NE | | 3571442-1001 | 3571442-1003 | |
| TSO-C4c | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | RAIS-60A 19911() 1976910-() 1978799-() 1990513-() | 17838() 19913() 1978130() 1978191-() | RAIS100 SAIS100 1978189-() 1990088-() |
| TSO-C4c | Bendix Aerospace 2150 N.W. 62nd Street P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | | ED-102E | | |
| TSO-C4c | Bendix Corporation Instr. & Life Support Div. 896 Waverly Avenue Holtsville, NY 11742 | NE | | DSA274 | DSA274-1 | DSA309 |
| TSO-C4c | Bendix/King General Avn. Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | KDA 430:065-5030-06 KSA 372XT:065-0056-70 KSM 375XT:065-0015-70 KAM 432:065-0091-04 | | |
| TSO-C4c | Bendix/King Air Transport Avionics Division 2100 N.W. 62nd St. Ft. Lauderdale, FL 33310 | CE-A | | DH-841C:2181D-CF DH-866A:4000843-() DH-841V:4000868-() DH-841VE:4000869-() 2179B:4000884-() 2181E:4000885-() EFS-10 CP-103F:8095477-() SG-101A:3614311-1004 SG-101B:3614335-1004, -1005, -1006, -1007, -1008, -1010, -1011, -1012, -1013 | | |
| TSO-C4c | BVR Aero Precision Corp. 5459 Eleventh Street P.O. Box 6336 Rockford, IL 61125-1336 | CE-C | | 277700() | | |
| TSO-C4c | Century Flt. Systems, Inc. P.O. Box 610 Mineral Wells, TX 76067 | SW | | 52077-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|--|
| TSO-C4c | Clifton Precision 5050 State Road Drexel Hill, PA 19026 | NE | | 79800000-() |
| TSO-C4c | Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52498 | CE-W | | 329B-8Y-() 332D-11T 344C-7() ADI-55V ADI-55V1 ADI-44V:CPN 622-5139-001 ADI-70:622-4912-001 ADI-77:622-4423-001 ADI-84():787-6173-001, -201, -202, -203, -204, -205, -206, -207, -208, -211, -212, -213, -214, -215, -216, -217, -218 ADI-85:622-0224-001/002/003/004 ADI-85A:622-4808-001/002/003/004 APS-841H:332D-11V:622-4424-001 ASP-1000 CWC-65 DCP-1000 DPU-84:622-9682-001 DPU-85:622-6022-002, -012, -006 DPU-85A:622-7244-001, -002 DPU-85B:622-7245-001 DPU-85C:622-7448-001 DPU-85H DPU-85L:622-8022-001 DPU-85M DPU-85N:622-8678-002, -003 DPU-85U:622-9965-001 DPU-86A:622-7247-001, -002 DPU-86C:622-7248-003 DPU-86D:622-7249-001 DPU-86H:622-7711-002 DPU-86K:622-7713-003 DPU-86L DPU-86N:622-8713-002, -003 DPU-86S:622-9285-002 DPU-86U:622-9930-001 DU-1000:622-7484-411 EFD-84:622-9681-001, -002, -011, -012 EFD-85:622-6020-001/002/-011/-012/ -021/-022 EFD-85A:622-6464-011/-012/-021/-022 EFD-86:622-6342-011/-012/-013/-014 EFD-86A:622-6535-011/-012/-021/-022 EFD-870 EFIS-86D(2) HPU-86N KFD-85:622-6020-011, -012 KFD-85A:622-6464-001, -011, -012 KFD-86:622-6342-011, -012, -013, -014 KFD-86A:622-6535-011, -012 MPU-84:622-9684-001 MPU-85:622-6091-002, -012, -006 MPU-85A:622-7250-001, -002 MPU-85B:622-7251-001 MPU-85C:622-7454-001 MPU-85H MPU-85L:622-8023-001 MPU-85N:622-8679-002, -003 MPU-85U:622-9966-001 MPU-86C:622-7254-003 MPU-86D:622-7255-001 MPU-86A:622-7253-001, -002 MPU-86H:622-7716-002 MPU-86K:622-7713-003 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-----------|---|---|---|
| | | | | MPU-86K:622-7718-003 MPU-86L MPU-86N:622-8714-002, -003 MPU-86S:622-9286-002 MPU-86U:622-9967-001 329B-8J:772-5005-012 VGR-70():CPN 622-3618-001 | | |
| TSO-C4c | Collins General Avn. Div. Avionics Group Rockwell Int'l Corp. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | | AHC-85D:622-7386(), -001 AHC-85E:622-9336(), -001 | | |
| TSO-C4c | Collins General Avn. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32902 | CE-A | | ARC-85 AHC-85E:622-9336-(), -001 | | |
| TSO-C4c | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 329B-8R 329B-8J INS-61 916K-1 | 329B-8Y 329B-9L FD-109H 990J-5 | 329B-8U INS-60 FD-112A AP106/107 |
| TSO-C4c | Delco Electronics Div. General Motors Corp. 7929 S. Howell Milwaukee, WI 53201 | CE-C | | 7886005-() 7886580-() | | |
| TSO-C4c | Dynasciences Corp. Instrument Systems Div. 9601 Canoga Ave. Chatsworth, CA 91311 | NM | | AH-11() | AH-12() | |
| TSO-C4c | Edo-Aire Mitchell P. O. Box 610 Mineral Wells, TX 76067 | SW | | FD/AP282:52C77() FD/283:52C77() | | |
| TSO-C4c | Edo-Aire Wichita Division Sigma Tec 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 1U367-()-() 1U371-() 1U407 | | |
| TSO-C4c *F | Ferranti Limited St. Mary's Road Maston, Manchester, England | EU | | FH7A FH7C FH7E FH7F/2 FH7G/2 FH7K FH7X FH7T/3 FH7U/1 FH11E FH15A FH15E FH.30B FH.30C/2 | FH7A/1 FH7D FH7F FH7G FH7G/3 FH7L FH7T/1 FH7T/4 FH7U/3 FH14A FH15B FH15G FH.30C | FH7B FH7D/1 FH7F/1 FH7G/1 FH7J FH7N FH7T/2 FH7U FH11B FH14E FH15D FH.30A FH.30C/1 |
| TSO-C4c | FL Aerospace Corp. General Design/Janitrol Aero Div. 8600 Lankershim Blvd. Sun Valley, CA 91352 | NM | | 4300() 7205() | AH-11-() 8665-() | AH-12-() |
| TSO-C4c | Gables Engineering, Inc. | CE-A | | G7004()ADF:KDF-806ADF | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|-----------|---|
| | P.O. Box 360880 Coral Gables, FL 33114 | | | |
| TSO-C4c | General Motors Corporation Milwaukee Operations Milwaukee, WI 53201 | CE-C | | 7886604 7886605 |
| TSO-C4c | Global-Wulfsburg Systems Div. of Sundstrand Data Control, Inc. 6400 Wilkinson Dr. Prescott, AZ 86301 | NM | | NDB-2() 20110-()-() 20204-() 30050-() 30054-() 30300-()-()-() 30380-()-()-() 30360-()-()-() 30154-() 42701-() 43005-() 43010-() GNS-1000-() Ser GNS-1000:30150-02-02, 30150-03-03, 30150-03-40 |
| TSO-C4c | Guidance Technology, Inc. Santa Monica, CA 90406 | NM | | 442B 442C 462C 462D |
| TSO-C4c | Honeywell, Inc. Commercial Flight Systems 8840 Evergreen Blvd. Minneapolis, MN 55433-6040 | CE-C | | CG1151AC() CG1244AC() HG1150AC() HG1095AD() HG1095BD() HG11038A() |
| TSO-C4c | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | AD-200 AD-300() AD-3008 AD-350() AD600 ED2600/800:7003110-(), 7003400-(), 7003420-(), 7003430-(), 7004123-() GH-211(A) GH-211(B) GH-211(C) GH-14 GH-14A GH-14B GH-15:4030567-() GH-222:7000850-() H-5 HZ-4() HZ-5 HZ-6 VG-341() HZ-6F:259081-901, -907, -908, -909 MD-80:4055900-(), 4056510-(), 4056512-(), 4056511-(), 4056513-() 2588369-() 2558103-1 2558103-2 2583596-() 2583723-() 2587335-() 2588423-() 2592676-901 2594586-902 2594623-901 2594586-911 2594586-912 2594612-904 2594623-902 2594623-905 2594862-() 2594914-901 2594914-() 2586137-() 2591411-() 2593996-() 4020917-() 4020547-901 402739-() 4040749-() 4046401-() 4048501-() 4049210-() 4049214-() 4050201-() 4001808-() 4002531-() 4010657-() 4013290-() 4019286-() 4020550-() 4020936-() 7000622-() 7000788-() 7000466-() 7000836-() 7001182-() 7001931-() 7002541-() 7002542-() |
| TSO-C4c | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 W. Bell Road Glendale, AZ 85308 | CE-C | | AB600:7003360-() AB800 AC800, AC801:7004545-() AH600:7003360-932, -940, -941, -944 DC-800:7003420-965, -966 DC-810:7005819-763, -764, -765, -766, -767, -768, -933, -934 DC-811:7012977-765, -766, -767, -768, -933, -934 DC-820:7007277-() ED600 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|--|
| | | | | ED800:7003110-() EDZ-605/805 EDZ-600/800:4066300-(), 4066192-(), 4066191-(), 4066190-() CG1136AC CG1288AC() CG1136AC01 CG1137AC() CG1042AB() DG1034AC() GC1135AC() GC1227AC() GC1238AC() GH-14:4021541-691, 4021541-791 HG1050BD() HG1075AB-() HG1075A802 HG1066AE() HG1075AE() HG1076AAC() HG1050ADC() HG1095AC() MC-800:7007062-701, -702, -721, -722, -833, -834, -933, -934 MG-603:7007061-624, -824 MG-605:7011673-606 MG-605/805:7011673-605, -607, -805, -807, Mod F MG-611:7007321-512 MG-800:7007061-902 MG-800:7007062-() MG-803:7007061-624, -824 MG-805 MG-810:7007321-() MG-815:7011675-315 MG-816:7011675-216 MG-817 MG-820:7009289-() RI-820:7008703-() SC-610/810:7004544-(), 1801 SC-800:7004123-327, -328 SC-811 SG600/800:7003400-() SG-603:7003400-624, -824 SG-605/805:7011672-605, -607, -805, -807 7011673-605, -805 SG-605/705/805:7011672-605, -705, -805 Mod F SG-605:7011672-606 SG-611:7004544-512 SG-705:7011672-705, -707 SG-803:7003400-624, -824 SG-805 SG-806:7013788-807 SG-811:7004544-712 SG-815:7011674-117, -315 SG-816:7011674-216 SG-817 SG-820:7007356-() 7013788-() |
| TSO-C4c | Honeywell, Inc. Air Transport P.O. Box 2111 Phoenix, AZ 85036-1111 | NM-L | | BAe146:4066300-(), 4066192-(), 4066191-(), 4066190-() |
| TSO-C4c | Humphrey, Inc. 9212 Balboa Ave. San Diego, CA 92123 | NH | | AH08-0105-() VG24-()(())-() |
| TSO-C4c | Instruments & Flight Research, Inc. 2716 George Washington Blvd. Wichita, KS 67210 | CE-W | | IFR-85 |
| TSO-C4c | Jet Electronics & Technology, Inc. 5353 52nd St. | CE-C | | AI-804 ADI-330():501-1566-() ADI-331():501-1567-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|-----------|--|
| | P.O. Box 8239 Grand Rapids, MI 49508-0239 | | | AI-330():501-1568-() AI-340():501-1539-() AI-904() AI-804-() AI-804AB, -AC, -AD, -AE, -AF AM-101() 501-1036 5-4000 5-2030 501-1006-01 501-1000-01 501-1113-() 501-1115-() 510-1N:504-0017-932 510-21F:504-0024-906 510-32B:504-0042-903 510-31B:504-0041-902 P501-1091 RAI-302():501-1251-() RAI-303():501-1267-() RAI-303B:501-1292-() RAI-303C:501-1294-() VG-301-() VN-201 VN-201G-1 VN-202G-1 VN-205() VG-204() VG-302 VG-204B VG-204D VG-206() VG-206A 100 Ser. 251 Ser. 300 Ser. 305 Ser. 500 Ser. 500E-2 Ser. 505 Ser. 510 Ser. 520 Ser. 700 Ser. 900 Ser. 540-() |
| TSO-C4c | King Radio Corporation 400 N. Rogers Road Olathe, KS 66061 | CE-W | | KI 256:PN 060-0017-00,060-0017-01 KG 258:PN 060-0020-01 thru -06 KVG 350:PN 060-0026-() KDA 430:065-5030-001/-01/-02/-03/-04 KAM 432:065-0091-00 |
| TSO-C4c | Lear Jet Industries, Inc. 3975 Lake Michigan Dr., N.W. Grand Rapids, MI 49504 | CE-C | | AI-804 |
| TSO-C4c *F | Litef GmbH Lorracher Strasse 18 Postfach 774, D-7800 Freiburg, Germany | EU | | AHRU:121319-0 AHRU:121319-1 LCR-88:121319-10/-110 |
| TSO-C4c | Litton Aero Products Airworthiness Division 6101 Condor Drive Moorpark, CA 93021-2699 | NM | | LTN-51-() LTN-51-100 LTN-58 LTN-72-() LTN-72 INS LTN-72R LTN-90 LTN-90-100:461800-02-122 461800-03-122 LTN-91 LTN-92:461800-02-08-116 463000-10 463001-02-04 463001-04-09 463001-05-04 458900-06-01 LTN-104-() LRN-76 LTR-81-01 461320-01-02 461985-03 461995-02 43600-01-01,-02,-02 460800-01-02,-03,-22-20, -02-04-120, -02-08-116, -30,-32, 461800-02-04-120 461320-01-02 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|-----------|--|
| | | | | 463001-02-02 AHRU:460800-03-04 |
| TSO-C4c *F | Litton Sys. (Canada) Ltd. 25 Cityview Drive Rexdale, Ontario Canada M6W 5A7 | NE | | LTN-51-100 LTN-51INS(ERIM) LTN-72:452520-73, 460502-21 LTN-72MRS LTN-72R LTN-72RL:460502-17, -18, -19, -20 LTN-76 LTN-90:461650-() LTN-90-100:461370-01 LTN-91:461870-03 LTN-92 |
| TSO-C4c *F | Microtecnica Torino, Italy | EU | | AC-4 C112333-() C115553-() |
| TSO-C4c | Poly Scientific Div. of Litton Industries 111 N. Main St. Blacksburg, VA 24060 | NE | | LTN-51:663550-() |
| TSO-C4c | Production Research Corp. Cummings & Sander 6426 San Francisco Rd. Glendale, CA 91209 | NM | | SP-7700-() SP7701-() SP-7702-() SP-7710-() |
| TSO-C4c *F | S.F.E.N.A. Societe Francaise d'Equip pour la Navigation Arienne Aerodrome de Villacoublay B.P. 59 78140 Velizy-Villacoublay France | EU | | 644 644LH 645 645LH 703()() 705()() 705-1() 705-7() 705-13() 705-15() 707AF 803()() 820()() 900 903()() 904()() 911()() 916()() 923()() 926()() 42-86()() 42-86 V12 ADI 48.60()() H138()() H140()()() H140JLM() H200()()() H221()()() H301()()() H321()()() H341()()() |
| TSO-C4c *F | S.F.I.M. Societe de Fabrication d'Instruments de Mesure (s.a.) 13, Avenue M. Ramolfe-Garnier 91301 Massy, France | EU | | GV75-2 75-52 GV 76() BSM Type 60 54-711 |
| TSO-C4c | Singer-Kearfott Div. 1150 McBride Ave. Little Falls, NJ 07424 | NE | | GAMMA I |
| TSO-C4c | Smiths Industries SLI Avionic Systems Corp. 4141 Eastern Ave., S.E. Grand Rapids, MI 49518-8727 | CE-C | | 1601E 138829-01 3335B 1413000-01 139800-01 4003DD 142640-01 137000-01 149150-01 149155-01 149190-01 7003E 124623-01 6000 1080Y:134338-02-01 2809C:156561-01-01 3853A1:159793-02-01 3853A2:159793-03-01 3853A3:159793-04-01 3853A4:159793-05-01 4003T:139800-01-01 4003AD:146051-01-01 4005H:118930-01 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|--|---|
| | | | | 4005T:140100-01-01 4005T1:140100-03-01 4005AC:142640-01-01 4012D:137000-01 4055K:139602-01 4058AC/A:149150-01-01 4058AC/B:149155-01-01 4058AC/D:149150-01-02 4058AC/E:149155-01-02 4060P:139001-01 4145F:149190-01-02 5513B:133189-01-01 5513H:143200-01-01 5513K:143310-01-01 6504T:156558-01-01 6504T1:156558-02-01 6504Y:159790-01-01 6504Y1:159790-02-01 6504Y2:159790-03-01 7000E:124623-01-() 7650E:140180-01-01 7650C:140540-01-01 7901A:156555-01-02 7901C:159787-01-01 7901F:162953-01-01 9000C-():145974-01-03 9000C-():145974-01-04 |
| TSO-C4c *F | Societe D'Application Generales d'Electricite et de Meconique (SAGEM) 6 Avenue d'Iena Paris, France | EU | | 649-915-09() |
| TSO-C4c | Southwestern Industries, Inc. 5880 Centinela Ave. Los Angeles, CA 90045 | NM | | AO-10-() AO-10-2A() |
| TSO-C4c *F | Tokyo Aircraft Instrument Co., Ltd. 1600 Izumi, Komae-shi Tokyo, Japan | NM | | HE-3:HE-31-1B, HE-31-1C |
| TSO-C4c | Vandling Corp. 16270 Raymer Van Nuys, CA 91406 | NM | | NDB-2:20110-2-3 |
| TSO-C4c | Vesto Instrument Corp. Houston, TX 77002 | SW | | EV-70 EV-71 |
| TSO-C5 *F | Aeritalia, S.p.A. Nerviano (Milan), Italy | EU | DIRECTION INSTRUMENT, NONMAGNETIC, GYRO STABI- LIZED TYPE (DIRECTIONAL GYRO) | 31100 8.043.003 8.043.008 8.043.008.1 8.043.008.1.01 |
| TSO-C5 | R. C. Allen, Inc. Instrument Division 67B Front Avenue, N. W. Grand Rapids, MI 49501 | CE-C | | RCA-11 RCA-11() J414-01 J414-02 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|--------------|---|------|--|------------------------------------|-------------------|-------------------|
| TSO-C5 | Collins Radfo Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | INS-60B 345E-1A | INS-61B 916S-1 | 345E-1 |
| TSO-C5 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 400() ANS735-1 | 4000() 646050 | 23-1150 649742 |
| TSO-C5 | Honeywell, Inc. Sperry Comm. Flt. Sys. Inc. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | G-1 | G-1A | |
| TSO-C5 | Instrument Flight Res. Corp. 2716 George Washington Blvd. Wichita, KS 67210 | CE-W | | SC-100 | | |
| TSO-C5 | Lear Siegler, Inc. Instrument Division 4141 Eastern Ave., S. E. Grand Rapids, MI 49508 | CE-C | | 2152L:140070-01 4060P:139001-01 | | |
| TSO-C5 *F | Litton Systems Limited 25 Cityview Dr. Rexdale, Ontario, Canada H6W 5A7 | NE | | LTN-51() | | |
| TSO-C5 | Production Research Corp. Cummings & Sander 6426 San Francisco Rd. Glendale, CA 91209 | NM | | SP-7535A-() SP-7577-() | SP-7575-() | SP-7576-() |
| TSO-C5b | Aerosonic Navigation Systems 3312 Wiley Post Road Carrollton, TX 75006 | SW | DIRECTION INSTRUMENT, NONMAGNETIC, GYRO STABI- LIZED TYPE (DIRECTIONAL GYRO) | ANS-20() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|--|---|---|---|
| TSO-C5b | R. C. Allen, Inc. Instrument Division 678 Front Ave., N. W. Grand Rapids, MI 49501 | CE-C | | J3895 J4184-01 RCA-11D-() | J4114-01 J4184-02 RCA-11A | J4114-02 RCA-15 |
| TSO-C5b | Karnish Instrument Inc. 210 Third Avenue Lock Haven, PA 17745 | NE | | AN5737-1 | | |
| TSO-C5b *F | Smith Industries, Ltd. Aviation Division Bishops Cleeve Cheltenham, Gloucestershire England | EU | | 2DG | | |
| TSO-C5c *F | Aeritalia, S.p.A. Nerviano (Milan) Italy | EU | DIRECTION INSTRUMENT, NONMAGNETIC, GYRO STABI- LIZED TYPE (DIRECTIONAL GYRO) | 31101() | 32200() | 32300() |
| TSO-C5c *F | Aircraft Radio AG Flughafenstrasse 22 8302 Kloten Switzerland AND Merag, Switzerland | EU | | G-212A, 134770-() | | |
| TSO-C5c | R.C. Allen Instruments, Inc. Aircraft Instrument and Development, Inc. 535 S. Topeka Wichita, KS 67202 | CE-W | | RCA15BK-() RCA 11A-() RCA11D-() RCA11D-5:103-0012-01 RCA11A-1 RCA11A-12 RCA11A-15 RCA11A-21 | RCA15AK-() RCA11D-4:103-0011-01 RCA11A-9 RCA11A-13 RCA11A-16 103-0030 | RCA15CM-() RCA11A-11 RCA11A-14 RCA11A-17 J8000 |
| TSO-C5c | Allied-Signal Aerospace Co. Guidance Systems Division Counter Operations 375 N. Lake St. Boyne City, MI 49712 | CE-C | | 18-1686-() | | |
| TSO-C5c | R.C. Allen 678 Front Ave. NW Grand Rapids, MI 49501 | CE-C | | RCA15CM-() | RCA158K-() | |
| TSO-C5c *F | Badin-Crouzet. Aeroport de Toussus-le-Noble, P. O. Box 17 78530 Buc, France | EU | | 33 430 830 | 33 440 831 | |
| TSO-C5c | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | INS-60 990J-5 | INS-61 | 916K-1 |
| TSO-C5c | Delco Electronics Div. of Gen. Motors Corp. 7929 S. Howell Milwaukee, WI 53201 | CE-C | | 7886005-() | 7886580-() | |
| TSO-C5c | EDO-AIRE Wichita Division | CE-W | | 4000C-2:1U262-008-30 4000C-3:1U262-009-31 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|-----------|---|
| | 1326 South Walnut Street Wichita, KS 67213 | | | 1U445-()-() 1U445-002-2 |
| TSO-C5c | Edo-Aire Mitchell P. O. Box 610 Mineral Wells, TX 76067 | SW | | 52D136-() |
| TSO-C5c | FL Aerospace Corp. General Design/Janitrol Aero Division 8600 Lankershim Blvd. Sun Valley, CA 91352 | NM | | 4305() |
| TSO-C5c | General Motors Corporation Milwaukee Operations Milwaukee, WI 53201 | CE-C | | 7886604 7886605 |
| TSO-C5c | Global-Wulfsberg Systems Div. of Sundstrand Data Control, Inc. 6400 Wilkinson Dr. Prescott, AZ 86301 | NM | | NDB-2() 20204-() 30054-() 30154-() 20110-(x) 30050-()-() 30150-()-() 30300-()-()-() 30190-() 30360-()-()-() 30380-()-()-() 43010-() 43005-() 42701-() GNS-1000-() Ser GNS-1000:30150-02-02, 30150-03-03, 30150-03-40 |
| TSO-C5c | Guidance Technology, Inc. Santa Monica, CA 90406 | NM | | 325A |
| TSO-C5c | Honeywell, Inc. Sperry Corporation Comm. Flt. Sys. Div. 5353 W. Bell Road Glendale, AZ 85308 | NM | | PC-800 |
| TSO-C5c | Honeywell, Inc. Commercial Flight Systems 8840 Evergreen Blvd. Minneapolis, MN 55433-6040 | CE-C | | CG1244AC() HG11038A() |
| TSO-C5c | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Sys. Div. P.O. Box 21111 Phoenix, AZ 85036-1111 | NM | | CG1136AC01 CG1137AC() CG1042AB() CG1136AC() CG1227AC() CG1238AC() DG1034AC() DG-411:2585706 HG1050BD() HG1075AB-() HG1076AA() RH-102:2587688 YG1761():DG1034AC() 4040749-() 4046401-() 4048501-() 4049210-() 4049214-() 4050201-() |
| TSO-C5c | Humphrey, Inc. 9212 Balboa Ave. San Diego, CA 92123 | NM | | DG04-01-09-1 GR06-0102-1 GR06-0102-() DG04-0109-1 PS06-()-()-()-() DG04-()-()-()-() |
| TSO-C5c | Instruments & Flight Research, Inc. 2716 George Washington Blvd. Wichita, KS 67210 | CE-W | | IFR-80 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|-----------|--|
| TSO-C5c | JET Electronics and Technology, Inc. 5353 52nd St. P.O. Box 8239 Grand Rapids, MI 49508-0239 | CE | | 200-() Ser. 210-() Ser. 213 220-() Ser. 230-() Ser. 283 800-() 2180() 220Del-() |
| TSO-C5c | King Radio Corporation 400 W. Rogers Road Olathe, KS 66061 | CE-W | | KG102A/KSG105:060-0016-00 KG107:060-0022-() |
| TSO-C5c | Litton Aero Products Airworthiness Division 6101 Condor Drive Moorpark, CA 93021-2699 | NM | | LRN-76 LTN-51-() LTN-51-100 LTN-58 LTN-72-() LTN-72 INS LTN-72R LTN-90 LTN-104-() LTR-81-01 LTN-90-100 LTN-91 LTN-92 |
| TSO-C5c *F | Litton Systems (Canada) Ltd. NE 25 Cityview Drive Rexdale, Ontario Canada M6W 5A7 | | | LTN-51-100 LTN-51INS(ERIM) LTN-72:452520-73, 460502-21 LTN-72MRS LTN-72R LTN-72RL:460502-17, -18, -19, -20 LTN-76 LTN-90:461650-() LTN-90-100 LTN-91:461870-03 LTN-92 |
| TSO-C5c | Marco Avionics Corp. Commerce Drive Fort Washington, PA 19034 | NE | | HSI 100() |
| TSO-C5c | Poly Scientific Div. Litton Industries 111 N. Main St. Blacksburg, VA 24060 | NE | | LTN-51:663550-() |
| TSO-C5c | Production Research Corp. Cummings & Sander 6426 San Francisco Rd. Glendale, CA 91209 | NM | | SP-7600-() SP-7601-() SP-7602-() SP-7610-() |
| TSO-C5c | Singer-Kearfott Div. 1150 McBride Ave. Little Falls, NJ 07424 | NE | | GAMMA1 |
| TSO-C5c | Smiths Industries SLI Avionic Systems Corp. 4141 Eastern Ave., S. E. Grand Rapids, MI 49518-8727 | CE-C | | 33358:1413000-01 6000 6502E:140200-01 2152L:140070-01-01 4060P:139001-01 3809C:156561-01-01 3853A1:159793-02-01 3853A2:159793-03-01 3853A3:159793-04-01 3853A4:159793-05-01 6504T:156558-01-01 6504T1:156558-02-01 6504Y:159790-01-01 6504Y1:159790-02-01 6504Y2:159790-03-01 7901A:156555-01-02 7901C:159787-01-01 7901F:162953-01-01 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|---|--|
| TSO-C5c *F | Societe d' Application Generales d' Electricite et de Mecanique (SAGEM) 6 Avenue d'Iena Paris, France | EU | | 649-915-09() 759 452-03() |
| TSO-C5c | Vandling Corporation 16270 Raymer Street Van Nuys, CA 91406 | NM | | NDB-2 |
| TSO-C5d | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 5353 W. Bell Road Glendale, AZ 85308 | CE-C | DIRECTION INSTRUMENT, NON-MAGNETIC, (GYROSCOPI- CALLY STABILIZED) | AB600:7003360() AC800, AC801:7004545() AH600:7003360-932, -940, -941, -944 CG1151AC() CG1227AC() CG1238AC() CG1288AC() HG1066AE() HG1075AE() HG1095AC() HG1076AA() HG1075AB02 HG1150AC() HG1095BD() HG1095AD() |
| TSO-C5d | JET Electronics and Technology, Inc. 5353 52nd St. P.O. Box 8239 Grand Rapids, MI 49508-0239 | CE | | 205-() 210-() |
| TSO-C5d | Litton Aero Products 6101 Condor Drive Moorpark, CA 93021-2699 | WP | | AHRU:460800-03-04 LTN-72 LTN-92:461800-02-08-116 463000-10 463001-02-04 463001-04-09 463001-05-04 458900-06-01 LTN-90-100:461800-02-122 461800-03-122 458900-03,-04 452100-02-03 461320-01-02 460800-01-02,-02,-03,-04 -20,-22,-30,-32 461800-02-04-120 461995-02 461985-03 463600-01-01 |
| TSO-C5e *F | Litef GmbH Lorracher Strasse 18 Postfach 774 D-7800 Freiburg, Germany | EU | DIRECTION INSTRUMENT, NON-MAGNETIC (GYROSCOPICALLY STABILIZED) | AHRU:121319-0 AHRU:121319-1 LCR-88:121319-10/-110 |
| TSO-C5e | Universal Navigation Corp. 3260 East Lerdo Road Tucson, AZ 85706 | | | 1500-01-() 1500-02-() |
| TSO-C6 | Bendix Radio Division Baltimore, MD 21233 | NE | DIRECTION INSTRUMENT, MAGNETIC (GYRO-STABI- LIZED TYPE) | M-72A M-72B M-89A RMI |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|--|------|-----------|---|--|---|
| TSO-C6 | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | CB-60A 2290 17257() 18838() | CB-60B 12078 17265 36001 | CB-70 16500 Ser. 18773 36101 |
| TSO-C6 | Bendix Navigation & Control Div. South Montrose, PA 18843 | NE | | 36126 36155 36160 1903976 | 36148 36158 36162 1925179 | 36154 36159 1903585 1925813 |
| TSO-C6 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | CB-60A CB-70 1990658-() | 18942() 1964391-() 3756002-() | 18851 1903711-() 3853021-() |
| TSO-C6 | BVR, Inc. 5459 Eleventh Street Rockford, IL 61125 | CE-C | | 276470-() | | |
| TSO-C6 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 327C-2 331A Ser. 331A-6K1 331A-7A 331A-8K 332E-5 337A-2W 344C-1B 344C-1F 344C-1G 890J-2 MC-102 522-0925-005 777-1258-001 | 328A-2A 331A-3C 331A-6P 331A-8G 331C-() 336B-1 341C-1 344C-1D 344C-1H 344C-1P 344C-1P FD-105C VIP 522-1771-014 | 329B-() 331A-3G 331A-7 331A-8H 332E-4 337A-2 344C-1 344C-1E 344C-1K 345C-2A MC-101 522-3875-001 |
| TSO-C6 | Edo-Aire Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 1166() | | |
| TSO-C6 | Edo-Aire Mitchell P. O. Box 610 Mineral Wells, TX 76067 | SW | | MSD285() | | |
| TSO-C6 | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | A-2 C-6() C-11A C-6347 1783993 | A-2T C-9 C-11B C-6347-ASN 4002963-() | C-4A C-11 C-12 RH-103() |
| TSO-C6 | Instrument Flight Res. Corp. 2716 Geo. Washington Blvd. Wichita, KS 67210 | CE-W | | SG-100 SG-200T | SG-500 | SG-500P |
| TSO-C6 | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KMT-110 | KSG-100 | |
| TSO-C6 | Lear Siegler, Inc. Instrument Division 4141 Eastern Ave., S.E. Grand Rapids, MI 49508 | CE-C | | 2152L 5005G | 4060P 5513B | 5005E 7650E |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|--------------|--|------|---|---|--|---|
| TSO-C6 *F | Litton Systems Limited 25 Cityview Dr. Rexdale, Ontario, Canada M6W 5A7 | NE | | LTN-51 LTN-91 | LTN-90-100 | |
| TSO-C6 | Singer-General Precision, Inc. Kearfott Division 1150 McBride Ave. Little Falls, NJ 07424 | NE | | N-1 | S-100-2D | |
| TSO-C6a | Allied-Signal Aerospace Co. Guidance Systems Div. 375 N. Lake Street Boyne City, MI 49712 | CE-C | DIRECTION INSTRUMENT, MAGNETIC (GYRO- STABILIZED TYPE) | 18-1732-1 | | |
| TSO-C6b | Aircraft Radio Corporation Boonton, NJ 07005 (Transferred to Sperry Flight Systems Glendale, AZ | NM-L | DIRECTION INSTRUMENT, MAGNETIC (GYRO-STABI- LIZED TYPE) | | | |
| TSO-C6b | Ametek Aerospace Products, Inc. 50 Fordham Rd. Wilmington, MA 01887 | NE | | SC-1 8KH26 | 8KJ3 8DJ90 | 8KD6 |
| TSO-C6b | Bendix Radio Division Baltimore, MD 21233 | NE | | M-72D | MN-72() | |
| TSO-C6b | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | 5920() 7233 15431-2-A 26500 Ser. 36106 Ser. 36135 | 7226 Ser. 7244 15777() 36102 Ser. 36109 Ser. 36140-1AF-25-A1 | 7227 Ser. 7234-3A-12-A1 16527 Ser. 36105 Ser. 36126 |
| TSO-C6b | Bendix Navigation and Control Div. South Montrose, PA 18843 | NE | | 36105 36140 | 36135 | 36137 |
| TSO-C6b | Collins Avionics Division Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | 341C-1 | | |
| TSO-C6b | Global-Wulfsberg Systems Div. of Sundstrand Data Central, Inc. 6400 Wilkinson Dr. Prescott, AZ 86301 | NM-L | | GNS-1000:30150-02-02, 30150-03-03, 30150-03-40 | | |
| TSO-C6b | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NH | | 5525 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | | | |
|---------------|---|------|---|---|--|--|---|-----------------------------|
| TSO-C6c | Aeronetics Div. of AAR Brooks and Perkins Corp. 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | DIRECTION INSTRUMENT, MAGNETIC (GYRO-STABI- LIZED TYPE) | 2105 2109-() 4107() 4127() 4147() 520-0250-000 520-6137-() BDI-303A BDI-303B:520-3031-XXX DCU-201A:520-2010-() DCU-201B:520-2011-001 FXU-803A:520-8030-() FXU-803B:520-8140-() FXU-803B:520-8140-() HSI-4X1X MCU-804A:520-8040-() 421B 431A 431D 3115LB-X-X-X 3125LB-X-X-X 3137LB()() 3337LB-X-X-X 520-2010-() 520-301()-() 520-3030-XXX 520-8100() 520-7100-() 520-8030-() 520-8131() 520-9100() 520-9150() 520-8130-() H3137LB-()-()-() HSI-4()1() | 2107-() 2137() 4117() 4135() | 2108-() 4105() 4125() 4137() | 421A 421D 431C RMI-301() 3127LBX-X-X 520-2351() 3117LB-()-()-() 520-3031-XXX 520-913() 520-7137-() 520-8040-() 520-8140-() 520 9110() 520-301()-() | H3137LB-X-X-X 3117LB2-1A |
| TSO-C6c | Aircraft Radio Corporation Boonton, NJ 07005 (Transferred to Sperry Flight Systems Glendale, AZ | NM-L | | G-530B | | | | |
| TSO-C6c | Allied-Signal Aerospace Co. Guidance Systems Division Courier Operations 375 N. Lake St. Boyce City, MI 49712 | CE-C | | 18-1732() | 18-1874-() | | | |
| TSO-C6c *F | Astronautics C.A. Ltd. of Israel 8 Hayarken Street Bnei Brak, Israel | EU | | 111302-() | | | | |
| TSO-C6c | Astronautics Corporation of America 907 S. First St. P.O. Box 523 Milwaukee, WI 53201-0523 | CE-C | | AQU-4A 1D663A/U 111300-() 111302-4 138740-7 | 104500 111302-() 129222-() 133640 | 1D663/U 120100 129400() 138740-1 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|-----------|---|
| TSO-C6c | Aviation Instrument Manufacturing Corporation 817 Dessau Road Austin, TX 78753 | SW | | 400-() Ser. G20-() Ser. 254-() Ser. 289-() Ser. 293-() Ser. 297-() Ser. 299-() Ser. 400-() Ser. 403-() Ser. 424-() Ser. 610-() Ser. RMI810-() Ser. 254-13-() Ser. 254-14-() Ser. 800-() Ser. RMI 810 Ser |
| TSO-C6c | Barfield Instrument Corp. 4101 N.W. 29th Street Miami, FL 33142 | CE-A | | 2280F-() 2276F-() |
| TSO-C6c | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | CB-60 CQ-83 RMA-21() 7233 7237 7232-2A-14-82 7241 7244 17248() 18841() 18851() 18942 36147() 36148() 36155() 36158() 36159() 36160() 36204() 1903585-() 1903711-() 1903976-() 1925179-() 1925813-() 1990658-() |
| TSO-C6c | Bendix Navigation and Control Div. Teterboro, NJ 07608 | NE | | 7241() 17265() 18773 Q27A1 2290-() 1925757-() 1964392-() 3809139-() 3809142-() |
| TSO-C6c | Bendix Radio Division Baltimore, MD 21233 | NE | | RMA-21() RMI MN-72() |
| TSO-C6c | Bendix Aerospace 2150 N.W. 62nd St. P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | | ED-102E |
| TSO-C6c | Bendix, Flight Systems Div. Teterboro, NJ 07608 | NE | | 1925711-() |
| TSO-C6c | Bendix/King General Avn. Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | KSG 105:060-0013-02 K1525A:066-3046-10 K1525A:066-3046-11 KCC 462:65-00148-0100, -0200, -0300, -0400, -0500, -0600, -0700, -0800, -0900 KDA 430:065-5030-06 KAM 432:065-0091-4 |
| TSO-C6c | Bendix/King Air Transport Avionics Division 2100 N.W. 62nd St. Ft. Lauderdale, FL 33310 | CE-A | | RMA-21() IN-831() SG-832B() MN-72() IN-863A SG-832C HSD-880:IN-881(), DG-882(), SC-883() AD-884():4001315-() CP-103F EFS-10 SG-101A:3614311-1004 SG-101B:3614335-1004, -1005, -1006, -1007, -1008, -1010, -1011, -1012, -1013 |
| TSO-C6c | H. O. Boehme, Inc. 45 S. Service Rd. Plainview, NY 11803 | NE | | AN/ASN-43 |
| TSO-C6c | BVR Aero Precision Corp. 5459 Eleventh St. P.O. Box 6336 Rockford, IL 61125-1336 | CE-C | | 275540-() |
| TSO-C6c | Century Flight Systems, Inc. | SW | | 1C714-() 1C722-() 10755-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|---|
| | P.O. Box 610 Mineral Wells, TX 76067 | | | 52D136-() 52D137-() |
| TSO-C6c | Clifton Division Litton Systems, Inc. 5100 State Rd. Drexel Hill, PA 19018 | NE | | 9803-06() () 9813-07() () 9813-13() () 77900000-() |
| TSO-C6c | Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | 161N-3:622-4774-001 331A-8A(S/N 5000 and up):772-5025-() 331A-8K(S/N 5000 and up):777-1397-() 332C-10() 331A-10() 331A-8L:777-1825-01 614E-55:622-4775-001 614E-55A (HSVD-800):622-6866-001 ASP-1000 ALS-1000 CCU-65:622-6135-001 thru 004 CHP-85A DCP-85 DCP-85A:622-6320-001/-002 DCP-85B:622-6021-001/002 DCP-85E:622-6794-001/-002 DCP-85F:622-8148-001/-002 DCP-1000:622-7485-301 DGS-65:622-6136-001 DPU-84:622-9682-001 DPU-85:622-6022-002 DPU-85A:622-7244-001, -002 DPU-85B DPU-85C:622-7448-001 DPU-85L:622-8022-001 DPU-85M DPU-85N:622-8678-002, -003 DPU-85U:622-9965-001 DPU-86A:622-7247-001, -002 DPU-86C:622-7248-003 DPU-86D:622-7249-001 DPU-86H:622-7711-002 DPU-86K:622-7713-001, -003 DPU-86N:622-8713-002, -003 DPU-86L DPU-86S:622-9285-002 DPU-86U:622-9930-001 DSP-84:622-9683-001, -002 DSP-85:622-6795-001/-002/-003/-004 DSP-85A:622-7728-001-002-003-004 DSP-85B:622-9116-001, 005, -006, -012, -013, -014, -015, -016 DSP-85C:622-9117-005, -006, -011, -012, -013, -014, -015, -016 DSP-85D DSP-85E DU-1000:622-7484-301 622-7484-411 EFD-74:622-6197-001/002 EFD-85:622-6020-001/002 EFD-85A:622-6464-011/-012/-021/-022 EFD-86:622-6342-011/-012/-013/-014/ -021/-022 EFD-86A:622-6535-011/-021/-022/-023/-024 EFD-87 EFIS-86D(2) FDU-70:622-5812-001 FDU-70A:622-8154-001-002 HCP-74:622-6200-001/002/003/004 HCP-74A:622-6199-001 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---------------------------------------|
| | | | | HCP-85:622-4177-001/002/003/004 |
| | | | | HCP-86:622-4178-001/002/003/004 |
| | | | | HFD-85A |
| | | | | HPU-74:622-6198-001 |
| | | | | HPU-74A:622-6199-001 |
| | | | | HPU-86H:622-7716-002 |
| | | | | HPU-86K:622-7718-001 |
| | | | | HSI-70/A:CPN622-4913-001/622-4914-001 |
| | | | | HSI-84():622-4151-001 |
| | | | | HSI-85:622-4176-001/002/003/004 |
| | | | | KFD-85:622-6020-011, -012 |
| | | | | KFD-85A:622-6461-011, -012 |
| | | | | 622-6464-001, -011, -012 |
| | | | | KFD-86:622-6342-011, -012, -013, -014 |
| | | | | KFD-86A:622-6535-011, -012 |
| | | | | MEM-871 |
| | | | | MFD-80:622-4774-001 |
| | | | | MFD-85:622-6090-001/002 |
| | | | | MFD-85A:622-7236-001/-002/-011/-012 |
| | | | | MFD-85B |
| | | | | MFD-85C:622-9849-011, 622-9849-012 |
| | | | | MPU-84:622-9684-001 |
| | | | | MPU-85:622-6091-002 |
| | | | | MPU-85A:622-7250-001, -002 |
| | | | | MPU-85B:622-7251-001 |
| | | | | MPU-85C:622-7454-001, -003 |
| | | | | MPU-85M |
| | | | | MPU-85N:622-8679-002, -003 |
| | | | | MPU-85L:622-8023-001 |
| | | | | MPU-85U:622-9966-001 |
| | | | | MPU-86A:622-7253-001, -002 |
| | | | | MPU-86D:622-7255-001 |
| | | | | MPU-86H |
| | | | | MPU-86K:622-7718-003 |
| | | | | MPU-86N:622-8714-002, -003 |
| | | | | MPU-86L |
| | | | | MPU-86S:622-9286-002 |
| | | | | MPU-86U:622-9967-001 |
| | | | | PNA-74:622-8925-001/-002 PCP-25E |
| | | | | RCP-65:622-6174-001 |
| | | | | RMI-733A:622-6084-001, -002 |
| | | | | RMI-36:622-2506-014 |
| | | | | RCP-74A |
| | | | | RDM1-743:622-5001-003 |
| | | | | RDM1-743A:622-5818-001 |
| | | | | SDD-640:622-7207-002 |
| | | | | SDU-640A:622-8336-010, -011, -012 |
| | | | | TVI-920D:622-9728-001, -002, -011, |
| | | | | -012, -021, -022, -031, -032, -201, |
| | | | | -202, -211, -212, -221, -222, -231, |
| | | | | -232 |
| | | | | WXP-85A WXP-85B |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|-----------|--|
| TSO-C6c | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | | AHC-85E:622-9336-(), 001 AHC-85D:622-7386(), 001 HCP-85:622-4177-001/002/003/004 328A5:777-1556-001/002 328-A3G:522-2644-00 REU-84:622-4152-001 REU-84A:622-4569-001 |
| TSO-C6c | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 323A-2G 323A-3G-1 323A-2G-1 328A-5 331A-8D 331A-9G 332C-10 FH-109H FD-112A 332E-5 |
| TSO-C6c | Collins Radio Group Rockwell Int'l 400 Collins Rd. NE Cedar Rapids, IA 52406 | CE-W | | EFD-74:1/622-6197-001/-002 BD1-36:CPN622-3702-001 thru -014 HS1-45:CPN622-4298-001 HPU-74B:622-9221-001 HCP-74B:622-9222-001/-002/-003/-004 RMI-30:CPN622-4938-001/002/003/004/ 005/006 RMI-36() |
| TSO-C6c | Delco Electronics General Motors Corp. Milwaukee Operations Milwaukee, WI 53201 | CE-C | | 7886005-() |
| TSO-C6c | Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213 | CE-W | | 1U295E:1U295-()-() |
| TSO-C6c | Edo-Aire Mitchell P. O. Box 610 Mineral Wells, TX 76067 | SW | | FD/AP282 1D494() 52C78() 1B537() 52B110() FD283() 1C714-() 52D137-() 1C722-() DG/NSD360: 52D137-1332, -1333, -2331, -2334 1D755-() |
| TSO-C6c *F | Electronique Aerospatiale P. O. Box 4 93350 LeBourget Aeroport Paris, France (Formerly Europe Air Service) | EU | | IVA551D IVA552D IVA553D |
| TSO-C6c | General Electric Co. Aerospace Instrument Program 50 Fordham Rd. Wilmington, MA 01887 | NE | | MA-1 8KD3 8KE5 8KE7 8KJ4 |
| TSO-C6c | General Motors Corp. Milwaukee Operations Milwaukee, WI | CE-C | | 7886604 7886605 7888701 |
| TSO-C6c | Global-Wulfsberg Systems 6400 Wilkinson Dr. Prescott, AZ 86301 | NM | | NDB-2() GNS-1000-() Ser |
| TSO-C6c | Group Technologies Corp. 10901 Malcolm McKinley Dr. Tampa, FL 33612 | NM-L | | CS412:2593379-() |
| TSO-C6c | Honeywell, Inc. Sperry Comm. Fit. Sys. Gp. | NM-L | | CG1042AB() CG1135AC() CG1136AC() CG1137AC() CG1227AC() CG1238AC() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|----|-----------|--|
| | Avionics Facility 5353 W. Bell Road Glendale, AZ 85308 | | | CG1288AC() CG1151AC() DC-800:7003420-965, -66 DC-810:7005819-747 thru 758, -763, -764, -765, -766, -767, -768, -933, -934 DC-811:7012977-747 thru 758, -763, -764, -765, -766, -767, -768, -933, -934 DG-1034AC() ED-800 EDZ-605/805 HG-1050AD() HG1050BD() HG1066AE() HG1075AB-() HG1075AE() HG1075AE() HG1076AA() HG1150AC() HG1095BD() HG1095AD() MC-800:7007062--701, -702, -721, -722, -833, -834, -933, -934 MG-800:7007061-902 MG-603:7007061-624, -824 MG-605:7011673-606 MG-605/805:7011673-605, -607, -805, -807, Mod F MG-611:7007321-512 MG-805 MG-810 MG-815:7011675-315 MG-816:7011675-216 MG-817 MG-800 MG-803:7007061-624, -824 MG-820 SG-800:7004123-327, -328 SG-603:7003400-624, -824 SG-605:7011672-606 SG-600/800 SG-605/805:7011672-605, -607, -805, -807 7011673-605, -805 -805, Mod F SG-610/611/810 SG-611:7004544-512 SG-705:7011672-705, -707 SG-803:7003400-624, -824 SG-806:7013788-807 SG-811:7004544-(),7004544-312, -712 SG-815:7011674-117, -315 SG-815/816:7011674 SG-816:7011674-216 SG-817 SG-820 RI-820 YG1761() AB600:7003360() AC800, AC801: 7004545() AH600:7003360-932, -940, -944 DC-820:7007277-() ED-600:7003430-() FX-600:7010133-() MG-800 MG-810:7007321-() MG-815, -816:7011675-() MG-820:7009289-() PI-600: 7010133-() RI-820:7008703-() SG-600/800 SG-605 SG-610/810: 7004544-() SG-705 SG-805 SG-815, -816:7011674 SG-820:7007356-() 7013788-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|-----------|---|
| TSO-C6c | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 86036-1111 | NM | | AN/ASN-43 C-2 C-10 C-10-2A CI-6 CI-600 DB-100:4034559-() RH-6 DG-206 DG-207-() DRC-1 PD-350 RD-1() RD-2 RD-200 RD-350() C-14 MD-80:4055900-(), 4056510-(), 4056512-(), 4056511-(), 4056513-() C12:2586333-() C14A:4019190-() RD-500() RD-600() RD-650() RD-500A:4029529-() RD-700() RD-800() RH-300() RH-350() RH-551() ED-800:7003110-() RH-102() 1775277-() 620783-() HG1095AC() 1783867-() 2558103-1 2558103-2 2575334 2575570 2575513 2575570-() 2575592 2585703 2586047-() 2586257-() 2587193() 2587832 2587833-() 2588423-() 2587451-() 2588302-() 2588302-7 2588533-() 2589201-() 2589419-() 2589420-() 2591200-901 2591201-() 2591202-() 2591438-() 2592789-902 2592799-() 2592801-() 2592838-901 2592848 2592934-1 2594586-902 2592920-() 2593379-() 2593996-() 2594586-911 2594586-912 2594816 2594862-() 2594625-() 2594911-901 4014879-() 4002342-() 4004256-() 4002963-() 4020577-() 4020936-() 4032211-() 4013584-() 4032739-() 4040749-() 4040750-() 4046401-() 4048501-() 4049210-() 4049214-() 4050201-() 7002493-() |
| TSO-C6c | Honeywell, Inc. Commercial Flight Systems 8840 Evergreen Blvd. Minneapolis, MN 55433-6040 | CE-C | | CG1244AC() CG1151AC() HG1095BD() HG1095AD() HG1103BA() HG1150AC() |
| TSO-C6c | Humphrey, Inc. 9212 Balboa Ave. San Diego, CA 92123 | NM | | DG11-() () () () () () FD01-() () () () () () FD01-0201-2 |
| TSO-C6c | Instrument & Flight Research, Inc. 2716 George Washington Blvd. Wichita, KS 67210 | CE-W | | SG-600 RSG-700 7131000-3 731000-3 IFR-82B IFR-83P |
| TSO-C6c | Jet Electronics & Technology 5353 52nd Ave. P.O. Box 8239 Grand Rapids, MI 49508 | CE-C | | DN-101 DN-103() DN-104A CM-710() CT-710() DG-710() 601-1359() 289() 154-13 Ser. 400 Series 800 Series 810 Series 254-14 Series |
| TSO-C6c | King Radio Corporation 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KCS-55 KI-226 KI-229 KNI-581() KNI-582 KPI-550 KPI-551 KSG-105 KMI-112 KA51B KMT 112 KPI-552B KAM-432 KPI-553B KDA-430:065-5030-00/-01/-02/-03/-04 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|-----------|--|
| | | | | KPI-552B:066-3069-00,-01,-03,-04 KPI-553B:066-3069-00,-01,-03,-04 |
| TSO-C6c | Litton Aero Products 6101 Condor Drive Moorpark, CA 93021-2699 | NM | | LRN-76 LTN-51-() LTN-51-100 LTN-58 LTN-72-() LTN-72 INS LTN-72R LTN-72RL LTN-104-() LTN-90-100 LTN-91 LTN-72:452080-05-33-61, -02-33-61 LTR-81-01 LTN-90-100:461800-02-122 461800-03-122 LTN-92:461800-02-08-116 463000-10 463001-02-04 463001-04-09 463001-05-04 458900-06-01 452100-02-03 458900-03-04 452080-05-33-61 452080-02-33-61 460800-01-02, -02-03, -03-04, -30, -30-32, -32 461320-01-02 461800-02-04-120, -02-08-116 461985-03 461995-02, -03 463001-02-02 463600-01-01 AHRU:460800-03-04 |
| TSO-C6c *F | Litton Systems (Canada) Ltd. 25 Cityview Drive Rexdale, Ontario Canada M6W 5A7 | NE | | LTN-51-100 LTN-72MRS LTN-72R LTN-72RL LTN-72 INS LTN-76 LTN-51INS(ERIM) LTN-90:461650-() LTN-72:452520-73, 460502-21 LTN-72RL:460502-17, -18, -19, -20 LTN-90-100:461370-01, 461800-02-08-116 LTN-91:461870-03 LTN-96-100 LTN-91-14,-15 |
| TSO-C6c | LSI Service Corporation Harrisburg Division 6700 Allentown Blvd. Harrisburg, PA 17112 | NE | | 1000A |
| TSO-C6c | Narco Avionics Corporation Commerce Drive Fort Washington, PA 19034 | NE | | HSI 100S() |
| TSO-C6c | John Oster Mfg. Co. Racine, WI 53401 | CE-C | | 9813-07 |
| TSO-C6c | Poly Scientific Div. of Litton Industries Blacksburg, VA 24060 | NE | | LTN-51: 663550-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|-----------|--|
| TSO-C6c | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVI-200 Ser. AVI-201 Ser. AVI-203 Ser. AVI-202 Ser. |
| TSO-C6c | Shelter, Ltd. 171 East 118th Street New York, NY 10035 | NE | | SM15 SM20a SM20d SM20a/d |
| TSO-C6c | Singer-Kearfott Div. 1150 McBride Ave. Little Falls, NJ 07424 | NE | | GAMMA I |
| TSO-C6c *F | (S.F.I.M.) Societe de Fabrication d Instruments de Mesure (s.a.) 13, Avenue M. Ramolfo Garnier 91303 Massy, France | EU | | 75-52 CG 52-2 CG 130 |
| TSO-C6c | Smiths Industries SLI Avionic Systems Corp. 4141 Eastern Ave., S.E. Grand Rapids, MI 49518-8727 | CE-C | | 33358 3805D 5513H 5513K 6502E 7650C 6000 2152L:140070-01-01 4060P:139001-01 5513B:133189-01-01 5513H:143200-01-01 5513K:143310-01-01 7650C:140540-01-01 3809C:156561-01-01 3853A1:159793-02-01 3853A2:159793-03-01 3853A3:159793-04-01 3853A4:159793-05-01 6504T:156558-01-01 6504T1:156558-02-01 6507Y:159790-01-01 6504Y1:159790-02-01 6504Y2:159790-03-01 7901A:156555-01-02 7901C:159787-01-01 7901F:162953-01-01 |
| TSO-C6c | Sperry Flight Systems Electra Components Plant Durham, NC 27701 | CE-A | | 2591201-901 2591201-922 ED2 600/800:7003110-(), 7003400-(), 703420-(), 7003430-(), 7004123-() |
| TSO-C6c | Sunbeam Electronics Industrial Park Fort Lauderdale, FL 33307 | CE-A | | 9813-07 |
| TSO-C6c | Vandling Corporation 16270 Raymer Street Van Nuys, CA 91406 | NM | | NDB-2 |
| TSO-C6c | Wilcox Electric Co., Inc. 1400 Chestnut St. Kansas City, MO 64127 | CE-W | | 1041A:098028-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|--|---|-------------|-------|
| TSO-C6d | Aeronetics 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | DIRECTION INSTRUMENT, MAGNETIC (GYRO-STABILIZED TYPE) | DCU-201B:520-2011-001 HSI-415():520-415()-()()() HSI-423A:520-4230-()()() 520-2011-001 520-415()-()()() | | |
| TSO-C6d | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Business & Commuter Avn. Systems Division 5353 W. Bell Road Glendale, AZ 85308 | NM-L | | ED2-600/800:4066300-(), 4066192-(), 4066191-(), 4066190-() | | |
| TSO-C6d | Honeywell, Inc. Air Transport P.O. Box 21111 Phoenix, AZ 85036-1111 | NM-L | | BAe146:4066300-(), 4066192-() 4066191-(), 4066190-() | | |
| TSO-C6d *F | Litef GmbH Lorracher Strasse 18 Postfach 774, D-7800 Freiburg, Germany | EU | | AHRU:121319-0 AHRU:121319-1 RMCU:120231 LCR-88:121319-10/-110 | | |
| TSO-C6d | Rockwell International Collins Avionics Div. 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | EFD-84:622-9681-001, -002, -011, -012 SDO-640A:622-9347-001 SDU-640B:622-9735-001, -002 | | |
| TSO-C7 | AMETEK/U.S. Gauge 900 Clymer Ave. Sellersville, PA 18960 | NE | DIRECTION INSTRUMENT, MAGNETIC, NON-STABI- LIZED TYPE (MAGNETIC COMPASS) | C-4B | C-5A | |
| TSO-C7 | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Highway So. Merrimack, NH 03054 | NE | | 758 | 758L | 814B |
| TSO-C7 | Lear Siegler, Inc. Instrument Division 4141 Eastern Ave., S.E. Grand Rapids, MI 49508 | CE-C | | 4060P | | |
| TSO-C7b | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | DIRECTION INSTRUMENT, MAGNETIC, NON-STABI- LIZED TYPE (MAGNETIC COMPASS) | 1823 Series | 1841 Series | |
| TSO-C7b | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Highway So. Merrimack, NH 03054 | NE | | 398F 1980U | 1630 | 1979U |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|---|---|--|--|
| TSO-C7c | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | DIRECTION INSTRUMENT, MAGNETIC NON-STABI- LIZED TYPE (MAGNETIC COMPASS) | MSC-AQU-3/A | MC-NS-3/A | |
| TSO-C7c | AMETEK/U.S. Gauge 900 Clymer Avenue Sellersville, PA 18960 | NE | | C-4D | C-4E | C-5() |
| TSO-C7c | Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | RDM1-743:622-5001-003 RDM1-743A:622-5818-001 RMI-733A:622-6084-001, -002, 622-5002-501, -502 | | |
| TSO-C7c | Hamilton Instruments, Inc. 106 Neuhaus W. P. Hobby Airport Houston, TX 77061 | SW | | HI 325/HPS 328-1 HI-350-1 | VC-100 | HI-350 HT425 |
| TSO-C7c | Hoover Industries, Inc. P.O. Box 522337 Miami, FL 33166 | CE-A | | FR-46:4600() | | |
| TSO-C7c | Precision Aviation, Inc. Precision Lane at 8100 Lockheed Houston, TX 77061 | SW | | HSI-400 | PA1C-1 | |
| TSO-C7c | Precision Aviation, Inc. 8124 Lockheed Houston, TX 77061 | SW | | PA1-700 | | |
| TSO-C7c | Smiths Industries SLI Avionic Systems Corp. 4141 Eastern Ave., S. E. Grand Rapids, MI 49518-8727 | CE-C | | 3805D 4060P:139001-01 | 6502E | |
| TSO-C7d | Instrument and Flight Research 2716 George Washington Blvd. Wichita, KS 67210 | CE | DIRECTION INSTRUMENT, MAGNETIC NON-STABILIZED TYPE (MAGNETIC COMPASS) | IFR 31-00, 31-12, 31-24 | | |
| TSO-C7d *F | Smiths Industries Cheltenham England | EU | | KCA0101W WL1001KCA1 | KCA0104W | KCA0105W |
| TSO-C8 *F | Aeritalia, S.p.A. Nerviano(Milan), Italy (Formerly Filotecnica Salmoiraghi) | EU | RATE OF CLIMB INDICATOR, PRESS. ACTUATED (VERTICAL SPEED INDICATOR) | 21020() 21060() 8.041.008.1 8.041.503 8.041.603 8.041.703 | 21030() 8.041.003 8.041.008.1.01 8.041.508 8.041.608 8.041.708 | 21040() 8.041.008 8.041.508.1 8.041.608.1 8.041.708.1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|--------------|--|------|--|---|--|-------------------------|
| TSO-C8 | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | | 35060(1117) | 35060(1118) | |
| TSO-C8 | Bendix Instrument & Life Support Div Hickory Grove Rd Davenport, IA 52802 | CE-W | | 1634 1650 1654 1659 | 1648 1652 1655 1662 | 1649 1653 1657 |
| TSO-C8 | Bendix Eclipse-Pioneer Division Teterboro, NJ 07608 | NE | | 1634-1-C1-1 1634-6Q-B2 | 1634-1AE-B1 | 1634-1AG-B1 |
| TSO-C8 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | G991 22-202-() 1409-()-() | G993 22-204-() | 22-200 1403-()-() |
| TSO-C8 | Karnish Instrument, Inc. 210 Third Ave. Lock Haven, PA 17745 | NE | | AC111 | | |
| TSO-C8 | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Highway So. Merrimack, NH 03054 | NE | | B2536()-()-() B4018()-()-() | | |
| TSO-C8 | Lear Siegler, Inc. Instrument Division 4141 Eastern Ave. Grand Rapids, MI 49508 | CE-C | | B0352() | B0352-81101 | |
| TSO-C8 | Teledyne Avionics P. O. Box 6400 Charlottesville, VA 22906 | NE | | D3() M6() SL2 8126() | D6() M6() SL2 8286() | M3() B3 SL2 9541 |
| TSO-C8 *F | Tokyo Aircraft Instrument Co., Ltd. 1600 Izumi, Konae-chi, Kitatama-gun, Tokyo, Japan | NM | | CA-5 CA-53-1A CA-54-1B | CA-52-1A CA-53-1B | CA-52-1B CA-54-1A |
| TSO-C8a | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | VERTICAL VELOCITY INSTRUMENT (RATE OF CLIMB) | 1634-1AB-C1-1 1634-1AF-C1-1 1634-1AH-C1-1 1634-1AN-C1-1 1634-1AN-B1 1634-1AL-B1 1634-1AH-B1 | 1634-1AE-C1-1 1634-1AG-C1-1 1634-1AK-C1-1 1634-1AB-B1 1634-1AF-B1 1634-1AK-B1 | |
| TSO-C8a | Karnish Instrument, Inc. 210 Third Ave. Lock Haven, PA 17745 | NE | | AC 119 | | |
| TSO-C8a | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Highway So. Merrimack, NH 03054 | NE | | A26877-10-001 A32081-00-001 D07165-10-004 | A32081-10-004 D01763-10-055 F07165-10-055 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|--|---|--|--|
| TSO-C8b | Aero Mechanism, Inc. 20327 Nordhoff Street Chatsworth, CA 91405 | NM | VERTICAL VELOCITY INSTRUMENT (RATE OF CLIMB) | 8064() 8504-() | 8064-1() | 8065() |
| TSO-C8b | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | | 30020-() 30260-() 31060-() 37060-() RCM-10-3 RC-20-1LB1 RCS-20-10 RC-30-V() RC-30-V-10 RC-60-V() RC-60-MS-AAU-9/A-10 RC-60-MS-10-31 RC-60-MS-AAU-9/A-101 RCS-60-1LW RCS-60-1L-3 RCS-60-10-V | 30160-() 30840() 31260-() 35060-() RC-20 RCH-20-CM RCS-20-10-V RC-30-10 RC-60 RC-60-MS-10-3 RC-60-V-10 RC-60-10-() RCM-60-AC RCS-60-1L-10 RCS-60-1L-31 RCS-60-MS-3 | 30230-() 30860() 35020-() 37020-() RC-20-1LB RCM-20-MS RC-30 RC-30-10-V-() RC-60-AC RC-60-V-10 RC-60-10-() RCM-60-AC RC-60-1L8 |
| TSO-C8b *F | Badin-Crouzet Aeroport de Toussus Le Noble P. O. Box 17 78530 BUC France | EU | | 33405-01 38 210-000 | 33405-10 IVS1 38 210-390 | |
| TSO-C8b | Collins Avionics Division Rockwell International 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | | ADC-80B:622-8070-099, -345 ADC-800:622-7577-799 ADC-81A:622-4401-001 ADC-82A:622-6475-001 thru -006, -021 ADC-82L:622-8105-012, -013, -099, -399 ADC-80H:622-4365-537 ADC-80Q:622-7577-555, -556 ALI-80A:622-3975-001 thru -008 VNI-80A:622-4185-001 thru -008 VNI-80C:622-7683-001 thru -008 VNI-80D:622-7690-001 thru -008 VSI-80:622-1910-001 thru -008 | | |
| TSO-C8b | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | ADC-80:622-4365-022/203/204/205/207/ 208/211/213/220/221/225/310/324 ADC-80J:622-5206-014/017/022/027 ADC-80K:622-5465/209/214/215/217/222/ 227/228/310/326 ADC-80M:622-2704-002 VSI-80:622-1910-001 thru -008 VSI-80A:622-4782-001 thru 008 VSI-80M:622-2700-001 | | |
| TSO-C8b | Collins Radio Group Rockwell International 400 Collins Road NE Cedar Rapids, IA 52406 | CE-W | | ADC-62L ADC-80F ADC-80R ADC-82C ADS-81:ADC-81A, ADS-81A VNI-80D | ADC-80 ADC-80N:622-7576-521/-554 ADC-80Q:622-7577-799 ADS-80:ADC-80F, VSI-80 VSI-80 VNI-80C | ADC-80() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-----------|---|---|--|
| TSO-C8b | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | 2594468-() 4013013-902 4013013-905 4013013-909 4039893-() | 2594619-() 4013013-903 4013013-906 4013013-911 4012384 | 4013013-901 4013013-904 4013013-907 4013013-912 HG2800-() |
| TSO-C8b | Instrument Specialties P. O. Box 365 Euless, TX 76039 | SW | | 6601-() | | |
| TSO-C8b | Karnish Instrument, Inc. 210 Third Ave. Lock Haven, PA 17745 | NE | | AC-132-() | AC-135-() | |
| TSO-C8b | Kearflex Engineering Co. 66 Cypress Street Warwick, RI 02888 | NE | | 843-67-2A | 843-67-3 | 2183 |
| TSO-C8b | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Highway So. Merrimack, NH 03054 | NE | | A25363-10-005 A40187-10-002 A4512()-()-() | A34521-10-006 A3206()-()-() | |
| TSO-C8b | Kollzman/IDC Avionics Group 170 Coolidge Ave. Englewood, NJ 07631 | NE | | 180138-() 34670-() | 22719-() 35260-() | 18417-() 37320-() |
| TSO-C8b | MacLeod Instrument Corp. Sub. of Aerosonic Corp. P. O. Box 5163 Clearwater, FL 33518 | CE-A | | 320-() 360-() | 330-() | 340-() |
| TSO-C8b | Smiths Industries, Inc. St. Petersburg/ Clearwater Airport Clearwater, FL 33732 | CE-A | | 02-100-1() | | |
| TSO-C8b *F | Smiths Industries Ltd. Bishops Cleeve Cheltenham Gloucestershire, England | EU | | WL 401 RC() | | |
| TSO-C8b *F | (S.F.E.N.A.) Societe Francaise d'Equipment pour la Navigation Aeriennne Aerodrome de Villacoublay P.O. Box 59 78140 Velizy, Villacoublay France | EU | | AVSI:P/N A43()() | | |
| TSO-C8b | Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906 | NE | | Type T():SLZ() D1:SLZ()()()()-() | | SLZ9665 |
| TSO-C8b *F | Tokyo Aircraft Instrument Co., Ltd. 1600 Izumi, Komae-shi Tokyo, Japan | NM | | CA-34-1 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|---|--|
| TSO-C8b | United Instruments, Inc. 3625 Comotara Avenue Wichita, KS 67226 | CE-W | | 7000()() 7030()() 7040()() 7100:7120()-(), 7130()-(), 7140()-(), 71 7200()() 7201()() 7210()() 7211()() |
| TSO-C8c | Bendix/King Air Transport Div. 2100 N.W. 62nd St. Fort Lauderdale, FL 33310 | CE-A | VERTICAL VELOCITY INSTRUMENT (RATE-OF- CLIMB) | RA/VS1:066-50002-8101 thru -8104 TA/VS1:066-50001-8101 thru -8108 066-50001-0901 thru -1201 |
| TSO-C8c | Bendix/King General Aviation Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | KAV 485:066-3077-00 thru -07, -10 066-3077-17, -20 thru -27, -28 066-3077-30 thru 37 KDC 481:065-0082-02, -04 |
| TSO-C8c | Collins Avionics Division Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | ADC-85:622-8051-002 ADC-86 ADM-86 ALI-8508 ALI-850 ALI-850C:622-9751-001, -002 ADC-850:622-7208-002 ADM-85:622-8692-002, -003, -004, -005, -006, -011 ADM-86:622-9282-002, -004 ADM-850:622-7737-002, -007 RA/VS1:066-50002-8101 thru -8104 TA/VS1:066-50001-8101 thru -8108 :066-50001-0901 thru -1201 TVI-920 VS1-TCAS:622-9353-001, -011, -021, -031, -201, -211, -221, -231 |
| TSO-C8c | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport System Div. 21111 N. 19th Ave. Phoenix, AZ 85036-1111 | NM-L | | 4067241-() 4067487-() |
| TSO-C8c | Instrument and Flight Research 2716 George Washington Blvd. Wichita, KS 67210 | CE | | IFR 33-20, 33-30, 33-40, 33-60 |
| TSO-C8c | Kollsman 220 Daniel Webster Hwy Merrimack, NH 03054-4809 | NE | | 47174-003, -004 |
| TSO-C8c | Kollsman/IDC Avionics Group 170 Coolidge Avenue Englewood, NJ 07631 | NE | | 40620-() 43010-() 43000-() |
| TSO-C8c | Rockwell International Collins Avionics Group 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | TVI-920D:622-9728-001, -002, -011, -012, -021, -022, -031, -032, -201, -202, -211, -212, -221, -222, -231, -232 |
| TSO-C8c *F | Sextant Avionique Div. Instruments de Bord 31 rue Camille Desmoulins BP 12, 92132 Issy Les Moulineaux France | EU | | RA/TA VS1-TCAS:457400()-() |
| TSO-C8c | Smiths Industries | EA | | 2074-()()-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|----|---------------------|---|---|--|
| | 255 Great Valley Parkway Malvern, PA 19355 | | | | | |
| TSO-C8c *F | Smiths Industries Limited Cheltenham, Gloucestershire United Kingdom | EU | | 602RC() | | |
| TSO-C8c | Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906 | NE | | SL27606 | SL27656 | SL27656-1 |
| TSO-C9 | Astronautics Corporation of America 2416 Amsler St. Torrance, CA 90505 | NM | AUTOMATIC PILOTS | P1-TC() P2A-H() | P2-C() | P2A-C() |
| TSO-C9 | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | PB-20J | PB-60A | DY 22() |
| TSO-C9 | Bendix Navigation & Control Div. South Montrose, PA 18843 | NE | | DY-12-() DY-22 DQ-29-() 4564 15647-() 16733-() 16787 16797- 16923- 17013- 1954604- 1975548-() | DY-16 DY-25 DQ-43 4570-() 15653-() 16781-() 16788-() 16906- 16928- 17015-() 1954631 1975549-() | DY-19-() DY-26 4562 4572 16729-() 16782- 16792- 16921-() 16963- 1954603- 1954900-() 1990858-() |
| TSO-C9 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | PB-60 SD92() 16762() 19911() 1925737() 1925958() 1954564() 1964570() 1978121() 1978730() 1978976-1 1990013() 1990111() 1990554() 3743000() 3757079() 3757085() 3757132() 3759029() 3838010() 3757091() | PB-60A PB-100() 16767() 1925458() 1925742() 1954099() 1954565() 1964810() 1978728() 1978732() 1978980() 1990039() 1990548() 1990872() 3757021() 3757081() 3757087() 3757133() 3838006() 3853022() 3757096() | FGS-70 15101-() 16797() 1925735() 1925956() 1954358() 1964567() 1970766() 1978729() 1978976() 1978983() 1990074() 1990552() 1998763() 3757049() 3757082() 3757121() 3759027() 3838008() 3880000 |
| TSO-C9 | Bendix Radio Division Baltimore, MD 21233 | NE | | PB-20D | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|---|------|-----------|---|--|--|
| TSO-C9 | Brittain Industries, Inc. Wilmington, DE 19899 | NE | | B5A: 702 B-VII: 701 B-VIII: 706 807 810 | 710 711 707 808 | TC-100 806 805 809 |
| TSO-C9 | Brittain Industries, Inc. Div. of Harco Scientific Ind Commerce Dr. Fort Washington, PA 19034 | NE | | B5A TC 100() | B-VII | B-VIII |
| TSO-C9 | Collins Radio Co. 5225 "C" Ave. N. E. Cedar Rapids, IA 52406 | CE-W | | AP-101 AP-103D FD109 161E-2 332C-2 334C-3A 334C-3E 334D-2-33/A/B/C/D/E/F 345C-2A 351B-3C 351B-6() 351B-6C 562C-4 590A-3D 614E-2F 790M-1 614E-20A | AP-102 AP-103E 121A-2 161E-2A 332G-2 334C-3B/C 334C-3F 351B-3A 351B-3E 351B-6A 351B-7() 562C-4E 590A-3E 614E-2G 790M-1C | AP-103 AP-103F 161A-1A 161F-1 334C-3 334-3D 327D-1/1W 345A-4/A/B 351B-3B 351B-3D 351B-6B 390R-5B 590A-3A 590B-2 614E-4 890H-2 |
| TSO-C9 | Globe Industries Div. of TRW, Inc. 2275 Stanley Ave. Dayton, OH 45404 | CE-C | | 69-A-103 | | |
| TSO-C9 | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Systems Div. P.O. Box 21111 Phoenix, AZ 85036-1111 | NM | | AS440 | | |
| TSO-C9 | Honeywell, Inc. Sperry Comm. Flt. Sys. Inc. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | A-12 SP-40 SP2-200 2587329 4006719() 4011026 | SP-20 SP-50() 616418 2587349 4008515 | SP-30AL SP-53 683269-1 4005842 4008519() |
| TSO-C9 | Instrument Flight Research 2716 George Washington Blvd. Wichita, KS 67210 | CE-W | | SG-200T | | |
| TSO-C9 | Jet Electronics & Technology 5353 52nd St. Grand Rapids, MI 49508 | CE-C | | FC-110 SA-141 RG-228() | FC-110() SA-142 AL-228() | PC-110 RG-227 |
| TSO-C9 | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | BG174 CG117 CG317 GG205A4 GG302 PG51 | BG274 CG136 CG417 GG205C4 MG112 SG28 | BG374 CG217 CG517 GG301 MG113 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|---|------|---------------------|--|--|---|
| TSO-C9 | Kollzman/IDC Avionics Group 170 Coolidge Ave. Englewood, NJ 07631 | NE | | 18210-3() | | |
| TSO-C9 | Lear Jet Corp. Municipal Airport P. O. Box 1280 Wichita, KS 67201 | CE-W | | FC-110() | | |
| TSO-C9 | Lear Siegler, Inc. Instrument Division 4141 Eastern Ave., S. E. Grand Rapids, MI 49508 | CE-C | | L-1 L-5 L-102B 1101B | L2-B L-5B 760B 1102B | L2-C L-102A 1101A 1106C |
| TSO-C9 | Minneapolis-Honeywell Regulator Company Minneapolis, MN 55401 | CE-C | | H-14 MH6-1A | MH6 | MH6-1 |
| TSO-C9a | ANSCO, A Division of General Aniline & Film Corp. Binghamton, NY 13902 | NE | AUTOMATIC PILOTS | R | | |
| TSO-C9a | Bendix-Nov. & Control Div. Teterboro, NJ 07608 | NE | | 3757109-8 | | |
| TSO-C9a | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | PB-10 | PB-10A | |
| TSO-C9a | Howell Instruments, Inc. 3479 W. Vickery Blvd. Fort Worth, TX 76107 | SW | | H901()-2() | | |
| TSO-C9a | LSI Service Corp. Harrisburg Division 6700 Allentown Blvd. Harrisburg, PA 17112 | NE | | L-5 | L-5B | |
| TSO-C9a | Rockwell International Collins Avionics Div. 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | ATC-850:622-9377-001 | | |
| TSO-C9a | S-TEC Corporation Route 3, Building 945 Walters Industrial Complex Mineral Wells, TX 76067 | SW | | 0103-() | 0104-() | 0110-() |
| TSO-C9a | Summers Gyroscope Co. Santa Monica, CA 90406 | NM | | S-1 | | |
| TSO-C9b | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | AUTOMATIC PILOTS | PB-10A DR-55() SD52() SD68() PB-20E 4570() 4957() | PB-20B DY-16() SD64() SD91() PB-20G 4572() 4970() | PB-20D SD-48() SD65() SD93() PB-20H 4953() 16781() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|---------------------|---|------------------|------------|
| | | | | 16788() | 16792() | 16929() |
| | | | | 16930() | 18749() | 18750() |
| | | | | 18756() | 18757() | 18762() |
| | | | | 18763() | 18765() | 19117() |
| | | | | 19118() | | |
| TSO-C9b | Bendix Flight Systems Division Teterboro, NJ 07608 | NE | | 3822070-() | | |
| TSO-C9b | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | PB-200 | SD69() | SD74() |
| | | | | SD105() | SD112() | SD113() |
| | | | | SD116() | 16957() | 16963() |
| | | | | 16964() | 16966() | 18746() |
| | | | | 18747() | 18764() | 18852() |
| | | | | 1925740-1 | 1925956-1 | 1925957-1 |
| TSO-C9b | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | SP-3 | SP-30 | SP-30A |
| | | | | SP-40 | SP-50 | 2587335 |
| | | | | 2597545 | 2592800-() | 2586137-1 |
| TSO-C9b | International Telephone & Telegraph Corp. Industrial Products Div. San Fernando, CA 91340 | NM | | FS-102 | FS-103 | FS-104 |
| TSO-C9b | Motorola Aviation Electronics, Inc. Santa Monica, CA 90406 | NM | | 2287() | 4041() | 5527() |
| | | | | L-2 | | |
| TSO-C9b | Smiths Industries SLI Avionic Systems Corp. 4141 Eastern Avenue, S.E. Grand Rapids, MI 49518-8727 | CE-C | | 2157F:112375-01 | | |
| | | | | 2157G:119540-01 | | |
| | | | | 2157H:112375-01 | | |
| | | | | 2162C:121437-01 | | |
| TSO-C9b *F | Smiths Industries Limited Aviation Division Bishops Cleeve Cheltenham, Gloucestershire England | EU | | S.E.P.2 | | |
| TSO-C9b | Sperry Rand Corp. Electro Components Plant Durham, NC 27701 | CE-A | | SP-20:618319, 6043908, 616418-166, 669780, 683269-1, 4002132 | | |
| TSO-C9c | Astronautics Corp. of America P.O. Box 523 Milwaukee, WI 53201-0523 | CE-C | AUTOMATIC PILOTS | 17595 | 131140-1, -11 | |
| | | | | 132510 | 133160 | 134280 |
| | | | | A/PG300A() | 131880-1, -3, -5 | |
| | | | | 135050-9 | | |
| TSO-C9c | Astronautics Corp. of America 2416 Amsler St. Torrance, CA 90505 | NM | | P1 | P2 | P2A |
| | | | | P3 | P3A | P3B, P3-PH |
| | | | | M1 | M2 | M3 |
| | | | | M2A | M3A | M3B |
| | | | | P1-SD-() | P3B-38() | P3-TC() |
| | | | | A/PG300A | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | | | | |
|---------|--|-------------|-----------|---|-------------|-------------|-----------|-----------|-----------|
| TSO-C9c | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | DY-13() | DY-15() | DY-16() | | | |
| | | | | DY-20() | DY-21() | DY-22() | | | |
| | | | | DY-23() | DY-24() | PB-60() | | | |
| | | | | 2290() | 2291() | 4912() | | | |
| | | | | 4564() | 4945() | 14156() | | | |
| | | | | 14168() | 15101() | 15527() | | | |
| | | | | 15869() | 16733() | 16782() | | | |
| | | | | 16787-1A | 16923() | 16945() | | | |
| | | | | 17013() | 17014() | 17015() | | | |
| | | | | 18719() | 18720() | 18731() | | | |
| | | | | 18778() | 18823() | 18887() | | | |
| | | | | 18889() | 18890() | 18896() | | | |
| | | | | 18897() | 18898() | 18943() | | | |
| | | | | 18946() | 19903() | 19905() | | | |
| | | | | 1880758() | | | | | |
| | | | TSO-C9c | Bendix Flt & Engine Instr. Div. South Montrose, PA 18843 AND Bendix Flight Systems Div. Teterboro, NJ 07608 | NE | | 1936100-5 | 1954103-4 | 1954354-4 |
| | | | | | | | 1954355-4 | 1954356-4 | 1954358-4 |
| | 1964192-7 | 1964193-6 | | | | 1964566-4 | | | |
| | 1964567-5 | 1964570-4 | | | | 1964679-4 | | | |
| | 1978172-4 | 1978729-4 | | | | 1978730-4 | | | |
| | 1978731-4 | 1978981-4 | | | | 1978983-4 | | | |
| | 1990013-5 | 1990040-4 | | | | 1990074-4 | | | |
| | 1990097-4 | 1990111-7G | | | | 1990115-4 | | | |
| | 1990548-7 | 1990549-7G | | | | 1990553-4 | | | |
| | 1990554-4 | 3743000-4 | | | | 3743001-4 | | | |
| | 3743003-4 | 3743004-4 | | | | 3743007-4 | | | |
| | 3743010-4 | 3743011-() | | | | 3743012-() | | | |
| | 3743013-() | 3743014-() | | | | 3743015-() | | | |
| | 3743016-() | 3757021-7 | | | | 3757043-7G | | | |
| | 3757049-7 | 3757078-7 | | | | 3757079-7G | | | |
| | 3757080-7 | 3757081-7G | | | | 3757082-7 | | | |
| | 3757083-9 | 3757085-9G | | | | 3757087-9G | | | |
| | 3757088-9 | 3757089-9H | | | | 3757091-9 | | | |
| | 3757109-9H | 3757121-9 | | | | 3757122-9 | | | |
| | 3757132-9 | 3757146-7 | | | | 3757147-7G | | | |
| | 3757319-7B | 3757320-7 | | | | 3759027-6 | | | |
| | 3759028-6 | 3759029-6 | | | | 3759050-6 | | | |
| | 3759078-6 | 3759082-6 | | | | 3759083-6 | | | |
| | 3759081-6 | 3822170-4 | | | | 3822182-4 | | | |
| | 3822183-4 | 3838006-4 | | | | 3838007-4 | | | |
| | 3838008-4 | 3838009-4 | | | | 3838010-4 | | | |
| | 3838011-4 | 3838012-4 | | | | 3838023-4 | | | |
| | 3838026-4 | 3838029-4 | | | | 3838039-4 | | | |
| | 3838042-4 | 3838033-4 | | | | 3838037-4 | | | |
| | 3838043-4 | 3854009-() | | | | 3856084-4 | | | |
| | 3838044-4 | | | | | | | | |
| TSO-C9c | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | | | | DY-19() | DY-22() | DY-25 |
| | | | | | | | DY-25() | DY-26() | DY-27() |
| | | | | DB-43() | PB-75() | PB-70J | | | |
| | | | | 4574() | | | | | |
| | | | | 13105() | 14168() | 15101() | | | |
| | | | | 15108() | 15115() | 15869() | | | |
| | | | | 16797() | 18749() | 18787() | | | |
| | | | | 18954() | 19911() | 19912() | | | |
| | | | | 19913() | 19917() | | | | |
| | | | | 1880107-() | 1903025-() | 1903243() | | | |
| | | | | 1903244() | 1903245() | 1903246() | | | |
| | | | | 1925194() | 1925961() | 1925736() | | | |
| | | | | 1925738() | 1925743() | 1925911() | | | |
| | | | | 1925957() | 1964569() | 1964566 | | | |
| | | | | 1978172() | 1978731() | 1978733() | | | |
| | | | | 1978977() | 1978981() | 1978984() | | | |
| | | | | 1990036() | 1990040() | 1990097() | | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|-----------|--|
| | | | | 1990115() 1990549() 1990553() 1990762() 1990858() 1990890() 1999602() 3743001() 3757043() 3742010-() 3743003-() 3743004-() 3757078() 3757080() 3757083() 3757088() 3757089() 3757097() 3757122() 3759028() 3822090-() 3838004() 3838007() 3838009() 3838011-() 3838012-() 3743004() |
| TSO-C9c | Bendix Radio Division Baltimore, MD 21233 | NE | | M-4 2203() 4100() 5489() |
| TSO-C9c | Bendix Avionics Division 2100 N.W. 62nd St. P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | 2203() 2268() 3013() 3014() 3019() 4100() 5488() 5489() 5487() 5536() 6743() 6744() AD816() FCS-810 AD856() M-4D:5485A 5486A 5487G 5536F FDS-840:AC844() AD-854A:4000594-() AD-873A CV-8704():4001538-() FCS-870:CA-871(), FC-872(), MA-872(), SA-873(), SE-873(), ST-873(), SR-874() FCS-8700 FC-8702():4001533-() FCS-8700B:MC-8702(A), FC-8702(B), VP-8702(A) FCS 8700B:AD-8703A MA-8702():4001532() SA-8703():4001534-() SE-8703():4001535-() SR-8703():4001537-() PT-8705():4001539-() |
| TSO-C9c | Bendix/King General Avn. Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | KA 52:071-1055-01 KA 151:065-05062-0000, -0001 KA 153:065-0143-00 KAA 15:071-1466-01 KAD 297B:065-0065-01 KAM 432:065-0091-04 KAS 297:065-0046-06 KAS 297C:065-0089-08 KC 190:065-0055-02, -03, -04, -05 KC 191:065-0054-02, -03, -04, -05, -06, -07 KC 192:065-0042-02, -03, -04, -05, -06, -07 KC 193:065-0144-00 KC 296:065-0036-30 KCP 220:065-0064-06, -08 065-5034-06, -07, -08, -10, -11, -16, 065-5051-06, -07, -08, -10, -11, -16 065-5052-06, -07, -08, -10, -11, -16 065-5053-06, -07, -08, -10, -11, -16 KCP 220:065-0064-05, 07, -08, KCP-420:065-0069-07, -10, -13, -14, -15 KDA 430:065-5030-06 KM 275H:065-0030-60 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|-----------|--|
| | | | | KMC 440:065-0070-38 KMC 440:065-0073-36, -37 KMS 446:065-0073-22, -23 KMS 447:065-00154-0101 KMS 447S:065-00156-0101 KRB 434:065-0092-01 KS 271AH:065-0060-60, -61 KSA 372:065-0056-71 KSA 372TR KSA 372XT:065-0056-70 KSM 375XT:065-0015-70 KSM 475:065-0079-11, -12, -13 KTA 435:065-5046-10 |
| TSO-C9c | Brittain Industries Div. Narco Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | B-11 |
| TSO-C9c | Brittain Industries, Inc. 3266 N. Sheridan Road Tulsa, OK 74115 | SW | | B5A B11 B1-817:280-001-XXX B7(B-VII) B-12: 280-003-501 |
| TSO-C9c | BVR Aero Precision Corp. 5459 Eleventh Street P.O. Box 6336 Rockford, IL 61125-1336 | CE-C | | BVR 590A-6A |
| TSO-C9c | Century Flight Systems, Inc. P.O. Box 610 Mineral Wells, TX 76067 | SW | | 1C497-() 1C709-() 1C722-() 1C763-() 1C774-() 1D757-() 1D937-() 1C543-() 1C714-() 1C727-() 1C771-() 1C778-() 1D762-() 52D136-() 1C718-() 1C753-() 1C772-() 1D755-() 1D946-() 52D-137-() |
| TSO-C9c | Collins Aviation Rockwell International Avionics & Missiles Group 400 Collins Road NE Cedar Rapids, IA 52406 | CE-W | | APC-65 FCC-85 FCC-860 FCC-86C SVO-80C 614E-42A APC-65B FCC-86 FCC-85B SMT-85B SVO-85B KA-154 FCC-86C FCC-86B SVL-85 351B-8C |
| TSO-C9c | Collins Avionics Division Rockwell International 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | 161E-2A APS-80: FGC-80, FGC-80A, FGP-80, APC-80, APA-80, APA-80A, APP-80, APP-80A AP-107H: 913K-2H, 562C-15H, 334C-12 614E-20K 454N-2 SVO-80() 454N-3 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|-----------|---|
| TSO-C9c | Collins Avionics Division Rockwell International 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | 614E-22G 614E-22L ACP-201() 913K-1A 562C-13A ACC-201 FGP-81():622-2265-() SVO-85C:622-6717-003/-004 SMT-85A:622-5028-001/-002 SMT-85B:622-5029-001/-002 SMT-85C:622-6718-001/-002 334D-6:622-0965-001/-002 622-0965-003/-004 622-0965-005/-006 622-0965-008 622-0965-009 334D-6A:622-3260-001 622-3260-002 334D-6B:622-5026-001/-002 334D-6C:622-5082-001/-002 351B-6:777-1062-001 777-1062-003 351B-6A:792-6784-001 792-6784-003 792-6784-004 351B-6B:792-6785-001 792-6785-002 792-6785-003 351B-6C:792-6973-001 792-6973-002 792-6973-003 351B-6E:622-5229-001/-002 351B-6F:622-5150-001/-002 351B-6G:622-5151-001/-002 351B-6H:622-5152-001/-002 351B-6J:622-6155-001 351B-6K:622-6156-001 351B-6L:622-6157-001 351B-6M:622-6158-001 351B-7:777-1557-001 351B-7A:792-6782-001 351B-7B:792-6783-001 351B-7C:792-6974-001 351B-8C:792-6975-001 562A-18:622-4869-001 562C-8F:622-3167-055 590A-3J1:622-4393-001/002/019 590A-3K1:622-4394-001 590E-1:622-5477-001 614E-51:622-4965-001 614E-51B (FDS-800):622-7014-001 916A-19:622-4176-001 916B-6:622-4465-001 998E-1:622-4217-001 AP-107H:622-3180-002 AP-107H:622-3097-001 AP-107H:622-3979-001 APA-80:622-2263-001, 013 thru -016, -018, -019, -021 thru -025, -027, -028, -029, -031, -032 APA-80:622-4248-001 thru -016, -018, -019, -021 thru -025, -027, -028, -029, -031, -032 APA-80A:622-3108-001 thru -016, -018, -019, -021 thru -025, -027, -028, -029, -031, -032 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | APA-80C:622-4248-001 thru -016, -018, -019, -021 thru -025, -027, -028, -029, -031, -032 |
| | | | | APA-80F:622-5441-020, -021, -026 |
| | | | | APA-80G:622-7562-034 |
| | | | | APC-65:622-8434-099 |
| | | | | APC-65E:622-9046-XXX |
| | | | | APC-80:622-2901-028 |
| | | | | APC-80A:622-3992-019 |
| | | | | APC-65/APP-65:APP-65A, SVO-65, SMT-65D, FCP-65, FCP-65A, ADS-65, MAP-65, SSS-65, SMT-65, NAC-80 |
| | | | | APC-65:622-5796-107 |
| | | | | APC-65A:622-7890-099, -018 |
| | | | | APC-65B:622-8315-099, -123, -302 |
| | | | | APC-65E:622-9046-099 |
| | | | | APC-65F:622-9267-027, -099 |
| | | | | APC-65H:622-9724-017, -028, 099, -128 |
| | | | | APP-85:622-6208-204, -208 |
| | | | | APP-85D:622-7411-204 |
| | | | | APS-85 |
| | | | | APS-841():APC-841, AAM-830, SVO-830, 590A-6, HAS-751 |
| | | | | APS-841H:APC-841, AAM-830, SVO-830, 590A-6, HAS-751 |
| | | | | ASU-80() ATC-80 ATC-830() |
| | | | | ATC-81:622-9575-001 |
| | | | | ATC-850:622-9377-001 |
| | | | | CWC-80:622-6392-001 thru -010 |
| | | | | FAC-1000:622-7478-301, -311, -321 |
| | | | | FCC-85:622-6193-015 |
| | | | | FCC-85B:622-7491-001 |
| | | | | FCC-85D:622-7410-001, -002, -099, -101, -201 |
| | | | | FCC-86:622-6195-015 |
| | | | | FCC-86B:622-7492-001 |
| | | | | FCC-86C:622-7493-005/-008/-018 |
| | | | | FCC-86D:622-7978-011, 219 |
| | | | | FCC-86E:622-8196-002 |
| | | | | FCC-86G:822-0175-002 |
| | | | | FCC-1000:622-7476-301, -311, -321, -331 |
| | | | | FCS-240:FCC-201(), GSP-201() |
| | | | | FCP-65:622-5798-002 thru -020, -027, -028 |
| | | | | FCP-65A:622-5953-001/-002/-003/-004 |
| | | | | FGC-80B:622-3106-001 thru -030, 622-3106-101 thru -130 |
| | | | | FGC-80F:622-5224-001 thru -030, 622-5224-101 thru -130 |
| | | | | FMP-1000:622-7477-301, -401 |
| | | | | FYD-65:622-9627-005, -017, -099 |
| | | | | ICC-850A:622-8364-001 |
| | | | | ICC-851:622-9342-001 |
| | | | | IOC-851:622-7405-002, -003 |
| | | | | MCC-1000:622-7479-301, -311, -321 |
| | | | | MSP-850A:622-8330-001, -002, -003, -004, -005, -101, -102, -103, -104, -105 |
| | | | | MAP-65:622-5799-001 |
| | | | | PWR-851A:622-8365-001, -002 |
| | | | | QCS-111:622-4601-001 |
| | | | | RMP-1000:622-7480-301 |
| | | | | SCC-80:622-4120-001 |
| | | | | SCP-80:622-4121-001 |
| | | | | SMA-86A SMA-86B SMA-86C |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|---|
| | | | | SMT-65D:622-6411-003, -004 |
| | | | | SMT-85B:622-5029-001 |
| | | | | SMT-86A:622-6508-001, -002, -003, -004, -101, -102, -103, -104 |
| | | | | SMT-86B:622-6509-001, -002, -003, -004, -101, -102, -103, -104 |
| | | | | SMT-86C:622-6719-001, -002, -003, -004, -101, -102, -103, -104 |
| | | | | SVO-80C:622-3017-001 |
| | | | | SVO-85B:622-5027-001, -002 |
| | | | | SVL-85 |
| | | | | SVT-65:622-6142-001, -002 |
| | | | | SVT-80:622-4101-001 |
| | | | | SHT-1000:622-7926-301 |
| | | | | SMT-1000:622-7926-303 |
| | | | | SMT-1000A:622-8069-301, -303 |
| | | | | SVT-1000A:622-7910-301 |
| | | | | SMT-1001:622-7927-301 |
| | | | | SVT-1000B:622-7911-301 |
| | | | | SVL-1000:622-8071-301 |
| | | | | SVO-80:622-3014-001 |
| | | | | SVO-80A:622-3015-001 622-3015-002 |
| | | | | SVO-80B:622-3016-001 |
| | | | | SVO-80C:622-3037-001 |
| | | | | SVO-85A:622-4404-001/-002 |
| | | | | SVO-1000:622-7925-301, -302, -303 |
| | | | | TSM-80:622-4107-001 |
| | | | | TSN-1000:622-7584-301 |
| | | | | TSM-1001:622-7928-301 |
| TSO-C9c | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | AAM-830:622-5193-001/002 |
| | | | | ADS-65:622-5797-001 |
| | | | | APC-65:622-5796-(XXX) |
| | | | | APC-841:622-5192-001/002 |
| | | | | APP-65:622-6122-001 |
| | | | | FCP-65:622-5798-001 |
| | | | | SMT-65:622-5735-001/004 |
| | | | | SMT-65D:622-6411-001/002 |
| | | | | SVO-65:622-5734-001/002 |
| | | | | SVO-80A:622-3015-001/002 |
| | | | | SVO-80B:622-3016-001 |
| | | | | SVO-80C:622-3017-001 |
| | | | | SVO-830:622-5194-001/002/003 |
| | | | | SVO-830A:622-5445-001/002 |
| | | | | 161E-2A:792-6255-001/004/005 |
| | | | | 161H-1:622-1036-001 |
| | | | | 334C-6:777-1061-001 |
| | | | | 334C-6A:792-6780-001 |
| | | | | 334C-6B:792-6781-001/003 |
| | | | | 334C-6C:792-6972-001/003 |
| | | | | 334C-9A:622-2366-001 thru -006 |
| | | | | 334C-11:622-2366-003/004 |
| | | | | 334C-11:622-2733-001/002/003/004 |
| | | | | 334C-13:622-4585-001 |
| | | | | 334C-13A:622-4586-001 |
| | | | | 345C-2A:522-4399-002 |
| | | | | 351B-6:777-1062-001/003 |
| | | | | 351B-6A:792-6784-001/003/004 |
| | | | | 351B-6B:792-6785-001/002/003 |
| | | | | 351B-6C:792-6793-001/002/003 |
| | | | | 351B-6E:622-5299-001/002 |
| | | | | 351B-6F:622-5150-001/002 |
| | | | | 351B-6G:622-5151-001/002 |
| | | | | 351B-6H:622-5151-001/002 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|---|
| | | | | 351B-7B:792-6783-001 454N-2:622-2297-001 454N-2D:622-5375-001/003/004 562A-5M5:792-6703-001/003 562C-4:622-4600-001 562C-5:522-2900-001 thru -009/-013 thru -028/-114 562C-8A:777-1406-001 thru -008/010/ 011/012/018 thru -028/056 562C-8F:622-3167-001 thru -028/-041 thru -049 562C-13A:622-3593-002 562C-13A:622-3595-001/006/007 590A-3J1:622-4393-001/002/019 590A-3K1:622-4394-001/002 590E-1:622-5477-001 614E-23R:622-0945-003/006 614E-41:622-1210-001/002 614E-54:622-4966-001 913K-1A:622-3202-001/003/004/005/013 |
| TSO-C9c | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | AP-104 AP-105 AP-106/107 FD109H 161E-6 161H-1 327J-6A 327J-8 327D-5 326J-6() 327J-5 332D-12 334C-6() 334D-6 334C-9 345A-9 562C-13 562R-4 562S-3 562Y-4 562A-13 590A-3H 614E-4C 614E-20 614E-37 614E-27 614E-36 614E-39 614E-41 614E-42 913K-1 914G-3 916A-2 916A-3 916A-4 916A-5 916A-6 916B-2 991L-1 |
| TSO-C9c | Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | AAM-751():622-3802-() VGR-70:622-3618-001 FMC-28():622-3342-001 614E-42A:622-3891-001 |
| TSO-C9c | Columbia Research Laboratories, Inc. MacDade Blvd. & Bullens Lane Woodlyn, PA 19094 | NE | | SA 111128 |
| TSO-C9c | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 1U367-() 1U295E:1U295-()-() 4000C-2:1U262-008-30 4000C-3:1U262-009-31 1U371-() 1D755-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|-----------|--|
| TSO-C9c | Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067 | SW | | 1C714-() 52D136-() 52D137-() 1C709-() 1C718-() 1C722-() DG/NSD 360: 52D137-1332, -1333, -2331, -2334 1C727-() 1C497-() 1C543-() 1D496-() FD/AP 1C753-() 1D755-() 1C771-() 1C774-() 1D757-() 1D772-() 1C753-() 1C763-() 7011050 7003183-913 7008439 4066453-901,-902 |
| TSO-C9c | Group Technologies Corp. 10901 Malcolm McKinley Dr. Tampa, FL 33612 | CE-A | | AY311:7003227-() RZ220:4015901-() SP200:4008519-() SP600:4029377-() SP650:7000473-() SP711:4025008-() SP717:7004206-901 SZ400:7003180-() SZ600:7000254-() SZ601:7004187-() TZ701:7000298-901 |
| TSO-C9c | Gulton-Servonic A Mark IV Company 1644 Whittier Ave. Costa Mesa, CA 92627 | NM | | 4723A 451318AA 4723A() 451318AA-() 455318AA() |
| TSO-C9c | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. 5353 W. Bell Road Glendale, AZ 85308 | NM-L | | SG28 MG112 MG113 CG417 CG517 GC205A4/C4 FZ-600/800 SM-512 AN-701 7003974-() FZ-200:7003513-() FZ-450 FZ-400:7004126-901, -904, -908 FZ-450:7010680-903, -930 FZ-600/800: 7003974() FZ-700:7003183-922 FZ-703:7004383(), -904 FZ-710:7008138-() FZ-820:7003974-904 GC-300 GC-501 GC-600, -300, -501, -880: 7603975() GC-810 GC-880 GP-820 GH-14:4021541-691, 4021541-791 ID-800, -801, -802: 7003652() PC-400:7003897-() RG-204:7007453 RZ-710:7012693-() SM-300:7002260-821 SM-310:7004245-() SM-710:4012373-817 SM-725:7002800-914 SP-200:4008519-929 SPZ-200 SZ-400:7003180-908 SZ-411:7003180-908 TM-400:7003032-601 TM-420:7014600-903, -904, -913, -914 4066453-902 4006719-917 4015901-930 7005383-() 7007990-() 7009025-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|---|
| | | | | 7000299-909 7003183-912 7003974-603, -710, -714, -719, -720 7011050-801 thru -806, -813 thru -816, -825, -826, -901 thru -906, -913 thru -916, -925, -926 |
| TSO-C9c | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | GH-14 GH-14A SFG 980 SPZ-200 SP-50F VG-341 2586137-() 2589175-() 2597545 2587335-() 2592800-() 2592676-901 4011049-() 4031474-() 4034233-() 4040749-() 4046401-() 4048501-() 4019286-() 4012373-() 4015901-() 4018639-() 4025008-() 4015373-() 4015374-() 4029377-() 4031475-() 615743-27 615144-() 7000254-() 7000120-() 7001305-() 7001975-() 7000298-() 7000299-() 700473-() 7004126-() 7004187-() 7002800-() 7002260-() 7003100-() 7003227-() 7001931-() 7002541-() 7002542-() 7003032-() 7003183-() 7003245-() 7004305-() SZ-400:7003180-() SP717:7004206-() |
| TSO-C9c | Jet Electronics & Technology 5353 52nd St. Grand Rapids, MI 49508 | CE-C | | AD-102A AC-180() AC-500() AD-102B AL-299 AL-300 AC-530-() AC-535-() AV-500() AC-531():501-5174-() CA-500() CA-530() FC-200:SA-200(), AL-200(), AD-101(), FU-500C FU-372 FU-500D IA-535-() MS-535-() SA-141 SA-142 PC-500() RG-228() SA-151():501-1535-() SA-501():501-1263-() SA-503():501-1264-() YD-202(), AC-200(), IA-201(), CA-200() YD-502() YD-530-() YD-531:501-1552-() TS200-() ser 540-() |
| TSO-C9c | King Radio Corp. 400 N. Rogers Road P.O. Box 106 Olathe, KS 66061 | CE-W | | CG515 DG114() DG1009() DG1010() KAA-15 KA117:KPN065-5006-() KA136 KA152 KA154 KA185 KAC325 KAS297 KAS297B:065-0065-00/04 KAP315A KAP419 KAM432 KC190 KC191 KC192 KC292():065-0037-() KCP299 KCP220 KCP20 KCP420 KDA430:065-5030-00/-01/-02/-03/-04 KDC222 KDC298 KDC380 KDC381 KFC200 KFC300 KHC440 KHC441 KHC442 KMC221 KMC331 KMC442 KMS446 KRB434 KRG332 KS177 KS178 KS179 KSA370 KSA371 KSA373 KSA470 KSH375 KSM376 KSM475 KRG331 KRG332 KSS294 KTA435 KTA436 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|-----------|--|
| | | | | KVN-395 KVC350:060-0026-() KVG350:060-0026-() |
| TSO-C9c | Kollzman/IDC Avionics Group 170 Coolidge Ave. Englewood, NJ 07631 | NE | | 18210-() 18415() 17000-500 39380-() 40860-() |
| TSO-C9c | LearAvia Corp. 5980 Alpha Avenue Reno, NV 89506 | NM | | AFC-70:800002() AFS-70:800880-() YSAS-3:500-0001-() |
| TSO-C9c | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 5109() 345C-5 345C-5A 345C-5B 562T-1 562T-2 562P-4 |
| TSO-C9c | Motorola Aviation Electronics, Inc. Santa Monica, CA 90406 | NM | | M-4 |
| TSO-C9c *F | O.C.E.M. Avionica s.r.l. Via Canaletta 3/2 40050 Argelato (Bologna) Italy | EU | | AP-1-B AP-2-B AP-3-B |
| TSO-C9c | Rockwell International Avionics & Missiles Group 400 Collins Road, NE Cedar Rapids, IA 52406 | CE-W | | ATC-830A MAP-80() FCC-85B:622-7491-001 FCC-86B:622-7492-001 FCC-86C:622-7493-005/-008 FCC-86E MSP-85:622-6209-110, -111, -114 MSP-85A:622-6563-413 SMT-86A:622-6508-001/-002 SMT-86B:622-6509-001/-002 SMT-86C:622-6719-001/-002 |
| TSO-C9c | Rosemount, Inc. P.O. Box 35129 Minneapolis, MN 55435 | CE-C | | 1221G1() 542AV-() 1241S1 1221M1 |
| TSO-C9c | Schaevitz Engineering P.O. Box 505 Camden, NJ 08101 | NE | | LSXC0266 NAC-80:LSXC0266-020 |
| TSO-C9c *F | (S.F.E.N.A.) Societe Francaise d'Equipment pour la Navigation Aerieenne Aerodrome de Villacoublay P. O. Box 59 78140 Velizy Villacoublay France | EU | | 01.109 01-86()() 01-96()() 01-102()() 01-109()() 01-113()() CADV A6()() A62()() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|---|---|---|---|
| TSO-C9c *F | (S.F.I.M.) Societe de Fabrication d'Instruments de Mesure(s.a) 13 Ave. Ramolfo-Garnier 91301 Mussy France | EU | | GV 75-2 BSM Type 60 P/W 54-711 CDV-85() () () PA85E() () () PA85T(3)(1)() PA85E() () () PA85T() () () PA155D() () () PA155P() () () | CG52-2 | CG130-() |
| TSO-C9c | Smiths Industries SLI Avionic Systems Corp. 4141 Eastern Ave., S. E. Grand Rapids, MI 49518-8727 | CE-C | | 6502 7000E 2152L:140070-01-01 3335B:141300-01-02 7650B:140180-01-01 7650C:140540-01-01 9000C-():145974-01-03 :145974-01-04 | | |
| TSO-C9c | S-TEC Corporation Route 3, Building 945 Wolters Industrial Complex Mineral Wells, TX 76067 | SW | | 0110-() 0113-() 0116-() 0130-() 0140-() | 0110-T 0114-() 0117-() 0131-() 0141-() | 0110-TF 0115-() 0129-() 0132-() 0142-() |
| TSO-C9c | Systron-Donner Corp. Inertial Division 1090 San Miguel Road Concord, CA 94518 | NM | | 4311A-3-P82A 4384A-2-P33 | 4383A-5-P6 | |
| TSO-C10 *F | Aeritalia, S.p.A. Nerviano(Milan), Italy (Formerly Filotecnica Salmoiraghi) | EU | AIRCRAFT ALTIM., ALTIM., PRESSURE ACTUATED, SEN- SITIVE TYPE | 16030() 8.040.003 8.040.008.1 8.040.508 8.040.608 8.040.608.1.01 8.040.708 | 16050() 8.040.003.1 8.040.503 8.040.508.1 8.040.608.1 8.040.708.1 | 8.040.008 8.040.503.1 8.040.603 8.040.703 |
| TSO-C10 | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | | A-80-AAU-7A/A() | | |
| TSO-C10 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | G371 | | |
| TSO-C10 | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Hwy. So. Merrimack, NH 03054 | NE | | A3372 Ser. A32057-10-021 A44871-10-001 A4375() () () A42899-10-216 A4513()-()-() B3083() () () B4033 Ser. B4086() () () B4361()-()-() B25946-10-001 B37736-10-008 | A3872 B27546-10-001 B37736-10-022 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|--|--|--|--|
| | | | | 838119-10-001 | B38119-10-006 | |
| | | | | 838119-10-007 | B38119-10-008 | |
| | | | | B38119-10-010 | B38119-10-016 | |
| | | | | B38119-10-017 | B38119-10-026 | |
| | | | | 1845-4-06 | 2259X-4-01 | |
| TSO-C10 | Lear Siegler, Inc. Instrument Division 4141 Eastern Ave., S. E. Grand Rapids, MI 49508 | CE-C | | A0009() B0040() B0063-81100 B0063-81107 B0063-82103 B0070-14103 B0090-81107 B0090-81111 B0090-81114 B0090-81119 B0090-81123 B0090-81126 B0090-81129 B0090-82113 B0200-81104 C0001() C0060() C0060-84102 | B0020() B0060() B0063-81103 B0063-81108 B0070() B0090-81102 B0090-81108 B0090-81112 B0090-81115 B0090-81120 B0090-81124 B0090-81127 B0090-81130 B0090-82114 B0245() C0001-81103 C0060-81102 50001 | 0020-81112 B0060-81106 B0063-81104 B0063-81110 B0070-14102 B0090-81104 B0090-81109 B0090-81113 B0090-81117 B0090-81122 B0090-81125 B0090-81128 B0090-81131 B0200() B0247() C0001-84106 C0060-81106 |
| TSO-C10 *F | Tokyo Acft. Instrument Co. 1600 Izumu, Homae-machi Kitatama-gun, Tokyo, Japan | NH | | LA-4 LA-7 LA-71-1A LA-71-11F LA-72-11 LA-72-1C LA-72-11D | LA-44-11 LA-71-1 LA-71-11A LA-71-11G LA-72-1A LA-72-1D | LA-45-11 LA-71-11 LA-71-11C LA-72-1 LA-72-11A LA-72-11C |
| TSO-C10a | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | AIRCRAFT ALTIM., PRES- SURE ACTUATED, SENSITIVE TYPE | A-50-A | A-80-MA | |
| TSO-C10a | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Highway So. Merrimack, NH 03054 | NE | | A3199()() A28586-10-004 A30397-10-001 A32057-10-001 A32657-10-004 A32677-10-010 B25946-10-001 B29227-10-010 | | A28586-10-001 A29534-10-006 A30836-10-001 A32657-10-001 A32677-10-001 A33233-10-001 B27546-10-001 B2206()() |
| TSO-C10a *F | Smiths Industries Ltd. Aviation Division Bishops Cleeve, Cheltenham, Gloucestershire, England | EU | | 117AM/PC() | 130/1 AM/PC() | |
| TSO-C10b *F | Aeritalia, S.p.A. Nerviano(Milan), Italy | EU | AIRCRAFT ALTIM., ALTIM., PRES- SURE ACTUATED SENSITIVE TYPE | D22061() 16032() 16054() | 16031() 16052() | 16051() 16034() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|-----------|---|
| TSO-C10b | Aero Mechanism, Inc. 20327 Nordhoff Street Chatsworth, CA 91311-6161 | NM | | 8020 8047()Ser. 8060-() 8140-() 8200-() AR-800 8141B() 8111-X3XX() 8100-() 8112-M3XX() 8211-X3XX() 8142 8503-() 8048-() 8151B-() 8152B-() 8140B 8142B 8161B-() |
| TSO-C10b | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 34618 | CE-A | | A-2-CM AB/A-10-3 AB/A-10-4 A-20() A-20-H A-20-H-10 A-20-CM A-20-ILD() A-35() A-35-MA A-35-MA-10 A-35-MA-10L A-35-AAU-8A/A() A-50-H A-50-AAU-7A/A-6 A-50-MA-3 A-50-AAU-8A/A() A-50-MA-4 A-50-MA-16 A-80 A-80-AAU-7/A A-80-AAU-8A/A A-80-AAU-8/A A-80-AAU() AR15-M() AR25-MA() AR35-MA() AR50-MA() 10050-0102 10020() 10035() 10180() 10225() 10250() 10450() 10550() 101025() 101235() 101250() 101020-() 101220() 101420-() 101435-() 101450-() 101535-() 101550-() 101617-() 101627-() 101635-() 101720-() 101730-() 101735-() 101750-() 102200-() 10460-11880 10460-11884 10460-11938 11653-1149 11653-1150 16450() 16550() |
| TSO-C10b | Aerosonic Corporation Dallas Division 3312 Wiley Post Road Carrollton, TX 75006 | SW | | 1301-() |
| TSO-C10b | Aircraft Instrument & Development, Inc. 317 Lewis St. Wichita, KS 67202 | CE-W | | 37-1001-() |
| TSO-C10b | AMETEK/U.S. Gauge 900 Clymer Ave. Sellersville, PA 18960 | NE | | AW2832AE01 |
| TSO-C10b | Avionix Corporation 8 Romanelli Avenue South Hackensack, NJ 07606 | EA | | 2D440-(XXXXXX) |
| TSO-C10b | Bendix/King General Aviation Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | KAV 485:066-3077-00 thru -07, -10 066-3077-17, -20 thru -27, -28 066-3077-30 thru 37 KDC 481:065-0082-02, -04 |
| TSO-C10b | Clifton Division Litton Systems, Inc. 5100 State Rd. Drexel Hill, PA 19018 | NE | | 9602-10-() () 9802-07() () 9802-15() () |
| TSO-C10b | Clifton Precision Instr. & Life Support Div. 2734 Hickory Grove Rd. Davenport, IA 52808 | CE-W | | 3252013-() 3252014-() 3252027-() 3252028-() |
| TSO-C10b | Collins General Avn. Div. | CE-A | | ADC-80B:622-8070-099,-345 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|---|
| | Rockwell International Melbourne Operations 1100 West Hibiscus Ave. Melbourne, FL 32901 | | | ADC-80H:622-365-022/203/204/205/207/208/ 211/213/220/221/225/310/324 ADC-80J:622-5206-014/017/022/027 ADC-80K:622-5465-209/214/215/217/222/227/ 228/310/326 ADC-80M:622-2704-022 ADC-81A:622-4401-001 ADC-82L:622-8105-012, -013, -099, -399 ALI-80:622-2292-001 thru -008 ALI-80A:622-3975-001 thru -008 ALI-80M:622-2701-001/-011 thru -018 |
| TSO-C10b | Collins Avionics Div. Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52498 | CE-W | | ADC-62L ADC-82C ADC-80N ADC-80R ADC-81A ADC-86 ADS-80 ADS-80F ADC-80H:622-4365-537 ADS-81 ADC-80Q:622-7577-555, -556 ADC-82A:622-6475-021 ADC-85:622-8051-002 ADC-850:622-7208-002 ADM-85:622-8692-002 thru -006, -011 ADM-86:622-9282-002, -004 ADM-850:622-7737-002, -007 ALI-80 ALI-80A ALI-80B ALI-80L ALI-80M ALI-850A:622-8334-001, -002, -003 ALI-850B:622-9238-001, -002, -011, -012 ALI-850C:622-9751-001, -002 ARP-850:622-9292-001, -002 ASI-850A ASI-850A:622-8335-001, -002, -003, -010, -011, -012 ADM-850 ASP-1000 ADM-86 DU-1000:622-7484-411 DCP-1000 |
| TSO-C10b | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 1U306 1U309 375A 375B |
| TSO-C10b | Hamilton Standard, Div. of United Aircraft Corp. Windsor Locks, CT 06096 | NE | | HSA 101:748430-() HSA102:748430-() |
| TSO-C10b | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Systems Div. P.O. Box 21111 Phoenix, AZ 85036-1111 | NM | | HG280D-() |
| TSO-C10b | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | 2594620-() 4005123-() 4019953-() 4039892-() 4016341() HG280D-() HG280D80-() HG4808-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|---|--|---------|
| TSO-C10b | Instrument & Flight Research, Inc. 2716 George Washington Blvd. Wichita, KS 67210 | CE-W | | E41-20 IFR 41:5934-() IFR-46-20 | E41-25 IFR-46-20M | E41-34 |
| TSO-C10b | Instrument Technology Corp. P. O. Box 20478 Dallas, TX 75229 | SW | | 1301-() | | |
| TSO-C10b | Karnish Instrument, Inc. 210 Third Ave. Lock Haven, PA 17745 | NE | | AC-157, Type | I | |
| TSO-C10b | King Radio Corporation 400 N. Rogers Road Olathe, KS 66062 | CE-W | | ADC-82C KAS-489 | KAV-485 | KDC-481 |
| TSO-C10b *F | Kollsman Instrument Limited Southampton, Hampshire England | EU | | L.8312()-() ()-() () () L.8344()-() ()-() () () L.8345()-() ()-() () () | | |
| TSO-C10b | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Hwy. So. Merrimack, NH 03054 | NE | | 4515() () () ()4550()-()-() ()4552()-()-() ()4553()-()-() ()4580()-()-() ()4581()-()-() ()4583()-()-() ()4584()-()-() ()4619() () A2916() () () A3488 Ser. A3636 Ser. A3742 Ser. A4016() () () A4031() () () A4186() () () A4430() () () A4545()-()-() A28586-10-001 A30837-10-001 A30837-10-021 A31626-10-001 A32657-10-001 A32677-10-001 A33793-10-007 B3623() () () B3774 Ser. B3775 Ser. B3904 Ser. B4154() () () B4420() () () B4545()-()-() B27546-10-001 B37736-10-006 C3868() () () C4035() () () D2206() () () KS200-() | A3199() () () A3549() () () A3868() () () A4017() () () A4086() () () A4407() () () A4448() () () A18586-10-004 A30397-10-010 A30837-10-004 A31616-10-001 A32506-10-004 A32657-10-006 A33014-10-008 A42899-10-016 B3733() () () B3868() () () B4035() () () B4361() () () B4451() () () B25946-10-001 B29227-10-001 B43921-10-226 C3904() () () C30077-10-018 E4245() () () | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|--|---|---|
| TSO-C10b | Kollzman/IDC Avionics Group 170 Coolidge Ave. P.O. Box 81 Englewood, NJ 07631 | NE | | 15790L 17000-() 23080-() 25005-() 28007-() 29007-() 29020-() 30510-() 33932-() 28704-() 48711-() 33934-() 37630-() 48707-() 40400-() | 16000-() 18210-() 23932-() 519-22701-() 28702-() 29702-() 38007-() 39711-() 31400-() 49711-() 32979-() 38620-() 36920-() 49707-() 34929-() | 16007-() 18711-() 24929-() 28711-() 29711-() 39007-() 32935-() 29704-() 34100-() 29790-() 46000-() 39499-() 41707-() |
| TSO-C10b *F | Leigh Instruments Ltd. Carleton Place Ontario, Canada | NE | | LE300: | 01-200-102 | 01-200-103 |
| TSO-C10b | MacLeod Instrument Corp. Sub. of Aeronomic Corp. P. O. Box 5163 Clearwater, FL 33518 | CE-A | | 120() 1250() | 135() 1335() | 1235() 1350() |
| TSO-C10b | Precise Devices Company 1889 Palace Drive Clearwater, FL 34616 | SO | | 10490 | | |
| TSO-C10b *F | Shinko Electric Co., Ltd 42-, 3-Chome Mallore Kanagawa-Prefecture, Japan | NM | | SEA-1:1434 SEA-21:1432M | SEA-1:1432 | SEA-11:1434M |
| TSO-C10b | Sigma Tek, Inc. 17621 N. BlackCanyon Hwy. Phoenix, AZ 85023 | NM | | 401A | 801A | |
| TSO-C10b | Smiths Industries SLI Avionic Systems Corp. 4141 Eastern Ave., S. E. Grand Rapids, MI 49518-8727 | CE-C | | 80063() 80072() 80090-81101 80090-81137 4442A4 80063-():81101, 81103, 81104, 81106, 81107, 81108, 81109, 81110, 81111, 81112, 81114, 82103, 82109, 80070-():14102, 14103, 80072-():81101, 81102, 81103, 80090-():81101, 81105, 81111, 81128, 81137, 81138 4440A1:314200-01-01 4440A2:314200-02-01 4440A3:314200-03-01 4440A4:314200-04-01 4440A5:314200-05-01 4440A6:314200-06-01 4440A7:314200-07-01 4440A8:314200-08-01 4440A17:314200-17-01 4440A18:314200-18-01 4440A19:314200-19-01 4440A20:314200-20-01 4441A1:314201-01-01 4441A2:314201-02-01 4441A3:314201-03-01 4441A4:314201-04-01 | 80063-81106 80072-81103 80090-81105 4441A 4440A4 | 80070-14103 80090() 80090-81110 4440A4 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|--|----------------------------|--------------|--------------|
| | | | | 4442A1:314202-01-01 | | |
| | | | | 4442A2:314202-02-01 | | |
| | | | | 4442A3:314202-03-01 | | |
| | | | | 4442A4:314202-04-01 | | |
| | | | | 4442A5:314202-05-01 | | |
| | | | | 4442A6:314202-06-01 | | |
| | | | | 4442A7:314202-07-01 | | |
| | | | | 4442A8:314202-08-01 | | |
| TSO-C10b | Smiths Ind. Aerospace & Defense Systems, Inc. Harrowe Division 255 Great Valley Parkway Malvern, PA 19355 | NE | | 2050-01-1 | 2050-04-01 | 2050-08-01 |
| | | | | 2050-10-1 | 2051-03-1 | 2051-04-1 |
| | | | | 2054-01-1 | 2055-01-1 | 2056-01-1 |
| | | | | 2057-01-1 | 2057-02-1 | 4019-01 |
| | | | | 4019-02 | 4019-05 | 4030-01 |
| | | | | 4030-03 | 4030-03-1 | 4030-03-2 |
| | | | | 4030-04 | | |
| TSO-C10b *F | Smiths Industries, Ltd. Aviation Division Bishops Cleeve Cheltenham, Gloucestershire England | EU | | 139AM | 701AM/() | 706AM/() |
| | | | | 708AM/() thru 749AM/() | | 1105AM/() |
| | | | | 804AM thru 849AM | | 1106AM/() |
| | | | | 1102AM/() thru 1104AM/() | | 1109AM/() |
| | | | | 1110AM/() | 1112AM/() | 1113AM/() |
| | | | | 1350AM/() | 1401AM/() | 1403AM/() |
| | | | | 1404AM/() | 1407AM/() | WL/1701AM() |
| | | | | WL1801AM() | WL1802AM | WL1152AM() |
| | | | | WL101AMS() | WL102AMS() | WL1605AM() |
| | | | | WL1107AM() | WL1704AM() | |
| | | | | WL875AM() | WL1307AM() | |
| TSO-C10b *F | Smiths Industries Ltd. Cheltenham, Gloucestershire United Kingdom | EU | | 1750AM() | | |
| | | | | 1190AM() | | |
| TSO-C10b *F | Thomson-CSF 31 rue Camille Desmoulins 92131 Issy-les-Moulineaux France | EU | | 64111-3()-() | | |
| | | | | 64141-3()-() | | |
| | | | | 64142-5()-() | | |
| | | | | 64111-9()-() | | |
| | | | | 64141-5()-() | | |
| TSO-C10b *F | Tokyo Acft. Instr. Co., Ltd. 35-1, Izumi-Honcho 1-Chome Komae-shi, Tokyo 201, Japan | NM | | LK-35 | LK-35-4 | LK-35-5 |
| | | | | LK-35-7 | LK-35-8 | LK-35-9 |
| TSO-C10b | United Instruments, Inc. 3625 Comotara Avenue Wichita, KS 67210 | CE-W | | 5934-()-() | 5035-()-() | 5500-() |
| | | | | 5506L-S()()1() | | |
| | | | | 5506L-S()()2 | | |
| TSO-C11 | Control Products, Inc. Harrison, NJ 07029 | NE | FIRE DETECTORS (THERMAL SEN- SING AND IONI- ZATION SENSING TYPES) | ASA-12-1 | BSA-4 | |
| TSO-C11 | Graviner, Inc. 1121 Bristol Rd. Mountainside, NJ 07092 | NE | | 390D | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|----|--|---------------------------------|---------------------------|---------------|
| TSO-C11 | Walter Kidde & Co., Inc. 675 Main St. Belleville, NJ 07109 | NE | | Control: | 893410 | |
| | | | | Sensing: | 704043 | 705078 |
| | | | | 727120 | 785125 | 805313 |
| | | | | 805314 | 805320 | 805325 |
| | | | | 805329 | 805330 | 805316 |
| | | | | 842759 | 872278 | 872281 |
| | | | | 872289 | 872293 | 872294 |
| | | | | 872295 | 874394 | 874397 |
| | | | | 874401 | 875126 | 875127 |
| | | | | 875128 | 875129 | 894873 |
| | | | | 894876 | 894981 | 895004 |
| | | | | 895030 | 895031 | 895297 |
| | | | | 895298 | 895299 | 895267 |
| | | | | 895268 | 895312 | 895387 |
| | | | | 895389 | 895390 | 895396 |
| | | | | 895397 | 895899 | |
| TSO-C11 | Wilcolator Company Elizabeth, NJ 07207 | NE | | C-5900 | | |
| TSO-C11a | American Machine & Foundry Boston, MA 02109 | NE | FIRE DETECTORS (THERMAL SENSING AND IONIZATION SENSING TYPES) | 1071-A | 1071-B | |
| TSO-C11a | Fenwal, Inc. 400 Main St. Ashland, MA 01721 | NE | | 35000 Ser. | 17343-35 | |
| TSO-C11a *F | Graviner (Colnbrook) Ltd. Poyle Road Colnbrook, Slough, Buckinghamshire, England | EU | | Control Units, Conduction | D879() D1200() D1760() | |
| | | | | Accessories, Conduction | D826() D828() D949() | |
| | | | | D2087() | | |
| | | | | Elements or Sensors, Conduction | | |
| | | | | D890() | D891() | D938() |
| | | | | D938/N() | D939() | D939/N() |
| | | | | D989() | D989/N() | D1385() |
| | | | | D1870() | D1870/N() | D1871() |
| | | | | D1871/N() | D2369/20() | D2369/30() |
| | | | | D2369/60() | D2369/120() | D2371() |
| | | | | D2372() | | |
| TSO-C11a | McGraw-Edison Co. Edison Electronics Div. Grenier Municipal Airport Manchester, NH 03103 | NE | | Detection: | 297-115-() | 297-11522-() |
| | | | | Sensing: | 234-54G | |
| TSO-C11a | A. C. Palmer Research Corp. Los Angeles, CA 90052 | NM | | 1096 | | |
| TSO-C11a | Walter Kidde & Co., Inc. 675 Main St. Belleville, NJ 07109 | NE | | D-19 D-30-0 | D-20 | D-30 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|----|--|---|---|---|
| TSO-C11b | Fenwal, Inc. 400 Main St. Ashland, MA 01721 | NE | FIRE DETECTORS (THERMAL SENSING AND IONI- ZATION SENSING TYPE) | 17343-771-XXX 17343-831 | 17343-781-XXX | |
| TSO-C11b *F | Graviner (Colnbrook) Ltd. Poyle Road Colnbrook, Slough, Buckinghamshire, England | EU | | Accessories, D2447() Type 51291-120 | Conduction D2450() | D2475 |
| TSO-C11b | McGraw-Edison Co. Edison Electronics Div. Grenier Municipal Airport Manchester, NH 03103 | NE | | Detection: Sensing: 244-XXX42 294-XXX13 | 297-11522-() 244F-() 244-XXX82 294-XXX43 | 244-XXX12 294F-() 294-XXX83 |
| TSO-C11b | Walter Kidde & Co., Inc. 675 Main St. Belleville, NJ 07109 | NE | | Control: 890700 | 871511 891234 | 890350 891491 |
| TSO-C11d | Armtec Industries, Inc. Manchester Municipal Airport Manchester, NH 03103 | NE | FIRE DETECTORS (THERMAL SENSING AND IONIZATION SENSING TYPE) | 227-() 324-() 644-() | 244-() 377-() 677-() | 294-() 477-() |
| TSO-C11d | Armtec Industries, Inc. Edison Electronics Division Manchester Municipal Airport Manchester, NH 03103 | NE | | 477 | 644 | |
| TSO-C11d | Fenwal, Inc. P.O. Box 309 400 Main St. Ashland, MA 01721 | NE | | 17343-61-450 17343-108 17343-509 35009-15 35008-13, -32, | 17343-62-450 17343-501 35009-() 35805-0 -43, -44, -45 | 17343-61 17343-505 35009-12 |
| TSO-C11d *F | Graviner (Colnbrook) Ltd. Poyle Road Colnbrook, Slough, Bucks Buckinghamshire, England | EU | | Control Units, 166D() 390D() 335D() WL1801AM Control Unit 193D-03 51653-122, -124 Accessories, D3131() D5653() Cable Connectors 51444-123 51444-127 51444:137 & 138 51444-144, -145 Cable Harness 51315-102 51315-105 Elements, Triple FD Specified D3894() D889/N() D1384/N() D2370/60() | Triple FD 167D() 391() WL1802AM 51653-120 -154 Triple FD D3170() D5922() 51444-124 51444-129 51315-103 51315-106 D6489() D890/N() D2370/20() D2370/89() | 186D() 391D-1() WL1152AM() 51444-126 51444-130 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|----|-----------|--|
| | | | | D4176/M() D5020() D5025() D5030() D5121() D5122() D5123() D6187() D6401() D6486() D6487() D6488() 51216-001 51216-002 51216-070() 51226-070() 51236-070() 51216-093 51216-094 51236-001 51236-002 51236-003 51236-071() 51236-072() Firewire Assemblies 51291-013 51291-014 51291-015 51291-016 51291-017 51291-018 51291-025 51291-026 51291-027 51291-028 51291-029 51291-030 51291-040 51291-051 51291-052 51291-067 51291-065 51291-066 51291-105 51291-111 51291-112 51291-113 51291-114 41164-239 41164-240 41164-242 51444-2XX Series 201 thru 206 51444-3XX Series 301 thru 308 51444-4XX Series 401 thru 404 51653-114 Detection 51653-151 51653-027 51653-152 51653-154 Control Units 41164-239 41164-240 41164-242 51216-093 51216-094 51444-144 51444-145 |
| TSO-C11d | Graviner, Inc. 1121 Bristol Rd. Mountainside, NJ 07092 | NE | | 391D-1 |
| TSO-C11d *F | Graviner Ltd. Colnbrook, Slough Bucks, United Kingdom | EU | | 51653-176-02 51291-124, -125 |
| TSO-C11d *F | Kidde-Graviner Ltd. Colnbrook, Slough, Berkshire SL3 0HB United Kingdom | EU | | 51291-151, -152, -153, -154, -155, -156, -157, -158, -159, -160, -161, -162, -163, -164, -165, -166, -167, -168 -169, -170, -171, -172, -173, -174, -175, -176, -178, -179, -180 51218-014/246 51228-014/246 51238-014/246 51653-177 |
| TSO-C11d | McGraw-Edison Co. Edison Electronics Div. Grenier Municipal Airport Manchester, NH 03103 | NE | | Detection Control: 324-02808 324-02809 324-02810 377-02808 377-02826 377-02828 377-02829 377-02833 377-02836 Sensing: 244-(----)5 244-(----)6 244F-70G-() 244-(XXXX)3 244-(XXXX)4 294F-70F-() |
| TSO-C11d *F | Louis l'Hotelier Company 10 rue de l'Abbe-Gatz 92270 Bois-Colombes France | EU | | Type B() Type D() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|----|-----------|---|
| TSO-C11d | McGraw-Edison Co. Edison Electronics Div. Grenier Municipal Airport Manchester, NH 03103 | NE | | Detection: 227-28-() 324-02805-() 324-0806-() 324-02807-() 377-115-() 377-11522-() 377-11523-() 377-02810 377-02808 377-02801 377-02829 377002833 Sensing: 244C-() 244F-54G-() |
| TSO-C11d | Safety Systems Div. Systron-Donner Corp. 1440 Fourth St. Berkeley, CA 94710 | NM | | Sensing: 802-DRB 803BIT 801 801() Ser. 801-D 801-DH 801-DRH 801-DRS 801-FS 801-GS 801-MS 801-US 809-() Ser. 809-A 809-B |
| TSO-C11d | Systron Donner Safety System Division 2731 Systron Drive Concord, CA 94518 | NM | | Detector 801-RDS |
| TSO-C11d | Walter Kidde & Co. Inc. 675 Main St. Belleville, NJ 07109 | NE | | Detection Control: 892121 892294 892478 892809 893229 893382 893572 893877 894090 894105 894926 894943 895899 896167 892121-0350 896586 897080 898087 899172 895911-01 896390 896912 896913 896914 896390-0250 892561 896586 Sensing: 700XXX 701XXX 702XXX 703XXX 704XXX 705XXX 716XXX 726041 712001 thru 712240 716052 760048 760062 760074 776162 776240 805303 805304 805305 805307 805324 876640 876641 874683 876894 876895 876903 876882 876883 876900 876885 876895 876903 877011 894875 894885 894938 894939 894980 895398 895439 895654 895693 895694 895695 895926 896413 896414 896415 896416 896901 896902 896912 896913 896914 896917 896918 896934 897628 897504 897505 896770 thru 896775 896390-0250 896440 894926 896900 896951 897807 Sensing Element: 876904 876905 895983 896916 896951 897807 898462 472163 472164 472165 472166 472177 472178 472179 472180 472262 472263 472264 472265 472266 472305 472306 472565 472566 472567 472568 472569 472570 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|-----------------------|------|-----------|------------------------|
| | | | | 472571 472572 472573 |
| | | | | 472574 472575 472576 |
| | | | | 472577 472578 472579 |
| | | | | 472580 472585 472586 |
| | | | | 895004 895312 895980 |
| | | | | 896374 896375 896802 |
| | | | | 896803 898418 898419 |
| | | | | 898450 898451 898452 |
| | | | | 898453 898732 898737 |
| | | | | 898738 899185 899186 |
| | | | | 899280 899281 899287 |
| | | | | 899288 899289 899290 |
| | | | | 899344 899978 |
| | | | | 21700100 to 21730000 |
| | | | | 21800100 to 21830000 |
| | | | | 21900100 to 21930000 |
| | | | | 2200100 to 22030000 |
| | | | | 22100100 to 22130000 |
| | | | | 22200100 to 22230000 |
| | | | | 22300100 to 22330000 |
| | | | | 22400100 to 22430000 |
| | | | | 22500100 to 22530000 |
| | | | | 22600100 to 22630000 |
| | | | | 22700100 to 22730000 |
| | | | | 22800100 to 22830000 |
| | | | | 23300100 to 23330000 |
| | | | | 23400100 to 23430000 |
| | | | | 23500100 to 23530000 |
| | | | | 23600100 to 23630000 |
| | | | | 23700100 to 23730000 |
| | | | | 23800100 to 23830000 |
| | | | | 23800100 to 23830000 |
| | | | | 23900100 to 23930000 |
| | | | | 24000100 to 24030000 |
| | | | | 24100100 to 24130000 |
| | | | | 24200100 to 24230000 |
| | | | | 24300100 to 24330000 |
| | | | | 24400100 to 24430000 |
| | | | | 24500100 to 24530000 |
| | | | | 24600100 to 24630000 |
| | | | | 24700100 to 24730000 |
| | | | | 24800100 to 24830000 |
| | | | | 24900100 to 24930000 |
| | | | | 25000100 to 25030000 |
| | | | | 25100100 to 25130000 |
| | | | | 25200100 to 25230000 |
| | | | | 25300100 to 25330000 |
| | | | | 25400100 to 25430000 |
| | | | | 25500100 to 25530000 |
| | | | | 25600100 to 25630000 |
| TSO-C11d | Walter Kidde | CE-A | | 472094 472163 472164 |
| | 2500 Airport Drive | | | 472056 472059 472165 |
| | Wilson, NC 27893-9643 | | | 472166 472177 472178 |
| | | | | 472179 472180 472260 |
| | | | | 472262 472263 472264 |
| | | | | 472265 472266 472299 |
| | | | | 472305 472307 472565 |
| | | | | 472566 472567 472568 |
| | | | | 472569 472570 472571 |
| | | | | 472572 472573 472574 |
| | | | | 472575 472576 472577 |
| | | | | 472578 472579 472580 |
| | | | | 472581 472582 472583 |
| | | | | 472584 472585 472586 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|------------------------|
| | | | | 472619 |
| | | | | 472094 |
| | | | | 472925 |
| | | | | 472933 |
| | | | | 895004 |
| | | | | 896373 |
| | | | | 896383-05 |
| | | | | 896803 |
| | | | | 898419 |
| | | | | 898452 |
| | | | | 898737 |
| | | | | 899094 |
| | | | | 899251 |
| | | | | 899280 |
| | | | | 899287 |
| | | | | 899290 |
| | | | | 899321 |
| | | | | 899978 |
| | | | | 21700100 to 21730000 |
| | | | | 21800100 to 21830000 |
| | | | | 21900100 to 21930000 |
| | | | | 22000100 to 22030000 |
| | | | | 22100100 to 22130000 |
| | | | | 22200100 to 22230000 |
| | | | | 22300100 to 22330000 |
| | | | | 22400100 to 22430000 |
| | | | | 22500100 to 22530000 |
| | | | | 22600100 to 22630000 |
| | | | | 22700100 to 22730000 |
| | | | | 22800100 to 22830000 |
| | | | | 23300100 to 23330000 |
| | | | | 23400100 to 23430000 |
| | | | | 23500100 to 23530000 |
| | | | | 23600100 to 23630000 |
| | | | | 23700100 to 23730000 |
| | | | | 23800100 to 23830000 |
| | | | | 23900100 to 23930000 |
| | | | | 24000100 to 24030000 |
| | | | | 24100100 to 24130000 |
| | | | | 24200100 to 24230000 |
| | | | | 24200100 to 24330000 |
| | | | | 24400100 to 24430000 |
| | | | | 24500100 to 24530000 |
| | | | | 24600100 to 24630000 |
| | | | | 24700100 to 24730000 |
| | | | | 24800100 to 24830000 |
| | | | | 24900100 to 24930000 |
| | | | | 25000100 to 25030000 |
| | | | | 25100100 to 25130000 |
| | | | | 25200100 to 25230000 |
| | | | | 25300100 to 25330000 |
| | | | | 25400100 to 25430000 |
| | | | | 25500100 to 25530000 |
| | | | | 25600100 to 25630000 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---------------------------|--|--|--|
| TSO-C12 | Air Cruisers Company P. O. Box 180 Belmar, NJ 07719 | NE | LIFE RAFTS (TWIN TUBE) | 2910 3110 3200 3616 12D11725-() 12D11726 14D23040-() 15D23174() 17D11758-14 17D11758-17 17D11758-20 18D23350-4 | 2915 3115 3311 11D11141 12D11804 14D23041-6 17D11758-12 17D11758-15 17D11758-18 17D11758-21 21D23541 | 2920 3120 3400 12D11504 14D23004 14D23081-() 17D11758-13 17D11758-16 17D11758-19 17D11758-22 D23835-() |
| TSO-C12 | American Safety Inflatable Survival Systems 7000 N.W. 46th Street Miami, FL 33148 | CE-A | | M-20 PAR-20 | PAR-10 | PAR-15 |
| TSO-C12 | B. F. Goodrich Engineered Products Div. P.O. Box 340 Troy, OH 44318 | CE-C | | 10-man | 15-man | 20-man |
| TSO-C12 | Switlik Parachute Co. Inc. 1325 E. State St. P. O. Box 1328 Trenton, NJ 08607 | NE | | SPC-SA-10-002 SPC-SA-25002-2 SPC-SA-25002-4 | SPC-SA-20-002 SPC-SA-25002-3 | |
| TSO-C12a | Air Cruisers Co. P.O. Box 180 Belmar, NJ 07719 | NE | LIFE RAFTS (TWIN TUBE) | 12D11758 14D23040 | 13D11905-() 14D23041-() | 13D23004 |
| TSO-C12b | Air Cruisers Co. P. O. Box 180 Belmar, NJ 07719 | NE | LIFE RAFTS (TWIN TUBE) | 12D11769 14D23100 | 14D23077 15D23177 | 14D23081 |
| TSO-C12b | American Safety Inflatable Survival Systems P.O. Box 480213 7000 N.W. 46th Street Miami, FL 33148 | CE-A | | C-10() | C-20() | C-25() |
| TSO-C12b *F | Beaufort (Air-Sea) Equip. Ltd. Beaufort Road Birkenhead, Cheshire, England | EU | | 26V/A3.25 Person | | |
| TSO-C12c | OBSOLETE (See TSO-C70a) | | | | | |
| TSO-C13 | Air Cruisers Co. P. O. Box 180 Belmar, NJ 07719 | NE | LIFE PRESERVERS | AD-1 AD-4 CH-1 | AD-2 AD-5 CH-2 | AD-3 INF-1 CH-3 |
| TSO-C13 | L. W. Foster Sportswear Co. Philadelphia, PA 19104 | NE | | L.W.I. | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|--------------------|---|---|---|
| TSO-C13 | Goodyear Tire & Rubber Co. 1210 Massilon Road Akron, OH 44316 | CE-C | | Navy Mark II | | |
| TSO-C13 | McLean Manufacturing Co. Passaic, NJ 07055 | NE | | MV-101 MV-104 | MV-102 MV-106 | MV-103 |
| TSO-C13 *F | Mitsubishi Electric Corp. 2-2-3 Marunouchi, Chiyada-ice Tokyo, Japan | NM | | MC-3 M150094 | | |
| TSO-C13 *F | RFD-GQ Limited Catteshall Lane Godalming, Surrey England | EU | | 97 Mk.1.() | | |
| TSO-C13c | Air Cruisers Co. P. O. Box 180 Belmar, NJ 07119 | NE | LIFE PRESERVERS | AD-4B AD-4H D21280 D21290 D21320 D21344 D21343-() D21352() 24D21233 24D21240 24D21255 25D21262 25D21269 25D21278 | AD-4C CH-2A D21282 D21312-() D21339 D21348 D21344() 24D21237 24D21251 25D21260-() 25D21265 25D21270 | AD-4E AD8E D21285 24D21232 D21343 D21349() D21351() 24D21238 24D21254-() 25D21261 25D21268 25D21271 |
| TSO-C13c | American Safety Inflatable Survival Systems P.O. Box 480213 7000 N.W. 46th Street Miami, FL 33148 | CE-A | | H2-L8 H8-L8() JUV-1() M2-L8 M5-L8 VS35()-L8 | H3-L8 H35-L8 M-3 M3-L8 PV-1 JUV-1L8() | 8H-() H47-L8 M-1 M4-L8 PV-1C VS35(1)-68 |
| TSO-C13c *F | A/S Nordisk Gumnibadsfabrik Postbox 3060 6700 Esbjerg Denmark | EU | | 35-20-01 35-21-02 | 35-23-04.1 | 35-23-04 |
| TSO-C13c *F | Balloonfabrik See-und Luftausrustung GmbH & Co. Ausstrasse 35 8900 Augsburg Germany | EU | | bfa-WL1 | | |
| TSO-C13c *F | Beaufort (Air-Sea) Equipment Ltd. Research & Develop. Div. Hunt Lane, Chadderton Oldham, Lancashire, England | EU | | MK.3 | MK.12 | |
| TSO-C13c *F | Beaufort Air-Sea Equipment, Ltd. Birkenhead, Merseyside England | EU | | Type 21 MK.23 (Adult and child) MK.27 | "Infant" MK.22 | |
| TSO-C13c | B.F. Goodrich Co. Bldg. 41-B, Dept. 1833 | CE-C | | SSV1027 | SSV1042 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|---|-------------------|----------------------------|
| | 500 South Main Street Akron, OH 44318 | | | | | |
| TSO-C13c | B.F. Goodrich Eng. Sys. Co. 500 South Main Street Akron, OH 44318 | CE-C | | 5SV1019 | 5SV1025 | 5SV1046 |
| TSO-C13c | Cline & Associates, Inc. P. O. Box 12285 Raleigh, NC 27605 | CE-A | | CP-100() | CP-110() | CP-410 |
| TSO-C13c | Eastern Aero Marine P. O. Box 593513 Airport Mail Facility Miami, FL 33159 | CE-A | | KS-9:P/W P0101-() KS-16 KS-35()-L8:P/W P0601-() KS-40()-L8 KSE35L8:P0723E105P, P0723E109P | | KS-12 CH-9:P0601-() |
| TSO-C13c | East Wind Industries 70 South Chapel St. Newark, DE 19711 | NE | | MD-1() | MD-2 | MD-3 |
| TSO-C13c | East Wind Industries, Inc. 800 Delaware Avenue Penthouse Suite Wilmington, DE 19801 | NE | | MD-6() | | |
| TSO-C13c | Emergency Systems Inter'l 7940 John Towers Ave. Gillespie Airport Santee, CA 92071 | NM | | 2000200-() Ser. | | |
| TSO-C13c | Hoover Industries, Inc. P.O. Box 522337 Miami, FL 33166 | CE-A | | FV-35E:3505-() | | |
| TSO-C13c *F | Irvin Maniffatture Industrial S.P.A. Cosella Postale 19 04011 Aprilia (LT) Italy | EU | | IMI 2.7.18 IMI 2.7.23/() | IMI 2.7.19 () | IMI 2.7.23 IMI2.7.34() |
| TSO-C13c | Jay-El Products, Inc. Gardena, CA 90247 | NM | | JLA-1 JLC-2 | JLA-2 JLC-3 | JLA-3 JLC-4 |
| TSO-C13c | J.C.R. Industries Inc. Part not manufactured | NM | | | | |
| TSO-C13c | MARAVIA Corporation 857 Thornton Street P. O. Box 395 San Leandro, CA 94577 | NM | | 2000200-() 6000100-() | 3000100-() | 5000100-() |
| TSO-C13c *F | Mitsubishi Electric Corp. 2-2-3 Marunouchi, Chiyoda-ku Tokyo, Japan | PC | | MC-38:M253322 | | |
| TSO-C13c *F | RFD-GO Ltd. Catteshall Lane Godalming, Surrey, England | EU | | 97MK1() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|--------------------|--|---|---------------------------------|
| TSO-C13c *F | RFD Inflatables, Ltd. Godalming, Surrey England | EU | | 105 Mk. 1 | | |
| TSO-C13c | RFD-Patten, Inc. P.O. Box 31 Lake Worth, FL 33450 | CE-A | | FP() | | |
| TSO-C13c | R.P.R. Industries, Inc. P.O. Box 30338 Raleigh, NC 27612 | CE-A | | CP-100 RPR-210 | CP-110 RPR-310 | CP-410 RPR-510 |
| TSO-C13c *F | Societe Aerozur 58 Bd. Gallieni 92130 Issy les Moullineaux France | EU | | C2()()() C3()()() | C2PN()()() C3PN()()() | |
| TSO-C13c | Soniform, Inc. - WITHDRAWN 10/30/89 El Cajon, CA 92020 | | | | | |
| TSO-C13c | Switlik Parachute Co. 1325 E. State St. P. O. Box 1328 Trenton, NJ 08607 | NE | | AV-2A & B AV-12A CV-1A & B EV-2A EV-2 H2L8:D-1261-() HCV-12 | AV-4A & B AV-2:S-9900 CV-2A & B EV-10A EV-12:S-9400 VS35()-L8:P/W D7017-() | AV-10A AV-4:S-9800 EV-12A |
| TSO-C13c *F | TUL Safety Equipment Ltd. 1432 Aberdeen Street Hawkesbury, Ontario Canada K6A 1K7 | NE | | 35, MK III:TUL-6154 35, MK IV:TUL-6174 UC):TUL-6175 | | |
| TSO-C13d | Air Cruisers Company P.O. Box 180 Belmar, NJ 07719 | NE | LIFE PRESERVERS | D21343-() D21349-() | D21344-() D21351-() | D21348-() D21352-() |
| TSO-C13d *F | A/S Nordisk Gumnibadsfabrik Postbox 3060 Esbjerg 6700, Denmark | EU | | 35-20-01 35-23-04 | 35-21-02 35-23-04.1 | |
| TSO-C13d | California Inflatables Co. 9820 East Rush Street South El Monte, CA 91733 | NM | | 35-(): 2DV1053-1 | | |
| TSO-C13d | Eastern Aero Marine P.O. Box 593513, AMF Miami, FL 33159 | CE-A | | KSD-35L8 | C8025L8 | IN-V20L8 |
| TSO-C13d *F | Fitz-Wright Suits Ltd. Surrey, B.C. Canada | EU | | FWS-10 | | |
| TSO-C13d *F | Irvin Manifatture Industriale S.P.A. Casella Postale 19 04011 Aprilia (LT) Italy | EU | | IM12.7.34() | | |
| TSO-C13d *F | RFD Aviation Godalming, Surrey England | EU | | Type 106 MK.1 Type 107 MK.1 | | |
| TSO-C13d | Switlik Parachute Company | NE | | AV-35: S-11xxx-(xxxx) | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|---|---|----------------------------|--------------------------|
| | 1325 East State Street P.O. Box 1328 Trenton, NJ 08607 | | | AV-35: S-11300-(), S-11350-() AV-40: S-12100-(xxxx), S-12150-(xxxx), S-12200-(xxxx), S-12250-(xxxx), S-12300-(xxxx), S-1250-(xxxx), S-12400-(xxxx), S-12450-(xxxx), S-12550-(xxxx) ILV-20: S-10000-(xxxx) S-11600-(XXXX) S-11650-(XXXX) HV-35C:S-7200, S-9400 | | |
| TSO-C13d *F | TUL Safety Equipment, Ltd. 1432 Aberdeen Street Hawkesbury, Ontario Canada K6A 1K7 | NE | | 35 MK III(-1): Tul-6154 35 MK IV (-2): Tul-6174 Tulmar:6502 | | |
| TSO-C13e *F | Aerazur 58 Bd Gallieni 92130 Issy. les Moulineaux, France | EU | LIFE PRESERVERS | C:210225(X) | 210479(X) | |
| TSO-C13e | Air Cruisers Company P.O. Box 150 Belmar, NJ 07719-0180 | NE | | D2134-() | D21344-() | |
| TSO-C13e *F | A/S Nordisk Gummibaadsfabrik Postbox 3060 DK 6710 Esbjerg V Denmark | EU | | 35-20-01 E 35-21-02 E | 35-23-04.1 E 35-23-04 E | |
| TSO-C13e *F | Beaufort Air-Sea Equipment Limited Birkenhead, Merseyside England | EU | | Mk.27 Mk20 MK.20-M | Mk.40 Mk22 | Type 21 (Adult) Mk22A |
| TSO-C13e | Eastern Aero Marine P.O. Box 593513 Miami, FL 33159 | CE-A | | KSE35L8:P0723E105P, P0723E109P | | |
| TSO-C13e | Hoover Industries, Inc. P.O. Box 522337 Miami, FL 33166 | CE-A | | FV-35E:3505-() | | |
| TSO-C13e *F | RFD Limited Godalming, Surrey England | EU | | Type 102 Mk3 Type 102 Mk4 | | |
| TSO-C14a | Flightex Fabric, Inc. New York, NY 10001 | NE | AIRCRAFT FABRIC, INTERMEDIATE GRADE; EXTERNAL COVERING MATERIAL | Intermediate | | |
| TSO-C15 | Reeves Brothers, Inc. Div. of A. W. Harris 1271 Avenue of the Americas New York, NY 10001 | NE | AIRCRAFT FABRIC, GRADE A; EXTERNAL COVER- ING MATERIAL | Grade "A" Fabric | | |
| TSO-C15a | Flightex Fabrics, Inc. New York, NY 10001 | NE | AIRCRAFT FABRIC, GRADE A: | Grade A | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|--|---|--|---|
| | | | EXTERNAL COVER- ING MATERIAL | | | |
| TSO-C15c | Hoye Textile Corp. Croton-on-Hudson, NY 10520 | NE | AIRCRAFT FABRIC, GRADE A: EXTERNAL COVER- ING MATERIAL | Grade A | | |
| TSO-C16 | Aero Dynamics, Inc. 7102 Thomas St. Buena Park, CA 90620 P/Ns formerly manufactured by HTL Advanced Technology | NM | AIR-SPEED TUBES ELECTRICALLY HEATED) | HF034() H7054() | H7045() H-7045-2 | H7047() H-7047-1 |
| TSO-C16 | Aero Instrument Co., Inc. P.O. Box 35262 14901 Emery Ave. Cleveland, OH 44135 | CE-C | | PH-500 PH-504 PH-520 PH503DH-13 PH5811-2 PH502HP-Left PH1100-EH-Left PH1100-():PH1100-MU-Left, PH1100-MU-Right, PH1100-1-BA PH1100-1-DHZ PH1100-1-LGP | PH-502 PH506-L PH520DH-11 PH502DH-14 PST-300A PH502HP-Right PH1100-EH-Right PH1100-MU-Right, PH1100-1-INV PH1100-1-INVf PH1100-1-RGP | PH502-12 PH506-R PH-502DH-12 PH5811DH-1 PST-305 |
| TSO-C16 | American Standard Aero Research Inst. Dept 9000 King St. Franklin Park, IL 60131 | CE-C | | H-1027-1 H-7007-2 H-7034-1A H-7038-1 H-7038-21 H-7047 | H-1027-2 H-7030 H-7034-18 H-7038-2 H-7039 | H-7007-1 H-7034 H-7035 H-7038-11 H-7045 |
| TSO-C16 *F | Badin-Crouzet Aerodrome de Toussus-le-Nobe B. P. 17, 78530 Buc France | EU | | 33615 33790-10 | 33615-01 | 33445-01 |
| TSO-C16 | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Hwy. So. Merrimack, NH 03054 | NE | | 369D 373E 782 832-02 2267-02 A28510-00-002 A30090-00-003 A30980-00-002 A31310-00-002 A34570-00-003 A34610-00-002 A34940-00-002 A3936()-()-() A42990-00-002 A43070-00-002 | 372C 518 923 1621 A26440-00-002 A28860-00-002 A30970-00-002 A34530-00-002 A34580-00-003 A34680-00-002 A3936() | 373D 781 831-02 1916 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|--|---|
| | | | | B16940-00-002 B28510-00-002 B28950 B28950-00-023 B34610-00-002 B26440-00-002 C28950 C28950-00-002 C28950-00-012 |
| TSO-C16 | Rosemount Engineering Co. P. O. Box 35129 Minneapolis, MN 55435 | CE-C | | 851AH 851AK 851AE 851CE-3 851CE-4 851CE-5 851CE-6 851CE-7 851CF 851CN 851CU 851T 851CU-1 851DK 851W 851Y 856AE-3 856AH-1 856AH-2 856CC-5 856CC-6 856DL-1 856DL-2 856CR-1 856CR-2 856KB-5 856KB-6 856LR() |
| TSO-C16 | Rosemount, Inc. 12001 West 78th St. Eden Prairie, MN 55343 | CE-C | | 851AH 851AK 851AE 851CE-3 851CE-4 851CE-5 851CE-6 851CE-7 851CF 851CN 851CU 851T 851CU-1 851DK 851W 851Y 855EY 856AE-3 856AH-1 856AH-2 856CC-5 856CC-6 856DL-1 856DL-2 856CR-() 856KB-5 856KB-6 856EB-() 856KB-7 856KB-8 856CC-11 856CC-12 856LK 851EU() 856HK-() 856KR-7 856KR-8 |
| TSO-C16 | Rosemount, Inc. Aerospace Division 14300 Judicial Road Burnsville, MN 55337 | CE-C | | 856MG() 856ML() 856MU 851GN() 856M8() 856NF 851GE() 856PD() 856PF() 856PJ() 856NC() 0850L() 856NU() |
| TSO-C17a | Omni Equipment, Inc. 4767 E. 10th Lane Hialeah, FL 33013 | CE-A | FIRE RESISTANT AIRCRAFT SHEET AND STRUCTURAL MATERIAL | OP-20() |
| TSO-C18 | "TSO authorizations existing at the time of TSO cancella- tion remain in effect." | | POSITION LIGHT FLASHERS (AIR CARRIER AIRCRAFT) | |
| TSO-C18b | "TSO authorizations existing at the time of TSO cancella- tion remain in effect." | | POSITION LIGHT FLASHERS (AIR CARRIER AIRCRAFT) | |
| TSO-C19 | Fireguard Corporation Northbrook, IL 60062 | CE-C | PORTABLE WATER- SOLUTION TYPE FIRE EXTINGUISHER | LS-15 |
| TSO-C19 | General Fire Extinguisher Detroit, MI 48233 | CE-C | | FS-15 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | | | | |
|----------|--|------|---|--|--------|--------|---|--|--|
| TSO-C19b | Walter Kidde & Co. Inc. Belleville, NJ 07109 | NE | PORTABLE WATER- SOLUTION TYPE FIRE EXTINGUISHER | 871685 892480 | 890017 | 890275 | | | |
| TSO-C19b | Overland Avn. Svc. Co., Inc. 10271 Bach Boulevard St. Louis, MO 63132 | CE-W | | 11000 | | | | | |
| TSO-C20 | C & D Airmotive Products, Inc. 302 Post Road Buchanan, MI 49107 | CE-C | COMBUSTION HEATERS | 3000:1036 B3040():45D70-2 Model:50:1056 Model 3000:1035 B3040:90D38-1, 90D38-2 4000:1046, 1047, 1048, 1053, 1059, 1060, 1217 B4050:65D79-1, 65D79-2, 65D79-3, 81D94-3 Model 4500:1065, 1066, 1068, 1069, 1071, 1073, 1072, 1074, 1075, 1076, 1077, 1078 8259:8259-HL2, 8259-HR2, 8259-JR2, 8259-L, 8259-M 8472-C, 8472-D, 8472-E Model 2000:1215, 1216 Model 4000:1060 Model 4500:1074, 1076, 1077, 1078 Model 8259():8259-L | | | | | |
| TSO-C20 | FL Aerospace Corp. Aircraft Products Div. 1900 N.E. 25th Avenue Ocala, FL 32670 | CE-A | | S-100:90E60-1 | | | | | |
| TSO-C20 | Midland Ross Corp. Aircraft Products Div. Ocala Unit 1900 N.E. 25th Avenue Ocala, FL 32670 | CE-C | | B-1500(15D81) B-1500(96C60) B2030:96C92-1 B-2030(15D83) B-2030(15D23) B2030(20D35) B-2030(20D35-1) B-2030(82D31-2) B-2030(34D33) B-2030(42D79) B2030(74D01) B-2030(74D01-1) B-2030(B37D88) B-2030(82D31-1) B3040(07E02-1) B-3040(10E21-1) B3040(10E21-2) B3040(10E21-3) B3040(09E21-1) B3040(15D85) B3040(22D25) B3040(34D35) B3040(22D25-1) B3040(34D51) B3040(C34D51) B3040(39D59) B3040(C39D59) B3040(D39D59) B3040(39D84) B3040(B39D59) B3040(47D65) | | | B-1500(15D92) B-1500(99C42) B-1500(99C60) B-2030(15D83) B-2030(15D94) B2030:20D35-1 B-2030(21D66) B-2030(22D01) B-2030(37D88) B-2030(56D03) B-2030(74D01-2) B2030(74D01-3) B-2030(A37D88) B2030-(96C92) B3040(04E34-2) B3040(04E34-1) B3040(10E21-3) B3040(10E21-4) B3040(15D31) B3040(15D96) B3040(32D99) B3040(A34D35) B3040(B34D51) B3040(A34D51) B3040(37D77) B3040(A39D59) B3040(D34D51) B3040(56D86) B3040(41D95) B3040(45D70) B3040(45D70-1) | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|----------------------------|
| | | | | B3040(45D70-2) |
| | | | | B3040(62D95) |
| | | | | B3040(62D33-2) |
| | | | | B3040(62D95-1) |
| | | | | B3040(62D95) |
| | | | | B3040(47D65-1) |
| | | | | B3040(88D81-1) |
| | | | | B3040(63D98-1) |
| | | | | B3040(96C62) |
| | | | | B3040(96D75-1) |
| | | | | B3040(88D81-3) |
| | | | | B4050(02E17-1 and 02E17-2) |
| | | | | B4050(11E82-1) |
| | | | | B4050(10E21-1) |
| | | | | B4050(13E55-1 and 13E55-2) |
| | | | | B-4050(15D48) |
| | | | | B-4050(15D98) |
| | | | | B4050(23E62-1), (23E62-2) |
| | | | | B4050(26E46-1) |
| | | | | B-4050(34D37) |
| | | | | B4050(39D90-1) |
| | | | | B-4050(65D79) |
| | | | | B-4050(65D79-2) |
| | | | | B4050(81D94-2) |
| | | | | B4050(65D79-3) |
| | | | | B-4050(99C80) |
| | | | | B-4050(81D94-3) |
| | | | | S-25(09C29) |
| | | | | S-25(C15C54) |
| | | | | S-25(98A08) |
| | | | | S-50(820C61) |
| | | | | S-50(42C29) |
| | | | | S-50(43C82) |
| | | | | S-50(C52C89) |
| | | | | S-50(A58C26) |
| | | | | S-50(E83A28) |
| | | | | S-100(06C10) |
| | | | | S-100(B10D40) |
| | | | | S-100(D10D40) |
| | | | | S-100(20C63) |
| | | | | S-100(20C63M2) |
| | | | | S-100(B51C90) |
| | | | | S-100(52C90) |
| | | | | S-100(C77A63) |
| | | | | S-100(80C65) |
| | | | | S-100(B80C65) |
| | | | | S-100(C80C65) |
| | | | | S-100(86C67) |
| | | | | S-100(H93A22) |
| | | | | S-200(A49C65) |
| | | | | S-200(C49C65) |
| | | | | S-200(A51C19) |
| | | | | S-200(C54C55) |
| | | | | S-200(C52C98) |
| | | | | S-200(D54C55) |
| | | | | S-200(H54C55) |
| | | | | S-200(K54C55) |
| | | | | S-200(A83C84) |
| | | | | S-200(C83C84) |
| | | | | S-200(A90C13) |
| | | | | S-200(90C26) |
| | | | | S-200(94A40) |
| | | | | S-200(A97A28) |
| | | | | S-200(C97A28) |
| | | | | S-200(E97A28) |
| | | | | S-25(15C54) |
| | | | | S-25(20C27) |
| | | | | S-50(18C87) |
| | | | | S-50(23C47) |
| | | | | S-50(A42C29) |
| | | | | S-50(52C89) |
| | | | | S-50(D52C89) |
| | | | | S-50(C83A28) |
| | | | | S-50(F83A28) |
| | | | | S-100(10D40) |
| | | | | S-100(C10D40) |
| | | | | S-100(E10D40) |
| | | | | S-100(20C63M1) |
| | | | | S-100(C51C90) |
| | | | | S-100(A52C90) |
| | | | | S-100(A80C65) |
| | | | | S-100(A86C67) |
| | | | | S-100(D80C65) |
| | | | | S-100(90E60-1) |
| | | | | S-200(14D41) |
| | | | | S-200(B49C65) |
| | | | | S-200(51C19) |
| | | | | S-200(A52C98) |
| | | | | S-200(G52C98) |
| | | | | S-200(F52C98) |
| | | | | S-200(G54C55) |
| | | | | S-200(J54C55) |
| | | | | S-200(83C84) |
| | | | | S-200(B83C84) |
| | | | | S-200(90C13) |
| | | | | S-200(B90C13) |
| | | | | S-200(A90C26) |
| | | | | S-200(97A28) |
| | | | | S-200(B97A28) |
| | | | | S-200(D97A28) |
| | | | | S-200(F97A28) |
| | | | | B3040(62D33) |
| | | | | B3040(62D33-1) |
| | | | | B3040(47D65-3) |
| | | | | B3040(63D98) |
| | | | | B3040(37D77-1) |
| | | | | B3040(82D20-1) |
| | | | | B3040(90D38-1) |
| | | | | B3040(90D38-2) |
| | | | | B3040(88D81-2) |
| | | | | B3040(09E21-1) |
| | | | | B4050(11E82-1) |
| | | | | B-4050(15D87) |
| | | | | B-4050(19E69-1) |
| | | | | B-4050(32D70) |
| | | | | B-4050(39D90) |
| | | | | B-4050(07E94-2) |
| | | | | B-4050(65D79-1) |
| | | | | B-4050(81D94-1) |
| | | | | B4050(82D20-2) |
| | | | | B4050(90E00-1) |
| | | | | B4050(99C80-1) |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|--|---|--|--|
| | | | | S-200(K97A28) | S-200(99A50) | |
| | | | | S-300(13D13) | S-300(30D43) | |
| | | | | S-300(A30D43) | S-300(88A92) | |
| | | | | S-300(A88A92) | S-300(B88A92) | |
| | | | | S-300(C88A92) | S-600(B59C97) | |
| | | | | S-600(C59C97) | | |
| | | | | V-15(99C31) | V-25(02C08) | |
| | | | | V-25(B02C08) | | |
| TSO-C20 | Stewart Warner South Wind Corporation 3 Industrial Drive Troy, IN 47588 | CE-C | | 8240()Ser. 8240E 8248 8259-C 8259HR2 8259M 8472() 921()Ser. 921-J 930-A-2 937-A-2 940-B24 940-D12 940-F12 940-DC12 944-A-2 978-MF-24 979B-1 G477025B | 8240-A 8253-A 8259() 8259-DL 8259JR2 8458()Ser. 8472C 921-B-1 921-K-1 930-B-3 940()Ser. 940-C12 940-D24 940-F24 940D24 945-A 978-MH-24 G477025 | 8240-C 8253-C 8259-A 8259HL2 8259L 8458A, B 8472D 921-H-1 921-L 930-C-2 940-B12 940-C24 940-DA12 940-DB12 944-A1 978-MC-24 979-B G477025A |
| TSO-C21 | Associated Aircraft Ind. Memphis, TN 38101 | CE-A | SPECIAL AIRCRAFT TURNBUCKLE ASSEM- BLIES AND/OR TURN- BUCKLE SAFETYING DEVICES | "Stuke Lock" | | |
| TSO-C21 | Industrial Sales of Calif. Pasadena, CA 91109 | NM | | 14 316-732 | 16-332 | 18-532 |
| TSO-C21 | Pacific Scientific Co. Kin-Tech Division 1346 S. State College Blvd. Anaheim, CA 92803 | NM | | D6 D7-2001-2-1A D7-2001-6-00 | D7-200 D7-2001-3-00 D7-2001-6-1A | D7-200-2-00 D7-2001-3-1A |
| TSO-C21a | Hardman Aerospace Macrodyne Industries, Inc. 1845 S. Bundy Drive Los Angeles, CA 90025 | NM | SPECIAL AIRCRAFT TWINBUCKLE ASSEM- BLIES AND/OR TURN- BUCKLE SAFETYING DEVICES | VS100-() | VS150-() | VS200-() |
| TSO-C21a | Maney Aircraft Div. Macrodyne Industries, Inc. 3100 W. Segerstrom Ave. Santa Ana, CA 92704 | NM | | VS100-() | VS150-() | VS200-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|--|------|--------------|---|--|---|
| TSO-C21a | Shinn Fabrications Division 320 Dyer Road Santa Ana, CA 92707 | NM | | VS 100-() | VS 150-() | VS 200-() |
| TSO-C22 | Alofs Manufacturing Co. Grand Rapids, MI 49501 | CE-C | SAFETY BELTS | Lyfe A5100 | A5102 | |
| TSO-C22 | Aloha Airlines, Inc. Honolulu, Hawaii 96800 | NM | | 10001 | | |
| TSO-C22 | Am-Safe, Inc. Sub. of American Safety Equipment Corp. 240 N. 48th Avenue Phoenix, AZ | NM | | 9900() | | |
| TSO-C22 | Auto-Crat Mfg. Co. Bien Corporation Los Angeles, CA 90052 | NM | | 1-1500 1-1503 1-1506 1-1509 2-999 3-6004 | 1-1501 1-1504 1-1507 1-1513 3-1503 | 1-1502 1-1505 1-1508 1-2001 3-6000 |
| TSO-C22 | Automotive Safety Assoc. South Pasadena, CA 91109 | NM | | Harper Magnum | | Magnum |
| TSO-C22 | Beech Aircraft Corp. 9709 E. Central Wichita, KS 67201 | CE-W | | 50-534102 | 50-534130 | 50-534131 |
| TSO-C22 | Braniff Inter'l Airways Minneapolis, MN 55401 | CE-C | | B11293 E12229 E20006 | E11816 E12329 | E11820 E12393 |
| TSO-C22 | Continental Air Lines, Inc. Denver, CO 80202 | NM | | 128-3537 159-01129 | 128-4537 159-01138 | 159-001128 |
| TSO-C22 | Davis Aircraft Products, Co., Inc. 1150 Walnut Ave. Bohemia, NY 11716 | NE | | FDC-103C FDC-2700 FDC-5900-210 FDC-5900-202 FDC-6400 FDC-6400-58 | FDC-2700-67 FDC-2700D FDC-5900-189 FDC-5900-228 FDC-6400-39 FDC-6400B | FDC-5950s-25 FDC-5900 FDC-5900-222 FDC-5950 FDC-6400-35 |
| TSO-C22 | Douglas Aircraft Co. McDonnell Douglas Corp. 3855 Lakewood Blvd. Long Beach, CA 90801 | NM | | 3400373 3408947 5460071 S-5397227 | 3403325 4399288 5610175 | 3403452 4399298 5712345 |
| TSO-C22 | Eon Corporation TSO Approval Withdrawn | NM | | | | |
| TSO-C22 | Frontier Airlines 5900 E. 39th Ave. Denver, CO 80207 | NM | | FAL 102-956 | | |
| TSO-C22 | Gayo Manufacturing Co. East Peoria, IL 61611 | CE-C | | GLG 3 | GLG 5 | GLG 7 |
| TSO-C22 | General Motors Corp. Detroit, MI 48233 | CE-C | | GD 69 9901 | | |
| TSO-C22 | General Tube Company | CE-C | | WB2010 | WB2016 | WB2018 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|--------------|---------------------------|-------------------------|-------------------------|
| | Sturgis, MI 49091 | | | WB2019 | | |
| TSO-C22 | Jervis Corporation Grandville, MI 49418 | CE-C | | 841154 | | |
| TSO-C22 | Lear Jet Industries, Inc. P. O. Box 1280 Municipal Airport Wichita, KS 67201 | CE-W | | 2413114 | | |
| TSO-C22 | Maximoff Research Co. Van Nuys, CA 91408 | NM | | Mareco 15-1 | 15-1 DA | |
| TSO-C22 | Mesaba Aviation Grand Rapids, MN 55744 | CE-C | | 66 | 88 | |
| TSO-C22 | Mid-Continent Airlines Minneapolis, MN 55401 | CE-C | | 11916 | 11917 | 15393 |
| TSO-C22 | N. Central Airlines, Inc. 7500 Northliner Dr. Minneapolis, MN 55450 | CE-C | | Model A | | |
| TSO-C22 | Northwest Airlines, Inc. Minn-St. Paul Int'l Airport St. Paul, MN 55111 | CE-C | | Part Number not furnished | | |
| TSO-C22 | Pacific Northern Airlines Seattle, WA 98101 | NM | | 34 | | |
| TSO-C22 | Pacific Scientific Co. Kin-Tech Division 1346 S. State College Blvd. Anaheim, CA 92803 | NM | | F20-1101Ser. | 1101100 | 1101900 Ser. |
| TSO-C22 | Pan American World Airways Miami, FL 33159 | CE-A | | L2831 L4601 M1850 | L4599 L4602 M2969 | L4600 M1078 M3529 |
| TSO-C22 | Pan American World Airways S. San Francisco, CA 94101 | NM | | P1001 | P1002 | |
| TSO-C22 | Piedmont Airlines 815 Radar Road Greensboro, NC 27410 | CE-A | | ACD-82019 | | |
| TSO-C22 | Rose Manufacturing Co. Denver, CO 80202 | NM | | 850 M-62 | 858 | 865 |
| TSO-C22 | Rupert Industries, Inc. P. O. Box 624 Wheeling, IL 60090 | CE-C | | 50 80 | N50 82 | 65 S2194 |
| TSO-C22 *F | Sabena Brussels National Airport B-1930 Zaventem, Belgium | EU | | 1-6476 | 1-6477 | 1-6478 |
| TSO-C22 | Stebco Industries, Inc. 1020 W. 40th St. Chicago, IL 60609 | CE-C | | C1 | | |
| TSO-C22a | Aircraft Belt and Trim Los Angeles, CA 90052 | NM | SAFETY BELTS | 17001 | 18001 | 19001 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--------------|---|---|--------------------------------------|
| TSO-C22a | Beech Aircraft Corp. 9709 E. Central Wichita, KS 67201 | CE-W | | 35-534265 35-534268 50-534037 901-183333 | 35-534266 35-534269 404-183388 50-534131 | 35-534267 35-534280 404-183390 |
| TSO-C22a | Douglas Aircraft Co. McDonnell Douglas Corp. 3855 Lakewood Blvd. Long Beach, CA 90801 | NM | | 3409430 | | |
| TSO-C22a | National Airlines P. O. Box 2055, AMF Miami, FL 33159 | CE-A | | 2-47-1130 2-47-1133 | 2-47-1131 | 2-47-1132 |
| TSO-C22a | Pan American World Airways Miami, FL 33159 | CE-A | | P1001 | P1002 | |
| TSO-C22b | Aero Safety Equipment Co. Los Angeles, CA 90052 | NM | SAFETY BELTS | 19001 | | |
| TSO-C22b | Auto-Crat Manufacturing Co. Bien Corporation Los Angeles, CA 90052 | NM | | 3-1500 | 3-1504 | |
| TSO-C22b | Beech Aircraft Corp. 9709 E. Central Wichita, KS 67201 | CE-W | | 50-534269 | 414-183388 | 414-183389 |
| TSO-C22b | Brown-Line Corporation Beverly Hills, CA 90213 | NM | | WB2002 WB2021 | WB2010 WB2018 | WB2016 |
| TSO-C22b | Davis Acft. Products Inc. Scudder and Woodbine Ave. Northport, L. I., NY 11768 | NE | | FDC-2475Ser | FDC-2700 | FDC-2500 |
| TSO-C22b | M & B Sales Company Dallas, TX 75221 | SW | | 102 | | |
| TSO-C22b | Pacific Scientific Co. Kin-Tech Division 1346 S. State College Blvd. Anaheim, CA 92803 | NM | | F20-1001 | | |
| TSO-C22b | PTC Aerospace Bantam, CT 06750 | NE | | 102 | 102A | |
| TSO-C22b | Universal Equipment Corp. Beverly Hills, CA 90213 | NM | | MC-140 MC-740 | MC-140A | MC-440 |
| TSO-C22c *F | L'Aiglon P. O. Box 236 Bd Gaston-Birge 49009 Angers, France | EU | SAFETY BELTS | 341 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--------------|--|---|--|
| TSO-C22c | Air Carrier Interiors, Inc. 8167 Perimeter Rd. Boeing Field Seattle, WA 98108 | NM | | C-1500 | C-3000 | |
| TSO-C22c | Beech Aircraft Corp. 9709 E. Central Wichita, KS 67201 | CE-W | | 35-534377-61 414-183389-19 | 35-534376-1 95-534014-63 | 35-534376-3 |
| TSO-C22c | Douglas Aircraft Co. McDonnell Douglas Corp. 3855 Lakewood Blvd. Long Beach, CA 90801 | NM | | 3718325 | 5613980 | |
| TSO-C22c | Pacific Scientific Co. Kin-Tech Division 1346 S. State College Blvd. Anaheim, CA 92803 | NM | | 101100 Series | | |
| TSO-C22c *F | RFD-GQ Ltd. Woking Works, Portugal Td. Woking, Surrey England (Formerly Mills Equip. Co. Ltd. & GQ Parachute Co. Ltd.) | EU | | ME/2095 | | |
| TSO-C22d | Beech Aircraft Corp. 9709 E. Central Wichita, KS 67201 | CE-W | SAFETY BELTS | 35-534419 | | |
| TSO-C22d | Beltmaster Corporation P. O. Box 295 Manhattan Beach, CA 90266 | NM | | G6570 G6573 J8425 J8428 P8425 P8428 | G6571 G6574 J8426 J8429 P8426 P8429 | G6572 G6575 J8427 J8430 P8427 P8430 |
| TSO-C22d | Hoover Acft. Products Co. P. O. Box 337 International Airport Miami, FL 33148 | CE-A | | 247-3077() | 247-3077-1 | |
| TSO-C22d | United Air Lines International Airport San Francisco, CA 94101 | NM | | 9F-4103 | | |
| TSO-C22d | Universal Equipment Corp. Beverly Hills, CA 90213 | NM | | MF50B Series | | |
| TSO-C22e *F | L'Aiglou P.O. Box 236 1, Bd Gaston-Birge 49009 Angers, France | EU | SAFETY BELTS | 343 | | |
| TSO-C22e | American Safety Flight Systems, Inc. Commercial Products Div. 650 Jessie Street San Fernando, CA 91340 | NM | | AC-6000() M4450M1 M-7550() 9475() 444444() 445555() 449471() | HT1003() M4450H2 9400() 9600() 443440() 448800() 500310() | M4450 M-7500() 9450() 9650() 444625() 449470() |
| TSO-C22e | Associated Aircraft Equip. | CE-A | | AAE-1500() | AAE1505(A) | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|---|--|---|
| | P. O. Box 542 Miami, FL 33148 | | | | | |
| TSO-C22e | Auto-Crat Manufacturing Co. Bien Corporation Los Angeles, CA 90052 | NM | | 1-1511 1-1701 1-1704 1-1802 1-1805 1-1809 1-1814 1-2003 3-9200 | 1-1512 1-1702 1-1800 1-1803 1-1806 1-1810 1-2000 3-1505 4-3000 | 1-1700 1-1703 1-1801 1-1804 1-1808 1-1811 1-2002 3-9100 |
| | | | | See Also Eon Corporation | | |
| TSO-C22e *F | Autoflug GmbH Industriestrasse 10 D2084 Rellingen 2 Hamburg, Germany | EU | | Bagu FAG-6 | BaguV-FAC-6 | |
| TSO-C22e | Beech Aircraft Corp. 9709 E. Central Wichita, KS 67201 | CE-W | | 130498-C Ser 50-534269-1 50-534269-13 95-534017-35 414-183389-33 414-183389-37 414-183389-47 414-183389-73 B38727-53 B89709-21 B99518-1 MCO 893550-1 58-530219-47 | 130499-C Ser. 50-534269-3 50-534269-15 96-534039-23 B50869-1 B93446-1 MCO 877728-1 MCO 877728-3 | 50-534269-11 50-534269-27 414-183389-41 414-183389-65 414-183389-75 B83094-71 B94269-11 MCO 888233-1 58-530219-51 |
| TSO-C22e | Beltmaster Corporation P. O. Box 295 Manhattan Beach, CA 90266 | NM | | DH01()Ser. G6570() G6574() J8428() P8427() | FJ01()Ser. G6572() J8425() J8429() P8428() | PS01()Ser. G6573() J8427() P8425() P8429() |
| TSO-C22e | Cessna Aircraft Co. Aircraft Division Wichita, KS 67201 | CE-W | | S-1539 S-1060 S-1620 S-1996 | S-1540 S-1618 S-1624 S-1746 | S-1243 S-1619 S-1669 S-2070-100 Ser. |
| TSO-C22e | Davis Acft. Products Inc. Scudder & Woodbine Ave. Northport, L. I., NY 11768 | NE | | FDC-2700 FDC-4600 FDC-7000 | FDC-2700-134 FDC-5500 | FDC-5950 |
| TSO-C22e | Eon Corporation - WITHDRAWN | | | | | |
| TSO-C22e | Hamill Mfg. Co. Inc. 61166 Van Dyke Ave. Washington, MI 48094 | CE-C | | FA-1 GA-2 HA-2 | FA-2 GA-3 | GA-1 HA-1 |
| TSO-C22e *F | Irwin Great Britain Ltd. Letchworth, Hertfordshire England | EU | | AB1() | AB3() | AB6() |
| TSO-C22e | Irwin Industries, Inc. 1315 Versailles Rd. Lexington, KY 40507 | CE-A | | 77AC-2C | 77AC-7C | |
| TSO-C22e | Pacific Scientific Co. Kin-Tech Division 1346 S. State College Blvd. | NM | | -01 Ser. 0108164() 1101 Ser. | -01A() 0108168() 1101() | 0108152() 0108174() 1107001() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--------------|--|--|--|
| | Anaheim, CA 92803 | | | 1107002() 1107009() 1107118() 1107025-01 1107030() 1107034() | 1107006() 1107013() 1107018-01 1107027() 1107031() 1107260() | 1107008() 1107014() 1107019-01 1107022-05 1107033() 1108006() |
| TSO-C22e | Pan American World Airways Miami, FL 33159 | CE-A | | M5993-() M5604-() | M5599-() M6076-() | M5603-() M6077-() |
| TSO-C22e | Production Research Corp. Cummings & Sander 6426 San Francisco Rd. Glendale, CA 91209 | NM | | AC-6000 M-4450 | M-1 M-5100 | M-2 M-7500 |
| TSO-C22e *F | RFD-GQ Ltd. Woking Works Portugal Road Woking, Surrey, England (Formerly Mills Equip Co Ltd & GQ Parachute Co) | EU | | ME/GQ/2058() ME/2402T/() ME/2402TB/() ME/2402TD/() ME/2819/() | ME/2402() ME/2402TA/() ME/2402TC/() ME/2402TE/() ME/2819A/() | |
| TSO-C22e | Tower Avionics Center Hangar 8, Oakland Int'l Arpt Oakland, CA 94614 | NM | | S-1 2D()Ser. | S-2 2S()Ser. | S-3()Ser. |
| TSO-C22e | Trans World Airlines, Inc. Mid-Continent Int'l Airport 10 Richards Road Kansas City, MO 64108 | CE-W | | 1-73704() | | |
| TSO-C22f | Aero Fabricators, Inc. Box 181 Lyons, WI 53148 | CE-C | SAFETY BELTS | Models 65-50 (R-60, R-62, R-64) 65-51 (R-60, R-62, R-64) 65-80 (R-60, R-64) 89-81 89-82 89-91 (R-60, R-62, R-64) 89-92 (R-60, R-62, R-64) Model 90-91() Model H725() | | |
| TSO-C22f | Aero Interior Corporation 1521 22nd N.W. Auburn, WA 98001 | NM | | A-3000 | | |
| TSO-C22f *F | Aerolex Limited Camberley Surrey, England | EU | | AL.2786 | | |
| TSO-C22f | Air Carrier Interiors, Inc. 22645 76th Avenue South Kent, WA 98031 | NM | | C1500-() | C1501-() | C1502-() |
| TSO-C22f | Allegheny Cable Co., Inc. P.O. Box 249 Oakdale, PA 15071 | EA | | 802-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|--|
| TSO-C22f | Allnew Interiors, Inc. P.O. Box 54-0791, Bldg. 105 Opa Locka Airport Opa Locka, FL 33054 | CE-A | | Model SB-100 |
| TSO-C22f | American Classic Cushion - WITHDRAWN 8/24/89 Molders | | | |
| TSO-C22f | American Safety Equipment Corporation Quality Assurance & Reliability 501 Fourth Street San Fernando, CA 91340 | NM | | 501505() |
| TSO-C22f | Am-Safe Inc. Sub. of American Safety Equipment Corp. 240 N. 48th Ave. Phoenix, AZ 85043 | NM | | AC-6000() HY1003() M4450 M4450M1 M4450M2 M-7500() M-7550() 9400() 9450() 9475() 9600() 9650() 444444() 443440() 444625() 445555() 448800() 449470() 449471() 500310() 500850() 501302() 8W570-SS2 9900() 500530() 500580() 501615-() 501661-403 501662-407 501800-() 502062() 502216-() 502751-() 50275B-() |
| TSO-C22f *F | Anjou Aeronautique Ave de l' Osier 49125 Tierce, France | EU | | 343 343-1 346 |
| TSO-C22f | ARA, Inc. 160 South Hacienda Blvd. P.O. Box 3824 City of Industry, CA 91744 | NM-W | | C4381-1 |
| TSO-C22f | Associated Aircraft Equip. 6961 N.W. 42nd Street Miami, FL 33166 | CE-A | | AAE 1510() |
| TSO-C22f *F | Autoflug GmbH Industriestrasse 10 Postfach 1180 D2084 Rellingen 2 Hamburg, Germany | EU | | Bagu FAG-6-()-()-() Bagu -V FAG-6-()-() Bagu FAG-7A, B, C, D, E, F, G, H Bagu FAG-7A, B, C, D Bagu FAG-9A, -9C, -9D Schugu FAG-7A, B, C, D, E, F, G, H, I, K Schugu FAG-9A, -9B, -9D, -9E FAG-10 FAG-10A FAG-10B FAG-10C |
| TSO-C22f | Beech Aircraft Corp. P.O. Box 85 Wichita, KS 67201 | CE-W | | 58-530219-5, -7, -19, -21, -29, -31, -39, -43, -53, -57, -59, -61, -63 58-530081-15, -19, -29, -33, -51, -53 60-530318-1, -3, -13, -15 90-530159-1 |
| TSO-C22f | Belt Makers, Inc. 1815 West 205th St. Suite 304 Torrance, CA 90501 | NM | | H3600-() H3602-() H3604-() H3800-() H3606-() H3900-() H4000-() H4002-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|--|--|---|
| TSO-C22f | Beltmaster Corporation 685 Wahington Street Ashland, OR 97520 | NM | | DH01() G6570-() G6570-TD() G6572() G6573() G6574() G6579H-() N6572-() N6574-() PS02-() PS-801A-() | FJ01() G6570-H() G6575 G6572H-() G6573H-() G6574-H() N6570-() N6573-() N6578-() PS03-() R4005-() | G6570HTD-() G6575-TD() G6572-TD() G6573-TD() G6574-TD() N6570TD-() N6573TD-() PS01() PS04-() |
| TSO-C22f *F | Britan - Excelsior Limited Weybridge, Surrey, England | EU | | 4203-232 | | |
| TSO-C22f | Cameron Acft. Interiors Inc. DuPage Airport West Chicago, IL 60185 | CE-C | | 101 104 107 110 1102 1105 1108 1111 1114-() | 102 105 108 111 1103 1106 1109 1112 | 103 106 109 1101 1104 1107 1110 1113 |
| TSO-C22f | Carol's Acft. Interiors Inc. 4243 E. Lake Boulevard Birmingham, AL 35217 | CE-A | | W5010-() | | |
| TSO-C22f | Cessna Aircraft Co. Aircraft Division Wichita, KS 67201 | CE-W | | S-1539 S-1060 S-1620 S-1746 S-2070-100 Ser | S-1540 S-1618 S-1624 S-1996 | S-1243 S-1619 S-1669 S-2275-100 |
| TSO-C22f | Davis Acft. Products Inc. Scudder & Woodbine Ave. Northport, L. I., NY 11768 | NE | | FDC-2700 FDC-5900-210 FDC-6400B | FDC-2700-D FDC-5950 FDC-6400-58 | FDC-5900 FDC-6400B |
| TSO-C22f | Davis Restraint Sys., Inc. 820 S. Palm Avenue, #15 Alhambra, CA 91803 | NM | | FDC-6500-() | | |
| TSO-C22f | Eon Corporation - WITHDRAWN | | | | | |
| TSO-C22f | Flight Design Interiors c/o Aero Air, Inc. 2050 N.E. 25th Street Hillsboro, OR 97124 | NM | | FDI-() | | |
| TSO-C22f | Hamill Manufacturing Co. 61166 Van Dyke Road Washington, MI 48094 | CE-C | | GA-5 | | |
| TSO-C22f | Hooker Custom Harness 30 East Jefferson St. Freeport, IL 61032 | NE | | 36302G 201AXX 302XXYY 204AXX | C-452 202AXX 102XXYY 205AXX | 101XXYY 301XXYY 203AXX |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|--|--|--|
| TSO-C22f | Indiana Mills & Mfg., Inc. 120 W. Main St. Carmel, IN 46032 | CE-C | | IMM-11040-1 IMM-11040-4 IMM 16-90007 IMM 111050-6, -7, -8, -9, -20, -21, -22 IMM 1710-1200-0009-00 | IMM-11040-2 IMM-111040-8 IMM 16090008 | IMM-11040-3 |
| TSO-C22f | Infab Corporation 16700 Roscoe Boulevard Van Nuys, CA 91406 | NM | | IC 7900() | | |
| TSO-C22f *F | Irvin Great Britain Ltd. Letchworth, Hertfordshire England | EU | | AB5() AH8() | AH16/3 | AH6/6 |
| TSO-C22f *F | Irvin Manifatture Industriale SpA Casella Postale 19 04011 Aprilia (LT) Italy | EU | | I.M.I. 5.4.4. | | |
| TSO-C22f *F | Jet Aviation AG c/o Section of Aeronautical Material CH-3003 BERN Bundeshaus Inselgasse Switzerland | EU | | 5003/80-1 | 5003/80-2 | |
| TSO-C22f *F | Kangol Magnet Limited Norfolk Street Carlisle, Cumbria, England | EU | | 449470() 501401() | 449471() 501402() | 501300() |
| TSO-C22f *F | Morse Controls Limited Basildon, Essex England | EU | | C.183005 | 188500 | |
| TSO-C22f | Pacific Scientific 1346 S. State College Blvd. Anaheim, CA 92803 | NM-L | | 01A() 0108168() 0108900-09 1101020() 01117002-() 1101685() 1101756() 1101775() 1101831() 1101858() 1101887() 1101888() 1101917() 1101979-() 1101964-() 1101972-() 1107002() 1107009() 1107022-05 1107033() 1107039() 1107045() 1107060-03 1107062-05 1107068() 1107077-07 1107080-07 1107081-03 1107146() 1107177-() 1107260() | 0101936-11 0108169() 0108900-11 0108900-45 1101092-03 1101701() 1101759() 1101780() 1101835() 1101869() 1101882() 1101895-() 1101919() 1107001() 1101967-() 1101976-() 1107006() 1107018() 1107025() 1107034() 1107041-03 1107049-03 1107060-04 1107065-05 1107072() 1107079() 1107080-13 1107082-() 1107175-() 1107189-() 1107309() | 0108008() 0108900-07 1101() 0108900-47 1101099-03 1101740() 1101763() 1101789() 1101850() 1101884() 1101883() 1101904() 1101920() 1101994-() 1101989-() 1101994-() 1107008() 1107019() 1107030() 1107036() 1107043() 1107050() 1107061() 1107065-07 1107077-03 1107080-05 1107080-15 1107114() 1107176() 1107193() 1107387-01 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|---|---|--|
| | | | | 1107415() | 1107415-03 | 1107415-07 |
| | | | | 1107422() | 1107425() | 1107436() |
| | | | | 1107440() | 1107441-03 | 1107442() |
| | | | | 1107445() | 1107449() | 1107457() |
| | | | | 1107463() | 1107490() | 1107495() |
| | | | | 1107503() | 1107505() | 1107511() |
| | | | | 1107512() | 1107514() | 1107517() |
| | | | | 1107539() | 1107548() | 1107619() |
| | | | | 1107584-() | 1107656() | 1107553() |
| | | | | 1108019() | 1108020() | 1108021() |
| | | | | 1108029() | 1108059() | 1108034() |
| | | | | 1108271() | 1108272() | 1108279() |
| | | | | 1108333() | 1108343() | 1108344() |
| | | | | 1108345() | 1108346() | 1108376() |
| | | | | 1108381() | 1108370-() | 1108415-01 |
| | | | | 1108419() | 1108423() | 1108425() |
| | | | | 1108428-() | 1117050-() | 1117276() |
| | | | | 1117330() | 1117364() | 1117365() |
| | | | | 1111002-03 | 1111003-01 | 1111004-01 |
| | | | | 1111012-01 | 1111012-03 | 1111031() |
| | | | | 1111050() | 1111067() | 1111033() |
| | | | | 1108400-() | 1111343-01 | |
| | | | | 1111051-2, -4, -7, -9, -12, | -14, -17, -19 | |
| | | | | 1111062-() | 1108403() | 1108399-() |
| | | | | 1108419() | 1117241() | 1117030() |
| | | | | 1111005() | 1111221-() | 1111225-() |
| | | | | 1111223-() | 1111230-() | 1111244-() |
| | | | | 1111329 | 1117239() | 1117241-() |
| TSO-C22f | Piedmont Airlines 815 Radar Road Greensboro, NC 27410 | CE-A | | XC-82104-() | X082106-() | |
| TSO-C22f *F | RFD-GQ Ltd. Woking Works Portugal Road Woking, Surrey, England | EU | | ME2819B/() ME2819E/() | ME2819C/() | ME2819D/() |
| TSO-C22f | Rupert Industries, Inc. P. O. Box 624 Wheeling, IL 60090 | CE-C | | 50 65-80 65-528-() | 65-50 81 | 65-51 |
| TSO-C22f | Sacramento Avn. Upholstery Suite B 1420 Flight Line Dr. Lincoln, CA 95648 | NM | | 101-A | 201-B | |
| TSO C22f | Safety, Ltd. 31 W. 651 North Ave. DuPage Airport West Chicago, IL 60185 | CE-C | | 1201() 1204() 1207() 1210() 1213() | 1202() 1205() 1208() 1211() 1214() | 1203() 1206() 1209() 1212() |
| TSO-C22f *F | Secur Aiglon TRW Blvd. du l'Industrie Zone Industrielle, Ecoulfant F49000 Angers, France | EU | | 343-1 346() () () () | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|------------|---|--|---|
| TSO-C22f *F | SEFA Societe Etudes & Fabrication Aeronautiques 44, Blvd. Jean Jaures 92112 Clichy France | EU | | 602.5()()() 602.6()()() 302.5()()() | | |
| TSO-C22f *F | Teleflex Morse Ltd. Basildon, Essex England | EU | | E 74247 | | |
| TSO-C22f | Thornton Technology Corp. 2221 Las Palmas Dr., Suite G Carlsbad, CA 92008 | NM | | SS 7000() | | |
| TSO-C22f | Tower Avionics Center Hangar 8, Oakland Int'l Arpt Oakland, CA 94614 | NM | | 2S1 2S4() Series 2S3 () Series | 2S2 | |
| TSO-C22f | Transportation Safety Equipment Corp. 5355 N. 51st Ave. #19 Glendale, AZ 85301 | NM-L | | 22146 | 22147 | |
| TSO-C22f | Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64108 | CE-W | | 1-73704-() | 1-86800-() | 1-86800-8 |
| TSO-C22f | Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195 | CE-W | | 1-73704-() 1-86800-() | 1-73704-22 | |
| TSO-C22f | TWIB Industries, Inc. 8210 W. 30th Court Miami, FL 33016 | CE-A | | 611-531-86 | | |
| TSO-C23 | U.S. Dept. of Agriculture Forest Service Washington, DC 20000 | NE | PARACHUTES | FS-1 FS-4 | FS-2 FS-5 | FS-3 FS-5A |
| TSO-C23 | Capital Parachuting Enter. P. O. Box 3324 Fayetteville, NC 28303 | CE-A | | "Cavalier" "Charger" | "Cavalier" S-5 "Conquistador" | |
| TSO-C23 | General Textile Mills, Inc. New York, NY 10001 | NE | | G.T.M.-25 | | |
| TSO-C23 | Jalbert Aerology Lab., Inc. Boca Raton, FL 33432 | CE-A | | JAL-24-A | JAL-25 | JAL-28 |
| TSO-C23 | Paranetics El Monte, CA 91731 | NM | | Part number not furnished | | |
| TSO-C23 | Pioneer Parachute Co. Pioneer Industrial Park Manchester, CT 06040 | NE | | AN-SS-24 P1-QAC-24 P3B-28 P5S-28 P9B P9S-3 PT-R-24 PT-28 | AN-SS-28 P1-QAC-28 P5B-28 P7B P9B-4 PT-10 PSD-1-28 | P11B P3B-24 P5S-24 P7S P9S PT-R-10 PSD-2-32 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|------------|---|---------------------------------|-------------------------------|
| TSO-C23b | The Adventure Loft, Inc. 1425 Century, Suite 100 Carrollton, TX 75006 | SW | PARACHUTES | "Brief Case" "Brief Case Student Tandem" | | |
| TSO-C23b | Airotech, Inc. 8733 N. Magnolia, Suite 106 Santee, CA 92071 | NM | | Force 1() | | |
| TSO-C23b | Alpha Para-Equipment Route #2, Box 140 Bardstown, KY 40004 | CE-A | | AL-1() | AL-2() | |
| TSO-C23b | The Altitude Shop - WITHDRAWN | | | | | |
| TSO-C23b | The Annex, Inc. P.O. Box 1657 Deland, FL 32720 | CE-A | | RTS-1 | RTS-2 | |
| TSO-C23b | Barish Associates, Inc. 54 East 11th Street New York, NY 10003 | NE | | Beta 200 | | |
| TSO-C23b | Bruce Deville 29 Forest Drive Monroe, LA 71203 | SW | | DEVCOE #1 | | |
| TSO-C23b | Butler Parachute - WITHDRAWN 2/23/89 Systems, Inc. Georgetown, TX | | | | | |
| TSO-C23b | Butler Parachute Systems, Inc. 707 Ellis Street Ridgecrest, CA 93555 | NM | | BETA:101 | 102 | 103 |
| TSO-C23b | Cazer Para Loft 8420 Third Avenue North Birmingham, AL 35206 | CE-A | | Eagle I harness | | |
| TSO-C23b | Centaurus Corporation 2280 South Fox Denver, CO 80223 | NM | | 5011-Aux. Parachute Container | | |
| TSO-C23b | Eagle Parachute, Inc. Route 3, Box 249 Virgilina, VA 24598 | NE | | 79-1003 79-1004-1 81-1046 82-1066 | 79-1003-1 81-1040 81-1048 | 79-1004 81-1043 82-1058 |
| TSO-C23b | Eagle Systems P. O. Box 235 Zephyrhills, FL 33599 | CE-A | | EST-2-() | | |
| TSO-C23b | Free Flight Enterprises 17655 Grand Avenue Lake Elsinore, CA 92230 | NM | | GE-21() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|-----------|--|
| TSO-C23b | G Q Security Parachutes, Inc. A Subsidiary of G Q Parachutes Limited 295-139th Ave. P.O. Box 3096 San Leandro, CA 94578 | NM | | 78A1678-() 63E1162-1 64B1189-1 64C1202-1 69B1451-() Series 550:7481594-2 75B1642-() Series, -1, -2 75B1643-() Series, -1, -2 77B1673-1, -2 79A1684-() 79A1686-() GQ2575 Issue E GQS82-0200-() GGS/81-0065-01-() |
| TSO-C23b | Herb M. Graves, Jr. 4035 Plank Road Baton Rouge, LA 70805 | SW | | Herbie-Hog |
| TSO-C23b | Green Star Systems 109 S. Monroe Siding Rd. Xenia, OH 45385 | CE-C | | GSS-1(A) GSS-2(B) GSE-3() GST-2 |
| TSO-C23b | Guardian Parachute Div. of FXC Corporation 2930 West Central Ave. Santa Ana, CA 92704 | NM | | 71013A C319 71013A TR-1 0237206 (Emer. Backpack Assy) 821-00097() 721-00014 721-00015 721-00053 |
| TSO-C23b | Horizon Parachute System P.O. Box 111 Starkville, MS 39759 | CE-A | | Swine Flew |
| TSO-C23b | Irving Air Chute Co. Inc. 622 Rodier Dr. Glendale, CA 91201 | NM | | GID76-106 SRB-1-24 SRB-1-28 SRB-1-30 SRB-1-32 SRBW-1-24 SRBW-1-28 SRBW-1-30 SRBW-1-32 SRS-1-24 SRS-1-28 SRS-1-30 SRS-1-32 STBW-1-24 STBW-1-28 STBW-1-30 STBW-1-32 S-S-1 S-S-2 S-L-1 S-L-2 S-SB-1 S-FF-1 S-FF-2 S-QQ-1 S-QQ-2 |
| TSO-C23b | The Jump Shack, Inc. 45620 - 12 Mile Road Novi, MI 48050 | CE-C | | SST |
| TSO-C23b | Lite-Flite, Inc. 45620 Twelve Mile Road Novi, MI 48050 | CE-C | | SST-051 SST-051A SST-202 |
| TSO-C23b | Nat'l Parachute Supply, Inc. P.O. Box 1000 47 East Main Street Flemington, NJ 08822 | NE | | NP6-1 81101-1 |
| TSO-C23b | No. American Aerodynamics, Inc. P. O. Box 445, Highway 202 Flemington, NJ 08822 | NE | | NAA-1 NAA-2 NAA-P-1 NAAP-2: 20001 (less canopy) NAA-OA:60001 NAA 26' |
| TSO-C23b | North American Aerodynamics, Inc. 110 Carver Drive Roxboro, NC 27573 | CE-A | | Centaurus Harness NAA 22' |
| TSO-C23b | Northwest Aero Sports 2411 Williams Street Bellingham, WA 98225 | NM | | Harness H-1() Container C-1() |
| TSO-C23b | Northwest Parachute Co. | NM | | 76H1-() 76H2-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|--|--|--|
| | P. O. Box 103 Snohomish, WA 98290 | | | | | |
| TSO-C23b | The Parachute Company P. O. Box 533 Franklinton, NC 27525 | CE-A | | Model 1 | | |
| TSO-C23b *F | Parachutes Australia, Pty. Ltd. 407 Kent Street Sydney, N.S.W. 2000 Australia | NM | | Slimpack S3 Trimpig S11 Slimpack II S3 Conical Canopy P15 Pigme S-7 Piggyback Thinpack Parachute Assy S5 and P8 Tandem dual pack S18 | | |
| TSO-C23b *F | Parachutes Australia, Pty. Ltd. 68 Wentworth Avenue Sydney, New South Wales Australia | NM | | S15 | | |
| TSO-C23b | Parachute Laboratories, Inc. Suite 106 1665 Lexington Avenue Deland, FL 32720 | CE-A | | SST/RACER Firefly Reserve SST Pilotchute Sq. Reserve "D" Bag Racer 26' Reserve | | |
| TSO-C23b | Para-Flite, Inc. 5800 Magnolia Ave. Pennsauken, NJ 08109 | NE | | 809.000 811.056 811.306 827.300 | 811.006 811.056a 815.000 835.000 | 811.006a 811.302 827.200 |
| TSO-C23b | Para-Innovators Co., Inc. 321 South D Street Perris, CA 92370 | NM | | "Piglet 2" "Piglet 3" | "Piglet Maxi" "Wedge 1" | "Wedge 2" |
| TSO-C23b | Para-Phernalia, Inc. 14603 Cedar Grove Rd. SW Issaquah, WA 98027 | NM | | Northern Lite Para-Novice Harness | | Para-Novice Softie |
| TSO-C23b | Pioneer Parachute Co. Pioneer Industrial Park P.O. Box 631 Manchester, CT 06040 | NE | | AN-QAC-24 AN-SS-24 PA-R-24-(1) PA-PC-24-() PA-TP-26-(1) PA-O-28 PA-2L-32 PA-R-23-() PA-TP-26-() PA-R-26-(1) PA-R-26C-(1) P12-B-() PA-T-1-() PA-T-35-() P5-B-24-() | AN-QAC-28 PA-R-23 P-TR-24-() PA-PC-24-() PA-TU-28 PA-O-32 PA-SP-() PA-R-23-(1) PA-R-26-() PA-R-26C-() PA-TP-26-(2) PA-T-2-() P1-QAC-28-() PA-RW-() PA-R-22-(1) | P5-QAC-28-() PA-T-() PA-CR-24-(1) PA-TU-32 PA-2L-28 PA-SP-1-() PA-PC-24-() PA-R-26-() PA-RPC-23-() PA-RPC-27-() PA-T-3-() P3-B-26-() PA-R-22-(2) Shadow 20L-(1) Shadow 22L-(1) HAPPS-(1) Shadow 22S-(1) HAPPS-(2) HAPPS-9 |
| TSO-C23b | Precision Parachute Company 125 Valley View Drive Dunlap, TN 37327 | CE-A | | S-24 | | |
| TSO-C23b | Quantum Leap Enterprises 508-B North Spring Street Lake Elsinore, CA 92330 | NM | | EC-1() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|-----------|--|
| TSO-C23b | The Relative Workshop 1050 Flight Line DeLand, FL 32720 | CE-A | | "Wonderhog" |
| TSO-C23b | Reltny Parachute Service 7520 S.W. Canyon Drive Portland, OR 97225 | NM | | Harness Model H-1() Container Model C-1() R-1() |
| TSO-C23b | The Riggers Workshop 626 S. Madison Street Iowa City, IA 52240 | CE-W | | Omega OM-4() |
| TSO-C23b | J. E. Rodriguez 2H Sunchon Fort Bragg, NC 28307 | CE-A | | Rod's Rebel |
| TSO-C23b | Rodriguez Parachute Systems, Inc. 6107-A Yadkin Road Fayetteville, NC 28303 | CE-A | | "Spanish Fly" harness |
| TSO-C23b | Security Parachute Co. P. O. Box 3096 San Leandro, CA 94578 | NM | | 63E1162-1 64B1189-1 64C1202-1 69B1451-() 500 550 75B1642-() 75B1643-() |
| TSO-C23b | Sign of the Gul 4304 5th Avenue Birmingham, AL 35222 | CE-A | | 100-() |
| TSO-C23b | Sky Sports Inc. Rural Route #2 Hutchinson, KS 67501 | CE-W | | "Super Pig and Micro Pig" |
| TSO-C23b | Sky Supplies, Inc. Route 1, Box 894A DeLand, FL 32720 | CE-A | | Rapid Transit System - 1 |
| TSO-C23b | Steve Snyder Enterprises, Inc. 5801 Magnolia Ave. Pennsauken, NJ 08109 | NE | | SST |
| TSO-C23b | Springer Enterprises 6604 Harper Road Northport, AL 35476 | CE-A | | #1():Z2762S0-S |
| TSO-C23b | The Steintal Corporation 910 North Madison Blvd. Roxboro, NC 27573 | CE-A | | 1800-() Nimbus (-2) |
| TSO-C23b | Stencel Aero Engrg. Corp P. O. Box 5836 Asheville, NC 28803 | CE-A | | 1050910-1A 448SCAT |
| TSO-C23b | Stewart Systems Waynesville Airport 4925 North State Route 42 Waynesville, OH 45068 | CE-C | | Harness P/N SH-0014: Res. Container:SC-0001 |
| TSO-C23b | Strong Enterprises, Inc. 11236 Satellite Blvd. Orlando, FL 32809 | CE-A | | 68E1001,1045() 68E1001-T,1020-(),1050-() Lo-Po LITE 1163 1200 1165-4 |
| TSO-C23b | Swoop Shop | SW | | BETA |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|------------|--|
| | 401 E. Fawnridge Drive Austin, TX 78753 | | | |
| TSO-C23b | U.S. Dept. of Agriculture Payette National Forest McCall Smokejumper Unit 500 N. Mission Street McCall, ID 83638 | NM | | T-10R |
| | AND U.S. Dept. of Agriculture Redmond Air Center 1740 S.E. Ochoco Way Redmond, OR 97756 | | | T-10R |
| TSO-C23c *F | Defence Equipment Limited Catteshall Lane, Godalming, Surrey England | EU | PARACHUTES | 350 Mk.2 MR1GQ1277 Is.1 860 Mk.2 MR1GQ1284 Is.1 |
| TSO-C23c | F.T.S., Inc. 4945 Highway 9 Alpharetta, GA 30201 | CE-A | | R202R L7R R9R L250R L9R Rascal 262:E262, R262 Rascal 202:R202 Laser 7:L7R Rascal 9:R9R Laser 250:L250R Laser 9:L9R |
| TSO-C23c | F.T.S., Inc. 4125 Nine McFarland Rd. Alpharetta, GA 30201 | CE-A | | Bogy 178:BB178R |
| TSO-C23c | Glide Path International, Inc. 2348 John Glenn Drive Chamblee, GA 30341 | CE-A | | GP-101 GP-201 GP-301 GP-401 GP-501 |
| TSO-C23c *F | GQ Parachutes, Ltd. Portugal Road Woking, Surrey GU21 5JE England | EU | | GQ650:GQ1458() GQ750:GQ1442() |
| TSO-C23c | National Parachute Industries, Inc. P.O. Box 1000 47 E. Main Street Flemington, NJ 08822 | CE-C | | NP7-1, -2, -3, -4 |
| TSO-C23c *F | Parachute Australia Pty., Ltd. 55 Philpott Street Marrickville, Sydney N.S.W. 2204, Australia | NM | | Talon:6111-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|--|---|--|
| TSO-C23c *F | Parachutes DE France S.A. 9 chaussee Jules Cesar, BP 247 95523 Cergy-Pontoise Cedex France | EU | | P-512(XX)(XX) | | |
| TSO-C23c | Para-Flite, Inc. 5800 Magnolia Ave. Pennsauken, NJ 08109-1399 | NE | | Emergency Parachute 827400-0 | 827700 | 807000-0 |
| TSO-C23c | Performance Designs, Inc. 1300 Int'l Speedway Blvd. Deland, FL 32724 | CE-A | | PD143R PD193R | PD160R PD218R | PD176R PD253R |
| TSO-C23c | Precision Parachute Company P.O. Box 691 Dunlap, TN 37327 | CE-A | | Raven Model 1() Raven Model 2() Raven Model 3() Raven Model 4() Micro-Raven 150() Falcon 150(), 175(), 195(), 215(), 235(), 265(), 300() | | |
| TSO-C23c | Relative Workshop 1725 Lexington Avenue Deland, FL 32720 | CE-A | | Harness container P/N VT-1 Parachute canopy P/N VTC-1 | | |
| TSO-C23c | Rigging Innovations, Inc. 236-A East Third St. P.O. Box 896 Perris, CA 92370 | NM-L | | 6111-() | 6113-() | |
| TSO-C23c | Sun Path Products, Inc. 5037 Gall Blvd. Zephyrhills, FL 34248 | CE-A | | JH-101() | JC-101() | |
| TSO-C24 | TSO Cancelled Flares no longer required, few in use | | LANDING FLARES | | | |
| TSO-C25 | Aerosmith Products Corp. P. O. Box 542 Miami, FL 33144 | CE-A | AIRCRAFT SEAT AND BERTHS (TYPE I TRANSPORT, 6g FORWARD LOAD) | A2-22 C-15 C-18 C-111 C-224 H31 J117-3 L-4009 N3 N14B N24 N38 SX107 W19 W27 WN19 WN29 WNS38 X-1000 | C-11 C-16 C-19 C-112 CT-11 J2 J117-4 LRL-SW1 N3F N19A N28 N228 SX-1000 W24 W29 WN24-L/R WN31EAL X107 X-2000 | C-14 C-17 C-110 C-114 H21 J2A L20 LRL-W2 N14 N19B N34 SP-1 W14 W25 WN14 WN27 WNS28 X207 |
| TSO-C25 | Aircraft Mechanics, Inc. Mechanical Division 3200 N. Nevada Ave. P. O. Box 370 Colorado Springs, CO 80901 | NM | | 540-L | 540-R | |
| TSO-C25 | Airesearch Aviation Co. | NM | | 125-DC7-005 | 125-DC7-008 | 125-DC7-010 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|---|------|-----------|--|--|---|
| | Div. Garrett Corp. Airline Products Facility 19201 Susana Rd. Compton, CA 90221 | | | 125-DC7-011 1678-124-1 5594258-5 C-6200-15 | 1609-124-1A 5535929 S-100-338 C-2600 Ser. | 1609-125-1A 5594258-3 C-3500-13 C-4600 Ser. |
| TSO-C25 | Amerock Corporation Rockford, IL 61101 | CE-C | | 1-A | 1-B | |
| TSO-C25 | Beech Aircraft Corp. 9709 E. Central Wichita, KS 67201 | CE-W | | 414-183303 | | |
| TSO-C25 | Douglas Aircraft Co. McDonnell Douglas Corp. 3855 Lakewood Blvd. Long Beach, CA 90801 | NM | | 3535870 3535890 5405325 5535850 | 3535879 5346525 5406900 5596000 | 3535880 5402900 5490490 5597086 |
| TSO-C25 | Executive Air Service, Inc. Redbird Airport Dallas, TX 75221 | SW | | Model 100 | SW-1000 A1 | SW-1000 A2 |
| TSO-C25 | Fairchild Burns Co. Div. of Fairchild Ind. Inc. 1455 Fairchild Dr. Winston Salem, NC 27105 | CE-A | | 102-4 1345 1455 1450-SLRT 1465-1 1465-9 1520 1560 1590 1607 1630 1650 1670 1695-4 1720 1740-7 1790 1835 1840-6 1925-2 2081-4 2100 2110 2130 2640 2850 2875-4 2880-3 2880-6 2900-1 2926 2990 3059 3073 3190 3320-1 1-C-2 1C2-F2-M 2C2-7 6D1-2ST 11D1BT 14DH1-T 1-D() 8-D() | 1221ST 1425 1555-1 1455-LR 1465-2 1475 1540 1575 1595 1610 1635 1656 1680 1700 1730 1751 1825-1 1840 1850 1941 2081-74 2100-2 2120 2150 2640-20 2870 2875-5 2880-4 2895 2921 2927 2990-1 3059-1 3075 3240 1-B-1-2 1-C-2F-1 1C2-F2-NL 2C2-8 6D1-2S-1 11D1RBT 10GA1-SLRT 2-D() 1465FAR | 1221-6 1450 1460 1465 1465-8 1495 1550 1585 1599 1620 1640 1660 1690 1710 1740 1755 1825-2 1840-5 1925-1 2081 2095 2100-4 2120-1 2580 2800 2875-3 2875-6 2880-5 2900 2925 2927-1 2990-2 3071 3085 3245 1-B-2-2 1C2-2 2C2-2 2C3-1 11D1 14DH2 10GA2-LRT 7-D() 1465() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|-----------|--|
| | | | | 1740() 2110() 2940() 3330() 3400() 3410() 3470() 3530() B1600-1 B1600-2 B1601-1 B1700-1 B1700-2 B1701-1 B1701-2 B1701-2H B1701-501 B1701-502 B1702-1 B1702-3 B1728-2 B1729-1 B1734-2 B1807-1 B1801-1 B1808-1 B1808-2 B1814-1 B1814-3 B1829-2 B1829-4 B1833-2 B1833-4 B1838-1 B1838-2 B1839-1 B1599H() B1710() B1711() B1599 B1800() B1801() B1809() B1810() B1811() B1815() B1816() B1830() 1825-1 1825-2 1850-2 |
| TSO-C25 | Flight Equipment & Engineering Corporation P. O. Box 173 Miami, FL 33148 | CE-A | | 102 102-3 105 105-1 106 106-1 107() 201 201-1 405 702 A12 A12-H A12-3H A22H() A27-F A27-FT A22FT A22() A32() A37-FT A32-F B11 B12-G B12-3H B21 B21A B22() B22H C-11 C12 C-21 C-21-2 C-22 C-22-2 C-30 C-31 E22 E22-2 P-1 P-2 P-3 S-11 21012() 21010() TE-317-2 TE-317-3 101() |
| TSO-C25 | General Motors Corp. Detroit, MI 48233 | CE-C | | 69-9910 |
| TSO-C25 | Hardman Aerospace A Macrodyne-Chatillon Co. 1845 S. Bundy Dr. Los Angeles, CA 90025 | NM | | 611 615 623 625 1200 M 2003 S 2003 WD 3003 3004 3017 D 3017 T 3019 3020 D 3020 T 3022 D 3023 3024 3025 D 3025T 3025 TH 3027 D 3027 T 3028 D 3028 T 3030 3031 3032 D 3032 T 3032 V 3034 3038 3041 D 3041 NDA 3042 D 3042 T 3044 3045 3050 3059 D 4007 M 4012 D 4012 T 3000 Ser. 3015 Ser. 3040 Ser. 3048 Ser. 3053 Ser. |
| TSO-C25 | Horton & Horton Custom Works SW Fort Worth, TX 76101 | | | CE0-100 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|-----------|--|--|--|
| TSO-C25 | Inter'l Acft. Service Inc. Sun Valley, CA 91352 | NM | | 61001 Ser. | 62002 Ser. | |
| TSO-C25 | Liljengren Engineering Co. P. O. Box 1451 Miami, FL 33101 | CE-A | | L-10 | L-20 | L-3000 |
| TSO-C25 | National Airlines, Inc. P. O. Box 2055, AMF Miami, FL 33159 | CE-A | | G-47-3035 G-47-3038 G-47-3043 | G-47-3036 G-47-3039 | G-47-3037 G-47-3042 |
| TSO-C25 | Northwest Airlines, Inc. Minn-St.Paul Int'l Arpt. St. Paul, MN 55111 | CE-C | | Crew Berths | | |
| TSO-C25 | Pan Air Corporation New Orleans, LA 70113 | SW | | PAC 2 Type 2P | PAC 162 Type 1P | |
| TSO-C25 | Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102 | CE-A | | W101DA W101SF | W101DF | W101SA |
| TSO-C25 | PTC Aerospace Aerospace Division Bantam, CT 06750 | NE | | 154-1J 158D 320 Ser. 343A-2 366P-2 443 Ser. 454 461-3 475-2 481-2 512 520A-3 525-2 527-3 541-2 | 154-2J 219D 335 Ser. 353-2 391A-2 449 454A 471-2 475-3 498-2 517-2 523-1 525-3 531D-2 555 Ser. | 157F 290 Ser. 343-2 357 Ser. 441 Ser. 450 461-2 471-3 476-3 501-2 520A-2 523-2 527-2 540A 621 Ser. |
| TSO-C25 *F | L. A. Rumbold Ltd. Old Oak Common Lane London N.W. 10 6 DX England | EU | | M305 M-431 M609 | M306 M502 | M430 M503 |
| TSO-C25 | Rupert Industries, Inc. P. O. Box 624 Wheeling, IL 60090 | CE-C | | 65 | 82 | |
| TSO-C25 *F | SABENA Brussels National Airport B-1930 Zaventem, Belgium | EU | | 687-AA 1-6476 | 687-AB 1-6477 | 687-AC 1-6478 |
| TSO-C25 | Safeair Manufacturing Corp. Miami, FL 33101 | CE-A | | S-2L S-10C S-30L | S-2R S-20A S-30R | S-10 S-20B S-100 |
| TSO-C25 *F | Scandinavian Airlines Sys. Kastrup, Denmark | EU | | 440457 | | |
| TSO-C25 | Sinclair Refining Co. Tulsa, OK 74101 | SW | | N5768A | N5768B | N5768C |
| TSO-C25 | Sky Service, Inc. Bethany, OK 73008 | SW | | 57 | | |
| TSO-C25 | Southern Air Transport, Inc. | CE-A | | SAT-R0-001 | SAT-R0-002 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|---|---|--|--|
| | Miami, FL 33101 | | | | | |
| TSO-C25 | Spartan Aircraft Co. Tulsa, OK 74101 | SW | | Part Number Not Furnished | | |
| TSO-C25 *F | Swiss Air Transport, Ltd. (Swissair) Zurich, Flughafen Switzerland | EU | | 9000 | | |
| TSO-C25 | Weber Aircraft, Inc. Special Products Div. 1300 E. Valencia Dr. Fullerton, CA 92631 | NM | | 200 1603 71914 71917 72101 72104 72524 72652 72775 74412 210011 | 1601 71912 71915 72002 72102 72481 72525 72654 72784 75832 210213 | 1602 71913 71916 72100 72103 72523 72576 72764 72929 75860 800999 |
| TSO-C25a | Aerosmith Products Corp. P. O. Box 542 Miami, FL 33144 | CE-A | AIRCRAFT SEAT AND BERTHS (TYPE I TRANSPORT, 6g FORWARD LOAD) | B126A C119 L-4005 N217 N317-3 SX107A-1 WN21EAL X106-1 X106-4 X106-7 X106-102 X106-105 X110 X206B | C-15D J217 L-4013 N217-1 SM-1 SX107A-2 WN27A X106-2 X106-5 X-106-8 X106-103 X106-107 X126A X206-T | C-113 L-4004 N215P N317 SX107A W27A X106 X106-3 X106-6 X106-101 X106-104 X106-108 X206 X106-106 |
| TSO-C25a | AiResearch Aviation Co. Div. Garrett Corp Airline Products Facility 19201 Susana Rd. Compton, CA 90221 | NM | | 127-STD-006 | | |
| TSO-C25a | American Airmotive Corp. P. O. Box 187 Miami International Airport Miami, FL 33148 | CE-A | | TAAC2 | TAAC3 | 25-58-002 |
| TSO-C25a | Associated Aircraft Equip. P. O. Box 542 Miami, FL 33148 | CE-A | | A22FT() AWN-1() F-100-2B() FLAM-1D() MD100-3 D3 AAE525() | AA32FT() F-100-2() F-200D K14S N14S D4 FAM22G() | AWN() F-100-2A() FAM-105() MD100-2 N14SB AAEB1600 |
| TSO-C25a | Fairchild Burns Co. Div. of Fairchild Ind. Inc. 1455 Fairchild Dr. Winston Salem, NC 27105 | CE-A | | 8DH1-11() B1599() BTE370B-3 BTE558 | B1600E B1599K() BTE432() P161-1-21() | B1601E BTE370B-2 BTE515() |
| TSO-C25a | Flight Equipment & Engineering Corporation P. O. Box 173 | CE-A | | 610 | 610-3 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-------------------------------|---|
| | Miami, FL 33148 | | | |
| TSO-C25a *F | Flying Service Engrg. & Equipment, Ltd. Springfield Road Chesham, Bucks HP5 1PP, England | EU | | D2001() F2002() |
| TSO-C25a | Hardman Aerospace A Macrodyne-Chatillon Co. 1845 S. Bundy Dr. Los Angeles, CA 90025 | NM | | 340DA |
| TSO-C25a | 4/Flight Industries 24955 Avenue Kearny Valencia, CA 91335 | NM | | 125 310()() 350-1 350-2 370()() 480() |
| TSO-C25a | Regina Airlines Miami Springs, FL 33166 | CE-A | | M-2D2 |
| TSO-C26 | Aircraft Braking Systems Corporation 1204 Massillon Road Akron, OH 44306-4186 | CE-C | AIRCRAFT WHEELS AND BRAKES | WHEEL ASSEMBLIES 9540977 |
| TSO-C26 | Airglas Engineering Co. Inc. P. O. Box 6107 Anchorage, AK 99502 | NM | | LWA wheel adapters |
| TSO-C26 | Bendix Energy Controls Div. 717 N. Bendix Dr. South Bend, IN 46620 | CE-C | | WHEEL ASSEMBLY 150611-1 150611-2 150611-3 150741 150741-1 150741-2 150741-3 150741-4 150741-5 150741-6 150757 150757-1 150835-5 151278-1 151655-5 151882-1 152051-2 152051-3 152061-1 152061-2 152061-3 152075-1 152889-2 153245-2 153400-1 153950-1 154251-1 154890-1 2601043-1 2601041-1 2601043-1 2601181-2 2601411-1 2603441-2 2603561-2 2603561-3 2603511-1 BRAKE ASSEMBLY 149482M-ST 150550-1 150550-3 150550-7 150550-9 150612-1 151135-1 151135-2 151158-1 151158-2 151395-1 151849 151851 151882-2 151924-1 151924-3 151955-1 152062-2 152062-3 152481-4 152482-1 152482-2 152889-1 153235-3 153950-1 154251-1 154251-2 154778-1 2600341-1 2600342-1 2601043-1 2601042-3 2601042-1 2601902-4 2602012-4 2603442-1 2603703-11 260377-2 2605155-1 2601182-2 2601902-1 2601182-6 WHEEL/BRAKE ASSEMBLY 2603561-1, -2, -3, -4, -5, -8/2605155-1 2603561-1, -2, -3, -4, -5, -8/ 2601902-1, -2, -3, -4, -5, -6 2603561-1, -2, -3, -4, -5, -8/2602012-3, -4, -5 2601901-1, -2, -3/2605392-1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|----------------|---|
| | | | | 2601901-1,-2,-3/2602012-3,-4,-5 2601901-1,-2,-3/2601902-1,-2,-3,-4,-5,-6 |
| TSO-C26 *F | Dunlop Limited Holbrook Lane Coventry CV6 4AA England | EU | WHEEL ASSEMBLY | AH50143 AH50643 AH50710 AH50764 AH50780 AH50786 AH50822 AH50841 AH50869 AH50916 AH50940 AH51060 AH51090 AH51128 AH51129 AH51138 AH51141 AH51142 AH51157 AH51177 AH51185 AH51291 AH51292 AH51299 AH51322 AH51491 AH51609 AH51691 AH52033 |
| | | | BRAKE ASSEMBLY | AH50781 AH50782 AH50824 AH50864 AH50865 AH50866 AH50867 AH51030 AH51080 AH51124 AH51179 AH51186 AH51187 AH51293 AH51323 AH51324 AH51461 AH51502 AH51531 AH51532 AH51610 AH51611 AH51658 AH51659 AH51680 AH51681 AH51767 AH51768 |
| TSO-C26 | General Tire & Rubber Co. Government Aviation Div. P. O. Box 951 Akron, OH 44309 | CE-C | WHEEL ASSEMBLY | 214A99M1 219A967/-1 |
| TSO-C26 | B. F. Goodrich Engineered Systems Co. Div. of B. F. Goodrich P. O. Box 340 Troy, OH 45373 | CE-C | WHEEL ASSEMBLY | B-3-41A Y-3-163M D-3-761-MD-2 3-661-1 3-699-2 3-787-1 G-3-852 G-3-853 G-3-880 G-3-897 H-3-650M H-3-735 H-3-752 H-3-772 H-3-808 H-3-845 H-3-857 H-3-866 H-3-895 3-913 3-917 3-919 3-920 3-921 3-929-1 3-958 3-978 3-999 3-1002-3 3-1003 3-1022 3-1027 3-1029 3-1034 3-1036-1 3-1038 3-1047 3-1070 3-1081 3-1082 3-1086 |
| | | | BRAKE ASSEMBLY | D-2-565-1 D-2-662R/L G-2-597 G-2-597-6 G-2-608-2 G-2-609 G2-597-5 D-2-622 G-2-626 H-2-603 G-2-626 G-2-639 H-2-555-1 H-2-602-3 H-2-603-3 H-2-623 H-2-629-3 H-2-630-3 H-2-642 H-2-647 H-2-648 H-2-660 H-2-661 2-3977 2-5977 2-697* 2-720 2-721 2-699 2-747 2-722 2-735** 2-740 2-756-1 2-773 2-784-1 2-786 2-798 2-798-3 2-798-4 2-849-2 2-849-4 2-863 2-864 2-872 2-872-1 2-872-2 2-872-3 2-873 2-899 2-931 2-931-1 2-931-2 2-936 |

TSO NO. HOLDER NAME & ADDRESS RG TSO TITLE MODELS OR PART NUMBERS
 =====

2-991 2-993 2-1101
 2-1104 2-1123-2 2-1134
 2-B1138 2-1139 2-1147
 2-1147-1 2-1147-2 2-1174-1
 2-1195-1 2-1195-6 2-1195-7
 2-B1283 14-1119
 * With automatic adjuster 107-100
 and 107-133
 ** With automatic adjuster 107-100
 WHEEL/BRAKE ASSEMBLY
 3-991-3/2-784-1 3-1093-1/2-936-3
 3-1283/2-1203 3-1283/2-1205
 3-1283/2-1205-1 3-81283/2-81138
 3-1283/2-1244 3-1287/2-1147-1
 3-1287/2-1190 3-1304/2-1174
 3-1304-1/2-1174 3-1306/2-1147
 3-1306/2-1147-1 3-1306/2-1147-2
 3-1306/2-1147-3 3-1309/2-1185
 3-1311-1/2-1195-1 3-1311-3/2-1195-1
 3-1311-3/2-1195-5, -6, -7
 3-1313/2-1206 3-1313/2-1061-1
 3-1337/2-1268 3-1345/2-1284
 3-1341/2-1301

In addition, the applicant has stated that all Goodrich models previously approved under the type certification system will meet all the provisions of TSO-C26 requirements

TSO-C26 Loral Systems Group
 Aircraft Braking
 Systems Div.
 1210 Massillon Road
 Akron, OH 44315-0001

CE-C

WHEEL ASSEMBLY
 510656M 511960S 512129M
 530462M-1 530751M 530858-M1
 530884G 530884M 531031
 5000002 5000307 5000402
 5000404 5000519 5000708
 5000919 5000919-1 5000306
 5000306-1 5000437-1 500436
 5002198 9520265 9520653
 9530505 9530506 9530853
 9530895 9531065 9531193
 9531319 953133 9531374
 9531392 9531395 9531432
 9531442 9531445 9531447
 953145 9531502 9531528
 9531622 9531638 9531651
 9531637-1 9531711 9531718
 9531794 9531832 9531846
 9531924 9531925 9531932
 9531942 9531952 9531954
 9531966 9532014 9532039
 9532101 9532102 9532111
 9532424 9532425 9532453
 9532489 9532498 9532515
 9532522 9532549 9532112
 9532135 9532186 9532197
 9532242 9532254 9532278
 9532305 9532554 9532614
 9532615 9532669 9532673
 9532674 9532692 9532725R
 9532761 9532926 9532975
 9532976 9533232 9533233
 9533235 9533961 9533983
 9534088 9535725-() 9535725
 9536304 9540484 9540512
 9540552 9540753 9540754

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|------------------------|
| | | | | 9540758 |
| | | | | 9540862 |
| | | | | 9540906 |
| | | | | 9540977 |
| | | | | 9541085 |
| | | | | 9541259 |
| | | | | 9541333 |
| | | | | 9541352 |
| | | | | 9541438 |
| | | | | 9541514 |
| | | | | 9541543 |
| | | | | 9541591 |
| | | | | 9541617 |
| | | | | 9541687 |
| | | | | 9541737 |
| | | | | 9541746 |
| | | | | 9541874 |
| | | | | 9541932 |
| | | | | 9542045 |
| | | | | 9542265 |
| | | | | 9542297 |
| | | | | 9542327 |
| | | | | 9542429 |
| | | | | 9542496 |
| | | | | 9542623 |
| | | | | 9542639 |
| | | | | 9542678 |
| | | | | 9542709 |
| | | | | 9542796 |
| | | | | 9543079 |
| | | | | 9543162 |
| | | | | 9543339 |
| | | | | 9543426 |
| | | | | 9543531 |
| | | | | 9543629 |
| | | | | 9543705 |
| | | | | 9543785 |
| | | | | 9550207 |
| | | | | 9550463 |
| | | | | 955463-1 |
| | | | | 9450484 |
| | | | | 9560892 |
| | | | | 9544391-1 |
| | | | | 5E3-5619 |
| | | | | 5E5-304 |
| | | | | 9540806 |
| | | | | 9540876 |
| | | | | 9540934 |
| | | | | 9541026 |
| | | | | 9541192 |
| | | | | 9541302 |
| | | | | 9541334 |
| | | | | 9541364 |
| | | | | 9541493 |
| | | | | 9541519-2 |
| | | | | 9541545 |
| | | | | 9541598 |
| | | | | 9541624 |
| | | | | 9541731 |
| | | | | 9541743 |
| | | | | 9541823 |
| | | | | 9541876 |
| | | | | 9541934 |
| | | | | 9542068 |
| | | | | 9542293 |
| | | | | 9542301 |
| | | | | 9542334X |
| | | | | 9542468 |
| | | | | 9542557 |
| | | | | 9542637 |
| | | | | 9542662 |
| | | | | 9542699 |
| | | | | 9542794 |
| | | | | 9542882 |
| | | | | 9543143 |
| | | | | 9543164 |
| | | | | 9543341 |
| | | | | 9543431 |
| | | | | 9543591 |
| | | | | 9543637 |
| | | | | 9543751 |
| | | | | 9543809 |
| | | | | 9550265 |
| | | | | 9550493 |
| | | | | 9558187 |
| | | | | 9560791 |
| | | | | 9560906 |
| | | | | 5E3-5196 |
| | | | | 5E4-3340 |
| | | | | 9560569 |
| | | | | BRAKE ASSEMBLY |
| | | | | 500709-1 |
| | | | | 5000298-1 |
| | | | | 5000758-3 |
| | | | | 500758-11 |
| | | | | 9520926 |
| | | | | 9530303 |
| | | | | 9530721 |
| | | | | 9531194 |
| | | | | 9531393 |
| | | | | 9531456 |
| | | | | 9531712 |
| | | | | 9531833 |
| | | | | 9532019 |
| | | | | 9532167 |
| | | | | 9532278 |
| | | | | 9532412 |
| | | | | 9532475 |
| | | | | 9532693 |
| | | | | 9532699 |
| | | | | 5000003-2 |
| | | | | 5000486-1 |
| | | | | 5000919 |
| | | | | 9522181 |
| | | | | 9530504 |
| | | | | 9530997 |
| | | | | 9531386 |
| | | | | 9531446 |
| | | | | 9531597 |
| | | | | 9531731 |
| | | | | 9531926 |
| | | | | 9532109 |
| | | | | 9532181 |
| | | | | 9532292 |
| | | | | 9532448 |
| | | | | 9532485 |
| | | | | 9532694 |
| | | | | 9532725 |
| | | | | 9520297-1 |
| | | | | 5000758-1 |
| | | | | 9520425 |
| | | | | 9522181 |
| | | | | 9530504 |
| | | | | 9530997 |
| | | | | 9531386 |
| | | | | 9531446 |
| | | | | 9531637-1, -2 |
| | | | | 9531779 |
| | | | | 9531933 |
| | | | | 9532113 |
| | | | | 9532243 |
| | | | | 9532355 |
| | | | | 9532449 |
| | | | | 9532491 |
| | | | | 9532698 |
| | | | | 9540528 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | | | | 9540494-1 |
| | | | | 9540559-1 |
| | | | | 9540039-1 |
| | | | | 9540266-1 |
| | | | | 9540504-1 |
| | | | | 9540505-1 |
| | | | | 9540534-1 |
| | | | | 9540711-1 |
| | | | | 9540713-1 |
| | | | | 9540755-1 |
| | | | | 9540716-1 |
| | | | | 9540534 |
| | | | | 9540553 |
| | | | | 9540731 |
| | | | | 9540754 |
| | | | | 9540755 |
| | | | | 9540883-1 |
| | | | | 9540886 |
| | | | | 9540968 |
| | | | | 9540973 |
| | | | | 9541047 |
| | | | | 9540998-1, -2, -3 |
| | | | | 9541101-1, -3 |
| | | | | 9541193 |
| | | | | 9541302 |
| | | | | 9541308 |
| | | | | 9541353 |
| | | | | 9541432 |
| | | | | 9541515 |
| | | | | 9541519-2 |
| | | | | 9541543 |
| | | | | 9541544 |
| | | | | 9541573 |
| | | | | 9541599 |
| | | | | 9541626 |
| | | | | 9541626A |
| | | | | 9541584 |
| | | | | 9541658 |
| | | | | 9541685 |
| | | | | 9541731 |
| | | | | 9541877 |
| | | | | 9541968 |
| | | | | 9542384 |
| | | | | 9550208 |
| | | | | 9550266 |
| | | | | 9550405 |
| | | | | 9550504 |
| | | | | 9560156-1 |
| | | | | 9541519-4 |
| | | | | 530886S-2 |
| | | | | 530886G-2 |
| | | | | 530886SG-2 |
| | | | | 9560164 |
| | | | | 9560166-1 |
| | | | | 9560185-1 |
| | | | | 9560188-1 |
| | | | | 9560209 |
| | | | | 9560229 |
| | | | | 9560231 |
| | | | | 9560245 |
| | | | | 9560246 |
| | | | | 9560285 |
| | | | | 9560286 |
| | | | | 9560306 |
| | | | | 9560351 |
| | | | | 9560364 |
| | | | | 9560385 |
| | | | | 9560393 |
| | | | | 9560394 |
| | | | | 9560447 |
| | | | | 9560448 |
| | | | | 9560478 |
| | | | | 9560479 |
| | | | | 9560507 |
| | | | | 9560531 |
| | | | | 9560788-5 |
| | | | | 9560669-1 |
| | | | | 9560746 |
| | | | | 9561043 |
| | | | | 5E3-5619 |
| | | | | 5E4-1816 |
| | | | | WHEEL/BRAKE ASSEMBLY |
| | | | | 3080D/37-200A |
| | | | | 5000001/5000003 |
| | | | | 5000306/5000003 |
| | | | | 5000206/5000486 |
| | | | | 5000306/5000709 |
| | | | | 5000444/5001571, 9550377 |
| | | | | 5000402/5000403 |
| | | | | 5000405/5000403 |
| | | | | 5000444/9550377-4 |
| | | | | 9530505/9520506 |
| | | | | 9581925/9532425 |
| | | | | 9532424/9532425 |
| | | | | 9542068/9560585 |
| | | | | 9542566/9560669 |
| | | | | 9543989/9550608 |
| | | | | 9544391/9561113 |
| | | | | 9550207/9550208 |
| | | | | 9220207-1/5000263 |
| | | | | 9550265/9550661 |
| | | | | 9550463/9550208 |
| | | | | 9550463-1/5000268 |
| | | | | 9550493/9550494 |
| | | | | 9550609/9560965 |
| | | | | 9560571B/9560949 |
| | | | | 9560787/9560788 |
| | | | | 9560892/9560788 |
| | | | | In addition, the applicant has stated that all Goodyear models previously approved under the certification system will meet all the provisions of TCO-C26 requirements |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-------------------------------|---|
| TSO-C26 | Parker Hannifin Corp. Aircraft Wheel & Brake Div. 1160 Avon Center Rd. Avon, OH 44011 | CE-C | | WHEEL ASSEMBLY 27-100(40-26) 27-100D(40-1) 3040(40-6) 3050(40-7) 3060 3070(40-5) 3080 3080E(40-4) 40-10 40-11 40-12 40-16 40-21 40-24 40-32 40-37 40-61 40-80 BRAKE ASSEMBLY 30-4 30-5 30-7 30-6 30-9 30-18 30-21 30-23 30-24 35-200(30-14) 35-200A(30-1) 37-200(30-8) 3000 3000-250(30-12) C2000(30-2) C7000(30-3) WHEEL/BRAKE ASSEMBLIES 40-57/30-40 40-75/30-52 40-86/30-55 40-97/30-63 40-98/30-69 40-98/30-66 40-113/30-75 40-113()/30-75() 30808/37-200-2 30800/37-2008 40-132/30-97 40-131/30-96 40-78/30-9 AUX. WHEEL ASSEMBLY (NOSEWHEEL) 500-100 40-2 40-77 |
| TSO-C26a | Aircraft Braking Systems Corporation 1204 Massillon Road Akron, OH 44306-4186 | CE-C | AIRCRAFT WHEELS AND BRAKES | WHEEL ASSEMBLY 9543809 9532926-6 9532926-7 5000444-3 9544382-2 9540512 9560892 9560859-7 BRAKE ASSEMBLY 9550377-2 9560788-7 9542558-2 9560861-3 NOSE WHEEL ASSEMBLY 9532186-3 |
| TSO-C26a | The Bendix Corporation Aircraft Brake & Strut Div. 3520 West Westmoor Street P.O. Box 10 South Bend, IN 46624 | CE-C | | WHEEL/BRAKE ASSEMBLY 2601041-1/2601042-4 |
| TSO-C26a | Bendix Energy Controls Div. 717 N. Bendix Dr. South Bend, IN 46620 | CE-C | | WHEEL ASSEMBLY 152051-1 152051-4 152051-5 152075-2 152481-3 152081-4 152888-1 153245-1 153245-3 154234-1 154478-1 154251-2 154480-1 2600341-1 2600342-1 2600811-1 2601045-1 2601045-2 2601411-2 2601505-1 2601571-1 2601901-1 2602095 2603441-1 2603561 2603561-1 2603561-2 2603561-3 2604589-1 2604561-1 2604601-1 BRAKE ASSEMBLY 150550-11 150787-1 150787-2 150787-3 150787-4 151183-2 151882-1 151882-2 151882-3 151882-4 152052-1 152052-2 152482-5 152889-2 154252-1 154252-2 154252-3 154252-4 154479-1 2600997-1 2600997-2 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|---|
| | | | | 2600997-3 2601042 2601042-3 2601182-1 2601182-4 2601182-5 2601182-6 2601225-1 2601240-1 2601412-1 2601412-2 2601901-1 2601902-1 2602902-2 2601902-3 2602012-1 2602012-2 2602012-3 2603442-2 2603703-1 2603703-12 2603703-13 2603732 WHEEL/BRAKE ASSEMBLY 2601411-2/2601412-2 |
| TSO-C26a *F | Dunlop Ltd. Holbrook Lane Coventry, CV6 4AA, England | EU | | WHEEL ASSEMBLY AH51687 AH51691 AH52033 AH52171 AH52228 AH52279 AH51178 BRAKE ASSEMBLY AH51852 AH51853 WHEEL/BRAKE ASSEMBLY AH52617/AH52618 AH52623/AH52618 AH52771/AH51186 AH52771/AH51187 |
| TSO-C26a | General Tire & Rubber Co. Cuyahoga Falls, OH 44222 | CE-C | | WHEEL ASSEMBLY 12.50-16 219A967/-1 |
| TSO-C26a | George M. Adams 1031 W. Alondra Blvd. Compton, CA 90220 | NM | | WHEEL ASSEMBLY DGA-2000 JO-200F-3 JO-200FM-3 |
| TSO-C26a | B. F. Goodrich Engineered Systems Co. Div. B. F. Goodrich Co. P. O. Box 340 Troy, OH 45373 | CE-C | | WHEEL ASSEMBLY 3-991-3 3-1001 3-1002-1 3-1003-4 3-1069 3-1076 3-1078 3-1092 3-1093-1 3-1095 3-1102 3-1103 3-1104 3-1112 3-1118 3-1124 3-1129 3-1130-1 3-1142 3-1142-2 3-1146 3-1162 3-1162-2 3-1162-3 3-81164 3-81165 3-1174 3-1183 3-1190 3-81194 3-1197 3-1208 3-1208-1 3-81209 3-81209-1 3-1214 3-1215 3-1225 3-1240 3-1243 3-1245 3-1247 3-1249 3-1249-1 3-1251 3-1252 3-1253 3-1274 3-1279 3-1279-1 3-1281 3-1282-5 3-1283 3-81285 3-1287 3-1288 3-1290 3-1295 3-1297 3-1304 3-1306-1 3-1311 3-1312 3-1313 3-1313-1 3-1317 3-1319 3-1319-1 3-1320 3-1331 3-1349 3-1369-1 BRAKE ASSEMBLY 2-756-2 2-849-4 2-872 2-872-3 2-872-4 2-872-5 2-863 2-873 2-899 2-931 2-931-1 2-931-2 2-931-3 2-934 2-935 2-936-1 2-936-3 2-955 2-8977 2-991 2-993 2-993-1 2-998 2-81011 2-1090 2-1093 2-1106 2-1123-2 2-1133-1, -3 2-1135 2-81138 2-1139 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|---|
| | | | | 2-1147 2-1147-1 2-1147-2 |
| | | | | 2-1172-1 2-1192 2-1203 |
| | | | | 2-1205 2-1205-1 2-1206-1 |
| | | | | 2-1206-2 2-1206-3 2-1216 |
| | | | | 2-1244 2-1244-1 |
| | | | | BRAKEDRUM |
| | | | | G-13-280 G13-280-1 |
| | | | | WHEEL/BRAKE ASSEMBLY |
| | | | | 3-1162/2-756-2 3-1174/2-993-1 |
| | | | | 3-1247/2-1090 3-1252/2-1142 |
| | | | | 3-1252/2-1192 |
| | | | | 3-1281/2-1133-1, -2, -3 |
| | | | | 3-1283/2-1244-1 3-1297/2-1172-1 |
| | | | | 3-1306/2-872() 3-1306/2-931() |
| | | | | 3-1312/2-1172-1 3-1313-1/2-1206-2 |
| | | | | 3-1313-1/2-1206-3 3-1317/2-1216 |
| | | | | 3-1333/2-1262 |
| | | | | 3-1370/2-1244-1, 2-1138, 2-1203 |
| | | | | 3-1373/2-878, 2-971, 2-1087, 2-1103 |
| | | | | In addition, the applicant has stated that all Goodrich models previously approved under the type certification system will meet all the provisions of TSO-C26 requirements |
| TSO-C26a | Loral Systems Group Aircraft Braking Systems Div. Akron, OH 44315-0001 | CE-C | | WHEEL ASSEMBLY |
| | | | | 5000437 5000444-3 |
| | | | | 9535725-1 9541587 A9541624 |
| | | | | 9542876 9542918 95544382-2 |
| | | | | 9542988 9542898-1 9542989-1 |
| | | | | 9543027 9543062 9543138 |
| | | | | 9543447 9543871 9543928 |
| | | | | 9543939-1 9543998 9544037-2 |
| | | | | 9544058 9544061 9544171 |
| | | | | 9544207 9544318 9544382() |
| | | | | 9544396 9550107 9550262 |
| | | | | 9550267 9550267-3 9550267-4 |
| | | | | 9550328 9550332 9550377-1, -4 |
| | | | | 9550337 9550504 9550597 |
| | | | | 9550706 9550657 9560556 |
| | | | | 9560571B 9560645 9560708 |
| | | | | 9560786() 9560787 9560859 |
| | | | | 9560859-1 9560859-2 9560859-3 |
| | | | | 9560859-4 9560892 9560901 |
| | | | | 9561061() 9541624 |
| | | | | BRAKE ASSEMBLY |
| | | | | 5001571-3 5000758-11 5000709-2 |
| | | | | 5000709-3 5000709-4 9531637-2 |
| | | | | 9540245-1, -2 9540485-1, -2 |
| | | | | 9540976-1, -2 9540998-1, -2, -3 |
| | | | | 9541659-1, -2 |
| | | | | 9541104-1, -2, -3, -4 |
| | | | | 9541105-1, -2 9541732 9541659-1, -2 |
| | | | | 9542111 9542989-1 9542558 |
| | | | | 9542711 9542866-1, -2 |
| | | | | 9543946-1, -3 |
| | | | | 9550092 9550125 9550212 |
| | | | | 9550273 9550336 9550338 |
| | | | | 9550427 9550608 95601 |
| | | | | 9560569 9560646 9560551 |
| | | | | 9560791 9560651 9560685 |
| | | | | 9560738 9560742 9560743 |
| | | | | 9560746A 9560786 9560788 |
| | | | | 9560812 9560954 9560955 |
| | | | | 5E5-304 2-1147-4 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------|---|----------------|----------------|---|----------------------|------------|----------------|----------------|-----------|--------|-----------|-----------|-------|--------|---------|--------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|----------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|-------|-------|-------|-------|--------|--------|--------|--------|---------|---------|---------------|--|------------|--|--|-------|-------|-------|-------|-------|-------|-------|-------|-------|----------|-------|-------|-------|-------|-------|-------|-------|----------|----------|-------|-------|-------|-------|-------|-------|-------|--|--------------|-------------|--------------|--------------|--------------|--|
| | | | | <p>WHEEL/BRAKE ASSEMBLY</p> <p>5000444/9550377-4 9541498/9543946</p> <p>9542988/9543946 9543051/9550377-4</p> <p>9543138/9541650 9543809/9550504</p> <p>9544382/9550377-4 9544391/5000297(LH)</p> <p>9544391/5000297-1, 8-1, 8(RH)</p> <p>9544391/9561128 9550493/9541584</p> <p>9550616/9560685 9561042/9561043</p> <p>9561061/9561062</p> <p>In addition, the applicant has stated that all Goodyear models previously approved under the certification system will meet all the provisions of TSO-C26 requirements</p> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| TSO-C26a | McCauley Accessory Division Cessna Aircraft Corp. 3535 McCauley Drive P.O. Box 430 Vandalia, OH 45377 | CE-C | | <table border="1"> <thead> <tr> <th>WHEEL/BRAKE ASSY P/N</th> <th>WHEEL SIZE</th> <th>WHEEL ASSY P/N</th> <th>BRAKE ASSY P/N</th> </tr> </thead> <tbody> <tr> <td>D-30039-X</td> <td>6.00-6</td> <td>D-30063-X</td> <td>C-30018-X</td> </tr> <tr> <td></td> <td>5.00-5</td> <td>C-30053</td> <td></td> </tr> </tbody> </table> | WHEEL/BRAKE ASSY P/N | WHEEL SIZE | WHEEL ASSY P/N | BRAKE ASSY P/N | D-30039-X | 6.00-6 | D-30063-X | C-30018-X | | 5.00-5 | C-30053 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| WHEEL/BRAKE ASSY P/N | WHEEL SIZE | WHEEL ASSY P/N | BRAKE ASSY P/N | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| D-30039-X | 6.00-6 | D-30063-X | C-30018-X | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 5.00-5 | C-30053 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| TSO-C26a | Parker Hannifin Corporation Aircraft Wheel & Brake Div. 1160 Avon Center Road Avon, OH 44011 | CE-C | | <p>WHEEL ASSEMBLY</p> <table border="1"> <tbody> <tr><td>40-8</td><td>40-17</td><td>40-18</td></tr> <tr><td>40-21</td><td>40-23</td><td>40-28</td></tr> <tr><td>40-30A</td><td>40-33</td><td>40-34</td></tr> <tr><td>40-36</td><td>40-40</td><td>40-40A</td></tr> <tr><td>40-44</td><td>40-45</td><td>40-46</td></tr> <tr><td>40-47</td><td>40-50</td><td>40-55</td></tr> <tr><td>40-57</td><td>40-58</td><td>40-66</td></tr> <tr><td>40-67</td><td>40-74</td><td>40-75()</td></tr> <tr><td>40-76</td><td>40-77</td><td>40-78</td></tr> <tr><td>40-79</td><td>40-83</td><td>40-84</td></tr> <tr><td>40-85</td><td>40-86</td><td>40-87</td></tr> <tr><td>40-88</td><td>40-90</td><td>40-90D</td></tr> <tr><td>40-96</td><td>40-97</td><td>40-98</td></tr> <tr><td>40-99</td><td>40-101</td><td>40-102</td></tr> <tr><td>40-112</td><td>40-113</td><td>40-113A</td></tr> <tr><td>40-113B</td><td colspan="2">3080D(40-116)</td></tr> <tr><td colspan="3">40-78/30-9</td></tr> </tbody> </table> <p>BRAKE ASSEMBLY</p> <table border="1"> <tbody> <tr><td>30-19</td><td>30-31</td><td>30-32</td></tr> <tr><td>30-35</td><td>30-39</td><td>30-40</td></tr> <tr><td>30-41</td><td>30-45</td><td>30-51</td></tr> <tr><td>30-52()</td><td>30-54</td><td>30-55</td></tr> <tr><td>30-56</td><td>30-58</td><td>30-61</td></tr> <tr><td>30-63</td><td>30-65</td><td>30-65DRH</td></tr> <tr><td>30-65DLH</td><td>30-66</td><td>30-67</td></tr> <tr><td>30-68</td><td>30-69</td><td>30-71</td></tr> <tr><td>30-75</td><td>30-79</td><td></td></tr> </tbody> </table> <p>37-200A(30-72)</p> <p>WHEEL/BRAKE ASSEMBLY</p> <table border="1"> <tbody> <tr><td>40-40A/30-28</td><td>40-90/30-65</td></tr> <tr><td>40-101/30-67</td><td>40-113/30-79</td></tr> <tr><td>40-117/30-80</td><td></td></tr> </tbody> </table> | 40-8 | 40-17 | 40-18 | 40-21 | 40-23 | 40-28 | 40-30A | 40-33 | 40-34 | 40-36 | 40-40 | 40-40A | 40-44 | 40-45 | 40-46 | 40-47 | 40-50 | 40-55 | 40-57 | 40-58 | 40-66 | 40-67 | 40-74 | 40-75() | 40-76 | 40-77 | 40-78 | 40-79 | 40-83 | 40-84 | 40-85 | 40-86 | 40-87 | 40-88 | 40-90 | 40-90D | 40-96 | 40-97 | 40-98 | 40-99 | 40-101 | 40-102 | 40-112 | 40-113 | 40-113A | 40-113B | 3080D(40-116) | | 40-78/30-9 | | | 30-19 | 30-31 | 30-32 | 30-35 | 30-39 | 30-40 | 30-41 | 30-45 | 30-51 | 30-52() | 30-54 | 30-55 | 30-56 | 30-58 | 30-61 | 30-63 | 30-65 | 30-65DRH | 30-65DLH | 30-66 | 30-67 | 30-68 | 30-69 | 30-71 | 30-75 | 30-79 | | 40-40A/30-28 | 40-90/30-65 | 40-101/30-67 | 40-113/30-79 | 40-117/30-80 | |
| 40-8 | 40-17 | 40-18 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-21 | 40-23 | 40-28 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-30A | 40-33 | 40-34 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-36 | 40-40 | 40-40A | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-44 | 40-45 | 40-46 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-47 | 40-50 | 40-55 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-57 | 40-58 | 40-66 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-67 | 40-74 | 40-75() | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-76 | 40-77 | 40-78 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-79 | 40-83 | 40-84 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-85 | 40-86 | 40-87 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-88 | 40-90 | 40-90D | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-96 | 40-97 | 40-98 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-99 | 40-101 | 40-102 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-112 | 40-113 | 40-113A | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-113B | 3080D(40-116) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-78/30-9 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 30-19 | 30-31 | 30-32 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 30-35 | 30-39 | 30-40 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 30-41 | 30-45 | 30-51 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 30-52() | 30-54 | 30-55 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 30-56 | 30-58 | 30-61 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 30-63 | 30-65 | 30-65DRH | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 30-65DLH | 30-66 | 30-67 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 30-68 | 30-69 | 30-71 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 30-75 | 30-79 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-40A/30-28 | 40-90/30-65 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-101/30-67 | 40-113/30-79 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 40-117/30-80 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|----------------------------|---|
| TSO-C26b | Aircraft Braking Systems Corporation 1204 Massillon Road Akron, OH 44306-4186 | CE-C | AIRCRAFT WHEELS AND BRAKES | WHEEL ASSEMBLY 5000757-8 5000757-8 5004913-3 5004913-4 5004913-5 4004913-6 5004913-7 5004913-8 5001477-3 5001477-2 5003783 5002460-1 5002460-2 5000306-5 5000444-1 5000757-10 9544455-1 BRAKE ASSEMBLY 5000758-10R 5000758-12 5001446-5 5001446-6 5002116 5000758-10R |
| TSO-C26b | Allied Bendix Aerospace Aircraft Brake & Strut Div. 3520 West Westmoor Street P.O. Box 10 South Bend, IN 46624 | CE-C | | WHEEL ASSEMBLY 2603561-12, -13, -14 2604589-1 2608601-3 BRAKE ASSEMBLY 2605155-1 2605662-1 WHEEL/BRAKE ASSEMBLY 2603561 2603561-1, -2, -3, -4, -5, -7, -9, -10, -11, -12, -13, -14/2601902-1, -2, -3, -4, -5, -6 2603561-1, -2, -3, -4, -5, -7, -9, -10, -11, -12, -13, -14/2605155-1 2603561-10, -12/2605662-1 (upgraded) 2606671-1-2/2606672-1, -2, -3, -4 2606741-1/2607092-1 2606801-1/2606802-1 2606821-1/2606822-1 2607081-1/2605662-1 |
| TSO-C26b | Bendix Energy Controls Div. 717 W. Bendix Dr. South Bend, IN 46620 | CE-C | | WHEEL ASSEMBLY 2604561-1 2601901-1, -2, -3, -4, -5, -6 BRAKE ASSEMBLY 151882-2 2605155-1 2601182-5 2601182-6 WHEEL/BRAKE ASSEMBLY 2601901-1, -2, -3/2605365-1 2603561-1, -2, -3, -4, -5, -7, -9, -10/ 2601902-1, -2, -3, -4, -5, -6 2603561-1, -2, -3, -4, -5, -7, -8, -9, -10/ 2602012-3, -4, -5 2601901-1, -2, -3/2605392-1 2601901-1, -2, -3/2602012-3, -4, -5 2601901-2, -3/2601902-1, -2, -3, -4, -5, -6 2603441-3/2603442-3 2605391-1, -2, -3, -4/ 2601902-1, -2, -3, -4, -5, -6 2605391-1, -2, -3, -4/2605391-1 2603561-1, -2, -3, -4, -5, -7, -8, -9, -10, -12/ 2605662-1, -2 2603561-1, -2, -3, -4, -5, -7, -9, -10, -11, -12/ 2605155-1 2603591-1, -2, -3/2601902-1, -2, -3, -4, -5, -6 2605391, -2, -3, -4/2602012-3, -4, -5 WHEEL/WHEEL ASSEMBLY/BRAKE ASSEMBLY 17.25x11.50-6/2606801-1/2606802-1, -2, -3 |
| TSO-C26b | Bodell Manufacturing, Inc. d/b/a Wheeler-Dealer P.O. Box 421 Harbor City, CA 90710 | NM | | BMI-2000 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | | | |
|----------------|--|------|-----------|---|----------------------|------------------------|--|--|
| TSO-C26b *F | Dunlop Australia, Ltd. Dunlop Industrial & Aviation Mountain Highway P.O. Box 41 Bayswater, Victoria 3153 Australia | NM | | NOSEWHEEL ASSEMBLY DW1550 | | | | |
| TSO-C26b *F | Dunlop Aviation & Automotive Corp. P.O. Box 41, Bayswater, 3153 Mountain Highway Bayswater, Victoria Australia | NM | | WHEEL/BRAKE ASSEMBLY 6.00-6 NOSEWHEEL ASSEMBLY 5.00-5 | | | | |
| TSO-C26b *F | Dunlop Ltd. Holbrook Lane Coventry CV6 44A, England | EU | | AH9033 | | | | |
| TSO-C26b | Gerdes Products Co. Inc. P. O. Box 142 Brookville Park Brookville, OH 45309 | CE-C | | WHEEL/BRAKE A-1960 A-1780/A-1870-4 | WHEEL ASSY A-1780 | BRAKE ASSY A-1870-4 | | |
| TSO-C26b | B. F. Goodrich Aerospace & Defense Div. Acut Wheel & Brake Operations P.O. Box 340 Troy, OH 45373 | CE-C | | WHEEL ASSEMBLY 3-999 3-1304-2 3-1309 3-1331 3-1337 3-1345 3-1352 3-1368-1 3-1375-1, -3 3-1395 3-1403 BRAKE ASSEMBLY G-13-280 2-1174 2-1190 2-1195-5, -6, -7, -8, -9 2-1262 2-1301 2-1311 2-1367, -1, -2 WHEEL/BRAKE ASSEMBLY 2-1407/3-1341 2-1443-1/3-1397-1 3-1070/2-873 3-1085, 3-1085-1/2-697, 2-699 3-1208, 3-1208-1/2-1139 3-1247/2-1090 3-1274/2-1123-2 3-1283 and 3-1370/2-1138, 2-1203, 2-1203-2 3-1304-2/2-1174-1 3-1306, 3-1306-1/2-1147 3-1306-1/2-1147-3 3-1309/2-1185 3-1311-3/2-1195-6, -7, -8, -9 3-1311-3, 3-1365/2-1195-9 3-1311-3/2-1367, -1 3-1398/2-1444 3-1341/2-1301 3-1341-1/2-1438 3-1351/2-1303 | | | 3-1076 3-1306 3-1311-3 3-1332 3-1341 3-1349 3-1362 3-1247 3-1377 3-1401 3-1409 2-1147 2-1174-1 2-1195 2-1268 2-1301-1 2-1337-2 2-1147-3 2-1185 2-1090-1 2-1284 2-1303 2-1449 | 3-1303 3-1306-2 3-1319-2 3-1333 3-1341-1 3-1351 3-1369-1 3-1375 3-1388 3-1439-2 3-1414 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|-----------|--|
| | | | | 3-1352/2-1311, -2 3-1354/2-1329 3-1357/2-1203 3-1357/2-1138 3-1357 and 3-1371/2-1203, 2-1138 3-1365-1/2-1367-1, 2-1195-6, -7, -8, -9 3-1368/2-1375 3-1369/2-1337-2 3-1371/2-1203 3-1372/2-1378 3-1375-2/2-1367-1, -2; 2-1195-6, -7, -8, -9 3-1389/2-1408 3-1392/2-1378 3-1392/2-1435-1, -2, -3 3-1397/2-1443 3-1398, -1, -2/2-1444 3-1439-2/2-1474-1, -2, -3 3-1439-3/2-1444 In addition, the applicant has stated that all Goodrich models previously approved under the type certification system will meet all the provisions of TSO-C26b requirements |
| TSO-C26b | Loral Systems Group Aircraft Braking Systems Div. 1210 Massillon Road Akron, OH 44318-0001 | CE-C | | WHEEL ASSEMBLY 5000404, -1, -2 5000919-2 9543705 5001571-3, -4 9543705-1 5003427-1 3-1369-1 9543367 5003427-1 5004175-5 3-1369-1 9543991-2 9544061 9544061-1 9550267-3, -4 9550597-2 A9550597 9543367 9544207 9544207-1 5003427 (Helicopter) BRAKE ASSEMBLY 5000709-8 5000758-10, 11 5000268-3 5001571-6 5004070-2 5001694 956081-1 9550338 5001897-1 2-1093 WHEEL/BRAKE ASSEMBLY 5000306/5000709-1, -5, 5003879 5000400/5000403 5000444-1/5001571, 5001571-2, -5 5004236 5000441-1/5001571-1 5000757/5000758 5000757-1/5000758-1, -2, -3 5000757, -1, -2/5000758, -1, -2, -3 5000791/5000827 5001477-1/50001445-1(LH) 5001477-1/5001446-1(RH) 5001477-2/5001445-2(LH) 5001477-2/5001446-2(RH) 5001251/5001252 5001251-1/5001252-1 5001563/5001564 5001571-4 5001580/5001476-1 5002460/5002256 5002373/5002374 5002566/5003647 (Helicopter) 5002566/6002567 5002806-1/5002805-1 5003064/5003065 5003279/5003280-1, -2 5003279-1/5003280-2 |

TSO NO. HOLDER NAME & ADDRESS RG TSO TITLE MODELS OR PART NUMBERS
 =====

5003384/5003410
 5003425/5003426, 5003426-1 (Helicopter)
 5003588/5003086-1, 9541584
 5003706
 5003783/5001445-3LH, 5001446-3R/H
 5003848/5003849 5003850/5003851
 5004069/5004070
 5004175/5004190-1, -4, -6
 5004175-1/5004190-2
 5004320, -1, -4/5004321-1, -2, -6, -11
 5004410/5003426-1
 5004506/5004507
 5004784/500470
 5004899/5004902
 5004913/5003096
 500757-7/5003870
 5007897/5004321-10
 5004012-1/5004013-1
 9543809/9550504
 9531924
 9543809/9550504
 9543991/5003096
 9543991-2/5001694
 9544171-1/5002376
 9544391-2/5002871
 9544455/5002116
 9550207-1, -2/5000268-1
 9550207-1/5000268
 9550463-1/5000268
 9550463-1, -2/5000268-1, -2
 9550493-1/5003086, 9541584
 9550597/9550338
 9550597-2/9550338, -1
 9560901 9561061() 9541624
 9561042/5001897
 9561061-7/9561062

In addition, the applicant has stated that all Goodyear models previously approved under the certification system will meet all the provisions of TSO-C26b requirements

TSO-C26b McCauley Accessory Div. CE-C
 Cessna Aircraft Co.
 3535 McCauley Drive
 P.O. Box 430
 Vandalia, OH 45377

| WHEEL/BRAKE ASSY P/N | WHEEL SIZE | WHEEL ASSY P/N | BRAKE ASSY P/N |
|----------------------|------------|----------------|----------------|
| | 6.00-6 | D-30204 | |
| | 6.00-6 | D-30179 | |
| D-30114-X | 6.00-6 | D-30063-X | D-30118-X |
| D-30173-X | 6.00-6 | D-30175-X | D-30018-X |
| | 6.00-6 | D-30218 | |
| | 5.00-5 | C-30174 | |
| | 6.00-6 | D-30255 | |
| D-30261-X | 6.00-6 | D-30260-X | C-30018-X |
| | 6.00-6 | D-30288 | |
| D-30292-X | 6.00-6 | D-30291-X | D-30118-X |
| | 5.00-5 | C-30480 | |
| D-30443-X | 6.00-6 | D-30291-X | C-30018-X |
| | 6.00-6 | D-30570 | |
| | 2.75-4 | D-30380 | |
| | 6.00-6 | D-30585 | |
| D-30590-X | 6.00-6 | D-30580-X | C-30018-X |
| | 5.00-5 | D-30500 | |
| | 6.00-6 | D-30625 | |
| D-30629-X | 6.00-6 | D-30600-X | C-30018-X |
| D-30670-X | 6.00-6 | D-30660-X | C-30018-X |
| | 6.00-6 | D-30665 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-------------------------------|---|
| | | | | D-30671-X D-30793-X |
| | | | | 6.00-6 D-30660-X C-30118-X |
| TSO-C26b | Parker Hannifin Corporation Aircraft Wheel & Brake Div. 1160 Avon Center Road Avon, OH 44011 | CE-C | | WHEEL 5:00x5, Type 111, 40-110 BRAKE ASSEMBLY *30-88 30-80 30-93D 30-89C WHEEL ASSEMBLY 40-56 40-76 40-117 40-112 40-115 40-115 *40-124 40-140 WHEEL/BRAKE ASSEMBLY 40-41/30-30 40-59/30-59, -30-53 40-60/30-60 40-83/30-54 40-101/30-89 40-101/30-67, 30-67C, 30-67D, 30-67X 40-106/30-106 40-107/30-107 40-108/30-92 40-111/30-74 40-114/30-73 40-119/30-119 40-120/30-83 40-124/30-88 40-127/30-91 40-128/30-93, 30-93D 40-129/30-94 40-130/30-90 40-130/30-95 40-131/30-96 40-132/30-97 40-133/30-84 40-133/30-98 40-134/30-99 40-135/30-100 40-137/30-103 40-138/30-113 40-151/30-133 40-141/30-123 *used with torque plate LH assemblies P/Ns 075-10100 (LH) and 075-10150 (RH) |
| TSO-C26c | Aircraft Braking Systems Corporation 1204 Massillon Road Akron, OH 44306-4186 | CE-C | AIRCRAFT WHEELS AND BRAKES | WHEEL ASSEMBLY 5006858-2 5007995 5008653 5007996 5004410-1 5007554-1 5010488 5008447-3 5008689-4 5004899-5 5008132-7 5008689-5 5006528-1 5007045-4 9543362-1, -2 5008447-1 5008447-3 5006856-4 NOSE WHEEL ASSEMBLY 9543476 9543362-1, -2 BRAKE ASSEMBLY 5008132-6 5008541-1 5004902-4 5010933, -3 5008676-4 5004902-4 5006857-2 5010995 5009027 5009027-2 5007898-1, -2, -3 5006484-3 5008132-7 5011075 9543601-4 WHEEL & BRAKE ASSEMBLY 5006586-2/5006484-2 5010720/5010614, 5010721 5008131-4/5008132-6 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|---|
| TSO-C26c | Allied Bendix Aerospace Bendix Acft. Brake & Strut Div. 3520 W. Westmoor Street P.O. Box 10 South Bend, IN 46624 | CE-C | | WHEEL ASSEMBLY 2606735-1,-2 2606801-3 2606735-1 2607825-1 2609471-2, -3 WHEEL/BRAKE ASSEMBLY 3-1352/2-1311-1 2606671-1,-2,-3/2606672-1,-2,-3,-4 2606672-4/2606671-1,-2,-3 2606741-1/2607092-1,-2,-3,-4 2608811-2,-4/2607092-1,-2,-3,-4 2608811-3,-5/2608812-1,-2,-3,-4 2608891-1/2608892-1 2609431-1/2609432-1 2609801-1/2606672-2,-3,-4 2609801-1/2610002-1 BRAKE ASSEMBLY 152482-4 2607932-1 2609472-2 |
| TSO-C26c | Allied-Signal Aerospace Co. Bendix Wheels and Brakes Div. P.O. Box 10 South Bend, IN 46624 | CE-C | | WHEEL/BRAKE ASSEMBLY 2609801-1/2606672-2, -3, -4 2609801-1/2610002-1 2609801-1/2610262-1 2609471-1/2609472-1 2608811-1, -3, -5/2608812-6 3-1341, -1/2-1301, -1 381341-1/281527 3-1352/2-1311-1 3-1354-1/2-1329-2,-3 3-1357, -1/2-1203-2, -3 3-1371, 2-1203-4 3-1392/2-1435-3 3-1397/2-1443-1 3-1397-1/2-1443-1 3-1398, -1, -2/2-1444 1398-1/2-1474-4,-5 3-1399-1,-2,-3/2-1445-1,-2 3-1399-2,-3/2-1502,-1 3-1400/2-1446 3-1416/2-1301-1 3-1421-1/2-1450-1, 2-1505 3-1422-1/2-1455,-1 3-1424/2-1435-2 3-1420/2-1454 3-1427-1/2-1455,-1 3-1435-2/2-1466-3,-4 3-1436/2-1465 3-1438-1 3-1439-2/2-1444,-1,-2 3-1439/2-1474,-5 3-1446/2-1479-1 3-1455/2-1492 3-1450/2-1486-1 3-1457/2-1495 3-1469/2-1509 3-1471/2-1510 3-1476/2-1090 3-1485/2-1522 3-1478/2-1514 3-1479/2-1515 3-1480/2-1517 3-1487/2-1524 3-1484/2-1521 3-1490-1/2-1528-1 40-143/30-129 40-146/30-130 40-152 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|--|------|-------------------------|------------------------|------------------------|--------------------------|
| | | | | 40-176A/30-150 | 40-177/30-151 | |
| | | | | 40-179/30-153 | 40-179/30-163 | |
| | | | | 40-181/30-154 | 40-182/30-155 | |
| | | | | 40-192/30-156 | 40-258/30-146A | |
| | | | | 40-270/30-191 | 40-194/30-157 | |
| | | | | 40-195/30-158 | 40-198/30-159 | |
| | | | | 40-198/30-159C | 40-200/30-142 | |
| | | | | 40-202/30-161 | 40-203/30-162 | |
| | | | | 40-211/30-170 | 40-223/30-176 | |
| | | | | 40-179()/30-182() | | |
| | | | | 40-230()/30-181() | | |
| | | | | 40-239()/30-189() | | |
| | | | | 40-240/30-191 | 40-240A/30-191 | |
| | | | | 40-258/30-146A | | |
| | | | | NOSE WHEEL ASSY | | |
| | | | | D-30204-(X) | D30174 | D-30179 |
| | | | | D30218 | D-30063-(X) | D30175 |
| | | | | D-30255 | D30288 | D-30260 |
| | | | | D30291-(X) | C-30480 | D30585 |
| | | | | D-30570 | D30580-() | D-30291-(X) |
| | | | | D30625 | D-30500 | D30665 |
| | | | | D-30600-(X) | D30660-(X) | D-30660-(X) |
| | | | | D30768 | 40-115C | |
| | | | | WHEEL AND BRAKE ASSY | | |
| | | | | D30114-(X) | D-301173-(X) | D30118-(X) |
| | | | | D-30018-(X) | D-30261-(X) | D30292-(X) |
| | | | | C30018-(X) | D-30118-(X) | D30443-(X) |
| | | | | D-30380 | C-30018-(X) | D-30590-(X) |
| | | | | D-30629-(X) | C-30018-(X) | D-30018-(X) |
| | | | | D-30670-(X) | D-30764-(X) | C-30018-(X) |
| | | | | D-30671-(X) | C-30764-(X) | D-30118-(X) |
| | | | | D-30793-(X) | | |
| | | | | 40-202/30-161 | 40-239/30-189 | |
| | | | | 40-240A/30-191 | 40-255/30-67A | |
| | | | | 40-256/30-195 | | |
| | | | | 040-25900/030-19100 | | |
| | | | | 040-21101/30-170 | | |
| | | | | WHEEL ASSEMBLY | | |
| | | | | 040-26000 | 040-26200 | 40-240A |
| | | | | BRAKE ASSEMBLIES | | |
| | | | | 30-1598 | | |
| TSO-C26c | Repco, Inc. 445 Cardinal Lane Hartland, WI 53029 | CE-C | | RFS-15K Kit | RFS 207-111 | |
| | | | | RFS-15 | RFS-27 | RFS-151 |
| | | | | RFS6029 | RFS5119 | RFS-3096 |
| | | | | RFS6425 | RA164-02501 | |
| | | | | RA164-02502 | RA66-105M | |
| TSO-C26c | Tanger Aire, Inc. Royalton Airport Dale and Mackey Road R.O. 2, Gasport, NY 14067 | NE | | WHEEL/BRAKE ASSEMBLY | | |
| | | | | 522-170 | | |
| TSO-C27 | Aerofab, Inc. One High St. Sanford, ME 04073 | NE | TWIN SEAPLANE FLOATS | B1800 2300 2950 | 3500A C3500 3000 | B3500 C3500A B2300 |
| TSO-C27 | Airglas Engineering Co.Inc. P. O. Box 6107 Anchorage, AK 99502 | NM | | LJ-2800 | | |
| TSO-C27 | Altair Enterprises, Inc. 2589 Seppala Blvd. | CE-C | | 3630 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|---------------|---|--|--|
| | St. Paul, MN 55109 | | | | | |
| TSO-C27 *F | Canadian Aircraft Products International Airport Vancouver, British Columbia AND 261 Viscount Way Richmond, British Columbia Canada | NE | | 3000 67-2000 | 3000C 12000 | 30000 |
| TSO-C27 | CAPRE, Inc. 805 Geiger Road Zephyrhills, FL 33599 | CE-A | | 180-85 3526 | 1900 | 2400 |
| TSO-C27 | Capre Inc., Aqua Float Co. P.O. Box 247 Brandon, MN 56315-0247 | CE-C | | 180-85 2200 | 1500 2400 | 1900 3526 |
| TSO-C27 | Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599 | CE-A | | Aqua 1500 Aqua 2400 | Aqua 1900 Aqua 3526 | Aqua 2200 |
| TSO-C27 | DeVore Aviation Corporation 6104B Kircher Blvd. N.E. Albuquerque, NM 87109 | SW | | D3500A D4000A | 2050 | C4000 |
| TSO-C27 | EDO-AIRE Div. of Edo Corporation 65 Marcus Drive Melville, NY 11746 | NE | | 696-3500 | 696M3500 | |
| TSO-C27 | EDO-AIRE Div. of Edo Corporation Republic Airport East Farmingdale, NY 11735 | NE | | 797-2500 | | |
| TSO-C27 | Edo Commercial Corp. 65 Rushmore St. Westbury, L. I., NY 11590 | NE | | 248-2440 249-2870 338-2200 439-2705 FD 3500 | 248A-2440 249A-2870 339-2250 597-2790 | 248B-2440 289-2700 339-JHS 628-2960 |
| TSO-C27 | Fiberfloat Corporation 895 East Gay Street Bartow, FL 33830 | CE-A | | 2400 | | |
| TSO-C27 | Greenwood Fiberglass Co. 2699 Geneva Highway Manitou Beach, MI 49253 | CE-C | | Model B | | |
| TSO-C27 | Pee-Kay Aircraft Products International Falls, MN 56649 | CE-C | | 1500 A3500 | 81800 | 3500 |
| TSO-C27 | Wipaire, Inc. 8520 River Road Inver Grove Heights, MN 55076 | CE-C | | 3700 6000() 7000 | 3730 9500 8000 | 3900 9812 4000() |
| TSO-C28 | Aero Ski Manufacturing Co. Park Rapids, MN 56470 | CE-C | AIRCRAFT SKIS | M1500 M3000 | M1800 3700 | M2000 R2800() |
| TSO-C28 | Airglas Engineering Co. Inc. P. O. Box 6107 Anchorage, AK 99502 | NM | | L-1200A L-1650A L-2500 | L-1500 L-2000 L-2500A | L-1500A L-2000A L-3000 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-----------|---|--|---|
| | | | | LW-3000 LW-3600 | L-14500 LW-5100 | L-14500NA |
| TSO-C28 | Anderson Alaska Skis Anchorage, AK 99502 | NM | | AA20 AA25H | AA20H | AA25 |
| TSO-C28 | Aqua Float Corp. Fleming Field So. St. Paul, MN 55075 | CE-C | | 3000 | | |
| TSO-C28 | Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599 | CE-A | | Aqua 3400 | | |
| TSO-C28 | Dakota Aviation Co. Huron, SD 57350 | NM | | NL-2050 | | |
| TSO-C28 | F. Atlee Dodge Aircraft Maintenance P. O. Box 6409 Anchorage, AK 99502 | NM | | AD 2500 x 10.5 | | |
| TSO-C28 | Fluidyne Engineering Corp. 5900 Olsen Memorial Hwy. Minneapolis, MN 55422 | CE-C | | 2000 3000 6500 6500C A-2500-A A-300000L AWB-3500-A AWB-8000 NA-800 C3000 C4200 C4200A BXR | 2500 4030 12000 A-1500-A A-3000 AWB-2500-A AWB-4000 AWN-1200 AWB-2100 C5500 NA-1200 NB-1200 | 2500A 6000 6500A A-2000-A A-3500-A AWB-3500 AWB-4820 AWN-1200A C2200 C3600 CF3000 NA-1200A |
| TSO-C28 | Kenyon Aircraft 3 Mile SW of McCarthy, AK on Jim Edwards Airstrip P.O. Box 189 Glennallen, AK 99588 | NM | | 3400 | C2800 | |
| TSO-C28 *F | S.E.F.A. Aerodrome de Cannes Mandelieu 06150 Cannes LaBocca, France | EU | | 5000 8000A | 5000A 8000B | 5000B |
| TSO-C28 | Ski Manufacturing Co. Inc. Park Rapids, MN 56470 | CE-C | | M2000 | M3000 | |
| TSO-C28 | Wilbur's Flight Operations Anchorage, AK 99500 | NM | | Tire-Cushioned 2300 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|--|--|------------|--|
| TSO-C28 | Woychik Aircraft Equipment Middleton, WI 53562 | CE-C | | R-1 | R-1A | |
| TSO-C29 | "TSO authorizations existing at the time of TSO cancella- tion remain in effect." | | POSITION LIGHTS (FOR NON-AIR CARRIER AIRCRAFT) | | | |
| TSO-C30 | Midland-Ross Corporation Grimes Division 515 North Russell Street Urbana, OH 43078 | CE-C | AIRCRAFT POSITION LIGHTS | Types I and II A1285 A-1815A A-1815A-R-7512 A-1815A-G-7512 A-1815A A-2138 A-3520 B-6345 D-7995 G-9060-1 G-9060-2 G-9190-1 G-9190-2 G-9910-1 22885-21-4174 22885-22-4174 22885-21-11631 22885-22-11631 30-0025 30-0030-() 30-0055 30-0191 30-0788-() 30-0516-()-() 30-1228-() 30-0787-1 30-0787-3 30-0788-1 30-0788-2 31330-21 31330-21-7512 31330-22-7512 31330-22 32010 36425-21-7512 36425-22-7512 40075-21-4174 40075-22-4174 40165-21-4174 40165-22-4174 42295-21-4174 42295-22-4174 43310-21-4174 43310-22-4174 43310-221-4174 43310-222-4174 46140 Type III 30-1229-() Type III and IV A-2064 A-2064-1680 A-2064-1683 A-4585 B-1943 B-4090 B-4335 B-4742 B-7890 B-7890-1 B-7890-2 B-7890-3 B-7890-4 B-7890-5 B-9730-3 D-7420 G-9925-1 41-0184-1 12307 23950-23-1680 36260-23-1683 26900-()-()-() | | |
| TSO-C30b | Hoskins Division of Sheldahl Corp. 15771 Redhill Ave. Tustin, CA 92680 | NM-L | AIRCRAFT POSITION LIGHTS | 702242 | 702495 | |
| TSO-C30b | Hoskins, Inc. 34 N. Bennett Geneva, IL 60134 | CE-C | | 30-0218(- - -) | 30-0329() | |
| TSO-C30b | Midland-Ross Corporation Grimes Division 550 Route 55 P.O. Box 247 Urbana, OH 43078 | CE-C | | Types I and II A1815A-()-() A-2064-A A-2138-G-7512 22875-()-() 30-0009-() 30-0234-()-() 30-0243-()-() 30-0516 30-0191 30-0538 30-0573 30-0758-()-() 30-0757-()-() 30-0323-()-() 30-0446-() 30-0790-()-() 31-1749 26900 30-0244-()-() 30-0323-()-() Types III and IV 20595-23-1683 30-0120-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|-----------|--------------------------------------|
| | | | | 5004410/500342-1 |
| | | | | WHEEL ASSEMBLY |
| | | | | 2608811-3, -5 |
| | | | | 2609471-3 |
| | | | | 2609471-2 |
| | | | | 2606821-3 |
| | | | | BRAKE ASSEMBLY |
| | | | | 2608812-5 2609472-2 |
| | | | | 2609472-2 2606822-1 |
| | | | | 2608812-4 |
| TSO-C26c | The BF Goodrich Company Acft Wheel & Brake Operations P.O. Box 340 Troy, OH 45373 | CE-C | | WHEEL AND BRAKE ASSEMBLIES |
| | | | | 3-1357-1/2-1203-3 3-1484/2-1521 |
| | | | | 2-1474 Series |
| | | | | 3-1508/2-1541-1 |
| | | | | 3-1491/2-1526 |
| | | | | 3-1497/2-1537, 2-1537-1 |
| | | | | 3-1500/2-1535 |
| | | | | 3-1509/2-1542 |
| | | | | WHEEL ASSEMBLY |
| | | | | 3-1469 3-1490-1 |
| | | | | 3-1480-1 3-1478-1 |
| | | | | 3-1435-3 3-1485 |
| | | | | 3-1448 3-1492 |
| | | | | 3-1438 3-1480-1 |
| | | | | 3-1446-1 3-1485 |
| | | | | 3-1479 3-1479 |
| | | | | 3-1487 3-1490-1 |
| | | | | 3-1501 3-1372-1 |
| | | | | 3-1471-1 3-1428 |
| | | | | 3-1470-1 3-1398-1 |
| | | | | 3-1439 3-1484 |
| | | | | 3-1497 3-1070 |
| | | | | 3-1209-2 (101-8015-3) |
| | | | | 45373 3-1375, -1 |
| | | | | 3-1371 3-1354, -1 |
| | | | | 3-1395 3-1398 |
| | | | | 3-1401 3-1403 |
| | | | | 3-1412 3-1418 |
| | | | | 3-1422-1 3-1423-1, -2 |
| | | | | 3-1426 3-1427-1 |
| | | | | 3-1428 3-1438 |
| | | | | 3-1442 3-1444 |
| | | | | 3-1437 3-1448 |
| | | | | 3-1487 3-1451 |
| | | | | 3-1512 3-1460 |
| | | | | 3-1465 3-1469 |
| | | | | 3-1479-2 3-1470 |
| | | | | 3-1508 3-1512 |
| | | | | 3-1481 381481 |
| | | | | 6.00-6/3-1413 |
| | | | | 5003427 |
| | | | | 18x4.4/3-1418 |
| | | | | BRAKE ASSEMBLY |
| | | | | 2-1509-1 2-1529-2 |
| | | | | 2-1517 2-1514 |
| | | | | 2-1466-3 2-1522-1 |
| | | | | 2-1517 2-1524, -1 |
| | | | | 2-1532 2-1541-1 |
| | | | | 2-1541-2 2-1479-1 |
| | | | | 2-1522-1 2-1515-1, -2 |
| | | | | 2-1529-3, -4 2-1528-2 |
| | | | | 2-1528-3 2-1530-2 |
| | | | | 2-1378 2-1524-1 |
| | | | | 2-1474-5 2-1133-2 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|----|-----------|--|
| | | | | 2-1203-2, -3 2-1509-1 2-1515-1 2-1529-1/-2-1530-1 2-1445-1, -2 2-1455 2-1457-1 2-1474, 2-1474-1, -2, -3 3-1458/2-1496 3-1461-1/2-1504-1 NOSE WHEEL ASSEMBLIES 3-1495 3-1496 3-1498 3-1501 WHEEL/WHEEL/BRAKE ASSEMBLY 6.50/3-1421/2-1450 6.50-8/3-1421/2-1450 6.50-10/3-1372/2-1378 6.50-10/3-1392/2-1435-2 22x5.5/3-1399/2-1445 |
| TSO-C26c *F | Dunlop Limited Holbrook Lane Coventry CV6 4A4, England | EU | | <p>MAIN WHEEL</p> <p>AHA 1211 Mod 1 or 2 AHA 1287 Mod Standard 3() AHA 1291 AHA1297 AHA 1343 Mod 1 AHA 1372 Mod Standard F AHA 1405 Mod 1 AHA 1462() AHA 1480 Mod Standard 2() AHA1489() 1490() AHA 1567() AHA.1648() AHA.1663() AHS2339() AHA 1606 Mod () AHA 1890 MOD ()</p> <p>NOSEWHEEL</p> <p>AHA 1349 Mod Standard 1 AH 54422 Mod. 1() AHS2688() AH 54450()</p> <p>WHEEL-BRAKE</p> <p>AHA 1288 Mod Standard 2() AHA 1301 Mod Standard 2 AHA 1292() AHA 1301 Mod Standard 2() AHA 1412() AHA 1413() AHA 1455 Mod Standard 2() AHA 1456 Mod Standard 2() AHA 1558() AHA 1559() AHA 1612() AHA 1637() AHA1676 Mod() AHA 1693 Mod() AHA1897 BRAKE AHA 1884()</p> |
| TSO-C26c *F | Dunlop Limited Coventry, United Kingdom | EU | | <p>MAINWHEEL 1752 Mod() AHA 1814 Mod() AHA 1881() NOSEWHEEL AH 54452 Mod() AHS4474 Mod() AHS2688 Issue() BRAKE AHA 1653 Mod() AHA 1805() AHA 1806()</p> |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|--|---|
| | | | | 36260-2 Types - - - 30-0626-() 30-0627-() 30-0127-1 30-0801-1 D-8225-()-() 30-0037 30-0038 30-0030-() 30-0248-() 30-1080 30-1085 30-0863-() 30-1265-() 30-1205-() 30-1133-() 30-1192-() |
| TSO-C30b | Symbolic Displays, Inc. 1762 McGraw Ave. P.O. Box 19626 Irvine, CA 92705 | NM | | 30-0329() 30-0218() 701364() 701557() 702084() 702242 |
| TSO-C30b | Whelen Engineering Co. Inc. Deep River, CT 06417 | NE | | A460 V & H A480 V & H W1285 PG & PR A460 A A480 A A500 A555 A600 A675 W1250 W1555 |
| TSO-C30b | Whelen Engineering Route 145, Winthrop Road Chester, CT 06412 | NE | | A460-() A460-A() A480-() A480A-() A500-() A555-() A600-() A675-() W1250-() W1285-() W1555-() |
| TSO-C30c | Baker Electronics, Inc. 1734 Northgate Blvd. Sarasota, FL 33580 | CE-A | AIRCRAFT POSITION LIGHTS | M1050() |
| TSO-C30c | Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | ACS-45A; AS-451B |
| TSO-C31 | Aeronautical Communications Equipment, Inc. Miami, FL 33101 | CE-A | HIGH FREQUENCY (HF) RADIO COMMUNICATION TRANSMITTING EQUIPMENT OPERATING WITHIN THE RADIO FREQUENCY RANGE OF 1.5 TO 30 MEGACYCLES | AAT Type 3 AAT Type 4 AAT Type 5 AAT Automatic Tuning Unit |
| TSO-C31 | Collins Radio Co. 5225 "C" Ave. N. E. Cedar Rapids, IA 52406 | CE-W | | 490T-1A 490T-2 490T-4 490T-9 490T-10 490Y-1 490Y-2 490Y-4 614D-2 618S-1 618S-4 618T 618T-1 618T-2 618T-3 618T-1B/2B/3B 628T-2A 714E-() 714E-2 714E-2a 714E-2b 714E-3 714E-3D 714E-3F 714E-6 714E-6A 714E-6B 780Y-1/2/4 790S-3 790S-4 790S-5 1803L-2 1803L-3 1803L-3A 49T-() 153L-() 180R-4 309A-17 350T-2 409S-1 416W-2 416A-3 992C-2 999W-2 999W-2A |
| TSO-C31 | Radio Corp. of America Camden, NJ 08101 | NE | | AVT-49 |
| TSO-C31 | Remington Rand Univac | CE-C | | 116769 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|---|--|---|
| | St. Paul, MN 55101 | | | | | |
| TSO-C31 | SunAir Electronics, Inc. 3101 S.W. Third Ave. Ft. Lauderdale, FL 33315 | CE-A | | ASB-100 | | |
| TSO-C31c | Bendix/King General Avn. Avionics Division 400 North Rogers Road Olathe, KS 66062-1212 | CE-W | HIGH FREQUENCY (HF) RADIO COMMUNICATION TRANSMITTING EQUIPMENT OPERATING WITHIN THE RADIO FREQUENCY RANGE OF 1.5 TO 30 MEGACYCLES | KA 160:071-01269-0002 KA 161:071-01271-0002 KA 162:071-01270-0002 | | |
| TSO-C31c *F | Chelton (Electrostatics) Ltd EU Marlow Buckingham, United Kingdom | | | Masts Type 40-5, 40-14 | | |
| TSO-C31c *F | Codan Pty Ltd. Grave Street Newton, South Australia | NM | | 2001 2004 2103 2202 | 2002 2101 2104 | 2003 2102 2201 |
| TSO-C31c | Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52498 | CE-W | | 718U-4() CCD-810:622-5419-001 CTL-201:622-4471-001 CTL-201A:622-4490-001 CMS-80() 514A-3 548S-3 548S-5A 641D-1 671D-4AM 628T-1() 990C-2 990C-8 990C-12 990C-13, -14 990C-12():622-3922-001, -002 9926-2:622-5420-001 999C-2() 992C-3 SCC-811:622-5417-001 SCC-812:622-5418-001 | HF-200() HFP-702 514A-4 548S-3A 514A-7:622-4093-001 671D-2 671D-4A 628T-2, -3, -3A 718-4C 990C-5 990C-9 990C-30 999W-3, -3A 999W-1() | CMS-80() HF-200() HF-121A CCD-806 HFS-700 514A-7 548S-5 999-2/2A 999-2/2A |
| TSO-C31c | Collins General Avn. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | HF-200 AAC-220P HF-230:CTL-230 PWR-230 | HF-220 PAC-200 | AAC-200P AAC-220 TCR-230 |
| TSO-C31c | Collins Radio Co. 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | 490S-() 718U-4B | AT-107 790S-() | 718V-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|--|--|
| TSO-C31c | Dayton Aircraft Products 812 N.W. First St. Ft. Lauderdale, FL 33310 | CE-A | | DAP-10() |
| TSO-C31c | Gables Engineering, Inc. P.O. Box 340880 Coral Gables, FL 33114 | CE-A | | G6288-() ARINC 719:G6201-() G622S() G6201() |
| TSO-C31c | King Radio Corporation 400 N. Rogers Road Olathe, KS 66061 | CE-W | | KA 98:071-1252-() KA 158:071-0019-() KA 160:071-1269-() KA 161:071-1271-00, -01 KA 162:071-1270-XX KA 594:KPN 071-1263-00 KAC 592:064-1017-() KAC 992:064-1029-00, -01 KCU 951:064-1016-(05) KFS-594:KPN 071-1274-00, -04 KTR 953:064-1015-() KTR 993 (with KFS 594):063-1007-00 |
| TSO-C31c | Rockwell International Avionics Group 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | | 180R-4M 309A-19 628T-3A 992C-2 999W-2 514A-14:622-4957-001, -002, -003, -004, -006, -007, -008, -009 790S-19:622-8963-001 913Z-4:622-4589-002 |
| TSO-C31c | SunAir Electronics, Inc. 3101 S.W. Third Ave. Ft. Lauderdale, FL 33315 | CE-A | | ASB-60() ASB-125() ASB-130() ASB-320() ASB-850 ACU-150A() ACU-150B() ACU-150C() ASB-500HF AGU-150D() CU-105() CU-106() CU-110() SAC-69() |
| TSO-C31d | Collins General Avn. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | HIGH FREQUENCY (HF) RADIO COM- MUNICATION TRANSMITTING EQUIPMENT OPERATING WITHIN THE RADIO FRE- QUENCY RANGE OF 1.5 to 30 MEGACYCLES | RF-230-PAC-230: 622-7139() |
| TSO-C31d | Collins Avionics Group Rockwell International 400 Collins Road, NE. Cedar Rapids, IA 53498 | CE-W | | 490A-1 490A-2 490S-4 728U-2 790S-10 790S-11 790S-20 993S-1 790S-10 HF9000 HF-9041 HFP-712 MF9010 MF9030 MT903GA MT9030 MT9040 MT9040A MT9041 MT9041A MT9042 MT9042A 309A-19A:622-9261-001 514A-9:622-5690-001, -002, -003 728U-4:622-9861-001 993S-4:622-6994-001 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|--|--|--|--|
| TSO-C31d *F | Electronique Aerospatiale EAS B.P.51 93350 Le Bourget, Principal France | EU | | BCH2725:8992725()() | | |
| TSO-C31d | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G6934() | G6984() | |
| TSO-C31d | Page AvJet Corporation Aviation Design & Mod. Div. Orlando Int'l. Airport Orlando, FL 32812 | CE-A | | PAM-100: P/N 600-1500-(), -1501-(), -1503-(), -1505-() | | |
| TSO-C32 *F | Canadian Marconi Co. 2442 Trenton Ave. Montreal 301, Quebec Canada | NE | HIGH FREQUENCY (HF) RADIO COMMUNICATION RECEIVING EQUIPMENT OPERATING WITHIN THE RADIO FREQUENCY RANGE OF 1.5 TO 30 MEGACYCLES | CMA 100/201 | | |
| TSO-C32 | Collins Radio Co. 5225 "C" Avenue N. E. Cedar Rapids, IA 52406 | CE-W | | 49T-() 416W-2 618S-1, -4 618T-1B/28/3B 618T-3 714E-2A 714E-3D 714E-6 | 49T-6 416W-3 618T 618T-2 714E-() 714E-2B 714E-3F 714E-6A | 350T-2 614D-2 618T-1 714E-2 714E-3 714E-3G 714E-6B |
| TSO-C32 | Hamlyn Electronics Corp. Hicksville, L.I., NY 11802 | NE | | HTR-5 | | |
| TSO-C32 | Radio Corp. of America Camden, NJ 08101 | NE | | AVR-22 | | |
| TSO-C32 | Remington Rand Univac St. Paul, MN 55101 | CE-C | | 116769 | | |
| TSO-C32b | Alpha-Para Equipment Route #2, Box 140 Bardstown, KY 40004 | CE-A | HIGH FREQUENCY (HF) RADIO COMMUNICATION RECEIVING EQUIPMENT OPERATING WITHIN THE RADIO FREQUENCY RANGE OF 1.5 TO 30 MEGACYCLES | AL-2() | AL-3() | |
| TSO-C32b | Panatronics Corp. Ft. Lauderdale, FL 33315 | CE-A | | DX20-RT | | |
| TSO-C32b | SunAir Electronics, Inc. 3101 S.W. Third Ft. Lauderdale, FL 33315 | CE-A | | ASB-100() | CU-2200 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|---|---|-------------------------------|
| TSO-C32c | Bendix/King General Avn. Avionics Division 400 North Rogers Road Olathe, KS 66062-1212 | CE-W | HIGH FREQUENCY (HF) RADIO COMMUNICATION TRANSMITTING EQUIPMENT OPERATING WITHIN THE RADIO FREQUENCY RANGE OF 1.5 TO 30 MEGACYCLES | KA 160:071-01269-0002 KA 161:071-01271-0002 KA 162:071-01270-0002 | | |
| TSO-C32c *F | Chelton (Electrostatics) Ltd EU Marlow Buckingham, United Kingdom | | | Masts Type 40-5, 40-14 | | |
| TSO-C32c *F | Codan Pty Ltd. Grave Street Newton, South Australia | NH | | 2001 2004 2103 2202 | 2002 2101 2104 | 2003 2102 2201 |
| TSO-C32c | Collins Avionics Division Rockwell International 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | | CCD-806 CCD-810:622-5419-001 CMS-80() CTL-201 CTL-201A HF-121A HFP-702 HFS-700 SCC-811:622-5417-001 SCC-812:622-5418-001 514A-3 514A-4 514A-7 548S-3 548S-3A 548S-5 548S-5A 628T-2:622-3372-001 628T-2A 628T-3 641D-1 671D-2 671D-4A 671D-4AM 718U-4() 790S-10 990C-13, -14 992G-2:622-5420-001 992C-2 999-2/2A 999C-2() 999W-2 999W-2A 992C 990C-2 990C-5 990C-6 990C-8 990C-9 990C-9A 990C-12 990C-12 990C-30 HF-9010 HF-9041 MT-903GA MT-9042A RF-9030 | | |
| TSO-C32c | Collins General Avia. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | HF-200 AAC-220P HF-230:CTL-230 PWR-230 | HF-220 PAC-200 TCR-230 | AAC-200P AAC-220 |
| TSO-C32c | Collins Radio Co. 5225 "C" Avenue N. E. Cedar Rapids, IA 52406 | CE-W | | 718U-() | 718U-4B | |
| TSO-C32c | Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | 628T-1() 718U-4A 990C-12():622-3922-001, -002 CCD-806 999W-3A | 999W-1() HF-200() 628T-3, -3A 992C-3 | 992C-1() 514A-7 999W-3 |
| TSO-C32c | Dayton Aircraft Products 812 N.W. First St. Ft. Lauderdale, FL 33310 | CE-A | | DAP-10-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|---|--|
| TSO-C32c | Gables Engineering, Inc. P.O. Box 340880 Coral Gables, FL 33114 | CE-A | | G6228-() ARINC 719:G6201-() G6225() G6201() |
| TSO-C32c | King Radio Corp. 400 N. Rogers Road Olathe, KS 66061 | CE-W | | KA 158:071-0019-00 KA 160:071-1269-00, -01 KA 161:071-1271-00, -01 KA 162:071-1270-XX KA 594:KPN 071-1263-00 KAC 952:064-1017-() KAC 992:064-1029-00, -01 KCU 951:064-1016-(05) KFS-594:FPN 071-1274-00 thru 04 KTR 993 (with KFS 594):063-1007-00 KTR-953:064-1015-() |
| TSO-C32c | Rockwell International Avionics Group 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | | 628T-3A 992C-2 999W-2 514A-14:622-4957-001, -002, -003, -004, -006, -007, -008, -009 790S-19:622-8963-001 913Z-4:622-4589-002 |
| TSO-C32c | SunAir Electronics, Inc. 3103 S.W. Third Ft. Lauderdale, FL 33315 | CE-A | | ASB-60() SAC-69() CU-105() CU-106() CU-110() ASB-125() ASB-130() ASB-320() ASB-850 ACU-150A() ACU-150B() ACU-150C() ASB-500 HF AGU-150D() |
| TSO-C32d | BR Communications 1249 Innsbruck Drive Sunnyvale, CA 94088 | NM | HIGH FREQUENCY (HF) RADIO COMMUNICATION TRANSMITTING EQUIPMENT OPERATING WITHIN THE RADIO FREQUENCY RANGE OF 1.5 TO 30 MEGACYCLES | RCS-6() |
| TSO-C32d | Collins Avionics Group Rockwell International 400 Collins Road, NE. Cedar Rapids, IA 53498 | CE-W | | 514A-9:622-5690-001, -002, -003 490A-1 490A-2 490S-4 728U-2 790S-11 790S-20 993S-1 790S-10 HF-9030 HF-9010 HFP-712 HF-9000 HF-9030A HF-9041 HF-9042A 309A-19A:622-9261-001 728U-4:622-9861-001 993S-4:622-6994-001 |
| TSO-C32d | Collins General Avn. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | RF-230-PAC-230:622-7139() |
| TSO-C32d *F | Electronique Aerospatiale B.P. 51, 93350 Le Bourzet, Principal France | EU | | BCH2725:899 2725()()() |
| TSO-C32d | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G6934() G6984() |
| TSO-C32d | Page AvJet Corporation Aviation Design & Mod. Div. | CE-A | | PAM-100: P/N 600-1500-(), -1501-(), -1503-(), -1505-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|---|--|---|---|
| | Orlando Int'l. Airport Orlando, FL 32812 | | | | | |
| TSO-C33 | AviAid Products, Inc. P.O. Box 96 Winnetka, IL 61101 | CE-C | POSITION LIGHT FLASHERS, SINGLE CIRCUIT (FOR NON- AIR CARRIER AIRCRAFT) | AS 273 | | |
| TSO-C33 | Barber-Colman Co. Rockford, IL 61101 | CE-C | | SYLZ 8291 SYLZ 8869 | SYLZ 8454 | SYLZ 8769 |
| TSO-C33 | Justin, Inc. San Gabriel, CA 91776 | NM | | SS12 Type II | SS24 Type I | |
| TSO-C33 | Midland-Ross Corporation Grimes Division 515 N. Russell St. Urbana, OH 43078 | CE-C | | 70-0116-1 | | |
| TSO-C33 | Omega Electronics Co. Evansville, IL 47708 | CE-C | | Type II | | |
| TSO-C33 | Phillips Control Corp. Navigade Division Joliet, IL 60400 | CE-C | | C-300 | | |
| TSO-C34 | Bendix Bendix Radio Division Baltimore, MD 21204 | NE | AIRBORNE ILS GLIDE SLOPE RECEIVING EQUIPMENT | GSA-8 Ser. | MSA-26b | |
| TSO-C34 | Clover Field Radio Supply Co Santa Monica, CA 90405 | NM | | CRF-118 | | |
| TSO-C34 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | VIR-30() 313N-() 313N-6C 390R-() 51V-3 51V-5 51RV-1A 599A-1() 614U-7 | 147B-1 313N-2/3 344A-2 390Y-7 51V-4 51R-6 51RV-1C 614U-3 614U-8 | 197B-1 313N-2D/3D 344B-2 516B-3 51V-4A 51RV-1 51RV-2B 614U-4 |
| TSO-C34 | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KN1-500 KN1-520 | KN1-500L KGS-680 | KN1-510 KGM-690 |
| TSO-C34 | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 4087A | 4087B | 5607 |
| TSO-C34 | NARCO Avionics Div. NARCO Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | UGR-1 | DGO-10 | |
| TSO-C34a | Bendix Avionics Division | CE-A | AIRBORNE ILS GLIDE SLOPE | INA-21() PSA-8 | GSA-8A() | MTA-7() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|---|--|---|
| | P.O. Box 9414 Ft. Lauderdale, FL 33310 | | RECEIVING EQUIPMENT | | | |
| TSO-C34a | Bendix Bendix Radio Division Baltimore, MD 21204 | NE | | GSA-8A() MTA-7() | INA-21 Ser. PSA-8 | RNA-26C |
| TSO-C34a | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | 313N-2:522-2447-005/015/045 | | |
| TSO-C34a | NARCO Avionics Div. NARCO Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | UGR-1A | | |
| TSO-C34a | Rockwell International Avionics Group 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | 313N-2:522-2447-574 | | |
| TSO-C34b | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | AIRBORNE ILS GLIDE SLOPE RECEIVING EQUIPMENT | GSA-25() RNA26C() CNA-26() | MSA-25() RNA26CF() | RNA26 MSA-26() |
| TSO-C34b | Bendix Bendix Radio Division Baltimore, MD 21204 | NE | | GSA-25() RNA-26CF | MSA-25() RNA-26C | MSA-26() |
| TSO-C34b | Collins Radio Co. 5225"C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 51RV-2() | 51RV-2B | |
| TSO-C34b | Communications Components Corporation 3000 Airway Ave. Costa Mesa, CA 92626 | NM | | AT-902AF 35-5017 CU 994 MI 592127 VT10-02 | AT-902AR 35-5023 NC10-54 GSNC20-05 VT10-56-6:35-5038 | 35-5011() 35-5024 HC10-124 RGS10-48 |
| TSO-C34b | Dorne and Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM N25-1 DM N41-1 | DM N25-2 | DM N25-3 |
| TSO-C34b *F | Electronique Aerospatiale P. O. Box 4 93350 Le Bourget Aeroport Paris, France (Formerly Europe Air Service) | EU | | RD671 | RGA671 | |
| TSO-C34b *F | Elliott Brothers (London) Ltd. Christopher Martin Rd. Basildon, Essex, England (Formerly Marconi Co. Ltd.) | EU | | AD260 | | |
| TSO-C34b | Honeywell, Inc. Sperry Comm Flt Sys. Div. 2111 N. 19th Avenue Phoenix, AZ 85027 | NM | | 2588654() Ser. | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|---|---|------------------------|------------------------|
| TSO-C34b | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KN-70 | | |
| TSO-C34b | NARCO Avionics Div. NARCO Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | UGR-2 | VOA-9 | |
| TSO-C34b | Phaostron Instruments & Electronic Co. 151 Pasadena Ave. S. Pasadena, CA 91030 | NM | | PWB1874() Ser. | | |
| TSO-C34b | Radio Corp. of America Aviation Equip. Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | ANV-210 M1-592100-1 | AVN-214 M1-592100-3 | AVN-220 M1-592100-4 |
| TSO-C34b | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM | | S41422() | | |
| TSO-C34b | Sigma Tek, Inc. 17621 N. Black Canyon Hwy Phoenix, AZ 85023 | NM | | A326A | | |
| TSO-C34c | Aeronetics Div of AAR Brooks & Perkins Corp. 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | AIRBORNE ILS GLIDE SLOPE RECEIVING EQUIPMENT | 520 8130() 520 913() | 520-8131-() | |
| TSO-C34c | Aire-Sciences, Incorporated 216 Passaic Avenue Fairfield, NJ 07006 | NE | | R-664:CID-664, CID-664A/0 | | |
| TSO-C34c | Allied/Bendix Aerospace P.O. Box 9327 Fort Lauderdale, FL 33210 | CE-A | | RNA-34AF: 3614303-3401 | | |
| TSO-C34c | Allied-Signal Aerospace Co. Bendix/King General Avn. Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | 069-1024-30 thru 069-1024-49 066-1101-00, -10 VN 4118:066-1101-00 | | |
| TSO-C34c | Allied/Signal, Inc. Bendix/King Air Transport Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33309 | CE-A | | RIA-35A:2041230-3518 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|--|
| TSO-C34c | Avtech Corporation 3400 Wallingford North Seattle, WA 98103 | NH | | 6233-1-1 6233-1-2 |
| TSO-C34c *F | Becker Flugfunkwerk GmbH Baden-Baden-Oos Germany | EU | | NAV 2000 |
| TSO-C34c | Bendix Radio Division Baltimore, MD 21204 | NE | | MTA-7() |
| TSO-C34c | Bendix Aerospace 2150 Northwest 62nd St. P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | | ED-102E:8095351-() |
| TSO-C34c | Bendix General Aviation Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | MTA-32A RIA-32A RN-242 GM-247A PS243A IN-245A HSD-880:IN-881(), DG-882(), SC-883() NP-2041A:4000896-() CN-2013A:4000895-() CD-412A: 3614005() CN-269A CP-103F DG-882() EFS-10 IN-881() IN-2014() MTA-332 MT-263B MT-265A MTA-34A:2041276-() NC-104A NC-104B NC-105B RN-262B RIA-35A RN-260B:RN-262B,CN-269A,MT-263B,MT-265A RNA-34A:2041234-() SG-101A SG-101B SD-442B SC-883 VNS-41A VN-411A: 3614003() |
| TSO-C34c | Bendix/King Air Transport Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310 | CE-A | | SG-101A:3614311-1004 SG-101B:3614335-1004, 1005, 1006, 1007, 1008, 1010, 1011, -1012, -1013 |
| TSO-C34c | Bendix/King General Avn. Avionics Div. 400 North Rogers Road Olathe, KS 66062-1212 | CE-W | | 066-4010-91, -92, -93, -94 |
| TSO-C34c *F | Chelton (Electrostatics) Ltd Marlow Buckingham, United Kingdom | EU | | 17-21() |
| TSO-C34c | Clifton Division Litton Systems, Inc. 5100 State Rd. Drexel, PA 19018 | NE | | 62000000-()()() |
| TSO-C34c | Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52498 | CE-W | | ANS-31R CMS-80() CCD-806 DPU-84:622-9682-001 DPU-85:622-6022-002/-012/-006 DPU-85A:622-7244-001, -002 DPU-85B DPU-85G DPU-85L DPU-85M DPU-85N:622-8678-002, -003 DPU-85U:622-9965-001 DPU-86A:622-7247-002 DPU-86C:622-7248-003 DPU-86D:622-7249-001 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|-----------|--|--|---|
| | | | | DPU-86H:622-7711-002 DPU-86K:622-7713-003 DPU-86L DPU-86N:622-8713-002, -003 DPU-86S:622-9285-002 DPU-86U:622-9930-001 EFD-85:622-6020-001/002/-011/-012/ -021/-022 EFD-85A:622-6464-011/-012/-021/-022 EFD-86 EFD-86A HPU-86H HPU-86K HPU-86N ILS-700:622-5221-020 KFD-85:622-6020-011, -012 KFD-85A:622-6464-001, -011, -012 KFD-86:622-6342-011, -012, -013, -014 KFD-86A:622-6535-011, -012 MPU-84:622-9684-001 MPU-85:622-6091-002/-012/-006 MPU-85A:622-7250-001, -002 MPU-85B:622-7251-001 MPU-85C MPU-85G MPU-85L MPU-85M MPU-86L MPU-85N:622-8679-002, -003 MPU-85U:622-9966-001 MPU-86A:622-7253-001, -002 MPU-86C:622-7254-003 MPU-86D:622-7255-001 MPU-86H:622-7713-003 MPU-86K:622-7718-003 MPU-86N:622-8714-002, -003 MPU-86S:622-9286-002 MPU-86U:622-9967-001 | | |
| TSO-C34c | Collins General Avn. Div. Rockwell International Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | ANS-31A GLS-350 IND-31 IND-351 IND-351D VIR-350 462-A-1 998K-1 | ANS-31C GLS-350E IND-31C IND-351A NCS-31A 339R-18 639U-1 VIR-32 | ANS-31R IND-30 IND-350A IND-351C VIR-315 339R-19 899P-1 |
| TSO-C34c | Collins Radio Group Rockwell International 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | VIR-108 IND-350 462A-1() | CNC-23 VIR-351 462B-1() | NCS-31R 639U-1 |
| TSO-C34c | Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | 51RV-4() HPU-74B VIR-31() 899P-1 339R-2 339R-16 | CCD-806 HCP-74B ANS-31 9134-1 339R-3 339R-17 | EFD-74 8902-2 NCS-31 9134-2 339R-8 |
| TSO-C34c | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | CI 120 CI 193 CI 215 | CI 158() CI 212 CI 259 | CI 159() CI 212-1 CI 259C |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|-----------|---|---|---|
| TSO-C34c | Dayton-Granger, Inc. West Coast Division 3000 Airway Avenue Costa Mesa, CA 92636 | NM | | CU994 M1592129 RGS10-259 VT10-56-6 35-5023 35-5036 | DGSC20-02 NC-10-98-() VT10-02 35-50-11-() 35-5024 35-5038 | GSNC20-05 RGS10-48 VT10-20 35-5017 35-5035 |
| TSO-C34c | Dorne and Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM N4-17-1 DM H22-1 | DM N4-17-2 DM H23-1 | DM H21-1 DM H24-1 |
| TSO-C34c | Gables Engineering, Inc. P.O. Box 340880 Coral Gables, FL 33114 | CE-A | | G7005() | G-67005() | G6692-() |
| TSO-C34c | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 West Bell Road Glendale, AZ 85308 | NM | | ED-600 DC-811:7012977-763, -764 SC-800:7004123-327/-328 SG-600/800 SG-603:7003400-624, -824 SG-803:7003400-624, -824 DC-800:7003420-965, -966 | ED-800 | |
| TSO-C34c | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KN73-() KNR605() KNR631() KGM-691() KI-207() KI-209:066-3056-01 CN-2011:CN-2011A, IN-2014A, IU-2016A KA139 KX155()/KX165() KNR634 KA120 KNR634:066-1078-00, -07 KFS-564A:071-1283-() KFS-579A:071-1281-() KPI-552B | KFS560B KNR615() KNR665() KI-204() KN 75:066-1063-00 KN53 KNS-81 KFS564 KA140 KNR-634A KFS-573 KPI-552V | KCU561() KNR630() KGS-681 KI-206() KN53 KNR6030 KA145 KNR-634A KFS-573 KPI-553B |
| TSO-C34c | Narco Avionics Div. NARCO Scientific Ind. 270 Commerce Drive Fort Washington, PA 19034 | NE | | NAV-112 ID 124() 825 VDA822 | NAV-114 NAV 124 ID825 MK-12D NE800 | NAV 122() NAV 200 |
| TSO-C34c | Radio Corp. of America Aviation Equip. Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVN-211 AVN-214A AVN-220A | AVN-210A MI-585079-() MI-585073-() | MI-585072-() |
| TSO-C34c | Rockwell International Avionics & Missiles Group 400 Collins Road, NE Cedar Rapids, IA 52406 | CE-W | | ILS-700:622-5221-001 | | |
| TSO-C34c | Rockwell International Collins Avionics Div. 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | HPU-74A:622-6199-001 HCP-74:622-6200-001, -002, -003, -004 | | |
| TSO-C34c | Rockwell International Collins Division 7201 Lemon Avenue Dallas, TX 75209 | SW | | 648-4774-() | | |
| TSO-C34c | Sigma Tek, Inc. | NM | | 443B | 843A | 1043A |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|--|-------------------------------|---------------------------|
| | 17621 N. Black Canyon Hwy. Phoenix, AZ 85023 | | | | | |
| TSO-C34c | Sperry Flight Systems Avionics Division P.O. Box 29000 Phoenix, AZ 85038 | NM | | 6098032-() ED2600/800:7003110-C, 7003400-(), 7003420-(), 7003430-(), 7004123-() | 6098025-() | |
| TSO-C34c | Trivec-Avant Corp. 17851 Jamestown Lane Huntington Beach, CA 92647 | NM | | 21-37-() 24-37-() | 22-37-() 44-70-() | 23-30-01-() 46-70-() |
| TSO-C34d | Aeronetics Div. of AAR Brooks & Perkins Corporation 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | AIRBORNE ILS GLIDE SLOPE RECEIVING EQUIPMENT | 421A 421D 431C | 421B 431A 431D | 421C 431B |
| TSO-C34d | Aeronetics A Div. of AAR Brooks & Perkins Corp. 2100 Touhy Avenue Elk Grove Village, IL 60007 | CE-C | | HSI-4X1X | | |
| TSO-C34d *F | Becker Flugfunkwerk Gmbh Niederwaldstr. 20 D-7550 Rastatt Germany | EU | | NAV 3300 | | |
| TSO-C34d | Collins Avionics Division Rockwell International 400 Collins Road NE Cedar Rapids, IA 52406 | CE-W | | ASP-1000 DU-1000:622-7484-411 DCP-1000 313N-60 | EFD-870 MEM-871 | |
| TSO-C34d | Collins General Avn. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32902-1060 | CE-A | | CTL-32:622-6521 CAD-31 VIR-32:622 6137 RTU-870 RTU-870(A) | CTL-32a 313N-6C VIR-432 | |
| TSO-C34d | Collins General Avn. Div. Avionics Group Rockwell Int'l Corp. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | | RTU-870A:622-9346-011, -012, -013 CAD-870:622-7695() | | |
| TSO-C34d | Dorne & Margolin Inc. 2950 Veterans Memorial Hwy Bohemia, NY 11716 | CE-C | | DN H9-17-1 | | |
| TSO-C34d *F | Electronique Aerospatiale B.P. 51 93350 Le Bourget France | EU | | BCI 2323:889-2323()() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|-----------|---|
| TSO-C34d | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G6164() G6165() G6227() G6229() G6895() G6950() G6860() G6868() G6966() G7007() G7016() G7024():01, -02, -03, -04, -07, -08, -09, -10, -11, -14, -15, -18, -19, -23, -24, -25, -26, -27 G7045() G7056() |
| TSO-C34d | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. Avionics Facility 5353 W. Bell Road Glendale, AZ 85308 | NM | | DC-811:7012977-747 thru -758, -763, -764, -765, -766 DC-810:7005819-747 thru -758, -763, -764, -765, -766, -767, -768, -933, -934 DC-820:7007277-() DC-811:7012977-767, -768, -933, -934 EDZ-605/805 MG-603 MC-800:7007062-(), -701, -702, -721, -722, -833, -834, -933, -934 MG-605/805:7011673-605, -606, -607, -805, -807, Mod F MG-603:7007061-624, -824 MG-611:7007321-512 MG-800:7007061-(), -902, 7007062-() MG-803:7007061-624, -824 MG-805 MG-810:7007321-() MG-815, 816:7011675-(), -315 MG-816:7011675-216 MG-817 MG-820:7009289 MG-800 RNZ-850:7210100-901, 902, -903, -904, -907, -911, -912, -913, -914 RM-850:7012100-943, -944, -953, -954 SC-800 SC-610 SG-605/705/805:7011672-605, -705, -805 SG-605:7011672-606 SG-605/805:7011672-605, -607, -805, -807 7011673-605, -805 SG-611:7004544-512 SG-705:7011672-705, -707 SG-811:7004544-712 SG-815:7011674-117, -315 SG-816:7011674-216 SG-817 SG-610/810:7004544-() SG-815, -816:7011674 SG-820:7007356-() SR2-850 SG-805 |
| TSO-C34d | Marco Avionics, Inc. 270 Commerce Drive Fort Washington, PA 19034 | NE | | NS 801 NE 800 |
| TSO-C34d | Sensor Systems, Inc. 8929 Fulbright Avenue Chatsworth, CA 91311 | NM | | S65-247-() Series |
| TSO-C34d | Skylight Avionics Co. 38629 6th Street East Palmdale, CA 93550 | NM | | NAV-550:500-500-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|--|--|
| TSO-C34e | Aeronautics 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | ILS GLIDE SLOPE RECEIVING EQUIPMENT OPERATING WITHIN 328.6 TO 335.4 MEGAHERTZ | HSI-415():520-415()-() () () 520-2011-002 DCU-201B-1:520-2011-002 HSI-423A:520-4230-() () () |
| TSO-C34e | Aeronetics Div. of AAR Brooks & Perkins Corp. 2100 Touhy Ave. Elk Grove Village, IL 60007 | CE-C | | 520-2011-002 520-415()-() () () |
| TSO-C34e | Bendix/King Radio Corp. 400 North Rogers Road Olathe, KS 66062-1212 | CE-W | | KW40:066-01130-0501, -0601, -0701, -0801 |
| TSO-C34e | Dorne & Margolin Inc. 2950 Veterans Memorial Hwy Bohemia, NY 11716 | NE | | DM N4-45-4 DM N4-17/N VOR/LOC/GS :DM U227-(), DM N4-45-4 |
| TSO-C34e | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G6979() Model G4422() |
| TSO-C34e | Honeywell, Inc. Air Transport P.O. Box 21111 Phoenix, AZ 85036-1111 | NM-L | | BAe146:4066300-(), 4066192-(), 4066191-(), 4066190-() |
| TSO-C34e | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Division 21111 N. 19th Avenue Phoenix, AZ 86036-1111 | NM-L | | MD-80:4055900-(), 4056510-(), 4056512-() 4056511-(), 4056513-() |
| TSO-C34e | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Business & Commuter Avn. Systems Div. 5353 W. Bell Road Glendale, AZ 85308 | NM-L | | ED2-600/800:4066300-(), 4066192-(), 4066191-(), 4066190-() SG-806:7013788-807 |
| TSO-C34e | Rockwell International Collins Avionics Div. 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | ADD-640B:622-9735-001, -002 EFD-84:622-9681-001, -002, -011, -012 ILS-720:622-9738-020, -220 ILS-720 ILS:622-9738-020 SDD-640:622-7207-002 SDD-640A:622-8336-010, -011, -012 622-9347-001 SDU-640B:622-9735-001, -002 |
| TSO-C35 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | AIRBORNE RADIO MARKER RECEIVING EQUIPMENT | 51Z-2 Ser. 51Z-3 51Z-4 VIR-30() |
| TSO-C35 | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KA40() KNI-500/500L KGM-690 KA23() KA35() KMR675() KMR-670 |
| TSO-C35 | Lear Siegler, Inc. | NM-W | | 5608 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|---|---|----------------------------|---------------------------|
| | Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | | | | | |
| TSO-C35 | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM-W | | AVN-221 MI-592100-4 | MI-592100-1 | MI-592100-3 |
| TSO-C35 | Trivec Corporation 4014 Chandler Avenue Santa Ana, CA 92704 | NM-W | | 31-10-() 32-10-() | | |
| TSO-C35a | Bendix Radio Division Baltimore, MD 21233 | NE | AIRBORNE RADIO MARKER RECEIVING EQUIPMENT | MTA-7() MKA-23 Ser. | MKA-7 Ser. MTA-23 Ser. | INA-21 Ser. PSA-7 Ser. |
| TSO-C35a | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM-W | | AVR-200 | AVR-200A | |
| TSO-C35b | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | AIRBORNE RADIO MARKER RECEIVING EQUIPMENT | MKA-28() MKA-7() PSA-7() | MTA-8() MKA-23() | INA-21() MTA-23() |
| TSO-C35b | Bendix Radio Division Baltimore, MD 21233 | NE | | MTA-7() MKA-23 Ser. | INA-28 Ser. MTA-23 Ser. | MKA-28() PSA-7 Ser. |
| TSO-C35b | Sigma Tek, Inc. 17621 W. Black Canyon Hwy. Phoenix, AZ 85023 | NM | | 402A | 402B | |
| TSO-C35b | Sperry Flight Systems Avionics Division P.O. Box 29000 Phoenix, AZ 85038 | NM-W | | 6098032-() | | |
| TSO-C35c | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | AIRBORNE RADIO MARKER RECEIVING EQUIPMENT | MKA-28D() MKA-300 VN-411A:3614003() CD-412A:3614005() | MKA-28C() | MK-301() |
| TSO-C35c | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM-W | | 16D00400 | CI 118 | CI 155() |
| TSO-C35c | Communications Components 3000 Airway Ave. Costa Mesa, CA 92626 | NM-W | | AT908A MI-592130 | EMB-10-14 35-5016 | FMB-10-148() |
| TSO-C35c | Dorne and Margolin, Inc. 3950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM N27-1 DM N43-1 | DM N27-2 | DM N27-3 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|----------------|---|--|--------------------|
| TSO-C35c | Dynair Electronics, Inc. 6360 Federal Blvd. San Diego, CA 92114 | NM-W | | NB 4050 | 9900-0721() Ser. | |
| TSO-C35c *F | Electronique Aerospatiale P. O. Box 4 93350 LeBourget Aeroport Paris France | EU | | RM671 | | |
| TSO-C35c *F | Elliott Brothers (London) Ltd. Christopher Martin Rd. Basildon, Essex, England | EU | | AD260 | | |
| TSO-C35c | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KR21() | KMA200-() | KGM691() |
| TSO-C35c | Marconi, Ltd. See Elliott Brothers Ltd. | | | | | |
| TSO-C35c | Phaostron Instrument & Electronic Company 151 Pasadena Ave. So. Pasadena, CA 91030 | NM | | PWB 1874() | Ser. | |
| TSO-C35c | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVN-210 AVN-214 AVN-210A AVN-214A AVN-220A AVN-212A | AVN-211 AVN-215 NI-585072-() NI-585079-() NI-585073-() NI-585078-() | AVN-212 AVN-220 |
| TSO-C35c | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM | | S35-1000-() S35-2000-() | Ser. Ser. | |
| TSO-C35d | Aire-Sciences, Inc. 216 Passaic Avenue Fairfield, NJ 07006 | NE | AIRBORNE RADIO | AM-660-() | Century 85 | |
| TSO-C35d | ARC Avionics Division P.O. Box 150 Boonton, NJ 07005 | NE | | F-490A | | |
| TSO-C35d | Avtech Corporation 3400 Wallingford North Seattle, WA 98103 | NM | | 6233-1-1 | 6233-1-2 | |
| TSO-C35d *F | Becker Flugfunkwerk GmbH Baden-Baden-Oos Germany | EU | | NAV 2000 | NAV 3300 | |
| TSO-C35d | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 3310 | CE-A | | RN-242 IN-245 CN-2011:CN-2011A CN-2013A:4000895-() RN-260B:RN-262B, CN-269A, MT-263B, MT-265A VN-411A:3614003() CD-412A:3614005() | GM-247A RVA-36A | PS243A |
| TSO-C35d | Bendix/King Air Transport | SO | | RVA-36A:2041231-3610 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|--|
| | Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310 | | | |
| TSO-C35d *F | Chelton (Electrostatics) Ltd Marlow Buckingham, United Kingdom | EU | | 17-9() |
| TSO-C35d | Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | VOR-700 DU-1000 DCP-1000 313N-6G:622-7490-001/-002/-003 DU-1000:622-7484-250, -301, -411 DCP-1000:622-7485-301, -201 EFD-870:622-7391-101 MEM-871:622-7395-101 |
| TSO-C35d | Collins Avionics Division/ Radio Group Rockwell International 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | VIR-108 |
| TSO-C35d | Collins General Avia. Div. Rockwell International Melbourne Operations P.O. Box 1060 Melbourne, FL 32907 | CE-A | | MKR-350 MKL-350 MKL-351 AMR-350 AMR-350H VIR-32:622-6137() VIR-432:622-7194-() CAD-31:622-6332-001 CAD-31:622-8332-001 313N-6C:622-7490-001/-002/-003 |
| TSO-C35d | Collins Radio Co. 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | VIR-() |
| TSO-C35d | COMANT Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | CI 102 CI 118 CI 158() 16D00400-1 16D00400-2 CI 159() 16D00500() |
| TSO-C35d | Dayton-Granger, Inc. West Coast Division 3000 Airway Avenue Costa Mesa, CA 92626 | NM | | EM810-14 35-5016 MI-592130 FM810-272() |
| TSO-C35d | Dorne & Margolin Inc. 2950 Veterans Memorial Hwy Bohemia, NY 11716 | CE-C | | DM-H21-1 |
| TSO-C35d | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G7005() G-67005() G6828() G6436() G7056() |
| TSO-C35d | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. P.O. Box 21111 Phoenix, AZ 85027 | NM | | 6098032-() |
| TSO-C35d | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 W. Bell Road Glendale, AZ 85308 | NM | | SRZ-850 RM-850:7012100-943, -944, -953, -954 RNZ-850:7510100-901, -902, -903, -904 -907, -911, -912, -913, -914 |
| TSO-C35d | King Radio Corporation 400 North Rogers Road Olathe, KS 66061 | CE-W | | KA 26 KFS 564 K1 203 KI 204 KMA 24 KNR 634 KNR 634A VN4118:066-1101-00, -10 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|---|---|--|---|
| | | | | KN 40:066-01130-0501, -0601, -0701, -0801 | | |
| TSO-C35d | Narco Avionics Corporation Commerce Drive Fort Washington, PA 19034 | NE | | MKR 101 NAV 122() CP 136 | MKR 101R NAV 124() CP 136T | MKR 101PL CP 135 ID 124() |
| TSO-C35d | Sigma Tek, Inc. 17621 N. Black Canyon Hwy. Phoenix, AZ 85023 | NM | | F490A | | |
| TSO-C35d | Trivec-Avant Corporation 17851 Jamestown Lane Huntington Beach, CA 92647 | NM | | 31-10-01 | 32-10-02 | 32-10-03 |
| TSO-C36 | Bendix Radio Division Baltimore, MD 21233 | NE | AIRBORNE ILS LOCALIZER RECEIVING EQUIPMENT | MVA-22 Ser. | MSA-26() | MVA-21 Ser. |
| TSO-C36 | Clifton Division Litton Systems, Inc. 5100 State Rd. Drexel Hill, PA 19018 | NE | | 62000000-()()() | | |
| TSO-C36 | Collins Radio Co. 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | 51R-4 51R-7 51RV-1A 51X-2 51X-3 197B-1 313N-2/3 313N-2D/3D 344A-2 837-() VIR-30M 614U-3 618U-8 | 51R-4A 51R-8 51RV-2B 51X-2B 51X-3A 313N-() 313N-4B 344D-1 344B Ser. VIR-30() VIR-31() 614U-4 | 51R-6 51RV-1 51RV-1C 51X-2C 147B-1 313N-6C 313N-4C 344A-1 837 VIR-30A 599A-1() 614U-7 |
| TSO-C36 | Communications Components 3000 Airway Ave. Costa Mesa, CA 92626 | NM | | 35-5016 | 35-5023 | EMB 10-14 |
| TSO-C36 | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KA39 KN74() KNI-520 175() | KN70/71 KNI500/500L KNR-600 KNR-660 | KN74 KNI-510 KNR-610 KR-21() |
| TSO-C36 | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 2374 | 5609B | |
| TSO-C36 | NARCO Avionics Div. NARCO Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | VOA-3A NAV 110 NAV 114 | VSC-2 NAV 111 DGO 10 CONV | VSRP-1 NAV 112 DGO 10 GYRO |
| TSO-C36a | Aire-Sciences, Incorporated 216 Passaic Avenue Fairfield, NJ 07006 | NE | AIRBORNE ILS LOCALIZER RECEIVING EQUIPMENT | R-664 | | |
| TSO-C36a | Bendix | CE-A | | INA-21() | MNA-21() | NVA-21() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|---|--|--|-------------------------------------|
| | Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | | | RA-21() EFS-10 SG-101A:3614311-1004 SG-101B:3614335-1004 | NVA-22() | RA-22() |
| TSO-C36a | Bendix Radio Division Baltimore, MD 21233 | NE | | NVA-21() MTA-21() PSA-21() RA-21() | INA-21 Ser. NVA-22() OBS-21 Ser. RNA-26C | MNA-21 Ser. EA-22() RA-22() |
| TSO-C36a | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | 313N-2:522-2447-005/015/045 RTU:622-7356-() | | |
| TSO-C36a | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 4087A | 4087B | |
| TSO-C36a | NARCO Avionics Div. NARCO Scientific Ind. Commerce Drive Fort Washington, PA 19034 | NE | | NAV 200 | | |
| TSO-C36a | Rockwell International Avionics Group 400 Collins Road W.E. Cedar Rapids, IA 52498 | CE | | 313N-2:522-2447-574 | | |
| TSO-C36b | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | AIRBORNE ILS LOCALIZER RECEIVING EQUIPMENT | RNA-26 MSA26() | RNA-26C() RNA-26CF | RNA26CF() CNA-26b |
| TSO-C36b | Bendix Radio Division Baltimore, MD 21233 | NE | | CNA-26b | RNA-26CF | |
| TSO-C36b | Bendix/King Air Transport Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33309 | CE-A | | RPA-1BB:8055730-() | | |
| TSO-C36b | Collins Avionics Division Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | 51RV-2B | | |
| TSO-C36b | Collins Radio Co. 5225"C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 51RV-2() | 837B-() | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|---|---|--|--|
| TSO-C36b | Communications Components 3000 Airway Ave. Costa Mesa, CA 92626 | NM | | 35-5008 35-5024 NC 10-124 AT-902AR | 35-5011() VT 10-02 MI-592127 GSNC 20-05 | 35-5017 NC 10-54 AT-902AF |
| TSO-C36b | Dorne and Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM M5 DM N4-8 DM N4-20 | DM N4-4 DM N4-10/8 DM N4-21 | DM N4-7 DM N4-15 DM N42-1 |
| TSO-C36b *F | Electronique Aerospatiale P. O. Box 4 93350 LeBourget Aeroport Paris, France | EU | | RV 671 | RGA 671 | |
| TSO-C36b *F | Elliott Brothers (London) Ltd. Christopher Martin Rd. Basildon, Essex, England | EU | | AD260 | | |
| TSO-C36b | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Avenue Phoenix, AZ 85027 | NM | | 2588654-() Ser. | | |
| TSO-C36b | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KNR-601 | KNC-610() | KNR-661() |
| TSO-C36b | NARCO Avionics Div. NARCO Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | COM/NAV-100 VOA-9 | Mark 24 | VOA-8 |
| TSO-C36b | Phaotron Instrument & Electronic Company 151 Pasadena Ave. So. Pasadena, CA 91030 | NM | | PWB 1874() Ser. | | |
| TSO-C36b | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVN-210 AVN-211A AVN-214 AVN-215A AVN-221 | AVN-210A AVN-212 AVN-214A AVN-220 AVN-221A | AVN-211 AVN-212A AVN-215 AVN-220A |
| TSO-C36b | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM | | S65-147-() Ser. | | |
| TSO-C36c | Aeronetics Div. of AAR Brooks & Perkins Corp. 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | AIRBORNE ILS LOCALIZER RECEIVING EQUIPMENT | 520 8130() | 520 8131() | 520 913() |
| TSO-C36c | Aire-Sciences, Incorporated 216 Passaic Avenue Fairfield, NJ 07006 | NE | | CID-662, CID-662 A/O CID-664 R-662() | PS-661() | |
| TSO-C36c | Allied/Bendix Aerospace P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | | RNA-34AF: 3614306-3401 | | |
| TSO-C36c | Avtech Corporation | NM | | 6233-1-1 | 6233-1-2 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|---|
| | 3400 Wallingford North Seattle, WA 98103 | | | |
| TSO-C36c *F | Becker Flugfunkwerk GmbH Baden-Baden-Oos Germany | EU | | NAV 2000 |
| TSO-C36c | Bendix Aerospace 2150 Northwest 62nd St. P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | | ED-102E:8095351-() |
| TSO-C36c | Bendix General Aviation Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | MTA-32A RIA-32A RN-242 RN-242A PS-243A 1N-244A 1N-245A RIA-35A CN-2011:CN-2011A, 1N-2014(), 1U-2016A HSD-880:1N-881(), DG-882(), SC-883() NP-2041A:4000896-() CN-2013A:4000895-() RN-2608: RN-262B, CN-269A, MT-263B, MT-265A RNA-34A:2041234-() MTA-34A:2014276-() CP-103F:8095477-() VN-411A:3614003() CD-412A:3614005() SD-442B:8095263-() NC-104A:3614313-() NC-104B:3614331-() NC-105B:8095679-() SG-101A SG-101B |
| TSO-C36c | Bendix/King Air Transport Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310 | SO | | EFS-10:SG-101A, SG-101B RIA-35A:2041230-3518, -3519, -3523 SG-101B:3614335-1012, -1013 |
| TSO-C36c | Bendix/King Radio Corp. 400 North Rogers Road Olathe, KS 66062-1212 | CE-W | | KNR 634A:206-0103-06 |
| TSO-C36c | Century Flight Systems, Inc. SW P.O. Box 610 Mineral Wells, TX 76067 | | | IC707-() |
| TSO-C36c | Cessna Aircraft Company ARC Avionics Division P.O. Box 150 Rockaway Valley Road Boonton, NJ 07005 | NE | | 479A |
| TSO-C36c *F | Chelton (Electrostatics) Ltd. Marlow Buckingham, United Kingdom | EU | | 7-41() 17-14() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|-----------|--|--|--|
| TSO-C36c | Collins General Avn. Div. Rockwell International Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | ANS-351 GLS-350 IND-31 IND-350A IND-351A VIR-315 | ANS-351C:P/N GLS-350E IND-31C IND-350G IND-351C VIR-350 | 622-5579-() IND-30 IND-350 IND-351 IND-351D VIR-32 |
| TSO-C36c | Collins Radio Group Rockwell International 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | VIR-108 CNC-23 462B-1() | VIR-351 639U-1 | 614E-44 462A-1() |
| TSO-C36c | Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | NCS-31R 51RV-4() EFD-85:622-6020-011/-012/-021/-022 EFD-85A:622-6464-011/-012/-021/-022 MPU-74B:622-9221-001 MCP-74B:622-9222-001 thru 004 | ANS-31R 51R-10() | RPU-31A |
| TSO-C36c | Collins Radio Co. 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | 390Y-7 VIR-31() DRC 20-04 899P-1 339R-2 339R-16 | 890Z-2 VT 10-56() Ser. NCS-31 913Y-1 339R-3 339R-17 | 1LS-70() ANS-31 913Y-2 339R-8 |
| TSO-C36c | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | CI 120 CI 215 | CI 158C() CI 259 | CI 159C() CI 259C |
| TSO-C36c | Communications Components 3000 Airway Avenue Costa Mesa, CA 92626 | NM | | VT10-56-6:35-5038 | | |
| TSO-C36c | Dayton-Granger, Inc. West Coast Division 3000 Airway Avenue Costa Mesa, CA 92636 | NM | | 35-5008 35-5024 DRC20-04 NC10-98-() VT10-56() | 35-5011-() 35-5038 GSN20-05 VT10-20 | 35-5017 CU994 MI592129 VT10-56-6 |
| TSO-C36c | Delta Electronics Mfrg. Co. Suite 605 11311 Harry Hines Blvd. Dallas, TX 75229 | SW | | DE127 | | |
| TSO-C36c | Dorne and Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM N4-17-1 | DM N4-17-2 | |
| TSO-C36c | Edo-Aire Mitchell P. O. Box 610 Mineral Wells, TX 76067 | SW | | 1C707-() | | |
| TSO-C36c | Foster Airdata Systems, Inc. 7020 Buntley Road Columbus, OH 43229 | CE-C | | RNAV-612 LNS616A/RNC601A | LNS616/RNC 601 | |
| TSO-C36c | Gables Engineering, Inc. P.O. Box 340880 Coral Gables, FL 33114 | CE-A | | G7005() G6692 | G-67005() G-7024() | G7016() G6164() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|-----------|--|---|--|
| TSO-C36c | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KR-21() KFS560B KNR615() KNR632() KNR634 K1203 K1208:066-3056-00 K1209:066-3056-01 KNR634A KNR-633:066-4007-03 KX175B KA139 KX155()/KX165() KFS-564A:071-1283-() KFS-579A:071-1281-() KFS564A:071-1285-28 thru -33 KFS579A:071-1291-12,-13,-15,-16,-17,-18,-20,-21,-22,-23,-25,-26,-27 KFS-579A:071-121-28 thru 33 KPI553B:066-3069-00,-01,-03,-04 KNR634A:066-1078-10 thru -17 KNS 81:066-4010-91,-92,-93,-94 KPI552V:066-3081-00 thru -04 KFS564A:071-1283-12,-13,-15 thru -18,-20 thru -23,-25,-26,-27 KFS579A:071-1281-12,-13,-15 thru -18,-20 thru -23,-25,-26,-27 KFS579A:1281-28 thru -33 KX 155 NAV-COM:069-1024-30 thru 069-1024-49 VN411B:066-1101-00,-10 | KN-77 KCU561() KNR630() KNR665() KA140 K1204 KFS564 KNR634 KNR6030 KN74 KNS-81 KPI552B KPI553B | KX175 KNR605() KNR631() KN 72() KA145 K1206 KFS564 KNR634 KNR6030 KN53 KPI552B KPI553B |
| TSO-C36c | Marco Avionics Corp. 270 Commerce Drive Fort Washington, PA 19034 | NE | | OC-110 NAV 124() 824 1D825 VOA 822 | NAV 121() 1D124() 1D824 MK-12D | NAV 122() RNAV 161 825 VOA 821 |
| TSO-C36c | Rockwell International Avionics & Missiles Group 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | | EFD-85:622-6020-001/002 DPU-65:622-6022-002 1LS-700:622-5221-001,-020 IND-350G MPU-65:622-6091-002 | | |
| TSO-C36c | Rockwell International Collins Division 7201 Lemon Avenue Dallas, TX 75209 | SW | | 648-4774-() | | |
| TSO-C36c | SCI Technology, Inc. 8600 S. Memorial Parkway P.O. Box 1000 Huntsville, AL 35807 | CE-A | | 5184100-001 | | |
| TSO-C36c | Sigma Tek, Inc. 17621 N. Black Canyon Hwy. Phoenix, AZ 85023 | NM | | 328T B-445A 485A 428B IN-381AC IN-382AC IN-483AC IN-1049A 1048A | 385A 478A 485B IN-380AC IN-480AC IN-383AC IN-1048A IN-1049AC 1048B | 428A 479A 878A IN-381A IN-481AC IN-482AC IN-1048AC 1079A |
| TSO-C36c | Trivec-Avant Corp. | NM | | 21-37-() | 21-37-01 | 22-37-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|---|--|
| | 17851 Jamestown Lane Huntington Beach, CA 92647 | | | 22-30-() 22-37-01 22-37-02 22-37-05 22-37-11 22-37-12 23-30-() 24-37-() 24-37-01 24-37-11 |
| TSO-C36d | Aeronatics Div. of AAR Brooks & Perkins Corp. 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | AIRBORNE ILS LOCALIZER RECEIVING EQUIPMENT | HS1-4X1X 421A:520-4210-001, 520-4210-002, 520-4210-003, 520-4210-004 421B:520-4211-001, 520-4211-002, 520-4211-003, 520-4211-004, 421C:520-4212-001, 520-4212-002, 520-4212-003, 520-4212-004 421D:520-4213-001, 520-4213-002, 520-4213-003, 520-4213-004, 520-4213-006 431A:520-4310-001, 520-4310-002, 520-4310-003, 520-4310-004 431B:520-4311-001, 520-4311-002, 520-4311-003, 520-4311-004 431C:520-4312-001, 520-4312-002, 520-4312-003, 520-4312-004 431D:520-4313-001, 520-4313-002, 520-4313-003, 520-4313-004 |
| TSO-C36d *F | Becker Flugfunkwerk Niederwaldstr. 20 D-7550 Rastatt Germany | EU | | NAV 3300 |
| TSO-C36d | Collins Avionics Division Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | MEM-871:622-7395-101 EFD-870:622-7391-101 313N-6G:622-7490-001/-002/-003 313N-60:622-7490-001/-002/-003 DU-1000:622-7484-301,-250,-411 DCP-1000:622-7485-301,-201 DCP-1000:622-7485-201,-301 |
| TSO-C36d | Collins General Avn. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | CTL-32:622-6521() VIR-32:622-6137() VIR-432:622-7194-() CTL-32A:622-8738-() CAD-31:622-8332-001 RTU-870:622-7356-() VIR-32/DME-42:622-8738-() 001 thru 016, 025 thru 032, 801 thru 804 |
| TSO-C36d | Collins General Avn. Div. P.O. Box 1060 Miami, FL 32901 | CE-A | | RTU-870:622-7356-001 |
| TSO-C36d | Collins General Avn. Div. Avionics Group Rockwell Int'l Corp. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | SO | | RTU-870A:622-9346-001, -002, -003, -011, -012, -013 CAD-870G:622-7695():-001, -002 |
| TSO-C36d | Dorne & Margolin Inc. 2950 Veterans Memorial Hwy Bohemia, NY 11716 | CE-C | | DM H21-1 DM N-9-17-1 |
| TSO-C36d *F | Electronique Aerospatiale B.P. 51 93350 Le Bourget | EU | | BC12323:889-2323()()() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|---|--|
| ===== | | | | |
| France | | | | |
| TSO-C36d | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G7007() G6165() G6868 G6895() G6950() G6860() G7024():-01, -02, -03, -04, -07, -08, -09, -10, -11, -14, -15, -18, -19, -23, -24, -25, -26, -27 G7045() G6227() G6229() G7056() |
| TSO-C36d | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 West Bell Road Glendale, AZ 85308 | NM | | SRZ-850 RM-850:7012100-943, -944, -953, -954 RNZ-850:7510100-901, -902, -903, -904, -907, -911, -912, -913, -914 |
| TSO-C36d | Narco Avionics, Inc. 270 Commerce Drive Fort Washington, PA 19034 | NE | | NS 801 NE800 |
| TSO-C36d | Sensor Systems, Inc. 8929 Fulbright Ave. Chatsworth, CA 91311 | NM | | S65-247-() |
| TSO-C36d | Skylight Avionics Company 38629 6th Street East Palmdale, CA 93550 | NM | | NAV-550:550-500-() |
| TSO-C36d | Trivec-Avant Corporation 17851 Jamestown Lane Huntington Beach, CA 92647 | NM | | 31-10-02 |
| TSO-C36e | Aeronetics 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | AIRBORNE ILS RECEIVING EQUIPMENT OPERATING WITHIN 108-112 MEGAHERTZ (MHz) | HSI-423A:520-4230-() () () DCU-2018-1:520-2011-002 |
| TSO-C36e | Dorne & Margolin Inc. 2950 Veterans Memorial Hwy. Bohemia, New York 11716 | CE-C | | VOR/LOC/GS P/W DM U227-(), DM N4-17/N, DM N4-17-1/N VOR:DM N36-4 |
| TSO-C36e | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | Model G4422() G6979() |
| TSO-C36e | King Radio Corp. 400 N. Rogers Rd. P.O. Box 106 Olathe, KS 66061 | CE-W | | KN 40:066-01130-0501, -0601, -0701, -0801 |
| TSO-C36e | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | ILS-720:622-9738-020, -220 |
| TSO-C37 | Bendix Radio Division Baltimore, MD 21204 | NE | VHF RADIO COMMUN- ICATIONS TRANS- MITTING EQUIPMENT OPERATING WITHIN THE RADIO FREQUENCY RANGE | TA-20B PSA-21() RA-22() MSA-41() RTA-41() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|---|------|--------------------------|--|--|---|
| | | | OF 118-136 MEGACYCLES | | | |
| TSO-C37 | Bendix Avionics Div. P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | SG-101A:3614311-1004 SG-101B:3614335-1004 | | |
| TSO-C37 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 17L-6 17L-8 VHF-20() 313N-2/3 427D-1 614U-6 618F-1B 618M-1 618M-1C 618M-2B 37R Ser. | 17L-7 17L-8A 313N-() 390R-11C 614U-1 618F-1 618F-1C 618M-1A 618M-1D 618M-2D 137X Ser. | 17L-7A 17L-8B 313N-2D/3D 390U-4() 614U-2 618F-1A 618F-1D 618M-1B 618M-() 516J Ser. |
| TSO-C37 | Dorne and Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM C25-7 DM C50-3B DM C63-1 | DM C50-2 DM C50-11 DM C63-1/A | DM C50-3 DM-C50-11A DM-C58-1 |
| TSO-C37 | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KA39 KTR-9000 | KN70/71 | KTR-900 |
| TSO-C37 | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 5639 | 5640 | |
| TSO-C37 | WARCO Avionics Div. Narco Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | VSC-1 NAV-111 | VSC-2 | VSRP-1 |
| TSO-C37 | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVC-111A | | |
| TSO-C37 | Rockwell International Avionics Group 400 Collins Road NE Cedar Rapids, Iowa 52498 | CE-W | | 137X-1:CPN 522-1136-011 | | |
| TSO-C37 | Turner Aircraft Radio, Inc. Indianapolis, IN 46206 | CE-C | | 230C-1 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|------------------------------------|-----------------------------------|---------------------------------|
| TSO-C37a | Aircraft Radio Corp. Boonton, NJ 07005 | NE | VHF RADIO COMMUNICATIONS TRANSMITTING EQUIPMENT OPERATING WITHIN THE RADIO FREQ. RANGE OF 118-136 MEGACYCLES | RT-11D T-27A M309G | T-25C 317A RT-302B | T-25D M302G RT-320A |
| TSO-C37a | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | ANA-20() PSA-20() TA-21() | TA-20() PSA-21() TA-22() | MTA-21 ANA-22() RA-21() |
| TSO-C37a | Bendix Radio Division Baltimore, MD 21204 | NE | | ANA-20 MTA-21() TA-22 | PSA-20() TA-21() | TA-20() ANA-22 |
| TSO-C37a | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | 313N-2 | | |
| TSO-C37a | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | 66950() | | |
| TSO-C37a | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE | | 313N-2:522-2447-574 | | |
| TSO-C37b | Aircraft Radio & Control Div. of Cessna Aircraft Boonton, NJ 07005 | NE | VHF RADIO COMMUNICATIONS TRANSMITTING EQUIPMENT OPERATING WITHIN THE RADIO FREQ. RANGE OF 118-136 MEGACYCLES | 428A 485B | 1038A | 485A |
| TSO-C37b | Aire-Sciences, Incorporated Fairfield, NJ 07006 | NE | | PS-661 | RT-661A() | |
| TSO-C37b | Allied/Signal, Inc. Bendix/King Air Transport Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33309 | CE-A | | RTA-44A:2041237-4417 | | |
| TSO-C37b | Avtech Corporation 3400 Wallingford North Seattle, WA 98103 | NM | | 6123-1 | | |
| TSO-C37b *F | Becker Flugfunkwerke GmbH Baden-Baden-Oos, West Germany | EU | | COMM 2000 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|---|--|---|
| TSO-C37b | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | RT-221() MSA-41() PS-243A RT-241A CN-2011:CN-2011A, AT-2073A NP-2041A:4000896-() CN-2013A:4000895-() PA-2018A:401169-() RTA-44A:2041237 | MSA-42A RTA-41() RTA-43 | RTA-42A() RT-241B MTA-43A |
| TSO-C37b | Bendix Radio Division Baltimore, MD 21204 | NE | | TA-20() | | |
| TSO-C37b *F | Chelton (Electrostatics) Ltd Marlow Buckingham, United Kingdom | NH | | VHF 12-66() | | |
| TSO-C37b | Collins Avionics Division Rockwell International 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | CNC-23 618M-3 | VHF-251 618M-2B | VHF-20A/20B |
| TSO-C37b | Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | VHF-251S:622-3307-() VHF-250():622-2079-001, 622-3365-001, 622-3364-001 CMS-80() CTL-21() CTL-40() CTL-61() VFP-702 313N-5:622-2599-502 | CCD-806 CTL-30() CTL-41() CTL-90() VHF-700 | CTL-20() CTL-31() CTL-60() CTL-91() |
| TSO-C37b | Collins General Avia. Div. Rockwell International Costa Mesa Operations 3000 Airway Avenue Costa Mesa, CA 92626 | NH | | VF10-10()* VF10-108() 35-5006()* 35-5003 35-5011-() *Authorization is extended to include series approval for these part numbers. | VFS10-90() VF10-347 35-5039()* AT-907A NC10-98-() | VC10-126() 35-5002 VF10-60 MI-592128 |
| TSO-C37b | Collins General Avia. Div. Rockwell International Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | VHF-251 VHF-250 VHF-253 339R-7 639U-1 | VHF-251S VHF-250E VHF-253S 339R-11 889P-1 | VHF-251E VHF-250S NCS-31A 462-A-1 |
| TSO-C37b | Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | NCS-31R | CTL-20()/21() | |
| TSO-C37b | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 390R-11() 339R-9 618M-3 VHF-20A 899P-1 339R-2 339R-6 639U-1 | 390Y-7 339R-11 618M-3A VHF-20B 913Y-1 339R-3 339R-7 462A-1() | 618M-2A 618M-2C NCS-31 913Y-2 339R-5 462B-1() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|--|---|--|
| TSO-C37b | Comant Industries Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | CI-175 CI 119() CI 139() CI 196() CI 108() CI 211() | CI 121 CI 127A() CI 144() CI-177 CI 238() CI 122() | CI 109 CI 138() CI 145() CI 238 CI 177() |
| TSO-C37b | Communications Components 3000 Airway Avenue Costa Mesa, CA 92626 | NM | | AT-902-AF MI-592127 VC 10-124 | AT-902-AR NC 10-54 VF 10-179 | 35-5011() NC 10-124 CSM 10-308-() |
| TSO-C37b | Dayton-Granger, Inc. West Coast Division 3000 Airway Avenue Costa Mesa, CA 92636 | NM | | 35-5002 35-5011-() MI592128 VC10-126() VF10-108() VF10-223 | 35-5003 35-5039() NC10-04 VF10-10() VF10-185 VF10-347() | 35-5006() AT-907A NC10-98-() VF10-60 VF10-222 VFS10-90() |
| TSO-C37b | Delta Electronics Mfrg. Co. Suite 605 11311 Harry Hines Blvd. Dallas, TX 75229 | SW | | DE149 | | |
| TSO-C37b *F | Walter Dittel GmbH Erpftingen Strasse 36 Postfach 260 Landsberg 1 Lech 1 Germany | EU | | Dittel FSG 50 Dittel FSG 60M | | |
| TSO-C37b | Dorne and Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM C25-1 DM C25-11 DM C60-1 | DM C25-2 DM C33-2 DM C70-1 | DM C25-3 DM C50-() DM C50-17 |
| TSO-C37b *F | Electronique Aerospatiale P. O. Box 4 93350 Le Bourget Aeroport Paris, France | EU | | TTR-730 | ERO-671 | ER 1-671 |
| TSO-C37b *F | Elliott Brothers (London) Ltd. Christopher Martin Rd. Basildon, Essex England | EU | | AD.160 | AD.170A | |
| TSO-C37b | Gables Engineering, Inc. P.O. Box 340880 Coral Gables, FL 33134 | CE-A | | G-6233 | G-6317 | |
| TSO-C37b | Global-Wulfsberg Systems Div. of Sundstrand Data Control, Inc. 6400 Wilkinson Drive Prescott, AZ 86301 | CE-W | | WT-200 RT-118():400-0119-000/001 | WT-200B | WT-2000 |
| TSO-C37b | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 No. 19th Ave. Phoenix, AZ 85027 | NM | | 6097936-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|-----------|---|--|---|
| TSO-C37b | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KX175 KTR-9100() KCU-591() KX175B KTR908 KTR903 KTR905() KX 155 NAV-COM:069-1024-30 thru 069-1024-49 | KY195() KTR905 KY92() KN74 KX155()/KX165() KTR9100() KFS578() | KTR-900A KFS590B KY196() K1206 |
| TSO-C37b | NARCO Avionics Div. NARCO Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | Mark 24 COM 111B COM 200 | NAV/COM-100 COM 120 COM 810 | COM/NAV-110 COM 120/20 COM 811 |
| TSO-C37b | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVC-110 | AVC-110A | AVC-111 |
| TSO-C37b | Rockwell International Avionics Group 400 Collins Road NE Cedar Rapids, IA 52498 | CE | | 618M-2B:522-4088-001, -003, -004, -006, -007, -009, -010, -201, -203, -204, -206, -207, -209 618M-3A:-003, -010, -011 618M-3A:622-1396-101, -102, -103, 110, -111, -203, -205, -206, -208, -209, -210 | | |
| TSO-C37b | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM | | S65-DC-9 S65-1016 S65-8262-() S65-8262-2A S65-8262-3 S65-8262-(300) S65-8262-DC10A S65-8280-() S65-8280-(3) | S65-111 S65-880 S65-8262-1 S65-8262-301 S65-8262-3A S8264-() S65-8280-(305) S65-8282-() | S65-111-() S65-8262-2 S65-8262-30 S65-8262-30 |
| TSO-C37b | Sigma Tek, Inc. 17621 N. Black Canyon Hwy Phoenix, AZ 85023 | NM | | A15A A-29A 3281 485A | A-25A A-29B 385A 428B | A-25D A-29C 428A 1038A |
| TSO-C37b | Terra Corporation 3520 Pan American Freeway, NE Albuquerque, NM 87107 | SW | | RADA1R 10B | | |
| TSO-C37b | Trivec-Avant Corp. 17851 Jamestown Lane Huntington Beach, CA 92647 | NM | | 10-40-() 14-50-() 18-40-() 14-50-01 17-50-01 10-60-01 17-40-11 | 10-50-() 16-50-() 17-40-() 12-50-01 16-50-01 17-40-01 17-50-11 | 12-50-() 17-50-() 18-50-() 10-40-01 18-40-01 18-50-01 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|--|--|
| TSO-C37c *F | Becker Flugfunkwerk Niederwaldstr. 20 D-7550 Rastatt Germany | EU | VHF RADIO COMMUNICATIONS TRANSMITTING EQUIPMENT OPERATING WITHIN THE RADIO FREQUENCY RANGE OF 118-136 MEGACYCLES | AR3201-() AR3202-() |
| TSO-C37c | Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | VC8-40A |
| TSO-C37c | Collins Avionics Group Rockwell International 400 Collins Road, NE. Cedar Rapids, IA 53498 | CE-W | | VFP-712:622-6831-() |
| TSO-C37c | Collins General Avn. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | 622-6520-() VHF-21B:622-6390-() VHF-22B:622-6153-() VHF-422A:622-7292-() VHF-422B:622-7293-() VHF-22:622-8737-() VHF-21A:622-6389-() VHF-22A:622-6152-() CTL-22A:622-8737-() CAD-31:622-8332-001 RTU-870:622-7356-001 |
| TSO-C37c | Collins General Avn. Div. Avionics Group Rockwell International Corp. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | | VHF-422(A):622-7292-(), 001, 002, 101, 102 VHF-422(B):622-7293-(), 001, 002, 101, 102 RTU-870A:622-9346-001, -002, -003, -011, -012, -013 CAD-870G:622-7695():001, -002 |
| TSO-C37c | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | CI-291 CI-292-1() CI-292-2() CI-290-3() CI-292-4() |
| TSO-C37c | Dayton-Granger, Inc. Western Division 3000 Airway Avenue Costa Mesa, CA 92626 | NM | | VF10-210 |
| TSO-C37c | Dayton-Granger Inc. P.O. Box 350550 Fort Lauderdale, FL 33335 | SO | | VF10-210 |
| TSO-C37c *F | Electronique Aerospatiale EAS B.P. 51 93350 Le Bourget Principal, France | EU | | BCC 2125:8992125()()() |
| TSO-C37c | Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43225 | CE-C | | CD-850:80500710-XX |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|--|
| TSO-C37c | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G-6074:-04 G6200():04, 05 G6164() G6223():03, 04 G6723() G6165() G6950() G7001():KTR-908 G4422() G6860() G6868 G6692() G6984() G7000() G7002() 7008() G7015():WT200B G7023():-01, -02, -03, -04, -05, -06, -07, -13, -14, -15, -16, -17, -18, -19, -20, -21, -22, -23, -24, -25, -29, -30, -31, -32, -34, -35, -36, -37 G7032() G7044() G7055() |
| TSO-C37c | Global-Wulfsberg Systems Div. of Sundstrand Data Control, Inc. 6400 Wilkinson Drive Prescott, AZ 86301 | NM | | GNS-1000:42000-02-02 AFIS() 400-045500-0001/-0002 42000-01-01/-02 43000-01-01-X |
| TSO-C37c | Gull Airborne Inst., Inc. 395 Oser Avenue P.O. Box 9400 Smithtown, NY 11787 | NE | | RCC-202 COMM/COMM:901-206-0011, 0012, 0013, 0014 RCN-202 COMM/NAV:901-207-0011, 0012, 0013, 0014 RCT 202 COM/TPDR:901-203-0011, 0012, 0013, 0014 RCX-202 COMM-A/B:901-204-0011, 0012, 0013, 0014 RNC-202 NAV/COMM:901-208-0011, 0012, 0013, 0014 |
| TSO-C37c | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 West Bend Road Glendale, AZ 85308 | NM | | SRZ-850 RCZ-850:7510700-901 RM-850:7012100-943, -944, -953, -954 |
| TSO-C37c | King Radio Corporation 400 North Rogers Road Olathe, KS 66061 | CE-W | | KFS-598A:071-1282-() KFS-598A:071-1282-46 thru -56 VCS-40A KY-97A:064-1051-10/-11/-30/-31/-50/ -60/-61 KY-96A:064-1052-10/-11/-30/-31/-50/ -51/-60/-61 KY-196A KY-197A |
| TSO-C37c *F | Marconi Italiana S.P.A. Via A. Negrone IA 16153 Genova Cornigliano, Italy | EU | | ART 151:145-0183/01 145-0183/02 |
| TSO-C37c | Narco Avionics Commerce Drive Fort Washington, PA 19034 | NE | | MK-12D |
| TSO-C37c | Trivec-Avant Corporation 17831 Jamestown Lane Huntington Beach, CA 92647 | NM | | AV201 AV 418 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--|--|---|--|
| TSO-C37c | Val Avionics Ltd. P.O. Box 13025 3280 25th St. S.E. Salem, OR 97309-1025 | NM-S | | COM 760 VHF Transceivers Model 801000-() | | |
| TSO-C37c *F | W. Dittel GmbH Luftfahrtgeratebau 8910 Landsberg/Lech 1 Germany | EU | | FSG-70 | | |
| TSO-C38 | Bendix Radio Division Baltimore, MD 21233 | NE | VHF RADIO COMMUNICATIONS RECEIVING EQUIP. OPERATING WITHIN THE RADIO FREQ. RANGE OF 118-136 MEGACYCLES | ACA-20 | EA-22C NVA-22() | |
| TSO-C38 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 37R Ser. 51R-4A 51X-2 313N-() 313N-4B 390R-11A 614U-3 614U-7 618F-1A 618-1D 618M-1A 618M-1D 618M-2D | 137X Ser. 51R-7A 51X-2B 313N-2/3 313N-4C 390U-4() 614U-4 614U-8 618-1B 618M-() 618M-1B 618M-2A | 51R-4 51R-8A 51X-2C 313N-2D/3D 313N-6C 427D-1 614U-6 618F-1 618-1C 618M-1 618M-1C 618M-2B |
| TSO-C38 | Dorne and Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | C33-2 DM C50-3 | DM C25-7 DM C50-11 | DM C50-2 DM C50-11A |
| TSO-C38 | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KA39 | KTR-900 | KTR-9000 |
| TSO-C38 | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 2304 | 5609B | 5609-1 |
| TSO-C38 | NARCO Avionics Div. NARCO Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | VSC-1 COM-III | VSC-2 | VSRP-1 |
| TSO-C38 | Rockwell International Avionics Group 400 Collins Road NE Cedar Rapids, Iowa 52498 | CE-W | | 137X-1:CPN 522-1136-011 | | |
| TSO-C38 | Turner Aircraft Radio, Inc. Indianapolis, IN 46206 | CE-C | | 230C-1 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--|---|--|--|
| TSO-C38a | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | VHF RADIO COMMUNICATIONS RECEIVING EQUIP. OPERATING WITHIN THE RADIO FREQ. RANGE OF 118-136 MEGACYCLES | ANA-20() PSA-21() TA-21() | ANA-22() RA-18C RA-22() | MTA-21() RA-21() |
| TSO-C38a | Bendix Radio Division Baltimore, MD 21233 | NE | | ANA-20 PSA-21() RA-22() | ANA-22() RA-18C | MTA-21() RA-21 |
| TSO-C38a | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | 313N-2:522-2447-005/015/045 | | |
| TSO-C38a | PTC Aerospace Bantom, CT | CE-C | | 910()-2()A | | |
| TSO-C38a | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE | | 313N-2:522-2447-574 | | |
| TSO-C38b | Aire-Sciences, Inc. 216 Passaic Avenue Fairfield, NJ 07006 | NE | VHF RADIO COMMUNICATIONS RECEIVING EQUIP. OPERATING WITHIN THE RADIO FREQ. RANGE OF 118-136 MEGACYCLES | RT-661A | PS-661 | |
| TSO-C38b | Allied/Signal, Inc. Bendix/King Air Transport Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, Fl 33309 | CE-A | | RTA-44A:2041237-4417 | | |
| TSO-C38b | Avtech Corporation 3400 Wallingford N. Seattle, WA 98103 | NM | | 6123-1 | | |
| TSO-C38b *F | Becker Flugfunkwerk GmbH Baden-Baden-Oos Germany | EU | | COMM 2000 | | |
| TSO-C38b | Bendix Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | RT-221() MSA-42A RTA-43 CN-2011 | MSA-41() RTA-42A() MTA-43A NP-2041A | RTA-41() RT-241A & B PS-243A RTA-44A |
| TSO-C38b *F | Chelton (Electrostatics) Ltd Marlow Buckingham, United Kingdom | EU | | 12-6() | | |
| TSO-C38b | Collins Avionics Division Rockwell International 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | CNC-23 618M-3 | VHF-20A/20B | 618M-2B |
| TSO-C38b | Collins Avionics Division Rockwell International | CE-W | | CTL-20()/21() CCD-806 | VFP-702 | CMS-80() VHF-700() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|---|
| | 400 Collins Road, NE Cedar Rapids, IA 52406 | | | 313N-5:622-2599-502 |
| TSO-C38b | Collins General Avn. Div. Rockwell International Costa Mesa Operations 3000 Airway Avenue Costa Mesa, CA 92626 | NM | | VF10-10()* VFS10-90() VC10-126() VF10-108() VF10-347 35-5002 35-5006()* 35-5039()* VF10-60 35-5003 AT-907A MI-592128 35-5011-() NC10-98-() *Authorization is extended to include series approval for these part numbers. |
| TSO-C38b | Collins General Avn. Div. Rockwell International Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | VHF-251 VHF-251S VHF-251E VHF-250 VHF-250E VHF-250S VHF-253 VHF-253S NCS-31A 339R-7 339R-11 462-A-1 639U-1 889P-1 |
| TSO-C38b | Collins Radio Co. 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | 390R-11() 390Y-7 618M-2C 618M-3 618M-3A VHF-20() VHF-20A VHF-20B 913Y-2 339R-2 339R-3 339R-5 339R-6 339R-7 339R-9 339R-11 339R-14 NCS-31 899P-1 913Y-1 462A-1() 462B-1() 639U-1 |
| TSO-C38b | Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | CTL-20() CTL-21() CTL-30() CTL-31() CTL-40() CTL-41() CTL-60() CTL-61() CTL-90() CTL-91() NCS-31R RPU-31W |
| TSO-C38b | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | CI 121 CI 126 CI-175 CI 178 CI 109 CI 119() CI 127RA() CI 138() CI 139() CI 108() CI 211() CI 122() CI 144() CI 145() CI 196() CI 177 CI 223 CI 238 |
| TSO-C38b | Communications Components 3000 Airway Avenue Costa Mesa, CA 92626 | NM | | AT-902AF AT-902AR 35-5011() NC 10-54 NC 10-124 VF 10-179 MI-59217 CSM 10-308-() |
| TSO-C38b | Dayton-Granger, Inc. West Coast Division 3000 Airway Avenue Costa Mesa, CA 92636 | NM | | 35-5003 35-5006() 35-5011-() 35-5022 35-5039() AT-907A MI592128 NC10-04 NC10-98-() VC10-126() VF10-10() VF10-60 VF10-108() VF10-185 VF10-222 VF10-223 VF10-347() VFS10-90() |
| TSO-C38b | Delta Electronic Mfrg. Co. Suite 605 11311 Harry Hines Blvd. Dallas, TX 75229 | SW | | DE187 |
| TSO-C38b *F | Walter Dittel GmbH Erpftingen Strasse 36 Posxxach 260 Landsberg/Lech 1 Germany | EU | | Dittel FSG 50 Dittel FSG 60M |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|---|--|--|
| TSO-C38b | Dorne and Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM C25-1 DM C25-11 DM C58-1 DM C63-1/A | DM C25-2 DM C33-2 DM C60-1 DM C70-1 | DM C-25-3 DM C50() DM C63-1 DM C50-17 |
| TSO-C38b *F | Electronique Aerospatiale P. O. Box 4 93350 Le Bourget Aeroport Paris, France | EU | | TTR-730() ER4-671B | ERO-671 | ER1-671 |
| TSO-C38b *F | Elliott Brothers (London) Ltd. Christopher Martin Rd. Basildon, Essex England | EU | | AD.160 | AD.170A | |
| TSO-C38b | Gables Engineering, Inc. P.O. Box 340880 Coral Gables, FL 33134 | CE-A | | G-6233 | G-6317 | |
| TSO-C38b | Global-Wulfsberg Systems Div. of Sundstrand Data Control, Inc. 6400 Wilkinson Drive Prescott, AZ 86301 | NM | | WT-200 RT-118():400-0119-000/001 WT-200:400-0044-000 WT-2000:400-0050-000 WT-200B:400-0107-000,-001 RT-118:400-0119-000,-001 | WT-200B | WT-2000 |
| TSO-C38b | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 5353 W. Bell Road Glendale, AZ 85038 | NM | | A15 A-29A 328T 428A | A-25A A-29C 385A 485A | A-25D A-29B 1038A 485B |
| TSO-C38b | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KX 175 NAV/COM KFS590B KTR905 KX175B KY196() KX155()/KX165() KFS598 KX 155 NAV-COM:069-1024-30 thru 069-1024-49 | KCU591() KTR-9100() KN74 KTR908 KTR9100A | KY195 KTR-900A KY 92() K1206 KTR 905() |
| TSO-C38b | NARCO Avionics Div. NARCO Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | Mark 24 NAV/COM-100 COM 120 COM 811 | VOA-8 COM/NAV-110 COM 120/20 | VOA-9 COM 111B COM 810 |
| TSO-C38b | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVC-110 AVC-111A | AVC-110A | AVC-111 |
| TSO-C38b | Rockwell International Avionics Group 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | 618M-2B:522-4088-001, -003, -004, -006, -007, -009, -010, -201, -203, -204, -206, -207, -209 618M-3A:-003, -010, -011 618M-3A:622-1396-101, -102, -103, 110, -111, -203, -205, -206, -208, -209, -210 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|---|---|---|
| TSO-C38b | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM | | S65-DC-9 S65-1016 S65-8262-() S65-8262-2A S65-8262-30 S65-8262-(300) S8264-() S65-8280-(3) S65-8282-() | S65-111-() S65-8262-1 S65-8262-3 S65-8262-301 S65-8262-DC10A S-65-8280-() S-65-8280-(305) | S65-880 S65-8262-2 S65-8262-3A |
| TSO-C38b | Terra Corporation 3520 Pan American Freeway, NE Albuquerque, NM 87107 | SW | | RADAIR 10B | | |
| TSO-C38b | Trivec-Avant Corporation 17851 Jamestown Lane Huntington Beach, CA 92647 | NM | | 10-40-() 14-50-() 18-40-() 10-40-01 14-50-01 17-40-11 18-40-01 | 10-50-() 16-50-() 17-40-() 10-50-01 16-50-01 17-50-01 | 12-50-() 17-50-() 18-50-() 12-50-01 17-40-01 17-50-11 |
| TSO-C38c *F | Becker Flugfunkwerk GmbH Niederwaldstr. 20 D-7550 Rastatt Germany | EU | VHF RADIO COMMUNICATIONS RECEIVING EQUIPMENT OPERATING WITHIN THE RADIO FREQUENCY RANGE OF 118-136 MEGACYCLES | AR3202-() | AR3201-() | |
| TSO-C38c | Collins General Avn. Div Melbourne Operations P.O. Box 1060 Melbourne, FL 32902-1060 | CE-A | | 622-6520-() VHF-21B:622-6390-() VHF-22B:622-6153-() VHF-422A:622-7292-() VHF-22:622-8737-1() VHF-21A:622-6389-() VHF-22A:622-6152-() VHF-422B:622-7293-() RTU-870:622-7356-() CTL-22A:622-8737-() CAD-31:622-8332-001 RTU-870:622-7356-001 | | |
| TSO-C38c | Collins Avionics Group Rockwell International 400 Collins Road, NE. Cedar Rapids, IA 53498 | CE-W | | VFP-712:622-6831-() | | |
| TSO-C38c | Collins General Avn. Div. Avionics Group Rockwell International Corp. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | | VHF-422(A):622-7292-(), 001, 002, 101, 102 VHF-422(B):622-7293-(), 001, 002, 101, 102 RTU-870A:622-9346-001, -002, -003, -011, -012, -013 CAD-870G:622-7695():001, 002 | | |
| TSO-C38c | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | CI-291 CI-292-3() | CI-292-1() CI-292-4() | CI-292-2() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|---|
| TSO-C38c | Dayton-Granger Western Division 3000 Airway Avenue Costa Mesa, CA 92626 | NM | | VF10-210 |
| TSO-C38c | Dayton-Granger Inc. P.O. Box 350550 Fort Lauderdale, FL 33335 | CE-A | | VF10-210 |
| TSO-C38c *F | W. Dittel GmbH Luftfahrtgeratebau 8910 Landsberg/Lech 1 | EU | | FSG-70 |
| TSO-C38c *f | Electronique Aerospatiale (EAS) B.P. 51 93350 LeBourget Principal France | EU | | BCC2125:8992125()()() |
| TSO-C38c | Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43225 | CE-C | | CD850 P/N 805D0710-XX |
| TSO-C38c | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G4422() G-6074:-04 G6164() G6223():03, 04 G6723() G6165() G7001():KTR-908 G6950() G6860() G6868 G6692-() G6984() G7000() G7002() 7008() G7015():WT200B G7023():-01, -02, -03, -04, -05, -06, -07 -13, -14, -15, -16, -17, -18, -19, -20, -21, -22, -23, -24, -25, -29, -30, -31, -32, -34, -35, -36, -37 G7032() G7044() G7055() G6200():04, 05 |
| TSO-C38c | Global-Wulfsberg Systems 6400 Wilkinson Drive Prescott, AZ 86301 | NM-L | | AFIS() GNS-1000:42000-02-02 MCX-1000 |
| TSO-C38c | Gull Airborne Inst., Inc. 395 Oser Avenue P.O. Box 9400 Smithtown, NY 11787 | NE | | RCC-202 COMM/COMM:901-206-0011, 0012, 0013, 0014 RCN-202 COMM/NAV:901-207-0011, 0012, 0013, 0014 RNC-202 NAV/COMM:901-208-0011, 0013, 0014 RCX-202 COMM-A/B:901-204-0011, 0012, 0013, 0014 RCT-202 COM/TPDR:901-203-0011, 0012, 0013, 0014 |
| TSO-C38c | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 West Bend Road Glendale, AZ 85308 | NM | | SRZ-850 RCZ-850:7510700-901 RM-850:7012100-943, -944, -953, -954 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|------------------------------|--|--|--|
| TSO-C38c | King Radio Corporation 400 North Rogers Road Olathe, KS 66061 | CE-W | | KFS-598A:071-1282-() KY 96A KY 97A KY 197A:084-1053-10,-11/-12/-30/ -31/-32 KY 196A:064-1054-10/-11/-12/-30/ -31/-32/-40/-41/-42 KFS 598A:071-1282-45 KFS 598A:071-1282-24 thru -27, -29 thru -32,-34 thru -44 | | |
| TSO-C38c *F | Marconi Italiana S.P.A. Via A. Negrone 1A 16153 Genova, Italy | EU | | ART151:145-0183/01 ART151:145-0183/02 | | |
| TSO-C38c | Marco Avfonics Commerce Drive Fort Washington, PA 19034 | NE | | MK-12D | | |
| TSO-C38c | Trivec-Avant Corporation 17851 Jamestown Lane Huntington Beach, CA 92647 | NH | | AV201 AV403 | AV205 AV 418 | AV223 |
| TSO-C39 | Aerosmith Products Corp. P. O. Box 542 Miami, FL 33144 | CE-A | AIRCRAFT SEATS AND BERTHS | B226 C117 C129 H22 H43 H313 J126 L-4003 N21EAL N32EAL N215 N215AJ N215G N227-4 N314A N327-4 SX-107C SX1009 W214B W314 WN314 X109A X2009 | C15C C118-1 C139 H32 H213 HD12-1 L4001 L-4007 N22EAL M117 N215A N215B N215J N2350-() N314B N333-() SX-107C-1 W214 W214C WN214 WN333-() X1009 D-4001 | C116 C120 H12 H42 H213A J11 L-4002 N2EAL N31EAL N117-1 N215AF N215F N227-3 N314 N327-3 N333C-() SX-107C-2 W214A W214D WN233-() X109 X1109 |
| TSO-C39 | Aerostar Aircraft Corp. P. O. Box 72 Kerrville, TX 78028 | SW | | 1001 1007 | 1002 1034 | 1004 |
| TSO-C39 | Aero Tech United P.O. Box 1220 Springdale, AK 72765-1220 | SW | | 2303-() Type 1 Divan Assembly (frame only) | | |
| TSO-C39 | AirCapital Design Develop. 7300 S. East Blvd. Derby, KS 67037 | CE-W | | 64-129-300 | 64-129-400 | 64-129-500 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|-----------------------------|----|-----------|------------------------|----------------------------|--------------|
| TSO-C39 | Aircraft Furnishing Limited | EU | | 301 | 302 | 307 |
| *F | Hersham Station Works | | | 310 | 311G | 313 |
| | Walton-on-Thames | | | 322 | 323 | 326 |
| | Surrey, England | | | 352 | 362 | 402 |
| | | | | 503 | 507 | 508 |
| | | | | 510 | 512 | 513 |
| | | | | 515 | 518 | 520 |
| | | | | 521 | 701 | 702 |
| | | | | 703 | 704 | 705 |
| | | | | 706 | 708 | 712 |
| | | | | 713 | 716 | 717 |
| | | | | 724 | 801 | 803 |
| | | | | 804 | 1002 | 1003 |
| | | | | 1005 | | |
| TSO-C39 | Aircraft Mechanics, Inc. | NM | | 540-1 | 540-2 | 540-3L-1 |
| | Mechanical Division | | | 540-3R-1 | 540-5L-1 | 540-5R-1 |
| | P. O. Box 370 | | | 540-7L-1 | 540-7R-1 | 597-1-1 |
| | Colorado Springs, CO 80901 | | | 597-2-1 | 597-3-1 | 597-4-1 |
| | | | | 630-1L | 630-2R | 630-11L |
| | | | | 630-12R | 630-13 | 630-14 |
| | | | | 665-3A | 677 | 677-21 |
| | | | | 677-201 | 686-5A | 687-7A |
| | | | | 706 | 707 | 716 |
| | | | | 716-1 | 716-2 | 716-11 |
| | | | | 716-12 | 716-21 | 716-22 |
| | | | | 732 | 732-1 | 732-2 |
| | | | | 745 | 745-5 | 745-6 |
| | | | | 757-1 | 760-201 | 760-301 |
| | | | | 762-201 | 762-301 | 768 |
| | | | | 768-1 | 807 | 820 |
| | | | | 821 | 830-1 | 830-2 |
| | | | | 835-101 | 840-1 | 840-2 |
| | | | | 842 | 851 | 851-100 |
| | | | | 851-200 | 865 | 874 |
| | | | | 919 | 932 | 933-1 |
| | | | | 943-1 | 965-1 | 965-3 |
| | | | | 965-5 | 865-7 | 971() |
| | | | | 972() | 973() | 1052-1 |
| | | | | 1052-()Ser. | 1056-1() | 1056-() |
| | | | | 1056-2() | 1057-() | 1057-1() |
| | | | | 1058-() | 1058-1() | 5641031-501 |
| | | | | 5641031-503 | 5641031-505 | 5641031-507 |
| | | | | 5641031-509 | 5641031-511 | 5641031-513 |
| | | | | 5641031-515 | 5641031-517 | 5641031-519 |
| | | | | 5641031-521 | 5641031-523 | 5641031-525 |
| | | | | 5641031-527 | 5641031-529 | 5641031-531 |
| | | | | 5641031-533 | 5641031-535 | 5641031-537 |
| | | | | 5641031-539 | 5641031-541 | 5641031-543 |
| | | | | 5641031-545 | 5641032-1 | 5641032-501 |
| | | | | 5641032-503 | 5641032-505 | 5641032-507 |
| | | | | 5641032-509 | 5641033-1 | 5641033-501 |
| | | | | 5641033-503 | 5641033-505 | 5641033-507 |
| | | | | 5641033-509 | 5641034-501 | 5641034-511 |
| | | | | 917J10000-1 | 917J10000-2 | 918J10000-1 |
| TSO-C39 | AiResearch Aviation Co. | NM | | 109-159-018 | 109-DC6-0048109-JS-020-3 | |
| | Div. Garrett Corp. | | | 109-STD-018 | 121-VC8-010 | 121-VC8-047 |
| | Airline Products Facility | | | 124-707-062A | 124-JS-060-1124-JS-060-501 | |
| | 19201 Susana Rd. | | | 124-JS-060-503 | 124-JS-060-505 | |
| | Compton, CA 90221 | | | 125-125-059() | | 125-707 Ser. |
| | | | | 125-JS-007 | 1678-125-3 | S-100-80 |
| | | | | S-100-81 | S-100-82 | S-100-83 |
| | | | | S-100-84 | S-100-85 | S-100-86 |
| | | | | S-100-87 | S-100-88 | S-100-89 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-----------|---|---|---|
| | | | | S-100-90 | G110-() | G110B-() |
| | | | | BH-111() | F111-() | G111-() |
| | | | | G11B-() | F111K-() | J111() |
| | | | | BH112() | F112-() | 112-() |
| | | | | G112L-() | G112BL-() | G113L-() |
| | | | | G113BL-() | BH114() | 114-() |
| | | | | 115() | 170() | 180() |
| | | | | 210() | G211-() | 212() |
| | | | | 213() | 215() | 218() |
| | | | | 219() | G404-() | F405-() |
| | | | | G405() | G406() | 408() |
| | | | | 409() | 29411001-401 | |
| | | | | 29411001-406 | | |
| TSO-C39 *F | Air France 115, Ave. Docteur Marie-Orly 94396 Orly Aerogare Paris, France | EU | | 13972.21 | 14374.21 | |
| TSO-C39 | Airline Products Co. No. Hollywood, CA 91603 | NM | | 918F 1012-R | 918FR | 1012-F |
| TSO-C39 | Air-Mod Engineering Co. Will Rogers World Airport Oklahoma City, OK 73125 | SW | | 50032 | | |
| TSO-C39 | ALSCO, Inc. Fort Worth, TX 76101 | SW | | AL-1021-1 Type III AL-1027-3 Type IV | | SM 1100 Type I |
| TSO-C39 | American Airmotive Corp. Miami Inter'l Airport P. O. Box 187 Miami, FL 33148 | CE-A | | 60-075 25-58-002 62-028-100 | 60-230 92-59-004 62-028-200 | 61-051 92-59-012 |
| TSO-C39 | AMI Industries, Inc. P.O. Box 370 Colorado Springs, CO 80901 | NM | | 716(-) | 865(-) | |
| TSO-C39 | Associated Aircraft Equipment, Inc. P. O. Box 542 Miami, FL 33148 | CE-A | | BA4L() DDF() D2L DD300A DF13366-D() DH-400 D4D OTO-5 DTF() FA2-1() F100-3A() F100SA F100SFT-7 F100SFTA-2() F200D HB100-2() HB100-FA() HB200 LJ8() WA2-2 WA3-1 WA3-() LJ8A() | BA4R() D2 D2L-1 D3D DH-200() DT-300 DS631-1() DTO-6 DTFA() FA3 F100-4() F100SFT() F100SFT-2 F100SFTA-8 H300 HB100-2A() HB100-G HB300() WA2 WA2-2A WA3-2 WA3-4() | BA-5() D2818 DD200 DF13366() DH-300 D4899 DS631-1A() DTO-7() FA2 F100-3() F100S F100SFT-3() F100SFTA() HB100-1-C() HB100-F HB100() JS100() WA2-1 WA2-3 WA3-3 L188-1 |
| TSO-C39 | Brice Manufacturing Co. 11395 Bradley Avenue Pacoima, CA 91331 | NM-W | | RA110 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|----|-----------|--|--|---|
| TSO-C39 | Broadie's Aircraft & - WITHDRAWN 10/15/86 Engine Service | | | | | |
| TSO-C39 *F | Canadian Aircraft Products 261 Viscount Way Richmond, British Columbia Canada | NE | | 12 | | |
| TSO-C39 | Castle Industries Inc., of CA. 601 S. Dupont Avenue Ontario, CA 91761-1502 | NM | | 50103 | 50104 | |
| TSO-C39 *F | Contour Seats Limited Farnborough, Hants England | EU | | 900 Series | | |
| TSO-C39 | Douglas Aircraft Company McDonnell Douglas Corp. 3855 Lakewood Blvd. Long Beach, CA 90801 | NM | | 5656171 5711902-1 5713110 5714739 5760325 | 5656172 5711902-503 5713943 5716862 5760327 | 5706684 5713106 5714500 5719211 5761052 |
| TSO-C39 | 4/Flight Industries 24955 Avenue Kearny Valencia, CA 91335 | NM | | 100() 110 130 205() 265() 295 310()() 360() 400() 505()() 530-2 540 565()() 648() A670() 680()() 710()() 750 705 820() 870-2 900-1 920 940 975() 990 1035-2 1038-1 1040-2 1050 1080 1130()() 1165()() 1205()() 1230 1260 1320 1345 1385 1415()() 1520()() | 105 120 165 240() 275 295-1 341 370() 435() 525() 530-3 545 580() 655()() A675()() 690()() 720()() 755 800-1 850() 870-3 900-2 930 950()() 980 1000() 1035-3 1038-2 1045-1 1055()() 1100() 1145 1185 1210 1240 1270 1325 1355 1395()() 1420()() 1525()() | 105()() 125()() 250() 280() 310 340()() 390() 505() 530-1 530-4 555()() 585() 660() 673() 700 Ser. 730()() 790()() 810() 870-1 870-4 910() 935 955()() 985 1035-1 1035-4 1040-1 1045-2 1075 1110() 1160()() 1200()() 1220 1250 1280 1330()() 1370()() 1410()() 1430()() 1540()() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|------------------------|
| | | | | 1560()() |
| | | | | 1580()() |
| | | | | 1620()() |
| | | | | 1660()() |
| | | | | 1690()() |
| | | | | 1795 |
| | | | | 1800()() |
| | | | | 1835()() |
| | | | | 1860()() |
| | | | | 1880()() |
| | | | | 1945()() |
| | | | | 1975()() |
| | | | | 2020-2 |
| | | | | 2030-3 |
| | | | | 2105()() |
| | | | | 2120()() |
| | | | | 2150()() |
| | | | | 2170()() |
| | | | | 2185()() |
| | | | | 2310()() |
| | | | | 2330()() |
| | | | | 2350()() |
| | | | | 2375()() |
| | | | | 2445()() |
| | | | | 2515()() |
| | | | | 2535()() |
| | | | | 2560()() |
| | | | | 2585()() |
| | | | | 2600()() |
| | | | | 2620()() |
| | | | | 2635()() |
| | | | | 2665()() |
| | | | | 2700()() |
| | | | | 2790()() |
| | | | | 2815()() |
| | | | | 2870()() |
| | | | | 2970()() |
| | | | | 3080()() |
| | | | | 3140()() |
| | | | | 3225 |
| | | | | 3290()() |
| | | | | 3450()() |
| | | | | 3580()() |
| | | | | 3610()() |
| | | | | 3680()() |
| | | | | 3740()() |
| | | | | 3960()() |
| | | | | 4125()() |
| | | | | 4145()() |
| | | | | 4400()() |
| | | | | 4425()() |
| | | | | 4540()() |
| | | | | 4795()() |
| | | | | 1565()() |
| | | | | 1590()() |
| | | | | 1630()() |
| | | | | 1670()() |
| | | | | 1780()() |
| | | | | 1796 |
| | | | | 1810()() |
| | | | | 1840()() |
| | | | | 1865 |
| | | | | 1910()() |
| | | | | 1950()() |
| | | | | 1985()() |
| | | | | 2020-4 |
| | | | | 2090()() |
| | | | | 2109()() |
| | | | | 2135()() |
| | | | | 2155()() |
| | | | | 2175()() |
| | | | | 2195()() |
| | | | | 2320()() |
| | | | | 2340()() |
| | | | | 2355()() |
| | | | | 2390()() |
| | | | | 2470()() |
| | | | | 2525()() |
| | | | | 2545()() |
| | | | | 2565()() |
| | | | | 2590()() |
| | | | | 2610()() |
| | | | | 2625()() |
| | | | | 2640()() |
| | | | | 2680()() |
| | | | | 2780()() |
| | | | | 2800()() |
| | | | | 2830()() |
| | | | | 2875()() |
| | | | | 3000()() |
| | | | | 3100()() |
| | | | | 3175()() |
| | | | | 3240()() |
| | | | | 3295()() |
| | | | | 3530()() |
| | | | | 3600()() |
| | | | | 3640()() |
| | | | | 360-38 |
| | | | | 3760()() |
| | | | | 4040()() |
| | | | | 4135()() |
| | | | | 4180()() |
| | | | | 4405()() |
| | | | | 4500()() |
| | | | | 4770()() |
| | | | | 5300()() |
| | | | | 1575()() |
| | | | | 1615()() |
| | | | | 1655()() |
| | | | | 1675()() |
| | | | | 1785()() |
| | | | | 1797 |
| | | | | 1830()() |
| | | | | 1850()() |
| | | | | 1875()() |
| | | | | 1920()() |
| | | | | 1955()() |
| | | | | 2005 |
| | | | | 2030-1 |
| | | | | 2100()() |
| | | | | 2110()() |
| | | | | 2140()() |
| | | | | 2165()() |
| | | | | 2180()() |
| | | | | 2300()() |
| | | | | 2325()() |
| | | | | 2345 |
| | | | | 2360()() |
| | | | | 2395()() |
| | | | | 2490()() |
| | | | | 2530()() |
| | | | | 2555()() |
| | | | | 2580()() |
| | | | | 2595()() |
| | | | | 2615()() |
| | | | | 2630()() |
| | | | | 2650()() |
| | | | | 2685()() |
| | | | | 2785()() |
| | | | | 2805()() |
| | | | | 2850()() |
| | | | | 2880()() |
| | | | | 3070()() |
| | | | | 3110()() |
| | | | | 3205()() |
| | | | | 3250()() |
| | | | | 3410()() |
| | | | | 3535()() |
| | | | | 3605()() |
| | | | | 3655()() |
| | | | | 3730()() |
| | | | | 3770()() |
| | | | | 4115()() |
| | | | | 4140()() |
| | | | | 4345()() |
| | | | | 4415()() |
| | | | | 4505()() |
| | | | | 4790()() |
| | | | | 5305()() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|--|------|-----------|------------------------|-----------------|--------------|
| TSO-C39 | Fairchild Burns Co. Div. of Fairchild Ind.Inc. 1455 Fairchild Dr. Winston Salem, NC 27105 | CE-A | | 2J1() | 2J1-7() | 2JF-7() |
| | | | | 2J1-25 | 2J2() | 3DH2 |
| | | | | 4J1-() | 5J1 | 101H-() |
| | | | | 2D1-() | 2D2-() | 2DH-() |
| | | | | 2DH1-() | 2DH2-() | 7D1-() |
| | | | | 7DH1-() | 7DH1-3() | 8D1-() |
| | | | | 8DH1-() | 10G1-() | 10G2-() |
| | | | | 10GA1-() | 10GA2-() | 10GA1F() |
| | | | | 10GA2F() | 10GA2-16() | 10G2-16() |
| | | | | 11DH1-() | 13G1-() | 13G2-() |
| | | | | 13G2-16() | 650-1() | 13J1() |
| | | | | 212() | 403E() | 650-2() |
| | | | | 650C-1-21() | 650D-1-21() | 650E-1() |
| | | | | 650B-2-39() | 650D-2-39() | 650E-2-39() |
| | | | | 700A-2-59LH | 700D-2() | 700E-2() |
| | | | | 700F-2() | 700G-3-70() | 700G-2-48() |
| | | | | 700H-2/3() | 701D-2() | 701E-2() |
| | | | | 701D-3() | 701E-3() | 705D() |
| | | | | 713-2() | 714-2() | 714-3() |
| | | | | 716-1() | 716-2() | 725-2() |
| | | | | 727() | 730-3() | 733-2() |
| | | | | 733-2-40() | 735() | 738-2-44() |
| | | | | 739-2() | 741-2-40() | 742-2-48() |
| | | | | 743-2() | 743-3() | 745-2() |
| | | | | 745-3() | 746-2() | 752-3-59() |
| | | | | 753-2-59() | 754-2() | 756-2() |
| | | | | 756-3() | 761-2-56() | 763-2-56() |
| | | | | 764-2-56() | 765-2() | 765-3() |
| | | | | 770-2() | 770-3() | 776-2() |
| | | | | 778-2() | 779-2() | 779-3() |
| | | | | 781-2() | 781-3() | 782-2/3() |
| | | | | 783-2() | 783-3() | 785-2() |
| | | | | 786-1() | 793-1() | 793-2() |
| | | | | 793-3() | 794-2() | 799-2() |
| | | | | 799-3() | 800-2() | 803-2() |
| | | | | 808-2() | 811B-2() | 811B-3() |
| | | | | 811-2() | 811-3() | 815-3-60() |
| | | | | 815A-3-60() | 817() | 820() |
| | | | | 821() | 822-2() | 823-1() |
| | | | | 823-2() | 824-1() | 839-3() |
| | | | | 851-1() | 853-2() | 1733 |
| | | | | 2950-13() | 2950-1 thru -11 | |
| | | | | 853-3() | 2950-14() | 3340() |
| | | | | 3350() | 853-4() | 3410-() |
| | | | | 3510-() | 3580-() | 3585-() |
| | | | | 4005-() | 4005-11() | 4005-12() |
| | | | | 4110-1() | 4180 | 4190 |
| | | | | 4220() | 4280-() | 4320 |
| | | | | 4380() | 4400-() | 4410-() |
| | | | | 5180 | 5190 | 5401() |
| | | | | 5402-() | 5413() | 5437-() |
| | | | | 5440-() | 5505-() | 5506 |
| | | | | 5508 | 5513 | 5518 |
| | | | | 5519() | A650-2-39() | A650-1() |
| | | | | A716-1() | A716-2() | A730-3() |
| | | | | A739-2() | A742-2-48() | A743-2() |
| | | | | A763-2() | A786-1() | A817() |
| | | | | A743-3() | | |
| | | | | AH162-1-21() | AH1601() | B700-2() |
| | | | | B700A-2() | B700B-2() | B700E-2() |
| | | | | B700F-2() | B700G-2() | B700H-2() |
| | | | | B701-2() | B701-3() | B701-D-2() |
| | | | | B701-E-2() | B701-E-3() | A2150() |
| | | | | B705-3() | B705C-3() | B705D-3() |
| | | | | B725-2() | B730-3() | B733-2() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|------------------------|
| | | | | B735-3() |
| | | | | B742-2() |
| | | | | B742-2-48() |
| | | | | B746-2() |
| | | | | B754-2() |
| | | | | B765-2() |
| | | | | B770-2-() |
| | | | | B778-2-() |
| | | | | B781-2() |
| | | | | B783-3() |
| | | | | B811-3() |
| | | | | B815A-3() |
| | | | | B823-2() |
| | | | | B1599GC() |
| | | | | B1601A |
| | | | | B1601H |
| | | | | B1710-() |
| | | | | B1712-17 |
| | | | | B1714-() |
| | | | | B1727-() |
| | | | | B1817-() |
| | | | | B4380() |
| | | | | BC764-2() |
| | | | | BD714-3() |
| | | | | BD735-3() |
| | | | | BD770-2() |
| | | | | BF714-2() |
| | | | | BF765-3() |
| | | | | BF779-2() |
| | | | | BH1601() |
| | | | | BTE403D-2-47A |
| | | | | BTE475B-2() |
| | | | | BTE475E-2() |
| | | | | BTE545A() |
| | | | | BTE700-2-48 |
| | | | | BTE788 |
| | | | | BTE788-3() |
| | | | | BTE801-3() |
| | | | | BTE801C-2() |
| | | | | C551-2-48() |
| | | | | C793-1() |
| | | | | C794-2() |
| | | | | C853-4() |
| | | | | C4380() |
| | | | | D714-3() |
| | | | | D735-3() |
| | | | | D779-2() |
| | | | | D793-2-() |
| | | | | D794-2() |
| | | | | E733-3() |
| | | | | E793-1() |
| | | | | E793-4() |
| | | | | F714-3() |
| | | | | F765-3() |
| | | | | F779-2() |
| | | | | H1599() |
| | | | | L793-2() |
| | | | | P160() |
| | | | | TE545A |
| | | | | Z735-3() |
| | | | | ZBTE788-2() |
| | | | | ZBTE801-3() |
| | | | | ZBTE801C-2() |
| | | | | ZBD714-2() |
| | | | | ZD714-3() |
| | | | | B738-2() |
| | | | | B743-2() |
| | | | | B745-2() |
| | | | | B752-3() |
| | | | | B763-2() |
| | | | | B765-3() |
| | | | | B770-3-() |
| | | | | B779-2() |
| | | | | B781-3() |
| | | | | B786-1() |
| | | | | B811B-2() |
| | | | | B815B-3() |
| | | | | B1599() |
| | | | | B1600() |
| | | | | B1601E |
| | | | | B1707 |
| | | | | B1711-() |
| | | | | B1713-() |
| | | | | B1715-() |
| | | | | B1730-() |
| | | | | B1828-() |
| | | | | BA730-3() |
| | | | | BD713-2() |
| | | | | BD730-3() |
| | | | | BD779-2() |
| | | | | BD770-3() |
| | | | | BF714-3() |
| | | | | BF770-2() |
| | | | | BF779-3() |
| | | | | BTE403-51F-9() |
| | | | | BTE404C-2-47 |
| | | | | BTE475C-2() |
| | | | | BTE515() |
| | | | | BTE601-2() |
| | | | | BTE700-3-70 |
| | | | | BTE788-2() |
| | | | | BTE788-2-44() |
| | | | | BTE788S-3() |
| | | | | BTE801A-2() |
| | | | | BTE801C-3() |
| | | | | C735-3() |
| | | | | C793-2() |
| | | | | C853-2() |
| | | | | C1599() |
| | | | | D713-2() |
| | | | | D730-3() |
| | | | | D770-2() |
| | | | | D779-3() |
| | | | | D793-3() |
| | | | | D1600() |
| | | | | E733-2() |
| | | | | E773-2() |
| | | | | E793-2() |
| | | | | E794-2() |
| | | | | F765() |
| | | | | F770-2() |
| | | | | F779-3() |
| | | | | J1599() |
| | | | | L793-3() |
| | | | | T821() |
| | | | | Z725-2() |
| | | | | Z8725-2() |
| | | | | ZBTE788-3() |
| | | | | ZBTE801A-2() |
| | | | | ZBTE801C-3() |
| | | | | ZBD714-3() |
| | | | | Z735-2() |
| | | | | ZB742-2() |
| | | | | ZBTE801-2() |
| | | | | ZBTE801A-3() |
| | | | | ZBTE805E-2() |
| | | | | ZD714-2() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-----------|--|---|---|
| TSO-C39 | Fairchild Industries, Inc. Aircraft Service Station P. O. Box 40 St. Augustine, FL 32084 | CE-A | | 1000-1 | | |
| TSO-C39 *F | Field Aviation Co., Ltd. Calgary Inter'l Airport Calgary, Alberta Canada | NE | | 37093 38482-()-DT() C6FF-1700-2 C6FF-1700-5 C6FF-1701-2 C6FF-1701-5 C6FF-1702-2 C6FF-1702-5 C6FF-1900-2 C6FF-1900-5 C6FF-1901-2 C6FF-1901-5 C6FF-1903-2 C6FF-1903-5 C6FF2702-() C6FF2702-3 C6FF2702-8 C6FF2703-1 C6FF2703-4 C6FF2902 C6FF2902-2 C6FF2902-5 C6FF2902-8 C6FF2903-1 C6FF2903-4 C6FF2903-7 | 37481 C6FF-1700-3 C6FF-1700-6 C6FF-1701-3 C6FF-1701-6 C6FF-1702-3 C6FF-1702-6 C6FF-1900-3 C6FF-1900-6 C6FF-1901-3 C6FF-1901-6 C6FF-1903-3 C6FF-1903-6 C6FF2702-1 C6FF2702-4 C6FF2703 C6FF2703-2 C6FF2703-7 C6FF2902-() C6FF2902-3 C6FF2902-6 C6FF2903 C6FF2903-2 C6FF2903-5 C6FF2903-8 | 37460 C6FF-1700-1 C6FF-1700-4 C6FF-1701-1 C6FF-1701-4 C6FF-1702-1 C6FF-1702-4 C6FF-1900-1 C6FF-1900-4 C6FF-1901-1 C6FF-1901-4 C6FF-1903-1 C6FF-1903-4 C6FF2702 C6FF2702-2 C6FF2702-7 C6FF2703-() C6FF2703-3 C6FF2703-8 C6FF2902-1 C6FF2902-4 C6FF2902-7 C6FF2903-() C6FF2903-3 C6FF2903-6 |
| TSO-C39 *F | Flight Equipment & Eng. Ltd. Amsterdam, Holland Netherlands | EU | | 1 | | |
| TSO-C39 | Flight Equipment & Engineering Corporation P. O. Box 173 Miami, FL 33148 | CE-A | | A12-3H 201A 404() 405A 460() 462 600 602 603-3 604-3 617-3() 621-3 624-1 627-1 629-3 632-1 634-3 636-3 638-3 640-3 643-1() 647() 650() 652() 700() 901-3() 21015-2 | A22-H 403() 404-3() 406 460-3() 463-3 601 602-3 603A-3 604G 619() 621-5 625 628-1 630-1 633() 635 637() 639() 641-3 645-3() 648() 650-3() 643A-1() 701() 902-3 | 201 403-3() 405() 451() 461() 501B 601-3 603 604 617() 620 623 625-3 629 631-1 633-3() 635-3 638 639-3() 642-3() 646-4() 649() 651-3() 644-4() 901() 21015-1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|----|-----------|--|---|--|
| TSO-C39 *F | Flight Equipment & Engineering, Ltd. Asheridge Road Chesham, Bucks, England | EU | | 249() 272F() 372F() | 259() 372() | 272() 372A() |
| TSO-C39 | Flight Line Corp. 8330 San Fernando Rd. Sun Valley, CA 91352 | NM | | 1D 10FD 16S 27FD 28P-2 34P-2 120 222 275 275C 310A 350 370 390 486-20 486M 515 516-48 521-22A 540-3 560C 598 630 650 720-60 720C-4 720C-22 720C-42A 721-60 865 870C 880-2 880-7 910 920C 945 980 1040 1085 1091 1180 1416 1524-4 1534-2 1544-4 1544-8 1555-1 1600-2 1672 1710 1745 1825-1 1825-4 1825-7 1825-10 1920 2260-2 2260-4 2260-7 2260-10 | 1T 16D 16T 27FT 30D 39S 125 222-5 275A 275D 315 360 375 486 486-20-1 505-0 516 517 521-22M 540-4 586 600 635 665 720A Ser. 720C-7 720C-22A 721-40 721A-60 870 875 880-3 880-9 915 920C-1 955 980A 1070 1087 1092 1185 1417 1524-6 1544-1 1544-6 1544-9 1555-2 1660-1 1672-20 1730 1750 1825-2 1825-5 1825-8 1835 1955 2260-3 2260-5 2260-8 2260-11 | 10FT 16P 24P-10 28P-1 34P-1 44D 175 222-6 275B 310 320-1 365 385 486-1 486B 512 516-24 521-22 540 560 587 610 641 720-40 720C-3 720C-8 720C-42 721A-40 860 870B 880-1 880-5 900-60 920 920F 955A 1035 1081 1090 1095 1407 1524-2 1534-1 1544-2 1644-7 1544-11 1600-1 1660-2 1672-21 1735 1825 1825-3 1825-6 1825-9 1990-1 2260-1 2260-6 2260-9 2260-12 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|----------------------------|----|-----------|--------------------------------------|----------|----------|
| | | | | 2260-13 | 2260-14 | 2260-15 |
| | | | | 2260-16 | 2260-17 | 2260-18 |
| | | | | 2260-19 | 2260-20 | 2280-3 |
| | | | | 2380-1 | 2380-2 | 2380-3 |
| | | | | 2380-5 | 2480 | 2530-1 |
| | | | | 2530-2 | 2530-3 | 2530-4 |
| | | | | 2530-5 | 2530-6 | 2530-7 |
| | | | | 2530-8 | 2540-1 | 2540-3 |
| | | | | 2540-3A | 2540-5 | 2606 |
| | | | | 2620-1 | 2620-2 | 2620-3 |
| | | | | 2620-4 | 2620-5 | 2620-6 |
| | | | | 2620-7 | 2620-8 | 2620-9 |
| | | | | 2620-10 | 2620-11 | 2620-12 |
| | | | | 2620-13 | 2620-14 | 2620-15 |
| | | | | 2620-16 | 2620-17 | 2620-18 |
| | | | | 2620-19 | 2620-20 | 2730-1 |
| | | | | 2730-3 | 2730-5 | 2730-6 |
| | | | | 2730-7 | 2730-8 | 2730-9 |
| | | | | 2730-10 | 2801 | 2801-1 |
| | | | | 2801-2 | 2801-3 | 2801-4 |
| | | | | 2801-5 | 2801-6 | 2801-7 |
| | | | | 2801-8 | 2880-1 | 2880-3 |
| | | | | 2890-1 | 2950-1 | 2980-1 |
| | | | | 2980-2 | 2980-3 | 2980-4 |
| | | | | 2980-5 | 2980-6 | 2980-7 |
| | | | | 2980-8 | 2980-9 | 2980-10 |
| | | | | 2980-11 | 2980-12 | 3000-S3 |
| | | | | 3000-S5 | 4000-1 | 4000-2 |
| | | | | 4000-39 | 4000-40 | 4001-1 |
| | | | | 4001-2 to | 4025-1 | 4025-2 |
| | | | | See Also John B. Rudy Co. | | |
| TSO-C39 | Flying Service Engineering | EU | | F1007() | F1024() | F1025() |
| *F | and Equipment, Ltd. | | | F1026() | F1027() | F1028() |
| | Springfield Road | | | F1030() | F1031() | F1032() |
| | Chesham, Buckinghamshire | | | F1033() | F1034() | F1035() |
| | HP5 IPP, England | | | F1036() | F1038() | F2050() |
| | | | | F2055() | F2061() | F2066() |
| | | | | F2067() | F2070() | F2075() |
| | | | | F2077() | F2079() | F2086() |
| | | | | F2090() | F2100() | F2101() |
| | | | | F2106() | F2108() | F2110() |
| | | | | F2111() | F2112() | F2125() |
| | | | | F2126() | F2127() | F2128() |
| | | | | F2129() | F2130() | F2137() |
| | | | | F2175() | F3050() | F3066() |
| | | | | F3067() | F3070() | F3075() |
| | | | | F3077() | F3086() | F3100() |
| | | | | F3101() | F3112() | F3123() |
| | | | | F3124() | F3126() | F3137() |
| | | | | F3138() | F3140() | F3175() |
| TSO-C39 | Flying V Interiors | SW | | 100 | 100-1 | 100-4 |
| | Fort Worth, TX 76101 | | | 100-5 | | |
| TSO-C39 | Gull Airborne Instr., Inc. | NE | | RCT 202 COM/TPDR:901-203-0011, 0012, | | |
| | 395 Oser Avenue | | | 0013, 0014 | | |
| | Smithtown, NY 11787 | | | | | |
| TSO-C39 | Hamburger Flugzeugbau | EU | | G112 | G113 | G116 |
| *F | Germany | | | G117 | G118 | G119 |
| | | | | G121 | | |
| TSO-C39 | Hardman Aerospace | WN | | 340DA | TE542 | TE543 |
| | A Macrodyne-Chatillon Co. | | | TE546 | 600 | 600M |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|--|------|-----------|--|--|---|
| | 1845 S. Bundy Dr. Los Angeles, CA 90025 | | | 700() 3004SX 3045 3054TDM 3087 4023S 5000 Ser. 5003 Ser. 5006 Ser. 5012D 5020 Ser. 5962 6001 6004 6010 6847-1()Ser 8000T 8520 Ser. 8727-2() 9008 Ser. 9108-2() 9300() 9700-2 9700-3()Ser 9750-1() 9760-2() 101155 05-2-44 | 3000 3041D 3045SX 3070 4007 Ser. 4275 5001 Ser. 5004 Ser. 5010 5013D 5025 Ser. 6000AS 6002 6005 6500 Ser. 7070 8027 Ser. 8727 8727-3() 9061 Ser. 9111 9350() 9700-2() 9727 Ser. 9750-2() 10000-2()Ser. 101156 08-1-20A | 3004 3041SXA 3053TDM 3086 Ser. 4023D 4276 5002 Ser. 5005 Ser. 5011D 5013T 5960 6000SS 6003 6006-2()Ser. 6747-1()Ser. 8000 8037 Ser. 8727-1() 9000 9108 9200() 9500()Ser. 9700-3 9927()Ser. 9750-3() 10010-2() 09-1-20 |
| TSO-C39 | Howard Aero, Inc. San Antonio, TX 78205 | SW | | 500 | | |
| TSO-C39 | Kerr Aviation P. O. Box 399 Bethany, OK 73008 | SW | | 1121-590010 | | |
| TSO-C39 | Mooney Aircraft Corp. P. O. Box 72 Kerrville, TX 78028 | SW | | AB1001 AB1001-(501) AB1002-A AB1004 | AB1001-A AB1001-(502) AB1007 | AB1001-C AB1002 AB1034 |
| TSO-C39 | Navan Products, Inc. Los Angeles, CA 90052 | NM | | C-326 | | |
| TSO-C39 | Oro Manufacturing Co. P. O. Box 479 Monroe, NC 28110 | CE-A | | ACA-3912 ACA-3912-31 ACA-3912-61 ACA-3912-91 ACA-3921 ACA-3921-5 ACA-3922 ACA-3922-5 | ACA-3912-11 ACA-3912-41 ACA-3912-71 ACA-3912-101 ACA-3921-1 ACA-3921-7 ACA-3922-1 ACA-3922-7 | ACA-3912-21 ACA-3912-51 ACA-3912-81 ACA-3921-3 ACA-3921-9 ACA-3922-3 ACA-3922-9 |
| TSO-C39 | PABCO Company Rockford, IL 61101 | CE-C | | 1-A | 1-B | 501 |
| TSO-C39 | PTC Aerospace Aerospace Division Bantam, CT 06750 | NE | | 501-2 512H-1 523-1 536-2 536AM-A 538-3 544-1 555-3 558A-3H | 512 Ser. 520-2 523-2 536-3 537-2 540A 546-2 556 559 | 512H 520-3 535-2 536 AH-4 538-2 544 555-2 558A-3AH 572-2A |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------------|----|-----------|------------------------|
| | | | | 587-2 |
| | | | | 587-3 |
| | | | | 588-2 |
| | | | | 588-3 |
| | | | | 595 |
| | | | | 600-1 |
| | | | | 600-2 |
| | | | | 601-2 |
| | | | | 601-3 |
| | | | | 603-2 |
| | | | | 603-2A |
| | | | | 603A-2L |
| | | | | 603A-3AL |
| | | | | 603-2S |
| | | | | 603B-2L |
| | | | | 603C-2L |
| | | | | 603C-3L |
| | | | | 607 |
| | | | | 607-1 |
| | | | | 608-2 |
| | | | | 612-2 |
| | | | | 614-2 |
| | | | | 614-3 |
| | | | | 614B-1A |
| | | | | 614B-2A |
| | | | | 615-2 |
| | | | | 618 |
| | | | | 618-1 |
| | | | | 619-3 |
| | | | | 621-2 |
| | | | | 622 Ser. |
| | | | | 625()-2A() |
| | | | | 626-2 |
| | | | | 627-2 |
| | | | | 627-3 |
| | | | | 630 |
| | | | | 630-1 |
| | | | | 630-2 |
| | | | | 631-2 |
| | | | | 631-2A |
| | | | | 632-2 |
| | | | | 632-3 |
| | | | | 633-2 |
| | | | | 633-3A |
| | | | | 635-2 |
| | | | | 639 |
| | | | | 643-2 |
| | | | | 643-2A |
| | | | | 645-2 |
| | | | | 647-3 |
| | | | | 648()-2 |
| | | | | 648()-2A |
| | | | | 648-3 |
| | | | | 648()-3 |
| | | | | 648()-3A |
| | | | | 652()-2 |
| | | | | 652()-3 |
| | | | | 653-2 |
| | | | | 653()-2A() |
| | | | | 653()-1() |
| | | | | 655-2 |
| | | | | 660-2 |
| | | | | 660-3 |
| | | | | 664-2 |
| | | | | 664-3 |
| | | | | 670 |
| | | | | 670-1 |
| | | | | 671 |
| | | | | 671-1 |
| | | | | 672-3 |
| | | | | 672()-2() |
| | | | | 674-2 |
| | | | | 674()-() |
| | | | | 674()-3() |
| | | | | 674-3 |
| | | | | 677-2 |
| | | | | 677-3 |
| | | | | 679-2 |
| | | | | 679-3 |
| | | | | 680-3 |
| | | | | 681()-3 |
| | | | | 682()-2 |
| | | | | 682()-3 |
| | | | | 683()-3 |
| | | | | 689()-2 |
| | | | | 689()-3 |
| | | | | 691()-2 |
| | | | | 691()-2A |
| | | | | 693()-2() |
| | | | | 693()-3() |
| | | | | 694()-2 |
| | | | | 695()-2A |
| | | | | 696()-2 |
| | | | | 697()-2 |
| | | | | 699()-2() |
| | | | | 702()-3A |
| | | | | 705() |
| | | | | 705()-1 |
| | | | | 706()-3A() |
| | | | | 708()-3() |
| | | | | 709()-2() |
| | | | | 709()-3() |
| | | | | 712()-6() |
| | | | | 713()-5() |
| | | | | 721()-2() |
| | | | | 721()-2A() |
| | | | | 743()-1() |
| | | | | 723()-2() |
| | | | | 723()-3() |
| | | | | 736()-2() |
| | | | | 736()-3() |
| | | | | 741()-2() |
| | | | | 742()-1() |
| | | | | 742()-2() |
| | | | | 743()-2() |
| | | | | 743()-3() |
| | | | | 744()-2() |
| | | | | 745()-2() |
| | | | | 746()-2() |
| | | | | 747()-3() |
| | | | | 748()-2() |
| | | | | 749()-1() |
| | | | | 750()-3() |
| | | | | 751()-1() |
| | | | | 752()-2() |
| | | | | 753()-2() |
| | | | | 755()-2() |
| | | | | 756()-2() |
| | | | | 757()-1() |
| | | | | 759()-2() |
| | | | | 761()-2() |
| | | | | 761()-3() |
| | | | | 763()-2() |
| | | | | 764()-2() |
| | | | | 764()-3() |
| | | | | 765()-2() |
| | | | | 766()-2() |
| | | | | 767()-3() |
| | | | | 768()-2() |
| | | | | 769()-1() |
| | | | | 771()-1() |
| | | | | 772()-2() |
| | | | | 774()-2() |
| | | | | 774()-3() |
| | | | | 775()-2() |
| | | | | 775()-3() |
| | | | | 776()-1() |
| | | | | 776()-2() |
| | | | | 781()-2() |
| | | | | 782()-2() |
| | | | | 783()-2() |
| | | | | 784()-2() |
| | | | | 785()-3() |
| | | | | 786()-2() |
| | | | | 800()-2() |
| | | | | 801()-2() |
| | | | | 802()-2() |
| | | | | 803()-2() |
| | | | | 804()-2() |
| | | | | 805()-2() |
| | | | | 806()-2() |
| | | | | 807()-2() |
| | | | | 808()-2() |
| | | | | 812()-2() |
| | | | | 1003 |
| | | | | 1006 |
| | | | | 10003 |
| TSO-C39 | Qantas Airways, Ltd. | NM | | G-230 R&L |
| *F | Qantas House | | | G-251 R&L |
| | 70 Hunter St. | | | G-252 R |
| | Sydney, N. S. W., Australia | | | G-284 |
| | | | | G-285 |
| | | | | G-285-1 |
| | | | | C-400 R&L |
| | | | | C-600 |
| | | | | C-621 |
| | | | | C-631 |
| | | | | 400000 |
| | | | | 400001 |

Note: These seats are produced by various manufacturers and are limited to certain serial numbers for Qantas. For

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|----|-----------|--|--|---|
| | | | | information, contact Pacific Region Engineering and Manufacturing Branch. | | |
| TSO-C39 | John B. Rudy Co. 20950 Brant Ave. Long Beach, CA 90810 | NM | | 222() 560() 900() 1672() 2260 2530 2950 3980 | 360() 720() 920() 1745 2380 2540 2980 4000 | 486() 880() 955() 1990 2480 2620 3060 |
| | | | | SEE Also AiResearch Aviation Co. | | |
| TSO-C39 *F | L. A. Rumbold Ltd. Old Oak Common Lane London, N. W.10, England | EU | | M.564 M.603 M.746 M.790 M.796 M.807 M.818 M.899 M.938 M.949 M.952 M.960 M.964 M.971 M.976 M.983 M.998 M.1023 M.1110 M.1156 M.1168 M.1204 M.1192 M.1214 M1215 M.1275 M.1278 M.1295 M.1298 M.1302 M.1309 M.1319 M.1331 M.1337 M.1341 M.1344 M.1355 M.1365 M1373() M.1402 M.1413 M.1416 M.1500 M.1503 M.1506 M.1509 M.1513 M.1517 M.1521 M.1526 M.1529 M.1532 | M.601 M.689 M.747 M.791 M.799 M.808 M.892 M.919 M.941 M.950 M.953 M.961 M.966 M.972 M.977 M.984 M.1001 M.1108 M.1129 M.1158 M.1169 M.1215 M.1193 M.1269 M.1273 M.1276 M.1279 M.1296 M.1299 M.1303 M.1313 M.1321 M.1333 M.1338 M.1342 M.1353 M.1356 M1371() M1374() M.1404 M.1414 M.1451 M.1501 M.1504 M.1507 M.1510 M.1514 M.1518 M.1523 M.1527 M.1530 M.1533 | M.602 M.745 M.789 M.795 M.806 M.809 M.893 M.937 M.942 M.951 M.954 M.963 M.970 M.973 M.982 M.994 M.1002 M.1109 M.1155 M.1159 M.1199 M1198 M.1198 M.1270 M.1274 M.1277 M.1280 M.1297 M.1301 M.1304 M.1317 M.1327 M.1335 M.1339 M.1343 M.1354 M.1363 M1372() M.1401 M.1403 M.1415 M.1452 M.1502 M.1505 M.1508 M.1512 M.1516 M.1519 M.1524 M.1528 M.1531 M.1534 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|---------------------------|----|-----------|------------------------|-----------|-----------|
| | | | | M.1536 | M.1537 | M.1538 |
| | | | | M.1539 | M.1540 | M.1541 |
| | | | | M.1542 | M.1549() | M.1550() |
| | | | | M1555() | M1556() | M1557() |
| | | | | M1558() | M1561() | M1562() |
| | | | | M1563() | M1564() | M1565() |
| | | | | M1567() | M1570() | M.1601 |
| | | | | M.1602 | M.1603 | M.1604 |
| | | | | M.1605 | M.1606 | M.1607 |
| | | | | M.1608 | M.1615 | M.1616 |
| | | | | M.1617 | M.1618 | M.1621 |
| | | | | M.1622 | M.1623 | M.1624 |
| | | | | M.1625 | M.1626 | M.1627 |
| | | | | M.1629 | M.1631() | M.1632() |
| | | | | M.1633() | M.1634() | M.1635() |
| | | | | M.1636() | M1637() | M1645() |
| | | | | M1646() | M1705() | M1706() |
| | | | | M.1701() | M.1702() | .1703() |
| | | | | M.1704() | M.1801() | M.1803() |
| | | | | M.1804() | M.1805() | M.1807() |
| | | | | M.1809() | M.1811() | M1810() |
| | | | | M1817() | M1821() | M1822() |
| | | | | M1823() | M1825() | M1827() |
| | | | | M1828() | M1829() | M1830() |
| | | | | M.1813() | M.1814() | M.1815() |
| | | | | M.1816() | M.1819() | |
| TSO-C39 | SABENA | EU | | AA.01 | AB.01 | AC.01 |
| *F | Brussels National Airport | | | 438-7 | 438-8 | 438-10 |
| | B-1930 Zaventem, Belgium | | | 438-11 | 535-2 | |
| TSO-C39 | Siebelwerke - ATG, GmbH | EU | | 101 | 102 | G112 |
| *F | Donanworth, Germany | | | G113 | G116 | G117 |
| TSO-C39 | Sky Service Co. | SW | | 568 | | |
| | Bethany, OK 73008 | | | | | |
| TSO-C39 | Societe Industrielle & | EU | | 326 | 338 | 339 |
| *F | Commerciale de Material | | | 354-20 thru 354-29 | | |
| | Aeronautique (SICMA) | | | 355-20 thru 355-25 | | Y-13-310 |
| | 7, Rue Lucien Coupet | | | Y-23-13-10 | Y-23-130 | Y-23-140 |
| | 36100 Issoudun, | | | Y-23-220 | Y-23-320 | Y-23-520 |
| | France | | | Y-23-720 | Y-33-120 | Y-33-240 |
| | | | | Y-33-250 | Y-33-260 | Y-33-270 |
| | | | | Y-33-620 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|-----------|--|
| TSO-C39 | W. H. Spinks Enterprise Inc. P. O. Box 11099 Fort Worth, TX 76110 | SW | | AL-1021-1 Type III AL-1027-3 Type IV SM 1000 Type I |
| TSO-C39 | Spinks Industries, Inc. P. O. Box 11099 Fort Worth, TX 76110 | SW | | AL-1021-1 Type III AL-1027-3 Type IV SM 1000 Type I |
| TSO-C39 | TECO, Inc. Burbank, CA 91500 | NM | | TE403-1-27F-2 TE403-51-9 TE403A-51F-9 TE404C-2-47 TE543D-2-44-9 TE453D-2-44CR-9 TE453D-3-61-9 TE453D-3-65-9 TE475A-3-65CR-9 TE488A-2 TE488D-2 TE515C-1 TE537 TE542-1 TE542-9 TE543-3 TE546-1 TE550-2 TE551B TE565B-2 TE600-2-42 TE600-3-59 TE600-3-64 TE611-2-40 TE620-1 TE704-2-56 TE788 Ser. TE801-3-64 TE806 Ser. TE1000-3 TE1001-3 SEE Also Burns Seat Co. TE488B-2 TE515A-1 TE515D-1 TE540A-1 TE542-2 TE543-1 TE543-4 TE546-3 TE550B-2 TE565A-2 TE565B-3 TE600-2-42A TE600-3-59A TE601-2-41 TE611-2-40A TE700 Ser. TE705-3-59 TE801-2-44 TE801A-3-64 TE1000-1 TE1001-1 TE1003-2-40 TE403-47F-9 TE403-51F-9 TE403D-2-47A TE453D-2-41-9 TE453D-2-44A-9 TE453D-3-60CR-9 TE453D-3-64-9 TE453D-3-65CR-9 TE475A-2-45 TE488C-2 TE515B-1 TE529-2 TE541A TE542-3 TE543-2 TE545A TE546-4 TE551 TE565A-3 TE580G TE600-2-44 TE600-3-61 TE605-2-44 TE611-2-40B TE701 Ser. TE705C-3-59 TE801A-2-44 TE805 Ser. TE1000-2 TE1001-2 TE1003-3-59 |
| TSO-C39 *F | Tenryu Industries Co.Ltd. 4-1, Soharakocho Kakamigahara, Gifu Japan | NM | | TB770-2A TB770-3A |
| TSO-C39 | Tracor Custom Products P.O. Box 1141 1113 N. Main Street Mooresville, NC 28115 | CE-A | | 13109-1, -3 |
| TSO-C39 | Turbo Flight, Inc. Chicago, IL 60607 | CE-C | | 9960 |
| TSO-C39 | United Airmotive Svc. Inc. Fort Worth, TX 76101 | SW | | 379 |
| TSO-C39 | Universal Equipment Corp. Beverly Hills, CA 90213 | NM | | E-126 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|--|------|------------------------------|--|---|--|
| TSO-C39 | Weber Aircraft, Inc. Special Products Div. 1300 E. Valencia Drive Fullerton, CA 92631 | NM | | 2022 72913 210213 801136 801138-400 801138-613 801140 804001-407 804002-409 804003-421 804003-424 804003-427 805700-401 805701-401 806050 Ser. 807200-401 807200-404 807201 Ser. 807201-405 807201-411 807201-417 807201-423 807202-403 807202-409 807202-415 807202-421 807601() 808737() 810201() 810739() 811372() | 72911 74003 801135 801136-607 801138-402 801138-614 802730 804001-602 804003 804003-422 804003-425 804003-428 805700-403 805701-403 806051 Ser. 807200-402 807200-405 807201-401 807201-407 807201-413 807201-419 807202 Ser. 807202-405 807202-411 807202-417 807202-423 807602() 809100() 810737() 811369() 813825() | 72912 77207() 801135-607 801138 801138-403 801139 804001 804002 804003-604 804003-423 804003-426 804003-605 805700-405 805701-405 807200 Ser. 807200-403 807200-406 807201-403 807201-409 807201-415 807201-421 807202-401 807202-407 807202-413 807202-419 807600() 807603() 810200() 810738() 811370() 815838() |
| TSO-C39 | Jay Womack Aircraft Dallas, TX 75221 | SW | | 3511690 | | |
| TSO-C39a | Advanced Technology & Research, Inc. 11440 66th Street North Largo, FL 33543 | CE-A | AIRCRAFT SEATS AND BERTHS | ATR-TTA() | ATR-TTF() | |
| TSO-C39a | Aerosmith Products Corp. P. O. Box 542 Miami, FL 33144 | CE-A | | N239-() N244E-() N344-() C129-65-3 H25-() H25D-() | N239E-() N339-() N344E-() H15-() H25A-() H25E-() | N244-() N339E-() C129-65-1 H15C-() H25C-() |
| TSO-C39a | Aero-Seats, Inc. 300 Boone Road, Suite A-6 Burleson, TX 76028 | CE-A | | AS1-5000 | | |
| TSO-C39a | Aero Tech United P.O. Box 1220 Springdale, AR 72765 | SW | | 1240-1000-1009 1240-1000-1045 1240-1001-1032 | | |
| TSO-C39a | Air Center, Inc. P. O. Box 32168 Oklahoma City, OK 73132 | SW | | 1121-590010 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|-----------------------------|----|-----------|------------------------|------------|-----------|
| TSO-C39a | Acft. Furnishing Int'l. Ltd | EU | | 509 | 702 | 705/2 |
| *F | Mersham Station Works | | | 705/3 | 725 | 726 |
| | Walton-on-Thames | | | 726A | 727 | 729 |
| | Surrey, England | | | 730 | 732 | 733 |
| | | | | 829-1 | 1006 | 1007 |
| | | | | 1008 | 1010 | 1010/1 |
| | | | | 1012 | 1013 | 1016 |
| | | | | 1736 | 2001/1 | 2001/2 |
| | | | | 2005 | 2008() | 2731 |
| | | | | 3026() | 3029()() | 3030() |
| | | | | 3034() | 3035() | 3036() |
| | | | | 3037() | 3038() | 3039() |
| | | | | 3040() | 3043() | 3100() |
| | | | | 5001 | 035802() | 035803() |
| | | | | 100402() | 100403() | 160102() |
| | | | | 160103() | 200501() | 300003() |
| | | | | 304402() | 300103() | 300202() |
| | | | | 300203() | 300303() | 300402() |
| | | | | 300403() | 300502() | 300503() |
| | | | | 300504() | 300602() | 300603() |
| | | | | 300702() | 300703() | 300802() |
| | | | | 300803() | 300902() | 300903() |
| | | | | 301002() | 301003() | 301102() |
| | | | | 301103() | 301202() | 301203() |
| | | | | 301302() | 301303() | 301602() |
| | | | | 301603() | 301702() | 301703() |
| | | | | 302002() | 302003() | 302102() |
| | | | | 302103() | 302202() | 302203() |
| | | | | 302302() | 302303() | 302501() |
| | | | | 302601() | 302303() | 302501() |
| | | | | 302502() | 302503() | 302601() |
| | | | | 302602() | 3044403() | 304602() |
| | | | | 304603() | 304801() | 304802() |
| | | | | 304902() | 304903() | 305002() |
| | | | | 305003() | 305004() | 305102() |
| | | | | 305103() | 305201() | 305302() |
| | | | | 305401() | 305402() | 305403() |
| | | | | 305502() | 305503() | 305803() |
| | | | | 305825() | 305902() | 306101() |
| | | | | 306102() | 306402() | 306403() |
| | | | | 306902() | 306501() | 306502() |
| | | | | 306903() | 306801() | 369002() |
| | | | | 307002() | 3500() | 3510() |
| | | | | 350002() | 352002() | 307003() |
| | | | | 354002() | 355002() | 307004() |
| | | | | 356002() | 356004() | 359001() |
| | | | | 359002() | 359003() | 367001() |
| | | | | 365002() | 3073021() | 367002() |
| | | | | 36601 | 368001() | 4001-1() |
| | | | | 500301() | 500401() | 4001-2() |
| | | | | 3072() | 4001-3() | 307303() |
| | | | | 3029()() | | |
| TSO-C39a | Aircraft Mechanics, Inc. | NM | | 762R/1000-203 | 1069-() | |
| | P. O. Box 370 | | | 2026-() | 2027-() | 2028-() |
| | Colorado Springs, CO 80901 | | | 943-3 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|---|--|---|
| TSO-C39a | Aircraft Modular Products 4000 NW. 36 Avenue Miami, FL 33142 | CE-A | | 2524.001() 2523.020() 2524.002() 2524.003() 2524.004() 2523.613() 2523.612 | 2523.003() 2524.006() 2524.007() 2524.008() 2524.009() 2524.005() | 2523.012() 2523.015() 2523.016() 2523.021() 2523.103() 2524.202() |
| TSO-C39a | Aircraft West Mfrg. Co. 7821 Alabama Avenue Canoga Park, CA 91304 | NM | | 7505-1 | 7505-1A | |
| TSO-C39a | AiResearch Aviation Co. Div. Garrett Corp. Airline Products Facility 19201 Susana Rd. Compton, CA 90221 | NM | | G-110() G-118() BA-111() F112() G-112L() 114() 117() B-120() 123() HS-182() HS-183() G-211() 215() 220() 223() 231() 270() F301() 304() F-405() 409() 414() 29411001-401 2124002 J-197() HS-129() | G-110B() J-111() F-111K() 112() G-113L() 115() 118() B-121() 170() 128() 184 212() 218() 221() 224() 232() 277() 302() 400() G-405() 412() 415() 29411001-406 2124003 CL-129() 405() | G-111() SL-111() BH-111() G-112BL() G-113BL() 116() 119() F-122() 180() 150() 210() 213() 291() 222() 225() 233() 300() 303 G-404() 408() 413() 2124001 G-197() CL-239() J-129() |
| TSO-C39a *F | Air New Zealand Christchurch Engineering Base Christchurch, New Zealand | NM | | ANZ 2000:B7470 to B7481 ANZ 2000:F3515 to F3518 | | |
| TSO-C39a | Alamo Accessories, Inc. 10843 Vandale San Antonio, TX 78216 | SW | | M1-304 | | |
| TSO-C39a | All Products Co. P. O. Box 520 Mineral Wells, TX 76067 | SW | | ACS-2 | | |
| TSO-C39a *F | Alven s.r.l. Viale Delle Industrie 80040 S. Sebastiano Al Vesuvio, Napoli, Italy | EU | | 100DM001()()() 100DM005()()() 100DM013()()() 100DM033()()() 100DM037()()() 100DMC013()()() 100DMC033()()() 200ALV201()()() 200ALV202()()() 300ALV101()()() 300ALV106()()() 300ALV108()()() 300ALV150()()() 300ALV153()()() | thru 100DM0041()() thru 100DM006()()() thru 100DM030()()() 100DM036()()() thru 100DM040()()() thru 100DMC030()()() thru 100DMC036()()() 300ALV104()()() 300ALV109()()() 300ALV151()()() 300ALV154()()() | |

TSO NO. HOLDER NAME & ADDRESS RG TSO TITLE MODELS OR PART NUMBERS
 =====

300ALV159()() 300ALV160()()
 300ALV161()() 300ALV162()()
 300ALV163()() 300ALV164()()
 300ALV165()() 300ALV166()()
 300ALV167()() 300ALV168()()
 300ALV169()() 300ALV170()()
 300ALV171()() 300ALV172()()
 300ALV173()() 300ALV174()()
 3120001-XXXXX 3120002-XXXXX
 3120003-XXXXX 3120004-XXXXX
 3120005-XXXXX 3120006-XXXXX
 3120007-XXXXX 3120008-XXXXX
 3120009-XXXXX 3120010-XXXXX
 3120011-XXXXX 3120012-XXXXX
 3120013-XXXXX 3120014-XXXXX
 3120015-XXXXX 3120016-XXXXX
 3120017-XXXXX 3120018-XXXXX
 3120019-XXXXX 3120020-XXXXX
 3120021-XXXXX 3120022-XXXXX
 3120023-XXXXX 3120024-XXXXX
 3120025-XXXXX 3120026-XXXXX
 3120027-XXXXX 3120028-XXXXX
 3120033-XXXXX 3120034-XXXXX
 3120035-XXXXX 3120036-XXXXX
 3130001-XXXXX 3130002-XXXXX
 3130003-XXXXX 3130004-XXXXX
 3130005-XXXXX 3130006-XXXXX
 3130007-XXXXX 3130008-XXXXX
 3130009-XXXXX 3130010-XXXXX
 3130011-XXXXX 3130012-XXXXX
 3130013-XXXXX 3130014-XXXXX
 3130015-XXXXX 3130016-XXXXX
 3130017-XXXXX 3130019-XXXXX
 3130021-XXXXX 3130022-XXXXX
 3130023-XXXXX 3130024-XXXXX
 3130025-XXXXX 3130027-XXXXX
 3130028-XXXXX 3130029-XXXXX
 3130030-XXXXX 3130031-XXXXX
 3130033-XXXXX 3130034-XXXXX
 3140001-XXXXX 10V0101-XXX
 10V0102-XXX
 124()()-20()()
 124()()-21()()
 124()()-22()()
 124()()-65()()
 300ALV101()()
 300ALV104()()
 300ALV108()()
 300ALV109()()
 300ALV149()()
 300ALV152()()

TSO-C39a ALVEN s.r.l.
 *F Dunstable, Bedfordshire
 England

EU

"SINGLE"
 200ALV057(), 058()
 "DOUBLE"
 200ALV003() 200ALV004() 200ALV005()
 200ALV006()
 200ALV047(), 048(), 051(), 052(),
 053(), 054(), 055(), 056(),
 061(), 062()
 200ALV093(), 094(), 097(), 098()
 "TREBLE"
 200ALV001() 200ALV002() 200ALV049
 200ALV059()
 200ALV091(), 092(), 095(), 096()

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|--|--|---|
| | | | | 300ALV001() to 300ALV020() | | |
| TSO-C39a | AMI Industries, Inc. P.O. Box 370 Colorado Springs, CO 80901 | NM | | 943-5 3200 971-() 965-() 2037-() | 943-6 1091-1 972-() 1052-() | 1078-() 1042-5 973-() 1100-() |
| TSO-C39a | Antenna Products Co. P. O. Box 520 Mineral Wells, TX 76067 | SW | | ACS-1 | | |
| TSO-C39a | ARA, Inc. 160 South Hacienda Blvd. P.O. Box 3824 City of Industry, CA 91744 | NM-W | | D4144-1 S76:D4600-3, D4600-4 | | |
| TSO-C39a | Associated Aircraft Equip. P. O. Box 542 6961 N.W. 42nd St. Miami, FL 33166 | CE-A | | DF13366-1F DF13366-2R LL100-4-() HB100-MU PA 730-1 AAE-2FW() AAE-300-000 SE440-P2520 SWS-1-2348 AAE-11002 AAE-11004(1) AAE-11007 | DF13366-1R HB100-1-D LL100-6-() AAE-2(4) PA 730-2 AAE-2001S AAE-11010 F200SFTA-EMB-02 SWS-1-2347 AAE-11003 AAE-11008 AAE-11006 | DF13366-2F LL100-2-() LL200-2-() G21-P() AAE-FB2(1) AAE-CS3 |
| TSO-C39a | Atlantic Aviation Corp. Greater Wilmington Airport Box 1709 Wilmington, DE 19899 | NE | | 21.737 (This seat no longer manufactured.) 22.737 | | |
| TSO-C39a | Avcon Industries, Inc. City-County Airport P.O. Box 748 Newton, KS 67114 | CE-W | | 4001-101 4001-104 4001-201, -202, -203, -204, -207, -208, -209, -210, -211, -212, -213, -214, -215, -216, -217, -218 4001-300 | 4001-102 4001-105 -205, -206, 4006-101 | 4001-103 4001-106 |
| TSO-C39a *F | Aviatech, Inc. 2400 Guenette Street Ville St. Laurent, PQ Canada H4R 2H2 | NE | | TYPE I Model 386 Model 391: 391-(30), 391-(40), 391-(50), 391-(60) 394-() --: 396-() --: 397-() --: 403-() Model 398: 398-(20) 402-() Model 403: 403-(10) --: 404-() --: 405-() 416-() --: 409-() Model 412: 412-()-30-01 413-(10) --: 414-() 416-() | | |
| TSO-C39a *F | Aviation Furnishings Ltd Redhill, Surrey, England | EU | | 801-1 to -7 819-1 | 804-1 820-() | 1005 862() |
| TSO-C39a *F | Avioninteriors S.p.A. L. GO Luigi Antonelli 4 00145 Rome | EU | | 20 1001 281()() 20 1000 188()() 20 1000 285()() | | 20-10-50() 20-10-51() 20-10-60() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | Italy | | | 20 1000 382()() () 20-10-61() |
| | | | | 20 1000 479()() () |
| | | | | 20 1000 576()() () |
| | | | | 20 1000 673()() () |
| | | | | 20 1001 184()() () |
| | | | | 20 2000 864()() () |
| | | | | 20 2000 961()() () |
| | | | | 20 2001 084()() () |
| | | | | 20 3000 182()() () |
| | | | | 20 3000 279()() () |
| | | | | 20 3000 376()() () |
| | | | | 20 10 60 170()() () |
| | | | | 20 10 50 173()() () |
| | | | | 20 10 60 267()() () |
| | | | | 20 10 50 270()() () |
| | | | | 20 10 60 364()() () |
| | | | | 20 10 50 367()() () |
| | | | | 20 10 60 461()() () |
| | | | | 20 10 50 464()() () |
| | | | | 20 10 60 558()() () |
| | | | | 20 10 50 561()() () |
| | | | | 20 10 60 655()() () |
| | | | | 20 10 50 658()() () |
| | | | | 20 10 50 755()() () |
| | | | | 20 10 51 169()() () |
| | | | | 20 10 51 266()() () |
| | | | | 20 10 61 360()() () |
| | | | | 20 10 51 363()() () |
| | | | | 20 10 61 457()() () |
| | | | | 20 10 51 460()() () |
| | | | | "ITALIA TWO" |
| | | | | 11050-01()() () thru 11050-02()() () |
| | | | | "AMERICA" |
| | | | | 100()()-() () () () |
| | | | | 100()()-21() () |
| | | | | 100()()-83() () () () |
| | | | | 101()()-20() () |
| | | | | 101()()-21() () |
| | | | | 101()()-37() () |
| | | | | 101()()-38() () |
| | | | | 101()()-39() () |
| | | | | 101()()-47() () |
| | | | | 101()()-48() () |
| | | | | 101()()-55() () |
| | | | | 101()()-75() () |
| | | | | 101()()-76() () |
| | | | | 101()()-77() () |
| | | | | 101()()-78() () |
| | | | | 101()()-82() () () () |
| | | | | 101()()-83() () |
| | | | | 101()()-84() () |
| | | | | 101()()-88() () |
| | | | | 101()()-90() () |
| | | | | 101()()-91() () |
| | | | | 101()()-98() () |
| | | | | 102()()-25() () () () |
| | | | | 102()()-30() () () () |
| | | | | 102()()-34() () () () |
| | | | | 102()()-35() () () () |
| | | | | 102()()-36() () () () |
| | | | | 102()()-37() () () () |
| | | | | 102()()-38() () () () |
| | | | | 102()()-40() () () () |
| | | | | 102()()-41() () () () |
| | | | | 102()()-42() () () () |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|------------------------|
| | | | | 102()()-46()()() |
| | | | | 102()()-56()()() |
| | | | | 102()()-57()()() |
| | | | | 102()()-58()()() |
| | | | | 102()()-59()()() |
| | | | | 103()()-01()()() |
| | | | | 103()()-36()()() |
| | | | | 103()()-37()()() |
| | | | | 103()()-38()()() |
| | | | | 103()()-40()()() |
| | | | | 103()()-41()()() |
| | | | | 103()()-42()()() |
| | | | | 103()()-43()()() |
| | | | | 103()()-50()()() |
| | | | | 103()()-51()()() |
| | | | | 103()()-55()()() |
| | | | | 103()()-60()() |
| | | | | 103()()-61()() |
| | | | | 103()()-65()()() |
| | | | | 103()()-66()()() |
| | | | | 103()()-81()()() |
| | | | | 103()()-82()()() |
| | | | | 106()()-05()()() |
| | | | | 106()()-32()()() |
| | | | | 106()()-34()()() |
| | | | | 106()()-60()()() |
| | | | | 106()()-65()()() |
| | | | | 107()()-20()()() |
| | | | | 107()()-25()()() |
| | | | | 107()()-26()()() |
| | | | | 107()()-30()()() |
| | | | | 107()()-31()()() |
| | | | | 107()()-46()()() |
| | | | | 107()()-32()()() |
| | | | | 107()()-40()()() |
| | | | | 107()()-41()()() |
| | | | | 107()()-42()()() |
| | | | | 107()()-43()()() |
| | | | | 107()()-44()()() |
| | | | | 107()()-45()()() |
| | | | | 107()()-47()()() |
| | | | | 107()()-48()()() |
| | | | | 107()()-50()()() |
| | | | | 107()()-60()()() |
| | | | | 107()()-65()()() |
| | | | | 107()()-69()()() |
| | | | | 107()()-70()()() |
| | | | | 107()()-71()()() |
| | | | | 107()()-72()()() |
| | | | | 107()()-73()()() |
| | | | | 107()()-74()()() |
| | | | | 107()()-75()()() |
| | | | | 107()()-76()()() |
| | | | | 107()()-77()()() |
| | | | | 107()()-78()()() |
| | | | | 107()()-79()()() |
| | | | | 107()()-80()()() |
| | | | | 107()()-81()()() |
| | | | | 107()()-82()()() |
| | | | | 108()()-74()()() |
| | | | | 108()()-76()()() |
| | | | | 108()()-77()()() |
| | | | | 108()()-78()()() |
| | | | | 109()()-05()()() |
| | | | | 109()()-31()()() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|------------------------|
|---------|-----------------------|----|-----------|------------------------|

109()()-40()()()
 110()()-84()()()
 110()()-85()()()
 110()()-86()()()
 110()()-87()()()
 110()()-88()()()
 110()()-89()()()
 117()()-02()()()
 117()()-03()()()
 118()()-34()()()
 118()()-35()()()
 118()()-54()()()
 118()()-57()()()
 118()()-58()()()
 118()()-59()()()
 118()()-60()()()
 119()()-01()()()
 119()()-10()()()
 122()()-50()()()
 123()()-10()()()
 123()()-11()()()
 125()()-10()()()
 11077-01()()()
 11077-10()()()
 11077-11()()()
 11077-12()()()
 11077-13()()()
 11077-50()()()
 11077-51()()()
 11077-52()()()
 11077-53()()()
 11078-10()()()
 11078-11()()()
 11078-12()()()
 11078-13()()()
 11078-50()()()
 11078-51()()()
 11078-52()()()
 11078-53()()()
 11086-01()()()
 11087-01()()()
 11088-01()()()
 "AMERICA TWO"
 11071-01()() thru
 11071-08()()
 "AMERICA THREE"
 11073-01()() thru
 11078-08()() ,
 11073-20()()
 11073-24()() thru
 11073-28()()
 11073-21()()

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|---|
| | | | | "AMERICA FOUR" 11074-01() thru 11074-07() 11089-01()()() "AMERICA FIVE" 11075-01() thru 11075-05, 11075-07 12007-01()()L6 12007-02()()L6 "AFRICA" 102()()-31()() thru 102()()-33()() 12010-01()()T9 12010-02()()T9 "AFRICA FIVE" 11095-01 thru 11095-03 12011-01()()T8 12011-02()()T8 "VIP" 11069-01(), 11069-02 "EUROPA" 11040-01()()() thru 11040-17()()() 111()()-01()()() 11099 |
| TSO-C39a | Beech Aircraft Corp. P.O. Box 85 Wichita, KS 67201 | CE-W | | 15795-1001-() 15795-1002-() |
| TSO-C39a | Castle Industries, Inc. of California 601 S. Dupont Avenue Ontario, CA 91761-1502 | NM | | 0801801-() 11-007-() 10-003-() |
| TSO-C39a *F | Contour Seats Ltd. 13 Eelmoor Road Farnborough, Hampshire GU14 0HR England | EU | | 900 Series 0907-27, -28, -29, -30 1000-1 to -10 inclusive 0902-021 to -026 inclusive 0904-01-001, -003, -004 0907-35 to -41 inclusive 0909-1 to -7 inclusive 0920() 0930() 0940() 0930-01-001 0920-01-001 0950-01-001 0950-01-002 0950-01-003 0950-01-004 0950-01-005 0950-01-006 0950-01-007 0950-02-001 0950-02-002 0950-02-003 0950-02-004 0950-02-005 0950-02-006 0950-02-007 0950-02-008 0950-02-009 |
| TSO-C39a | Crestview Aerospace Corp. Bob Sikes Airport P.O. Box 1177 Crestview, FL 32536 | CE-A | | 4251-11-() 4251-13-() 5402 (Subvariants: 5401, 5403) |
| TSO-C39a | Design Engineering Corp. of America, DECA P.O. Box 59-3210 Miami, FL 33159 | CE-A | | 2523.226() 2523.227() 2523.231() 2523.234() 2523.501() 2524.001() 2524.002() 2524.003() 2524.004() 2524.005() 2524.008() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|--|---|--|
| TSO-C39a | Engineering Research and Development Associates P.O. Box 172 Peshtigo, WI 54157 | CE-C | | 3000 3100() 3200() 3401() | 3002() 3101() 3300() | 3003() 3102() 3400() |
| TSO-C39a | Enginetics Corporation 4060 Lisa Drive Tipp City, OH 45371 | CE-C | | 100() 200(A) 203() 204() 102(A) | 200() 101() 102() 205() 103(A) | 100(A) 201() 103() 205(A) 204(A) |
| TSO-C39a | Fairchild Industries, Inc. Aircraft Service Station P. O. Box 40 St. Augustine, FL 32084 | CE-A | | L793-2-() D793-3-() | D793-1-() 803-2-() | D793-2-() A851-2-() |
| TSO-C39a | Fairchild Republic Div. Hagerstown, MD 21740 | NE | | 853-2-() C853-1-() C853-4-() | 853-3-() C853-2-() | 853-4-() C853-3-() |
| TSO-C39a *F | Field Aviation Co., Ltd. Calgary Inter'l Airport Calgary, Alberta Canada | NE | | 91740 93731 93783 | 93674-1, -2 C6FF-1702-() | 93730-1, -2 |
| TSO-C39a | Flight Controls Systems 7118 NW. 72nd Avenue Miami, FL 33166 | CE-A | | Fixed single seat Model 2524.006() 2-place L-shaped divan Model 2523.612() 3-place divan Model 2523.613() 3-place tracking divan Model -- 4-place tracking divan Model 2523.611() Folding jumpseat Model 2524.202() 2523.012() | | |
| TSO-C39a | Flight Equipment & Engineering Corporation P. O. Box 522173 Miami, FL 33148 | CE-A | | 639 653() 657() 659-1() 662-3() 664-53() 667-3() 671-4-() 673-1() 675-3() 679-3 682-3() 690-1() 162F() 272A() 284A() 295F() 384F() 390F() 479F() | 639-3 654() 657-1() 660-3() 663-1() 665-1() 669-1-() 672-4() 674() 676-3() 681-3() 675(2) 690-3() 172F() 272F() 284F() 372F() 389F() 395F() 484F() | 648() 656() 658() 661-1() 664-52() 666() 670-3() 673() 675() 677 682() 683-1 SK1493 262F() 279F() 290F() 379F() 390() 399F() |
| TSO-C39a *F | Flight Equipment & Engineering, Limited Asheridge Road Chesham, Buckinghamshire England | EU | | 150F() 250F 295A 272F() 284F() 295F() 372A() 384F() D399F() 395F() 479F() | 162A() 262A() 395A 279F() 285F() 350F 372F() 389F() 390() 399F() 484F() | 172F() 267FA() 272A() 284A() 290F() 362F 379F() D389F() 390F() 462F() 295AF() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|----|-----------|--|
| | | | | 395AF() 2101F() 3101F() OAO 69-0014/2 OAO69-0043/4 OAO79-0019/20 OAO88-0009-10 |
| TSO-C39a | Flying Service Engineering and Equipment, Ltd. Springfield Road Chesham, Buckinghamshire HP5 1PP. England | EU | | F1003() F1016() F1016-001() F1023() F1030() F1031() F1031-C() F1033() F1034() F1035() F1035-F-001() F1035-G-001() F1035-K-001() F1036-B() F1036-C-001/2() F1038() F1038-F-() F1038-G-() F1038-H-() F1038-J-001() F1038-L-001() F1039-B-001() F1039() F1040() F1044() F1045() F1046() F1071-001() F1071-B-001/002() F1072-001() F1072-B-001() F1073-001/002() F1073-B-001/2() F1073-C-001/2() F1073-D-001/2() F1073-E-001/2() F1076-001() F1073-G-001/002() F1073-H-001/002() F1078-B-001() F1079-B-001() F1080-001() F1200-001/002() F1200-B-001/002() F1201-001/002() F1203-001/002() F1204-001/002() F1204-B-001/-002() F1205-001/002() F2010-B-001() F1209-B-001() F1209-001() F1209-C-001() F1209-D-001() F1210-001() F1210-B-001() F1210-C-001() F1211-001() F1212-001() F1227-001/2() F1227-B-001/2() F1230-001() F1230-B-001() F1236-001/002() F1239-001/002() F1239-B-001/002() F1239-C-001/002() F1279-001() F1281-B-001/002() F1289-001() F2021-B-001() F2021-B-002() F1281-001/002() F2055() F2055-001 F2055-C-001 F2055-D-001() F2055-E-001/002() F2055-F-001/002() F2055-G-001/002() F2055-H-001/002() F2055-J-001/002() F2055-K-001/002() F2055-L-001/002() F2055-M-001/002() F2055-N-001/2() F2061-D-001/2() F2061-E-001/2() F2061-F-001/2() F2066() F2066-C() F2067-C-001/002() F2067-D-001/002() F2077-G-001/-002() F2087() F2087-001() F2090() F2096-L-001/002() F2096-M-001/002() F2100() F2107() F2112() F2107-H-001() F2109-G-001/002() F2109-H-001/002() F2125() F2125-C-() F2125-D-001/2() F2127() F2125-F-001/-002() F2128() F2129() F2130-C() F2130-F-001/002() F2130-G-001/002() F2134() F2135() F2144() F2146() F2147() F2151() F2153() F2155() F2156() F2158() F2161() F2162() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | F2162-G-001/002() F2162-H-001() |
| | | | | F2165() F2166()F2167() |
| | | | | F2171() F2173-001/002() |
| | | | | F2173-B-001/2() F2173-C-001/2() |
| | | | | F2173-D-001/2() F2173-E-001/2() |
| | | | | F2176() F2173-F-001/002() |
| | | | | F2173-G-001/002() F2173-H-001/002() |
| | | | | F2180() F2180-B-001() |
| | | | | F2181-001() F2181-B-001() |
| | | | | F2183-001/002() F2184-001/002() |
| | | | | F2187(001) F2187-C-001/2() |
| | | | | F2190-D-001() F2190-J-001/002() |
| | | | | F2191-001/002() F2193-D-001/2() |
| | | | | F2193-E-001/002() F2193-001/002() |
| | | | | F2193-B-001/002() F2193-C-001/002() |
| | | | | F2193-G-001/002() F2193-H-001/002() |
| | | | | F2195-001/002() F2215-E-001/002() |
| | | | | F2215-F-001/002() F2200-001() |
| | | | | F2200-001/3200-001() |
| | | | | F2201-B-001() F2204-001() |
| | | | | F2204-B-001/002() F2204-C-001() |
| | | | | F2214-001/002() F2214-B-001() |
| | | | | F2215-001() F2215-B-001() |
| | | | | F2215-D-001/002() F2215-G-001() |
| | | | | F2216-001/002() F2216-B-001/002() |
| | | | | F2217-001() F2217-B-001() |
| | | | | F2218-001/002() F2219-001/002() |
| | | | | F2219-B-001/002() F2219-C-001/002() |
| | | | | F2219-D-001/002() F2219-E-001/002() |
| | | | | F2219-F-001/002() F2219-G-001/002() |
| | | | | F2220-001() F2221-001/002() |
| | | | | F2221-B-001/002() F2221-C-001/002() |
| | | | | F221-E-001/002 F221-R-001() |
| | | | | F2223-001/002() F2226-C-001() |
| | | | | F2227-001/2() F2227-B-001/2() |
| | | | | F2230-001() F2230-B-001() |
| | | | | F2236-001/002() F2237-001/002() |
| | | | | F2237-B-001/002() F3041 |
| | | | | F2237-C-001() F2237-D-001() |
| | | | | F2238-001() F2238-C-001() |
| | | | | F2238-D-001() F3066() |
| | | | | F2239-001/002() F2239-B-001/()002() |
| | | | | F2239-C-001() F2277() |
| | | | | F2279-001() F2281-001/002() |
| | | | | F2282-001() F2282-B-001() |
| | | | | F2287-001() F2287-B-001/002() |
| | | | | F2287-C-001 Type 1() |
| | | | | F2287-D-001() F2288-001() |
| | | | | F2288-B-001() F2289-001/002() |
| | | | | F2289-B-001/002() F2291-001() |
| | | | | F2297-D-001/-002() F2297-001/-002() |
| | | | | F2297-E-001/-002() F2297-B-001/-002() |
| | | | | F2297-F-001/-002() F2297-C-001/-002() |
| | | | | F2301-001/-002() F2301-B-001/-002() |
| | | | | F2301-C-001/-002() F3066-D() |
| | | | | F3066-E() F3066-F() |
| | | | | F3066-G() F3066-H()F3100() |
| | | | | F3096-L-001/002() F3096-M-001/002() |
| | | | | F3112() F3135()F3136() |
| | | | | F3138() F3144()F3146() |
| | | | | F3146-C-001/002 F3146-D-001/002() |
| | | | | F3156() F3159()F3162() |
| | | | | F3162-G-001/002() F3162-H-001() |
| | | | | F3169() F3162-J-001/002 |
| | | | | F3162-K-001/002 F3171() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|------------------------|
| | | | | F3176() |
| | | | | F3180() |
| | | | | F3180-B-001() |
| | | | | F3180-C-001/002() |
| | | | | F3193-001/002() |
| | | | | F3193-B-001/002() |
| | | | | F3193-C-001/000() |
| | | | | F3193-D-001/2() |
| | | | | F3193-G-001/002() |
| | | | | F3193-H-001/002() |
| | | | | F3195-001/002() |
| | | | | F3198-001/002() |
| | | | | F3200-001() |
| | | | | F3203-001/002() |
| | | | | F3200-B-001/-002() |
| | | | | F3214-001/002() |
| | | | | F3214-B-001 |
| | | | | F3214-C-001/002() |
| | | | | F3214-D-001/002 |
| | | | | F3216-001() |
| | | | | F3216-B-001/002() |
| | | | | F3216-C-001() |
| | | | | F3216-D-001() |
| | | | | F3216-E-001() |
| | | | | F3216-F-001() |
| | | | | F3216-G-001() |
| | | | | F3216-H-001() |
| | | | | F3219-001/002() |
| | | | | F3219-B-001() |
| | | | | F3219-C-001/2() |
| | | | | F3219-D-001() |
| | | | | F3221-000/002() |
| | | | | F3221-B-001/002() |
| | | | | F3221-C-001/002() |
| | | | | F3221-D-001/002() |
| | | | | F3221-E-001/002() |
| | | | | F3221-F-001/002() |
| | | | | F3221-G-001/002() |
| | | | | F3221-H-001/002() |
| | | | | F3221-J-001/002() |
| | | | | F3221-K-001/002() |
| | | | | F3221-L-001/002() |
| | | | | F3221-M-001/002() |
| | | | | F3221-N-001/2() |
| | | | | F3221-P-001/2() |
| | | | | F3221-Q-001/002 |
| | | | | F3221-R-001() |
| | | | | F3221-T-001() |
| | | | | F3222-001() |
| | | | | F3226-C-001() |
| | | | | F3227-001/002() |
| | | | | F3237-B-001/002() |
| | | | | F3237-C-001() |
| | | | | F3237-D-001/002() |
| | | | | F3276-001() |
| | | | | F3277() |
| | | | | F3279-001() |
| | | | | F3287-001() |
| | | | | F3287-B-001() |
| | | | | F3287-C-001 Type 1 () |
| | | | | F3287-D-001() |
| | | | | F3290-001() |
| | | | | F3289-001/002() |
| | | | | F3289-B-001/002() |
| | | | | F3297-001/002 |
| | | | | F3297-B-001/002() |
| | | | | F3297-C-001/002() |
| | | | | F3297-D-001/002() |
| | | | | F3297-E-001/002() |
| | | | | F3297-F-001/002() |
| | | | | F3297-G-001/002() |
| | | | | F3297-H-001/002() |
| | | | | F3297-T-001/002() |
| | | | | F3297-U-001/002() |
| | | | | F3297-W-001/002() |
| | | | | F3297-X-001/002() |
| | | | | F3297-J-001/002() |
| | | | | F3297-K-001/002() |
| | | | | F3297-M-001/002() |
| | | | | F3297-N-001/002() |
| | | | | F3297-P-001/002() |
| | | | | F3297-Q-001/002() |
| | | | | F3297-R-001/002() |
| | | | | F3297-S-001/002() |
| | | | | F3297-AA-001/002() |
| | | | | F3297-AB-001/002() |
| | | | | F3297-AC-001() |
| | | | | F3297-AD-001() |
| | | | | F3297-AE-001/002() |
| | | | | F3297-AF-001() |
| | | | | F4013() |
| | | | | F4014() |
| | | | | F4014-C-001() |
| | | | | F4015() |
| | | | | F4015-E-001() |
| | | | | F4017() |
| | | | | F4017-001/002() |
| | | | | F4018-001() |
| | | | | F4019-001() |
| | | | | F4020-001() |
| | | | | F4021-001/2() |
| | | | | F4024-001() |
| | | | | F4024-B-001() |
| | | | | F4024-C-001() |
| | | | | F4024-D-001() |
| | | | | F6003-001() |
| | | | | F6004-001() |
| | | | | F6005-001/002() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|----|-----------|--|
| TSO-C39a | 4/Flight 11626 Tuxford St. Sun Valley, CA 91352 | NM | | 100()() 105()() 240()() 1040()() 1045()() 1050()() 1800()() 1822()() 1875()() 2200()() 2370()() 2390()() 2545()() 3080()() 3085()() 3080ULW()() 3220()() 3230()() 3240 LW()() 3290()() 3375()() 3385()() 3575()() 3530-18 3580()() 3580 LW()() 3585()() 3815()() 3820()() 3830()() 3870()() 4040()() 4040LW()() 4045()() 4485()() 4620()() 4670()() 4675()() 4830()() 5210()() 5130()() 5230()() 5235()() 5310()() 5330()() 5365()() 5370()() 5390()() 5405()() 5430()() 5465()() 5590()() 5595()() 5500()() 5520()() 5540()() 5585()() 5680() 5610()() 5615()() 5680()() 5700()() 5720()() 5730()() 5745 5750()() 5755 5760 5765 5770 5775()() 5785()() 5795()() 5800()() 5810()() 5820()() 5830()() 5840()() 5850()() 5880()() 5900()() 5940()() 6070()() 6100()() 6115()() 6130()() 6140()() 6240()() 6245()() 6270()() 6400()() 6405()() 6410()() 6415()() 6420()() 6440()() 6425()() 6505()() 6530()() 6550()() 6570()() 6575()() 6620()() 6625()() 6650()() 6655()() 6720()() 6735()() 6770()() 6820()() 6825()() 6845()() 6865()() 6980()() 7080()() 7085()() 7095()() 7100()() 7115()() 7210()() 7220 7250()() 7260()() 7270()() 7350()() 7380()() 7360()() 7420()() 7425()() 7480()() 7485()() 7490()() 7492()() 7493()() 7495()() 7520()() 7545()() 7560()() 7670()() 7700 7720()() 7800()() 7795()() 7810()() 7815()() 7820()() 7825()() 7860()() 8025()() 8030()() 8040()() 8050()() 8080()() 8095()() 8180()() 8285()() 8350()() 8385()() 8420()() 8430()() 8470()() 8480()() 8485()() 8490()() 8500()() 8520()() 8540()() 8565()() 8635()() 8660()() 8665()() 8670()() 8685()() 8690()() 8700()() 8705()() 8710()() 8730()() 8770()() 8775()() 8780()() 8785()() 8795()() 8910()() 8920()() 8925()() 8930()() 8960()() 8990()() 8990LW()() 8995()() 8995LW()() 9040()() 9045()() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|----|-----------|------------------------|---------------|----------------|
| | | | | 9100()() | 9280()() | 9280LW()() |
| | | | | 9340()() | 9400()() | 9420()() |
| | | | | 9460()() | 9470()() | 9480()() |
| | | | | 9490 | 9505 | 9510 |
| | | | | 9515 | 9520()() | 9570 |
| | | | | 9610 | 9615 | 9630()() |
| | | | | 9635()() | 9710()() | 9770()() |
| | | | | 9970()() | 10000()() | 10030()() |
| | | | | 10040()() | 10055-(X) | 10055-()-() |
| | | | | 10095()() | 10120()() | 10160-()-() |
| | | | | 10170-()-() | 10180()() | 10230-()() |
| | | | | 10240-()() | 10250-()() | 10260-()() |
| | | | | 10320-()() | 10325-()() | 10330-()() |
| | | | | 10335-()() | 10360()() | 10380()() |
| | | | | 10390()() | 10400()() | 10410()() |
| | | | | 10420() | 10440()() | 10450()() |
| | | | | 10460()() | 10500()() | |
| | | | | 10495 ULW-()() | | |
| | | | | 10515LW00 | 10520()() | 10530()() |
| | | | | 10540()() | 10545()() | 10560()() |
| | | | | 10590()() | 10595LW()() | |
| | | | | 10600()() | 10605-P()() | |
| | | | | 10615()() | 10620-()() | 10630-()() |
| | | | | 10650()() | 10660()() | 10670 LW()() |
| | | | | 10680()() | 10705()() | 10725()() |
| | | | | 10760()() | 10765()() | 10795 LW |
| | | | | 10875()() | 11065()() | 11080()() |
| | | | | 10930()() | 11090()() | 11115()() |
| | | | | 11130()() | 11125()() | 11195()() |
| | | | | 11175()() | 11520()() | 11200()() |
| | | | | 11485-()() | 11635()() | 11640-()() |
| | | | | 11875()() | 11845-()-() | |
| | | | | 11530()() | 11250()() | 11260()() |
| | | | | 11700-()-() | 11880()() | 11990()() |
| | | | | 12030-1()() | 12250-()-() | |
| | | | | 13080-()-() | 12230()() | 12410-()-() |
| | | | | 12240-()-() | 12610()() | 12640-()-() |
| | | | | 12260-()-() | 12270-()-() | |
| | | | | 12830-()-() | 2340LW-()() | |
| | | | | 11055()() | 11550()() | 12690()-() |
| TSO-C39a | Frakes Aviation Route 3, Box 229-D Cleburne, TX 76031 | SW | | FA6501-1 | FA6501-2 | FA6502-1 |
| | | | | FA6502-2 | FA6503-1 | FA6504-1 |
| | | | | FA6520-1 | | |
| TSO-C39a | Furnishing International Ltd Walton-on-Thames Surrey, England | EU | | 302801() | 302802() | 302803() |
| *F | | | | | | |
| TSO-C39a | Golan Industries Bnei Yehuda Center Ramat Ha Golan, Israel | EU | | GI-1018-0 | GI-1070-0 | |
| *F | | | | GI 1070-00K | GI 1070-00H | |
| | | | | GI 1070-00KH | GI 1070-00WKL | |
| | | | | GI 1070-00G | GI 1070-00PKH | |
| | | | | GI 1070-00IK | GI 1071-0 | |
| | | | | GI 1071-00K | GI 1071-00G | |
| | | | | GI 1071-00H | GI 1071-00KH | |
| | | | | GI 1071-00PKH | GI 1071-00IK | |
| | | | | GI 1071-00WKL | GI 1072-0 | |
| | | | | GI 1073-0 | GI 1089-0 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|----|-----------|--|
| | | | | GI 1090-00K GI 1090-00KH GI 1090-00KW GI 1091-00K GI 1090-00KIH GI 1091-00KIH GI 1091-00KH GI 1091-00KW |
| TSO-C39a | Hardman Aerospace A Macrodynne-Chatillon Co. 1845 S. Bundy Dr. Los Angeles, CA 90025 | NM | | 670() 671() 680() 9227() 9777() 9778() 9780() 9781() 9785() 9810() 9827() 9900() 10000() 10027() HA543P-() 105346-() 20-100-() 20-200-1 20-300-() 20-400-() |
| TSO-C39a *F | Hawker deHavilland Australia Pty. Ltd. P. O. Box 30 Bankstown, N.S.W. Australia 2200 | NM | | 23-H-294-() 23-H-296-() 23-H-390-() 23-H-620-() 23-H-651-() 23-H-652-() 23-H-653-() 23-H-654-() 23-H-657-() 23-H-658-() 23-H-659-() 23-H-661-() 23-H-662-() 23-H-739-() |
| TSO-C39a | Heath Techna Corp. Precision Structures Div. 19819 84th Ave. S. Kent, WA 98031 | NM | | MPD 2-1100() Ser. MPD 2-2200() Ser. MPD 2-3300() Ser. MPD 2-5500() Ser. |
| TSO-C39a *F | Ipeco Europe Ltd. Southend-on-Sea, Essex England | EU | | OA005 0009 OA005 0010 OA006 005 OA006 0006 OA008 0013 OA008 0014 OA010 0005 OA010 0006 OA019 0005 OA019 0006 OA014 0007 OA003-0015 OA003-0016 OA020-007/008 OA028-0005 OA028-0006 OA029-0007/0008 OA032-0005/0006 OA035-0007/8 OA0033/34 OA035-0029/30 OA039-0003 OA041-0037/38 OA041-0045/46 OA044-0019/20 OA045-0031 OA046-0011/12 OA049-0065/6 OA049-0027/8 OA049-0071/2 OA053-0007/8 OA056-0007/8 OA058-0007/8 OA059-0007/8 OA061-0001/8 OA063-0049/50 OA063-0063/4 OA063-0083/84 OA064-001/12 OA066-0007/8() OA067-0011() OA068-0015 OA069-0041/2 OA069-0043/4 OA076-0005/6 OA077-0015 OA077-0017 OA079-0019/20 OA088-0009/10 OA089-0011/12 OA093-0001/2 OA094-0001/2 OA095-0001/2 OA097-0001/2 OA098-0001/2 1A026-0007, -008, -0015/16 1A042-0029 2A010-0013, -0014 |
| TSO-C39a *F | Japan Aerospace Co., Ltd. 1-2 Suehiro-cho Ome City, Tokyo, Japan | NM | | J9777 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|-----------|--|
| TSO-C39a | Jepson Burns Corp. Div. of Fairchild Ind.Inc. 1455 Fairchild Rd. Winston-Salem, NC 27105-4588 | CE-A | | 803-2-() 809-1() 839-3() 871-2() 873-3() 853-2() 853-3() 853-4() A853-3() A851-2() A853-2() C808-2() C853-1() C853-2() C853-3() C853-4() 855-1-() 855-2-() 855-3-() 855-4-() D793-1-() PC855-3-() 2020-3-() 2000BG\$-3-() 2000D-2-() 2020C-2-() 2000BG\$-2-() 2000D-3-() 2000BG&-1-() 2000D-4-() 2000UMDE-3-() 2000NG\$A-3-() 2000UHDF-3-() 2020D-1-() 2000UHDF-2-() 2020D-2-() 2000NG\$-4-() 2000NG\$D-3-() 2000NG\$D-2-() 2000UHDF-3-() D793-2-() D7933() D794-1() D794-2() E793-2() E793-3() E793-4() 786-1() 851-1-() 857-2-() A857-2-() 858-1-() A858-1-() 858-2-() A858-2-() 861-1-() 861-2-() 862-1-() 862-2-() BF669-2-() 770-1-() 864-2-() 770-2-() 770-3-() BF770-2-() D770-2-() D770-3-() B770-1() B770-2-() B 770-3-() BD770-2-() BD770-3-() F770-2-() 803-2-() 823-1-() B823-1-() 823-2-() B823-2-() FBC-2000-1-() FBC-2000-2-() FBC-2000-3-() FBC-2001-2-() 864-1-() 786-1 B786-1 A786-1 FBC-2000 FBC-2000A-2-() FBC-2000A-3-() FBC-2000B-2-() FBC-2000B-3-() FBC-2000-C-1-() FBC-2001-C-2-() FBC-2000M-3-62 FBC-2000M-2-42 FBC-2000UHD-1-() FBC-2000-UHD-3-() FBC-2000-UHDC3-() FBC-2000UHDE3-() FBC-2000-UHDC2-() FBC-2000-4-() FBC-2000UHD-4-() FBC-2000UHDE4-() FBC2823-2-() 2855-2-() 2855-3-() FBC-2000-UHD-2-() () FBC-2000UHDE2-() FBC-2000-UHDC-2-() FBC-2000-UHDA2-() FBC-2000-UHDC-3-() FBC-2000-UHDP-3-() FBC-2020-2-() FBC-2001-3-() JB5.0-2-() JB5.0-3-() PC855-3-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|--|---|---|
| TSO-C39a *F | Koito Industries, Ltd. 100, Maeda-cho, Totouka-ku Yokohama, Japan | NM | | ARS-189 ARS-255 ARS-289 ARS-276 ARS-311-A ARS-276:117-1320-414F,-421F,424F,431F, -434F,-439F 117-1322-401F,-411F,-421F,-426F 117-1324-421F,-424F,-425F,-428F,-429F 117-1325-401F,-404F 117-2932-401F ARS-311:145-3172-401F,-402F,-403F,-405F, 145-3173-401F,-402F,-403F,-404F 145-3174-401F | ARS-190 ARS-289 ARS-300 ARS-304 ARS-352 | ARS-242 ARS-276 ARS-301 ARS-311 ARS-357 |
| TSO-C39a *F | Koito Industries, Ltd. 8-3, 4-Chome, Takanawa, Minato-kee Tokyo, Japan | NM | | 83106-933-404 83106-933-404-1 ARS-254:83106-933-401 83106-933-401 83106-934-401 83106-934-401-1 ARS-255:83107-935-401-1,-2,-3,-4 83107-935-404-1,-2,-3,-4 83107-936-401-1,-2,-3,-4 83107-937-401-1,-2,-3,-4 83107-938-401-1,-2,-3,-4 83107-939-401-1,-2,-3,-4 83107-940-401-1,-2,-3,-4 83107-941-401-1,-2,-3,-4 CRB-366:175-4100-401 | | |
| TSO-C39a | Kosola & Associates, Inc. P.O. Box 3542 1302 W. Broad Avenue Albany, GA 31706 | CE-A | | Single seat S101(GA)-() Double seat D201() S201(GA)-() Three place D301() side facing divan | | |
| TSO-C39a | LVS Aircraft Co. 7281 NW. 77 Street Miami, FL 33166 | CE-A | | CS402-1 | CS402-2 | |
| TSO-C39a | Maney Aircraft Div. Macrodyne Industries, Inc. 3100 W. Segerstrom Ave. Santa Ana, CA 92704 | NM | | HA543P-() 20-200-() | 105346-() 20-300-() | 20-100-() 20-400-() |
| TSO-C39a | Mercer Seat Co., Inc. 510 S. Lansing Tulsa, OK 74120 | SW | | MC11 17301 | | |
| TSO-C39a *F | Messerschmitt-Bolkow-Blohm Hamburg, Germany | EU | | E-1-0-21-25147() E-3-0-57-25147() CE-3-0-18-25145() E-3-C-17-24243() E-3-0-19-25143() E-3-0-59-03527() FC-2-0-53-04527 | E-1-0-21-03527() CE-2-0-16-25149() E-2-0-15-25147() E-2-0-39-04527() E-3-0-58-04527() E-2-0-40-03527() | |
| TSO-C39a | Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406 | NM | | 50402 50408-100 | 50403-() | |
| TSO-C39a | Oro Manufacturing Co. | CE-A | | ACA-3902-9 | ACA-3903-11 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|----|-----------|---|
| | P. O. Box 479 Monroe, NC 28110 | | | |
| TSO-C39a | PTC Aerospace, Inc. Aerospace Division Route 202 Bantam, CT 06750 | NE | | 672-200()-3() 674()-3() 694-100()-2() 672-201()-3() 816()-3() 817()-2() 819()-2() 821()-3() 823()-3() 825()-2() 827()-2() 829()-2() 830-100()-3() 830-101()-3() 830-103()-3() 830-105()-2() 830-106()-3() 830-107()-3() 830-108()-3() 830-111()-3() 830-113()-3() 830-116()-2() 830-118()-3() 830-119()-3() 830-121()-2() 830-123()-2() 830-201()-3() 830-202()-3() 830-204()-2() 830-205()-3() 830-207()-2() 830-208()-3() 830-300()-3() 830-302()-2()A 830-302()-2() 831-100()-3() 831-101()-3() 831-103()-2() 831-104()-3() 831-105()-3() 831-107()-3() 831-109()-3() 831-111()-3() 831-120()-3() 831-200()-3() 831-400()-3() 831-401()-2() 831-401()-4() 831-403()-2() 831-500()-4() 831-501()-3() 831-502()-3() 841-100()-3() 850()-2() 850-102()-2() 850-104()-2() 850-106()-2() 850-108()-2() 850-200()-2() 850-202()-2() 850-204()-2() 850-206()-2() |
| | | | | 674()-2() 677BA-3L 694-102()-2() 694-101()-2() 816()-4() 818()-1() 820()-2() 822()-3() 824()-3() 826()-2() 828()-2() 830-100()-2() 830-100()-4() 830-102()-3() 830-104()-3() 830-106()-1(c) 830-107()-2() 830-107()-4() 830-111()-2() 830-112()-3() 830-115()-3L 830-117()-3() 830-119()-2() 830-120()-2() 830-122()-3() 830-200()-2R 830-201()-3() 830-203()-2() 830-204()-3() 830-206()-3() 830-207()-3() 830-300()-2() 830-301()-3()A 830-302()-1() 831-100()-2() 831-100()-4() 831-102()-3() 831-103()-3() 831-104()-2() 831-106()-2() 831-108()-3() 831-110()-3() 831-112()-3() 831-200()-2() 831-201()-3() 831-400()-4() 831-401()-3() 831-500()-2() 831-500()-5() 831-501()-4() 840()-2() 850-100()-2() 850-101()-2() 850-103()-2() 850-105()-2() 850-107()-2() 850-109()-2() 850-201()-2() 850-203()-2() 850-205()-2() 850-300()-2() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|------------------------|
| | | | | 850-301()-2() |
| | | | | 850-500()-2() |
| | | | | 850-502()-2() |
| | | | | 852-600A |
| | | | | 853-200()-3() |
| | | | | 853-201()-3() |
| | | | | 853-300()-1() |
| | | | | 853-300()-3R |
| | | | | 855-100()-1() |
| | | | | 856()-2() |
| | | | | 856-100()-2() |
| | | | | 856-500()-2() |
| | | | | 857-401()-2() |
| | | | | 860-200()-3() |
| | | | | 860-202()-3() |
| | | | | 860-204()-3() |
| | | | | 860-206()-3() |
| | | | | 860-300()-3() |
| | | | | 861-100()-3() |
| | | | | 861-101()-3() |
| | | | | 861-103()-3() |
| | | | | 861-200()-2() |
| | | | | 861-201()-2() |
| | | | | 861-202()-3() |
| | | | | 861-204()-3() |
| | | | | 861-205()-3() |
| | | | | 861-207()-3() |
| | | | | 861-208()-3()A |
| | | | | 861-211()-3() |
| | | | | 861-300()-3() |
| | | | | 861-301()-3() |
| | | | | 861-303()-3() |
| | | | | 861-500()-3() |
| | | | | 861-500()-5() |
| | | | | 861-700()-3() |
| | | | | 861-702()-3() |
| | | | | 861-704()-3() |
| | | | | 872-600()-4C |
| | | | | 879-100()-1() |
| | | | | 879-100()-2() |
| | | | | 879-101()-2() |
| | | | | 879-102()-2() |
| | | | | 879-103()-2() |
| | | | | 879-110()-3() |
| | | | | 879-111()-3() |
| | | | | 879-113()-2() |
| | | | | 880-200()-3() |
| | | | | 880-201()-3() |
| | | | | 880-202()-3() |
| | | | | 880-204()-3() |
| | | | | 880-206()-3() |
| | | | | 881-()-2() |
| | | | | 881-()-4() |
| | | | | 883()-2() |
| | | | | 900-100()-2C |
| | | | | 900-101()-2() |
| | | | | 900-102()-2() |
| | | | | 900-103()-3() |
| | | | | 900-200()-2() |
| | | | | 900-201()-3 |
| | | | | 900-400()-3() |
| | | | | 900-401()-3() |
| | | | | 900-701()-2() |
| | | | | 900-702()-3() |
| | | | | 900-700()-3() |
| | | | | 850-400()-2() |
| | | | | 850-501()-2() |
| | | | | 851-103()-1() |
| | | | | 853-200()-2() |
| | | | | 853-201()-2() |
| | | | | 853-202()-3() |
| | | | | 853-300()-2L |
| | | | | 853-301()-2() |
| | | | | 856()-1() |
| | | | | 856()-3() |
| | | | | 856-101()-2() |
| | | | | 857-400()-2() |
| | | | | 860-200()-2() |
| | | | | 860-201()-3() |
| | | | | 860-203()-3() |
| | | | | 860-205()-3() |
| | | | | 860-300()-2() |
| | | | | 861-100()-2() |
| | | | | 861-100()-4() |
| | | | | 861-102()-3() |
| | | | | 861-104()-3() |
| | | | | 861-200()-3() |
| | | | | 861-201()-3() |
| | | | | 861-203()-3() |
| | | | | 861-205()-2() |
| | | | | 861-206()-3() |
| | | | | 861-208()-2()A |
| | | | | 861-210()-2() |
| | | | | 861-300()-2() |
| | | | | 861-301()-2() |
| | | | | 861-302()-3() |
| | | | | 861-500()-2() |
| | | | | 861-500()-4() |
| | | | | 861-700()-2() |
| | | | | 861-701()-3() |
| | | | | 861-703()-3() |
| | | | | 871-600()-4C |
| | | | | 873-600()-2() |
| | | | | 874-600()-3() |
| | | | | 879-100()-3() |
| | | | | 879-101()-3() |
| | | | | 879-102()-3() |
| | | | | 879-110()-2() |
| | | | | 879-110()-4() |
| | | | | 879-112()-3() |
| | | | | 880-200()-2() |
| | | | | 880-201()-2() |
| | | | | 880-202()-2() |
| | | | | 880-203()-3() |
| | | | | 880-205()-3() |
| | | | | 880-207()-3() |
| | | | | 881-()-3() |
| | | | | 881-()-5() |
| | | | | 885()-2() |
| | | | | 900-100()-3C |
| | | | | 900-101()-3() |
| | | | | 900-102()-3() |
| | | | | 900-104()-3() |
| | | | | 900-200()-3() |
| | | | | 900-400()-2() |
| | | | | 900-401()-2() |
| | | | | 900-402()-2() |
| | | | | 900-701()-3() |
| | | | | 900-700()-2() |
| | | | | 901()-1() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|----|-----------|--|--------------|---------------|
| | | | | 901()-2() | 901()-3() | |
| | | | | 901()-4() | 901()-5() | |
| | | | | 910()-1() | 910()-2() | |
| | | | | 910()-2()A | 910()-4() | |
| | | | | 911()-5() | 911()-3() | |
| | | | | 911()-2() | 912()-1() | |
| | | | | 912()-2() | 912-()-3() | |
| | | | | 912()-5() | 920()-3() | |
| | | | | 920()-2() | 940()-2() | |
| | | | | 1006 | | |
| | | | | Type I, Forward: Facing triple passenger seat. | | |
| TSO-C39a | PTC Aerospace Hardman Operations 11752 Markon Drive Garden Grove, CA 92641 | NM | | 831() | 850() | 857() |
| | | | | 875() | 881() | 850()-2() |
| | | | | 901() | 910() | 911() |
| | | | | 9777() | 9778() | 9780() |
| | | | | 940() | 940()-2() | 9781() |
| | | | | 9785() | 901()-5() | 920()-3() |
| | | | | 920()-2() | 910()-2() | A881-()-2() |
| | | | | 881-()-3() | | |
| TSO-C39a | PTC Aerospace Route 202 Bentam, CT 06750 | NE | | 910()-1(), -2() | | |
| TSO-C39a *F | Recara-Aircomfort Postfach 100306 7170 Schwabisch Hall Germany | EU | | 3210-1-1 | 3210-2-1 | 3210-2-2 |
| | | | | 3210-2-3 | 3210-3-1 | 3210-3-2 |
| | | | | 3210-4-1 | 132-E-056 | |
| TSO-C39a *F | RECARD GmbH & Co. 73 Stuttgart Street 7312 Kirchheim-T West Germany | EU | | 9777RA-1 | 9777RA-2 | 9777RA-3 |
| | | | | 9777RA-4 | 1010-2 | 1010-3 |
| | | | | 1010-4 | 1030-2 | 1030-3 |
| | | | | 2010-2 | 2020-2 | 3010-2 |
| | | | | 3010-3 | 3010-1-1 | 3010-4-1 |
| | | | | 3010-4-2 | 4010-2 | 4010-3-1 |
| | | | | 5010-2-1 | | |
| TSO-C39a | Riley Turbostream Corp. P.O. Box 5247 Waco, TX 76708 | SW | | 6501-1 | 6501-2 | 6502-2 |
| | | | | 6503-1 | 6504-1 | |
| TSO-C39a | Rockwell International Sabreliner Division 827 Lapham Street El Segundo, CA 90245 | NM | | 282-530110-() Series | | |
| TSO-C39a | Ro-Tech Industries - WITHDRAWN 10/30/89 Commercial Air Services Gardena, CA 90248 | | | | | |
| TSO-C39a | John B. Rudy Co. 20950 Brant Ave. Long Beach, CA 90810 SEE Also AiResearch Aviation | NM | | 50-() | 51-() | |
| TSO-C39a *F | L. A. Rumbold Ltd. Old Oak Common Lane London N.W. 10 6DX England | EU | | M1371() thru | M1382() | |
| | | | | M1390 | M1395() | |
| | | | | M1391() thru | M1394() | |
| | | | | M1396() | M1397() | |
| | | | | M1398() | M1431() | |
| | | | | M1413() thru | M1416() | |
| | | | | M1460 thru | M1466() | |
| | | | | M1500 | M.15113() | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|----------------------------------|
| | | | | M.15114() |
| | | | | M1555() thru M1558() |
| | | | | M1561() thru M1567() M1570() |
| | | | | M1593() thru M1599() M15100() |
| | | | | M15103 thru M15106 |
| | | | | M1600() M1631() M1632() |
| | | | | M1637() M1645() M1646() |
| | | | | M1651() thru M1654() M1655() |
| | | | | M1656() |
| | | | | M1671() thru M1678() |
| | | | | M.1683() thru M.1692() M1700 |
| | | | | M1700() |
| | | | | M1705() thru M1730() |
| | | | | M1741() thru M1758() |
| | | | | M1765() M1766() M1769() |
| | | | | M1777() M1778() M1779() |
| | | | | M1780() M1781() M1782() |
| | | | | M1783() M1784() M1785() |
| | | | | M1786() M1787() M1788() |
| | | | | M1789() M1790() M1797() |
| | | | | M1795() M1796() M1798() |
| | | | | M1800 M1810() |
| | | | | M1821() thru M1823() M1825() |
| | | | | M1827() thru M1842() |
| | | | | M1843() M1844() M1845() |
| | | | | M1846() M1847() M1848() |
| | | | | M1849() M1850() M1851() |
| | | | | M1852() M1909() M1910() |
| | | | | M1951 M1952 M1955 |
| | | | | M1956 M1961 M1962 |
| | | | | M1963 M1964 M1965 |
| | | | | M1966 M1967 M1968 |
| | | | | M2100 |
| | | | | M2101() thru M2108() |
| | | | | M2111() M2112() M2200() |
| | | | | M2205() M2206() M2209() |
| | | | | M2210() M2213() M2214() |
| | | | | M2215() M2216() M2217() |
| | | | | M2218() M2219() M2220() |
| | | | | M2221() M2222() M2500 |
| | | | | M2501() M2509() M2510() |
| | | | | M2511() M2512() M2525() |
| | | | | M2527() M2528() M2529() |
| | | | | M2531() M2700 M2701() |
| | | | | M2555() M2557() M2700 |
| | | | | M2729() M2730() M2797() |
| | | | | M2798() M2795() M2796() |
| | | | | M2711() M2712() M2713() |
| | | | | M2714() M2715 M2716 |
| | | | | M2717 M2718 M2719 |
| | | | | M2720 M2721() M2722() |
| | | | | M2723() M2724() M2727() |
| | | | | M2728() M2731() M2732() |
| | | | | M2743 M2744 M2745 |
| | | | | M2746 M3721 M3724 |
| | | | | M3748 M3765 M3766 |
| | | | | M3700 M3747() M3779() |
| | | | | M3780() M3781() M3782() |
| | | | | M3777 M3778 M3784 |
| | | | | M7000() M7001() M7002() |
| | | | | M7005() M7006() M7007() |
| | | | | M7008() M7009() M7011() |
| | | | | M7012() M7013() M7014() |
| | | | | M7015() M7016() M7019() |
| | | | | M7020() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|-------------------------------|
| | | | | M7021.001, 002 and 003 |
| | | | | M7022.001, 002 and 003 |
| | | | | M7023.001, 002 |
| | | | | M7025() M7026() M7027() |
| | | | | M7028() M7043() M7044() |
| | | | | M7091() M7092() M7093() |
| | | | | M7094() M7095() M7096() |
| | | | | M7097() M7098() M7131 |
| | | | | M7132 M7133 M7135 |
| | | | | M7136 M7137 M7139 |
| | | | | M7140 M7141 M7142 |
| | | | | M7143 M7144 M7145 |
| | | | | M7146 M7147 M7148 |
| | | | | M7150 M7183 M7185 |
| | | | | M7186 M7187 M7188 |
| | | | | M7203() M7204() M7205() |
| | | | | M7206() M7207() M7208() |
| | | | | M7209() M7210() M7212() |
| | | | | M7214() M7215() M7216() |
| | | | | M7217() M7219() M7220() |
| | | | | M7221() M7241() M7265() |
| | | | | M7266() M7267() M7268() |
| | | | | M7274() M7287() M7288() |
| | | | | M8033() M7291() M7292() |
| | | | | M8034() M7303() M7304() |
| | | | | M7339() M7340() M7341() |
| | | | | M7353() M7354() M7355() |
| | | | | M7357() M7358() M7359() |
| | | | | M7361() M7362() M7367() |
| | | | | M7368() M7369() M7342() |
| | | | | M7343() M7344() M7348() |
| | | | | M7345() M7346() M7350() |
| | | | | M7363() M7364() M7365() |
| | | | | M7366() M7367() M7368() |
| | | | | M7369() M7371() M7372() |
| | | | | M7373() M7374() M7377() |
| | | | | M7378() M7379() M7381() |
| | | | | M7387() M7388() M7375-001 |
| | | | | M7383-001 M7385-001 M7389-001 |
| | | | | M7413() M7414() M7419() |
| | | | | M7420() M7421() M7422() |
| | | | | M7422() M7423() M7424() |
| | | | | M7425() M7429() M7463() |
| | | | | M7464() M7485() M7486() |
| | | | | M7487() M7489() M7491() |
| | | | | M7495() M7498() M7500() |
| | | | | M7502() M7506() M8000 Ser. |
| | | | | M8001() M8002() M8003() |
| | | | | M8004() M8021() M8022() |
| | | | | M8033() M8034() M8035() |
| | | | | M8036() M8039() M8040() |
| | | | | M8041() M8042() M8043() |
| | | | | M8044() M8045() M8046() |
| | | | | M8047() M8048() M8049() |
| | | | | M8050() M8171() M8173() |
| | | | | M8174() M8175() M8176() |
| | | | | M8177() M8179() M8180() |
| | | | | M8181() M8182() M8183() |
| | | | | M8184() M15100() |
| | | | | M15103 thru M15106 |
| | | | | M15119() M15120() M15121 |
| | | | | M15123 M15124 M17107() |
| | | | | M17108() M17109() M17110() |
| | | | | M17113() M17114() M17315() |
| | | | | M17316() M17321() M17322() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|-----------|-------------------------|----------------------|------------|
| | | | | M17324() | M17326() | M17347() |
| | | | | M17348() | M17500 | M17481() |
| | | | | M17482() | M17483() | M17484() |
| | | | | M17485() | M17486() | M17501() |
| | | | | M17502() | M17503() | M17504() |
| | | | | M17505() | M17507() | M17509() |
| | | | | M17510() | M17511() | M17512() |
| TSO-C39a | Sabena Technics | EU | | 1-9115-00-00 | | |
| *F | Brussels National Airport B-1930 Zaventem Belgium | | | | | |
| TSO-C39a | Sermi Aero | EU | | 298(XXXX)(XXX)(XXX)(XX) | | |
| *F | Aeroport Bordeaux Merignac Cedex 46 33700 Merignac, France | | | 300(XXXX)(XXX)(XXX)(XX) | | |
| | | | | 600(XXXX)(XXX)(XXX)(XX) | | |
| TSO-C39a | Sicma America, Inc. | CE-A | | America 600 Series | | |
| | 6929 NW 46th Street Miami, FL 33166 | | | Mark II | 421-() | 423-20-() |
| | | | | 422 | 424 | |
| | | | | 423-30-() | 424-10-() | |
| TSO-C39a | Sicma Canada, Ltd. | NE | | 386 | 386-1 | 386-() |
| *F | 2400 Guenette Street Ville Saint-Laurent Quebec H4R 2H2, Canada | | | | | |
| TSO-C39a | (S.I.C.M.A.) | EU | | 937 | 937-1 | 937-2 |
| *F | Societe Industrielle et Commerciale de Materiel Aeronautique 7 Avenue Bugeaud 75116 Paris, France | | | 937-3 | 937-10 | 937-11 |
| | | | | 937-20 | 937-20D | 937-20G |
| | | | | 937-21 | 937-21D | 937-21G |
| | | | | 937-22 | 937-23 | 937-30 |
| | | | | 937-30D | 937-30G | 937-31 |
| | | | | 937-31D | 937-31G | 937-32 |
| | | | | 937-33 | 937-34 | 937-35 |
| | | | | 937-36 | 937-37 | 937-38 |
| | | | | 937-39 | 937-40 | 937-41 |
| | | | | 937-42 | 937-43 | 937-44 |
| | | | | 937-45 | 937-46 | 937-48 |
| | | | | 937-49 | 937-50 | 937-51 |
| | | | | 937-57 | 937-60 | 937-61 |
| | | | | 937-62 | 937-63 | 937-70 |
| | | | | 937-71 | 937-70M1 | 937-71M1 |
| | | | | 937-75 | 937-80 | 937-81 |
| | | | | 937-82 | 937-84 | 937-90 |
| | | | | 937-91 | 937-101 | 937-102 |
| | | | | 937-103 | 937-104 | 999 |
| | | | | 999-1D | 999-1G | 999-10D |
| | | | | 999-10G | 999-20D | 999-20G |
| | | | | 999-30 | 999-31 | RE999 |
| | | | | 002561 | | |
| | | | | Z 13.102 () () () | Z 23.102 () () () | |
| | | | | Z 23.201 () () () | Z 23.202 () () () | |
| | | | | Z 23.301 () () () | Z 23.302 () () () | |
| | | | | Z 23.401 () () () | Z 23.402 () () () | |
| | | | | Z 23.501 () () () | Z 23.502 () () () | |
| | | | | Z 23.602 () () () | Z 23.701 () () () | |
| | | | | Z 23.702 () () () | Z 23.801 () () () | |
| | | | | Z 23.802 () () () | Z 23.902 () () () | |
| | | | | Z 23.1002 () () () | Z 33.101 () () () | |
| | | | | Z 33.102 () () () | Z 33.201 () () () | |
| | | | | Z 33.202 () () () | Z 33.302 () () () | |
| | | | | Z 33.402 () () () | Z 33.502 () () () | |
| | | | | Z 33.602 () () () | F13 100 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|--------------------|-----------------------|----|--------------------|------------------------|
| 20 101 1375 | () () () | | | |
| 20 102 0570 | () () () | | | |
| 20 105 0173 | () () () | | | |
| 20 105 0270 | () () () | | | |
| 20 105 0367 | () () () | | | |
| 20 105 0464 | () () () | | | |
| 20 105 0561 | () () () | | | |
| 20 105 0658 | () () () | | | |
| 20 105 0755 | () () () | | | |
| 20 105 1266 | () () () | | | |
| 20 105 1169 | () () () | | | |
| 20 105 1363 | () () () | | | |
| 20 105 1460 | () () () | | | |
| 20 105 1557 | () () () | | | |
| 20 105 1654 | () () () | | | |
| 20 106 0170 | () () () | | | |
| 20 106 0267 | () () () | | | |
| 20 106 0364 | () () () | | | |
| 20 106 0461 | () () () | | | |
| 20 106 0558 | () () () | | | |
| 20 106 0655 | () () () | | | |
| 20-106-1360 | () () () | | | |
| 20 106 1457 | () () () | | | |
| 20-106-1554 | () () () | | | |
| 20-106-1651 | () () () | | | |
| 20 1000 188-1 | () () () | | | |
| 20 1000 188-2 | () () () | | | |
| 20 1000 285-1 | () () () | | | |
| 20 1000 285-2 | () () () | | | |
| 20 1000 382-1 | () () () | | | |
| 20 1000 382-2 | () () () | | | |
| 20 1000 479-1 | () () () | | | |
| 20 1000 479-2 | () () () | | | |
| 20 1000 576-1 | () () () | | | |
| 20 1000 576-2 | () () () | | | |
| 20 1000 673-1 | () () () | | | |
| 20 1000 673-2 | () () () | | | |
| 20 1001 184-2 | () () () | | | |
| 20 1001 281-2 | () () () | | | |
| 20 1030 179 | | | 20 1030 276 | |
| 20 1030 373 | | | 20 1030 470 | |
| 20 1030 567 | | | 20 1030 664 | |
| 20 1031 175 | | | 20 1031 273 | |
| 20 1040 176 | | | 20 1040 273 | |
| 20 1040 370 | | | 20 1040 467 | |
| 20 2000 864 | () () () | | | |
| 20 2000 961 | () () () | | | |
| 20 2001 084 | () () () | | | |
| F23 100 | | | F23 200 | F23 400 |
| F23 500 | | | 340 | |
| C25 () () () | | | 41()2() () () | |
| 61() 4() () () | | | 63()1() () () | |
| 63()3() () () | | | 67() 6() () () | |
| 68() 1() () () | | | 68() 2() () () | |
| 68() 3() () () | | | 69()6() () () | |
| 70()2() () () | | | 70()3() () () | |
| 71()1() () () | | | 71()2() () () | |
| 71()3() () () | | | 71()4() () () | |
| 71()8() () () | | | 73()2() () () | |
| 73()3() () () | | | 74()7() () () | |
| 75()2() () () | | | 76()1() () () | |
| 76()2() () () | | | 77()2() () () | |
| 77()3() () () | | | 103() () () | |
| 104() () () | | | 111() () () | |
| 112() () () | | | 113() () () | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|------------------------|
| | | | | 114()()() |
| | | | | 115()()() |
| | | | | 116()()() |
| | | | | 117()()() |
| | | | | 120()()() |
| | | | | 121()()() |
| | | | | 122()()() |
| | | | | 123()()() |
| | | | | 125()()() |
| | | | | 128()()() |
| | | | | 129()()() |
| | | | | 132()()() |
| | | | | 340-20() |
| | | | | 340-21() |
| | | | | 340-22() |
| | | | | 340-23() |
| | | | | 340-24() |
| | | | | 340-25() |
| | | | | 340-26() |
| | | | | 340-27() |
| | | | | 340-28() |
| | | | | 340-29() |
| | | | | 340-30() |
| | | | | 340-31() |
| | | | | 340-32() |
| | | | | 340-33() |
| | | | | 340-34() |
| | | | | 340-35() |
| | | | | 340-36() |
| | | | | 340-37() |
| | | | | 340-38() |
| | | | | 340-39() |
| | | | | 340-40() |
| | | | | 340-41() |
| | | | | 340-42() |
| | | | | 340-43() |
| | | | | 340-44() |
| | | | | 340-45() |
| | | | | 340-50() |
| | | | | 340-51() |
| | | | | 340-52() |
| | | | | 340-53() |
| | | | | 340-54() |
| | | | | 340-55() |
| | | | | 340-56() |
| | | | | 340-57() |
| | | | | 340-58() |
| | | | | 340-59() |
| | | | | 340-60() |
| | | | | 340-80() |
| | | | | 340-81() |
| | | | | 340-82() |
| | | | | 340-83() |
| | | | | 340-84() |
| | | | | 340-85() |
| | | | | 340-86() |
| | | | | 340-87() |
| | | | | 340-88() |
| | | | | 340-89() |
| | | | | 340-90() |
| | | | | 340-91() |
| | | | | 340-92() |
| | | | | 340-93() |
| | | | | 340-94() |
| | | | | 340-95() |
| | | | | 340-96() |
| | | | | 340-97() |
| | | | | 340-98() |
| | | | | 340-99() |
| | | | | 340-100() |
| | | | | 340-101() |
| | | | | 340-102() |
| | | | | 340-103() |
| | | | | 377-51() |
| | | | | 377-52() |
| | | | | 377-53() |
| | | | | 377-54() |
| | | | | 386()()() |
| | | | | 394-1()()() |
| | | | | 394-2()()() |
| | | | | 394-10 |
| | | | | 394-20 |
| | | | | 396()()() |
| | | | | 397.51() |
| | | | | 397.61() |
| | | | | 398.51() |
| | | | | 398.61() |
| | | | | 401()()() |
| | | | | 407 10() |
| | | | | 407 11() |
| | | | | 407 20() |
| | | | | 407 21() |
| | | | | 407 30() |
| | | | | 407 31() |
| | | | | 412-10() |
| | | | | 412-11() |
| | | | | 412-12() |
| | | | | 412-13() |
| | | | | 412-14() |
| | | | | 412-15() |
| | | | | 412-16() |
| | | | | 412-17() |
| | | | | 412-70() |
| | | | | 413-10()()() |
| | | | | 413-11()()() |
| | | | | 413-12()()() |
| | | | | 413-13()()() |
| | | | | 413-16()()() |
| | | | | 413.20()() |
| | | | | 413.21()() |
| | | | | 416.20 |
| | | | | 418-10 |
| | | | | 422-20()()() |
| | | | | 421()()() |
| | | | | 433()()() |
| | | | | 423()()() |
| | | | | 424()()() |
| | | | | 502.10() |
| | | | | 502.11() |
| | | | | 502-20() |
| | | | | 502-21() |
| | | | | 502-22() |
| | | | | 502-23() |
| | | | | 502-24() |
| | | | | 502-25() |
| | | | | 502-26() |
| | | | | 502-27() |
| | | | | 502-28() |
| | | | | 502-29() |
| | | | | 502-30() |
| | | | | 502-31() |
| | | | | 502-50() |
| | | | | 502-51() |
| | | | | 502-52() |
| | | | | 502-53() |
| | | | | 502-54() |
| | | | | 502-55() |
| | | | | 502-56() |
| | | | | 502-57() |
| | | | | 502-60() |
| | | | | 502-61() |
| | | | | 502-62() |
| | | | | 502-63() |
| | | | | 502-64() |
| | | | | 502-65() |
| | | | | SINGLE SEAT |
| | | | | 502.A-1028 |
| | | | | 60()1()()() |
| | | | | DOUBLE SEAT |
| | | | | 502.A-201() |
| | | | | 502.A-205() |
| | | | | 502.A-209() |
| | | | | 502.A-211() |
| | | | | 502.A-215() |
| | | | | 502.A-219() |
| | | | | 502.A-502() |
| | | | | 502.A-512() |
| | | | | 502.A-2018() |
| | | | | 502.A-2059() |
| | | | | 502.A-5128() |
| | | | | 502.A-5298() |
| | | | | 60()2()()() |
| | | | | TRIPLE SEAT |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|----|-----------|---|
| | | | | 502.A-301() 502.A-305() 502.A-311() 502.A-315() 502.A-602() 502.A-605() 502.A-612() 502.A-615() 502.A-700() 502.A-712() 502.A-3019() 502.A-3051() 502.A-3052() 502.A-3059() 502.A-3119() 502.A-3151() 502.A-3152() 502.A-3159() 502.A-3209() 502.A-3219() 502.A-6025() 502.A-6125() 502.A-6228() 60()3() () () 55()2() () () 60()4() () () 61()1() () () 61()3() () () 62()2() () () 62()3() () () 63()2() () 63() 2() () () 64()2() () () 64()3() () 66() 2() () () 66() 3() () () |
| TSO-C39a *F | (S.O.C.E.A.) Groupe Aerospetiale Ancien Arsenal - B.P. 110 17303 Rochefort-sur-Mer France | EU | | 2520 107() () () 2520 108() () () 2520 109() () () 2520 110() () 2520 111() () 2520112() () 2520-115() () 2520-118() () 2520 137() () 2520 144() () 2520 198(XXXX)(XX) 2520 198(XX)(XXX)(XX) 2520 149(XXXX)(XX) 2520 150(XXXX)(XX) 213-100 223-100 thru 223-1000 233-100 thru 233-600 |
| TSO-C39a *F | SONACA S.A. Route Nationale 5 B-6200 Gosselies Belgium | EU | | FBCA-2000-1() FBCA-2000-2() FBCA-2000-3() FBCA-2000-4() FBCA-2000 UHD-2-() FBCA-2000 UHD-3-() FBCA-2000 UHD-4-() FBCA-2001-2-() |
| TSO-C39a | Spinks Industries, Inc. P.O. Box 11099 Fort Worth, TX 76110 | SW | | AL 1018-00-00 |
| TSO-C39a *F | Teleflex Morse, Ltd. Basildon, Essex England | EU | | E.179760 E.179761 183740 183741 187931 188099 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|----|-----------|--|
| TSO-C39a *F | Tenryu Industries Co., Ltd. 4-1, Sahara-Koa-Cho Kakamigahara City Gifu Prefecture, Japan | NM | | TB751-2:9752-1, -1P, -3 TB751-3:9753-1, -1P, -1S, -2, -2P, -2S, -3, -4, -6, -8, -10, -11, -12, -13, -14 TB752-2:9754-11 TB752-3:975-5, -22 TB754-2:59005-3-() TB771-2 TB755:9758-1, -1S, -2, -2S, -3, -4, 9759-1, -4, -5, -6 TB771-3 TB780-2:9732-4M, -12M TB780-3:9733-1M, -4M, -7M TB781-1:9746-1, -2 TB781-2:9747-1, -2, -11, -12, -21, -22, -31, -32, -51, -52 TB781-3:9748-1 TB782-2:9749-1, -2, -11, -12 TB782-2:9750-1, -2 TB880-2:9832-101, -102, -1M, -3M, -4M 740:9740-1M, -2M 9012:9012-101, -102, -101B, -102B, -111, -112 9740-11, -12 |
| TSO-C39a | Tosington Enterprises, Inc. 2261 Madera Road Simi Valley, CA 93065 | NM | | T100()() T115()() T120()() T125()() T135()() T140()() T145()() T150()() T155()() T160-()-() T165-()-() T170-()-() T175-()() T180-()-() T185-()-() T190-()() T195-()() T200()() T215()() T220()() T225()() T230-()-() T235()() T240-()-() T240(40)() T245()() T250()() T255()() T260()() T265()() T270-()-() T280-()-() T285-()-() T300()() T295-()-() T305()-() T315()() T320()() T330()() T335()() T340()() T345()() T350()() T355()() T365()() T370-()-() T380-()-() T385-()-() T390-()-() T395-()() T400()() T405()() T410()() T415()() T420()() T425()() T430()() T435()() T440-()-() T445()() T450()() T455()() T460()() T465()() T470-()-() T480-()() T505-()-() T490-()-() T500-(5)-() T1005()() T1020()() T1025()() T1030()() T1045()() T1055()() T1060-()-() T1060(L)() T1065()() T1075()() T1100()() T1110()() T1115-()-() T1105()() T1120()() T1125()() T1135()() T1140()() T1150(L)() T1150()() T1160()() T1190()() T1175()() T1180()() T1195-()-() T1200()() T1215()() T1225-()-() T1230()() T1240()() T1250-()() T1265-()() T1275-()() T1280-()() T1260(L)() T1270()() T1285-()-() T1290()() T1295-()-() T1300-()-() T1305()() T1310-()-() T1315-()-() T1320()() T1330-()-() T1335-()-() T1340()() T1345-()-() T2000-()-() T2010()() T2015()() T2040-()-() T2025()() T2050-()() T2060()() T2065()() T2075-()() T2100-()-() T2130()() T2160-()-() T2150-()() T2180-()() T2170-()-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|---|
| | | | | T2175-()-() T2270()() T3015-()() T3025()() T3040-()() T3100-()() T2165-()-() T3005()() T3025-()-() T3020-()-() T3050()() T3055-()-() T3060-()-() T3065()() T3070-()-() T3090-()-() T3655()() T4000()() T4005()() T4010()() T4025-()-() T4055-()-() T4030()() T4060-()-() T4065-()-() |
| TSO-C39a | Tracor Custom Products P.O. Box 1141 Mooresville, NC 28115 | CE-A | | 13108-() 10580()() |
| TSO-C39a | Trans-Aero Industries 12641 Beatrice St. Airport Marina Center Los Angeles, CA 90066 | NM | | 1776 1776A 1836 1877 1878 1879 1880 1881 1882 1883 2301-1 2305-1 1885 1886 1888 2301-1 2302-1 1889 2000 2301-1D 1900 1201-8 1201-9 1201-11 1201-13 1209-08 1209-17 1209-19 2303-1 2305-1 2305-1A 2305-3 2401-6 2401-7 2402-2 2601-4 2501-1 2509-1 2509-4 2503-20 2503-21 2601-1 2701 5000 6000 |
| TSO-C39a *F | Transport Canada Centennial Towers, 7th Floor 200 Kent Street Ottawa, Ontario Canada K1A 0N8 | NE | | 412 413 402-() |
| TSO-C39a | Ventura Manufacturing Co. P.O. Box 37367 San Antonio, TX 78237 | SW | | 158-0000-101 159-0000-101 472 473 481 482 482F 483 483F 180-000-1 182-0000-1 189-000-1 189-000-2 161-0000-101 |
| TSO-C39a | Weber Aircraft 2000 Weber Drive Gainsville, TX 76240 | SW | | 4001-2() 4001-3() 4001-4() 4001-5() 835542() 829818() |
| TSO-C39a | Weber Aircraft Special Products Division 1300 East Valencia Dr. Fullerton, CA 92631 | NM | | 001-205-3 001-206-3 001-207-3 001-208-3 001-209-3 001-210-3 001-211-3 001-212-3 001-214-3 001-700-3 001-701-2 16738-401 808737() 811369() 811370() 811372() 815827() 815829() 815830() 815831() 815832() 816138() 817471() 817472() 817473() 817474() 817475() 818350() 818357() 818390() 818391() 818392() 818393() 818401() 818402() 818403() 818405() 818472() 818473() 818474() 818475() 819230() 819232() 819291() 819492() 819493() 819494() 819550() 819812() 819813() 819871() 819872() 819873() 819900() 820030() 820080() 820081() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|------------------------|
| | | | | 820082() |
| | | | | 820192() |
| | | | | 820203() |
| | | | | 820253-403 |
| | | | | 820253-409 |
| | | | | 820253-410() |
| | | | | 820253-411 |
| | | | | 820263() |
| | | | | 820299-403 |
| | | | | 820703-() |
| | | | | 821463() |
| | | | | 821899() |
| | | | | 822073() |
| | | | | 822272() |
| | | | | 822302() |
| | | | | 822343() |
| | | | | 822353() |
| | | | | 822438() |
| | | | | 822444() |
| | | | | 822580() |
| | | | | 822732-() |
| | | | | 822742-() |
| | | | | 822812M() |
| | | | | 823120() |
| | | | | 823358() |
| | | | | 823484() |
| | | | | 823672() |
| | | | | 823675() |
| | | | | 823880() |
| | | | | 823884() |
| | | | | 824059-401 |
| | | | | 824093() |
| | | | | 824100() |
| | | | | 824103() |
| | | | | 824250() |
| | | | | 824945() |
| | | | | 824985() |
| | | | | 826342() |
| | | | | 826366() |
| | | | | 826612() |
| | | | | 826620() |
| | | | | 826623() |
| | | | | 826643() |
| | | | | 826650() |
| | | | | 826653() |
| | | | | 827092() |
| | | | | 827110() |
| | | | | 827163() |
| | | | | 827193() |
| | | | | 827502-() |
| | | | | 827513-() |
| | | | | 827533-() |
| | | | | 828573-() |
| | | | | 828576-() |
| | | | | 828633-() |
| | | | | 828690() |
| | | | | 828862-() |
| | | | | 828872-() |
| | | | | 828883-() |
| | | | | 828893-() |
| | | | | 829402() |
| | | | | 829430() |
| | | | | 829441() |
| | | | | 829453() |
| | | | | 829472() |
| | | | | 820083() |
| | | | | 820193() |
| | | | | 820252() |
| | | | | 820253-405 |
| | | | | 820253-409() |
| | | | | 820253-410 |
| | | | | 820253-413 |
| | | | | 820264() |
| | | | | 820700-401 |
| | | | | 820704-() |
| | | | | 821897() |
| | | | | 821900() |
| | | | | 822123() |
| | | | | 822273() |
| | | | | 822303() |
| | | | | 822351() |
| | | | | 822424() |
| | | | | 822442() |
| | | | | 822475-() |
| | | | | 822595() |
| | | | | 822733-() |
| | | | | 822743-() |
| | | | | 822813() |
| | | | | 823150() |
| | | | | 823359() |
| | | | | 823485() |
| | | | | 823673() |
| | | | | 823851() |
| | | | | 823881() |
| | | | | 823950() |
| | | | | 824082-() |
| | | | | 824094() |
| | | | | 824101() |
| | | | | 824127() |
| | | | | 824251() |
| | | | | 824975() |
| | | | | 826300() |
| | | | | 826343() |
| | | | | 826602() |
| | | | | 826613() |
| | | | | 826621() |
| | | | | 826624() |
| | | | | 826644() |
| | | | | 826651() |
| | | | | 827082() |
| | | | | 827102() |
| | | | | 827111() |
| | | | | 827182() |
| | | | | 827472-() |
| | | | | 827503-() |
| | | | | 827522-() |
| | | | | 827757() |
| | | | | 828574-() |
| | | | | 828577-() |
| | | | | 828682-() |
| | | | | 828698() |
| | | | | 828867-() |
| | | | | 828873-() |
| | | | | 828891-() |
| | | | | 828894-() |
| | | | | 829403() |
| | | | | 829432() |
| | | | | 829442() |
| | | | | 829454() |
| | | | | 829473() |
| | | | | 820191() |
| | | | | 820202() |
| | | | | 820253-401 |
| | | | | 820253-407 |
| | | | | 820262() |
| | | | | 820299-401 |
| | | | | 820702-() |
| | | | | 821462() |
| | | | | 821898() |
| | | | | 822011-() |
| | | | | 822169() |
| | | | | 822283() |
| | | | | 822342() |
| | | | | 822352() |
| | | | | 822437() |
| | | | | 822443() |
| | | | | 822476-() |
| | | | | 822596() |
| | | | | 822741-() |
| | | | | 822812() |
| | | | | 822813M() |
| | | | | 823357() |
| | | | | 823482() |
| | | | | 823516-401 |
| | | | | 823674() |
| | | | | 823879() |
| | | | | 823882() |
| | | | | 823972() |
| | | | | 824092() |
| | | | | 824099() |
| | | | | 824102() |
| | | | | 824128() |
| | | | | 824252() |
| | | | | 824984() |
| | | | | 826301() |
| | | | | 826344() |
| | | | | 826603() |
| | | | | 826614() |
| | | | | 826622() |
| | | | | 826642() |
| | | | | 826645() |
| | | | | 826652() |
| | | | | 827083() |
| | | | | 827103() |
| | | | | 827162() |
| | | | | 827192() |
| | | | | 827480-() |
| | | | | 827512-() |
| | | | | 827523() |
| | | | | 828572-() |
| | | | | 828575-() |
| | | | | 828632-() |
| | | | | 828683() |
| | | | | 828861-() |
| | | | | 828868-() |
| | | | | 828882-() |
| | | | | 828892-() |
| | | | | 828895-() |
| | | | | 829404() |
| | | | | 829440() |
| | | | | 829452() |
| | | | | 829460-() |
| | | | | 829482() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|------------------------|
| | | | | 829483() |
| | | | | 829523-() |
| | | | | 829552() |
| | | | | 829556-() |
| | | | | 829641-() |
| | | | | 829632-() |
| | | | | 829635-() |
| | | | | 829766-() |
| | | | | 829817-() |
| | | | | 829880-() |
| | | | | 829913-() |
| | | | | 829922-() |
| | | | | 829851-() |
| | | | | 830002-() |
| | | | | 830007-() |
| | | | | 830058-() |
| | | | | 830152-() |
| | | | | 830160-() |
| | | | | 830164-() |
| | | | | 830182-() |
| | | | | 830252-() |
| | | | | 830272-() |
| | | | | 830275-() |
| | | | | 830312-() |
| | | | | 830332-() |
| | | | | 830422-() |
| | | | | 830443-() |
| | | | | 830473-() |
| | | | | 830492-() |
| | | | | 830503-() |
| | | | | 830512-() |
| | | | | 830542-() |
| | | | | 830553-() |
| | | | | 830584-() |
| | | | | 832200-() |
| | | | | 830682-() |
| | | | | 830702-() |
| | | | | 830663-() |
| | | | | 830833-() |
| | | | | 830842-() |
| | | | | 830845-() |
| | | | | 830672-() |
| | | | | 830711-() |
| | | | | 830751-() |
| | | | | 830763-() |
| | | | | 830766-() |
| | | | | 830862-() |
| | | | | 830903-() |
| | | | | 830906-() |
| | | | | 830924-() |
| | | | | 830972-() |
| | | | | 830992-() |
| | | | | 830995-() |
| | | | | 832952-() |
| | | | | 833024-() |
| | | | | 833027-() |
| | | | | 833071-() |
| | | | | 833290-() |
| | | | | 833303-() |
| | | | | 833532-() |
| | | | | 833542-() |
| | | | | 833920-() |
| | | | | 833944-() |
| | | | | 833387-() |
| | | | | 833871-() |
| | | | | 829493() |
| | | | | 829532-() |
| | | | | 829554-() |
| | | | | 829557-() |
| | | | | 829562() |
| | | | | 829633-() |
| | | | | 829672-() |
| | | | | 829767-() |
| | | | | 829818-() |
| | | | | 829882-() |
| | | | | 829914-() |
| | | | | 829934-() |
| | | | | 829982-() |
| | | | | 830003-() |
| | | | | 830021-() |
| | | | | 830111-() |
| | | | | 830153-() |
| | | | | 830162-() |
| | | | | 830165-() |
| | | | | 830192-() |
| | | | | 830262-() |
| | | | | 830273-() |
| | | | | 830282-() |
| | | | | 830320-() |
| | | | | 830397-() |
| | | | | 830441-() |
| | | | | 830462-() |
| | | | | 830482-() |
| | | | | 830493-() |
| | | | | 830508-() |
| | | | | 830525-() |
| | | | | 830545-() |
| | | | | 830582-() |
| | | | | 830612-() |
| | | | | 830660-() |
| | | | | 830632-() |
| | | | | 830722-() |
| | | | | 830667-() |
| | | | | 830834-() |
| | | | | 830843-() |
| | | | | 830846-() |
| | | | | 830675-() |
| | | | | 830712-() |
| | | | | 830752-() |
| | | | | 830764-() |
| | | | | 830767-() |
| | | | | 830863-() |
| | | | | 830904-() |
| | | | | 830922-() |
| | | | | 830925-() |
| | | | | 830982-() |
| | | | | 830993-() |
| | | | | 832940-() |
| | | | | 833022-() |
| | | | | 833025-() |
| | | | | 833035-() |
| | | | | 833072-() |
| | | | | 833301-() |
| | | | | 833304-() |
| | | | | 833540-() |
| | | | | 833603-() |
| | | | | 833942-() |
| | | | | 833945-() |
| | | | | 833609-() |
| | | | | 833842-() |
| | | | | 829503-() |
| | | | | 829551() |
| | | | | 829555-() |
| | | | | 829558-() |
| | | | | 829572() |
| | | | | 829634-() |
| | | | | 829673-() |
| | | | | 829800-() |
| | | | | 829830-() |
| | | | | 829912-() |
| | | | | 829915-() |
| | | | | 829850-() |
| | | | | 830000-() |
| | | | | 830006-() |
| | | | | 830022-() |
| | | | | 830112-() |
| | | | | 830155-() |
| | | | | 830163-() |
| | | | | 830172-() |
| | | | | 830233-() |
| | | | | 830263-() |
| | | | | 830274-() |
| | | | | 830298-() |
| | | | | 830322-() |
| | | | | 830416-() |
| | | | | 830442-() |
| | | | | 830472-() |
| | | | | 830483-() |
| | | | | 830502-() |
| | | | | 830509-() |
| | | | | 830541-() |
| | | | | 830552-() |
| | | | | 830583-() |
| | | | | 830693-() |
| | | | | 830681-() |
| | | | | 830701-() |
| | | | | 830662-() |
| | | | | 830832-() |
| | | | | 830835-() |
| | | | | 830844-() |
| | | | | 830850-() |
| | | | | 830677-() |
| | | | | 830742-() |
| | | | | 830762-() |
| | | | | 830765-() |
| | | | | 830861-() |
| | | | | 830902-() |
| | | | | 830905-() |
| | | | | 830923-() |
| | | | | 830931-() |
| | | | | 830990-() |
| | | | | 830994-() |
| | | | | 832950-() |
| | | | | 833023-() |
| | | | | 833026-() |
| | | | | 833037-() |
| | | | | 833202-() |
| | | | | 833302-() |
| | | | | 833355-() |
| | | | | 833541-() |
| | | | | 833692-() |
| | | | | 833943-() |
| | | | | 833386-() |
| | | | | 833791-() |
| | | | | 833892-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|----|------------------------------------|--|
| | | | | 833982-() 834793-() 834887-() 834981-() 834992-() 834994-() 835281-() 835282-() 835331-() 835332-() 835333-() 835334-() 835335-() 835336-() 835337-() 835338-() 835339-() 835411-() 835412-() 835432-() 835492-() 835073-() 4001-2-() 4001-3-() 4001-5-() 4001-4-() 7001-() 834962LV-() 834963LV-() |
| TSO-C39a *F | Weber-Futair Limited Bournemouth, Dorset England | EU | | DA200 DA300 4001() 4016() |
| TSO-C39b | Aero Tech United P.O. Box 1220 Springdale, AR 72765-1220 | SW | AIRCRAFT SEATS AND BERTHS | "Three-Place Side-Facing Divan" 2303-0006 Type I frame only 2303-0007 Type I frame only 2303-0009 Type I frame only 2303-() Type 1 Divan Assembly (frame only) 1252 Dual Seat (Frame only) |
| TSO-C39b *F | Aircraft Furnishing Ltd. Walton on Thames Surrey, United Kingdom | EU | | Single Passenger Seat 0950-01() 640001() Double Passenger Seat 0950-02() 300502() 356002() 420102() 640002() Triple Passenger Seat 640003() 420103() 0510() Quadruple Passenger Seat 420104() Single/Triple Passenger Seat 3077() |
| TSO-C39b | Aircraft Modular Products 4000 Northwest 36th Ave. Miami, FL 33142 | SO | | Model 2523.112() Model 2523.113() Model 2523.122() Model 2524-011() Model 2524.013() Model 2525.001() |
| TSO-C39b | Aircraft Products Division 4249 Westroads Drive West Palm Beach, FL 33407 | SO | | 11029() 12438() 11438() 13438() |
| TSO-C39b *F | ALVEN s.r.l., Via delle Industrie 80040 S. Sebastiano Al Vesuvio Napoli, Italy | EU | | Double Seat 3120044-XXXXX Cushion 12019-A()() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|--|---|--|
| TSO-C39b | AMI Industries, Inc. 3200 N. Nevada Ave. Colorado Springs, CO 80907-5347 | NM-S | | 1101-() 1109-() 2038-() 2043-() 2046-() 2053-() 1056-549 | 1102() 1110-() 2039-() 2044-() 2047-() 2055-() 1056-550 | 1108-() 1113-() 2042-() 2045-() 2048-() 1056-559 |
| TSO-C39b | Associated Aircraft Equipment, Inc. 6961 N.W. 42nd St. Miami, FL 33166 | CE-A | | AAE-11001 AAE-11013 | AAE-11005 | AAE-11012 |
| TSO-C39b *F | Aviatech Inc. 2400 Guenette Street Ville St-Laurent, P.Q. Canada H4R 2H2 | EU | | Double Passenger Seat Model 413 | | |
| TSO-C39b *F | Avn. Furnishing Int'l Ltd. Redhill, Surrey United Kingdom | EU | | Single Passenger Seat 913() Double Passenger Seat 913() | | |
| TSO-C39b *F | Avionteriors S.p.A. Via Appia Km. 66.400 04013 Tor Tre Ponti Latina, Italy | EU | | TRIPLE SEATS 126() () -75() () () () , -76, -77, -78, -80, -81, -82, -70, -71, -72, -73, -74, -50, -55, -60, -65, -47, -32 126() () -53() () () () 126() () -59() () () () 132() () -51() () () () , -10, -11, -20, -52 132() () -53() () () () 132() () -55() () () () 132() () -57() () () () 132() () -58() () () () 132() () -69() () () () 134() () -76() () () () 134() () -77() () () () 134() () -80() () () () 3130026-() () () () () 3120029-() () () () () 3120030-() () () () () SEATS 107N2-() () () () () CQ 10722-() () () () CQ 170C4-() () () () () CM 107S4-() () () () CM 107C5-() () () () () CM 107S5-() () () () CM 118A2-() () () () () CP 107N3-() () () () CS 107Z3-() () () () () CS 102K2-() () () () CT 102S3-() () () () () () 107A2-() () () () () () 107S2-() () () () () () 107A5-() () () () () () 107S5-() () () () () () 107M6-() () () () () () 107S6-() () () () () () 118A3-() () () () () CR 120A2-() () () () () BM 123R2-() () () () () BM 102() () -01() () () () () 102() () -20() () () () () 102() () -21() () () () () 102() () -25() () () () () 102() () -30() () () () () 102() () -31() () () () () 102() () -34() () () () () | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|-----|-----------|------------------------|
| 102 |) () | -35 |) () () |) () () |
| 104 |) () | -20 |) () () |) () () |
| 107 |) () | -25 |) () () |) () () |
| 107 |) () | -47 |) () () |) () () |
| 107 |) () | -50 |) () () |) () () |
| 107 |) () | -75 |) () () |) () () |
| 107 |) () | -76 |) () () |) () () |
| 107 |) () | -77 |) () () |) () () |
| 107 |) () | -81 |) () () |) () () |
| 107 |) () | -82 |) () () |) () () |
| 112 |) () | -01 |) () () |) () () |
| 112 |) () | -10 |) () () |) () () |
| 112 |) () | -11 |) () () |) () () |
| 115 |) () | -10 |) () () |) () () |
| 123 |) () | -10 |) () () |) () () |
| 125 |) () | -10 |) () () |) () () |
| 125 |) () | -90 |) () () |) () () |
| 126 |) () | -13 |) () () |) () () |
| 126 |) () | -25 |) () () |) () () |
| 126 |) () | -26 |) () () |) () () |
| 126 |) () | -27 |) () () |) () () |
| 126 |) () | -32 |) () () |) () () |
| 126 |) () | -42 |) () () |) () () |
| 126 |) () | -43 |) () () |) () () |
| 126 |) () | -45 |) () () |) () () |
| 126 |) () | -46 |) () () |) () () |
| 126 |) () | -48 |) () () |) () () |
| 126 |) () | -32 |) () |)CX |
| 126 |) () | -60 |) () |)CX |
| 126 |) () | -65 |) () |)CX |
| 132 |) () | -10 |) () () |) () () |
| 132 |) () | -12 |) () () |) () () |
| 132 |) () | -13 |) () () |) () () |
| 132 |) () | -14 |) () () |) () () |
| 132 |) () | -15 |) () () |) () () |
| 132 |) () | -17 |) () () |) () () |
| 132 |) () | -19 |) () () |) () () |
| 132 |) () | -21 |) () () |) () () |
| 132 |) () | -23 |) () () |) () () |
| 132 |) () | -25 |) () () |) () () |
| 132 |) () | -26 |) () () |) () () |
| 132 |) () | -27 |) () () |) () () |
| 132 |) () | -28 |) () () |) () () |
| 132 |) () | -47 |) () () |) () () |
| 132 |) () | -52 |) () () |) () () |
| 132 |) () | -54 |) () () |) () () |
| 132 |) () | -56 |) () () |) () () |
| 132 |) () | -60 |) () () |) () () |
| 132 |) () | -61 |) () () |) () () |
| 132 |) () | -62 |) () () |) () () |
| 132 |) () | -63 |) () () |) () () |
| 132 |) () | -75 |) () () |) () () |
| 132 |) () | -76 |) () () |) () () |
| 132 |) () | -80 |) () () |) () () |
| 132 |) () | -81 |) () () |) () () |
| 132 |) () | -82 |) () () |) () () |
| 133 |) () | -16 |) () () |) () () |
| 133 |) () | -17 |) () () |) () () |
| 133 |) () | -18 |) () () |) () () |
| 133 |) () | -43 |) () () |) () () |
| 133 |) () | -49 |) () () |) () () |
| 133 |) () | -53 |) () () |) () () |
| 133 |) () | -57 |) () () |) () () |
| 133 |) () | -59 |) () () |) () () |
| 133 |) () | -60 |) () () |) () () |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|-------------------------|
| | | | | 133()()-70()()() |
| | | | | 133()()-71()()() |
| | | | | 133()()-72()()() |
| | | | | 133()()-73()()() |
| | | | | 133()()-74()()() |
| | | | | 133()()-75()()() |
| | | | | 133()()-76()()() |
| | | | | 133()()-90()()() |
| | | | | 133()()-91()()() |
| | | | | 135()()-01()()() |
| | | | | 135()()-10()()() |
| | | | | 136()()-01()()() |
| | | | | 136()()-10()()() |
| | | | | 137()()-10()()() |
| | | | | 137()()-11()()() |
| | | | | 137()()-50()()() |
| | | | | 137()()-51()()() |
| | | | | 137()()-52()()() |
| | | | | 137()()-53()()() |
| | | | | 137()()-54()()() |
| | | | | 150()()-01()()() |
| | | | | 150()()-10()()() |
| | | | | 150()()-11()()() |
| | | | | 150()()-12()()() |
| | | | | 150()()-13()()() |
| | | | | 150()()-14()()() |
| | | | | 150()()-15()()() |
| | | | | 150()()-16()()() |
| | | | | 150()()-17()()() |
| | | | | 150()()-19()()() |
| | | | | 150()()-20()()() |
| | | | | 150()()-21()()() |
| | | | | 150()()-22()()() |
| | | | | 150()()-23()()() |
| | | | | 150()()-24()()() |
| | | | | 150()()-25()()() |
| | | | | 150()()-49()()() |
| | | | | 150()()-50()()() |
| | | | | 150()()-51()()() |
| | | | | 312()()-05-XXXXX |
| | | | | 312()()-06-XXXXX |
| | | | | 3120029-XXXXX |
| | | | | 312()()31-XXXXX |
| | | | | 3120036-XXXXX |
| | | | | 312()()38-XXXXX |
| | | | | 3130036-XXXXX |
| | | | | 313()()38-XXXXX |
| | | | | 12036-A1()() PT |
| | | | | 12036-A2()() PT |
| | | | | 12089-01()() SS |
| | | | | 12089-02()() SS |
| | | | | 12092-01()() EU |
| | | | | 12092-01()() EU |
| | | | | 12094-01()() BA |
| | | | | 12094-02()() BA |
| | | | | 12097-01()() BA |
| | | | | 12097-02()() BA |
| | | | | 123R1-10()() MN |
| | | | | 123R3-10()() MN |
| | | | | 147AA-0001()() |
| | | | | 312()()31-XXXXX |
| | | | | 312()()38-XXXXX |
| | | | | 3120005-()()() |
| | | | | 3120006-()()() |
| | | | | 3120044-()()() |
| | | | | 3120019-()()() |
| | | | | 3120020-()()() |
| | | | | CUSHIONS |
| | | | | 12001-1()()A9 |
| | | | | 12001-2()()A9 |
| | | | | 12006-01()()A9 |
| | | | | 12006-A2()()A9 |
| | | | | 12009-01()()BM |
| | | | | 12009-02()()BM |
| | | | | 12016-01()()CQ |
| | | | | 12016-02()()CQ |
| | | | | 12014-01()()CM |
| | | | | 12014-02()()CM |
| | | | | 12017-1()()CP |
| | | | | 12017-2()()CP |
| | | | | 12019-A()() |
| | | | | 12020-1()()CS |
| | | | | 12020-2()()CS |
| | | | | 12021-01()()CR |
| | | | | 12021-02()()CR |
| | | | | 12021-A()() |
| | | | | 12022-1()()CT |
| | | | | 12022-2()()CT |
| | | | | 12023-A1()() (Bottom) |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | 12023-A2()() (Back) |
| | | | | 12024-1()() AG 12024-2()() AG |
| | | | | 12027-01()() IB 12027-02()() IB |
| | | | | 12027-01031B (Bottom RH STD) |
| | | | | 12027-01041B (Bottom LH STD) |
| | | | | 12027-02021B (Backrest STD) |
| | | | | 12028-01()() AS 12028-02()() AS |
| | | | | 12029-01()() AS 12029-02()() AS |
| | | | | 12030-01()() CW 12030-02()() CW |
| | | | | 12031-01()() EW 12031-02()() EW |
| | | | | 12032-02()() EW 12032-01()() EW |
| | | | | 12032-A1()() T3 12032-A2()() T3 |
| | | | | 12032-A1()() T4 12032-A2()() T4 |
| | | | | 12033-01()() DA 12033-02()() DA |
| | | | | 12034-01()() TK 12034-02()() TK |
| | | | | 12035-A1()() TB 12035-A2()() TB |
| | | | | 12035-01()() CW 12035-02()() CW |
| | | | | 12036-01()() CG (Bottom) |
| | | | | 12036-02()() CG (Back) |
| | | | | 12036-A1()() PT 12036-A2()() PT |
| | | | | 12042-01()() MN 12042-02()() MN |
| | | | | 12043-01()() MN 12043-02()() MN |
| | | | | 12044-01()() MO (Bottom) |
| | | | | 12044-02()() MO (Back) |
| | | | | 12044-03()() MO (Head Rest) |
| | | | | 12045-01()() MO (Bottom) |
| | | | | 12045-02()() MO (Back) |
| | | | | 12050-01()() AZ 12050-02()() AZ |
| | | | | 12053-01()() EB 12053-02()() EB |
| | | | | 12056-01()() CX 12056-02()() CX |
| | | | | 12058-01()() AH 12058-02()() AH |
| | | | | 12058-03()() AH |
| | | | | 12059-01()() AF (Bottom) |
| | | | | 12059-02()() AF (Back) |
| | | | | 12059-03()() AF (headrest) |
| | | | | 12063-01()() AX (Bottom) |
| | | | | 12063-02()() AX (Back) |
| | | | | 12063-0101AX (Bottom) |
| | | | | 12063-0201AX (Back) |
| | | | | 12064-01()() MV (Bottom) |
| | | | | 12064-02()() MV (Back) |
| | | | | 12067-0101CI (Bottom) |
| | | | | 12067-0201CI (Back) |
| | | | | 12068-0101DW (Bottom) |
| | | | | 12068-0301DW (Headrest) |
| | | | | 12068-0201DW (Back) |
| | | | | 12068-0102DW (Bottom) |
| | | | | 12068-0202DW (Back) |
| | | | | 120069-01()() DY (Bottom) |
| | | | | 120069-02()() DY (Back) |
| | | | | 12070-01()() S7 12070-02()() S7 |
| | | | | 12071-01()() PT 12071-02()() PT |
| | | | | 12074-01()() ES 12074-02()() ES |
| | | | | 12074-01()() ES 12074-02()() ES |
| | | | | 12076-01()() C5 (Bottom) |
| | | | | 12076-02()() C5 (Back) |
| | | | | 12076-03()() C5 (Head Rest) |
| | | | | 12082-01()() S8 12082-02()() S8 |
| | | | | 12085-01()() EX 12085-02()() EX |
| | | | | 12088-01()() M1/M2 12088-02()() M1/M2 |
| | | | | 12089-01()() S5 12089-02()() S5 |
| | | | | 12090-01()() 5K 12090-02()() 5K |
| | | | | 12090-03()() 5K 12091-01()() K2 |
| | | | | 12091-02()() K2 12092-01()() EU |
| | | | | 12092-02()() EU 12094-01()() BA |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|--|
| | | | | 12094-02() () BA 12097-02() () BA 12098-02() () PF 12091-02() () K2 |
| TSO-C39b *F | Centro Tecnico Aeroespacial Instituto do Fomento E Coordenacao Industrial Divisao de Homologacao Aeronautica 12.225 Sao Jose dos Campos - SP Caixa Postal 6001 | EU | | Triple Tourist Class Seat 2110-0000-011-4 2110-0000-013-0 2110-0000-017-2 2110-0000-023-7 2110-0000-031-8 2110-0000-043-1 2110-0000-045-7 2110-0000-051-2 2110-0000-055-4 |
| TSO-C39b *F | Contour Seats Limited 13 Eelmoor Road, Farnborough, Hampshire GU14 0HR United Kingdom | EU | | 0950-01-() 0970-01-() |
| TSO-C39b | Dettmers Industries Aircraft Products Division 4249 Westroads Drive West Palm Beach, FL 33407 | CE-A | | 0950-02-() 0950-03-() 0970-02-() 0970-03-() |
| TSO-C39b | Engineering Research and Development Associates 701 U. S. Hwy. 41 Peshtigo, WI 54157 | CE-C | | 11031() Type I 12503() Type I 14003() Type I 11435() Type I 14003-3() Type I 11434(), -1, -2 Type I 11438-4() Type I 17003() Type I |
| | | | | 11034-1() Type I 16003() Type I 14005-C() Type I 11438-1() Type I 14012() Type I 17003S() Type I |
| | | | | 3004() 3007() 3012() 3016() 3021() 3024() 3104() 3107() 3111() 3153() 3203() 3403() 3408() 3411() 3414() 3417() 3421() 3424() 3427() 3500() |
| | | | | 3005() 3009() 3014() 3017() 3022() 3025() 3105() 3109() 3150() 3155() 3204() 3405() 3409() 3412() 3415() 3418() 3422() 3425() 3428() 3502() |
| | | | | 3006() 3010() 3015() 3018() 3023() 3103() 3106() 3110() 3151() 3201() 3301() 3406() 3410() 3413() 3416() 3420() 3423() 3425() 3429() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|----|-----------|--|
| TSO-C39b | 4/Flight Industries 24955 Avenue Kearny Valencia, CA 91335 | NM | | 10665-()-() 11975()-() 12755()-(), -5, -6 13490()-() 13770-2, -4 14130-25 14130-26 14130-27 11940-17 14195-() 14200-() 14210-() 14220-() 2330-132 3580-645 5720-108 12690-(9) 12790-() Model:3080-634-1, -634-2, -635-1, -635-2 13576-5, -6 13097-14 12937-4 Model:3580-603, -643 13575-4 13097-6 Model:3580-604 13576-12 13097-2 Model:3580-605P 13018-2 13097-2 Model:3580-607, -608 13576-2 13097-8 Model:3580-611 13576-8 13097-6 Model:3580-612 13575-10 13097-6 Model:3580-629 13575-6 13097-10 Model:3580-636 13576-4 13097-12 12937-4 Model:3580-637 13576-16 13097-4 12937-6 Model:3585-601A, -601F 13574-1, -2 13579-4 12937-10 Model:3585-616 13576-13 13097-16 Model:3585-623, -624 13573-1, -2 13098-3, -4 Model:3585-625, -626, -628 13573-1, -2 13098-3, -4 Model:3585-627 13573-7, -8 13098-9, -10 Model:3585-630, -631 13573-1, -2 13098-3, -4 Model:3585-632 13573-3, -4 13098-5, -6 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|---|-------------------|-----------|
| | | | | Model 3585-633 13573-5, -6 13098-7, -8 Model:4040-606 Model:4040-241 13575-8 13039-4 Model:4040-613, -614 13576-10 13039-2 12937-2 Model:4045-615, -638, -639 13576-10 13039-2 12937-2 Model:4620-602, -617, -618, -644 13024-2 13579-2 13077-2 Model:12690-7 12990-1 12990-2 12989 | | |
| TSO-C39b | Flight Equipment & Engineering Corporation P.O. Box 522173 Miami, FL 33152 | CE-A | | 221 | 673-3(E) | 683 |
| | | | | 631-1(E) | 690() | 690A() |
| | | | | 690-1() | 692-1() | |
| | | | | 673-(), -1(), -3() | | |
| | | | | 679-3() | 681-3() | |
| TSO-C39b *F | Flight Equipment & Engineering Chesham, Bucks United Kingdom | EU | | 162A() | 162F() | 262F() |
| | | | | Single Seats | | |
| | | | | 185F() | D1121F() | |
| | | | | Double Seats | | |
| | | | | D285F | D2121F() | D2101F() |
| | | | | D2101F117 | D2101F118 | D2101F119 |
| | | | | D2101F120 | D2101F121 | D2101F123 |
| | | | | D2101F125 | D2101F127 | D2101F129 |
| | | | | D2101F131 | D2101F133 | D2101F135 |
| | | | | D2101F137 | D2101F139 | D2101F141 |
| | | | | D2101F353 | D2101F() | D250F() |
| | | | | Triple Seats | | |
| | | | | D385F | D3115F() | D350F() |
| | | | | D3111F() | D3101() | D3101F() |
| | | | | D3101F114 | D2101F116 | D3101F118 |
| | | | | D3101F120 | D2101F122 | D3101F124 |
| | | | | D3101F126 | D2101F128 | D3101F130 |
| | | | | D3101F132 | D2101F134 | D3101F136 |
| | | | | D3101F138 | D2101F140 | D3101F514 |
| | | | | D3101F() | | |
| | | | | Quadruple Seats | | |
| | | | | D4121F() | 4111F() | |
| TSO-C39b *F | Flying Service Engineering & Equipment Ltd. Chesham, Bucks England | EU | | D211F() | F2302()() | |
| | | | | F2238-()-()-() | F2297-()-()-() | |
| | | | | F2287-()-()-() | F3302()() | |
| | | | | D311F() | F3287-()-()-() | |
| | | | | F3297-()-()-() | | |
| | | | | Single Seat | | |
| | | | | F1302() | | |
| | | | | Double Seat | | |
| | | | | F2304() | F2305() | F2306() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|---|
| | | | | Triple Seat F3304() Quadruple Seat F4026()() F4024-()-()-() Double/Triple Seat F3303-()-()-()-() |
| TSO-C39b *F | Ipeco Europe Ltd. Aviation Way Southend Airport Southend-on-Sea Essex SS2 6UN United Kingdom | EU | | OA096-0001/2 OA104-0001/2 AO 103-0009 OA 102-0009 OA105-0019 OA 107-0001/0002 OA 112-0001/0002 OA 118-0011/0012 OA134-0001/0002 OA134-0001F() OA134-0002F() OA142-0001/0002 OA142-0001F() OA142-0002F() OA159-0007/8 OA160-0001F OA163-0001 OA163-0001F() OA185-0001(F):3A185-0007-**-1 OA185-0002(F):3A185-0008-**-1 OA186-0011(F) OA 071-0015 OA 071-0016 OA 078-007 OA 078-008 |
| TSO-C39b | Jepson Burns Corporation 1455 Fairchild Road Winston-Salem, NC 27105-4588 | CE-A | | JB5.1-3() JB5.0-1() JB5.0-2-() JB5.03-() JB5.0-4-() JB5.1-2-() JB5.2-1-() JB5.2-2-() JB5.2-3-() JB5.2-4-() JB5.3-1-() JB5.3-2-() JB5.4-3-() JB6.0-2-() JB6.0-5-() JB6.2-2-() JB6.1-2-() JB6.6-1-() JB6.3-2-() JB6.4-1-() JB6.5-2-() JB7.0-1-() JB7.0-2-() JB7.1-1-() JB6.7-1-() JB6.7-2-() JB-W1.0-2-() 2000K-2-() 2000K-3-() 2020A-2-() 2000UHDD-2-() 2000UHDD-3-() 2000UHDK-2-() 2000UHDK-3-() 2020UHDK-2-() 2020UHDK-3-() 2020E-3() 2020K-1-() 2020B-1-() 2020B-2-() |
| TSO-C39b *F | Keiper Recaro GmbH & Co. Steinbeisweg 25-29 7170 Schwabish Hall Germany | EU | | SINGLE 5010-1-1 3230-1-1 3410-1-1 4210-1-1 5210-1-1 DOUBLE 3230-2-1 4210-2-1 3220-2-1 3410-2-1 5210-2-1 TRIPLE 5010-3-1 3230-3-1 3410-3-1 4210-3-1 3220-3-1 QUADRUPLE 3230-4-1 3410-4-1 Passenger Seat 2020-1-1 |
| TSO-C39b *F | Koita Industries, Limited Seat Engineering Dept. 100, Maeda-cho, Totsuka-ku Yokohama, Japan | EU | | ARS-311-B 145-4250-401 ARS-311-B 145-4250-402 ARS-276:117-1320-414F, -421F, -424F, -431F, -434F, -435F, -438F, -439F :117-1322-401F, -410F :117-1323-421F, -426F :117-1324-421F, -424F, -425F, -428F, -429F, :117-1325-401F, -404F, :117-2932-401F ARS-289:124-3253-401F, -404F :124-3254-401F |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|---|
| | | | | ARS-311:145-2455-401F, -402F, -403F, -404F :145-2456-401F, -402F :145-2930-401F :145-2931-401F |
| | | | | ARS-336:159-5049-401, -404 :159-5050-401 |
| | | | | ARS-354:170-3721-401, -404, -405, -406 -407, -408, -409, -411, -412, :170-3722-401, -402 :170-3831-401 |
| | | | | ARS-397:183-4907-401, -402, -403, -404 :183-4908-401, -402 :183-4909-401 :183-4910-401 :183-5386-401, -402 :183-5495-401, -402 :183-5496-401 :183-5497-401, -402 :183-5498-401 :183-5499-401, -402 |
| | | | | ARS-398:183-4911-401, -402 |
| | | | | ARS-415:178-5306-401, -402, -403, -404, -406, -411, -412, -413, -414, -415, -416, -417, -418 :178-5387-401, -402 :178-5307-401, -411 |
| | | | | ARS-437:184-5379-401, -402 :184-5380-401 |
| TSO-C39b *F | MaGeRik, Ltd. Station Road Shinnor, Oxfordshire, England OX9 4HA | EU | | 135-01() 136-01() |
| TSO-C39b | Med-Flite of Midamerica, Inc. 1132 N. Oliver Road Hangar H, City-County Airport Newton, KS 67114 | CE-W | | 4001-101, -102, -103, -104, -105, -106 4001-201, -202, -203, -204, -205, -206, -207, -208, -209, -210 4001-301, -302, -303, -304, -305, -306, -309, -310, -311, -312, -313, -314, -315, -316 4050-301, -302, -303, -304 4021-1, -2, -3, -4 |
| TSO-C39b *F | Morse Contrals Ltd. Basildon, Essex, England | EU | | CREW SEATS 181512/001() 188444/001() 188755/001() PILOT & CO-PILOT SEATS 187829() 187830() 187749() 187750() |
| TSO-C39b | Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406-1392 | NM | | 50402-200 50403-200 |
| TSO-C39b | PTC Aerospace 11752 Markon Drive Garden Grove, CA 92641 | NM-L | | Model 850 Model 881 Model 940 Model 950 |
| TSO-C39b | PTC Aerospace Route 202 Bantam, CT 06750 | EA | | SEAT 942()-2() 940()-2() |
| TSO-C39b *F | L. A. Rumbold Limited Doman Road, Camberley | EU | | Series M7000-Double M7343() M7344() M7348() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|----------------------------|----|-----------|--|
| | Surrey GU15 3DU England | | | M7345() M7346() M7350() M7515() M7516() M7517() M7518() M7523() M7524() M7525() M7529() M7530() M7531() M7533() M7534() M7542() M7543() M7544() M7535() M7536() M7541() M7551() M7553() M7554() M7555() M7556() M7559() M7560() M7561() M7562() M7565() M7566() M7573() M7574() M7575() M7576() M7581() M7583() M7584() M7585() M7587() M7588() M7589() M7590() M7591() M7592() M7611() M7612() M7619() M7620() M7623() M7624() M7626() M7637() M7638() M7641() M7642() M7699() M7701() M7702() M7703() M7704() M7953() M7954() M9065() M9066() M9067() M9068() M9103() M9106() M9113() M9114() M9116() M9124() M9126() M10121() M10122() M10125() M10126() M10129() M10130() M10131() M10132() M10235-001 M10235-002 M10125-029-001/002 Series M-7000-Quadruple M7365() M7366() M7519() M7521() M7557() M7563() Series M-7000- Triple M7339() M7340() M7341() M7342() M7507() M7508() M7513() M7514() M7509() M7510() M7511() M7512() M7537() M7539() M7545() M7547() M7549() M7569() M7571() M7577() M7633() M7639() M9069() M9070() M9071() M9072() M9073() M9074() M9095() M9096() M9097() M9098() M9099() M9100() M9107() M9108() M9109() M9110() M9111() M9112() M9113() M9114() M9117() M9118() M9119() M9120() M10123() M10127() Series M7000-Double M7542() M7543() M7544() M7527() M7579() M7580() M7551() M7581() M7553() M7554() M7555() M7556() M7559() M7560() M7561() M7562() M7565() M7566() M7573() M7574() M7575() M7589() M7590() M7591() M7592() M7613() M7614() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|-----------------------|----|-----------|-------------------------------------|
| | | | | M7615() M7616() M7617() |
| | | | | M7629() M7630() M7631() |
| | | | | M7632() |
| | | | | SINGLE |
| | | | | M7621() M7636() M10159-() |
| | | | | M9000 Double Passenger Seats |
| | | | | M9103() M9106() M9116() |
| | | | | M9124() M9126() |
| | | | | M9000 Triple Passenger Seats |
| | | | | M9107() M9108() M9109() |
| | | | | M9110() M9111() M9117() |
| | | | | M9118() M9119() M9120() |
| | | | | M10000 Series Double |
| | | | | M10147() M10151() M10155() |
| | | | | M10162() M10163() M10167() |
| | | | | M10171() M10172() M10175() |
| | | | | M10176() M10177() M10178() |
| | | | | M10179() M10180() M10183() |
| | | | | M10184() M10025-070-001 |
| | | | | M10025-070-002 |
| | | | | M10000 Series Triple |
| | | | | M10150() M10154() M10158() |
| | | | | M10166() M10170() M10173() |
| | | | | M10181() |
| | | | | Forward Facing Passenger Seat |
| | | | | M7555-002 M7555-003 M7556-002 |
| | | | | M7556-003 M7559-003 M7559-004 |
| | | | | M7559-005 M7560-003 M7560-004 |
| | | | | M7560-005 M7563-004 M7563-005 |
| | | | | M7571-002 M7575-002 M7576-002 |
| | | | | M7715-001 M7717-001 M7718-001 |
| | | | | M7721-001 M7727-001 M7557-001 |
| | | | | TRIPLE PASSENGER SEATS |
| | | | | M9121-001 M9122-001 |
| TSO-C39b | Sigma Aero Seat | EU | | 42()2() () () 47()1() () () |
| *F | 7 Avenue Bugeaud | | | 48()2() () () 49()2() () () |
| | 75116 Paris | | | 50()1() () () 50()2() () () |
| | France | | | 55()1() () () 65()1() () () |
| | | | | 65()2() () () 65()3() () () |
| | | | | 71()6() () () 73()1() () () |
| | | | | 78()2() () () 78()2() () () |
| | | | | 78()3() () () 78()7() () () |
| | | | | 79()2() () 80()2() () |
| | | | | 80()3() () 81()2() () () |
| | | | | 82()2() () () 82()3() () () |
| | | | | 83()2() () () 83()3() () () |
| | | | | 85()1() () () 85()2() () () |
| | | | | 85()3() () () 85()4() () () |
| | | | | 85()5() () () 90()1() () () |
| | | | | 90()2() () () 90()3() () () |
| | | | | 90()4() () () 90()7() () |
| | | | | 91()1() () () 91()2() () () |
| | | | | 91()3() () () 91()4() () () |
| | | | | 92()2() () () 92()3() () () |
| | | | | 92()4() () () 133() () () |
| | | | | 134() () () 135() () () |
| | | | | 136() () () 137() () () |
| | | | | 138() () () 139() () () |
| | | | | 140() () () 262() () () |
| | | | | 263() () () |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|----|-----------|--|
| TSO-C39b | Simula, Inc. 10016 S. 51st Street Phoenix, AZ 85044 | NM | | 101820 102100 |
| TSO-C39b *F | SOCEA Ancien Arsenal B.P. 109 17303 Rochefort Cedex France | EU | | 2510160() () 2510162() () 2510181() () () 2510183() () () 2510197() () () 2510161() () 2510201() () () 2510123-()-() 2520211() () FFRG1-()-() NCFK1-()-() |
| TSO-C39b | Tosington Enterprises, Inc. 2261 Madera Road Simi Valley, CA 93065 | NM | | T1090-()-() T1280s-()-() T4070-()-() T2280-()-() T2185-()-() 1184-()-() T1355-()-() T1400-()-() T1280s-()-() T405-()-() T1320-5 T510-()-() T2035-()-() T128B-()-() T1280A-()-() |
| TSO-C39b | Trans-Aero Industries, Inc. 502 N. Oak Street Inglewood, CA 90302-2942 | NM | | 2501-6:91466-119 2301-1AA:94039-1 2411-8:93791-1 |
| TSO-C39b *F | Transport Canada Centennial Towers, 7th Floor 200 Kent Street Ottawa, Ontario Canada K1A 0N8 | EU | | 422-() 429-() |
| TSO-C39b | Weber Aircraft 2000 Weber Drive Gainsville, TX 76240 | SW | | 8001:835662() 835203() 835213() 835681() 835682() 835683() 835684() 835692() 835693() 835694() 840442() 840443() 840444() 840445() 840473() 840653() 840662() 840672() 840673() 840682() 840692() 840101() 840109() 840090() 840094() 840349() 840350() 840351() 840352() 840353() 840121() 840164() 840168() 840179() 840182() 840352-() 840353-() 4001-2-() 4001-3-() 4004-3-() 4004-2-() 6002-2-() 6003-2() 6003-3() 7001-2-() 7001-3-() 7501-2-() 7502-2-() 8000-1-() 8001-2-() 8000-2-() |
| TSO-C39b | Weber Aircraft, Inc. Special Products Div. 1300 E. Valencia Dr. Fullerton, CA 92631 | NM | | 835662() 835672() 835681() 835682() 835683() 835684() 835692() 835693() 835694() |
| TSO-C39b *F | Weber-Futair Ltd. Bournemouth Dorset, England | EU | | WF 4016() Type 4001() WF 4018() WF401B/A() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|--|------|--|---|---|--|
| TSO-C40 | Bendix Radio Division Baltimore, MD 21204 | NE | VOR RADIO RECEIV. EQUIPMENT OPERAT. WITHIN THE RADIO FREQUENCY RANGE OF 108-118 MEGACYCLES (FOR AIR CARRIER AIRCRAFT) | EA-22() | | |
| TSO-C40 | Clifton Division Litton Systems, Inc. 5100 State Road Drexel Hill, PA 19018 | NE | | 62000000-() () () | | |
| TSO-C40 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 51R-3 51R-6 51RV-1 51RV-2B 51X-2C 147B-1 313N-4C 344A-1 416N-5 614U-7 VIR-30() 344B-2 | 51R-4 51R-7 51RV-1A 51X-2 51X-3A 313N-() 313N-2/3 344A-2 614U-3 614U-8 VIR-30A | 51R-4A 51R-8 51RV-1C 51X-2B 137X Ser. 313N-4B 313N-2D/3D 344D-1 614U-4 599A-1() VIR-30M |
| TSO-C40 | Dayton Aviation Radio & Equipment, Inc. Box 419 Troy, OH 45373 | CE-C | | DR-480 DN-560 | DR-480N() DN-560A | DR-560B ONC1-1 |
| TSO-C40 | King Radio Corp 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KA39 KNI-500/500L KNR-600 | KN70/71 KNT-510 KNR-660 | KX175() KNT-520 |
| TSO-C40 | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 2373 | 2374 | 56098 |
| TSO-C40 | NARCO Avionics NARCO Scientific Industries Commerce Dr. Fort Washington, PA 19034 | NE | | VSPR-1 VOA-100/110 NAV-114 | VSC-2 NAV-111 DGO-10 CONV | VOA-3A NAV-112 DGO-10 GYRO |
| TSO-C40 | Rockwell International Avionics Group 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | 137X-1:CPN 522-1136-011 | | |
| TSO-C40a | Aire-Sciences, Inc. 216 Passaic Avenue Fairfield, NJ 07006 | NE | VOR RADIO RECEIV. EQUIPMENT OPERAT. WITHIN THE RADIO FREQUENCY RANGE OF 108-118 MEGACYCLES (FOR AIR CARRIER AIRCRAFT) | R-662:CID-662, CID-662 A/O, CID-664 R-664:CID-664, CID-664AO | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|---|
| TSO-C40a | Allied-Signal Aerospace Co. Bendix/King Air Transport Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310 | CE-A | | RVA-36A:2041231-3610 |
| TSO-C40a | Astronautics Corp. of America P.O. Box 523 Milwaukee, WI 53204 | CE-C | | 129222-() |
| TSO-C40a | Avtech Corporation 3400 Wallingford North Seattle, WA 98103 | NM | | 6233-1-1 6233-1-2 |
| TSO-C40a *F | Becker Flugfunkwerk GmbH Baden-Baden-Oos Germany | EU | | NAV 2000 |
| TSO-C40a | Bendix Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | MNA-21() NVA-21() NVA-22() OBS-21() RA-21() RA-22() RMA-21() INA-21() RVA-33 RNA-26 RNA-26() RNA-26CF() MSA-26() CNA-26b() RN242 RN-242A PS-243A IN-244A IN-245A IN-2014() HSD-880:IN-881():DG-882(), SC-883() NP-2041A:4000896-() CN-2013A:4000895-() RN-2608: RN-2628, CN-269A, MT-2638, MT-265A RNA-34A:2041234-() MTA-34R:2041276-() SD-442B |
| TSO-C40a | Bendix Radio Division Baltimore, MD 21204 | NE | | MTA-21() NVA-21 NVA-22() OBS-21 PSA-21() RA-21 RA-22() RMA-21() RMA-26C RNA-26CF INA-21 Ser. MNA-21 Ser. MSA-26() CNA-26b |
| TSO-C40a | Bendix/King Air Transport Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33309 | CE-A | | RVA-36A:2041231-3610 |
| TSO-C40a | Century Flight Systems, Inc. P.O. Box 610 Mineral Wells, TX 76067 | SW | | IC707-() |
| TSO-C40a *F | Chelton (Electrostatics) Ltd Marlow, Buckingham United Kingdom | EU | | 7-41() 17-14() |
| TSO-C40a | Collins Avionics Division Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | CNC-23 VIR-351 614E-44 IND-350/351/351C 639U-1 462A-1() 462B-1() 51RV-28 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|---|--|--|
| TSO-C40a | Collins Avionics Division Rockwell International 400 Collins Rd., N.E. Cedar Rapids, IA 52406 | CE-W | | ANS-31R IND-350G CTL-30()/31() ANS-31C RDM1-743() | RPU-31A 6992-3() 998K-1 | 6992-1 CMS-80() CCD-806 VOR-700 |
| TSO-C40a | Collins General Avn. Div. Rockwell International Melbourne Operations P.O. Box 1060 Melbourne, FL 32902-1060 | CE-A | | ANS-31A ANS-351 GLS-350 IND-31 IND-350A IND-351C VIR-315 339R-18 639U-1 | ANS-31C ANS-351C GLS-350E IND-31C IND-350G IND-351D VIR-350 339R-19 899P-1 | ANS-31R DCE-400 IND-30 IND-350 IND-351 NCS-31A 313N-2 462-A-1 998K-1 |
| TSO-C40a | Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | NCS-31R 51RV-4() | RPU-31M 51R-10() | VIR-350 ANS-351() |
| TSO-C40a | Collins Radio Co. 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | 51RV-1() 390Y-7 ANS-31 913Y-1 339R-3 339R-17 | 197C-() 6992-1 NCS-31 913Y-2 339R-8 | 837B-() VIR-31() 899P-1 339R-2 339R-16 |
| TSO-C40a | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | CI 120 CI-215 | CI 158() CI 259 | CI 159() CI-259C |
| TSO-C40a | Communications Components 3000 Airway Ave. Costa Mesa, CA 92626 | NM | | 35-5008 35-5024() GSNC 20-05 MI 592127 VT 10-56() | 35-5011() AT-902AF NC 10-54 MI 592129 VT-56-6:35-5038 | 35-5017() AT-902AR NC 10-124 VY 10-02 |
| TSO-C40a | Dayton-Granger, Inc. West Coast Division 3000 Airway Avenue Costa Mesa, CA 92626 | NM | | CU994 M15992129 VT10-56() 35-5011-() 35-5038 | DRC20-04 NC10-98-() VT10-56-6 35-5017 | GSNC20-05 VT10-20 35-5008 35-5024 |
| TSO-C40a | Delta Electronics Mfrg. Co. Suite 605 11311 Harry Hines Blvd. Dallas, TX 75229 | SW | | DE127 | DE149 | DE187 |
| TSO-C40a | Dorne & Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM N4-4 DM N4-8 DM N42-1 DM N4-15 DM H23-1 | DM N4-5 DM N4-10/B DM N4-17-1 DM H21-1 DM H24-1 | DM N4-7 DM N4-21 DM N4-17-2 DM H22-1 DM N55-1 |
| TSO-C40a | Edo-Aire Mitchell P. O. Box 610 Mineral Wells, TX 76067 | SW | | 1C707-() | | |
| TSO-C40a *F | Electronique Aerospatiale P. O. Box 4 93350 LeBourget Aeroport Paris, France | EU | | RVA 671 RGA 671 | RNV 671 | RV 671 |
| TSO-C40a | Elliott Brothers | EU | | AD.260 | AD370() | AD380() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|--|------|-----------|---|--|--|
| *F | (London) Ltd. Christopher Martin Road Basildon, Essex England | | | | | |
| TSO-C40a | Foster Airdata Systems, Inc. 7020 Buntley Road Columbus, OH 43229 | CE-W | | RNAV-612 | | |
| TSO-C40a | Gables Engineering, Inc. Coral Gables, FL 33114 | CE-A | | G6164() | G6165() | |
| TSO-C40a | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. P. O. Box 21111 Phoenix, AZ 85027 | NM | | 2588654() | | |
| TSO-C40a | Jet Electronics and Technology, Inc. 5353 52nd St. P.O. Box 8239 Grand Rapids, MI 49508-0239 | CE | | RC-75 Ser | RC-75B | RC-75C |
| TSO-C40a | King Radio Corporation 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KN77 KNC-610 KNR-631() KFS-560B KNR 605() KI-203() KI-207() KI-267:066-3052-00 CN-2011:CN-2011A, IN-2014A, IU-2016A KI 208:066-3056-00 KI 209:066-3056-01 KNR-633:066-4007-03 KNR 634:066-1078-00, -07 KNS 81:066-4010-91, -92, -93, -94 KX175B KA139 KX155()/KX165() KI 229 NAV-COM:069-1024-30 thru 069-1024-49 | KX175 KNR-661 KNR-632() KFS 564 KNR 615() KI-204() KN 72() KNR-634A | KNR-601 KNR-630() KNR-665() KNR 634 KCU 561() KI-206() KI-226() KNS-81 KX 155 |
| TSO-C40a | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 4087A | 4087B | |
| TSO-C40a | NARCO Avionics NARCO Scientific Ind. Commerce Drive Fort Washington, PA 19034 | NE | | VOA-B Mark 24 NAV 121 ID 124() 824 | VOA-9 COM/NAV-110 NAV 122() RNAV 161 ID824 825 | NAV100 OC-110 NAV 124 NAV 200 ID825 |
| TSO-C40a | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVI-200 AVN-204 AVN-210A AVN-212 AVN-214A AVN-220 AVN-221A | AVI-201 AVN-205 AVN-211 AVN-212A AVN-215 AVN-220A AVI-203 | AVI-202 AVN-210 AVN-211A AVN-214 AVN-215A AVN-221 |
| TSO-C40a | Rockwell International Collins Division 7201 Lemon Avenue | SW | | 648-4774-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|---|--|--|---------------------------------|
| | Dallas, TX 75209 | | | | | |
| TSO-C40a | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | 137X-1:522-1136-011 313N-2:522-2447-574 | | |
| TSO-C40a | Sigma Tek, Inc. 17621 N. Black Canyon Hwy Phoenix, AZ 85023 | NH | | 328T 478A 485A 1048A | 385A 8445A 485B 1048B | 428A 479A 878A 1079A |
| TSO-C40b | Aeronetics Div. of AAR Brooks & Perkins Corp. 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | VOR RADIO RECEIVING EQUIPMENT OPERATING WITHIN THE RADIO FREQUENCY RANGE OF 108-118 MEGACYCLES (FOR AIR CARRIER AIRCRAFT) | 520 8130() HSI-4X1X DCU-201A:520-2010() 421A:520-4210-001, 520-4210-002, 520-4210-003, 520-4210-004 421B:520-4211-001, 520-4211-002, 520-4211-003, 520-4211-004 421C:520-4212-001, 520-4212-002, 520-4212-003, 520-4212-004 421D:520-4213-001, 520-4213-002, 520-4213-003, 520-4213-004, 520-4213-005 431A:520-4310-001, 520-4310-002, 520-4310-003, 520-4310-004 431B:520-4311-001, 520-4311-002, 520-4311-003, 520-4311-004 431C:520-4312-001, 520-4312-002, 520-4312-003, 520-4312-004 431D:520-4313-001, 520-4313-002, 520-4313-003, 520-4313-004 | 520 8131() | 520 913() |
| TSO-C40b | Aircraft Radio & Control Div. of Cessna Aircraft Co. P.O. Box 150 Rockaway Valley Road Boonton, NJ 07005 | NE | | IN-380A IN-381AC IN-480AC IN-483AC | IN-380AC IN-382AC IN-481AC | IN-381A IN-383AC IN-482AC |
| TSO-C40b *F | Becker Flugfunkwerk Gmbh Niederwaldstr. 20, D-7550 Rastatt Germany | EU | | NAV 3300 | | |
| TSO-C40b | Bendix Aerospace 2150 Northwest 62nd St. P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | | ED-102E:8095351 | | |
| TSO-C40b | Bendix General Aviation Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | CD-412A: 3614005() CP-103F:8095477-() NC-104B:3614331-() NM-431A:3614023-() SG-101A:3614311-1004 SC-101B:3614335-1004, 1005 VN-411A: 3614003() | CD-462A:3614024-() NC-104A:3614313-() NC-105B:8095679-() NM-461B:3614337-() | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|---|
| TSO-C40b | Bendix/King General Aviation Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | KNC 667:066-4011-26-00, -27-00 :066-4011-24-03, -25-03 :066-4022-00-05, -01-05 :066-4019-00-07, -01-07 :066-4011-06/07 :066-4011-24-05, -25-05 :066-4011-12-03, -13-03 :066-4011-18, -19 :066-4011-08, -09, -10, -11, -12, -13 :066-4011-24, -25 :066-4011-30, -31 :066-4011-46, -47, -48, -49 :066-4011-38, -39 :066-4011-32, -33 :066-4011-42, -43 :066-4011-04, -05 :066-4018-00, -01 :066-4011-40, -41, -44, -45, -48, -49 :066-4011-34, -35 :066-4011-00, -01, -02, -03 :066-4011-38, -39 :066-4011-20, -21, -22, -23, -24, -25, -26, -27, -28 KNC 667:066-4022-02, -03 KNC 667:066-4030-00, -01 KCU 567:066-4012-00/01/02/03/10/11/12/13 KCU 568:066-4013-00/01/02/03/04/05/ 10/11/12/13/52/62 RM-850:7012100-943, -944, -953, -954 |
| TSO-C40b | Bendix/King Air Transport Avionics Division 2100 N.W. 62nd St. Fort Lauderdale, FL 33309 | CE-A | | EFS-10:SG101A, SG101B SG-101B:3614335-1012, -1013 |
| TSO-C40b | Cessna Aircraft Co. ARC Avionics Division P.O. Box 150 Rockaway Valley Road Boonton, NJ 07005 | NE | | 479A |
| TSO-C40b | Collins General Avn. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32902-1060 | CE-A | | B1A-32:622-8613-001 CAD-31:622-8332-001 CTL-32:622-6521() CTL-32A:622-8738-() RTU-870:622-7356-() RTU-870:622-7356-001 VIR-32:622-6137() VIR-432:622-7194-() |
| TSO-C40b | Collins Avionics Division Rockwell International 400 Collins Road Cedar Rapids, IA 52498 | CE-W | | DCP-1000:622-7485-201, -301 DPU-85:622-6022-002 DPU-85A:622-7244-001 DPU-85B:622-7245-001 DPU-85C:622-7448-001 DPU-85M:622-8414-001 DPU-85N:622-8678-001 DPU-86A:622-7247-001 DPU-86D:622-7249-001 DPU-86H:622-7711-002 DPU-86K:622-7713-001 DPU-86L:622-7874-001 DPU-86N:622-8713-001 DU-1000:622-7484-250, -301, -411 EFD-74:622-6197-001, -002 EFD-85 EFD-85:622-6020-001/002/-011/-012/ -021/-022 EFD-85A:622-6464-011/012/021/022 EFD-86:622-6342-011/012/013/014/021/ 022/023/024 EFD-86A:622-6535-011/012/021/022 EFD-870:622-7391-101 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|---|
| | | | | EFIS-86D(2) HCP-74:622-6200-001/002 HCP-74:622-6200-003/004 HCP-74A:622-0793-001/002/003/004 HCP-74B:1/622-9222-001, -002, -003, -004 HPU-74:622-6198-001 HPU-74B:622-9221-001 HPU-86H:622-8714-001 KFD-74:622-6197-001/002 KFD-85:622-6020-011, -012 KFD-85A:622-6464-001, 011, 012 KFD-86:622-6342-011, -012, -013, -014 KFD-86A:622-6535-011, -012 KNC-667:066-4022-00-01 :066-4019-00-03/-01-03 MEM-871:622-7395-101 MFD-80:622-4777-001 MPU-85:622-6091-002 MPU-85:600-6091-002/012/006 MPU-85A:622-7250-001 MPU-85B:622-7251-001 MPU-85C:622-7454-001 MPU-85H:622-8679-001 MPU-85L:622-8023-001 MPU-85N:622-8445-001 MPU-86A:622-7253-001 MPU-86D:622-7255-001 MPU-86L:622-7874-001 MPU-86L:622-8023-001 SDD-640:622-7207-001 SDU-640A:622-8336-001 RMI-733A:622-5002-502 161N-3:622-4774-001 614E-55:622-4775-001 614E-55A(HSVD-800):622-6866-001 313N-6G:622-7490-001/002/003 |
| TSO-C40b | Collins General Avn. Div. Avionics Group Rockwell International Corp. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | | B1A-32:622-8613-() RTU-870A:622-9346-001, -002, -003, -011, -012, -013 CAD-870G:622-7695():-001, -002 |
| TSO-C40b | Dorne & Margolin, Inc. 2950 Veterans Memorial Hwy Bohemia, NY 11716 | NE | | DM N56-1 DM N9-17-1 |
| TSO-C40b *F | Electronique Aerospatiale (EAS) B.P. 51, 93350 Le Bourget France | EU | | BCN2223:899-2223()()() |
| TSO-C40b | Foster Airdata Systems, Inc. 7020 Buntley Road Columbus, OH 43229 | CE-C | | LNS616/RNC601 LNS616A/RNC601A CD-850:805D0710-XX |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|--|
| TSO-C40b | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G7005() G-67005-() G7016() G7024():-01, -02, -03, -04, -07, -08, -09, -10, -11, -14, -15, -18, -19, -23, -24, -25, -26, -27, G6895() G6950() G7045() G6868 G6860() G6229() G6979() G7056() |
| TSO-C40b | Global-Wulfsberg Systems 6400 Wilkinson Drive Prescott, AZ 86301 | NM | | GNS-1000-() 30150-()-() 30360-()-()-() 30380-()-()-() 30300()-()-() |
| TSO-C40b | Gull Airborne Instruments, Inc. 395 Oser Avenue Smithtown, NY 11787 | NE | | RCN-202 COMM/NAV:901-207-0011, 0012, 0013, 0014 RNC-202 NAV/COMM:901-208-0011, 0012, 0013, 0014 RNN-202 NAV/NAV:901-205-0011, 0012, 0013, 0014 RNT-202 NAV/TPDR:901-211-0011, 0012, 0013, 0014 RNX-202 NAV A/B:901-212-2025 |
| TSO-C40b | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 West Bell Road Glendale, AZ 85308 | NM | | SG-811:7004544-(), 7004544-312 SRZ-850:ED2-605/805 SG-815, -816:7011674, -817 MG-815:7011675-215 MG-817 DC-800:7003420-965, -966 DC-811:7012977-747 thru -758, -767, -768, -933, -934 DC-810:7005819-747 thru -758, -767, -768, -933, -934 (SG)820:7007356-() MC-800:7007062-701, -702, -721, -722 MG-820:7009289-() MG-603:7007061-624, -824 ED-800 MG-803 :7007061-624, -824 SG-600/800 SG-603:7003400-624, -824 SC-800 SG-705:7011672-707 SG-803:7003400-624, -824 RNZ-850:7210100-911, -912, -913, -914 |
| TSO-C40b | King Radio Corporation 400 N. Rogers Rd. P.O. Box 106 Olathe, KS 66061 | CE-W | | KA 140 KA 145 KFS-564A:071-1283-(), -011-1285-28 thru -33 KFS-579A:071-1281-(), -28 thru -33 KFS-579A:071-1291-28 thru -33 KNC-667:066-4011-22/-23/-04-03/-36-00/ -37-00/-42-43/ : -05-03/-06-00/-07-00/-12-00/-13-00 : -04-04/-05-04 :066-4022-00-0/-00-04/-01-04 KMR-620:066-1126-00 KMR-634 KNS-660 KPI-552B:066-3081-00 thru -04 KPI-553B:066-3069-00, -01, -03, -04 KA-167 KA-676 KA-677 KA-678 KA-679 KCU-567 KCU-568 VN411B:066-1101-00, -10 |
| TSO-C40b | Marco Avionics, Inc. 270 Commerce Drive | NE | | MK-12D:1D824/825 VOA 821 VOA 822 NS 801 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|---|--|
| | Fort Washington, PA 19034 | | | NE 800 |
| TSO-C40b | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM | | S65-247-() |
| TSO-C40b | Sigma Tek, Inc. 17621 N. Black Canyon Hwy Phoenix, AZ 85023 | NM | | IN-380A/AC IN-381A IN-381AC IN-480AC IN-481AC IN-382AC IN-383AC IN-482AC IN-483AC IN-1048A/AC IN-1049A/AC |
| TSO-C40b | Sperry Flight Systems Avionics Division P.O. Box 29000 5353 West Bell Road Phoenix, AZ 85038 | NM | | ED-600:7003430-() ED-800:7003110-() MC-800:7007062-() MG-800:7007061-() MG-810:7007321-() DC-820:7007277-() MG-815,816:7011675-() MG-820:7009289-() SG-600/800:7003400-() SG-610/810:7004544-() SG-815,816:7011674 SG-820:7007356-() |
| TSO-C40b | Trivec-Avant Corp. 17351 Jamestown Lane Huntington Beach, CA 92647 | NM | | 21-37-() 22-37-() 23-30-01-() 24-37-() |
| TSO-C40c | Aeronetics 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | VOR RECEIV. EQUIPMENT OPERATING WITHIN 108-117.95 MHZ. | DCU-201D:520-2013-() DCU-201A-1():520-2010-003, -004 DCU-201A-2():520-2010-005 HS1-423A:520-4230-()() |
| TSO-C40c | Bendix/King Radio Corp. 400 N. Rogers Road Olathe, KS 66062-1212 | CE | | KN 40:066-01130-0501, -0601, -0701, -0801 |
| TSO-C40c | Dorne & Margolin Inc. 2950 Veterans Memorial Hwy. Bohemia, New York 11716 | CE-C | | VOR/LOC/GS:DM U227-(), DM N4-17/N DM N4-17-1/N VOR:DM N36-4 |
| TSO-C40c | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | Model G4422() |
| TSO-C40c | Universal Navigation Corp. 3260 E. Lerdo Road Tucson, AZ 85706 | NM-L | | 1058-01-10 10580-1-12 |
| TSO-C40d | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Business & Commuter Avn Sys Div 5353 West Bell Road Glendale, AZ 85308 | NM | VOR RADIO RECEIVING EQUIP. OPERATING WITHIN THE RADIO FREQ. RANGE OF 108-118 MEGAHERTZ | RN2-850:7510100-901, -902, -903, -904, -907 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|---|---|---|--|
| TSO-C41 | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | AIRBORNE AUTOMATIC DIRECTION FINDING (ADF EQUIP.) | LPA-70() 2321B 4091E MN-58 NM-461A:3614023-() CD-462A:3614024-() | MIA-70() 2321E DFA-70A CNA-70() | PSA-70() 2321G DFA-70A-1 NM-461B:3614337-() |
| TSO-C41 | Bendix Radio Division Baltimore, MD 21204 | NE | | ADF-72 2321B LPA-73() | CMA-73() 2321E | CMA-301 4091E |
| TSO-C41 *F | Canadian Marconi Co. Ltd. 2442 Trenton Ave. Montreal, Quebec Canada | NE | | CMA-301 | | |
| TSO-C41 | Collins Radio Co. 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | 137A-2 179J-6A 179L-() 437M-2 51Y-4 440L-8 DF-203 | 137A-6 179J-8A 343A-1 437M-2A 51Y-4A 440S-1 | 137A-7 KDF-8000 390D-11A 51Y-3 DF-202 Ser. 614L-8 |
| TSO-C41 | Instrument Engineering & Service Co. (INESCO) N. Hollywood, CA 91603 | NM | | MN58A MN58D | MN58B | MN58C |
| TSO-C41 | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KR-85() KNI-585 | KDF-580 KFS-5800 | KNI-580 KNR665() |
| TSO-C41 | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 2321B 4084B 4084F 4091D | 2321C 4084C 4091B 4091E | 4084A 4084E 4091C 4096A |
| TSO-C41 | Motorola Avia. Electronics Santa Monica, CA 90406 | NM | | 2321E 4088B 4088E 4088H 4091F | 2321G 4088C 4088F 4088I 4096B | 4088A 4088D 4088G 4088J |
| TSO-C41a | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | AIRBORNE AUTOMATIC DIRECTION FINDING (ADF EQUIP.) | PSA-70() DFA-70() CNA-72() GMA-71() LPA-72() SG-101A:3614311-1004 SG-101B:3614335-1004 | CNA-70() DFA-72() CUA-72() GMA-72() MTA-72() | CUA-70() FLA-70() EFS-10 LPA-71() |
| TSO-C41a | Bendix Radio Division Baltimore, MD 21204 | NE | | DFA-72() LPA-72() CNA-73() 2321G | GMA-72() MTA-72() LPA-73() | CUA-72 ADF-73() OCA-73() |
| TSO-C41a | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | NCS-31A:622-2899-012/013/016 899P-1:622-1737-001/002 | | |
| TSO-C41a | Ellfott Brothers | EU | | AD712 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|--|------|---|--|---|---|
| *F | (London) Ltd. Christopher Martin Road Basildon, Essex England FORMERLY Marconi Co. Ltd. | | | | | |
| TSO-C41a | Narco Avionics Corp. Commerce Dr. Fort Washington, PA 19034 | NE | | ADF 140 | | |
| TSO-C41b | Aircraft Radio & Control Boonton, NJ 07005 | NE | AIRBORNE AUTOMATIC DIRECTION FINDING (ADF EQUIP.) | IN-12-1 DV-14A 21B R-30B() R-30B() M-58A 318G 346B | IN-13A-1 RA-21B 40B 40B M-59A 324A 446A | IN-21C 846A L-40B L-40B R-318A 346A 546E |
| TSO-C41b | Bendix Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | CNA-72() GMA-72() ADF-73 DFA-73() QCA-73() | CUA-72() LPA-72() CNA-73() LPA-73() MSA-73() | DFA-72() CMA-73() CUA-73() LSA-73() DFA-74A |
| TSO-C41b | Bendix Radio Division Baltimore, MD 21204 | NE | | CMA-73A | | |
| TSO-C41b | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 179J-12 DF-206 | 390Y-6 | 890Y-() |
| TSO-C41b | Collins Avionics Division Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | 51Y-7A 137A-4A | | |
| TSO-C41b | Elliott Brothers *F (London) Ltd. Christopher Martin Road Basildon, Essex England FORMERLY Marconi Co. Ltd. | EU | | AD360 | AD370 | |
| TSO-C41b | King Radio Corporation 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KDF-800 | KDF-8000 | KR-85() |
| TSO-C41b | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVI-200 AVI-203 | AVI-201 | AVI-202 |
| TSO-C41b | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | 390D-11:522-0801-018 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|--|---|
| TSO-C41b | Sigma Tek, Inc. 17621 N. Black Canyon Hwy. Phoenix, AZ 85023 | NM | | 346A 846A 446A 546E |
| TSO-C41c | Allied-Signal Aerospace Co. Bendix/King General Avn. Avionics Div. 400 W. Rogers Road Olathe, KS 66062-1212 | CE-W | AIRBORNE RADIO RECEIVING AND DIRECTING FINDING EQUIPMENT | KR 87:KPN 066-1077-01 KR 87:KPN 066-1072-02, -03, -04, -05 KDF 806:066-1077-01 |
| TSO-C41c | Allied/Signal Inc. Bendix King Air Transport Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33309 | CE-A | | DFA 76A:2041168-7513 EFS-10:SG101A, SG-101B DFA 75A:2041168-7513 KR 87:066-1072-01, -02, -03, -04, -05 SG-101B:3614335-1012, -1013 |
| TSO-C41c | ARC Avionics Division P.O. Box 150 Boonton, NJ 07005 | NE | | 347A |
| TSO-C41c | Avtech Corporation 3400 Wallingford North Seattle, WA 98103 | NM | | 6461-1 |
| TSO-C41c *F | Becker Flugfunkwerk GmbH Rastatt, Germany | EU | | ADF 2000 ADF 2081 ADF 2079 ADF 2080 |
| TSO-C41c | Bendix Aerospace 2150 Northwest 62nd St. P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | | ED-102E:8095351-() |
| TSO-C41c | Bendix General Aviation Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | ADF-2070:DF-2071(), IN-2072(), AT-2073(), AM-2073() CN-2011:IU-2016A IN-2072B:4001674-7001 DFA 75 DFS-43A NC-104A:3614313-() CP-103F:8095477-() NC-105B:8095679-() NC-1048:3614331-() SC-1018:3614335-1005 |
| TSO-C41c | BVR Aero Precision Corp. 5459 Eleventh Street P.O. Box 6336 Rockford, IL 61125-1336 | CE-C | | 276470-() |
| TSO-C41c *F | Chelton (Electrostatics) Ltd Marlow Buckingham, United Kingdom | EU | | 415() |
| TSO-C41c | Collins Avionics Division Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | ADF-650 ADF-60() ADF-60A() ADF-60B() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|--|
| TSO-C41c | Collins Avionics Division Rockwell International 400 Collins Road Cedar Rapids, IA 52498 | CE-W | | ADF-700 CCD-810 CTL-20() CTL-21() CTL-30() CTL-31() CTL-40() CTL-41() CTL-60() CTL-61() CTL-90() CTL-91() DFA-701A DFA-701B DFA-206A DFB-206A DFC-206A DFM-206A DFP-712:622-6829-001, -011, -021 DFP-712A:622-7080-001 DFP-713:622-6830-001, -011, -021 DFP-713A:622-7081-001 DFB-703 RMI-733() SCC-811 SCC-812 992G-2 RMI-733A:622-5002-501, -502 |
| TSO-C41c | Collins General Avn. Div. Rockwell International Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | ADA-650 ANT-650 ANT-650A IND-650 IND-650A RCR-650 RCR-650A ADF-700 DFA-701A DFA-701B DFA-701C DFA-701D DFP-702 462-A-1 639U-1 CAD-62:622-6590() CTL-62:622-6522() RTU-870:622-7356-(), -001 ADF-462:622-7382-() |
| TSO-C41c | Collins General Avn. Div. Avionics Group Rockwell Int'l Corp. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | | RTU-870A:622-9346-001, -002, -003, -011, -012, -013 CAD-870G:622-7695():001, 002 |
| TSO-C41c | Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | A462A-1() 462B-1() 639U-1 |
| TSO-C41c | Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | NCS-31R RPU-31N ANT-608:622-3710-() |
| TSO-C41c | Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | NCS-31 899P-1 913Y-1 913Y-2 33R-4 339R-5 339R-10 339R-13 339R-15 ADF-650 |
| TSO-C41c *F | EAS B.P.51 93350 Le Bourget Principal Paris, Frances | EU | | 2625: 889-2625()()() |
| TSO-C41c *F | Elliott Brothers (London) Ltd. Christopher Martin Road Basildon, Essex England | EU | | AD360() AD370() AD380() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|---|---|
| TSO-C41c | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G4204() G6225() G7004()ADF:KDF-806ADF G6095()ADF G6435()ADF G6762()ADF G6862() G7009()ADF G7018()ADF G7026(), -01, -02, -03, -04, -05, -06, -07, -08, -09, -10, -11, -12, -13, -19 G7047() G7048() G7058() |
| TSO-C41c | Gull Airborne Inst., Inc. 395 Ober Avenue P.O. Box 9400 Smithtown, NY 11787 | NE | | RAA-202 ADF/ADF:901-201-0001, 0002 0003, 0004 RAX-202 ADF A/B:901-202-0001, 0002, 0003, 0004 RTA-202 TPDR/ADF:901-209-0001, 0002, 0003, 0004 |
| TSO-C41c | King Radio Corporation 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KDF805 KCU578() KA 36() KCU-582 KR87 KA44 K1227 K1228 KA42B KDF806 KFS586 KFS586A KA44B K1229 KN1582 K1229 KFS 586A:071-1284-() KDA-430:065-5030-00/-01/-02/-03/-04/-06 KPI-552B:066-3081-00 thru -04 KPI-553B:066-3069-00,-01,-03,-04 KAM-432:065-0091-00, -04 |
| TSO-C41c | Narco Avionics Corp. Commerce Drive Fort Washington, PA 19034 | NE | | ADF 141 ADF 200 ADF-841 |
| TSO-C41c | Rockwell International Avionics Group 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | DFP-712A:622-7080-002, -003 DFC-206A:622-6813-003 |
| TSO-C41c | Sensor System, Inc. 8929 Fullbright Avenue Chatsworth, CA 91311 | NM | | S72-1712-() |
| TSO-C41c | Sigma Tek, Inc. 17621 N. Black Canyon Hwy. Phoenix, AZ 85023 | NM | | 347A 10468 |
| TSO-C41d | Aeronetics Div. of AAR Brooks & Perkins Corp. 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | AIRBORNE AUTOMATIC DIRECTION FINDING (ADF EQUIP.) | DCU-201A:520-2010() |
| TSO-C41d | Collins Avionics Division 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | SDD-640:622-7207-001 SDU-640A:622-8336-001 DU-1000:622-7484-250,-301, -411 DCP-1000:622-7485-201,-301 ADF-462:622-7382-() ANT-462A:622-7383-() ANT-462B:622-7384-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|---|--|--|--|
| TSO-C41d | Collins General Avn. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32902-1060 | CE-A | | CTL-62A:622-8739-() BIA-32:622-8613-001 | | |
| TSO-C41d | Collins General Avn. Div. Avionics Group Rockwell Int'l Corp. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | | BIA-32:622-8613-() ADF-462 System:622-7382(), 001, 101 622-7383() 622-7384() | | |
| TSO-C41d | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 West Bell Road Glendale, AZ 85308 | NH | | SRZ-850 RM-850:7012100-943, -944, -953, -954 RNZ-850:7510100-901, -902, -903, -904, -907, -911, -912, -913, -914 | | |
| TSO-C42 | Aeroquip Corporation Aeroquip Aerospace Div. 300 South East Avenue Jackson, MI 49203 AND Aero Hardware & Supply, Inc. Miami Springs, FL 33166 AND Aerotech World Trade Corp. Purchase, NY 10577 AND Cooper Airmotive Van Nuys, CA 91408 AND VanDusen Aircraft Engineering, Inc. Kansas City, KS 66100 AND Boeing Comm. Airplane Co. Auburn, WA 98002 | CE-C | PROPELLER FEATHERING HOSE ASSEMBLY (RUBBER AND WIRE BRAID CONSTRUCTION) | 624100 624300 624503-3 624503-6 624503-12 640339-10 640382-12 | 624117 624304 624503-4 624503-8 640293-10 640382-8 640383-10 | 624123 624305 624503-5 624503-10 640382-6 640382-10 |
| TSO-C42 | Deutsch Metal Components 14800 S. Figueroa St. Gardena, CA 90248-1795 AND Air Pro 2921 NW 79th Avenue Miami, FL 33152 AND Go Air 3562 Elm Street Atlanta, GA 30364 AND Hoseco, Inc. 5775 W. 56th Street Arvada, CO 80002 | NH | | TYPES 2 & 3 94F01000F () Series 94F01000D () Series 88F01000F () Series | | |
| TSO-C42 | Deutsch Metal Components Div. 14800 S. Figueroa Street Gardena, CA 90248-1795 | NH | | TYPES 2 & 3 36F(XX)0016DL 38F(XX)000116DL 88F(XX)000(04 thru 16)(F or X)L 88F01000F() Series 94(F or H)(XX)000(03 thru 06)(F or X)L 94(F or H)(XX)000(08 thru 12)(D or Y)L 94F01000F() Series 94F01000D() Series 38F(XX)000116DL | | |
| TSO-C42 | Hatfield Aviation | SW | | Part numbers not furnished. | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|--|
| | 16702 Lee Road Houston, TX 77338 | | | |
| TSO-C42 | Northwest Airlines Minn-St.Paul Int'l Airport St. Paul, MN 55111 | CE-C | | Part numbers not furnished |
| TSO-C42 | Resistoflex Corporation Roseland, NJ 07068 | NE | | TYPE 1 - (Pressure Line) SSFD3800-10 SSFD3800-10G SSFD3800K-10 SSFD3800AC-10 SSFJ3800-10 SSFD3800AC-10G SSFJ3800G-10 SSFJ3800AC-10 SSFJ3800K-10 SSFJ3800GAC-10 SSFR3800-10 SSFR3800-10G SSFR3800K-10 SSFR3800AC-10 TSFD3800-10 SSFR3800AC-10G TSFD3800G-10 TSFD3800AC-10 TSFD3800K-10 TSFD3800GAC-10 TSFJ3800-10 TSFJ3800G-10 TSFJ3800AC-10 TSFJ3800GAC-10 TSFJ3800R-10 TSFR3800-10 TSFR3800G-10 TSFR3800AC-10 TSFR3800GAC-10 TSFR3800K-10 Types II and III - (Supply Lines) SD3800-16Z TD3800-16Z SD3800DD-16Z TD3800DD-16Z SD38xx-16Z Series TD38xx-16Z Series SD101xx-16Z Series TD101xx-16Z Series SJ3800-16Z TJ3800-16Z SJ3800DD-16Z TJ3800DD-16Z SJ38xx-16Z Series TJ38xx-16Z Series SJ101xx-16Z Series TJ101xx-16Z Series SR3800-16Z TR3800-16Z SR3800DD-16Z TR3800DD-16Z SR38xx-16Z Series TR38xx-16Z Series SR101xx-16Z Series TR101xx-16Z Series |
| TSO-C42 | Stratoflex Aerospace & Military Connectors 220 Roberts Cut Off Road P.O. Box 10398 Fort Worth, TX 76114 and Burnsville, MN 55337 AND Air Distributors, Inc. - Withdrawn prior to 1989 2301 E. DelAmo Blvd. Carson, CA 90749 AND Aviall 16260 Raymer St. Van Nuys, CA 91406 AND Aviall 500 Industrial Avenue Teterboro Airport Teterboro, NJ 07608 AND Aviall 8210 Haskell Ave. Van Nuys, CA 91406 AND | SW | | 11147-16-L 11155-10-L 111F504-5 129F001-4SS 129F001-6SS 129F001-8SS 129F001-10SS 129F001-12SS 124F001-10SS-L-Series 124F001-16SS-L-Series |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|--|
| | Aviall 2742 Burbank Street Dallas, TX 75235 AND Durham Aircraft Serv., Inc. 3701 NW. 66th Ave. Miami, FL 33166 AND Hangar One, Inc. Opa Locka Airport 15001 42nd Street Miami, FL 33054 AND Hatfield Aviation 8109 Braniff Houston, TX 77017 AND Integrated Aircraft Systems 39 Milford Drive Hudson, OH 44236 AND Integrated Aircraft Systems, Inc. Commerce Center, Suite 9 1337 Commerce Drive Stow, OH 44224 AND Mid-State Aerospace, Inc. 710 N. Lindenwood Drive Olathe, KS 66062-2689 AND Precision Hose Technology 3324 N. 74th E. Avenue Tulsa, OK 74115 AND Sacramento Sky ranch Executive Airport Sacramento, CA 95822 AND Western Skyways, Inc. Troutdale Airport Troutdale, OR 97060 AND The Zee Company, Inc. 123 Braniff Drive P.O. Box 32842 San Antonio, TX 78216 AND Stratoflex Stone Mountain, GA - WITHDRAWN 7/10/89 AND Stratoflex Irvine, CA - WITHDRAWN 7/10/89 | | | |
| TSO-C42 | Titeflex, Inc. Atlas Corporation 603 Hendee St. Springfield, MA 01109 ALSO Alaska Transportation Co. ATCO Spad Division 4211 Donald Douglas Blvd. Long Beach, CA 90801 | NE | | 11000010-P (Types 1, 2, and 3) |
| TSO-C42 | The Weatherhead Company Syracuse, IN 46567 | CE-C | | TYPE 2 88F01000F Series (-4 thru -16) |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|---------------------------|--|
| | | | | 94F01000D Series (-8 thru -12) 94F01000F Series (-3 thru -6) Type 3 94F01000F Series (-3 thru -5) 94F01000D Series (-8 thru -12) 94F01000F Series (-4 thru -10) |
| TSO-C43 | Aero Instrument Supply, Inc. P. O. Box 7481 Dallas, TX 75209 | SW | TEMPERATURE INDICATORS | 210CY 214S-0-200F0L2, -1 214S-0-200-FSL2, -1 |
| TSO-C43 | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | | 65945-() 78200-() 32678 32679 |
| TSO-C43 | Aerosonic Corporation Dallas Division 3312 Wiley Post Rd. Carrollton, TX 75006 | SW | | 2600-0001 2612-0001 |
| TSO-C43 | Aircraft Instrument & Development, Inc. 317 E. Lewis St. Wichita, KS 67202 | CE-W | | 51-1210-() 51-1220-() 51-1226-() 51-2210-() 51-2220-() 51-3210-() 51-3220-() 51-4210-() 51-4220-() 51-4226-() 51-5210-() 51-5220-() 51-6210-() 51-6220-() 18-1000-() |
| TSO-C43 | AiResearch Manufacturing Company of California 2525 West 190th Street Torrance, CA 90509 | NM | | 2101254-3 |
| TSO-C43 | ALCOR, Inc. P. O. Box 32516 San Antonio, TX 78284 | SW | | 216-() 216-()B 227-()B |
| TSO-C43 | Ametek Aerospace Products, Inc. 50 Fordham Rd. P. O. Box 204 Wilmington, MA 01887 | NE | | 8DJ100 8DJ175LXA 8DJ175LMR() 8DJ175LWS() 8DJ175LWP() 8DJ175LX8() 8DJ175LWX 8DJ175LWM() 8DJ175LXF 8DJ175LWT() 8DJ175LWG1 8DJ175LWX() 8DJ175LWK2 8DJ177LWN1 8DJ177LWA1 8DJ177LWP 8DJ177LWL 8DJ177LWR 8DJ179()()-() 8DJ185LWF() 8DJ185LPC 8DJ185LWC 8DJ185LPB 8DJ185LWB 8DJ185LWE1 8DJ185LWG() 8DJ185LWF() 8DJ185LWL 8DJ185LWN 8DJ185LWP 8DJ185LWM() 8DJ185LWH() 8DJ185LWR() 8DJ313()()-() 8DJ()()-() 8DJ163---() |
| TSO-C43 | Ametek Aerospace Prod. Inc. Seattle Support Center 4560 15th Ave. N.E. Redmond, WA 98052-5374 | NM | | 8DJ163XXXX 8DJ185XXXX 8DJ175XXXX 8DJ177XXXX |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | | |
|---------------|---|------|-----------|--|---|---|---------------------------|
| TSO-C43 | AMETEK/U.S. Gauge 900 Clymer Ave. Sellersville, PA 18960 | NE | | SEL-OC19D SEL-OC19G VSDL-OC419A VSDL-OC204C:-OC219C, -OC419E MM-OC19A MML-OC19AN MML-OC19AT SEL-OC19BL SEL-OC19L SEL-OC19AR SEL-0198D SEL-0198G T6 Indicator | SEL-OC19E VSDL-OC204A SEL-OC19M MM-OC19E MML-OC19AR MMLOC19AU SEL-OC19BP SEL-OC19Y SEL-019AU SEL-019BU VSDL-OC-219U | SEL-OC19F VSDL-OC219A SEL-OC19N MM-OC19D MML-OC19AS SEL-OC19AB SEL-OC19K SEL-OC19AP SEL-0198C SEL-0198W VSDL-OC419F | |
| TSO-C43 | Armtec Industries, Inc. Manchester Municipal Airport Manchester, NH 03103 | NE | | 195-() 202-() 397-() | 200-() 203-() | 201-() 273-() | |
| TSO-C43 | Astronautics Corp. of Amer. 907 S. First St. Milwaukee, WI 53204 | CE-C | | EHU-15/A | | | |
| TSO-C43 | Atlantic Scientific Corp. 100 Brook Ave. Deer Park, NY 11729 | NE | | 206-351-001 206-351-0010-1 206-351-0010-3 206-351-0010-5 | 206-351-0001 206-351-0010-2 206-351-0010-4 206-351-0010-6 | | |
| TSO-C43 | AVMAR, Inc. 1038 Santerre Drive Grand Prairie, TX 75050 | SW | | 76-1000 | 76-300 | | |
| TSO-C43 | B & D Instruments, Inc. 209 W. Main Valley Center, KS 67147-2298 | CE-W | | 0201 0232-() 0227-() | 0202-() 0204-() | 0227 0219 CDT-11T | |
| TSO-C43 | Bendix Flight & Engine Inst. Div. South Montrose, PA 18843 | NE | | 358-1441-1001 3911213-9008 | | | |
| TSO-C43 | Bendix Flight Systems Division Teterboro, NJ 07608 | NE | | 3571251-9101, 9111, -9115, -9119, -9121, -9123, -9129, -9131 3911212-9001 3911213-9002, -9005 | | | 3911211-9002 3809590-1 |
| TSO-C43 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | 3581320-0() | 3581480-1() | | |
| TSO-C43 | Bendix Corporation Instruments & Life Support Div. 896 Waverly Avenue Holtville, NY 11742 | NE | | DST-16 | DST-17 | | |
| TSO-C43 *F | Canadian Marconi Co. 2442 Trenton Avenue Montreal, Quebec Canada H3P1Y9 | NE | | 730-14:418-105-() 418-080-() 418-085-() 100-476-675-120 | 418-120-() 418-101-() | 418-193-() CMA730-14 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|---|------|-----------|--|--|---|
| TSO-C43 | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | TAI-80A | TAI-80B | |
| TSO-C43 | Colt Electronics Company 137 West Ninth Avenue North Kansas City, MO 64116 | CE-W | | CD2031 | | |
| TSO-C43 | Digatron North 6463 Perry Spokane, WA 99207 | NM | | DT-10 DT-21 | DT-20 | DT-21() |
| TSO-C43 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 22-168-() 914 22-304-() | 169-() 22-294-() 1U378 | 910 22-299-() 1U417 |
| TSO-C43 | Eldec Corporation 16700 13th Avenue West Lynnwood, WA 98036 | NM | | 9-395-01 9-395-12 | 9-395-07 | 9-396-02 |
| TSO-C43 | Gull Airborne Inst., Inc. 55 Engineers Road Smithtown, NY 11787 | NE | | 203-002-() 204-909-() 208-905-XXX 217-905-XXX(001 & 002) 224-908-XXX 261-914-XXX(012) 261-926-XXX(001) | | 203-022-() 208-901-(XXX) 208-906-XXX 224-901-XXX 224-911-() 204906002 309-902-XXX |
| TSO-C43 | Harrowe Systems, Inc. 255 Great Valley Parkway Malvern, PA 19355 | NE | | 2091-() | | |
| TSO-C43 | Hartman Systems Co. 360 Wolf Hill Rd. Huntingdon Station, NY 11746 | NE | | VS-1PB(648-) VS-2PA(624-) VS-2PB(723-) VS-4PB(642-) VS-25B(625-) | VS-2PB(623-) VS-2SB(625-) VS-2PB(754-) VS-4PB(644-) | VS-2PA(621-) VS-2SC(626-) VS-2PB(749-) VS-25B(725-) |
| TSO-C43 | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | 2594617-() 2594549() | 2594467() | 4024130-() |
| TSO-C43 | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 5353 W. Bell Road Glendale, AZ 85038 | NM | | 4031609-() | 7002638-() | |
| TSO-C43 | Howell Instruments, Inc. 3479 W. Vickery Blvd. Fort Worth, TX 76107 | SW | | BH183() BH183M-62 BH187R4() Ser. H903 H903()-2() | BH183M-15 BH185R-3 H913 H901 | BH183M-16 BH185R() Ser. H900()-2() H900 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|---|----|--------------|---|---|---|
| TSO-C43 | Instrument Specialties Co. P. O. Box 365 Euless, TX 76039 | SW | | 5002-() 5012-() 5021-() 9018-() 5017-() 9036-() 9036-1053 9031-1001 9036-3079 9036-3093 5032-3130 5032-3145 5006-1057 5001-3023 5006-3066 5032-1138 | 5006-() 5003-() 9009-() 9024-() 5029-() 5022-() 9009-1036 9031-3020 9036-3082 5032-3094 5032-3135 5034-3009 5006-1063 5006-3056 5006-3067 5032-1138 | 5007-() 5008-() 9017-() 5001-() 5032-() 5034-() 9009-3037 9036-3074 9036-3089 5032-3129 5032-3144 5006-1004 5006-3006 5006-3060 5032-1119 |
| TSO-C43 | Instrument Technology Corp. P. O. Box 20478 Dallas, TX 75229 | SW | | 2600-(0001) | 2612-(0001) | |
| TSO-C43 | Kollzman/IDC Avionics Group 170 Coolidge Avenue P.O. Box 81 Englewood, NJ 07631 | NE | | 31651-() 33982-() 33986-() 39802-() | 31655-() 33984-() 33987-() | 31657-() 33985-() 37802-() |
| TSO-C43 | Lewis Engineering Co. 238 Water St., P.O. Box 231 Naugatuck, CT 06770 | NE | Thermocouple | 17B 117B 147L2 152B 152C 152L 153L 502BL Resistance 46B 77C 147BCL 147BL 147SL 161C 162BL Ser. 163B 162CD 177BDL 163LC Ser. 162LC555 163LC554 862LC Indicators 71700-() 61100-() 61101-() 71505-() 152LC() | 49B 124B 149B 152BCL 142C Ser. 152L1000 Ser 172B 502BL10 47B 77D 147D 147DS 161B 162B 162C 163BL 162L Ser. 162LRD Ser. 162LR() 163LC502 163LC555 863LC 71701-() 162CPT 61104-() 852B() | 76B 124D A1-100 152BL 152HL Ser. 153B 172BL 622L2 77B 147B 147DL 147DSL 161BCL 162BCL Ser. 162C Ser. 177BCL 162LC Ser. 163L Ser. 162LC554 163LC553 162LC553A 610BL()(() 61001-() 61401-() 172C() |
| TSO-C43 | Penn Airborne Products Co. Industrial Blvd. Southampton, PA 16966 | NE | | 9A-375-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-----------|--|---|--|
| TSO-C43 | Ragen Data Systems, Inc. 3 Oval Drive P.O. Box 417 Central Islip, NY 11722 | NE | | DST 29-4 | | |
| TSO-C43 | Ragen Data Systems, Inc. P.O. Box 418 125 Schmitt Boulevard Farmingdale, NY 11735 | NE | | DST 1017-() | | |
| TSO-C43 | Rogerson Kratos 403 S. Raymond Ave., Bin 45 Pasadena, CA 91109 | NM | | 114.021 124-()Series 115.079 | 114.022 124.412 115.() | 115.015 126.() |
| TSO-C43 | Servo Development Corp. 235 Schmitt Blvd. Farmingdale, NY 11735 | NE | | 40-302-1 | 40-302-() | 40-302-4-099 |
| TSO-C43 | Simmonds Precision Panton Rd. Vergennes, VT 05491 | NE | | 472017 | 472020 | |
| TSO-C43 | Smiths Industries Harowe Division 255 Great Valley Parkway Malvern, PA 19355 | NE | | 2262-() | | |
| TSO-C43 *F | Smith Industries, Ltd. Aviation Division Bishops Cleeve Cheltenham, Gloucestershire England | EU | | 727MV() 764MV() 420MV() 1002MV() | 732MV() 781MV() 466MV() WL706RSA() | 762MV() 782MV() 1001MV() WL718RSA() |
| TSO-C43 | S.M.S. Instruments, Inc. 120 Marcus Blvd. Deer Park, L.I., NY 11101 | NE | | 206101 206-523 206-526 | 206102 206-524 206-528 | 206-500 206-525 |
| TSO-C43 | Universal Corporation 730 Independent Avenue Grand Junction, CO 81505 | NM-D | | Model 1000 | Model 2000 | |
| TSO-C43 | Westberg Manufacturing Co. 3400 Westach Way Sonoma, CA 95476 | NM | | K28 | K29 | |
| TSO-C43 | Weston Instruments Div. 614 Frelinghuysen Ave. Newark, NJ 07114 | NE | | 727 1122 Type 66 1122 Type 31, 33 1822 Type 228 1822 Type 229 D 96450 248357 520530 521701 521916 522149 522320 | 728 1122 Type 69 1824 Type 17 QCIP-413 1812 248358 521389 521909 521917 522220 522368 | 248261 248836 521696 521910 521918 522222 522274 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|--|------|---------------------------|---|--|-----------|
| TSO-C43a | AMETEK U.S. Gauge Division Sellersville, PA 18960 | NE | TEMPERATURE INDICATORS | VSDL-OC- 204L VSDL-OC 419J SEL-OC190W | VSDL-OC 219G SEDL-OC4AU SEL-OC19EJ | |
| TSO-C43a | Bendix Flight Systems Division Teterboro, NJ 07608 | NE | | 3911212-9002 | 3911213-9012 | |
| TSO-C43a | B & D Instruments and Avionics, Inc. 209 West Main Valley Center, KS 67147 | CE-W | | 7330 7340-006 | 7340 | 7380 |
| TSO-C43a | Collins Avionics Division Rockwell International 400 Collins Road Cedar Rapids, IA 52498 | CE-W | | ADC-850:622-7208-001 ADM-850:622-7737-001 ADC-86:622-9237-001 ASI-850A:622-8335-001, -002, -003, -010, -011, -012 ADM-86:622-9282-XXX DU-1000A:622-8047-250, -411 MFCP-1000A:622-7957-201, -401 EFD-870:622-7391-101 MEM-873:622-8009-101 | | |
| TSO-C43a | Colt Industries Lewis Electronic Instrumentation Div. 238 Water Street Naugetuck, CT 06770-0231 | NE | | 71302-() | | |
| TSO-C43a | Electronics Int'l Inc. 5289 NE Elam Young Pky #G-200 Hillsboro, OR 97124 | NM-S | | A-1, OAT, C-1 CHT C-2, CHT left & right C-4, CHT 4 Channels C-6, CHT 6 Channels CA-1, CARB/OAT C-1P-(), CHT w/Light CC-1P-(), Dual CHT w/Light EC-1, EGT/CHT E-1, EGT EC-1D, EGT/CHT Differential E-2, EGT left & right EC-2, EGT/CHT left & right E-4, EGT 4 Channels E-6, EGT 6 Channels EAC-1, EGT/OAT/CHT EAE-1, EGT/OAT/EGT E-1P-(), EGT w/light EE-1P-(), Dual EGT w/light EC-1P-(), Dual EGT/CHT w/light T-1P-(), TIT w/light TT-1P-(), Dual TIT w/light TC-1P-(), Dual TIT/CHT w/light | | |
| TSO-C43a | General Aero Products Corp. 11 Lincoln Street Copiague, NY 11726 | NE | | 86434-1 | | |
| TSO-C43a | Honeywell, Inc. Sperry Commercial Flight Systems Division 2111 N. 19th Avenue Phoenix, AZ 85306-1111 | NM-L | | 4055372-() | | |
| TSO-C43a | Howell Instruments, Inc. 3479 West Vickery Blvd. | SW | | H2902-() H2900K-400 | H2900()-(XXX) BH26255 | BH27501-1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|--|------|--------------------|---|---|--|
| | Fort Worth, TX 76107 | | | BH27504-1 | BH27504 | |
| TSO-C43a | J.P. Instruments 9621 Bay Meadow Drive Huntington Beach, CA 92646 | NM-L | | CHT-100-() Series EGT-100-() Series | CHT-200-() Series EGT-200-() Series | |
| TSO-C43a | King Radio Corporation 400 N. Rogers Road Olathe, KS 66062 | CE-W | | KDC-481:065-0082-00, -04 KST-488:066-3080-00/-01/-02/-03 | | |
| TSO-C43a | Kolleman/IDC Avionics Group 170 Coolidge Avenue P.O. Box 81 Englewood, NJ 07631 | NE | | MDL 41813-() | | |
| TSO-C43a | Kratos Aviation Products 403 S. Raymond Avenue Pasadena, CA 91109 | NM-L | | 124-1211 | | |
| TSO-C43a | Penn Airborne Products Co. Industrial Boulevard Southampton, PA 18966 | NE | | 1300: 9A1120() 1400: 9A1070() | | |
| TSO-C43a | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | ASI-850A:622-8335-001, -002, -003, -010, -011, -012 ECD-870:622-8529-002, -003, -004, -005, -008 DU-1000A:622-8047-411 ADM-85:622-8692-011 | | |
| TSO-C43a | Schlumberger Industries Weston USA Transducer Div. 614 Frelinghuysen Ave. Newark, NJ 07114-1384 | NE | | 522459 522945 | 522848 | 523244 |
| TSO-C43a | Shadin Company, Inc. 14280 N. 23rd Ave. Plymouth, MN 55441-3635 | NE | | 913200 | | |
| TSO-C43a | Westburg Manufacturing, Inc. 3400 Westach Way Sonoma, CA 95476-9710 | NM-L | | Model K30 Model K34 Model K35011 | Model K31 Model K36 713-40() | Model K32 Model K33 713-70() |
| TSO-C44 | Ametek Aerospace Products, Inc. 50 Fordham Road P. O. Box 204 Wilmington, MA 01887 | NE | FUEL FLOWMETERS | 8DH64 8DJ121 8DJ127 8DJ170 8TJ50 8TJ61 8TJ88 8TJ100 | 8DJ88 8DJ125 8DJ136 8DJ171 8TJ51 8TJ77 8TJ89 8DJ96 | 8DJ97 8DJ126 8DJ142 8DJ180 8TJ54 8TJ85 8TJ95 |
| TSO-C44 | Bendix Instrument & Life Support Div Hickory Grove Rd. Davenport, IA 52802 | CE-W | | 9061 9130 9151 37001 37115 | 9100 9133 9152 37100 | 9112 9136 36722 37101 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|--------------------|---|--|--|
| TSO-C44 | Bendix Flight & Engine Inst. Div. South Montrose, PA 18843 | NE | | 6200 Ser. 6801 Ser. 25401 Ser. 27300 Ser. | 6300 Ser. 25101 Ser. 25601 Ser. 3581441-8001 | 6400 Ser. 25104 Ser. 25609 Ser. 9133-2581 |
| TSO-C44 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | 3581400-0001 3911212-9002 | | |
| TSO-C44 | Hartman Systems Co. Inc. 360 Wolf Hill Rd. Huntingdon Station, NY 11746 | NE | | DR-2PD(720-) VS-2PD(728-) | | VS-2PD(684-) |
| TSO-C44a | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | FUEL FLOWMETERS | 65840-() 33143 | 66840-() | 651035-0101 |
| TSO-C44a | Aero Tech, Inc. 10940 Dennis Rd. Dallas, TX 75620 | SW | | 15-2003-00E-S | | |
| TSO-C44a | AiResearch Manufacturing Company of California 2525 West 190th Street Torrance, CA 90509 | NM | | 2101254-4() | | |
| TSO-C44a | Ametek U.S. Gauge Division 900 Clymer Avenue Sellersville, PA 18960 | NE | | VSDL-OC408A VSDL-OC208B | VSDL-OC208A SEL-OC8G | |
| TSO-C44a | Ametek Aerospace Products, Inc. 50 Fordham Rd. P. O. Box 204 Wilmington, MA 01887 | NE | | 8DJ64C8A 8DJ88LWE 8DJ88GAB 8DJ121GAD 8DJ125()()()-5 8DJ125LWE 8DJ125LAA 8DJ125LWX 8DJ125LWK 8DJ125LXF 8DJ125LXE 8DJ125LXD4 8DJ126LWE 8DJ126LXA() 8DJ127LWR 8DJ142LAA 8DJ142GAC 8DJ142LWZ 8DJ170LWA 8DJ170LWN 8DJ180LWD 8DJ180LWC 8DJ180LWG 8TJ51G8B 8TJ61GBR() 8TJ64GCA 8TJ64GBM 8TJ64GCV 8TJ77GAA 8TJ85GAK 8TJ85GAT 8TJ85GAB | 8DJ64G8C 8DJ88LWF 8DJ88LWC 8DJ121LWG() 8DJ125LWF 8DJ125LAB 8DJ125LXA 8DJ125LWH 8DJ125LXG 8DJ125LWT 8DJ125LKD4 8DJ126LWN 8DJ126LXB() 8DJ127LWD 8DJ142G8C 8DJ142LWV 8DJ142LXG 8DJ170LWG 8DJ171LWA 8DJ180LWB 8DJ180LPC 8TJ50GAY 8TJ54GAD 8TJ64 8TJ64GAF 8TJ64GBR 8TJ64GCE 8TJ64GBW 8TF64GDT 8TJ85GBA 8TJ85GAS 8TJ88GAN | 8DJ64GAF 8DJ88LWK 8DJ99 8DJ125LWC 8DJ125LWG 8DJ125LWB 8DJ125LWY 8DJ125LXB 8DJ125LWR 8DJ125LXD 8DJ125LWS 8DJ125LXE4 8DJ126GAB 8DJ127LWH 8DJ136LAA 8DJ142GBL 8DJ142LWM 8DJ142GAD() 8DJ170LWL 8DJ171LWD 8DJ180LPB 8DJ180LWE 8TJ50GBZ 8TJ61GAX 8DJ64GBP() 8TJ64GBK 8TJ64GBL 8TJ64GCC() 8TJ64GBK 8TJ85GAP 8TJ85GAV 8TJ85GAZ 8TJ88GAE |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|--|
| | | | | 8TJ88GAF 8TJ88GAR 8TJ88GAV 8TJ88GAP 8TJ88GAN1 8TJ88GBN1 8TJ88GBN 8TJ88GAB 8TJ88GAD 8TJ89GAN 8TJ95GAA 8TJ95GAB 8TJ100GAD |
| TSO-C44a | Ametek Aerospace Prod., Inc. Seattle Support Center 4560-15th Avenue NE Redmond, WA 98052-5374 | NM-S | | 8DJ125XXXX 8DJ170XXXX 8DJ171XXXX 8DJ180XXXX 8TJ64XXX 8TJ50XXXX 8TJ85XXXX 8TJ88XXXX 8TJ95XXXX 8TJ100XXXX |
| TSO-C44a | Arnav Systems, Inc. 16100 S.W. 72nd Avenue Portland, OR 97224 | NM-L | | FUELGARD FUELTRON IG-() Series FUELTRON IP-() Series FUELTRON IIIK-() FUELTRON IPT-() FUELTRON IIIG-() FUELTRON IIIP-() FUELTRON IIII-() FUELTRON IK-() FUELTRON IIIPT-() |
| TSO-C44a | Ayres Corporation P.O. Box 3090 Albany, GA 31708-3201 | CE-A | | S2EEG-T63 |
| TSO-C44a | Bendix Flight Systems Div. Teterboro, NJ 07608 | NE | | 3571214-6001, -9001 3809591-1 |
| TSO-C44a | Bendix Instruments & Life Support Hickory Grove Rd. Davenport, IA 52808 | CE-W | | 3265011-() 3268010-() 3268014-() 3265013-0701 |
| TSO-C44a *F | Canadian Marconi Co. 2442 Trenton Avenue Montreal, Quebec Canada H3P1Y9 | NE | | 730-14:P/Ns 463-689-(), 418-107-() 418-082-(), 418-120-(), 418-193-() 418-085-() CMA730-14 100-476-675-120 |
| TSO-C44a | Collins Avionics Division 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | DU-1000A:622-8047-250, -411 MFCP-1000A:622-7957-201, -401 EFD-870:622-7391-101 MEM-873:622-8009-101 |
| TSO-C44a | Eldec Corporation 16700 13th Ave. West P.O. Box 100 Lynnwood, WA 98046-0100 | NM | | 9-112-() 9-114-() 9-115-() 9-115-19 9-116-() 9-118-() 9-127-() 9-127-58 9-138-() 9-138-16 9-127-12 9-217-12 9-231-02, -03, -06, -05, -07, -10, -13, -23 9-328-() 9-394-01 9-422-01 9-328-32 9-441-08 9-464-02, -12, -14, -15, -16, -21, -30, -25, -32, -33, -40, -41, -56, -60, -62, -66, -67, -68, -75 |
| TSO-C44a | Gull Airborne Instruments, Inc. 55 Engineers Road Smithtown, NY 11787 | NE | | 267-937-(XXX) 360-929-(XXX) 151-906-(XXX) 218-913-(XXX) 302-922-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|--|--|--|
| TSO-C44a | Hartman Systems Co., Inc. 360 Wolf Hill Rd. Huntingdon Station, NY 11746 | NE | | DR-2PD(685-) | VS-2PD(638-) | |
| TSO-C44a | Howell Instruments, Inc. 3479 W. Vickery Boulevard Fort Worth, TX 76107 | SW | | H930-() | | |
| TSO-C44a | Instrument Technology Corp. P. O. Box 20478 Dallas, TX 75229 | SW | | 15-2003-00E-S | | |
| TSO-C44a *F | Kent Meters, Ltd. Luton, Bedfordshire England | EU | | GKT.30 | GKT.40 | |
| TSO-C44a | Kollzman/IDC Avionics Group 170 Coolidge Avenue P.O. Box 81 Englewood, NJ 07631 | NE | | 585-31653-() | 37470-() | 37804-() |
| TSO-C44a | McGraw-Edison Company Edison Electronics Grenier Municipal Airport Manchester, NH 03103 | NE | | 9801-33-() | | |
| TSO-C44a | Ragen Data Systems, Inc. P.O. Box 418 125 Schmitt Blvd. Farmingdale, NY 11735 | NE | | TFF917(-1), (-2), (-3), (-4) DSF1549(-3) DSF1546(-1) SCF1548(-2) DSF1291-(2), -(3), -(5), -(6) 3268011-(0101) SCF1788-() 3265011-(0301) 3265013-(0601) 3265013-(0801) 3268011-1001 TFF1573 TFF-1573-2 3265001-(0401) 3268005-() | | |
| TSO-C44a | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | ECD-870:622-8529-002, -003, -004, -005, -008 DU-1000A:622-8047-411 | | |
| TSO-C44a | Shadin Company, Inc. Suite 221 6950 Wayzata Blvd. Minneapolis, MN 55426 | CE-C | | 660525 660526 660530 660534 680503 910503 910514 910523 910526 910533 910536 911216 911219 912002 912005 | 660526 660527 660531 660535 910501 910504 910521 910524 910531 910534 911214 911217 911501 912003 912006 | 680502 660529 660532 680501 910502 910510 910522 910525 910532 910535 911215 911218 912001 912004 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|--|--|--|--|
| TSO-C44a | Shadin Company, Inc. 14280 N. 23rd Ave. Plymouth, MN 55441-3635 | CE | | 910551 910554 910557 910572 910575 910578 910528 910537 912051 912054 912057 912063 912066 | 910552 910555 910558 910573 910576 910520 910529 910538 912052 912055 912061 912064 913200 | 910553 910556 910571 910574 910577 910527 910530 910539 912053 912056 912062 912065 |
| TSO-C44a | Sherwood Co. of Oklahoma P. O. Box 2125 Tulsa, OK 74101 | SW | | 3000 | | |
| TSO-C44a | Silver Instruments 4740 Ridge Drive, NE. Salem, OR 97307 | NM | | Fueltron IPT-() Fueltron IIIPT-() Fueltron IIIP() Fueltron IIIL-() Fueltron IIIP() Fueltron IL-() | Fueltron IG() Fueltron IIIG() Fueltron IL-() Fueltron IIIG() Fueltron IP() Fueltron IIIL-() | |
| TSO-C44a | Simmonds Precision Products Panton Road Vergennes, VT 05491 | NE | | 393002-009 | | |
| TSO-C44a | Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714 | NM | | CFS2000()/1000() FT-100/200:702048() CFS-1002/2002:702049-() CFS-1002/2002:702049-() CFS-2000/1000 CFS-2000/1000:701921 CFS-1001/2001:702047() FT-100/200:702048() P/N 702313-() | CFS1001()/2001() FT-101:702165-() | |
| TSO-C44a | United Instruments, Inc. 3625 Conotara Avenue Wichita, KS 67226 | CE-W | | 6400:6411()-() 6400:6414()-() 6400:6422()-() 6510:6511()-() 6520:6521()-() 6520:6525()-() 6523-()-() 6532()-() 6534()-() | 6400:6412()-() 6400:6421()-() 6400:6424()-() 6510:6512()-() 6520:6523()-() 6521-()-() 6525-()-() 6533-()-() | |
| TSO-C44a | XO Technologies, Inc. 28020 Avenue Stanford Valencia, CA 91355 | NM-L | | SC14-() PC800 | SC10-() | SC12-() |
| TSO-C45 | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | MANIFOLD PRESSURE INDICATING INSTRUMENTS | 65150-() 66350-() | 65350-() 66355-() | 651035-0101 |
| TSO-C45 | Aircraft Instrument & Development, Inc. 317 E. Lewis St. Wichita, KS 67202 | CE-W | | 27-1000-() 51-3120-() 53-6120-() | 27-2000-() 53-3120-() 21M102() | 21-1000-() 51-6120-() |
| TSO-C45 | Bendix Flight & Engine Instr. Div. | NE | | 6200 Ser. 25101 Ser. | 6300 Ser. 25401 Ser. | 6400 Ser. |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|--|---|
| | South Montrose, PA 18843 | | | |
| TSO-C45 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 1U028-()-() 1U028-005-() |
| TSO-C45 | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Hwy. S. Merrimack, NH 03054 | NE | | 728FU-6-04 728FX-4-054 A33253-10-001 |
| TSO-C45 | MacLeod Instrument Corp. Sub. of Aerosonic Corp. P. O. Box 5163 Clearwater, FL 33518 | CE-A | | 520-() 650-() 735-() 702-() 950-() 1020-() |
| TSO-C45 | Production Research Corp. Cummings & Sander 6426 San Francisco Rd. Glendale, CA 91209 | NH | | SP-37-()-()-() SP-39-()-()-() |
| TSO-C45 *F | Tokyo Aircraft Instrument Co 1600 Izumi, Komee-machi Kitatama, Tokyo Japan | NH | | PM-41-1A PM-41-11 PM-41-11CA PM-41-11FA PM-41-11FB PM-42-1A PM-42-11 PM-42-11CA PM-42-11CB PM-42-11DA PM-42-11DB PM-42-11DC PM-42-11DD PM-42-11DE PM-42-11DF PM-42-11FA PM-42-11FB PMF-41-11() PMF-41-21() |
| TSO-C45 | United Instruments, Inc. 2415 S. Glendale Wichita, KS 67210 | CE-W | | MANIFOLD PRESSURE 6111()() 6112()() 6121()() 6122()() MANIFOLD/FUEL PRESSURE 6311()() 6312()() 6313()() 6331()() 6332()() 6333()() 6300 6411()-() 6412()-() 6414()-() 6421()-() 6422()-() 6424()-() |
| TSO-C46 | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | MAXIMUM ALLOWABLE AIRSPEED INDICATOR SYSTEMS | 20130-2114 21142 SK-30-MC SK-30-MC-1L SK-40 SK-40-10 SK-40-10-1 S65K-AVU-10 S65K-L-7 S65K-L7-30 S65K-L7-30-2 MS-42-1LB MS-42-1LB-4 MS-42-1LB-6 MS-42-1LB-8 MS-42-1LB-6-10 SK-40-() MS-42-1LB-15 20140() MS-42-1LB-6-30 |
| TSO-C46 | Avionix 8 Romanelli Street South Hackensack, NJ 07606 | NE | | 2C13002B1() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | | | |
|---------------|--|------|--|--|---|--|--|--|
| TSO-C46 | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Hwy. S. Merrimack, NH 03054 | NE | | 856F Ser. 3462 3739 A27745 10 007 A27745-10-011 A32561-10-021 A3390-()-()-() A34635-10-1 - A35111 10 003 A36227-10-034 A3946-()-()-() A41019-()-() A4144()-()-() A4186-()-()-() B34627 10 043 B34635 10 024 B41597()-()-() C31835 10 011 | 1214DX-07 3463 35033-10-001 A27745-10-010 A32561-10-001 A32561-10-011 A34627-10-1 - A34737 10-011 A3615()-()-() A36995-10-001 A4106-()-()-() A4143-()-()-() A41597-()-() B34075 10 004 B34627 10 046 B3807()-()-() C31834 10 002 C31835 10 012 | 1701DX-01 3622 83615 | | |
| TSO-C46 | Lear Siegler Instrument Division 4141 Eastern Ave. Grand Rapids, MI 49508 | CE-C | | B0200-81124 B0201-81110 B0202-81109 B0204-81104 B0207 B0207-81904 B0243-81103 B0243-81107 B0243-81120 B0243-81128 B0243-81911 B0243-81937 B0243-81924 B0245-81910 B0248-81903 | B0200-84109 B0202-81105 B0202-81111 B0204-81105 B0207-81104 B0243-71101 B0243-81104 B0243-81113 B0243-81122 B0243-81129 B0243-81923 B0243-82128 B0245-81107 B0245-82107 B0248-81135 | 80201() 80202-81108 80204() 80204-81108 80207-81106 80243-81102 80243-81106 80243-81119 80243-81126 80243-81132 80243-81934 80243-81935 80245-81112 80248-81901 C0201() | | |
| TSO-C46 *F | Smiths Industries, Ltd. Aviation Division Bishops Cleeve Cheltenham, Gloucestershire England | EU | | 100AMA() | 200 AMA() | | | |
| TSO-C46a | Aero Mechanism, Inc. 20960 Knapp Street Chatsworth, CA 91311 | NM-L | MAXIMUM ALLOWABLE AIRSPEED INDICATOR SYSTEMS | Model 8502-() | | | | |
| TSO-C46a | Aerosonic Corporation P.O. Box 4627 Clearwater, FL 34618 | CE-A | | 20240() | 21140-() | 26135-1109 | | |
| TSO-C46a | AMETEK/U.S. Gauge 900 Clymer Ave. Sellersville, PA 18960 | NE | | AW2829()()() | | | | |
| TSO-C46a | Avionix Corporation 8 Romanelli Avenue South Hackensack, NJ 07606 | NE | | 2C130() | 2C131() | 3C175() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|-----------|---|--------------|---------------|
| TSO-C46a | Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | ASI-80A:622-5349-001 thru -008, -011 thru -018 ASI-80B:622-5350-001 thru -008, -011 thru -018 ASI-80G:622-5354-011 thru -018 ASI-80E:622-5353-001 ADC-80M:622-7576-521/-554 ADC-80R:622-8070-099, -345 ADC-80Q:622-7577-799 ADC-81A:622-4401 ADC-82A:622-6475-001 thru -006 ADC-82C:622-8329-099 ADC-82L:622-8015-012, -013, -099, -399 ADC-86:622-9237-001 ADC-850:622-7208-001 ADM-86:622-9282-XXX ADM-850:622-7737-001 ADS-81:ADC-81A, ASI-80E HSI-60A:622-2293-001 thru -008, -001 thru -108 MSI-80B:622-3711-001 thru -068 HSI-80C:622-4382-001 thru -008, -001 thru -018, -024 MSI-80D:622-6105-024, -003/-013/-023/ -033/-043/-053 MSI-80G:622-7665-011 thru -018 | | |
| TSO-C46a | Collins General Avn. Div. Rockwell International Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-W | | ADC-80H | ADC-80J | ADC-80K |
| | | | | ADC-80M | ADS-80 | ADS-80F |
| | | | | MSI-80A | MSI-80B | |
| TSO-C46a | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | 2594621-() | 2594466-() | |
| | | | | 403891-() | 4057800-() | |
| | | | | HG280D-() | HG480B() | |
| TSO-C46a | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 5353 W. Bell Road Glendale, AZ 85038 | NM | | 4018366-() | 7002860-() | 7005358-() |
| | | | | SG-815-816:7011674 | | |
| | | | | HG-815-816:7011675 | | |
| | | | | MG-81, -816:7011675-() | | |
| TSO-C46a | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Systems Div. P.O. Box 21111 Phoenix, AZ 85036-1111 | CE-C | | HG280D-() | HG280D80-() | HG480B() |
| TSO-C46a | Jaeger *F Div. Aeronautique 92303 Levallois - Perret France | EU | | 64010-4()() | | 64060-1()() |
| TSO-C46a | Kearflex Engineering Co. 66 Cypress Street Warwick, RI 02888 | NE | | 2152 | | |
| TSO-C46a | King Radio Corporation 400 North Rogers Road Olathe, KS 66062 | CE-W | | KDC-481:065-0082-00, -04 | | |
| | | | | KAI-486:066-3078-00-() | | |
| | | | | KAI-487:066-3079-00, -01, -02, -03, -10, -11, -12, -13, -14 | | |
| TSO-C46a | Kolleman/IDC Avionics Group | NE | | 18220-() | 21663-() | 534-23070-() |
| | | | | 24030-() | 25850-() | 21305-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|--|
| | 170 Coolidge Ave. P.O. Box 81 Englewood, NJ 07631 | | | 26107-() 24136-() 26320-() 26465-() 26325-() 25300-() 26700-() 29846-() 30680-() 30979-() 31480-() 31500-() 32755-() 32815-() 33025-() 33075-() 33115-() 35250-() 35348-() 35405-() 35415-() 35770-() 35900-() 36790-() 37230-() 37277-() 37788-() 38105-() 38106-() 39310-() 39846-() 39939-() 39948-() 39310-() 40590-() 40807-() 43400-() 44105-() 47230-() 49939-() |
| TSO-C46a | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Hwy. S. Merrimack, NH 03054 | NE | | A4201(-)(-)(-) A4292(-)(-)(-) A4321(-)(-)(-) A4144910011 |
| TSO-C46a | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | ASI-850A:622-9335-001, -002, -003, -010 -011, -012 MSI-80F:622-6785-021 ADM-85:622-8692-011 ASI-850A:622-8335-001, -002, -003, -010, -011, -012 |
| TSO-C46a | Smiths Industries Aerospace & Defense Systems, Inc. 255 Great Valley Parkway Malvern, PA 19355 | NE | | 2083-() 2084() 2086-01-1 |
| TSO-C46a | Smiths Industries 4141 Eastern Ave. Grand Rapids, MI 49508-8727 | CE-C | | B0200 B0200-81104 B0200-81105 B0200-81108 B0200-81110 B0200-81111 B0200-81117 B0200-81118 B0200-81119 B0200-81120 B0200-81121 B0200-81122 B0200-81127 B0200-81129 B0200-81903 B0200-81904 B0200-81914 B0200-81928 B0202-81904 B0202-81905 B0202-81108 B0202-81113 B0202-81116 B0202-81117 B0243-81953 B0204-81106 B0243() B0243()() B0243-81124 B0243-81131 B0243-81145 B0243-81108 B0243-81925 B0243-81105 B0243-81108 B0243-81120 B0243-81124 B0243-81126 B0243-81128 B0243-81129 B0243-81131 B0243-81144 B0243-81135 B0243-81142 B0243-81143 B0243-81144 B0243-81145 B0243-81925 B0243-81953 B0245() B0245-81104 B0245-81110 B0245-81101 B0247() B0247-81101 B0247-81105 B0247-81106 B0247-81107 B0248 B0248-81105 B0248-81901 B0248-81903 C0245-81101 |
| TSO-C46a *F | Smiths Industries, Ltd. Aviation Division Bishops Cleeve Cheltenham, Gloucestershire England | EU | | 104AMA() 256AS() 257AS() 30DASC() 505AMA() 604AMA() 605AMA() 606AMA() WL106AMA() WL/107AMA() WL401AMA() WL/508AMA() WL/509AMA() WL602AMA() |
| TSO-C46a *F | Smiths Industries Limited Cheltenham, Gloucestershire United Kingdom | EU | | 320AS() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--|--|--|---|
| TSO-C46a *F | Societe Jaeger 2 rue Baudin 92303 Levallois - Perret France | EU | | 63230-03()-() | | |
| TSO-C46a *F | Thomson-CSF 31 rue Camille De Desmoulins, 92131 Issy-les-Moulineaux, France | EU | | 64010-4(XX)-(X) 64032-2(XX)-(X) | 63230-03(X)-(X) 64060-1(XX)-(X) | |
| TSO-C46a | United Instruments, Inc. 3625 Comotara Avenue Wichita, KS 67226 | CE-W | | 8220 8240 | 8230 8500()-() | 8235 |
| TSO-C47 | Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | PRESSURE INSTRUMENTS - FUEL, OIL, AND HYDRAULIC | 65520-() 78200-() | 65620-() 32678 | 65945-() 32679 |
| TSO-C47 | Aerosonic Corporation Dallas Division 3312 Wiley Post Rd. Carrollton, TX 75006 | SW | | 3100-0001 | | |
| TSO-C47 | Aircraft Instrument & Development, Inc. 535 S. Topeka Wichita, KS 67202 | CE-W | | 18-1000-() 21-1000-() 51-2110-() 51-5110-() 53-2110-() 53-5110-() | 19-1000-() 21M102() 51-3110-() 51-6110-() 53-3110-() 53-6110-() | 19-2000-() 51-1110-() 51-4110-() 53-1110-() 53-4110-() |
| TSO-C47 | Allied-Signal Aerospace Co. Guidance Systems Division Counter Operations 375 N. Lake St. Boyer City, MI 49712 | CE-C | | 18-1105 18-1637 18-1814 18-2100 18-2105 | 18-1108 18-1750 18-1815 18-2101 18-2106 | 18-1284 18-1752 18-1835 18-2104 |
| TSO-C47 | AMETEK/U.S. Gauge 900 Clymer Ave. Sellersville, PA 18960 | NE | | SEDL-OC3C SEL-OC3H SR-() SR-4N SRD-0() SRDW-14A SRL-0() SRL-0 Ser. SED-03A SEL-OC4A SEL-OC4D ST-3() ST-7 ST-103() ST-104M ST-207 ST-504() ST-7T Ser. SRDWL-C4A ST-107J Ser. AW1817AB10 VT-0303F VT-0306(D) VT-0107F VT-0304G VIL-0(C)4 (A) VIL-0()4()() | SEL-OC3F SEL-OC3J SR-0() SR-157B SRDL-() SRDW-14B SRL-03A SRL-07 Ser. SEL-OC3A SEL-OC4B SEDL-OC3A ST-4 ST-7() ST-104 ST-107 ST-207() ST-504G ST-103B Ser. SRDWL-C4B AW-2-17-H VT-0301(a) VT-0304F VT-0308(A) VT-0303C VT-0304E | SEL-OC3G SEL-OC4P SR-3P SRD-() SRDL-0() SRL-() SRL-04A ST-3 SEL-OC3B SEL-OC4C SEDL-OC4A ST-4() ST-103 ST-104() ST-107() ST-504 ST-507() ST-104F Ser. SRDL-C7P AW-2-17-J VT-0304(b) VT-0306(A) VT-0107(B) VT-0304C VI-0(C)3 (B) VIL-0()3()() VIL-0()7()() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|--|
| | | | | VIL-0(C)-7 (B) VIL-0C3C VIL-0C4C VIL-0-(6)3 (B) VIL-0C42 SEDL-0C7B VIL-0C4F VIL-0C4E VI-04A VIL-0C7E VI-0107H VIL-0()4()() VI-0303G VI-0107K VSDL-OC204A VSDL-OC219A VSDL-OC204E VSDL-OC204D VSDL-OC204C, -OC219C, -OC419E VSDL-OC204K, 203B, 207A, 204L SEL-OC4G, -OC4H, -OC4J, -OC4K, -OC4AD, -OC4T, -OC4U SEDL-OC4G, -OC4K, -OC4N SEDL-OC4AU SEDL-OC7P PT-0104C PT-0104A PT-0104G |
| TSO-C47 | Armtec Industries, Inc. Manchester Municipal Airport Manchester, NH 03103 | NE | | 195-() 217-() 273-() 290-() 296-() 332-() 396-() 397-() 418-() 438-() 458-() 468-() 496-() 497-() 718-() 617-() |
| TSO-C47 | Atlantic Scientific Corp. 100 Brook Ave. Deer Park, NY 11729 | NE | | 206-351-001 206-351-0001 206-351-0010-5 206-351-0010-4 206-351-0010-3 206-351-0010-2 206-351-0010-1 206-351-0010-6 |
| TSO-C47 | B & D Instruments, Inc. 209 West Main Valley Center, KS 67147 | CE-W | | 1101 0212-003, 1129-() 5002-003 7330 7380 |
| TSO-C47 | Bendix Flight & Engine Inst. Div. South Montrose, PA 18843 | NE | | 344-()-()-() 6000 Ser. 7600 Ser. 7700 Ser. 25000 Ser. 26000 Ser. 27000 Ser. 3567749-6502 3567749-6503 3567749-6504 3567758-6501 |
| TSO-C47 | Bendix Flight Systems Division Teterboro, NJ 07608 | NE | | 3567401-3001 3567403-3001 3567404-7001 3567709-7202 3567758-6503 356-7407-0101 3561210-7021 3571110-6001 3571213-5003 3571221-2001 3571310-0004 3809593-1 3856158-1 3567749-9502 3571212-003 |
| TSO-C47 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | 3581320-1() |
| TSO-C47 | Bendix/Courter, Inc. 375 North Lakes Street Boyer City, MI 49712 | CE-C | | 18-1842-7 |
| TSO-C47 | Benz Sales and Engineering 8900 Trinity Blvd., Suite 101 Hurst, TX 76053 | SW | | 206-306 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-----------|-------------------------------|------------------|----------------|
| TSO-C47 | Benz Sales Company P.O. Box 183300 Fort Worth, TX 76118-3300 | SW | | BSE-206-30G-EMI | | |
| TSO-C47 | Bourns, Inc. Instrument Division 6135 Magnolia Avenue Riverside, CA 92506 | NM | | 2500 | | |
| TSO-C47 *F | Canadian Marconi Co. 2442 Trenton Avenue Montreal, Quebec Canada H3P1Y9 | NE | | 730-14: P/Ns | 418-106-() | 418-099-() |
| | | | | 463-692-() | 418-120-() | 418-193-() |
| | | | | 418-085-() | 100-476-675-120 | |
| | | | | CMA 730-14 | | |
| TSO-C47 | Clifton Division Litton Systems, Inc. 5100 State Rd. Drexel Hill, PA 19018 | NE | | 9807-56() () | | 9811-19() () |
| TSO-C47 | Collins Avionics Division 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | DU-1000A:622-8047-250, -411 | | |
| | | | | MFCP-1000A:622-7957-201, -401 | | |
| | | | | EFD-870:622-7391-101 | | |
| | | | | MEM-873:622-8009-101 | | |
| TSO-C47 | Consolidated Controls Corp. 15 Durant Avenue Bethel, CT 06801 | NE | | 41SG107-() | | |
| TSO-C47 | Data Instruments, Inc. 4 Hartwell Place Lexington, MA 02173 | NE | | AB-()SCD#85 | | |
| TSO-C47 *F | Druck Ltd. Groby, Leicestershire England | EU | | PDCR 320 | PDCR 330 | PDCR 340 |
| TSO-C47 | Edcliff Instruments 13100 Telfair Ave. Sylmar, CA 91342 | NM | | 4-901-() | 4-910-() | 4-931 |
| TSO-C47 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 22-111 | 22-168() | 22-864() |
| | | | | 169() | 910() | 914 |
| | | | | 1U028-003-() | 1U028-004-() | |
| | | | | 1U028-005-() | 1U378 | 1U417 |
| TSO-C47 | Eldec Corporation 16700 13th Avenue West Lynnwood, WA 98036 | NM | | 9-395-03 | | |
| TSO-C47 | General Aero Products Corp. 11 Lincoln Street Copiague, NY 11726 | NE | | 86432-101 | 86432-102 | |
| TSO-C47 | Gull Airborne Instruments, Inc. 55 Engineers Road Smithtown, NY 11787 | NE | | 200-071-003 | 203-002-() | |
| | | | | 203-022-() | 203-023-003 | |
| | | | | 215-009(XXXX) | 261-914-XXX(012) | |
| | | | | 261-914-XXX-014 | 261-926-XXX(001) | |
| | | | | 302-915-XXX | 371-005-() | |
| | | | | 371-007-() | 371-903-XXX(003) | |
| | | | | 371-903-004 | 371-908-001 | |
| | | | | 371-909-001 | 371-909-004 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|---|----|-----------|---|---|--|
| TSO-C47 | Gulton-Servonic A Mark IV Company 1644 Whittier Ave. Costa, Mesa, CA 92627 | NM | | 451338A | 451338B | 451338E |
| TSO-C47 | Hartman Systems Co. 360 Wolf Hill Rd. Huntingdon Station, NY 11746 | NE | | VS-2PB(623-) VS-25C(726-1) VS-2PC(751-) | VS-2SC(626-) VS-2SC(727-1) VS-2PC(752-) | VS-4PC(645-) VS-2PC(753-) |
| TSO-C47 | Howell Instruments, Inc. 3479 West Vickery Blvd. Fort Worth, TX 76107 | SW | | H940-() | | |
| TSO-C47 | Instrument Specialties Co. P. O. Box 365 Euless, TX 76039 | SW | | 4301-() 4321-() 9016-() 9019-() 9030-() 4358-() 4337-() 4308-3112 9009-3037 9036-3074 9036-3089 | 4306-() 4322-() 9017-() 4331-() 9034-() 9036-() 4308-1114 4308-3113 9036-3049 9036-3079 9036-3093 | 4313-() 9009-() 9024-() 4332-() 4344-() 9041-() 4344-3107 9009-1036 9036-3056 9036-3082 |
| TSO-C47 | Instrument Technology Corp. P.O. Box 20478 Dallas, TX 75229 | SW | | 3100-(0001) 124.043 | 124.041 124.044 | 124.042 124.045 |
| TSO-C47 | Kollzman/IDC Avionics Group 170 Coolidge Avenue Englewood, NJ 07631 | NE | | 31656-() | 31658-() | MDL 41813-() |
| TSO-C47 | Kulite Semiconductor 1039 Hoyt Avenue Ridgefield, NJ 07657 | NE | | APT-(XX)-1000-(YYY), (XX-75), (YYY-4000A) APT-(XX)-1000-(YYY), (XX-76), (YYY-100D) APT-75-1000-4000A APT-20-1000-XXX APT-51-1000-XXX APT-76-1000-100D APT-129-1000-150G APTE-6-1000-XXX APTE-(24)-1000-(5000) APTE-28RT1-1000-1000 APTE-28RT1-1000-100G APTE-51-1000-XXX BM-25-1100-300A ITQS-875 222-375-019(---) IPT-19-1000-() IPT-20-1000-() IPT-20-1000-250G IPT-20-1000-500G IPT-20B-1000-5000 IPT-20C-1000-60G/100G/250G IPT-24-1000-() IPT-36-1000-45G IPT-37-1000-1500A IPT-43-1000-50G IPT-44-1000-100G IPT-49-1000-5000A IPT-49-1000-4000A IPT-(XX)-1000-(YYY);(XX-61,YYY-3000) IPTE-2-1000-200G IPTE-3-1000-4000A IPTE-6-1000-100G IPTE-6-1000-200G IPTE-6-1000-3000A IPTE-7-1000-3000A IPTE-20-1000-30G/100G/115G/150G/2000G IPTE-51-1000-70D IPTE-51-1000-80D IPTE-(XX)-1000-(YYYY);(XX-16,YYYY-4000A) IPT-20RT-1000-250G IPT-20RT1-1000-80G IPT-20RT1-1000-100G IPT-20RT1-1000-250G IPT-20RT1-1000-150G IPT-24RT1-1000-190G IPT-24RT1-1000-200G IPT-24RT1-1000-250G IPT-20RT1-1000-30G | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|-----------|--|
| | | | | IPT-(XX)-1000-(YYY) -53RTI-1000-100C -53RTI-1000-150G -53ART1-1000-70G -53ART1-1000-150G |
| TSO-C47 | Kulite Semiconductor Products, Inc. One Willow Tree Road Leonis, NJ 07605 | EA | | APTE-7KBS-1500-200G APTE-139KBS-1000-1500SG APTE-6KBS-1000-100G, -200G, 3000A APTE-7KBS-1000-3000A HKM-74-375-4500SG APT-141-1000-220D APTE-HKM-74-375-4500SG APTE-138-50G, -100G, -150G BM-25-1100-300A |
| TSO-C47 *F | Labem Company 18, rue Camille Pelletan 92120 Montrouge, France | EU | | TC:53() () () 30-57() () () |
| TSO-C47 | The Lewis Engineering Co. 238 Water Street Naugatuck, CT 06770 | NE | | 162CPT 163D() 163LCP 162LCP() 604RL-() 61441-() 61541-() 162CDP-() |
| TSO-C47 | MacLeod Instrument Corp. Sub. of Aerosonic Corp. P.O. Box 5163 Clearwater, FL 33518 | CE-A | | 520-() 735-() 1020-() |
| TSO-C47 | Magnetek Transducers Prod. 650 Easy Street Simi Valley, CA 93065 | NM | | SP 100() |
| TSO-C47 | Penn Airborne Products Co. Industrial Boulevard Southampton, PA 18966 | NE | | 1100: P/N 9A1110() 1300: P/N 9A1120() |
| TSO-C47 | Production Research Corp. Cummings & Sander 6426 San Francisco Rd. Glendale, CA 91209 | NM | | SP-38()-()-() SP-39()-()-() |
| TSO-C47 | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | ECD-870:622-8529-002, -003, -004, -006, -009 DU-1000A:622-8047-411 |
| TSO-C47 | Rogerson Kratos 403 S. Raymond Ave. Pasadena, CA 91109 | NM | | 50() 50761-() 50781 50784 50787 50788 50806 50815 90014-() 90027-() 90028-() |
| TSO-C47 | Shadin Company, Inc. 14280 N. 23rd Ave. Plymouth, MN 55441-3635 | NE | | 913200 |
| TSO-C47 | Simmonds Precision Panton Rd. Vergennes, VT 05491 | NE | | 472021 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|--|---|--|---|
| TSO-C47 *F | Smiths Industries, Ltd. Aviation Division Bishops Cleeve Cheltenham, Gloucestershire England | EU | | 16 ACR/CP 181PG/SB 786 MV() 1021 PG/CP 1064 PG/CP | 19 ACR/MB 783 PG/SB 792PG/SB 1024 PG/SB 1051 PG/SB | 181 PG/CP 786PG/SB 1004 PG/SB 1047 PG/SB |
| TSO-C47 | S.M.S. Instruments, Inc. 120 Marcus Blvd. Deer Park, L.I., NY 11101 | NE | | 206105 206500 206525 | 206106 206523 206526 | 206107 206524 206528 |
| TSO-C47 *F | Tokyo Aircraft Instrument 1600 Izumi, Komae-machi Kitatama-gun, Tokyo Japan | NM | | PF-4 PF-4311 PMF-41 | PF-43-1A PF-44-11 PMF-41-11() | PF-44-1A PF-43-11JA PMF-41-21-() |
| TSO-C47 | Transducers, Inc. 12140 East Rivera Road Whitten, CA 90606 | NM | | AP-69M-2000-5745 GP-69M-80-5745 GP-69M-250-5745 | | GP-69M-30-5745 GP-69M-100-5745 |
| TSO-C47 | United Instruments Inc. 2415 S. Glendale Wichita, KS 67210 | CE-W | | Fuel Pressure 6211()() 6221()() 6200 Manifold/Fuel Pressure 6311()() 6331()() 6300 | 6212()() 6222()() | 6213()() 6223()() |
| TSO-C47 | Westburg Manufacturing, Inc. 3400 Westach Way Sonoma, CA 95476-9710 | NM-L | | K37 | K38 | K39 |
| TSO-C47 | Weston Instruments (Schbumberger Industries) 614 Frelinghuysen Avenue Newark, NJ 07114 | NE | | 522147 522457 522796 523244 | 522148 522458 522797 522945 | 522456 522459 522848 |
| TSO-C47a | Instrument Specialties Company, Inc. 1111 Stanley Drive, Box 365 Eules, TX 76039 | SW | PRESSURE INSTRUMENTS FUEL, OIL, AND HYDRAULIC | 6501-3101 | 6501-3105 | |
| TSO-C48 | Energy For Independence Inc. P.O. Box 155 Holland Patent, NY 13354 | NE | CARBON MONOXIDE DETECTOR INSTRUMENTS | TM R1() | | |
| TSO-C49 *F | Advance Power, Inc. 152 East Drive Bramaleo, Ont. Canada L6T 1Z1 | NE | ELECTRIC TACH. MAGNETIC DRAG (FOR AIR CARRIER AIRCRAFT) | 32005-005 | | |
| TSO-C49 | Atlantic Scientific Corp. 100 Brook Ave. Deer Park, NY 11729 | NE | | 206-351-0001 | | |
| TSO-C49 | Bendix Flight & Engine Inst. Div. South Montrose, PA 18843 | NE | | 34107 Ser. | 34108 Ser. | 351370-6001 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|--|--|--|-------------------------------------|
| TSO-C49 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | 3581470-0() | 3581470-1() | |
| TSO-C49 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 22-285() | | |
| TSO-C49 | Gull Airborne Inst., Inc. 395 Oser Avenue Smithtown, NY 11787 | NE | | 218-904-() 224-906-() 267-960-XXX | 218-907-() 224-910-() | 218-908-() 267-951-() |
| TSO-C49 | Hartman Systems Co., Inc. 360 Wolf Hill Rd. Huntingdon Station, NY 11746 | NE | | VS-2PA(624-) | VS-2SB(625-) | VS-2PC(747-) |
| TSO-C49 | Howell Instruments, Inc. 3479 W. Vickery Boulevard Fort Worth, TX 76107 | SW | | H901()-2() | | |
| TSO-C49 | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Hwy. S. Merrimack, NH 03054 | NE | | A33243 10 001 | 850691 20304 | |
| TSO-C49 | Lear Siegler, Inc. Power Equipment Div. P.O. Box 6719 Cleveland, OH 44101 | CE-C | | H60-000 32164-000 | H60-050 | 32005-002 |
| TSO-C49 | Lewis Engineering Company 238 Water Street Naugatuck, CT 06770 | NE | | 61111-() | | |
| TSO-C49 *F | LSI/Aircraft Appliances & Equipment Ltd. 152 East Dr. Bramalea, Ontario Canada | NE | | 32005-() H60-050 32164-010 32164-013 | 32010-000 32164-000 32164-011 32164-015 | 32050-000 32164-007 32064-012 |
| TSO-C49 *F | Smiths Industries, Ltd. Aviation Division Bishops Cleeve Cheltenham, Gloucestershire England | EU | | 106 RV/SB | | |
| TSO-C49 | S.M.S. Instruments, Inc. 120 Marcus Blvd. Deer Park, L.I., NY 11101 | NE | | 206110 | | |
| TSO-C49a | Aero Mechanism 20327 Nordhoff Street Chatsworth, CA 91405 | NM | ELECTRIC TACHO- METER: MAGNETIC DRAG (FOR AIR CARRIER AIRCRAFT) | AM305-() | | |
| TSO-C49a | Aerosonic Corporation P.O. Box 4627 Clearwater, FL 33518 | CE-A | | 78035-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|----|-----------|---|--|---|
| TSO-C49a *F | Advance Power, Inc. 152 East Drive Bramalea, Ontario Ontario, Canada L6T 1Z1 | NE | | TG 255 | TG 455 | |
| TSO-C49a *F | Aircraft Appliances and Equipment Limited 150 East Drive Bramalea, Ontario, Canada L6T 1C1 | EU | | 32164-010 | | |
| TSO-C49a | AiResearch Manufacturing Company of California 2525 West 190th Street Torrance, CA 90509 | NM | | N1:2101254-1, 2101254-11 N2:2101254-2, 2100948-2 | | |
| TSO-C49a | Ametek U.S. Gauge Division 900 Clymer Avenue Sellersville, PA 18960 | NE | | HML-OC29D SEL-OC29K SEL-OC29C8 SEL-OC29CP SEL-OC29D8 SEL-OC29CP SEL-OC29DH VSDL-OC410 VSDL-OC410B VSDL-OC410L VSDL-OC410N VSDL-OC-410T 10223N01R00 | SEL-OC29A8 SEL-OC329F SEL-OC29W SEL-OC29CT SEL-OC29BT SEL-OC29CN SEL-OC29AU SETL-OC329A VSDL-OC410A-1 VSDL-OC410H VSDLOC-410W VSDL-OC410R VSTL-OC410A 10224N01R00 | SEL-OC29AH SEDL-OC329A SEL-OC29U SEL-OC29CY SEL-OC29CN SEL-OC29AU SETL-OC329D VSDL-OC410K VSDL-OC410H VSDL-OC410S 10285N01R00 |
| TSO-C49a | Ametek Aerospace Products, Inc. 50 Fordham Rd. P. O. Box 204 Wilmington, MA 01887 | NE | | 2CM9A- -4 2CM9A- -8 8DJ67A-1 8DJ67M-1 8DJ81C-1 8DJ81W-() 8DJ82B-1 8DJ120 8DJ148L-1 8DJ150- -() 8DJ162---() 8DJ176LXA1 8DJ176LZA()N2 8DJ176LZN()N1 8DJ176LZK()N1 8DJ176LKK()N2 8DJ176LWZ() 8DJ176LWT() 8DJ176LZS() 8DJ186LWE 8DJ186LWS DJ186LPC() 8DJ186LWH()N1 8DJ186LWM()N1 8DJ186LWV() 8DJ186LWW N3 8DJ261()()()-() 8DJ215()()()-() 8DJ278()()()-() | 2CM9A- -6 2CM9ADB9 8DJ67F-1 8DJ81A-1 8DJ81L-1 8DJ81LVB 8DJ82C-1 8DJ131A-1 8DJ148C-1 8DJ176LWG2 8DJ176LWM1 8DJ176LZF() 8DJ176LXL N2 8DJ176LWZ()N1 8DJ176L2P 8DJ176LZC()N1 8DJ176L2D() 8DJ176LZB() 8DJ186LWF1 8DJ186LPD 8DJ186LWD 8DJ186LWC() 8DJ186LWL()N3 8DJ186LWN()N3 8DJ202LWA()N1 | 2CM9A- -7 2CM15- - -() 8DJ67K-1 8DJ81B-1 8DJ81L-() 8DJ82A-1 8DJ89C-1 8DJ131L- -1 8DJ148W-1 8DJ176LWS2 8DJ176LXE1 8DJ176LWV() 8DJ176LWZ()N1 8DJ176L2P 8DJ176LZC()N1 8DJ176L2D() 8DJ176LZB() 8DJ186LPE 8DJ186LWV() 8DJ186LWG 8DJ186LWT 8DJ186LWL()N3 8DJ186LWN()N3 8DJ202LWA()N1 8DJ324() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|---|--|--|
| TSO-C49a | Ametek Aerospace Products, Inc. 4560 - 15th Ave., N.E. Redmond, WA 98052-5374 | NM-S | | 8DJ81XXXX 8DJ162XXXX 8DJ202XXXX 8DJ278XXXX | 8DJ150XXXX 8DJ176XXXX 8DJ186XXXX 8DJ324XXXX | |
| TSO-C49a | B & D Instruments, Inc. 209 West Main Valley Center, KS 67147 | CE-W | | 0400-() 0520-(XXX) 0535-XXX 7311 55002 | 0402XXX 0521-XXX 7310 7321 55003 | 0403XXX 0530-(XXX) 7320 55006 N2 55007 |
| TSO-C49a | Bendix Flight & Engine Inst. Div. South Montrose, PA 18843 | NE | | 34100 Ser. 34103 Ser. 41103 Ser. 3571260 3581441-6003 | 34101 Ser. 41100 Ser. 41105 Ser. 3571371 3571262-5101 | 34102 Ser. 41102 Ser. 41303 Ser. 3581441-6001 3571262-5102 |
| TSO-C49a | Bendix Flight System Division Teterboro, NJ 07608 | NE | | 3571251-9110, 3571261-3102 3571262-5108, 3571281-7001, 3571371-9002, 3809589-1 3940233-9002, 3941231-9003 3942330-9003/9004 3943331-9001 | -9120, -9122 3571262-2303 -7301, -8104 -9004 3809588-1 3941213-9002, 3941233-9002, 3942330-9001 | -730b, -730b -9009 -9003 -9003 3943332-9001 |
| TSO-C49a *F | Canadian Marconi Co. 2442 Trenton Ave. Montreal, Quebec Canada H3P1Y9 | NE | | 730-14:P/Ns 418-079-() 418-085-() 100-476-675-120 | 463-690-() 418-120-() CMA 730-14 | 418-098-() 418-193-() |
| TSP-C49a | Collins Avionics Division 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | DU-1000A:622-8047-250, MFCP-100A:622-7957-201, EFD-870:622-7391-101 MEM-873:622-8009-101 | -411 -401 | |
| TSO-C49a | Consolidated Instruments Co. Aero Tach Division Teterboro Airport Teterboro, NJ 07608 | NE | | 3TE80(8) | | |
| TSO-C49a | Donallico, Inc. 724 Coldwater Canyon Avenue P.O. Box 3955 North Hollywood, CA 91605 | NM | | AG-44() | | |
| TSO-C49a | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 22-279-() | | |
| TSO-C49a | Eldec Corporation 16700 13th Avenue West Lynnwood, WA 98036 | NM | | 9-392-01 | 9-392-02 | 9-399-02 |
| TSO-C49a | Electro-Mech, Inc. 2600 South Custer Wichita, KS 67217 | CE-W | | EM8000 | EM8001 | EM8002 |
| TSO-C49a | Evans Industries - WITHDRAWN | | | | | |
| TSO-C49a | General Aero Products Corp. P.O. Box 94 | NE | | 86418-1 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|---|
| | Tunkhannock, PA 18657 | | | |
| TSO-C49a | Gull Airborne Inst., Inc. 395 Oser Avenue Smithtown, NY 11787 | NE | | 224-917-XXX(012) |
| TSO-C49a | Gull Airborne Inst., Inc. 55 Engineers Road Smithtown, NY 11787 | NE | | 200-972-XXX 204-905-XXX 218-901-XXX 218-909-XXX 224-902-XXX 224-907-XXX 224-909-XXX 224-917-XXX(011) |
| TSO-C49a | Harrowe Systems, Inc. 255 Great Valley Parkway Malvern, PA 19355 | NE | | 2092-() |
| TSO-C49a | Hartman Systems Co., Inc. 360 Wolf Hill Rd. Hungtingdon Station, NY 11746 | NE | | VS-2PA(621-) VS-4PA(641-) VS-2PD(721-) |
| TSO-C49a | Howell Instruments, Inc. 3479 West Vickery Boulevard Fort Worth, TX 76107 | SW | | BH185L-37 H901 |
| TSO-C49a | Instrument Specialties Co. P. O. Box 365 Euless, TX 76039 | SW | | 6501-() 6502-() 66-021-() 66-022-() 6503-() 6505-() 6505A-() 6503A-() 6511-() 6501-1099 6501-3078 6501-1098 6503A-3113 6503A-3157 6501-3077 6503A-3138 6503A-3139 6520-1007 6520-1006 6520-1005 6501-3111 6501-3112 6501-3077 6520-2002 6503A-3158 |
| TSO-C49a | Kollman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Hwy. S. Merrimack, NH 03054 | NE | | A3243 C30337-04-001 C30337-04-007 50691 10302 50681 10302 51231 10302 |
| TSO-C49a | Kollzman/IDC Avionics Gp. 170 Coolidge Avenue P.O. Box 81 Englewood, NJ 07631 | NH | | 30560-() 31650-() 33980-() 33981-() 37800-() 37801-() 39800-() 39801-() |
| TSO-C49a | KRATOS 403 S. Raymond Ave. Pasadena, CA 91105 | NH | | 124.() Series |
| TSO-C49a | Penn Airborne Products Co. Industrial Boulevard Southampton, PA 18966 | NE | | 1500: 9A1080() |
| TSO-C49a | Ragen Data Systems, Inc. 125 Schmitt Blvd. Farmingdale, NY 11735 | NE | | 3265015-0101 |
| TSO-C49a | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | ECD-870:622-8529-002, -003, -004, -006, -009 DU-1000A:622-8047-411 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--|--|---|---|
| TSO-C49a | Shadin Company, Inc. 14280 N. 23rd Ave. Plymouth, MN 55441-3635 | NE | | 913200 | | |
| TSO-C49a | Simmonds Precision Panton Road Vergennes, VT 05491 | NE | | 472018 | 472019 | |
| TSO-C49a *F | Smiths Industries, Ltd. Winchester Road Basingstoke Hampshire RG 224 HP England | EU | | KTD07() WL651 RSA() WL 717RSA() | 25()KTD WL 656 RSA() WL719 RSA() | KTD 40() |
| TSO-C49a | S.M.S. Instruments, Inc. 120 Marcus Blvd. Deer Park, L.I., NY 11101 | NE | | 206112 | | |
| TSO-C49a | Task Corporation 1600 N. Kraemer Blvd. Anaheim, CA 92806 | NM | | AG44 | | |
| TSO-C49a | Weston Instruments 614 Frelinghuysen Avenue Newark, NJ 07114 | NE | | 522464 | 522636 | |
| TSO-C50 | Andrea Radio Corp. 11-40 45th Road Long Island City, NY 11101 | NE | AIRCRAFT AUDIO AND INTERPHONE AMPLIFIERS | A-81 | | |
| TSO-C50 | Bendix Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | AMA-10() | ASA-2A | LA-178T() |
| TSO-C50 | Bendix Radio Division Baltimore, MD 21233 | NE | | ASA-2A | MI-51B | MS-92A-1 |
| TSO-C50 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 346b-3 356C() 356F-2 390R-10 | 346-1B 356C-2 387C-4 346D-1A | 346D-1 356F() 390D-9A 346D-1B |
| TSO-C50 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 169() | 22-279-() () | |
| TSO-C50 | Electronic Equip. Engrg. Inc. 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 728 | | |
| TSO-C50 | Instrument Systems Corp. Telephonics Div. 770 Park Avenue Huntingdon, L.I., NY 11745 | NE | | 20034 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|--|------------------------------------|---------------------------------|------------------------------------|
| TSO-C50 | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | 401() | 441() | KAA-445 |
| TSO-C50 | Lane Electronics Co. North Hollywood, CA 91603 | NM | | L400 Ser. | L407 Ser. | |
| TSO-C50 | Marathon Flite-Tronics, Inc. 3314 Burton Ave. Burbank, CA | NM | | CA-1 DS-5 | CA-2A DS-5B | CA-3A |
| TSO-C50 | NARCO Avionics Div. NARCO Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | VP-22B2 VP-22B1 | VP-22C | VP-22A |
| TSO-C50 *F | Racal-Amplivox Communications, Ltd. Beresford Avenue Wembley, Middlesex England | EU | | 16360 | | |
| TSO-C50 | Tramm Associates Fort Worth, TX 76101 | SW | | 1A160 | | |
| TSO-C50a | Andrea Radio Corp. Long Island City, NY 11101 | NE | AIRCRAFT AUDIO AND INTERPHONE AMPLIFIERS | AN/AIC-10A | | |
| TSO-C50a | Bendix Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | AMA-11() CNA-30() ASA-2() | ASA-31() MI-51() | CNA-2() MTA-10() |
| TSO-C50a | Bendix Radio Division Baltimore, MD 21233 | NE | | AMA-10() ASA-31() LA-17BT | AMA-11() CNA-2() MI-51B | ASA-2() CNA-30() MTA-10() |
| TSO-C50a | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | 346B-3 387C-4 | 356C-4 | 356F-3 |
| TSO-C50a | Electronic Equipment Engineering, Inc. 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 728001 | | |
| TSO-C50a | Gables Engineering, Inc. P.O. Box 880 Coral Gables, FL 33134 | CE-A | | G-486 | G-502A | G-503A |
| TSO-C50a | Instrument Systems Corp. Telephonics Division 770 Park Avenue Huntington, L.I., NY 11745 | NE | | 20035-1 | | |
| TSO-C50a | King Radio Corp. 400 North Rogers Road Olathe, KS 66061 | CE-W | | KMA 24 | | |
| TSO-C50a | Plantronics, Inc. | NM | | T50-() Ser. | T50-1 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|--|------|--|--|--|--|
| | P.O. Box 635 Santa Cruz, CA 95050 | | | | | |
| TSO-C50b | Aire-Sciences, Inc. 216 Passaic Avenue Fairfield, NJ 07006 | NE | AIRCRAFT AUDIO AND INTERPHONE AMPLIFIERS | AM-660-() | Century 80 | Century 85 |
| TSO-C50b | Andrea Radio Corp. 11-40 45th Road Long Island City, NY 11101 | NE | | A301-6() A301-62() | A201-12() A301-64() | A301-61() A301-65 |
| TSO-C50b | Autoflite Automatic Flight Control Systems P.O. Box 697 Monterey, CA 93940 | NM | | L-35 | | |
| TSO-C50b | Avtech Corporation 3400 Wallingford N. Seattle, WA 98103 | NM | | 1030-1 1340-1 1251-1 1250-1 Mod "C" 1286-1 1440-1 1460-1 1550-1 1630-1 1660-1 1852-1 1956-1 5031-1 5640-1 | 1040-1 1250-1 1251-1 Mod "C" 1286-1-1 1446-1-() 1530-1 1560-1 1640-1 1850-1 1853-1 1957-1 5032-1 | 1240-1 1430-1 1450-1 1540-1 1568-1 1650-1 1851-1 1866-1 5030-1 5034-1 |
| TSO-C50b | Baker Electronics, Inc. 7867 Bradenton Road Sarasota, FL 33580 | CE-A | | M1035() | M1045() | M1135() |
| TSO-C50b | Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | 62V-1 255R-1 390R-22 | 225Y-1 346D-2 PAU-700 | 255Q-1 346D-2B |
| TSO-C50b | Collins General Avn. Div. Rockwell International Melbourne Operations P. O. Box 1060 Melbourne, FL 32901 | CE-A | | AUD-250 AMR-350 | AUD-250H AMR-350H | AUD-251H |
| TSO-C50b | DB Systems, Inc. 2847 152nd Avenue NE Redmond, WA 98052 | NM | | 415 | | |
| TSO-C50b | EDO-AIRE Wichita Division 1326 S. Walnut Street Wichita, KS 67213 | CE-W | | 1U396-002 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|--|--|--|
| TSO-C50b | Gables Engineering, Inc. P.O. Box 340880 Coral Gables, FL 33134 | CE-A | | G-912() G-1565 G-3425 G-3440() G-3805() G-3804A | G-946() G-2566() G-3425(A) G-3444() G-3806() G5205() | G-956() G-3122() G-3426 G-3803() G-5515 G6205() |
| TSO-C50b | Instrument Systems Corp. Telephonics Division 770 Park Ave. Huntington, NY 11743 | NE | | 409E700 | | |
| TSO-C50b | King Radio Corp. 400 N. Rogers Rd. P.O. Box 106 Olathe, KS 66061 | CE-W | | KMA-20() KA 134():071-2009-XX KPN 071-2009-02 KPN 071-2009-03 KA119:071-1087-08, -15 | KAA 455 | KA 119 KMA 24H |
| TSO-C50b *F | Meeda Scientific Instrumentation Ltd. Devora Haneveea Street P.O.B. 13056 Tel Aviv, Israel | EU | | M-507 | | |
| TSO-C50b | NARCO Avionics Div. NARCO Scientific Ind. Commerce Dr. Fort Washington, PA 19034 | NE | | VP-22 CP126 CP136 | VP-22A2 CP127 CP136T | CP125 CP135 |
| TSO-C50b | Pacific Electro Dynamics, Inc. 14220 Sunset Highway Bellevue, WA 98007 | NM | | 255-() Ser. | 256-1 | |
| TSO-C50b | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVA-310 | M1592181-() Ser. | |
| TSO-C50b | Rockwell International Avionics Group 400 Collins Road N.E. Cedar Rapids, IA 52498 | CE-W | | PAU-700:622-5342-101 | | |
| TSO-C50b | Sigma Tek, Inc. 17621 Black Canyon Hwy. Phoenix, AZ 85023 | NM | | F-1010A | F-1010B | |
| TSO-C50b | Sigtronics Corp. 824-A Dodsworth Ave. Covina, CA 91724 | NM | | SPA-400 | | |
| TSO-C50b *F | (T.E.A.M.) Telecommunications Electro- nique Aeronautique et Maritime 9, rue Jules Ferry 94200 Ivry/Seine, France | EU | | AS1234() BR1660() CP1600() E1A1533() | BR1301() CP1302() EA1303() | BR1600() CP1339() EA1433() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--|--|---|---|
| TSO-C50c | ARC Avionics Division P.O. Box 150 Boonton, NJ 07005 | NE | AUDIO SELECTOR PANELS AND AMPLIFIERS | F-490A:51770-1000, -1100, -2500, -2600, -3500, -3600, -4500, -4600 | | |
| TSO-C50c | Avtech Corporation 3400 Wallingford Ave. N. Seattle, WA 98103-9095 | | | 5021-1 5083-1-3 5095-1-2 5141-1-20 thru 5020-1 5190-1-1 5260-1-1 5283-1-1 5390-1 | 5082-1 5090-1-2 5096-1-1 -27 5020-1-1 5191-1-2 5264-1-1 5360-1 5483-1 | 5082-1-1 5091-1 5140-1 5051-1 5192-1 5261-1 53161-1 |
| TSO-C50c | Baker Electronics, Inc. 1734 Northgate Blvd. Sarasota, FL 34234 | CE-A | | M1285 M1052() | M1050() M1090() | M2050() |
| TSO-C50c | B/E Avionics, Inc. 1601 East Chestnut Avenue Santa Ana, CA 92702 | NM | | 170845-() | | |
| TSO-C50c | Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | AS-451A | AS-451B | |
| TSO-C50c | DB Systems, Inc. 2847 152nd Avenue NE Redmond, WA 98052 | NM | | 414 418 218 240 | 420 425 221 | 421 437 419 |
| TSO-C50c | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G6937() G6940() | G6938() G6968() | G6939() G6977() |
| TSO-C50c | Gull Electronic System 395 Oser Avenue P.O. Box 9400 Smithtown, NY 11787 | NE | | 367-913-001-1 | | |
| TSO-C50c | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 W. Bell Road Glendale, AZ 85308 | NM | | SRZ-850 AV-850A:7511001-() | | |
| TSO-C50c | King Radio Corporation 400 North Rogers Road Olathe, KS 66061 | CE-W | | KMA24H KDA687:071-1449-00 | | |
| TSO-C50c | PS Engineering, Inc. Avionics Division 12636 Red Fox Drive Knoxville, TN 37922 | SW | | PM 1000 | | |
| TSO-C50c | Sigma Tek, Inc. 17621 N. Black Canyon Hwy. Phoenix, AZ 85023 | NM | | F-490A | | |
| TSO-C50c *F | TEAM 9 rue Jules Ferry 94200 Ivry Sur Seine, France | EU | | CP2425 | C2426 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|------------------------------|--|--------------|---------|
| TSO-C51 | Fairchild Industrial Prod. Div. Fairchild Camera & Instrument Corp. 529 E. Sheila St. Los Angeles, CA 90022 | NM | AIRCRAFT FLIGHT RECORDERS | 5424-501 | | |
| TSO-C51 | Lockheed Aircraft Ser. Inc Div. Lockheed Aircraft Corp. P. O. Box 33, Int'l Airport Ontario, CA 91764 | NM | | Model "C" | 109-C | 109-D |
| TSO-C51 | Spec Tool Co. 9626 E. Beverly Rd. Pico Rivera, CA 90661 | NM | | 25000 | | |
| TSO-C51a | AACO Corporation P.O. Box 7475 Bellevue, WA 98007 | NM | AIRCRAFT FLIGHT RECORDERS | FAA-0009-() | FAA-0009-001 | |
| TSO-C51a | Allied-Signal Aerospace Co. Guidance Systems Div. Courier Operations 375 N. Lake Street Boyer City, MI 49712 | CE-C | | 18-3001-() | | |
| TSO-C51a | Fairchild Weston Systems, Inc. Data Systems Division P.O. Box 3041 Sarasota, FL 33578 | CE-A | | F800:17-M6XX-(), 17-M7XX-(), 17-M8XX-(), 17-M9XX-() 5424:501, 502, 541, 601, 602, 603, 701, 741 | | |
| TSO-C51a | Lockheed Aircraft Ser. Inc. Div. Lockheed Aircraft Corp. P.O. Box 33, Int'l Airport Ontario, CA 91716 | NM | | 109-DA 209 209F:10077A500-(8XX) V2E24331-07F | | |
| TSO-C51a | Loral Fairchild Corporation Loral Data Systems Fairchild Avn. Recorders P.O. Box 3041 Sarasota, FL 34230 | CE-A | | F1000:S800-2000() :S800-3000() 5424-():501, 502, 541, 601, 602, 603, 701, 741 F800:17M90X-() :17M800-() :17M70X-() :17M60X-() :17M303-() | | |
| TSO-C51a | Magnetek Transducers Prod. 650 Easy Street Simi Valley, CA 93065 | NM | | 3001-01-() | GAH2246 | GAH2247 |
| TSO-C51a *F | Normalair - Garrett Ltd. Yeovil, Somerset England | EU | | 1123V000 | | |
| TSO-C51a *F | Plessey Company Ltd. West Leigh Havant, Hants, England | EU | | PV1584():650-1-14040() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | | |
|----------------|---|------|---------------------|--|---|--|---|
| TSO-C51a *F | Societe ENER TEC Schlumberger 78141 Velizy-Villacoublay Cedix, France | EU | | PE 6573() | | | |
| TSO-C51a | Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052 | NM | | F-542 FA-542() 573() 109000-0007 971-4193-001 980-2001-00X 980-4014-00X 980-4100-HXXS, -HXXN, -HXUS, HXUN, -HWXS, -HWXN, -HWUS, -HWUN, -HMXS, -HMXN, -HMUS, -HMUN 980-4100-943, -944, -945, -946, -947, -948, -949, -950, -951, -952, -953, -954 980-4101-001, -002 H-UFDR FA-542 Model G: 980-4100-GXXS, -GXXN, -GXUS, -GXUN, -GWXS, -GWXN, -GWUS, -GWUN, -GMXS, -GMXN, -GMUS, -GMUN | F-542()Ser. FB-542()Ser. FEB-542 980-2000-00X 980-4013-00X | | |
| TSO-C52 | Astronautics Corp. of Amer. 907 S. First St. Milwaukee, WI 53204 | CE-C | FLIGHT DIRECTORS | 111300-() 111303-() | 111301-() | 111302-() | |
| TSO-C52 | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | 100 Series: 200 Series: 19905() 300 Series: 17830() 19905() | Type 7237 Type 7237() 19903 Type 7237() 7244() 17832() 19903() | | |
| TSO-C52 | Bendix South Montrose Division South Montrose, PA 18843 | NE | | 7237-() 1975548() | 1954604 17810-() | 1954900 | |
| TSO-C52 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | FD60 FGS-70 PB-100 1964567-() 1978729-() 1978976-1() 1978733-() 1990039-() 1990097-() 1990548-() 1990553-() 1990762 1999602-() 3757049-() 3757080-() 3757083-() 3757121-() 3759027-() 3853022-() 200 Series 19912() 1880503-() | | 17838() 1990858-() 1954358-() 1964569-() 1978730-() 1978731-() 1978977-() 1978732-() 1990013-() 1990036-() 1990074-() 1990111-() 1990115-() 1990549-() 1990552-() 1990872-() 1990763 1990766 3743001-() 3757043-() 3757078-() 3757079-() 3757081-() 3757082-() 3757087-() 3757091-() 3838006-() 3838007-() 3759029 3838004-() SD-117() 300 Series 19911() 19917() 1926022-() 1926023-() | FCS-70 3853022-() 1964566-() 1978728-() 1978731-() 1978732-() 1990036-() 1990074-() 1990115-() 1990552-() 1990872-() 1990766 3757043-() 3757079-() 3757082-() 3757091-() 3838007-() 3838004-() 100 Series 19911() 19917() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|--|------|-----------|---|---|--|
| TSO-C52 | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Melbourne, FL 32901 | CE-A | | 614E-23R:622-0945-003/006 | | |
| TSO-C52 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | FD105C FS-108 161E-1 161F-1 329B-() 329B-7M 329B-8D 331A-() 331A-6P 344C-() 344C-1G 384E-1 54W-1D 562A-5F-1 562A-5G 562P-() 562R-1F 599B-1 614E-7F 614E-9B 614E-9E 614E-10C 614E-20() 614E-22 790H-3 890P-1 | FD-105D FD-109 161E-7 313H-3GA 329B-7B 329B-7R 329B-8G 331A-6E 331A-8G 344C-1D 344C-1P 54W-1 562A-5E-1 562A-5F2 562A-5M 562R-() 590A-3A/3D/3E 614E-() 614E-7L 614E-9C 614E-10 614E-13 614E-20A 614E-23 914G-1 | FD-108 FD-109V 161E-7B 327J-2() 329B-7J 329B-8() 329B-1D 331A-6K1 331A-8H 344C-1F 344C-4A 54W-1B 562A-5F 562A-5F4 562A-7 562R-1E 614E-7A1 614E-8B 614E-9D 614E-10A 614E-13A 614E-20C 614E-37 790H-3 914G-2 |
| TSO-C52 | Edo-Aire Mitchell P. O. Box 610 Mineral Wells, TX 76067 | SW | | FD283() 52B110() 10496() 1C497-8 1D695 | 1D494() 1B537() 1C497() 1C543() | 52C78() 52C77() 1C497-6 1C543-1 |
| TSO-C52 | Honeywell, Inc. Aerospace Division 2600 Ridgway Parkway Minneapolis, MN 55413 | CE-C | | AS406 | HG180U | HG180V |
| TSO-C52 | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | 2-11 11S-2 2-5 1780607-2 1780607-5 2588145-() 1783662 1777211() 1783180-8 2558103-1 2589210-902 | 1SC1-1() 11S-3 1780607 1780607-3 1780607-6 2588145-908 614937-() 1778905-4 1783180-12 2558103-2 2589216-901 | 11S-1 11S-8 1780607-1 1780607-4 2588146-() 1778905() 1778904 1783180-7 1783180-122 2589210-901 7000700-() |
| TSO-C52 | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KPI 552 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---------------------|--|--|---|
| TSO-C52 | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NH | | LIFE | | |
| TSO-C52 | Lear Siegler, Inc. Instrument Division 4141 Eastern Ave. S. E. Grand Rapids, MI 49508 | CE-C | | ARU-28/A | 4055K | 5023A |
| TSO-C52a | Aeronetics Div. of AAR Brooks & Perkins 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | FLIGHT DIRECTORS | 520-5160-() | | |
| TSO-C52a | R.C. Allen, Inc. 678 Front Avenue, NW Grand Rapids, MI 49501 | CE-W | | RCA23-() | | |
| TSO-C52a | Astronautics Corp. of America 4116 W. Teutonia Ave. P.O. Box 523 Milwaukee, WI 53201 | CE-C | | 111302-4 120100 129170() 129400() 131030 | 118600-(), -5, -7 128870 129180() 129855 133160 | 130530 129222-() 131270 |
| TSO-C52a *F | Astronautics C.A. Ltd. of Israel 8 Hayarkan Street Bnei Brak, Israel | EU | | 111302-() | 111303-() | |
| TSO-C52a | Bendix Flight & Engine Inst. Div. South Montrose, PA 18843 AND Bendix Flight Systems Div. Teterboro, NJ 07608 | NE | | 1936100-5 1954355-4 1964192-7 1964567-5 978172-4 1978731-4 1990013-5 1990097-4 1990548-7 1990554-4 3743003-4 3743010-4 3743013-() 3743016-() 3757049-7 3757080-7 3757083-9 3757088-9 3757109-9H 3757132-9 3757319-7B 3759028-6 3759078-6 3822170-4 3838006-4 3838009-4 3838012-4 3838029-4 3838043-4 | 1954103-4 1954356-4 1964193-6 1964570-4 1978729-4 1978981-4 1990040-4 1990111-7G 1990549-7G 3743000-4 3743004-4 3743011-() 3743014-() 3757021-7 3757078-7 3757081-7G 3757085-9G 3757089-9H 3757121-9 3757146-7 3757320-7 3759029-6 3759082-6 3822182-4 3838007-4 3838010-4 3838023-4 3838039-4 3854009-() | 1954354-4 1954358-4 1964566-4 1964679-4 1978730-4 1978983-4 1990074-4 1990115-4 1990553-4 3743001-4 3743007-4 3743012-() 3743015-() 3757043-7G 3757079-7G 3757082-7 3757087-9G 3757091-9 3757122-9 3757147-7G 3759027-6 3759050-6 3759083-6 3822183-4 3838008-4 3838011-4 3838026-4 3838042-4 3856084-4 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|---|
| TSO-C52a | Bendix Flight & Engine Inst. Div. South Montrose, PA 18843 | NE | | 3571442-1001 3571442-1003 3838033-4 |
| TSO-C52a | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | 7241() 14168() 15521() 16956() 17826() 17827() 18773() 18774() 1903712 1978121-() 3743004-() 3757088-() 3838011-() 3838012() 3757089-() 3757122-() 3757109-8 3743003-() |
| TSO-C52a | Bendix Aerospace 2150 Northwest 62nd St. P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | | ED-102E:8095351 |
| TSO-C52a | Bendix Flight Systems Div. Teterboro, NJ 07608 | NE | | 3757083-6 3759081-6 3822090-() 3838029-4 3856084-() 3822090-() 3822170-4 3838044-4 3838037-4 |
| TSO-C52a | Bendix General Aviation Avionics Division 2100 N. W. 62nd St. P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | AD-846-() AD-862A FDS-840 CC-843() PS-845() PS-847() AC-844() DH-841C FCS-810 FC-813() CA-814() PS-815() SA-816() SE-816() ST-816() PS-819() FG823A() FC-823B() M-4D 5485A 5486A 5487G 5536F DH-841V DH-866A DH-841VE FCS-870:CA-871(), FC-872(), MA-872(), SA-873(), SE-873, ST-873() SR-874() FCS-8700B:MC-8702(A), MC-8702(B), VP-8702(A) CP-103F:8095477 SC-101B:3614335-1005 SG-101B:3614335-1012, -1013 |
| TSO-C52a | Bendix/King Air Transport Avionics Division 2100 N.W. 62nd St. Ft. Lauderdale, FL 33309 | CE-A | | EFS-10: SG-101A SG-101B |
| TSO-C52a | BVR Aero Precision Corp. 5459 Eleventh St. P.O. Box 6336 Rockford, IL 61125-1336 | CE-C | | 273753-() 273756-() 590A-6A 277200-() |
| TSO-C52a | Century Flight Systems, Inc. SW P.O. Box 610 Mineral Wells, TX 76067 | | | 1C497-() 1C543-() 1C714-() 1C722-() 1C727-() 1C771-() 1C772-() 1C774-() 1D755-() 1D756-() 1D757-() 1D 946-() 52D77-() 52D136-() 52D137-() |
| TSO-C52a | Collins Avionics Division Rockwell International 400 Collins Road, NE. Cedar Rapids, IA 52498 | CE-W | | 331A-8A (S/N 5000 and up):772-5025-() 329B-8Y-() 331A-10() 344C-7() 331A-8K (S/N 5000 and up):777-1397-() 331A-86:777-1825-001 331A-86:777-1825-001 562A-18:622-4869-001 590A-3J1:622-4121-001 590A-3K1:622-4394-001 614E-7R:622-7563-001 614E-22G:622-1700-() 614E-22J:622-2274-001 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | | | | 614E-22L:622-3028-() |
| | | | | 614E-22M:622-4924-001 |
| | | | | 614E-23J:622-2274-001 |
| | | | | 614E-51:622-4965-001 |
| | | | | 999P-1() |
| | | | | 9161A-19:622-4476-001 |
| | | | | ACP-74B:622-9222/-001 thru -004 |
| | | | | ADA-85:622-8158-001 |
| | | | | ADC-80N:622-7576-521/-554 |
| | | | | ADC-80Q:622-7577-799 |
| | | | | ADC-80R:622-8070-099, -345 |
| | | | | ADC-850:622-7208-001 |
| | | | | ADA-85:622-8158-001 |
| | | | | ADC-82C:622-8329-099 |
| | | | | ADC-82L:622-8105-012, -013, -099, -399 |
| | | | | ADC-81A:622-4401-001 |
| | | | | ADC-82A:622-6475-001 thru -006 |
| | | | | ADI-44V:622-5139-001 |
| | | | | ADI-55V |
| | | | | ADI-55V-1 |
| | | | | ADI-70:622-318()-002 |
| | | | | ADI-77:622-4423-001 |
| | | | | ADI-85:622-0224-001/002/003/004 |
| | | | | ADI-85A:622-4808-001/002/003/004 |
| | | | | ADS-81:ADC-81A, PRE-80A |
| | | | | ADS-65C:622-6332-001 |
| | | | | ADM-85:622-8692-011 |
| | | | | ADM-850:622-7737-001 |
| | | | | AP-107N:562C-15H, 334-12 |
| | | | | AP-106/107:913K-1A, 562C-13A |
| | | | | APC65a-65:FCP-65, PCP-65A, ADS-65, MAP-65, |
| | | | | APC-65A:622-7890-018 |
| | | | | APC-65:622-8439-099 |
| | | | | APC-65B:622-8315-099 |
| | | | | APC-65E:622-9046-099 |
| | | | | NAC-80 |
| | | | | APS-80:FGC-80, FGC-80A, FGP-80, APC-80, |
| | | | | APA-80, APA-80A, APP-80, |
| | | | | APP-80A |
| | | | | APS-85 |
| | | | | APS-841():APC-841, 590A-6 |
| | | | | APS-841H:APC-841, 590A-6 |
| | | | | CBP-85C:622-6404-001/002 |
| | | | | CHP-55A/B:622-6319-001/002 |
| | | | | CHP-85A:622-6318-001/002, 622-6319-001/002 |
| | | | | CHP-85B:622-6319-001/-002 |
| | | | | CHP-85C:622-6404-001/-002 |
| | | | | CHP-85D:622-6898-001/002 |
| | | | | CHP-86A:622-6408-001/002 |
| | | | | CHP-86B:622-6899-001/002 |
| | | | | CHP-86C:622-7875-001/-002 |
| | | | | DCP-1000:622-7485-201 |
| | | | | DPU-85:622-6022-002 |
| | | | | DPU-85A:622-7244-001 |
| | | | | DPU-85B:622-7245-001 |
| | | | | DPU-85C:622-7448-001 |
| | | | | DPU-85H:622-8444-001 |
| | | | | DPU-85L:622-8022-001 |
| | | | | DPU-85M:622-8444-001 |
| | | | | DPU-85N:622-8678-001 |
| | | | | DPU-86A:622-7247-001 |
| | | | | DPU-86D:622-7249-001 |
| | | | | DPU-86H:622-7711-002 |
| | | | | DPU-86K:622-7713-001 |
| | | | | DPU-86L:622-7873-001 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | DPU-86N:622-8713-001 |
| | | | | DSP-85A:622-7728-001/-002/-003/-004 |
| | | | | DSP-85B:622-9116-001/-002/-003/-004 |
| | | | | DSP-85C:622-9117-001/-002/-003/-004 |
| | | | | DSP-85D:622-9118-001/-002/-003/-004 |
| | | | | DSP-85E:622-9119-001/-002/-003/-004 |
| | | | | DU-1000:622-7484-250, -411 |
| | | | | EFD-74:11622-6197-001/-002 |
| | | | | EFD-85:622-6020-001/002 |
| | | | | EFD-85:622-6020-011/-012/-021/-022 |
| | | | | EFD-85A:622-6464-011/-012/-021/-022 |
| | | | | EFD-85B: |
| | | | | EFD-86:622-6342-011/012/013/014/021/022/ 023/024 |
| | | | | EFD-86A:622-6535-011/012/021/022 |
| | | | | EFD-870:622-7391-101 |
| | | | | EFIS-86D(2) |
| | | | | FAC-1000:622-7478-301, -311, -321 |
| | | | | FCC-85:622-6193-015 |
| | | | | FCC-85B:622-7491-001 |
| | | | | FCC-86:622-6195-015 |
| | | | | FCC-86B:622-7492-001 |
| | | | | FCC-86C:622-7493-005/008 |
| | | | | FCC-86E:622-8196-004 |
| | | | | FCC-86G:822-0175-002 |
| | | | | FCC-201 |
| | | | | FCC-1000:622-7475-301, -311 |
| | | | | FCC-1000:622-7476-331 |
| | | | | FCP-65:622-5798-002 thru -020 |
| | | | | FCP-65A:622-5953-001/-002/-003/-004 |
| | | | | FGC-80B:622-3106-001 thru -030, 622-3106-101 thru -130 |
| | | | | FGC-80F:622-5224-001 thru -030, 622-5224-101 thru -130 |
| | | | | FGP-81():622-2265-() |
| | | | | FGS-65 |
| | | | | FMP-1000:622-7477-301 |
| | | | | FYD-65:622-9627-005 |
| | | | | GSP-201 |
| | | | | HCP-74:622-6200-001/002/003/004 |
| | | | | HCP-74A:622-0793-001/-002/-003/-004 |
| | | | | HCP-85:622-4177-001/002/003/004 |
| | | | | HCP-86:622-4178-001/002/003/004 |
| | | | | HCP-87 |
| | | | | HPU-74:622-6198-001:HPU-74B:622-9221-001 |
| | | | | HPU-86H:622-7716-002 |
| | | | | HPU-86K:622-7718-001 |
| | | | | HS1-45:CPN622-4298-001 |
| | | | | HS1-70/A:622-4913-001/622-4914-001 |
| | | | | HS1-84():622-4151-001 |
| | | | | HS1-85:622-4176-001/002/003/004 |
| | | | | KA-154:065-0139-00 |
| | | | | KFD-85:622-6020-011, -012 |
| | | | | KFD-85A:622-6464-001, -011, -012 |
| | | | | KFD-86:622-6342-011, -012, -013, -014 |
| | | | | KFD-86A:622-6535-011, -012 |
| | | | | MAP-65:622-5709-001 |
| | | | | MCC-1000:622-7479-301, -311 |
| | | | | MEM-871:622-7395-101 |
| | | | | MPU-85:622-6091-002/012/006 |
| | | | | MPU-85A:622-7250-001 |
| | | | | MPU-85B:622-7251-001 |
| | | | | MPU-85C:622-7454-001 |
| | | | | MPU-85L:622-8023-001 |
| | | | | MPU-85M:622-8445-001 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|--|
| | | | | MPU-85N:622-8679-001 MPU-86B:622-7253-001 MPU-86D:622-7255-001 MPU-86L:622-7874-001 MPU-86N:622-8714-001 MSP-85:622-6209-114 MSP-85A:622-6563-413 PRE-80A:622-2923-001 PRE-80B:622-7648-001 thru -006, -011 thru -016 RNP-1000:622-7480-301 SCC-80:622-4120-001 SCP-80:622-4121-001 VGR-70:622-3618-001 |
| TSO-C52a | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | ADC-80H:622-4365-022/203/204/205/207/208/ 211/213/220/221/225/310/324 ADC-80J:622-5206-014/017/022/027 ADC-80K:622-5465-209/214/215/217/222/227/ 228/310/326 ADC-80M:622-2704-002 APC-841:622-5192-001/002 HCP-85:622-4177-001/002/003/004 PRE-80A:622-2923-001 thru -006 PRE-80M:622-2703-001 REU-84:622-4152-001 REU-84A:622-4569-001 562C-13A:622-3593-002 562C-13A:622-3595-001/006/007 590A-3E:522-4798-001 590A-3J1:622-4393-001/002/019 590A-3K1:622-4394-001/003 614E-20S:622-5486-001 614E-22B:622-6221-001/002/003/004/005/006 614E-22M:622-4924-001 913K-1A:622-3202-001/003/004/005/013 |
| TSO-C52a | Collins Radio Group Rockwell International 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | 614E-20K 562A-5F5 |
| TSO-C52a | Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406 | CE-W | | FMC-28() AD1-84() ADS-80:ADC-80F 614E-42A:622-3891-001 614E-55A(HSVD-800):622-6866-001 614E-51B(FDS-800):622-7014-001 331A-86:777-1825-001 ADA-85:622-8158-001 ADC-80N:622-7576-521/-554 ADC-80R:622-8070-099, -345 APC-65E:622-9046-099 CHP-85D:622-6898-001/-002 CHP-86C:622-7875-001/-002 DCP-1000:622-7485-201 DPU-85H:622-8444-001 DPU-85L:622-8022-001 DPU-85N:622-8678-001 DPU-86N:622-8713-001 DSP-85A:622-7728-001/-002/-003/-004 DSP-85B:622-9116-001/-002/-003/-004 DSP-85C:622-9117-001/-002/-003/-004 DSP-85D:622-9118-001/-002/-003/-004 DSP-85E:622-9119-001/-002/-003/-004 DU-1000:622-7484-250, -411 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|--|------|-----------|---|--|---|
| | | | | EFD-85:622-6020-011/-012/-021/-022 EFD-85A:622-6464-011/-012/-021/-022 EFD-86:622-6342-011/-012/-013/-014 -021/-022/-023/-024 EFD-86A:622-6535-011/-012/-021/-022 MPU-85L:622-8023-001 MPU-85H:622-8679-001 MPU-86N:622-8714-001 | | |
| TSO-C52a | Collins Radio Co. 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | FD-109F 161E-7A 327J-5 327J-8 329B-8U 331A-8D 331H-3G 54W-4 562Y-4 614E-20 614E-39 914-6 916A-5 AP106/107: 161H-1 | FD-109H 161C-4 327J-6 329B-8J 329B-8Y 331A-8K 345A-7 562R-4 562A-13 614E-27 614E-22D 916A-2 991L-1 332D-12 614E-42 | FD112A 161E-11 327J-6A 329B-8R 329B-9L 331A-9G 345A-9 562S-3 590A-3H 614E-36 614E-37 916A-3 916A-4 913K-1 562C-13 |
| TSO-C52a | Columbia Research Labs, Inc. Macdade Blvd. & Bullens Lane Woodlyn, PA 19094 | NE | | SA-107-RS | SA-107-RSTX | |
| TSO-C52a | DPI Labs, Inc. 359 S. Rosemead Blvd. Pasadena, CA 91107 | NM-L | | 838 | | |
| TSO-C52a | Edo-Aire Mitchell P. O. Box 610 Mineral Wells, TX 76067 | SW | | FD/AP 282 52D136-() DG/NSD 360: 52D137-1332, -1333, -2331, -2334 1C727() 1C771-() 1D756-() | 52D137-() 1C722-() 1C497-() 1D496-()FD/AP 1C774-() 52C77() | 1C714-() 1C543-() 1C543-() 1D755-() 1D757-() |
| TSO-C52a | EDO-AIRE Wichita Div. 1326 S. Walnut Street Wichita, KS 67213 | CE-W | | 1C497-() 1C543-() | 1U371-() 1U367-() | 1U407 |
| TSO-C52a | Gables Engineering P.O. Box 880 Coral Gables, FL 33134 | CE-A | | G-2473-() | G-2915() | |
| TSO-C52a | Gulton-Servonic A Mark IV Company 1644 Whittier Ave. Costa Mesa, CA 92627 | NM | | 451318AA 451318AA-() | 4723A Ser. | 4723A() |
| TSO-C52a | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. Avionics Facility 5353 W. Bell Road Glendale, AZ 85308 | NM | | AD-500:7000836-() AD-600/AD-650:7000466-() AL-200/300:7002412-() AZ-649:7002353-913 AZ-800:7000700-864, -936, -948 AZ-800:7000706-938, -834 AZ-810:7000700-940 CM-400:7002078-() DC-800:7003420-965, -966 | | AD600 AL-801 AZ-800 -938, -943, -948 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | DC-810:7005819-747 thru -758, -767, -768, -933, -934 |
| | | | | DC-811:7012977-747 thru -758, -767, -768, -933, -934 |
| | | | | DC-820:7007277-() |
| | | | | ED-600:7003430-() |
| | | | | ED-800:7003110-() |
| | | | | EDZ-605/805 |
| | | | | EDZ 600/800:7003110-(), 7003400-() 7003420-(), 7003430-(), 7004123-() |
| | | | | EZ-200:7003513-() |
| | | | | FZ-400:7004126-909 |
| | | | | FZ-450:7010680-904-() |
| | | | | FZ-600/800:7003974-713 |
| | | | | FZ-703:7004383-(), -904 |
| | | | | GC-600, -300, -501, -880:7603975 |
| | | | | GC-810:7011702-() |
| | | | | GH-14 |
| | | | | GH-222:7508000-() |
| | | | | GP-650:7009750-() |
| | | | | GP-820:7007546-() |
| | | | | ID-800, -801, -802:7003652() |
| | | | | IU-400:7004384-() |
| | | | | MC-800:7007062-(), -701, -702, -721, -722 |
| | | | | MG-603:7007061-624, -824 |
| | | | | MG-800:7007061-() |
| | | | | MG-803:7007061-624, -824 |
| | | | | MG-810:7007321-() |
| | | | | MG-815, -816:7011675-() |
| | | | | MG-815:7011675-215 |
| | | | | MG-820:7009289-() |
| | | | | MS-400:7003938-() |
| | | | | SC-610/810:7004544-() |
| | | | | SG-600/800:7003400-() |
| | | | | SG-603:7003400-624, -824 |
| | | | | SG-610/810:7004544-() |
| | | | | SG-705:7011672-707 |
| | | | | SG-803:7003400-624, -824 |
| | | | | SG-811:7004544-(), 7004544-312 |
| | | | | SG-815, -816:7011674 |
| | | | | (SG)820:7007356-() |
| | | | | RD-450:7002493-() |
| | | | | RD500() |
| | | | | RD-650:7000469() |
| | | | | RI-801 |
| | | | | RI-802:7005973() |
| | | | | RI-815:7011345-() |
| | | | | RI-820:7008703-() |
| | | | | RI-870:7014726-() |
| | | | | VN-212:4020571-903, -903, -904, -905, -906, -907 |
| | | | | VN-801:7004577-() |
| | | | | 2591411-() |
| | | | | 2592920-() |
| | | | | 2593604-() |
| | | | | 2594732-() |
| | | | | 2594733-() |
| | | | | 4001939-() |
| | | | | 4002531-() |
| | | | | 4010657-() |
| | | | | 4012395-() |
| | | | | 4015985-() |
| | | | | 4018285-() |
| | | | | 4018368-() |
| | | | | 4018369-() |
| | | | | 4020550-() |
| | | | | 4020570-() |
| | | | | 4020571-() |
| | | | | 4026206-() |
| | | | | 4029516-() |
| | | | | 4030059-() |
| | | | | 4030182-() |
| | | | | 4033089-() |
| | | | | 700125-() |
| | | | | 7003974-() |
| | | | | 7000700-944 |
| | | | | 7000700-937 |
| | | | | 7000700-939 |
| | | | | 700605-() |
| | | | | 7000472-() |
| | | | | 7000789-() |
| | | | | 7000300-() |
| | | | | 7001182-() |
| | | | | 7001648-() |
| | | | | 7001676() |
| | | | | 7001770-() |
| | | | | 7001931-() |
| | | | | 7002353-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|-----------|---|
| | | | | 7002541-() 7002542-() 7003183-() 7003974-719, -720 7004126-() 7004283-() 7004536-() |
| TSO-C52a | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | HZ-4 HZ-6 HZ-6F R-1 RD-1() RD-2() R-4A 1783662 1783662-302 1783662-305 RD-200 2588370() RD-350() SCI-1() SFG 980 RD-600-() STARS IVC AD-200 2588369 AD-300() AD-300B AD-350() 1780607() 1780607-52 1780607-53 1780607-54 2587934-801 2588534-() 2588534-902 2588902-() Z-14 2588785-901 2588317() 2588318-901 2588420() 2588849() 2599654() 2588785() 2589433-() 2589758() 2590081() 2590680() 2590272() 2590281-901 2591162() 2591831() 2594623-901 2594623-902 2594623-904 2594623-905 4018149-() 4020917-() 4030056-() 4032211() 4034233-() 4040744() 2589582 RD-500A:4029529-(), 4039529-() |
| TSO-C52a | Jet Electronics and Technology, Inc. 5353 52nd Street Grand Rapids, MI 49508-0239 | CE-C | | AC-180():501-1482-() 251() 300() 700() 300-() Series 540-() |
| TSO-C52a | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66062 | CE-W | | KCI 310 KAP 315 KFC-300 KVM-395 KCP 320 KDC 380 KDC 381 KFC-300 KDA 692 KCP 320 KDC 380 KDC 381 KPI 300 KDA 335 KVG 350 KPI 553 KFC 200 KPI 553A KA 136:065-5013-() KI 256:060-0017-00, -01 KFC-300:KSC334:065-5012-() KAS 297 KDC 298 KCP 299 KC 190 KC 191 KC 192 KVC 350:060-0026-() KAP 315A KDC-222:065-0085-00 KCP-220:065-0064-00/-01, -06, -08 065-5034-08, -10, -11, -16 065-5051-08, -10, -11, -16 065-5052-08, -10, -11, -16 065-5053-08, -10, -11, -16 KCP-420:065-0069-00, -07, -13, -14, -15 KDA-430:065-5030-00/-01/-02/-03/-04/-06 KA-185:065-0058-00 KAM-432:065-0091-00, -04 KAP-315A:065-0063-00/-01 KAP-419:065-0088-00/-01 KHC-442:065-0072-00 thru -07 KHC-441:065-0071-00/-01 KAS 297B KMC-221 KMC-440:065-0070-00/-01/-02/-03/-04/ -05/-10/-11/-12/-13/-14/-15/-38 KMS-446:065-0073-00/-01/-02/-03/-04/ -05/-06/-07/-22,-23 KNC-221:065-0062-00 KNC-321:065-0086-00/-01/-02/-03 KSA 372X:065-0056-71 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|--|----------------------|-----------|
| TSO-C52a | Kollzman/IDS Avionics Group 170 Coolidge Ave. Englewood, NJ 07631 | NE | | 18210-() 17000-500 | 18210-5 40860-() | 18415-() |
| TSO-C52a | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 345C-5 562P-4 | 345C-5A | 345C-5B |
| TSO-C52a | LSI Service Corporation Harrisburg Division 6700 Allentown Blvd. Harrisburg, PA 17105 | NE | | CIS-100 | | |
| TSO-C52a | Rockwell International Avionics & Missiles Group 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | | MAP-80() MFD-80:622-4777-001 161N-3:622-4774-001 614E-55:622-4775-001 614E-10D:622-0917-002 PRE-80C:622-9462-001 thru -016, -021 thru -036 PRE-80D:622-9722-001 thru -016, -021 thru -036 FGC-65D:622-8891-099, -021 PA1-850:622-9250-001, -002, -003, -004 SIA-850:622-9732-001 | | |
| TSO-C52a | Rosemount, Inc. 12001 West 78th Eden Prairie, MN 55344 | CE-C | | 1241S1 | | |
| TSO-C52a | Schaevitz Engineering P.O. Box 505 Camden, NJ 08101 | NE | | LSXC0266 | MAC-80:LSXC0266-020 | |
| TSO-C52a *F | (S.F.E.N.A.) Societe Franciase d'Equip. pour la Navigation Aerodrome de Villacoublay P.O. Box 59 78140 Villizy, Villacoublay France | EU | | ADI 4860()() | FDS 90()() | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|--|--|
| TSO-C52a *F | (S.F.I.M.) Societe de Fabrication d' Instruments de Mesure 13 Avenue Marcel Remolfo Garnier 91301 Massy France | EU | | CDV-85()()() |
| TSO-C52a | Smiths Industries SLI Avionic Systems Corp. 4141 Eastern Ave., S.E. Grand Rapids, MI 49518-8727 | CE-C | | 4060P:139001-01 6502E 3335B:141300-01-02 4055K:139602-01 4058AC/A:149150-01-01 4058AC/B:149150-01-02 4058AC/E:149155-01-02 |
| TSO-C52a | Sperry Flight Systems Electra Components Plant Durham, NC 27701 | NM | | 4018149-903, -904 4040744-901 2588902-901, -902 |
| TSO-C52a | S-TEC Corporation Route 3, Building 945 Wolters Industrial Complex Mineral Wells, TX 76067 | SW | | 0103-() 0104-() 0110-() 0110-T 0110-TF 0113-() 0114-() 0115-() 0116-() 0117-() 0119-() 0141-() 0142-() |
| TSO-C52a | Systron-Donner Corporation Inertial Division 1090 San Miguel Road Concord, CA 94518 | NM | | 4960A-5-P6 4311A-3-P82A 4384A-2-P33 4383A-5-P6 |
| TSO-C53 | Aeroquip Corporation Aeroquip Aerospace Division 300 S. East Avenue Jackson, MI 49203 AND Aero Hardware & Supply, Inc. 4301 N.W. 36th St. Miami Springs, FL 33166 AND Aerotech World Trade Corp. P.O. Box 218 Purchase, NY 10577 AND Cooper Airmotive 16260 Raymer Street Van Nuys, CA 91406 AND VanDusen Aircraft Engineering, Inc. 3327 N. Seventh Street Kansas City, KS 66105 AND Boeing Comm. Airplane Co. Bldg. 17-55, Bay 1 Auburn, WA 98002 AND Garville Corporation 200 Clearbrook Road Elmsford, NY 10523 | NM | FUEL AND ENGINE OIL SYSTEM HOSE ASSEMBLIES (RUBBER OR TETRAFLURO- ETHYLENE TUBE AND WIRE BRAID CONSTRUCTION) | TYPE A 350-3 thru -6 360-8 thru -12 390A-16 thru -48 AR1014-3 thru -20 AR1015-3 thru -20 AR1016-3 thru -20 AR1021-3 thru -20 AT2011-3, -4, -5 AT2012-6D thru -32D AT2014-3 thru -6 AT2015-8 thru -48 601000 Series -3, -4, -6, -6D, -8D -10D, -12D, -16D, -20D, -24D, -32D 660051-3 thru -12 660269-8 thru -12 660270-8 thru -12 660271-8 thru -12 660276-8 thru -12 660426-3 thru -6 660427-3 thru -6 660428-3 thru -6 660429-3 thru -6 660514-3 thru -6 660569-3 thru -6 666124-8 thru -12 666125-8 thru -12 666148-8 thru -12 666169-8 thru -12 666272-8 thru -12 666273-8 thru -12 666314-3 thru -6 666319-3 thru -6 666344-3 thru -6 666372-3 thru -6 666987-3 thru -12 667012-16 thru -24 667055-16 thru -20 667124-16 thru -20 667127-16 thru -20 667142-16 thru -20 667143-16 thru -20 667168-16 thru -20 667169-16 thru -20 667170-16 thru -20 667322-16 thru -20 667387-16 thru -20 667394-16 thru -20 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | | | | 701000 thru 701799 Series -3, -4, -5, -6D, -8D, -10D, -12D, -16D, -20D, -24D, -32D |
| | | | | 950002-8 thru -48 950003-8 thru -48 |
| | | | | 950004-3 thru -48 950010-8 thru -48 |
| | | | | 950012-3 thru -48 950532-3 thru -24 |
| | | | | 950645-3 thru -24 950668-3 thru -6 |
| | | | | 950680-3 thru -6 950781-3 thru -24 |
| | | | | 950782-3 thru -6 950783-3 thru -6 |
| | | | | 950784-3 thru -6 950785-8 thru -24 |
| | | | | 950786-8 thru -24 950787-8 thru -24 |
| | | | | 950816-3 thru -6 |
| | | | | TYPE B |
| | | | | AR1011-3 thru -20 AR1012-3 thru -20 |
| | | | | AR1013-3 thru -20 AR1017-3 |
| | | | | AR1020-3 thru -20 AR1022-3 |
| | | | | 666000-3 thru -12 666049-3 thru -12 |
| | | | | 666100-8 thru -12 666101-8 thru -12 |
| | | | | 666102-8 thru -12 666103-8 thru -12 |
| | | | | 666104-8 thru -12 666261-8 thru -12 |
| | | | | 666276-8 thru -12 666277-8 thru -12 |
| | | | | 666278-8 thru -12 666279-8 thru -12 |
| | | | | 666300-3 thru -6 666301-3 thru -6 |
| | | | | 666302-3 thru -6 666303-3 thru -6 |
| | | | | 666304-3 thru -6 666371-3 thru -6 |
| | | | | 666384-3 thru -6 666385-3 thru -6 |
| | | | | 666386-3 thru -6 666387-3 thru -6 |
| | | | | 667000-16 thru -20 667014-16 thru -20 |
| | | | | 667108-16 thru -20 667118-16 thru -20 |
| | | | | 667123-16 thru -20 667126-16 thru -20 |
| | | | | 667129-16 thru -20 667171-16 thru -20 |
| | | | | 667172-16 thru -20 667173-16 thru -20 |
| | | | | 667174-16 thru -20 667175-16 thru -20 |
| | | | | TYPE C |
| | | | | AR1134-4 thru -20 (Hexagonal Sockets) |
| | | | | AR1137-4 thru -20 (M S Sockets) |
| | | | | AR1138-4 thru -20 (Round Sockets) |
| | | | | AT2111-3 AT2111-5 AT2112-20D |
| | | | | AT2114-4 |
| | | | | AT2115-6D, -8D, -10D, -12D, -16D, -24D, -32D |
| | | | | AT2120-3 thru -6 AT2121-8 thru -48 |
| | | | | AT2125-4, -5 AT2126-6D thru -32D |
| | | | | AT2127-8, -16, -20, -20D |
| | | | | AT2128-8, -16, -20, -20D |
| | | | | 624000-3 thru -48 624023-3 thru -48 |
| | | | | 624036-3 thru -48 624039-4 |
| | | | | 624040-3 thru -48 624055-3 thru -6 |
| | | | | 624071-3 thru -6 |
| | | | | 624100 Series -4, -6D, -8D, -10D, -12D, -16D, -24D, -32D |
| | | | | 624927-3 thru -24 630907-8 thru -48 |
| | | | | 630908-8 thru -48 630909-8 thru -48 |
| | | | | 630956-3 thru -6 630957-8 thru -24 |
| | | | | 630960-3 thru -6 630961-8 thru -24 |
| | | | | 630964-3 thru -6 630965-8 thru -24 |
| | | | | 630969-3 thru -6 630970-8 thru -24 |
| | | | | 630974-3 thru -6 630975-8 thru -24 |
| | | | | 634100-3, -5, -20D |
| | | | | 701800 thru 701999 Series -4, -5, -6D, -8D, -10D, -12D, -16D, -20D, -24D, -32D |
| | | | | TYPE D |
| | | | | 677-4, -6, -8 AR1111-3 |
| | | | | AR1112-3 AR1113-3 |
| | | | | AR1117-3 thru -20 AR1118-3 thru -20 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---------------------------------------|
| | | | | AR1119-3 thru -20 |
| | | | | AR1120-3 thru -20 |
| | | | | AR1121-3 thru -20 |
| | | | | AR1122-3 thru -20 |
| | | | | AR1123-4 thru -20 |
| | | | | AR1124-4 thru -20 |
| | | | | AR1125-4 thru -20 |
| | | | | AR1132-3 |
| | | | | AR1133-3 thru -20 (Hexagonal Sockets) |
| | | | | AR1135-3 thru -20 (Round Sockets) |
| | | | | AR1136-3 thru -20 (M S Sockets) |
| | | | | AR1141-3 |
| | | | | AR1144-3 thru -20 |
| | | | | AR1146-3 thru -20 |
| | | | | C600000 Series -3 thru -20 |
| | | | | V600000 Series -3 thru -20 |
| | | | | W600000 Series -3 thru -20 |
| | | | | 624283-8 thru -12 |
| | | | | 624284-3 thru -6 |
| | | | | 624285-8 thru -12 |
| | | | | 624286-3 thru -6 |
| | | | | 624287-8 thru -12 |
| | | | | 624288-3 thru -6 |
| | | | | 624289-8 thru -12 |
| | | | | 624290-3 thru -6 |
| | | | | 624291-8 thru -12 |
| | | | | 624292-3 thru -6 |
| | | | | 624503-3 thru -12 |
| | | | | 624518-8 thru -12 |
| | | | | 624519-3 thru -6 |
| | | | | 624520-3 thru -6 |
| | | | | 624541-8 thru -12 |
| | | | | 624542-3 thru -12 |
| | | | | 624545-8 thru -12 |
| | | | | 624569-3 thru -6 |
| | | | | 624572-3 thru -6 |
| | | | | 624574-3 thru -6 |
| | | | | 624589-8 thru -12 |
| | | | | 624590-8 thru -12 |
| | | | | 624701-16 thru -24 |
| | | | | 624784-16 thru -20 |
| | | | | 624785-16 thru -20 |
| | | | | 624787-16 thru -20 |
| | | | | 624789-16 thru -20 |
| | | | | 630003-3 thru -6 |
| | | | | 630004-8 thru -12 |
| | | | | 630005-3 thru -6 |
| | | | | 630006-8 thru -12 |
| | | | | 630007-8 thru -12 |
| | | | | 630403-16 thru -20 |
| | | | | 630404-16 thru -20 |
| | | | | 640305-3 thru -20 |
| | | | | 640314-3 thru -12 |
| | | | | 640315-3 thru -6 |
| | | | | 640316-3 thru -6 |
| | | | | 640329-8 thru -12 |
| | | | | 640330-8 thru -12 |
| | | | | 640331-8 thru -12 |
| | | | | 640346-8 thru -12 |
| | | | | 640347-8 thru -12 |
| | | | | 640369-3 thru -6 |
| | | | | 640378-3 thru -12 |
| | | | | 640379-3 thru -6 |
| | | | | 640380-8 thru -12 |
| | | | | 640390-3 thru -6 |
| | | | | 640391-3 thru -6 |
| | | | | 640473-3 thru -6 |
| | | | | 640484-3 thru -6 |
| | | | | 640546-8 thru -12 |
| | | | | 640600-16 thru -20 |
| | | | | 640627-16 thru -20 |
| | | | | 640630-16 thru -20 |
| | | | | 640633-16 thru -20 |
| | | | | 640636-16 thru -20 |
| | | | | 640639-16 thru -20 |
| | | | | 640642-16 thru -20 |
| | | | | 640684-16 thru -20 |
| | | | | 640720-16 thru -20 |
| | | | | 640721-16 thru -20 |
| | | | | 640723-16 thru -20 |
| | | | | 640725-16 thru -20 |
| | | | | 640727-16 thru -20 |
| | | | | 640838-16 thru -20 |
| | | | | 640910-1, -4, -6, -8 |
| | | | | 640910-2, -4, -6, -8 |
| | | | | 640911-1, -4, -6, -8 |
| | | | | 640912-1, -4, -6, -8 |
| | | | | 640962-16 thru -20 |
| | | | | 640963-16 thru -20 |
| | | | | 640964-16 thru -20 |

TSO-C53 Resistoflex Corporation NE
 Roseland, NJ 07068

TYPE A
 R28xx Series (MS28741) -3 thru -24
 TYPE B
 R38xx Series -4 thru -24Z
 R38xxDD Series -4 thru -24Z
 R98xx Series -4 thru -24Z
 R98xxDD Series -4 thru -24Z
 D38xx Series -3 thru -24Z
 D38xxDD Series -8 thru -24Z
 D98xx Series -3 thru -24Z
 D98xxDD Series -8 thru -24Z
 J38xx Series -3 thru -24Z
 J38xxDD Series -8 thru -24Z
 J98xx Series -3 thru -24Z
 J98xxDD Series -8 thru -24Z

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|--|
| | | | | TYPE C SR28xx Series -4 thru -24 TR28xx Series -4 thru -24 TYPE D SR38xx Series -4 thru -24Z TR38xx Series -8 thru -24Z SR38xxDD Series -4 thru -24Z TR38xxDD Series -4 thru -24Z SR98xx Series -4 thru -24Z TR98xx Series -4 thru -24Z SR98xxDD Series -4 thru -24Z TR98xxDD Series -4 thru -24Z SD38xx Series -3 thru -24Z TD38xx Series -3 thru -24Z SD38xxDD Series -8 thru -24Z TD38xxDD Series -8 thru -24Z SD98xx Series -3 thru -24Z TD98xx Series -3 thru -24Z SD98xxDD Series -8 thru -24Z TD98xxDD Series -8 thru -24Z SJ38xx Series -3 thru -24Z TJ38xx Series -3 thru -24Z SJ38xxDD Series -8 thru -24Z TJ38xxDD Series -8 thru -24Z SJ98xx Series -3 thru -24Z TJ98xx Series -3 thru -24Z SJ98xxDD Series -8 thru -24Z TJ98xxDD Series -8 thru -24Z R123 Series -5 thru -10 QR502XXCC -5 thru -10 QR122XX Series -5 thru -10 R11098-1 R11098-2 R11255 |
| TSO-C53 | Titeflex Division Atlas Corporation 603 Hendee St. Springfield, MA 01109 ALSO Alaska Transportation Co. ATCO Spad Division 4211 Donald Douglas Blvd. Long Beach, CA 90801 | NE | | TYPE D 21000004-F 21000006-F 21000008-F 11000004-F 11000005-F 11000006-F 11000008-F 11000010-F 11000012-F 11000016-F |
| TSO-C53 | The Weatherhead Co. 300 E. 131 St. Cleveland, OH 44108 AND 10671 Lorne St. Sun Valley, CA 91352 | CE-C | NM | TYPE A 94B0100003FL 94B0100004FL 94B0100005FL 94B0100006FL 94B0100008DL 94B0100010DL 94F01000D Series -8 thru -12 94F01000F Series -3 thru -6 94F0100003FL 94F0100004FL 94F0100005FL 94F0100006FL 94F0100008FL 94F0100010DL 41F01000D Series -8 and -12 148-50704-8 148-50705-12 MS-28741 Series -3 thru -20 MS-28759 Series -4 thru -16 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|----|--|---|
| | | | | TYPE B 70A01000C Series -3 thru -12 70B01000C Series -3 thru -12 70E01000C Series -8 70F01000C Series -8 71A01000C Series -4 and -6 71A01000J Series -4 and -6 72A01000C Series -16A and 20Z 72B01000C Series -16Z and -20Z 73A01000C Series -8 and -10 73A01000J Series -8 and -10 TYPE C 41F01000D Series -8 and -12 88F01000F Series 94F01000D Series -8 thru -12 94F01000F Series -3 thru -6 94F0100003FL 94F0100004FL 94F0100005FL 94F0100006FL 94F0100008DL 94F0100010DL TYPE D 70E01000C Series -8 70F01000C Series -8 |
| TSO-C53a *F | Aeroquip Aerospace S.A. 14 rue du Morvan SILIC 112 94153 Rungis Cedex, France | EU | FUEL AND ENGINE OIL SYSTEM HOSE ASSEMBLIES | TYPE A AT2011-3-4-5 AT2012-6-8-12-12-16-20-24-32 AT2014-3-4-5-6 AT2015-8-10-12-16-20-24-32-40-48 TYPE B AR1011-4, -5, -6, -8, -10, -12 AR1017-3, -4, -5, -6, -8, -10, -12 AR1048-4, -5, -6, -8, -10, -12, -16 TYPE C AT2103-4-6-8-10-12-16-20 AT2114-3-4-5-6-8-10-12-16-20-24-32 AT2115-6-8-10-12-16-24-32 AT2120-3-4-5-6 AT2121-8-10-12-16-20-24-32-40-48 AT2127-6-8-10-12-16-20 AT2128-3-4-5-6-8-10-12 AT2152-4-6-8-10-12-16-20 AT2154-4-6-8-10-12-16-20 AT2155-6-8 AT2156-6-8 TYPE D AR1117-3, -4, -5, -6, -8, -10, -12, -16, -20 AR1130-4, -5, -6, -8, -10, -12, -16, -20, -24 AR1132-3, -4, -5, -6, -8, -10, -12, -16, -20, -24 AR1136-3, -4, -5, -6, -8, -10, -12, -16, -20 AR1158-4, -5, -6, -8, -10, -12, -16 |
| TSO-C53a | Aeroquip Corporation Aeroquip Aerospace Division 300 S. East Avenue Jackson, MI 49203 AND Aero Hardware & Supply, Inc. 4301 N.W. 36th Street Miami Springs, FL 33166 AND Aerotech World Trade Corp. P.O. Box 218 Purchase, NY 10577 AND Herber Aircraft Service, Inc. | NM | | TYPE A AR1058-8, -10, -12, -16 AT2205-6, -8, -10, -12 AT22006 AT2013-12, -20, -24, -32 AT2206-6, -8, -10, -12 AT22008 AT2107-8, -20 AT2207-6, -8, -10, -12 AR1179-3 AT2108-6, -8, -10, -12 AR1175-24 AT2109-6, -8, -10, -12 AR1186-3 AT2202-6, -8, -10, -12 AR1195-4, -6-8 AT2203-6, -8, -10, -12 AR1196-6 AT2204-6, -8, -10, -12 AT2197-4, -6, -8, -10, -12, -16, -20 TYPE B AR116-2, -4, -6, -8 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|----|-----------|--|
| | 120 Center Street El Segundo, CA 90245 AND VanDusen Aircraft Enrg. Inc. 3327 North Seventh Street Kansas City, KS 66115 AND Boeing Comm. Airplane Co. Building 17-55, Bay 1 Auburn, WA 98124 AND Airparts Company, Inc. 5801 West Harry Wichita, KS 67277 AND Aeroquip Corporation Aeroquip Aerospace Division P.O. Box 369, Highway 264 Middlesex, NC 27557 AND Nelson-Dunn, Inc. 940 South Vail Avenue Montebello, CA 90640 AND Piedmont Aviation, Inc. Smith Reynolds Airport Winston-Salem, NC 27102 AND Grumman Aerospace Corporation Martin County Airport Stuart, FL 33494 AND Grumman Aerospace Corp. Bethpage, L.I., NY 11714 AND Hoses Unlimited, Inc. 618 Doolittle Drive San Leandro, CA 94577 AND Alamo Accessories, Inc. 10843 Vandale San Antonio, TX 78216 AND Bailey Hose, Inc. Rt. 1, P.O. Box 515 (Dove Road) Roanoke, TX 76262 AND Eastern Aero Supply, Inc. Municipal Airport Millville, NJ 08332 AND Ni-Cad, Inc. 4715 W. Progress Drive South Bend, IN 46628 | | | AR1011-20 AR1017-20 AR1048-10, -12, -16 AR1052-4, -5, -6, -8, -10, -12 AR1057-3 AR1063-05, -06, -08, -10, -12 AR1172-5, -8, -10 AR1417-4, -6, -8, -10, -12 AR1418-4, -6, -8, -10 K600000 Series -3 thru -20 L600000 Series -3 thru -20 M600000 Series -3 thru -20 725000-3 TYPE C AR1180-8, -10, -12, -16 AR1182-4, -8, -10 AT2114-3, -5, -6, -8, -10, -12, -16, -20, -24, -32 AT2127-6, -10, -12, -24, -32 AT2128-3, -4, -5, -6, -8, -10, -12 AT2146-3, -4, -5, -6, -8, -10, -12, -16, -20, -24, -32 AT2154-4, -6, -8, -10, -12, -16, -20 AT2155-6, -8 AT2156-6, -8 AT2164-8, -10, -12, -16, -20, -24, -32, -48 AT2171-6, -8, -10, -12 AT2172-6, -8, -10, -12 AT2175-3, -4, -5 AT2176-20 AT2182-8 AT2179-8, -20 AT2193-6, -8, -10, -12 AT2181-10, -12, -20 AT2194-6, -8, -10, -12 AT2185-3, -4, -5 AT2195-6, -8, -10, -12 AT2186-6, -8, -10, -16, -32 AT2187-3, -4, -5 AT2196-6, -8, -10, -12 AT2188-6, -8, -10, -16, -24 AT2190-24, -32 AT2191-6, -8, -10, -12 AT2192-6, -8, -10, -12 AT2198-20 TYPE D AR116-2-4-6-8 AR1154-3, -4, -5, -6, -8, -10, -12, -16, -20 AR1158-10, -12, -16 AR1164-4, -5, -6, -8, -10 AR1167-20, -24 AR1168-3, -4, -5, -6, -8, -10, -12, -16 AR1170-3 AR1171-3, -4, -5, -6, -8, -10, -12, -16, -20 AR1172-5, -8, -10 AR1173-3 AR1174-4, -6, -8, -10, -12, -16 AR1175-20, -24 AR1176-3 AR1177-4, -5, -6, -8, -10, -12, -16, -20, -24 AR1532-4, -6, -8, -10, -12 AR1533-4, -6, -8, -10, -12 AR1534-4, -6, -8, -10 AR1535-4, -6, -8, -10 AR1536-4, -6, -8, -10 AR1172-3, -4, -6, -12, -16 AR1174-3 AR1186-4, -5, -6, -8, -10, -12 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|----|-----------|--|
| | | | | AR1193-06, -08, -10, -12 AR1194-06, -08, -10, -12 AR1192-05, -06, -08, -10, -12 AR1187-10 |
| TSO-C53a *F | Aeroquip (Canada) Ltd. 287 Bridgland Avenue Toronto, Ontario Canada M6A 1Z7 | NE | | TYPE A AR2103-4, -6, -8, -10, -12, -16, -20 AT2200-6, -8 TYPE B AR1011-4, -5, -6, -8, -10, -12 AR1048-4, -5, -6, -8, -10, -12, -16 TYPE C AT2152-4, -6, -8, -10, -12, -16, -20 AT2156-6, -8 AT2181-4, -6, -8, -10, -12, -16 TYPE D AR1136-4, -5, -6, -8, -10, -12 AR1158-4, -5, -6, -8, -10, -12, -16 AR1171-4, -5, -6, -10, -12, -16, -20 AR1174-4, -6, -8, -12 AR1535-4, -6, -8, -10 AR1536-4, -6, -8, -10 |
| TSO-C53a | Aero Systems Mfg. and Overhaul Inc. Hangar No. 17, JFK Int. Arpt. Jamaica, NY 11430 | NE | | TR502XXCC TR503XXCC SR38XXCC SR98XXCC |
| TSO-C53a *F | Anglo American Aviation Co. (Singapore) Pte. Ltd. Block 1, Unit 1011, 10th Floor PSA Multi-Storey Complex Pasir Panjang Road Singapore 0511 | EU | | TYPE A AR1014-3 thru -20 AR1015-3 thru -20 AR1016-3 thru -20 AT2011-3, -4, -5 AT2012-6D thru -32D AT2014-3 thru -6 AT2015-8 thru -48 TYPE B AR1011-3 thru -20 AR1012-3 thru -20 AR1017-3, -4, -5, -6, -8, -10, -12, -16, -20, -24 AR1048-4, -5, -6, -8, -10, -12, -16 AR1051-3 AR1017-20 AR1417-4, -6, -8, -10, -12 TYPE C AT2127-20D, -24, -32 AT2146-3, -4, -5, -6, -8, -10, -12, -16, -20, -24, -32 AT2164-8, -10, -12, -16, -20, -24, -32, -48 AT2175-3, -4, -5 AT2176-20 TYPE D AR1132-3, -4, -5, -6, -8, -10, -16, -20, -24 AR1135-3 thru -20 AR1136-3 thru -20 AR1158-4, -5, -6, -8, -10, -12, -16 AR1160-3 AR1161-4 AR1168-4, -5, -6, -8, -10, -12 AR1170-3 AR1167-24 AR1171-20 AR1174-4, -6, -8, -10, -12 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|----|-----------|--|
| TSO-C53a | Deutsch Metal Components 14800 South Figueroa Street Gardena, CA 92048-1795 AND Air Pro 2921 N.W. 79th Ave. Miami, FL 33152 AND Go Air 3562 Elm Street Atlanta, GA 30364 AND Hoseco, Inc. 5775 W. 56th St. Arvada, CO 80002 | NM | | <p>TYPE A, Non-Fire-Resistant, Normal Temp. 36(B or J)(XX)000(06 thru 32)DL 36(B or J)(XX)000(03,04,05)FL 38(B or J)(XX)000(03, 04,05) FL 38(B or J)(XX)000(06 thru 32)DL PS36B0001-L PS36B00001-(*) PS36B00002-(*) , -L PS36B00003-(*) , -L PS36B00004-(*) , -L PS36B00005-(*) , -L 41B()000(*)D Length *-4, -6, -8, and -12 only 88(B, D, or J)(XX)000(04 thru 16)FL 94(B, D, or J)(XX)000(08 thru 32)DL 94(B, D, or J)(XX)000(03 thru 06)FL TYPE A, Non-Fire-Resistant Normal Temperature AND TYPE C, Fire-Resistant, Normal Temperature 36F(XX)000(06 thru 32)(D or Y)L 36F(XX)000(03,04,05)(F or X)L 41F()000(*)D Length *-4, -6, -8, and -12 only 88F(XX)000(04 thru 16)(F or X)L 94(F or H)(XX)000(03 thru 06)(F or X)L 94(F or H)(XX)000(08 ND 10)(D or Y)L S94B90157-L TYPE A, TYPE B, TYPE IIA, TYPE IIB, Class A-S/P 50A 0101-X-XXX-XXX 50A 0102-X-XXX-XXX 50A 0103-X-XXX-XXX 50A 0104-X-XXX-XXX 50A 0105-X-XXX-XXX 50A 0106-X-XXX-XXX 50A 0201-X-XXX-XXX 50A 0202-X-XXX-XXX 50A 0203-X-XXX-XXX 50A 0204-X-XXX-XXX 50A 0205-X-XXX-XXX 50A 0206-X-XXX-XXX 50A 0301-X-XXX-XXX 50A 0302-X-XXX-XXX 50A 0303-X-XXX-XXX 50A 0304-X-XXX-XXX 50A 0305-X-XXX-XXX 50A 0306-X-XXX-XXX 50A 0401-X-XXX-XXX 50A 0402-X-XXX-XXX 50A 0403-X-XXX-XXX 50A 0404-X-XXX-XXX 50A 0405-X-XXX-XXX 50A 0406-X-XXX-XXX 50A 0501-X-XXX-XXX 50A 0502-X-XXX-XXX 50A 0503-X-XXX-XXX 50A 0504-X-XXX-XXX 50A 0505-X-XXX-XXX 50A 0506-X-XXX-XXX TYPE B, Non-Fire-Resistant, High Temp. 70A()000(*)C Length *-4, -5, -6, and -8 only 70B()000()C Length 72A()000()C Length 72B()000()C Length 79(B,D,J,X)(XX)000(34 thru 16)CL S79B90201-0167 S79B90320-L S79B90202-0205, -L 80B()000()C Length S79E90201-L S79MBB001-04-() Series, -(1) S79MBB002-04-() Series, -(1 thru 9) S79MBB003-04-() Series, -(1) S79MBB001-05-() Series, -(1 and 2) S79MBB001-06-() Series, -(1 and 2) S79MBB001-08-() Series, -(1 thru 8) S79MBB002-08-() Series, -(1 thru 5) S79MBB003-08-() Series, -(1 thru 7) S79MBB001-10-() Series, -(1 thru 3) S79MBB003-10-() Series, -(1 thru 3) S79MBB005-04-(1)</p> |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | S79MB8006-04-(1 and 2) |
| | | | | 79A(XX)000(04 thru 08)CL |
| | | | | TYPE B, Non-Fire-Resistant, High Temperature AND |
| | | | | TYPE D, Fire-Resistant, High Temperature |
| | | | | 70E()000(*)C Length*-4,-5,-6,& -8 only |
| | | | | 70F()000()C Length |
| | | | | 72E()000()C Length |
| | | | | 72F()000()C Length |
| | | | | 79F()000()C Length |
| | | | | 80F()000()C Length |
| | | | | TYPE D |
| | | | | 79F0100005CL 79F0100005ZL |
| | | | | 79F0200005CL 79F0200005ZL |
| | | | | 79F0300005CL 79F0300005ZL |
| | | | | 79F0400005CL 79F0400005ZL |
| | | | | 79F0500005CL 79F0500005ZL |
| | | | | 79F0600005CL 79F0600005ZL |
| | | | | 79F5700005CL 79F5700005ZL |
| | | | | 79F0100034CL 79F0100034ZL |
| | | | | 79F0200034CL 79F0200034ZL |
| | | | | 79F0300034CL 79F0300034ZL |
| | | | | 79F0400034CL 79F0400034ZL |
| | | | | 79F0500034CL 79F0500034ZL |
| | | | | 79F0600034CL 79F0600034ZL |
| | | | | 79F5700034CL 79F5700034ZL |
| | | | | TYPE D, ARP 1055A-TYPE 11b & d, CL-P SP |
| | | | | 79E0100004CL 79E0100005CL |
| | | | | 79E0100006CL 79E0100008CL |
| | | | | 79E0200004CL 79E0200005CL |
| | | | | 79E0200006CL 79E0200008CL |
| | | | | 79E0300004CL 79E0300005CL |
| | | | | 79E0300006CL 79E0300008CL |
| | | | | 79E0400004CL 79E0400005CL |
| | | | | 79E0400006CL 79E0400008CL |
| | | | | 79E0500004CL 79E0500005CL |
| | | | | 79E0500006CL 79E0500008CL |
| | | | | 79E0600004CL 79E0600005CL |
| | | | | 79E0600006CL 79E0600008CL |
| | | | | 79E5700004CL 79E5700005CL |
| | | | | 79E5700006CL 79E5700008CL |
| | | | | 79E7100004CL 79E7100005CL |
| | | | | 79E7100006CL 79E7100008CL |
| | | | | 79E7200004CL 79E7200005CL |
| | | | | 79E7200006CL 79E7200008CL |
| | | | | 79E7300004CL 79E7300005CL |
| | | | | 79E7300006CL 79E7300008CL |
| | | | | 79E7400004CL 79E7400005CL |
| | | | | 79E7400006CL 79E7400008CL |
| | | | | 79E7500004CL 79E7500005CL |
| | | | | 79E7500006CL 79E7500008CL |
| | | | | 36F0700006Y-L 36F0700008Y-L |
| | | | | 36F0700010Y-L 36F0700012Y-L |
| | | | | 36F0700016Y-L 36F0700020Y-L |
| | | | | 36F0700024Y-L 36F0700032Y-L |
| | | | | 79B010003/4CL 79B0100005CL |
| | | | | 79B0100016CL 79B020003/4CL |
| | | | | 79B0200005CL 79B030003/4CL |
| | | | | 79B0300005CL 79B040003/4CL |
| | | | | 79B0400005CL 79B050003/4CL |
| | | | | 79B0500005CL 79B060003/4CL |
| | | | | 79B0600005CL 79B0700016CL |
| | | | | 79B0800016CL 79B0900016CL |
| | | | | 79B1000016CL 79B1100016CL |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|----|-----------|--|----------------|-----------|
| | | | | 79B570003/4CL | 79B5700005CL | |
| | | | | 79B5700016CL | 79B5800016CL | |
| | | | | 79B5900016CL | 79B6000016CL | |
| | | | | 79B6100016CL | 79B6200016CL | |
| | | | | 79B710003/4CL | 79B7100005CL | |
| | | | | 79B720003/4CL | 79B7200005CL | |
| | | | | 79B730003/4CL | 79B7300005CL | |
| | | | | 79B740003/4CL | 79B7400005CL | |
| | | | | 79B750003/4CL | 79B7500005CL | |
| | | | | 79F0100012CL | 79F0100016CL | |
| | | | | 79F0100016ZL | 79F0700016CL | |
| | | | | 79F0700016ZL | 79F0800016CL | |
| | | | | 79F0800016ZL | 79F0900016CL | |
| | | | | 79F0900016ZL | 79F1000016CL | |
| | | | | 79F1000016ZL | 79F1100016CL | |
| | | | | 79F1100016ZL | 79F5700016CL | |
| | | | | 79F5700016ZL | S79B90349-12-L | |
| | | | | S79M8B0005-04-01 | | |
| | | | | S79M8B006-04-01 | | |
| | | | | S79M8B006-04-2 | | |
| | | | | S94890157-L | | |
| | | | | TYPE C (and A) | | |
| | | | | 38F (XX)000(03, 04, 05)(F or X) L | | |
| | | | | 38F (XX)000(06 thru 32)(O or Y) L | | |
| | | | | TYPE D (Also B and AS1055B, TYPE 11a and 11b, Class A-S/P) | | |
| | | | | 79E (XX)000(04 thru 80)(C or Z) L | | |
| | | | | 79(F or H)(XX)000(34 thru 16)(C or Z) L | | |
| | | | | S79B90349-12-L | | |
| TSO-C53a | Fenwick S.A., | EU | | 130 | 370 | 400 |
| *F | 15 rue Fenelon 75480 Paris, France | | | 660 | | |
| TSO-C53a | ITALA S.p.A. | EU | | 90D XXXX XX XX XXX X | | |
| *F | Via Piane 13 Somma Lombardo Italy | | | 90E XXXX XX XX XXX X | | |
| | | | | 90F XXXX XX XX XXX X | | |
| | | | | 90G XXXX XX XX XXX X | | |
| | | | | 90H XXXX XX XX XXX X | | |
| | | | | 90J XXXX XX XX XXX X | | |
| | | | | 90K XXXX XX XX XXX X | | |
| | | | | 90M XXXX XX XX XXX X | | |
| | | | | 90N XXXX XX XX XXX X | | |
| | | | | 99X XXXX XX XX XXX X | | |
| | | | | 99X XXXX XX | | |
| TSO-C53a | Resistoflex Corporation | NE | | TYPE B | | |
| | Roseland, NJ 07068 | | | R502XXCC -3 thru -202 | | |
| | | | | R3800CC -3 | | |
| | | | | R38XXCC -4, -5, -6, -8, -10, -12, -16Z, -20Z, -24Z | | |
| | | | | R8960 Series -4, -5, -6, -8 -10, -12, -16, -20Z | | |
| | | | | R98XXCC -4, -5, -6, -8, -10, -12, -16Z, -20Z, -24Z | | |
| | | | | TYPE D | | |
| | | | | TR3800CC-3 | | |
| | | | | TR502xxCC-4, -6, -8, -10, -12, -16Z, -20Z, -24Z | | |
| | | | | TR503xxCC-4, -6, -8, -10, -12, -16Z, -20Z, -24Z | | |
| | | | | TR8960 Series -4, -5, -6, -8, -10, -12, -16Z, -20Z | | |
| | | | | PR502XXCC | | PR503XXCC |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|----|-----------|--|--|----------|
| TSO-C53a *F | Star Tech Aviation Industries, Inc. 2840-C Olafson Avenue Richmond, B.C. V6X 2R3 | NE | | D6010000 | D6010100 | D6010200 |
| TSO-C53a | Stratoflex, Inc. Aerospace & Military Connectors 220 Roberts Cut Off Road P.O. Box 10398 Fort Worth, TX 76114 AND Durham Aircraft Serv., Inc. 3701 NW. 66th Avenue Miami, FL 33166 AND Western Skyways, Inc. Troutdale Airport Troutdale, OR 97060 AND Sacramento Sky ranch Executive Airport Sacramento, CA 95822 AND Integrated Aircraft Systems 39 Milford Drive Hudson, OH 44236 AND Aviall 16260 Raymer Street Van Nuys, CA 91406 AND Aviall 2742 Burbank Street Dallas, TX 75235 AND Haxxfield Aviation 8109 Braniff Houston, TX 77017 AND Fas-Orient 21 Loyang Crescent Singapore 1750 AND The Zee Company, Inc. 123 Braniff Drive P.O. Box 32842 San Antonio, TX 78216 AND Precision Hose Technology 3324 N. 74th Avenue Tulsa, OK 74115 AND FAS-Orient (Pte) Ltd. 21 Loyang Crescent Singapore 1750 Note: Design approval part numbers for FAS-Orient listed in letter 8/31/82 Stratoflex Stone Mountain, GA - WITHDRAWN 7/10/89 Stratoflex Irvine, CA - WITHDRAWN 7/10/89 | SW | | TYPE A 111302-4-length 111302-6-length 111302-10-length 111302-16-length 111-312-312-3-length 111-312-312-5-length 111-312-312-8-length 111-312-312-12-length 111-312-312-16-length 111-312-312-20-length 111-312-312-24-length 111-312-312-32-length 111417-3-length 111417-5-length 111417-8-length 111417-12-length 111417-20-length 111417-32-length 125J-3-8 125(XXX)-3 thru -24 111428-1A 131-312-312-4-length 131-312-312-8-length 131-312-312-12-length 131-312-312-20-length 131-312-312-32-length 130001-5-length 130001-8-length 130001-16-length 130001-4S-length 130001-6D-length 130001-10D-length 130001-16D-length 130(XXX)-4S-L Series 130(XXX)-6S-L Series 130(XXX)-10D-L Series 130(XXX)-16D-L Series 156() sizes -3 thru -32 156F() sizes -3 thru -32 156001-3S-length 156001-4S-length 156001-8D-length 156001-12D-length 156001-20D-length 156003-3S-length 156003-5S-length 156003-8D-length 156003-12D-length 156003-20D-length 156005-3S-length 156005-5S-length 156005-8D-length 156005-12D-length 156005-20D-length 156060-4S-length 156060-8D-length 156060-12D-length 156060-3S-length 156060-20D-length | 111302-5-length 111302-8-length 111302-12-length 111302-20-length 111-312-312-4-length 111-312-312-6-length 111-312-312-10-length 111417-4-length 111417-6-length 111417-10-length 111417-16-length 111417-24-length 124J(XXX)-5 111() 125F(XXX) 111428-2 131-312-312-6-length 131-312-312-10-length 131-312-312-16-length 131-312-312-24-length 130001-4-length 130001-6-length 130001-12-length 130001-20-length 130001-5S-length 130001-8D-length 130001-12D-length 130001-20D-length 130(XXX)-5S-L Series 130(XXX)-8D-L Series 130(XXX)-12D-L Series 130(XXX)-20D-L Series 156001-5S-length 156001-6D-length 156001-10D-length 156001-16D-length 156001-24D-length 156003-4S-length 156003-6D-length 156003-10D-length 156003-16D-length 156003-24D-length 156005-4S-length 156005-6D-length 156005-10D-length 156005-16D-length 156005-24D-length 156060-6D-length 156060-10D-length 156060-16D-length 156060-5S-length 156060-24D-length | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|-------------------------|
| | | | | 156062-3S-length |
| | | | | 156062-5S-length |
| | | | | 156062-8D-length |
| | | | | 156062-12D-length |
| | | | | 156062-20D-length |
| | | | | 156115-3S-length |
| | | | | 156115-5S-length |
| | | | | 156115-8D-length |
| | | | | 156115-12D-length |
| | | | | 156115-20D-length |
| | | | | 156141-3S-10D-length |
| | | | | 156141-5S-16D-length |
| | | | | 156141-8D-24D-length |
| | | | | 156143-4S-12D-length |
| | | | | 156143-6D-20D-length |
| | | | | 156145-3S-10D-length |
| | | | | 156145-5S-16D-length |
| | | | | 156145-8D-24D-length |
| | | | | 156190-4S-12D-length |
| | | | | 156190-6D-20D-length |
| | | | | 156192-3S-10D-length |
| | | | | 156192-5S-16D-length |
| | | | | 156192-8D-24D-length |
| | | | | 156235-4S-12D-length |
| | | | | 156235-6D-20D-length |
| | | | | 156536-4S-length |
| | | | | 156536-8D-length |
| | | | | 156536-12D-length |
| | | | | 156537-4S-length |
| | | | | 156537-8D-length |
| | | | | 156537-12D-length |
| | | | | 156538-4S-length |
| | | | | 156538-8D-length |
| | | | | 156538-12D-length |
| | | | | 156539-4S-length |
| | | | | 156539-8D-length |
| | | | | 156539-12D-length |
| | | | | 156540-4S-length |
| | | | | 156540-8D-length |
| | | | | 156540-12D-length |
| | | | | 170(XXX)-4CR-L Series |
| | | | | 170(XXX)-6CR-L Series |
| | | | | 170(XXX)-8CR-L Series |
| | | | | 170(XXX)-10CR-L Series |
| | | | | 170(XXX)-12CR-L Series |
| | | | | 170(XXX)-16CR-L Series |
| | | | | 176H(XXX) |
| | | | | 176F(XXX) |
| | | | | TYPE B |
| | | | | 124() |
| | | | | 124001-4SS-L-Series |
| | | | | 124001-6SS-L-Series |
| | | | | 124001-10SS-L-Series |
| | | | | 124001-16SS-L-Series |
| | | | | 124701-4SS-L-Series |
| | | | | 124701-6SS-L-Series |
| | | | | 124701-10SS-L-Series |
| | | | | 124F() |
| | | | | 124H(XXX)-4 through -12 |
| | | | | 124J(XXX) |
| | | | | 125F(XXX) |
| | | | | 170(XXX)-4CR-L-Series |
| | | | | 170(XXX)-6CR-L-Series |
| | | | | 170(XXX)-8CR-L-Series |
| | | | | 170(XXX)-10CR-L-Series |
| | | | | 156062-4S-length |
| | | | | 156062-6D-length |
| | | | | 156062-10D-length |
| | | | | 156062-16D-length |
| | | | | 156062-24D-length |
| | | | | 156115-4S-length |
| | | | | 156115-6D-length |
| | | | | 156115-10D-length |
| | | | | 156115-16D-length |
| | | | | 156115-24D-length |
| | | | | 156141-4S-12D-length |
| | | | | 156141-6D-20D-length |
| | | | | 156143-3S-10D-length |
| | | | | 156143-5S-16D-length |
| | | | | 156143-8D-24D-length |
| | | | | 156145-4S-12D-length |
| | | | | 156145-6D-20D-length |
| | | | | 156190-3S-10D-length |
| | | | | 156190-5S-16D-length |
| | | | | 156190-9D-24D-length |
| | | | | 156192-4S-12D-length |
| | | | | 156192-6D-20D-length |
| | | | | 156235-3S-10D-length |
| | | | | 156235-5S-16D-length |
| | | | | 156235-8D-24D-length |
| | | | | 156536-6D-length |
| | | | | 156536-10D-length |
| | | | | 156536-16D-length |
| | | | | 156537-6D-length |
| | | | | 156537-10D-length |
| | | | | 156537-16D-length |
| | | | | 156538-6D-length |
| | | | | 156538-10D-length |
| | | | | 156538-16D-length |
| | | | | 156539-6D-length |
| | | | | 156539-10D-length |
| | | | | 156539-16D-length |
| | | | | 156540-6D-length |
| | | | | 156540-10D-length |
| | | | | 156540-16D-length |
| | | | | 176(XXX) |
| | | | | A1007 |
| | | | | 124001-3SS-L-Series |
| | | | | 124001-5SS-L-Series |
| | | | | 124001-8SS-L-Series |
| | | | | 124001-12SS-L-Series |
| | | | | 124001-20SS-L-Series |
| | | | | 124701-5SS-L-Series |
| | | | | 124701-8SS-L-Series |
| | | | | 124701-12SS-L-Series |
| | | | | 124H(XXX)-3 |
| | | | | 125(XXX) |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | 170(XXX)-12CR-L-Series |
| | | | | 170(XXX)-16CR-L-Series |
| | | | | 176H(XXX) -3, -4, -5, -6, -8, -10, -12 |
| | | | | 4124(XXX)-4, -5, -6, -8, -10, -12 |
| | | | | TYPE C |
| | | | | 111F302-4-length 111F302-5-length |
| | | | | 111F302-6-length 111F302-8-length |
| | | | | 111F302-10-length 111F302-12-length |
| | | | | 111F302-16-length 111F302-20-length |
| | | | | 111-312F312-3-length 111-312F312-4-length |
| | | | | 111-312F312-5-length 111-312F312-6-length |
| | | | | 111-312F312-8-length 111-312F312-10-length |
| | | | | 111-312F312-12-length 111-312F312-16-length |
| | | | | 111-312F312-20-length 111-312F312-24-length |
| | | | | 111-312F312-32-length |
| | | | | 111F-() 111E-() |
| | | | | 111D(XXX), sizes -4 thru -24 |
| | | | | 124F() sizes -3 thru -24 |
| | | | | 111F417-3-length 111F417-4-length |
| | | | | 111F417-5-length 111F417-6-length |
| | | | | 111F417-8-length 111F417-10-length |
| | | | | 111F417-12-length 111F417-16-length |
| | | | | 111F417-20-length 111F417-24-length |
| | | | | 111F417-32-length 111443-8-length |
| | | | | 112121-4-length 112121-16-length |
| | | | | 130F001-4-length 130F001-5-length |
| | | | | 130F001-6-length 130F001-8-length |
| | | | | 130F001-12-length 130F001-16-length |
| | | | | 130F001-20-length 130F001-4S-length |
| | | | | 130F001-5S-length 130F001-6D-length |
| | | | | 130F001-8D-length 130F001-10D-length |
| | | | | 130F001-12D-length 130F001-16D-length |
| | | | | 130F001-20D-length |
| | | | | 130F(XXX)-4S-L Series |
| | | | | 130F(XXX)-5S-L Series |
| | | | | 130F(XXX)-6S-L Series |
| | | | | 130F(XXX)-8D-L Series |
| | | | | 130F(XXX)-10D-L Series |
| | | | | 130F(XXX)-12D-L Series |
| | | | | 130F(XXX)-16D-L Series |
| | | | | 130F(XXX)-20D-L Series |
| | | | | 131-312F312-4-length 131-312F312-6-length |
| | | | | 131-312F312-8-length 131-312F312-10-length |
| | | | | 131-312F312-12-length 131-312F312-16-length |
| | | | | 131-312F312-20-length 131-312F312-24-length |
| | | | | 131-312F312-32-length 156E001-3S-length |
| | | | | 156E001-4S-length 156E001-5S-length |
| | | | | 156E001-6D-length 156E001-8D-length |
| | | | | 156E001-10D-length 156E001-12D-length |
| | | | | 156E001-16D-length 156E001-20D-length |
| | | | | 156E001-24D-length 156E003-3S-length |
| | | | | 156E003-4S-length 156E003-5S-length |
| | | | | 156E003-6D-length 156E003-8D-length |
| | | | | 156E003-10D-length 156E003-12D-length |
| | | | | 156E003-16D-length 156E003-20D-length |
| | | | | 156E003-24D-length 156E005-3S-length |
| | | | | 156E005-4S-length 156E005-5S-length |
| | | | | 156E005-6D-length 156E005-8D-length |
| | | | | 156E005-10D-length 156E005-12D-length |
| | | | | 156E005-16D-length 156E005-20D-length |
| | | | | 156E005-24D-length 156E080-3S-length |
| | | | | 156E080-4S-length 156E080-5S-length |
| | | | | 156E080-6D-length 156E080-8D-length |
| | | | | 156E080-10D-length 156E080-12D-length |
| | | | | 156E080-16D-length 156E080-20D-length |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | | | | 156E080-24D-length |
| | | | | 156060A thru 156060K(lgth)E(twist angle) |
| | | | | 156062A thru 156062K(lgth)E(twist angle) |
| | | | | 156115A thru 156115K(lgth)E(twist angle) |
| | | | | 156E141-3S-length 156E141-4S-length |
| | | | | 156E141-5S-length 156E141-6D-length |
| | | | | 156E141-8D-length 156E141-10D-length |
| | | | | 156E141-12D-length 156E141-16D-length |
| | | | | 156E141-20D-length 156E141-24D-length |
| | | | | 156E143-3S-length 156E143-4S-length |
| | | | | 156E143-5S-length 156E143-6D-length |
| | | | | 156E143-8D-length 156E143-10D-length |
| | | | | 156E143-12D-length 156E143-16D-length |
| | | | | 156E143-20D-length 156E143-24D-length |
| | | | | 156E145-3S-length 156E145-4S-length |
| | | | | 156E145-5S-length 156E145-6D-length |
| | | | | 156E145-8D-length 156E145-10D-length |
| | | | | 156E145-12D-length 156E145-16D-length |
| | | | | 156E145-20D-length 156E145-24D-length |
| | | | | 156190A thru 156190K(lgth)E(twist angle) |
| | | | | 156192A thru 156192K(lgth)E(twist angle) |
| | | | | 156235A thru 156235K(lgth)E(twist angle) |
| | | | | 156F001-3S-length 156F001-4S-length |
| | | | | 156F001-5S-length 156F001-6D-length |
| | | | | 156F001-8D-length 156F001-10D-length |
| | | | | 156F001-12D-length 156F001-16D-length |
| | | | | 156F001-20D-length 156F001-24D-length |
| | | | | 156F003-3S-length 156F003-4S-length |
| | | | | 156F003-5S-length 156F003-6D-length |
| | | | | 156F003-8D-length 156F003-10D-length |
| | | | | 156F003-12D-length 156F003-16D-length |
| | | | | 156F003-20D-length 156F003-24D-length |
| | | | | 156F005-3S-length 156F005-4S-length |
| | | | | 156F005-5S-length 156F005-6D-length |
| | | | | 156F005-8D-length 156F005-10D-length |
| | | | | 156F005-12D-length 156F005-16D-length |
| | | | | 156F005-20D-length 156F005-24D-length |
| | | | | 156F060-3S-length 156F060-4S-length |
| | | | | 156F060-5S-length 156F060-6D-length |
| | | | | 156F060-8D-length 156F060-10D-length |
| | | | | 156F060-12D-length 156F060-16D-length |
| | | | | 156F060-20D-length 156F060-24D-length |
| | | | | 156060A thru 156060K(lgth)F(twist angle) |
| | | | | 156F062-3S-length 156F062-4S-length |
| | | | | 156F062-5S-length 156F062-6D-length |
| | | | | 156F062-8D-length 156F062-10D-length |
| | | | | 156F062-12D-length 156F062-16D-length |
| | | | | 156F062-20D-length 156F062-24D-length |
| | | | | 156062A thru 156062K(lgth)F(twist angle) |
| | | | | 156F080-12D-length 156F080-16D-length |
| | | | | 156F080-20D-length 156F080-24D-length |
| | | | | 156F115-3S-length 156F115-4S-length |
| | | | | 156F115-5S-length 156F115-6D-length |
| | | | | 156F115-8D-length 156F115-10D-length |
| | | | | 156F115-12D-length 156F115-16D-length |
| | | | | 156F115-20D-length 156F115-24D-length |
| | | | | 156115A thru 156115K(lgth)F(twist angle) |
| | | | | 156F141-3S-length 156F141-4S-length |
| | | | | 156F141-5S-length 156F141-6D-length |
| | | | | 156F141-8D-length 156F141-10D-length |
| | | | | 156F141-12D-length 156F141-16D-length |
| | | | | 156F141-20D-length 156F141-24D-length |
| | | | | 156F143-3S-length 156F143-4S-length |
| | | | | 156F143-5S-length 156F143-6D-length |
| | | | | 156F143-8D-length 156F143-10D-length |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | | | | 156F143-12D-length |
| | | | | 156F143-16D-length |
| | | | | 156F143-20D-length |
| | | | | 156F143-24D-length |
| | | | | 156F145-3S-length |
| | | | | 156F145-4S-length |
| | | | | 156F145-5S-length |
| | | | | 156F145-6D-length |
| | | | | 156F145-8D-length |
| | | | | 156F145-10D-length |
| | | | | 156F145-12D-length |
| | | | | 156F145-16D-length |
| | | | | 156F145-20D-length |
| | | | | 156F145-24D-length |
| | | | | 156F190-3S-length |
| | | | | 156F190-4S-length |
| | | | | 156F190-5S-length |
| | | | | 156F190-6D-length |
| | | | | 156F190-8D-length |
| | | | | 156F190-10D-length |
| | | | | 156F190-12D-length |
| | | | | 156F190-16D-length |
| | | | | 156F190-20D-length |
| | | | | 156F190-24D-length |
| | | | | 156190A thru 156190K(lgth)F(twist angle) |
| | | | | 156192A thru 156192K(lgth)F(twist angle) |
| | | | | 156235A thru 156235K(lgth)F(twist angle) |
| | | | | 156F536-4S-length |
| | | | | 156F536-6D-length |
| | | | | 156F536-8D-length |
| | | | | 156F536-10D-length |
| | | | | 156F536-12D-length |
| | | | | 156F536-16D-length |
| | | | | 156F537-4S-length |
| | | | | 156F537-6D-length |
| | | | | 156F537-8D-length |
| | | | | 156F537-10D-length |
| | | | | 156F537-12D-length |
| | | | | 156F537-16D-length |
| | | | | 156F538-4S-length |
| | | | | 156F538-6D-length |
| | | | | 156F538-8D-length |
| | | | | 156F538-10D-length |
| | | | | 156F538-12D-length |
| | | | | 156F538-16D-length |
| | | | | 156F539-4S-length |
| | | | | 156F539-6D-length |
| | | | | 156F539-8D-length |
| | | | | 156F539-10D-length |
| | | | | 156F539-12D-length |
| | | | | 156F539-16D-length |
| | | | | 156F540-4S-length |
| | | | | 156F540-6D-length |
| | | | | 156F540-8D-length |
| | | | | 156F540-10D-length |
| | | | | 156F540-12D-length |
| | | | | 156F540-16D-length |
| | | | | 170(XXX)-4CR-L Series |
| | | | | 170(XXX)-6CR-L Series |
| | | | | 170(XXX)-8CR-L Series |
| | | | | 170(XXX)-10CR-L Series |
| | | | | 170(XXX)-12CR-L Series |
| | | | | 170(XXX)-16CR-L Series |
| | | | | 176(XXX) |
| | | | | 176F(XXX) |
| | | | | 176D(XXXX) |
| | | | | Type D |
| | | | | 124D001-3SS-length |
| | | | | 124D001-4SS-length |
| | | | | 124D001-5SS-length |
| | | | | 124D001-6SS-length |
| | | | | 124D001-8SS-length |
| | | | | 124D001-10SS-length |
| | | | | 124D001-12SS-length |
| | | | | 124D001-16SS-length |
| | | | | 124D001-20SS-length |
| | | | | 124D(XXX)-4 thru -24 - length |
| | | | | 124DS(XXX)-10CR-length(Series) |
| | | | | 124DS(XXX)-12CR-length(Series) |
| | | | | 124DS(XXX)-16CR-length(Series) |
| | | | | 124F() |
| | | | | 124F001-3SS-length |
| | | | | 124F001-4SS-length |
| | | | | 124F001-6SS-length |
| | | | | 124F001-8SS-length |
| | | | | 124F001-10SS-length |
| | | | | 124F001-12SS-length |
| | | | | 124F001-16SS-length |
| | | | | 124F001-20SS-length |
| | | | | 124H(XXX)-4 through -12 |
| | | | | 124J() |
| | | | | 141()141F() |
| | | | | 170(XXX)-4CR-L Series |
| | | | | 170(XXX)-6CR-L Series |
| | | | | 170(XXX)-8CR-L Series |
| | | | | 170(XXX)-10CR-L Series |
| | | | | 170(XXX)-12CR-L Series |
| | | | | 170(XXX)-16CR-L Series |
| | | | | 3130555 |
| | | | | 4124(XXX)-4, -5, -6, -8, -10, -12 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|----|-----------|---|
| *F | Route de Chateaudun 41000 Blois, France | | | 661 moduel 4 661 module 6 661 module 10 661 module 16 TYPE D 661 module 4 661 module 6 662 module 10 662 module 16 661 module 5 661 module 8 662 module 12 661 module 5 661 module 8 662 module 12 |
| TSO-C53a | Titeflex Division Atlas Corporation 603 Hendee St. Springfield, MA 01109 AND Alaska Transportation Co. 4211 Donald Douglas Blvd. Long Beach, CA 90801 AND Boeing-Vertol Company Essington, PA 19029 | NE | | TYPE A 410 Series, -24 41000004-length 41000008 thru 41000032 41202004 length 41000006-length 41202016 length TYPE B 12000004-() 12000006-() 12000010-() 12000016Z-() 13000004-() 13000006-() 13000010-() 13000016Z-() 12000005-() 12000008-() 12000012-() 12000020Z-() 13000005-() 13000008-() 13000012-() 13000020Z-() TYPE C RF410, -08, -10, -12, -16, -20, -24 410 Series, -24 41000008-S thru 41000032-S 41000004-S-length 41202004-S length 41000006-S-length 41202016-S-length thru 4120216-S-length TYPE D 12000004-()S 12000006-()S 12000010-()S 12000016Z-()S 13000004-()F 13000008-()F 13000016-()F 13000003-()FS 13000003-(length) thru 13000012-(length) 13000004-()S 13000006-()S 13000010-()S 13000016Z-()S 13000004-()W 13000006-()W 13000010-()W 13000016Z-()W 13202008-()S 13202012-()S 13202020-()S 13000005-()S 13000008-()S 13000012-()S 13000020Z-()S 13000005-()W 13000008-()W 13000012-()W 13202006-()S 13202010-()S 13202016Z-()S S395 sizes -0 thru -12 S408 sizes -05 thru -12 S409 sizes -05 thru -12 S410 sizes -05 thru -12 S411 sizes -05 thru -12 S412 sizes -05 thru -12 S428 sizes -03 thru -16Z S429 sizes -03 thru -16Z 130:M13XXX-03-(length) thru M13XXX-06-(length, M13XXX-08, -10, -12, -16Z-(length) |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | |
|----------------|--|------------------------|------------------------------|---|---|
| | | | | RF140 | |
| TSO-C53a *F | Titreflex Europe BP 73 77833 Ozoire La Ferriere France | EU | | Series 130 230/240 | 660 400/410 |
| TSO-C53a | The Weatherhead Company 300 E. 131st St. Cleveland, OH 44108 AND 10671 Lorne St. Sun Valley, CA 91352 | CE-C NM | | TYPE A 41B0100004DL 41B0100008DL 41B01000016D-L 41B0100024D-L TYPE B 70A0100004CL 70A0100006CL 70E0100004CL 70E0100006CL TYPE C 41F0100004DL 41F0100008DL 70E0100004CL 70E0100006CL | 41B0100006DL 41B01000012DL 41B0100020D-L 41B0100032D-L 70A0100005CL 70A0100008CL 70E0100005CL 70E0100008CL 41F0100006DL 41F0100012DL 70E0100005CL 70E0100008CL |
| TSO-C53a | Western Coupling Corp. Building 67 Mojave Airport Mojave, CA 93501 | NM-L | | 42(X-XX-XX-X-XXX-X-XXX-X) Series Type A 53(X-XX-XX-X-XXX-X-XXX-X) Series Type B 62(X-XX-X-XXX-X-XXX-X) Series Type C 73(X-XX-XX-X-XXX-X-XXX-X) Series Type D | |
| TSO-C54 | Bendix Flight & Engine Inst. Div. South Montrose, PA 18843 | NE | STALL WARNING INSTRUMENTS | 331038-1 | 3567300-0000 |
| TSO-C54 | Globe Industries Div. of TRW, Inc. 2275 Stanley Ave. Dayton, OH 45404 | CE-C | | 35A557 | |
| TSO-C54 | Gulton-Servonic A Marck IV Company 1644 Whittier Avenue Costa Mesa, CA 92627 | NM | | 25147A() Ser. 2568A() 455318AA() | 54301-() 54302() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|---|------|---|---|---------------------|---|
| TSO-C54 | Lear Siegler, Inc. Astronics Division 3171 S. Bundy Dr. Santa Monica, CA 90406 | NM | | 562T | | |
| TSO-C54 | Monmouth Electronics Corp. Marlboro, NJ 07746 | NE | | S-21341 | | |
| TSO-C54 | Rosemount, Inc. 14300 Judicial Road Burnsville, MN 55337 | CE-W | | 861CAN | | |
| TSO-C54 | Rosemount, Inc. 12001 W. 78th Street Eden Prairie, MN 55343 | CE-W | | 861CAB 861CAR() 861CAV() | 20AK() AOA/AOS | 30AK()/AOA 861CAS() |
| TSO-C54 | Rosemount, Inc. P.O. Box 35129 Minneapolis, MN 55435 | E-W | | 861CAK() | | |
| TSO-C54 | Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602 | NE | | Precision Stall Warning System C-25502 C-27207 C-27406 C-75802 C-75805-3 C75806-2 C-75807-2 C-75809-2 DHC-5 SC-150 SC-200 SY-101-() SY-102 SY-103-() SY-104-() SY-105() C77206-2 C77207 C81506-2 C81606-2 103-12 | | |
| TSO-C54 | Sundstrand Data Control Inc 15001 N.E. 36th St. P.O. Box 97001 Redmond, WA 98073-9701 | NM | | 3267-1G 965-4003-()Ser. 965-0347-002 965-0449-001 965-0041-036 | | 3267-() Ser. 965-0347-001Ser 965-4020-007 965-0041-031 965-0041-()Ser |
| TSO-C54 | Sundstrand Data Control, Inc. Building 2114 Grant County Airport Moses Lake, WA 98837 | NM-S | | 965-0449-() | | 965-0449-002, -011 |
| TSO-C54 | Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906 | NE | | SL112B3500 SLZ9798B | SLZ7270 SLZ9925B | SLZ9268-1 114B(XXXX) |
| TSO-C54 | Teledyne Controls 12333 West Olympic Blvd. Los Angeles, CA 90064 | NM | | CTR 542-()Ser. TA141():10000165-() | | CTR803-()Ser. |
| TSO-C55 | Ametek U.S. Gauge Division Sellersville, PA 18960 | NE | FUEL AND OIL QUANTITY INSTRU- MENTS (FOR RECIPROCATING ENGINE AIRCRAFT) | VSDL-OC203A | | VSDL-OC403A |
| TSO-C55 | Bendix Flight & Engine Instrument Div. South Montrose, PA 18843 | NE | | 3932241-9001 | | 3932241-9002 |
| TSO-C55 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | 3581320-2001 | | |
| TSO-C55 | Bendix | CE-W | | 3266004-010 | | 3266005-0101 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|-----------|--|
| | Instruments & Life Support Hickory Grove Rd. Davenport, IA 52808 | | | 3266005-0301 3266005-0401 3266005-0201 |
| TSO-C55 | Bendix Corporation Instruments & Life Support Div. 896 Waverly Avenue Holtsville, NY 11742 | NE | | CMF1167 DSF1539 DSF1539-1 PBA1542 PBA1543 PBA1544 PBA1545 |
| TSO-C55 | The Bendix Corporation Flight Systems Division Teterboro, NJ 07608 | NE | | 39332241-9002 3932241-9008 |
| TSO-C55 *F | Canadian Marconi Co. 2442 Trenton Ave. Montreal, Quebec Canada H3P1Y9 | NE | | 730-14:P/Ws 463-691-(), 418-100-(), 418-081-(), 418-120-(), 418-193-(), 418-085-() CMA 730-14 100-476-675-120 |
| TSO-C55 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 169() 910 914 MA 06()-() |
| TSO-C55 | Gull Airborne Instruments, Inc. 395 Oser Avenue Smithtown, NY 11787 | NE | | 010-913-(XXX) 014-931-(XXX) 014-942-(XXX) 016-903-(XXX) 028-025-001 203-021-003 205-018-XXX 205-032-001 206-010-XXX 206-012-XXX 206-016-002 267-959-(XXX) 267-989-001 206-009-(XXX) 302-911-(XXX) 302-913-(XXX) 360-962-(XXX) TYPE II 010-918-001 014-943-() 021-918-001 218-912-(XXX) 267-982-001 302-918-() 360-968-() 360-989-001 |
| TSO-C55 | INSCO Box 365 Euless, TX 76039 | SW | | 9032() 9032-1003 |
| TSO-C55 | Instrument Specialties Company, Inc. 1111 Stanley Drive, Box 365 Euless, TX 76039 | SW | | 9032-1034 9032-1029 5707-1042 5707-1042 5722-3001 9032-3015 |
| TSO-C55 | Kollzman/IDS Avionics Group 110 Coolidge Avenue P.O. Box 81 Englewood, NJ 07631 | NE | | 585-31654-() |
| TSO-C55 | Lewis Engineering Company 238 Water Street Naugatuck, CT 06770-0231 | NE | | Model: 61461-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|---|--|--|--|
| TSO-C55 | Ragen Data Systems, Inc. P.O. Box 413 125 Schmitt Boulevard Farmingdale, NY 11735 | NE | | 212 DSFG 1579-() PAB-575-1 PAA 1893 PAA 1896 PBA 1946-1 PCA 1949 | DSF 684-1 PAA 574-1, -2, -3, -4 PAC 1595-() PAA 1894 PBA 1944 PBA 1947 82-107-4 | DSFG 1594-() PAA 1596-() PAA 1895 PBA 1945 PBA 1948 |
| TSO-C55 | Ragen Data Systems, Inc. 3 Oval Drive P.O. Box 417 Central Islip, NY 11722 | NE | | 73-107-() 83-118-() | 73-108-() 85-119-() | 73-109-() |
| TSO-C55 | Shadin Company, Inc. 6950 Wayzata Blvd, Suite 221 Minneapolis, MN 55426 | CE-W | | 681502 | 911501 | |
| TSO-C55 | Simmonds Precision, Inc. Panton Road Vergennes, VT 05491 | NE | | 393002-007 391002-332, 333, 334, 417, 418, 419, 420, 421, 422 | 473382 | 391057-297 |
| TSO-C55 | Smiths Industries Civil Systems Div. 255 Great Valley Parkway Malvern, PA 19355 | EA | | OCTU-4221-01 | | |
| TSO-C55 | Smiths Industries Harowe Division 255 Great Valley Parkway Malvern, PA 19355 | EA | | 2120-() 2120-03-1 2120-10-1 2120-13-1 | 2120-01-1 2120-04-1 2120-11-1 2120-14-1 | 2120-02-1 2120-09-1 2120-12-1 |
| TSO-C55 *F | Yokogawa Corp. 30-1, Shimomaruko 3-chrome, Ohta-ku, Tokyo Japan | NM | | SPF-38:PF231-N1, PF015-N1, PF532-N1, PF532-N2, PF533-N1, PF533-N2, PF533-N3, PF535-N1 SPF-48:PF232-N1, PF534-N1 SPF-48-N2:PF232-N2, PF534-N2 SPF-48-N3:PF232-N3, PF534-N3 SPF-38 SPF-48 | | |
| TSO-C56 | Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735 | NE | ENGINE-DRIVEN DIRECT CURRENT GENERATORS FOR AIRCRAFT CERTIFI- CATED UNDER | 150SG1110 150SG1160 150SG1190 150SG1220 150SG1250 200SG1140 200SG1180 200SGL1200 250SG1140 250SG1160 300SG1180 | 150SG1140 150SG1170 150SG1200 150SG1230 200SG1110 200SG1150 200SGL1110 200SG1190 200SG1200 250SG1170 300SG1190 | 150SG1150 150SG1180 150SG1210 150SG1240 200SG1120 200SG1170 200SGL1190 250SG1120 250SG1150 300SG1170 300SG1200 |
| TSO-C56 *F | Auxilec 188 rue d'Estienne e'Orve F92700 Colombes France | EU | | 524()() | 8013()() | |
| TSO-C56 | Bendix Electric Power Div. Eatontown, NJ 07724 | NE | | 30837 30856 30890 | 30843 30858 30E20 | 30845 30869 |
| TSO-C56 | Breeze Corporation, Inc. Union, NJ 07083 | NE | | VG-600 | VG-700 | |
| TSO-C56 | Electro-Mech, Inc. | CE-W | | EM8003-1, -2 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|--|---|---|--|
| | 2600 South Custer Wichita, KS 67217 | | | | | |
| TSO-C56 | General Electric Co. Aircraft Equipment Div. 1200 Lawrence Parkway Erie, PA 16501 | NE | | 2CM82J1 2CM82J2 2CM73(J2A) 2CM73(L1) 2CM73(M4) 2CM73(N1) 2CM73(E4) 2CM306-() 2CM504-() | 2CM306C5 2CM73() 2CM73(J2) 2CM73(M1) 2CM73(M5) 2CM73(P1) 2CM82-() 2CM320-() 2CM82Jr | 2CM307() 2CM73(J1A) 2CM73(J3) 2CM73(M2) 2CM73(M6) 2CM73(EA1) 2CM302-() 2CM308-() |
| TSO-C56 | Lear Siegler, Inc. Power Equipment Div. P.O. Box 6719 Cleveland, OH 44101 | CE-C | | G29-78T 23031-004 23032-011 23032-04() 23032-05() 23065-015-2 23846-00() () 30059-000 30081-() | G35-11 23032-00() 23032-020 23035-000 23045-004 23080-() 30007-003 30060-0() 30060-001 | G300-48T 23032-010 23046-00() 13045-() () () 23048-0() () 23081-() 30010-000 30060-001 |
| TSO-C56 | Leland AES, Inc. 1200 Lawrence Parkway Erie, PA 16531 | EA | | 2CM73 2CM73 J2 2CM73 J2A 2CM73 M1 2CM73 M2 | 2CM73 E1A 2CM73 E4 2CM306 2CM306 C5 2CM307 | 2CM308 2CM504 2CM82 J1 2CM82 J2 2CM82 J4 |
| TSO-C56 | Lucas Aerospace Power Equipment Corp. 777 Lena Drive Aurora, OH 44202 | CE-C | | 23031-004 23032-010, 011, 020, 028 23032-04() 23032-045, 046, 047 23032-05() 23032-051, 052, 054 23035-000 23045-() () () 23045-004 23046-00() 23046-001, 002, 003, 004, 005, 006 23048-0() () 23048-001, 004, 006 23065-015-2 23081-() 23081-001, 002, 003, 004, 009, 010, 011, 012, 015, 016, 011-1, 012-1 30007-003 30060-00() G35-11 | 23032-00() 30010-000 30059-000, 002 30060-001 G29-78T G300-48T | |
| TSO-C56a *F | Advance Power, Inc. 152 East Drive Bramalea, Ontario Canada L6T 121 | NE | ENGINE-DRIVEN DIRECT CURRENT GENERATORS/ STARTER- GENERATORS | 7024 10024 | 7024-14 10024-14 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | | | |
|---------------|---|------|--|--|---|------------------|--|--|
| TSO-C56a | Aircraft Parts Corp. 160 Finn Court Farmingdale, NY 11735 | NE | | 300SG121Q 300SG126Q 300SG128Q 300SGL111Q-2 300SGL115Q 300SGL117Q 300SGL125Q 400SG111Q-1 400SG111Q-4 400SG114Q 400SG116Q-1 400SG-116Q, -117Q, -118Q, -119Q, -120Q, -121Q 400SG123Q 400SG125Q 400SG127Q 440SG129Q 400SG131Q 400SG133Q 150SG130Q 150SG133Q 150SG135Q | 300SG125Q 300SG127Q 300SFL111Q-1 300SGL114Q 300SGL116Q 300SGL118Q 300SGL127Q-1 400SG111Q-3 400SG112Q 400SG115Q 400SG117Q-1 400SG124Q 400SG126Q 400SG128Q 400SG130Q 400SG132Q 150SG127Q 150SG132Q 150SG134Q 150SG138Q | | | |
| TSO-C56a | Lucas Aerospace Power Equipment Div. 777 Lena Drive Aurora, OH 44202 | CE-C | | 23080-() 23080-002, 003, 005, 006, 011, 012, 013, 014, 014A, 015, 018, 019, 020, 023, 024, 025, 031, 032 30081-() | 30081-001 | | | |
| TSO-C56a | Vickers ElectroMech 2600 South Custer Wichita, KS 67217 | CE-W | | EM8023-1, -2, -3 EM2099-4 | | | | |
| TSO-C57 *F | Airmed Limited Harlow, Essex England | EU | AIRCRAFT HEAD- SETS AND SPEAKERS (FOR AIR CARRIER AIRCRAFT) | 62 | 70 | 71 | | |
| TSO-C57 | Carter Engineering Co., Inc. 232 S. Glasgow Avenue Inglewood, CA 90301 | NH | | CE550() | CEH 157TR() | | | |
| TSO-C57 | David Clark Co., Inc. P.O. Box 155 360 Franklin Street Worcester, MA 01613 | NE | | 12507G-() H10-56 | 12510G-() H10-76 | H10-50 H10-90 | | |
| TSO-C57 | Electro-Voice Buchanan, MI 49107 | CE-C | | 967M 625HS EV-900 | 967ME E-V 30 | 967TR E-V 300 | | |
| TSO-C57 | Gables Engineering, Inc. P.O. Box 340880 Coral Gables, FL 33134 | CE-A | | G-5515 | | | | |
| TSO-C57 | Gentex Corporation Carbondale, PA 18407 | NE | | DH-146 | | | | |
| TSO-C57 *F | Holmberg & Company Amsterdam, Holland | EU | | 57 DT 3() | 1385 GT 3 | | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--------------------------|--|---|---|
| TSO-C57 | Instrument Systems Corp. Telephonics Division 770 Park Avenue Huntington, L.I., NY 11745 | NE | | M-94A/A | N-181/GIC-10 555D800 | |
| TSO-C57 | Joyce Telectronics Corp. 2070 Calumet Ave. Clearwater, FL 33515 | CE-A | | JT-6A() JT-16A() | JT-85/U() JT-ANB-H | JT-905/A() JT-ANB-H-49() |
| TSO-C57 | The Murdock Corporation Chelsea, MA 02150 | NE | | P-33 | | |
| TSO-C57 | Plantronics, Inc. 345 Encinal Avenue Santa Cruz, CA 95060 | NM | | MS30/T34-() MS-50-() MS57/T30-() | MS30/T30-() MS50/T30-() MS60-6 | MS-50 HS0177-() MS50-75 |
| TSO-C57 *F | Racal-Amplivox Communications, Ltd. Beresford Avenue Wembley, Middlesex England | EU | | J.23 J.234 Version S (- -/- -) Version V (- -/- -) | J.231 13150 | J.232 16400 |
| TSO-C57 | Roanwell Corporation 180 Varick St. New York, NY 10014 | NE | | 10387-620 108630 112390 | 10850() 109740 RHE-798 | 108500() 110160 |
| TSO-C57 | Telephonics 789 Park Avenue Huntington, NY 11743 | NE | | 448D000-1, -2, -3 448D200-1, -2 497-0026-001/2/3/4/5/6 | | 448D100-1 448D300-1 |
| TSO-C57 | Telex Communications, Inc. 9600 Aldrich Ave., S. Minneapolis, MN 55420 | CE-C | | A1210 ARB-1400 CCM-2 CMT-2 HTX-2 PEM-77L 5Mark II TAH-29 MRB-1800 DBM-100() 63274-() 63800-() 63960-() | A610 ATT-1 CMM-2 HTL-2 MRB-600 PEM-77R PEM-78L 12226 HS-500 63600-() 63274-011 63700-() 64000-() | A1400 ATT-2 CCT-2 HTW-2 MRB-2400 PEM-78R 5x5 PRO I EBM-140() 5x5 Mark IIA 63515-() 63950-() 64060-() |
| TSO-C57a *F | Clement Clark Int., Ltd. of Airmed House Edinburgh Way Harlow, Essex United Kingdom | EU | HEADSETS AND SPEAKERS | Airlite 90, 2000 | | |
| TSO-C57a *F | Sony Corporation Dept. Audio Group 7-35 Kitashinagawa 6 Chome Shinagawa-ku, Tokyo 141 Japan | NM-L | | DR-6010:MDR-7010 | | |
| TSO-C57a *F | Sony Corporation 1-7-4, Konan Minato-ku, Tokyo 108 Japan | NM-L | | DR-6010:MDR-7010 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|--|---|--|---|
| TSO-C57a | Telephonics Corporation 789 Park Avenue Huntington, NY 11743 | NE | | 546-0000-001 | | |
| TSO-C57a | Telex Communications, Inc. 9600 Aldrich Avenue South Minneapolis, MN 55420 | CE-C | | 750: 64300-() 760: 64400-() : 70470-() | | |
| TSO-C57b | Gables Engineering, Inc. P.O. Box 880 Coral Gables, FL 33134 | CE-A | AIRCRAFT HEAD- SETS AND SPEAKERS (FOR AIR CARRIER AIRCRAFT) | G-2566() | G6946() | |
| TSO-C58 | Carter Engineering Co., Inc. 232 So. Glasgow Ave. Inglewood, CA 90301 | NM | AIRCRAFT MICROPHONES (FOR AIR CARRIER AIRCRAFT) | CE101TR CEH157TR() | CE201TR | CE550() |
| TSO-C58 | David Clark Company, Inc. P.O. Box 155 360 Franklin Street Worcester, MA 01613 | NE | | M-1/DC 12510G-() H10-56 | H10-76 | H10-50 H10-90 |
| TSO-C58 | Electro-Voice, Inc. Sum of Gulton Ind. Inc. Buchanan, MI 49107 | CE-C | | 205C 603T 967ME E-V 300 | 602FTR 603TR 205C EV-900 | 603A 967H E-V 30 |
| TSO-C58 | Gentex Corporation Carbondale, PA 18407 | NE | | DH-146 | 5060 | 5060-() |
| TSO-C58 *F | Holmberg & Company Amsterdam, Holland | EU | | 57DT() | 1385 GT 3 | |
| TSO-C58 | Instrument Systems Corp. Telephonics Division 770 Park Avenue Huntington, L.I., NY 11745 | NE | | M/94A/A RS-84 | 555D800 | 125 |
| TSO-C58 | Joyce Telectronics Corp. 2070 Calumet St. Clearwater, FL 33515 | CE-A | | JT-6A() JT-905/A() | JT-16A() JT-ANB-H-49() | JT-85/U |
| TSO-C58 | Plantronics, Inc. 345 Encinal Ave. Santa Cruz, CA 95060 | NM | | MS20/T30-() MS30/T34-() MS-50-() MS0177-() | MS20/T34-() MS40/T34-() MS50/T30-3 MS57/T30-() | MS30/T30-() MS40/T30-() MS50/T30-() MS50-75 |
| TSO-C58 *F | Racal-Amplivox Communications, Ltd. Beresford Avenue Middlesex, England | EU | | 16400 Version S(- -/- -) Version V(- -/- -) | | |
| TSO-C58 | Roanwell Corporation 180 Varick St. New York, NY 10014 | NE | | BM-515 ROM-62 108500() 110160 | RM-515 10387-620 108630 112390 | RRM-280 10850-() 109740 |
| TSO-C58 | Shure Brothers, Inc. 222 Hartrey Ave. Evanston, IL 60204 | CE-C | | 488T M700B | CM16TF | CM88TA |
| TSO-C58 | Telephonics | NE | | 448D000-1, -2, -3 | | 448D100-1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|--|--|--|
| | 789 Park Avenue Huntington, NY 11743 | | | 448D200-1, -2 497-0026-001/2/3/4/5/6 | | 448D300-1 |
| TSO-C58 | Telex Communications, Inc. 9600 Aldrich Ave., S. Minneapolis, MN 55420 | CE-C | | 66C 66TMA-() 100T 5x5 PRO I EBM-140() 6333-000 63515-() 63700-() 63999-() | 66T ARB-1400 MRB-2400 MRB-1800 63600() 67266-001 61600-01 63274-011 64000-() | 66TCM MRB-600 5x5 Mark II DBM-100() 500T 5x5 Mark IIA 63800-() |
| TSO-C58a | Electro-Voice, Inc. 600 Cecil Street Buchanan, MI 49107 | CE-C | AIRCRAFT MICROPHONES (EXCEPT CARBON) | 903E | 978-() | 913E() |
| TSO-C58a *F | Sony Corporation Dept. Audio Group 7-35 Kitashinagawa 6 chome Shinagawa-ku, Tokyo 141 Japan | NM-L | | DR6010:ECM-9030 | | |
| TSO-C58a *F | Sony Corporation 1-7-4, Konan Minato-ku, Tokyo 108 Japan | NM-L | | DR-6010:ECM-9030 | | DR-6010:ECM-9031 |
| TSO-C58a | Telephonics Corporation 789 Park Avenue Huntington, NY 11743 | NE | | RS38EL:107C800-21 thru 107C800-27 | | |
| TSO-C58a | Telex Communications, Inc. 9600 Aldrich Avenue South Minneapolis, MN 55420 | CE-C | | 750: P/N 64300-() 70470-() | | 64220-() |
| TSO-C58a | Telex Communications, Inc. Glencoe, MN | CE-W | | 70655-() | | |
| TSO-C59 | ColTech Inc. 21644 N. 9th Ave., Suite 102 Phoenix, AZ 85027 | NM | AIRBORNE SELECTIVE CALLING EQUIPMENT (FOR AIR CARRIER AIRCRAFT) | 1200008() | | |
| TSO-C59 | Delta Electronic Mfrg. Co. Suite 605 11311 Harry Hines Blvd. Dallas, TX 75229 | SW | | DE-207() | | |
| TSO-C59 *F | Elliott Brothers (London) Ltd. Christopher Martin Road Basildon, Essex England | EU | | AD900(), type 2880 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|--|--|--------------------------------|---------------------------------|
| TSO-C59 | Fredrickson Communications, Inc. 11100 W. 82nd St., #104 Lenexa, KS 66214 | CE-W | | 800-0012-002 | 800-0012-005 | |
| TSO-C59 | Motorola, Inc. Communications Division 8000 W. Sunrise Ft. Lauderdale, FL 33300 | CE-A | | NA 136 NA134D4 NA1295() N1401() | NA 135 NA126D2 NA1298() | NA 134D2 NA126D4 N1335() |
| TSO-C59 | Motorola, Inc. Communications Division 4545 W. Augusta Blvd. Chicago, IL 60607 | CE-C | | NA 136 | | |
| TSO-C59 | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM | | S65-8262-(300 Series) S65-8262-301 | S65-8280-(305) | |
| TSO-C59 *F | Team Cy 9 rue Jules Ferry 94200 Ivry sur Seine France | EU | | Selcat 2253() | | |
| TSO-C59 | Terra Corporation 3520 Pan American Freeway NE Albuquerque, NM 87107-4796 | SW | | Jet Call-2:2800-0012-102 Jet Call-5:2800-0012-105 | | |
| TSO-C60 | Bendix Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | AIRBORNE LORAN A RECEIVING EQUIP- MENT OPERATING WITHIN THE RADIO FREQUENCY RANGE OF 1800-2000 KILOCYCLES (FOR AIR CARRIER AIRCRAFT) | PPI-1M | PPI-1L | |
| TSO-C60 *F | Decca Navigator Co., Ltd. 247 Burlington Road New Malden Surrey, England | EU | | ADL 21M | ADL 23 | |
| TSO-C60 | Edo Aire Div. of Edo Corporation Fairfield, NJ 07006 | NE | | 141 142 345 800 | 141A 142A 345A 1200 | 141B 144 600T |
| TSO-C60 | General Instrument Corp. Electronic Systems Div. 600 W. John St. Hicksville, NY 11802 | NE | | LRN-700 02502-() | SPD-02501-() 02503-() | M742-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|--|--|
| TSO-C60a | Advanced Navigation, Inc. 621 Lofstrand Lane Rockville, MD 20850 | NE | AIRBORNE LORAN A & LORAN C RECEIVING EQUIPMENT OPERATING WITHIN THE RADIO-FREQUENCY RANGE OF 1800-2000 AND 90-110 KILO HERTZ RESPECTIVELY | 7000 Loran C:30410035-() |
| TSO-C60a | ARNAV Systems, Inc. 4740 Ridge Drive, NE. Salem, OR 97303 | NM-S | | AVA-1000 |
| TSO-C60a | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | LORAN C CI-109SP() CI-121SP() CI 122SP() CI-238() CI2382SP() CI154() |
| TSO-C60a | Foster AirData Systems, Inc. 7020 Huntley Road Columbus, OH 43229 | CE-C | | LR651 LA121:805C0567 NY153:805C0565 LRN500:805D0630-13, -14, LRN500(501):805D0630-31, -33 NY155:805D068-01 NY164:805C0566 F4 Phoenix LRN:805D0630-21, -22 F4(14):805D0630-41, 42, 43, 44 7000 Loran-C:30410035, -1 thru -11, -14, -16, -17, -18 F4:805D0630-23, -24 |
| TSO-C60a | Mid-Continent Instrument Co., Inc. 7706 East Osie Wichita, KS 67207 | CE-W | | MD40-():2010056-02, 02L, 04, 04L, -05, -05L, -08, -08L, -09, -09L, -10, -10L, -13, -13L, -15, -15L, -16, -16L, -21, -21L |
| TSO-C60a | II Morrow, Inc. 2345 Turner Road S.E. Salem, OR 97302 | NM | | A-16 Loran C: 430-0035-00 A-23 Loran C: 430-0066-00 Apollo I - Model 602 Apollo II - Model 611 Apollo II - Model 612 A-17 Loran-C:430-0038-10 Loran C - Model 602 Loran C - Model 611 Loran C - Model 612 Loran C - Model 612B Loran C - Model 614P Loran C - Model 614R FC-01:430-0125-001 A 16 Loran C, A-17, A-23 (Antenna) A 17 Loran C: Models (Receivers) 602 611 612 612B 614P 614R 614R FC-01 Apollo I: Model 611 Apollo II: Models 611 612 612A 612B 612BC 612BV 614P 614R 612BCV Loran-C Preamplifier Model A-6 MD40-() Loran CDI 612A:430-0132-001 612B:430-0073-004 430-0073-005 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|--|
| | | | | Apollo II - Model Morrow A-17:430-0038-10 611:430-0055-02-21, -12-21, -21-23, -12-24, -03-22, -002, -004, -005 430-0073-002, -003, -004, -005 430-0123-002, -003, -004, -005 Apollo II - Model 611:430-0112-004 Apollo II - Model 611:430-0112-005 Apollo II - Model 611:430-0122-002 Apollo II - Model 611:430-0122-003 Apollo II - Model 611:430-0123-002 Apollo II - Model 611:430-0123-003 Apollo II - Model 6128C:430-0112-12-15 Apollo II - Model 6128C:430-0112-22-27 Apollo II - Model 6128C:430-0112-002 Apollo II - Model 6128C:430-0112-003 Apollo II - Model 6128C:430-0055-004 Apollo II - Model 6128C:430-0073-004 Apollo II - Model 6128C:430-0073-005 Apollo II - Model 6128C:430-0112-004 Apollo II - Model 6128C:430-0112-005 Apollo II - Model 6128C:430-0122-002 Apollo II - Model 6128C:430-0122-003 Apollo II - Model 6128C:430-0123-002 Apollo II - Model 6128C:430-0123-003 Apollo II - Model 6128CV:430-0055-005 Apollo II - Model 6128CV:430-0123-004 Apollo II - Model 6128CV:430-0123-005 Apollo II - Model 614P:430-0071-01-01 Apollo II - Model 614P:430-0071-00-A00 Apollo II - Model 614P:430-0071-01-02 Apollo II - Model 614P:430-0071-01-03 Apollo II - Model 614R:430-0043-30-30 Apollo II - Model 614R:430-0043-30-31 Apollo II - Model 614RCDU:430-0043-30-32 Apollo II - Model 614RRCU:430-0039-10-10 Apollo II - Model 614R:430-0043-001(RCU) Apollo II - Model 614R:430-0039-001(CDU) 612:430-0026-11-11, -21-21, 430-0073-21, -23 612:430-0026-21-24, -002-003, 612B:430-0073-21-21, -11-11, -23-23, -22-24, -12-12, -002, -003, -004, -005, -0123-002, -003, -0055-004, -0112-004, -0122-002 |
| TSO-C60a | Teledyne Systems Co. 19601 Nordhoff Street Northridge, CA 91324 | NM-L | | TDL-711A:8018980-XXX |
| TSO-C60a | Texas Instruments, Inc. P.O. Box 405 Lewisville, TX 75067 | SW | | TI-91 Loran C:2788176-1 TI-9100 Loran C:2780562-1 TI-9100A Loran C:2242016-() |
| TSO-C60a | Trivec-Avant Corp. 17351 Jamestown Lane Huntington Beach, CA 92647 | NM | | Loran C: 12-95-() |
| TSO-C60a | Universal Navigation Corp. 3545 W. Lomita Blvd. (Unit 8) Torrance, CA 90505 | NM-L | | Loran C:1040() |
| TSO-C60a | Universal Navigation Corp. 3260 East Lerdo Road Tucson, Arizona 85706 | NM-L | | Loran:1040 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|--|-------------------------------------|----------------------|
| TSO-C60b | Arnav Systems, Inc. 16100 S.W. 72nd Ave. P.O. Box 23939 Portland, OR 97223 | NM | AIRBORNE AREA NAV. EQ. USING LORAN C INPUTS | R-501:452-0183 452-0138 R-501:453-1050-00 453-1050-02 | 455-6029 452-0139 453-1050-01 | |
| TSO-C60b | Bendix/King General Aviation Avionics Div. 400 North Rogers Road Olathe, KS 66062-1212 | CE-W | | KLN 88:066-4026-00, -01, -02, -03 KA 83:071-1431-00 KA 84:071-1432-00 071-01469-0101 KA 85:071-01472-0000 KLN88 Loran C | | |
| TSO-C60b | Global Wulfsberg Systems 6400 Wilkinson Drive Prescott, AZ 86301 | NM-L | | GNS-X:14141-0202-(), Mod 6 GNS-X:121-014379-(), Mod N/C GNS-500A:10050-()-5M-() Mod N/C GNS-X:14141-0220-() Mod NC | | |
| TSO-C61 | ACR Electronics 160 Fifth Avenue New York, NY 10010 AND 112 Voice Road Carle Place, NY 11514 | NE | PORTABLE AIR- CRAFT EMERGENCY COMMUNICATIONS EQUIPMENT (FOR AIR CARRIER AIRCRAFT) | ACR/RLB-5 | ACR/RLB-6 | ACR/RT-60B |
| TSO-C61 | Burton Instrumentation, Inc. Box 822 Fort Collins, CO 80501 | NM | | "ADAM"ARB-3 | | |
| TSO-C61 *F | Garrett Canada 255 Atwell Dr. Rexdale, Ontario Canada | NE | | Masow/1 | Rescu/99 | |
| TSO-C61a | ACR Electronics 160 Fifth Avenue New York, NY 10010 AND 112 Voice Road Carle Place, NY 11514 | NE | PORTABLE AIR- CRAFT EMERGENCY COMMUNICATIONS EQUIPMENT (FOR AIR CARRIER AIRCRAFT) | ACR/RLB-2 | ACR/RLB-2A | |
| TSO-C61a *F | Burndep Electronics, Ltd. St. Fidelis Rd. Erith, Kent, England | EU | | BE.346 | | |
| TSO-C61a | Dorne & Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM ELT 1-2 | | |
| TSO-C61a | Emergency Beacon Corp. 13 River St. New Rochelle, NY 10801 | NE | | EBC-102 EBC-202B | EBC-102A EBC-302 | EBC-202A EBC-302V |
| TSO-C61a | Hycon Manufacturing Co. Monrovia, CA 91016 | NM | | 111407 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|-------------------|--|
| TSO-C61a | Leigh Systems, Inc. 6081 Court Street Road Syracuse, NY 13206 | NE | | Model 3 Model 7A Model 5 Model 5A |
| TSO-C61a | Mar-Tech, Inc. Marine Technology Div. 812 W. W. First St. Ft. Lauderdale, FL 33310 | CE-A | | EB-3A EB-1B EB-3B EB-28() |
| | TSO-C61 SUPERSEDED BY TSO-C91 "TSO authorization existing at the time of TSO cancellation remain in effect." | | | |
| TSO-C62 *F | Bridgestone Tire Co., Ltd. 2800-1, Ogawa, Higashi-cho Kodairo-shi Tokyo, Japan | NM-L | AIRCRAFT TIRES | Tire Size/Ply Rating/Test Speed 5.00-5/4/120 6.50-8/6/120 7.00-6/4/120 8.50-10/8/120 8.50-10/10/120 9.00-6/10/120 9.50-16/10/120 12.50-16/12/120 12.50-16/14/120 15.00-16/14/120 15.50-20/14/120 15.50-20/16/120 15.50-20/20/120 17.00-16/12/120 24x7.7/10/120 24x7.7/14/200R, 225 29x7.7/12/200R 17.00-16/12/120 32x11.50-15/12/200R, 210 34x11/20/200R 34x11/22/225R 36x11/20/225 39x13/16/200R 39x13/22/200R 40x14/22/200R, 225 40x14/24/200R, 225 44x16/28/200R 44x16/20/225R 44.5x16.5-18/30/225R 46x16/24/210 46x16/26/225R 46x16/28/200R, 210, 225R 46x16/30/225R 49x17/26/200R 49x17/28/200R 49x17/30/225, 225R 50x20-20/34/225 50x21-20/30/210 51x21-20/28/210 52x20.5-20/36/225 R denotes reinforced thread |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|----|-----------|---|
| TSO-C62 *F | Dunlop Australia, Ltd. G.P.O. Box 21961 Melbourne, Victoria 3001 Australia | NM | | Size/Ply Rating/Test Speed 42x15/20/200 42x15/22/200 46x16/28/200 |
| TSO-C62 *F | Firestone Hispania Bilbao, Spain | EU | | Tire Size/Ply Rating/Part Numbers 26x6.6/10/00001 32x11.50/12/00003 40x14/24/00002 |
| TSO-C62 | Firestone Tire & Rubber Co. CE-C 1200 Firestone Parkway Akron, OH 44317 | | | Tire Size/Ply Rating/Part Numbers 5.00-5/4 5.00-5/6/00296 6.00-6/4/00297 6.00-6/6/00298 6.50-8/4/00315 6.50-8/6/00266, 00306, 00308 6.50-10/6/00264, 00310 6.50-10/8/00308 7.00-6/6 7.00-6/8 7.50-14/8/00271 8.50-10/6/00320 8.50-10/8/00322, 00263 8.50-10/10/00287 9.00-6/10/00403, 00285 11.00-12/8 12.50-16/12/00284 12.50-16/14/00392, 00383, 00391 18x4.25-10/6/00368 18x4.4/10/00279, 00277, 00252 18x4.4/12/00330 18x5.5/8/00311, 00313, 00289 18x5.5/10/00316 19.00-23/16 23x7.7/14/00351 24x7.25-10/11 C24.5x8.5-12/10/00440, 00443, 00427A C24.5x8.5-12/16/00427A 24.5x8.5/10/00440 26x6.6/8/00325, 00374 26x6.6/10/00365 26x6.6/12/00390 26x6.6/14/00332, 00327, 00291 26x7.75-12/10/00265 26x7.75-13/10 29x7.7/12 32x11.50-15/12/00409, 00341, 00261 34x11/18/00379 34x11/20/00361 34x11/22/00426 36x11/22/00255TL 39x13/14/00359, 00169TL 39x13/16/00358A, 00358, 00304, 00302 39x13/20/00328, 00328A, 00369, 00419 39x14/16/00434 40x12/16/00276, 00276A 40x12/18/00343 40x14/18/00275 40x14/20/00335, 00303, 00372A, 00372 40x14/22/00314, 00381, 00337 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|--|
| | | | | 40x14/24/00371, 00389, 00418, 00425 00340, 00339, 00305, 00272, 00509 C40x14.0-21/22/00404, 00405, 00408, 00410 C40x14.0-21/24/00396, 00396A, 00399 C40x18.0-17/20/00453, 00442, 00449 44.5x16.5-18/30/00394 44x16/26/00350, 00350A 44x16/28/00250TL, 00377, 00262, 00345 44x16/30/00329, 00423, 00378 44x16/32/00331 46x16/24/00292, 00319, 00344, 00349, 00353, 00385 46x16/26/00257, 00324, 00428, 00386, 00333, 00354 46x16/28/00260, 00278, 00323, 00342, 00345, 00347, 00352, 00376, 00375, 00342A, 00352A, 00406, 00413 49x17/26/00259, 00336, 00400, 00362, 00360 49x17/28/00307, 00326, 00373, 00397, 00387, 00398, 00412 49x17/30/00414 50x20.0-20/26/00318 |
| TSO-C62 | General Tire & Rubber Co. P. O. Box 951 Akron, OH 44309 | CE-C | | Size/Ply Rating/Part Numbers 8.50-10/10 15.50-20/20 49x17/26 49x17/28 TSO authorization terminated 1971 |
| TSO-C62 | B. F. Goodrich Co. 500 S. Main St. Akron, OH 44318 | CE-C | | Size/Ply Rating/Part Numbers 5.00x5/10 5.50x4/6 6.00-6/6/061-317 6.50x8/4 6.50x8/6 6.50x10/4 7.00-6/8 7.00-8/4 7.00-16/4 7.50-14/8 7.50-14/12 8.00-4/4 8.00-6/6 8.50-6/6 8.50-10/6 8.50-10/8/021-344-1 9.00-6/8 12.50-16/10 12.50-16/14 15.00-16/16 15.00x6.00-6/16 15.50x20/14 15.50x20/16 17.00-16/12 17.00-20/20 17.00-20/22 17.00-20/24 18x4.4/6 18x4.4/12 18x4.25-10/6 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---------------------------------------|
| | | | | 22x6.75-10/8/021-523 |
| | | | | 24x7.25-12/12 |
| | | | | 24x7.7/10/021-674 |
| | | | | 24x7.7/14 |
| | | | | 24x7.7/16/039-677 |
| | | | | 26x6.6/8/038-656 |
| | | | | 26x6.6/12 |
| | | | | 26x6.6/14 |
| | | | | 28x7.7/8 |
| | | | | 19x7.7/12 |
| | | | | 34x11/18 |
| | | | | 34x11/20 |
| | | | | 34x11/22/038-735 |
| | | | | 34x12-12/021-540 |
| | | | | 34x14/22 |
| | | | | 36x11/20/039-741 |
| | | | | 40x12/16 |
| | | | | 40x12/22 |
| | | | | 40x14/18 |
| | | | | 40x14/22/038-768-3 |
| | | | | C40x14-21/22/082-773, 083-773 |
| | | | | 41x15.0-18/18 |
| | | | | 41x15.0-18/22/039-856 |
| | | | | 44x16/20 |
| | | | | 44x16/24 |
| | | | | 44x16/30/039-778 |
| | | | | 44x16/32 |
| | | | | 46x16/20 |
| | | | | 46x16/28/039-784, 039-784-2 |
| | | | | 46x16/30/038-785, 038-785-3 |
| | | | | 46x16/32 |
| | | | | 49x17/26 |
| | | | | 50x20/24 |
| TSO-C62 | B. F. Goodrich, GmbH | EU | | Size/Ply Rating/Part or Approval No. |
| *F | Koblenz | | | 26x6.6/10/30.262-19, 30.262-22 |
| | West Germany | | | 32x11.50-15/12/321150-12-200K1 |
| | | | | 35x9.00-17/16/30.262-21 |
| | | | | 39x13/16/3913-16-200K, 3913-16-210K1, |
| | | | | 30.262-23 |
| | | | | 40x14/22/4014-22-200K1, 4014-22-225K1 |
| | | | | 40x14/24/4014-24-200K1, 4014-24-225K1 |
| | | | | 41x15-18/22/4115018-22-225K1 |
| | | | | 41x15.0-18/24/4115018-24-225K1 |
| | | | | 44x16/28/4416-28-200K |
| | | | | 44x16/28/4416-28-225K2 |
| | | | | 44x16/30/30.262-15 |
| | | | | 44.5x16.5-18/30/30.262-17 |
| | | | | 46x16/28/4616-28-200K |
| | | | | 46x16/28/4616-28-210K1 |
| | | | | 46x16/28/30.262-16 |
| | | | | 46x16/30/30.262-18 |
| | | | | 49x17/28/4917-28-200K1 |
| | | | | 49x17/30/30.262-14 |
| | | | | 50x20-20/26/30.262-20 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|---|
| TSO-C62 | Goodyear Tire & Rubber Co. 1210 Massillon Rd. Akron, OH 44316 | CE-C | | Tire Size/Ply Rating/Part Numbers 5.00-5/4/A505C41-4 5.00-5/6/A505C61-4 6.00-6/4/606C41-6, A606C41-5 6.00-6/6/A606C61-1, A606C61-6 6.00-6/8/A606C81-4 6.50-8/4/658C41-2 6.50/8/6/658C61-4, 658C61-5 6.50-8/8/658C81-3 6.50-10/4 6.50-10/6/650C61-4, 650C61-5 6.50-10/8/650C81-3, 650C81-4 7.00-6/4/706C41-3 7.00-6/6/A706C61-4 7.00-6/8/A706C81-3 7.00-8/4/708C41-1 7.00-8/6/708C61-1 7.00-8/8 7.00-8/14 7.50-14/8 7.50-14/10 7.50-14/12/754C26-1 7.50-14/14 8.00-4/4/804C41-1 8.50-6/4/856C41-1 8.50-6/6/A856C61-1 8.50-10/8/850C81-3 8.50-10/10/850C01-2 9.00-6/8/906C8A-1 9.00-6/10 9.50-16/12/956C26-1 11.00-12/8/112C81-1, 112C81-2 11.00-12/10/112C01-1 12.50-16/12/126C26-1, 126C26-2 13x5.0-4/14/B135F48-2 14.5x5.5-6/12 14.5x5.5-6/14/145K48-1 15x6.00-6/4/156E41-1 15x6.00-6/6/156E61-3 15.00-12/10/A152C01-1 15.50-20/20 16x4.4/4 16x4.4/6/164F66-1 17.50x6.00-6/6/176C64-1 17.50x6.25/8/175K81-1 18x4.25-10/6/181R68-1 18x4.4/6/184F66-1 18x4.4/10/184F00-4, 185F10-1 18x4.4/12/184F20-1 18x5.5/8 18x5.5/10/185F00-2 18x5.75-8/8 22x5.75/8/226K88-2 22x5.75-12/10/226K08-1 22x7.75x10/8/277K81-1 22x8.0-10/10/220K08-1, 228K08-1 22x8.00-8/10/228K04-1 23x7.00-12/10/237R08-1 24x7.25-12/10 24x7.7/14/247F40-1, 247F42-1 24x7.7/16/247F60-2 26x6.6/8/266F80-1, 266F80-2 26x6.6/10/266F02-1, 266F02-2, 266F08-2 26x6.6/12/A266F26-1 26x6.6/14/266F40-1, 266F40-2, 266F40-3 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---------------------------------------|
| | | | | 28x7.7/10/287F08-1 |
| | | | | 29x7.7/16 |
| | | | | 29x7.7/12/297F20-1 |
| | | | | 32x11.50-15/12/321K20-1 |
| | | | | 34x9.25-16/14 |
| | | | | 34x9.25-16/16/348F60-1, |
| | | | | GAEC1159SC-L206-3 |
| | | | | 34x9.9/12/349F20-1 |
| | | | | 34x11/18 |
| | | | | 34x11/20 |
| | | | | 34x11/22/341F20-1 |
| | | | | 35x9.00-17/14 |
| | | | | 36x10/00-18/18 |
| | | | | 36x11/20 |
| | | | | 36x11/22/8361F24-1 |
| | | | | 37x14.0-14/24/374F42-1 |
| | | | | 39x13/14/393F40-1, 393F48-1 |
| | | | | 39x13/16/393F60-1 |
| | | | | 39x13/20/393F00-1 |
| | | | | 39x13/22/4618-1854-TL |
| | | | | 40x12/16 |
| | | | | 40x12/18/402F88-1 |
| | | | | 40x12/22 |
| | | | | 40x14/14 |
| | | | | 40x14/18 |
| | | | | 40x14/20/404F00-1, 404F02-1 |
| | | | | 40x14/22/404F20-1, 404F22-1 |
| | | | | 40x14/24/404F40-1, 404F42-1, 404F40-2 |
| | | | | 40x15.5-16/26 |
| | | | | 40x18.0-16/18/408K80-1 |
| | | | | 40x15.0-18/22/415K20-1 |
| | | | | 41x15.0-18/24 |
| | | | | 44.5x16.5-18/30/456F02-1 |
| | | | | 44x16/26/446F60-1 |
| | | | | 44x16/28/446F87-5, FSN26208105145 |
| | | | | 44x16/30/446F00-1, 446F02-1 |
| | | | | 44x16/32 |
| | | | | 46x16/20 |
| | | | | 46x16/24/466F40-1 |
| | | | | 46x16/26/466F60-1, 466F62-1 |
| | | | | 46x16/28/466F80-1, 466F83-1 |
| | | | | 46x16/30/466F00-1, 466F02-1, 466F03-1 |
| | | | | 49x17/26/497F60-1 |
| | | | | 49x17/28/497F80-1, 497F80-3 |
| | | | | 49x17/30/8497F02-1 |
| | | | | 50x18/26 |
| | | | | 50x20.0-20/24 |
| | | | | 50x20.0-20/26/500K60-1 |
| | | | | 50x20.0-20/32/500K22-1 |
| | | | | 52x20.5-23/26/520K69-1, 520K69-2 |
| | | | | 56x20.0-20/22 |
| | | | | 56x20.0-20/24/560G40-1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|----|-----------|--|
| TSO-C62 *F | Goodyear Tyre & Rubber Co. (Australia) Ltd. P. O. Box 21 Granville, N.S.W., Australia | NM | | Tire Size/Ply Rating/Speed 26x6.6/8/200 32x11.50-15/12/200R 39x13/16/200 40x14/14/200R 40x14/24/200R 40x16/28/210 42x15/20/200R 42x15/22/200R 46x16/24/200R 46x16/26/210R 46x16/28/200R 49x17/30/225R 50x20.0-20/24/200R 50x20.0-20/26/200R |
| TSO-C62 | McCreary Tire & Rubber Co. Indiana, PA 15701 | NE | | Tire Size/Ply Rating/Part Numbers 5.00-4/6/41B 5.00-5/4/2630A, 2630AT 5.00-5/6/305-01-501 5.00-5/8/2632A 5.00-5/10/2633A 6.00-6/4/2700C 6.00-6/6/2701A, 2701AT 6.00-6/8/2702A, 2702ATL 6.50-8/4/350-501 6.50-8/6/350-01-501, 350-01-001 6.50-10/6/31C, 3101AT, 3101D 6.50-10/8/310-02-001 6.50-10/10/310-03-001 7.00-6/4/2800A, 314-00-501 7.00-6/6/318-01-001, 318-01-001A, 318-02-001-A, 2801B, 314-01-501 7.00-6/8/314-02-501 7.00-8/4/360-00-501 7.00-8/6/360-01-501 7.50-10/6/3201AT, 3201C 8.00-4/4/260 8.00-6/4/3000A1 8.00-6/6/300-01-001 8.50-6/4/324-00-001 8.50-10/6/3301A, 330-01-501 8.50-10/10/3303A, 3303AT 9.00-6/10/520A, 4413B 11.00-12/8/301-02-501 12.50-14/12/560C 12.50-16/12/306-04-542 15x6.00-6/4/420-00-001. 420-00-501 15x6.00-6/6/420-01-501 15.00-16/10/3403C 15.50-20/14/3705D 15.50-20/20/3708C 16x6.00-8/16/425-01-001 17.5x6.25-6/8/415-02-401 18x5.5/10/765-02-903 24x7.25-12/10/740-03-953 26x6.6/10/760-03-914, 756-03-915 26x6.6/14/710-05-124 34x11/18/723-07-954 34x11/22/754-09-915 39x13/14/741-05-403 39x13/16/736-06-954 39x13/18/736-07-954 40x14/18 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|-----------|---|
| | | | | 40x14/20/744-08-954 40x14/22/724-09-954, 746-09-955 40x14/24/746-10-955, 724-10-954 44x16/20 44x16/26/722-11-954, 732-11-954 44x16/28/734-12-604, 732-12-954, 752-12-604, 758-12-604 44x16/30/745-13-915 46x16/24/737-12-954, 737-10-954, 742-10-954 46x16/26/742-11-954 46x16/28/737-12-954, 751-12-955, 742-12-954, 742-12-916, 751-12-915 49x17/26/738-11-954, 753-11-604 49x17/28/738-12-954 |
| TSO-C62 *F | Nippon Goodyear Kabushiki Kaisha 9-13, 1-Chome Akasaka Minato-kee Tokyo, Japan | NM-L | | Tire Size/Ply Rating/Speed 12.50-16/12/120 12.50-16/14/160 24x7.7/10/120 24x7.7/14/200 29x7.7/12/200 32x11.50/12/200 34x11/20/200 34x11/22/225 39x13/14/200 39x13/16/200 39x13/22/200 40x14/22/200 40x14/24/200 44x16/28/200 44x16/30/225 46x16/28/200, 225 46x16/30/225 49x17/26/200 49x17/28/200 49x17/30/225 |
| TSO-C62 | UniRoyal Tire Co. 6600 E. Jefferson Ave. Detroit, MI 48232 | CE-C | | Tire Size/Ply Rating, Part Numbers 5.00-4/4/5901-009 5.00-5/2 5.00-5/4/C-113-1 5.00-6/6 6.00-6/2/C-110, C-110TL 6.00-6/6/QTR C-108, C-108TL 6.50-10/8/C-231-1, C-5941-048, 5907-048, QTR-C-231-1 7.00-6/4 7.00-6/6 7.00-6/8 8.50-10/6/C-120 9.50-16/10/QTR C-149 10.00-23/16 10-1/2x4/8/QTR C-165 12-1/2x4-1/2/10/C-209 14.5x5.5-6/12/C-215TL 17.00-16/16 18x4.4/10/C-175TL 18x5/10/C-193TL 18x5.5/10/C-211TL, C-218TL 21x7.25-10/8/C-223TL 22.0x8.00-18/10/C-323TL 22x8.0-8/6/C-232 22x8.0-8/10/C-201TL |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-------------------|--|
| | | | | 24x7.7/14/QTR C-138TL 24x7.25-12/10/C-195TL 26x6.6/8/C-172TL-1, 5902-935 26x6.6/8/16/QTR C-204TL, C-205TL, C-206TL, C-207TL 26x6.6/12 26x7.25-12/10/C-48 32x11.50-15/12/6953-055 32x11.50-15/16 34x11/22/6996-907 36x11/20/6902-939 37x14.0-14/24/6902-860 39x13/14 40x12/16/T-105TL-1 40x12/18/C-105TL-1 40x12/22 40x14/20/C-117TL, 6903-903 40x14/22/C-118TL 40x14/24/C-119TL, C-64TL, C-239TL 44x16/28/C-101TL-1, C-238TL 44x16/30/6903-924 44x16/32/6902-997 44.5x16.5-18/30/C-185TL-1 46x16/24/6903-091 49x17/30/6903-972 |
| TSO-C62a *F | Firestone Tyre & Rubber Co. Great West Road Brentford, Middlesex England | EU | AIRCRAFT TIRES | TIRE SIZE/PLY RATING/PART NUMBERS 26x7.75-13/10/ZA237 35x9.00-17/16/ZA287 |
| TSO-C62a | Goodyear Tire & Rubber Co. 1210 Massilon Rd. Akron, OH 44316 | CE-C | | Tire Size/Ply Rating/Part Numbers 10.50-16/10 |
| TSO-C62a | UniRoyal Tire Company 6600 E. Jefferson Ave. Detroit, MI 48232 | CE-C | | Tire Size/Ply Rating/Part Numbers 9.50-16/12/611L |
| TSO-C62b | Armstrong Rubber Company 2345 E. Market St. Des Moines, IA 50306 | CE-W | AIRCRAFT TIRES | Tire Size/Ply Rating/ 5.00-5/4 5.00-5/6 6.00-6/4 6.00-6/6 6.50-8/6 6.50-10/6 7.00x6/6 7.00-6/8 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|---|
| TSO-C62b *F | Bridgestone Tire Co., Ltd. 2800-1, Ogawa Higashi-cho, Kodaira-shi Tokyo, Japan | NM-L | | Tire Size/Ply Rating/Speed 24x7.7/16/225 26x6.6/10/225 36x11/22/225 39x13/16/200, 225 40x14/28/225 40x15.5-16/26/235 41x15.0-18/22/225 49x17/28/210 49x17/30/210, 225 49x17/32/225 49x19/32/235 50x21-20/30/210 52x20.5-20/34/225 52x20.5-23/28/235 |
| TSO-C62b *F | Continental Gummi Werke AG Hannover Germany | EU | | TIRE SIZE/PLY RATING/SERIAL NUMBER 24x7.7/14/100,097,126 26x6.6/10/089,095 26x7.75-13/10/015 34x11/20/026 34x11/22/037 35x9.00-17/14/024 35x9.00-17/16/025 39x13/16/115 40x14/22/114 40x14/24/021 40x15.5-16/26/ 41x15.0-18/22/003 41x15.0-18/24/011 44x16/30/022 44x16/32/023 44.5x16.5-18/30/027 46x16/24/113 46x16/28/123 46x16/30/044 46x16/30/122 49x17/26/029 49x17/28/120 49x17/30/047 50x20.0-20/26/009 50x20-20/32/016 50x21.0-20/30/117 |
| TSO-C62b *F | Dunlop Australia, Limited Box 2196T, G.P.O. Melbourne, Victoria 3001 Australia | NM | | TIRE SIZE/PLY RATING/CODE 49X17/32/960401 |
| TSO-C62b *F | Dunlop, Ltd. Fort Dunlop, Erdington Birmingham, England | EU | | TIRE SIZE/PLY RATING/PART NUMBERS 6.00-6/6/DR.7720, DR.7720.T 6.50-8/8/DR17421 6.50-10/10/DR12326T 6.50-10/14/DR12327T 8.50-7/6/DR0650 8.50-10/6/DR.8625, DR.8625.T 8.50-10/8/DR.8624, DR.8624.T 8.50-10/10/DR.8626.T 9.00-6/10/DR.4620, DR.4620T 11x12/8/DR.10623 11.00-12/8/DR10623T 17.00-20/22/DR.1431T 18x4.25-10/6/DR6384T 20.00-20/22/DR15024 23x7.00-12/10/DR14625T, 14626T |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | | | | 24x7.25-12/10/DRR7153.T, DR7153.T/DR7155T |
| | | | | 24x7.7/10/DRR15825.T, DR15834T, DR16834T, 15820T |
| | | | | 24x7.7/12/DR.15835.T |
| | | | | 24x7.7/14/DRR15822T, DRR15823.T DRR15828T, DRR15829.T |
| | | | | 24x7.7/16/DRR15826T, DRR15832.T, DRR15833T |
| | | | | 26x6.6/10/DR.3628T, DRR3628T, DR3630T, DRR.3630.T |
| | | | | 26x6.6/12/DR3631T |
| | | | | 28x9.00-12/8/DR11328T, DR11324, DR11324T |
| | | | | 28x9.00-12/12/DR11323T |
| | | | | 30x9.00-15/12/DR4924T, DR44925T |
| | | | | 32x8.8/12/DR7667T, DR7670T |
| | | | | 32x10.75-14/12/DR10728T |
| | | | | 32x11.50-15/12/DRR17220.T, DR17220T |
| | | | | 33.5x10.75-15/12/DR22620T |
| | | | | 34x10.75/16/DR0223T |
| | | | | 34x11/20/DRR.11923T, DR11923T |
| | | | | 34x11/22/DRR.11922T, DR11922T |
| | | | | 36x11/20/DRR.9520T, DRR9521.T, DR9521T |
| | | | | 36x11/22/DR9524T |
| | | | | 36x13.00-12/6/DR18322, DR18322T |
| | | | | 37x11.75-16/10/DR19921T |
| | | | | 37x13.0-16/20/DR22520T |
| | | | | 37x13.0-16/26/DR22521T |
| | | | | 37x14-14/24/DR20521T |
| | | | | 39x13/14/DRR11723T |
| | | | | 39x13/16/DRR11726T, DR11733/T, DR11737T, DR11737/T |
| | | | | 39x13/22/DRR/ARR11724T |
| | | | | 40x12/16/DR7529T, DRR7529T, DR7542T, DR7541T, DR7550T, DR7551T |
| | | | | 40x12/18/DRR7530T, DR7530T, DRR.7536.T, DR7543T, DR7544, DRR7543T, DR7544T, DR7552T, DR7553T |
| | | | | 40x12/20/DRR7524T, DRR7531T, DR7545T, DR7554T, DR7555T |
| | | | | 40x12/22/DR7532T, DRR7540T, DR7546T |
| | | | | 40x14/14/DR12646T |
| | | | | 40x14/16/DR12643T |
| | | | | 40x14/22/DRR12622/T, DRR.12623/T |
| | | | | 40x14/24/DRR12624T, DRR12621T, DRR/ARR12626T, DRR12627.T DR12636T, DR12637T, DR12640T |
| | | | | 41x15.00-18/22/DR21321T, DR21322T, DR21325T, DR21324T, DR21326T |
| | | | | 40x15.5-16/26/DR21520T |
| | | | | 41x15.00-18/24/DR21320T |
| | | | | 44x16/26/DR118/23/T, 11646/T |
| | | | | 44x16/28/DRR1827T, DR11641T |
| | | | | 44x16/30/DRR11822T, DR11645/T |
| | | | | 44x16/32/DR11837T |
| | | | | 46x16/28/DR11625T, DR11633T, DR11641T, DR11643T, DR11643/T, DR11647T |
| | | | | 46x16/30/DR11642T |
| | | | | 49x17/28/DRR15321T, DR15338T |
| | | | | 49x17/32/DR15332/T |
| | | | | 50x20.00-20/24/DRR.17120T |
| | | | | 50x20.0-20/26/DR17124T |
| | | | | 50x20.0-20/30/DR17129/T |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|--|
| | | | | 50x20.0-20/32/DR17127T, 17123T, DR17130T 50x20.0-20/34/DR17131T 50x21.0-20/30/DRR21720T 52x20.5-20/34/DR22420T 52x20.5-23/26/DR21420T 52x20.5-23/28/DR21421T, DR21424T 52x20.5-23/30/DR21425T 56x20.0-20/24/DR22220T |
| TSO-C62b *F | Dunlop of France Tour Atlantic Cedex No. 6 92080 Paris La Defence | EU | | TIRE SIZE/PLY RATING/PART NUMBERS 14.5x5.5-6/14/V3150 26x6.6/10/V1229 26x6.6/14/V3229 40x14/22 40x14/24 40x14/28/V1299 46x16/28 46x16/30 49x17/30 49x17/32/V1427 |
| TSO-C62b *F | Firestone Hispania S. A. of Basauri Appartado 406 Bilbao, Spain | EU | | Tire Size/Ply Rating/Part Number 40x14/24/DR12636T, 12637T 40x15.5-16/26/RT00006 41x15.0-18/22/RT.00007 46x16/30/RT00008 50x21.0-20/28/00004 50x21.0-20/30/N-3 4037 52x20.5-23/28/R.T.00005 |
| TSO-C62b | Firestone Tire & Rubber Co. 1200 Firestone Parkway Akron, OH 44317 | CE-C | | Tire Size/Ply Rating/Part Numbers 5.00-5/6/00317 6.00-6/8/00357 6.50-8/6/00430 6.50-10/6/00402 7.50-14/10/00267 7.50-14/12/00269 8.00-4/4/00299 8.50-10/8/00321 9.50-16/12/00288 12.50-16/12/00401 13.50x16/24/00268 15.50-20/20/00346 17.5x5.75-8/12/00507 18x4.4/6/00375 18x4.25-10/6/00488, 00525 18x5.5/10/00420, 00490, 00518 21x7.25-10/8/00370 23x7.00-12/10/00367 23x7.7/14/00363 24x7.7/14/00363A, 00471, 00497, 00520 24x7.7/16/00436, 00495, 00499, 00519 24x7.25-12/10/00501 C24.5x8.5-12/10/00427A, 00491 C24.5x8.5-12/12/00479 C25x9.0-12/10/00427 26x6/10/00529 26x6.6/8/00280, 00384, 00356, 00384A |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | 26x6.6/10/00380, 00380A, 00474, 00493, 00523 |
| | | | | 26x6.6/14/00473 |
| | | | | 28x7.7/10/00270 |
| | | | | 32x11.10-15/12/00411, 00446, 00447 |
| | | | | 32x11.50-14/12/00513 |
| | | | | 34x9.9/12/00348, 00522 |
| | | | | 34x9.25-16/16/00395 |
| | | | | 34x11/18/00429 |
| | | | | 34x11/22/00441, 00526 |
| | | | | 35x9.00-17/16/00273 |
| | | | | 36x11/20/00452, 00528 |
| | | | | 36x11/22/00515 |
| | | | | 37x14.0-14/24/00454, 00511 |
| | | | | 39x13/14/00433, 00433A |
| | | | | 39x13/16/00434 |
| | | | | 39x13/20/00428 |
| | | | | 40x12/18/00382, 00382A, 00382B, 00487 |
| | | | | 40x14/ /00480 |
| | | | | 40x14/22/00355A, 00355(), 00464, 00504, 00508, 00514 |
| | | | | 40x14/24/00451, 00462, 00465, 00505, 00509 |
| | | | | C40x14.0-21/22/00457, 00463 |
| | | | | C40x14.0-21/24/00421, 00399A, 00466, 00467 |
| | | | | C40x14.0-21/26/00496, 00467, 00530, 00532 |
| | | | | C40x18.0-17/20/00437, 00445, 00453, 00472, 00485, 00489, 00521, 00531 |
| | | | | C40x18.0-17/22/00524 |
| | | | | 41x15.0-18/22/00338, 00492, 00510 |
| | | | | 44.5x16.5-18/00407 |
| | | | | 44x16/30/00422, 00478 |
| | | | | 44.5x16.5-18/30/00481, 00500 |
| | | | | 46x16/24/00353A, 00486 |
| | | | | 46x16/26/00494 |
| | | | | 46x16/28/00469, 00470, 00484, 00527 |
| | | | | 46x16/30/00416, 00432, 00461, 00476 |
| | | | | 49x17/28/00438, 00435, 00439, 00444, 00455, 00455A, 00506 |
| | | | | 49x17/30/00415, 00456, 00459, 00459A, 00477, 00475, 00503 |
| | | | | 49x17/32/00498 |
| | | | | 50x20.0-20/32/00424, 00448, 00458, 00460, 00483, 00502 |
| | | | | 50x21.0-20/30/00468 |

ISO-C62b Firestone Tyre & Rubber Co. EU
 *F Great West Road
 Brentford, Middlesex
 England

Tire Size/Ply Rating/Part Numbers
 6.00-6/4/ZA365, ZA367
 6.00-6/6/ZA363
 6.00-6/8/ZA593, ZA617
 6.50-10/8/ZA567
 7.00-6/8/ZA565, ZA649
 26x6.6/10/ZA453, ZA569
 26x7.75-13/10/ZA219, ZA237
 28x9.00-12/10/ZA627
 32x8.8/12/ZA141
 34x10.75-16/10/ZA625
 34x11/22/ZA487
 35x9.00-17/14/ZA259, ZA261
 35x9.00-17/16/ZA287
 36x11/22/ZA585

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|--|
| | | | | 39x13/16/ZA233, ZA359, ZA417, ZA539, ZA555 40x12/20/ZA603 40x14/20/ZA513 40x14/22/ZA475, ZA543 40x14/24/ZA377, ZA455, ZA635, ZA637 41x15-18/22/ZA621 44x16/28/ZA313 44x16/30/ZA519 44.5x16.5-18/30/ZA523 46x16/24/ZA231 46x16/26/ZA229, ZA381, ZA413, ZA537 46x16/28/ZA393, ZA441, ZA535, ZA547, ZA589 46x16/30/ZA583, ZA618 48x16/28/ZA589 49x17/28/ZA575 49x17/30/ZA553 49x17/32/ZA595 50x20.0-20/32/ZA587 52x20.5-20/34/ZA647 52x20.5-20/36/ZA671 |
| TSO-C62b | General Tire & Rubber Co. P. O. Box 951 Akron, OH 44309 | CE-C | | Tire Size/Ply Rating/Part Numbers 6.00-6/6 7.00-6/6 8.50-10/8 9.50-16/10/N7137, N7138 9.50-16/12 12.50-16/12 15.50-20/14 17.00-20/20 46x16/28/N7801 49x17/28/N7783 TSO authorization terminated March 1971 |
| TSO-C62b | B. F. Goodrich Company 500 S. Main St. Akron, OH 44318 | CE-C | | Tire Size/Ply Rating/Part Numbers 5.00x4/4/021-308 5.00x4/6 5.00x5/4/021-308, 061-308 5.00x5/6/021-309, 061-309 6.00-6/4/021-315, 061-315 6.00-6/6/061-316, 021-316 6.00-6/8/061-317, 021-317 6.50-8/6/021-337, 061-337 6.50x8/8/061-338 6.50x10/6/021-344, 021-061 6.50x10/8/061-345 6.50x10/10/061-356, 021-356 6.50-10/12/021-357 7.00-6/4 7.00-6/6 7.00-8/6 7.00-8/16/001-339 7.50x10/6 7.50-14/8/021-360 7.50-14/10 7.50-14/12/028-362-1 8.00-4/6 8.00-6/4 8.00x6/6/061-323 8.50-6/4 8.50-10/8/021-349-1, 061-349, 021-349 8.50-10/10/021-350, 061-350 8.50-10/12/004-351 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | 8.90-12.50/6/021-436 |
| | | | | 9.00-6/10 |
| | | | | 9.50-16/10 |
| | | | | 9.50-16/12/021-366, 028-366 |
| | | | | 10.00-7/12 |
| | | | | 11.00-12/8 |
| | | | | 12.50-16/12/028-369 |
| | | | | 13.50-16/24 |
| | | | | 14.5x5-6/14/031-629 |
| | | | | 14.5x5.5-6/14/031-629-1 |
| | | | | 15.00-10/10 |
| | | | | 15.00-16/10 |
| | | | | 15.00-16/14 |
| | | | | 15.00x6.00-6/4 |
| | | | | 15.50x20/20 |
| | | | | 16x4/4/038-604 |
| | | | | 16x4.4/6/061-605, 164F66 |
| | | | | 17.00-16/10 |
| | | | | 17.00-20/16 |
| | | | | 17.5x5.75-8/12/038-627 |
| | | | | 17.5x6.25-6/10/061-326 |
| | | | | 18x4.4/6/021-611 |
| | | | | 18x4.4/8/031-612 |
| | | | | 18x4.4/10/031-613-2, -3 |
| | | | | 18x4.4/12/031-614 |
| | | | | 18x4.25-10/6/031-595, 033-595 |
| | | | | 18x5.5/8/028-630 |
| | | | | 18x5.5/10/038-631, 038-631-1, 038-631-2, 033-631 |
| | | | | 18x5.75-8/8/186K88-2 |
| | | | | 19.00-23/16 |
| | | | | 19.5x6.75-8/10/061-335, 021-335 |
| | | | | 21x7.25-10/8/031-507-1 |
| | | | | 22x5.75-12/8/028-519 |
| | | | | 22x5.75-12/10/038-520 |
| | | | | 22x7.75-10/8/021-526, 8TL-1601 |
| | | | | 22x7.75-10/10/021-527, 021-527-1 |
| | | | | 22x8.0-10/10/028-699 |
| | | | | 23x7.00-12/10/028-505, 030-505, 033-505, 038-505 |
| | | | | 24x7.25-12/10 |
| | | | | 24x7.7/10/10TL-1801A |
| | | | | 24x7.7/12/038-673 |
| | | | | 24x7.7/16/038-677, 033-677, 039-677 |
| | | | | 24x7.7/18/021-682 |
| | | | | 26x6.6/10/038-657, 038-657-1, 038-657-2, 039-657-1, -2, -3 |
| | | | | 26x6.6/12/038-658, 033-658 |
| | | | | 26x6.6/14/038-659-1, 033-659 |
| | | | | 26x6.75-10/8/021-523 |
| | | | | 26x6.75-14/14/038-671, 038-671-1, -3, -8, -38-671-2 |
| | | | | 26x6.75-14/16/265K68-1, 038-672 |
| | | | | 26x7.75-13/10 |
| | | | | 28x7.7/10 |
| | | | | 29x7.7/16 |
| | | | | 29x11.00-10/10/001-446-1, 021-446-1 |
| | | | | 30x11.0-14/4/070-829 |
| | | | | 32x8.8/12 |
| | | | | 32x11.50-15/12/031-837, 035-837, 035-837-1 |
| | | | | 34x9.9/12 |
| | | | | 34x9.25/16/038-831 |
| | | | | 34x9.25-16/16/038-831, 033-831 |
| | | | | 34x11/22/039-735, 038-735, 033-735 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | 34x12-12/14/028-541 |
| | | | | 35x9.00-17/16 |
| | | | | 36x10.75-16/1-2-16 |
| | | | | 36x11/22/001-742, 039-742 |
| | | | | 37x13/16/039-755 |
| | | | | 37x13-16/20/032-749 |
| | | | | 37x13-16/26/039-763, 039-763-1 |
| | | | | 37x13-16/30/033-749 |
| | | | | 37x14-14/24/039-749, 039-747-1 |
| | | | | 39x13/14/028-754 |
| | | | | 39x13/16/038-755, 039-755, 038-755-1 |
| | | | | 39x13/20/038-757(TRT-2101) |
| | | | | 39x13/22/038-758, 039-768, 039-768-2, 039-758, 039-758-2 |
| | | | | 40x12/18 |
| | | | | 40x14/20/039-767, 039-767-1, 033-767 |
| | | | | 40x14/22/039-768 |
| | | | | 40x14/24/032769, 032769-1, 033-769, 038-769, 039-769, 039-769-1 |
| | | | | 40x14/26/033-770, 033-770-1 |
| | | | | 40x14/28/033-771 |
| | | | | 40x15.5-16/26/020-844 |
| | | | | C40x14-21/22/082-773 |
| | | | | C40x14-21/24/083-774, 083-774-1 |
| | | | | H40x14.5-19/22/033-775 |
| | | | | 40x14.5-19/24/033-781 |
| | | | | 41x15.0-18/22/039-856, 039-856-1 |
| | | | | 41x15.0-18/24/039-857 |
| | | | | 41x15-18/22/039-856-1 |
| | | | | 42x17.0-16/22 |
| | | | | 44x16/26/038-776 |
| | | | | 44x16/28/008-777, 038-777, 039-777 |
| | | | | 44x16/30/038-778, 033-778, 033-778-1, -2, 033-785 |
| | | | | 44x16/32/032-779 |
| | | | | 44.5x16.5-18/30/039-865, 039-865-3, 039-865-1, 039-865-2, 032-865 |
| | | | | H45x17.0-20/26/032-862 |
| | | | | 46x16/24/038-702, 038-782, 033-782 |
| | | | | 46x16/26/039-778, 039-783-1, 039-789-2, 039-783-2 |
| | | | | 46x16/28/033-784, 039-784, 033-784-1, 032-784, 032-784-1, 033-784-2 |
| | | | | 46x16/30/039-785, 039-785-2, 033-785, 038-785-3, 032-785, 033-785-1, 033-785-2 |
| | | | | 49x17/28/038-788-1, 038-788-2, 038-788-3 038-788-4, 038-788-8, 033-788 |
| | | | | 49x17/30/039-789-1, 039-789-2, 039-789 038-789, 038-789-1, 033-789 032-789, 032-789-1, -2 |
| | | | | 49x17-30/30/039-789-2 |
| | | | | 49x17/32/032-791 |
| | | | | 50x20-20/26/038-872 |
| | | | | 50x20-20/30/038-874, 038-874-1, 038-874-2, 033-874 |
| | | | | 50x20-20/32/039-875, 039-875-1 |
| | | | | 50x20-20/34/039-876, 039-876-1 |
| | | | | 50x21-20/28/038-878 |
| | | | | 50x21-20/30/038-877, 038-877-1, 039-877 |
| | | | | 52x20.5-20/34/020-883, 039-883-1 |
| | | | | 52x20.5-20/36/039-890 |
| | | | | 52x20.5-23/26/020-879, 020-884 |
| | | | | 52x20.5-23/28/020-882 |
| | | | | 56x20.0/24 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|--|
| TSO-C62b *F | B. F. Goodrich GmbH Koblenz, West Germany | EU | | Tire Size/Ply Rating/Part Numbers 49x17/28/30.262/24 50x21-20/28/30.262/25 |
| TSO-C62b | Goodyear Tire & Rubber Co. 1210 Massillon Road Akron, OH 44316 | CE-C | | Tire Size/Ply Rating/Part Numbers 5.00-4/6/504C61-1, 504C61-2 5.00-4/8 5.00-4/10/504T01-1 5.00-4/12/504T21-1 5.00-5/4/505C41-4, 505C46-1, -2 5.00-5/6/505C61-4, 505C61-5, 505C61-6, 505C66-1, -2, -3 5.00-5/10/505C01-1, 505C06-1 6.00-6/4/A606C41-4, 606C41-7, A606C41-9, 606C41-8, 606C41-6, 606C41-9, 606C41A, 606C41B, 606C41C, 606C46-2, -3, -4 6.00-6/6/606C61-6, 606C61-7, 606C61-8, 606C66-1, 606C66-2, -3, -4, -5 6.00-6/8/606C81-5, 606C81-4, 606C861, 606C862 6.50-8/4/658C41-2 6.50-8/6/658T61-1, 658C61-4, 658C66-1, 658T66-1 6.50-8/8/658C81-4, 658T81-1, 658C81-3, 658C86-1, 658T86-1 6.50-10/6/650C61-4, 650T61-1, 650C66-1, 650T66-1 6.50-10/8/650C81-3, 650C86-1 6.50-10/10/650C0-1, 650C06-1, 650T06-1 7.00-6/4 7.00-6/6/706C61-4, 706C66-1 7.00-6/8/706C81-3, 706C86-1 7.00-8/4 7.00-8/6/708C61-2, 708C66-3 7.00-8/16/708G6C-4 7.50-10/16 7.50-14/12 8.00-4/4/804041-1 8.00-6/6/ 806C61-1, 806C61-2, 806C61-3 8.50-6/4/856C41-1 8.50-6/6/856C61-1, 856C61-2 8.50-10/8/850C81-3, 850C81-4, 850C86-1, 850T86-1 8.50-10/10/850C01-2, 850T06-1 8.90-12.50/6/892T61-1 9.00-6/8 9.50-16/10 9.50-16/12 11.00-12/8/112C81-3, 112C86-4, 112T86-5, -6 11.00-12/10/112001-1, 112T06-2 12.50-16/12 13x5.0/14/B135F48-2 13x5.04/14/135F48-2 13.50-16/24 14.5x5.5-6/10/145K01-1 14.5x5.5-6/12/145K21-1 14.5x5.5-6/14/145K43-1, 145K43-2 15x6.00-6/4/156E41-1 15x6.00-6/6/156E61-3 15.00-12/10/152T06-1 15.00-12/14/152T46-1 15.50-20/16 16x4.4/4/164F40-1, 164F43-1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | | | | 16x4.4/6/164F66-2 |
| | | | | 17.50x6.00-6/6 |
| | | | | 17.50x6.25/8 |
| | | | | 17.5x5.75-8/12/178K23-1, 178K23-2 |
| | | | | 18x4.25-10/6/B181R63-1, 181R63-1, 181K63-1 |
| | | | | 18x4.4/6/184F66-1 |
| | | | | 18x4.4/10/184F00-4, 184F10-1, 184F03-1, |
| | | | | 184F13-1, 184F13-3 |
| | | | | 18x4.4/12/184F20-3, 184F23-1 |
| | | | | 18x5.5/8/185F88-1, 185F88-2, 185F88-3 |
| | | | | 18x5.5/10/185F00-2, 185F03-1, 185F08-1, |
| | | | | 185F03-2 |
| | | | | 18x5.75-8/8/186K88-2, 186K88-3, 186K88-4 |
| | | | | 19.00-23/16 |
| | | | | 19.5x6.75-8/10/196K08-1, 196K08-2 |
| | | | | 21x7.25-10/8/217F80-1, 217F83-1, |
| | | | | 217F83-2 |
| | | | | 21x7.25-10/10/217F01-3, 217F03-1 |
| | | | | 22x5.75/8 |
| | | | | 22x5.75-12/8/226K88-2, 226K88-3 |
| | | | | 22x5.75-12/10/226K03-1 |
| | | | | 22x5.75-12/12/226K23-1 |
| | | | | 22x6.75-10/8/265F86-1, 265F86-2, 265F86-3 |
| | | | | 22x7.75-10/8/277K81-1, 277K81-2, 277K86-1 |
| | | | | 22x7.75-10/10/277K06-1 |
| | | | | 22x8.0-10/10/220K08-1 |
| | | | | 22x8.00-8/10/A228K04-1 |
| | | | | 22x8.00-10/10/220K08-1A, 220K08-2 |
| | | | | 23x7.00-12/10/237K03-1 |
| | | | | 24x7.7/14/247F40-1, 247F42-1 |
| | | | | 24x7.7/16/247F60-2, 247F63-1 |
| | | | | 24x7.25-12/10/247R00-3 |
| | | | | B24x9.5-10.5/18/249K83-1, 249K83-2 |
| | | | | 26x6.6/10/266F03-1, 226K08-3, 226F08-3 |
| | | | | 26x6.6/12/266F22-1, 266F22-2 |
| | | | | 26x6.6/14/266F40-4, 266F43-1 |
| | | | | 26x6.75-14/14/265K48-1, 265K48-2 |
| | | | | 26x7.75-13/10 |
| | | | | 26x10.5-6/6/260K611 |
| | | | | 28x7.7/10 |
| | | | | 29x7.7/12 |
| | | | | 29x11.00-10/8/110T81-1 |
| | | | | 29x11.00-10/10/110T01-1 |
| | | | | 32x8.8/12 |
| | | | | 32x10/75-14/12 |
| | | | | 32x11.50-15/12/321K20-2, 321K23-1, |
| | | | | 321K23-2, 321K23-3 |
| | | | | 34x9.25-16/16/348F60-2, 348F63-1, |
| | | | | 348F63-2 |
| | | | | 34x9.25-16/18/348F83-1 |
| | | | | 34x9.50-18/14 |
| | | | | 34x9.9/12 |
| | | | | 34x11/22/341F22-1 |
| | | | | 35x9.00-17/16 |
| | | | | 36x10.00-18/16 |
| | | | | 36x10.75-16-1/2 /16 |
| | | | | 36x11/20/361F100-1, 361F02-1 |
| | | | | 36x11/22/361F22-1 |
| | | | | 37x13.0-16/20/373K03E1 |
| | | | | 37x13.0-16/26/373K62-1 |
| | | | | 37x14.0-14/24/374F42-2, 374F42-3 |
| | | | | 39x13/16/393F62-2, 393F62G4, 393F63-1 |
| | | | | 39x13/20/393F62-1 |
| | | | | 40x12/18/402F88-3 |
| | | | | 40x14/20/404F03-1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|---|
| | | | | 40x14/22/404F22-2, 404F23-1 40x14/24/404F40-3, 404F43-1, 404F42-3 404F42-4, 404F43-2, 404F43-3, 404F43-4, 404F42-5 40x15.5-16/26/405K69-1, 405K69-2 40x15.50-16/28/405K89-1 40x18.0-16/18/408K80-1 41x15.0-18/22/415K22-1 41x15.0-18/24/415K42-2 42x15/20 44x16/30/446F02-3, 446F03-1 44.5x16.5-18/30/456F02-2 H44.5x16.5-20/24/446K42-1 H44.5x16.5-20/26/446K62-1 45x15.75-21/26 46x16/24/466F43-1 46x16/26/466F62-2 46x16/28/466F82-3, 466F82-4, -5, 466F875, 466F83-3A, -B, -C, -D, -E, 446F83-4 46x16/30/466F03-2, 466F03-03, 466F02-3 49x17/28/497F83-3, 497F83-2, 497F83-4 497F83-5, 497F83-6, 497F83-7 49x17/30/497F02-01, 497F03-2, 497F02-2, 497F03-1, 497F02-3, 497F03-3, 497F02-4, 497F02-3, 497F03-4 49x17/32/497F22G1, 497F22G4 49x19.0-20/32/491K29-1 50x18/24 50x20.0-20/26/500K63-1 50x20.0-20/32/500K22-2, 500K22-3, 500K22-4 50x20.0-20/34/500K42-1 50x21.0-20/30/501K03-1 52x20.5-20/36/521K62-1, 521K622 52x20.5-23/26/520K69-3, 520K69-2 52x20.5-23/28/520K89-1 52x20.5-23/30/520K09-1 56x20.0-20/24/560F40-1, 560F40-2 |
| TSO-C62b *F | Companhia Goodyear do Brasil S/A Rua dos Prazeres No. 284 Sao Paulo, SP Brazil | CE-A | | Tire size/Ply rating/Otr. No. 27"/10 30.00"/10 44"/14 5.00-5/6 6.00-6/04/06/461B-2724 6.00-6/04/08/461B-2725 6.00-6/8 6.50-8/04/06/461B-2695 6.50-8/04/08/461B-2694, 461B-2494TL 6.50-8/6/461B-2620 6.50-10/8 7.00-6/8 7.06-6/04/06/461B-2715 7.00-6/04/08/461B-2716 8.00-4/4 8.50-10/8 8.50-10/10 8.90-12.50/6/461B-2599TL 9.00-6/10 9.50-16/12 10.00-7/10/12/461B-2693 11.00-12/06/08/461B-2714 12.50-16/12 |

TSO NO. HOLDER NAME & ADDRESS RG TSO TITLE MODELS OR PART NUMBERS
 =====

15.00-12/14/152T46B1
 15.50-20/12/14/461B-2763
 15.50-20/16/461B2731
 17.00-16/12
 18x5.5/10/461B-2697-TL
 23x7.25-10/6
 24x7.25-12/10/461B-2614TL, 461B-1329
 24x7.7/10
 24x7.7/14
 24x7.7/16/461B-2584TL
 26x6.6/14/461B-2797-TL
 26x7.75-13/10/461B-1528TT
 28x7.50-14/10
 32x10.75-14/12
 32x11.50-15/12/46B-2628TL
 34x11.75-14/12
 35x9.00-17/16
 36x10.75-16 1/2/16
 39x13/16/393F63B1
 40x12/20/402F00B2
 40x14/24
 40x14/14/24/461B-2730TL
 40x15.5-16/26/461B-2847-TL
 44x16/30
 46x16/28
 47x12/12/461B-2757
 49x17/28
 49x17/30/461B-2618TL, 497F02B1,
 461B-2848-TL
 50x20.0-20/26
 52x20.5-23/18/461B-2818TL
 52x20.5-23/28
 56x16/20/461B-2717
 56x20.0-20/24-/APF6-079H1
 670x210-12/04/10/461B-2691TL (metric)
 670x210-12/10 (metric)

ISO-C62b Goodyear Tyre & Rubber Co. EU
 *F (Great Britain) Ltd.
 Wolverhampton, England

Tire Size/Ply Rating/Part Number
 8.50-10/8/850T84E1
 9.00-6/8/906T81E1
 36x11/22/361F22E1
 36x10.00-18/16/368R60E5
 37x13.0-16/26/373K62E1
 52x20.5-20/34/521K42E1

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---------------------------|----|-----------|---|
| TSO-C62b | Goodyear S. A. | EU | | Tire Size/PR/P/N and/or Dwg. No. |
| *F | Colmar-Berg | | | For wheel sizes |
| | Grand Duchy of Luxembourg | | | 5.00-5/4/505C41G1 |
| | | | | 5.00-5/6/505C61G1 |
| | | | | 6.00-6/4/606C41G1 |
| | | | | 6.00-6/6/606C61G1 |
| | | | | 6.00-6/8/606C81G1, 606T81G1 |
| | | | | 6.50-8/6/658C61G1, 658C61G2 |
| | | | | 6.50-8/8/658C81G, 658T81G1 |
| | | | | 6.50-10/6/650C61G1, 650C61G2 |
| | | | | 6.50-10/8/650C81G1, 650C81G2 |
| | | | | 6.50-10/10/650T01G1 |
| | | | | 7.00-6/6/706C61G1, 706C61G2 |
| | | | | 7.00-6/8/706C81G1, 706C81G2 |
| | | | | 7.50-14/8/LT.628, 754C86G2 |
| | | | | 7.50-14/10/, LT629 |
| | | | | 7.50-14/12/754C26G1 |
| | | | | 8.00-4/4/804C41G1 |
| | | | | 8.50-10/6/LT713, 850C61G3, 850T61G1 |
| | | | | 8.50-10/8/LT714, 850C81G4, 850T81G1 |
| | | | | 8.50-10/10/LT715, 850T01G1 |
| | | | | 9.25-12/8/LT517, 922T81G1, 922T86G1 |
| | | | | 9.25-12/28x9.00-12/8/982T86G1 |
| | | | | 10.50-16/10/LT518, 106T06G1 |
| | | | | 10.50-16/12/LT-632 |
| | | | | 10.50-16/34x10.75-16/10/146T06G1 |
| | | | | 12.50-16/12/LT-650, LT685, 126C26G7, |
| | | | | 126C26G1, 126T46G4 |
| | | | | 12.50-16/14/, 126C41G1, LT687 |
| | | | | 13.50-16/24/, LT-627 |
| | | | | 15.00-16/10/LT-635 |
| | | | | 15.00-16/14/LT-635, 156T46G1 |
| | | | | 15.00-16/16/156C66G1 |
| | | | | 15x6.00-5/16/385M61G1 |
| | | | | 17.5x6.25-6/8/175K88G1, 175K88G2, 175K81G1 |
| | | | | 18x5.5/8/185F88G1 |
| | | | | 18x5.5/10/185F03G1 |
| | | | | 22x5.75-12/8/226K88G2, LT677, 266K88G3 |
| | | | | 22x5.75-12/10/226K08G1, 226K08G3 |
| | | | | 24.5x8.5/10/LT-633, LT-658, 248F03G1 |
| | | | | 24x7.7/8/247P81G1 |
| | | | | 24x7.7/10/LT-644, 247F03G1 |
| | | | | 24x7.7/14/LT-664, 247F43G1 |
| | | | | 24x7.7/16/461B-2092-TL, 247F63G1, LT684 |
| | | | | 25.5x8.75-10/12/259K26G1, |
| | | | | 259K28G1, 259K28G2 |
| | | | | 26x6.6/10/LT-651, LT-622, 266F08G2, |
| | | | | 266F02G3, 266F02G4, 266F02G5, |
| | | | | 266F02G6 |
| | | | | 26x6.6/14/266F43G2 |
| | | | | 26x7.75-13/10/LT-625, LT-626, 267R08G2, |
| | | | | 267R00G2 |
| | | | | 29x7.7/16/297F62G2, LT602 |
| | | | | 32x8.8/16/328Q08G1 |
| | | | | 32x11.50-15/12/321K23G1, LT581 |
| | | | | 32x13/16/393F62G3 |
| | | | | 34x11/20/LT571 |
| | | | | 34x11/22/LT-636, LT571, 341F22G2, 341F22G3, |
| | | | | 341F20G2 |
| | | | | 35x9.00-17/14/LT-703, LT-675, LT-704, |
| | | | | LT614, LT585, 359R40G3, |
| | | | | 359R48G4, 359R48G5, 359R40G4 |
| | | | | 35x9.00-17/16/LT-704, LT-675, LT-690, |
| | | | | LT-669, LT-541, 359R68G3, |
| | | | | 359R68G4, 359R60G6, |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | 359R60G4, 359R60G5 35x9.00-17/18/, LT689, 359R80G2 37x11.75-16/10/371K08G1 39x13/14/393F40G3, 393F40G4, LT670, LT538, LT587 39x13/16/393F60G3, LT-671, 393F69G1, LT534, LT586, 393F63G2, 393F62G2, 393F62G3, 393F62G4 40x14/12/LT-634 40x14/14/LT-652, 404F33G1, LT716, 404F33G2, 404F33G3 40x14/16/404F63G1, 404F63G2, 404F63G3, 404F63G4 40x14/20/, 404F03G1, LT542, LT543, 404F02G4, 404F03G2, 404F03G3, 404F02G5, 404F03G4 40x14/22/, LT659, 404F22G3, LT603, 404F23G1, 404F23G2, 404F29G1, 404F23G3, 404F22G4, 404F22G5, 404F22G6, 404F29G2 40x14/24/, 404F42G1, 404F43G1, LT604, LT532, LT717, 404F43G2, 404F42G2, 404F42G4, 404F43G4 40x14/28/404F82G1 40x15.50-16/26/405K69G1, 405K69G2 41x15.0-18/22/LT-561, LT681, 415K22G3, 415K22G2, 415K22G4, 415K22G5, 415K22G6 41x15.0-18/24/, LT605, 415K42G3, LT630, LT682, 415K42G4, 415K42G5 44x16/28/LT-668, 446F82G2, 446F83G1, 446F82G3, LT514, LT537, LT606 44x16/30/LT-589-1, 446F02G2, 466F02G5 44x16/32/446F22G2, LT616 44.5x16.5-18/30/LT-643/456F02G2 46x16/24/466F43G1 46x16/26/466F63G2, LT572, LT588, LT696, 466F62G4 46x16/28/, LT615, LT667, LT563, LT570, 466F83G3, 466F82G6, 466F89G1, 466F83G4, 466F83G5, 466F82G7, 466F89G2, 466F89G3, 466F82G9, 466F82GA 46x16/30/466F02G3, 466F03G1, 466F02G4, LT693, 466F02G7, 466F02G8 47x15.75-22/26/472K67G1 49x17/26/LT599 49x17/28/497F83G1, LT613, 497F82G3 49x17/30/497F03G1, 497F02G3, 497F02G6, 497F02G4, LT678, 497F03G3, 497F02G8 49x17/32/497F22G1, 497F22G4, 497F22G3 49x19.0-20/32/491K29G1 50x20.0-20/26/LT580 50x21.0-20/28/LT724, 501K83G2 50x21.0-20/30/501K03G1, 501K03G2, 501K03G3 52x20.5-23/26/520K69G2, 520K69G3, 520K63G1, 520K69G4 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|-----------------------|----|-----------|---|
| | | | | 52x20.5-23/28/520K89G1, 520K89G2 |
| TSO-C62b | Kleber | EU | | Tire Size/PR/Speed/Tire Report No. |
| *F | Division Aerospatiale | | | 9.00-6/10/NO-5706 |
| | P. O. Box 9-16 | | | 11.00-12/8/160/M3-5517 |
| | 6, Avenue Kleber | | | 12.50-16/10 |
| | 75784 Paris, France | | | 12.50-16/12/N1-4823 |
| | | | | 15.50-20/14/M9-4631 |
| | | | | 15.50-20/20/M9-4883 |
| | | | | 17.00-16/12/M9-4860 |
| | | | | 18x5.5/10/210/M4-4898 |
| | | | | 24x7.7/14/210/M3-4225/1 |
| | | | | 24x7.7/16/210 |
| | | | | 26x6.6/10/180/NO-5728 |
| | | | | 26x6.6/10/225/M2-5232/1, M9-4816/2 |
| | | | | 26x7.75-13/10/200/10941/M/458 |
| | | | | 28x9.00-12/8/M9-4724/1 |
| | | | | 32x11.50-15/12/200/M8-4041, N1-4827, N5-558601 |
| | | | | 32x11.50-15/12/210/N5558601 |
| | | | | 34x9.9/10/M9-4813 |
| | | | | 34x10.75-16/10/M8-4598-1 |
| | | | | 34x11/10/200/11018/M/532 |
| | | | | 34x11/20/200 |
| | | | | 34x11/22/225/NO-5727/2, NO-5750, M8-4361/2M9-4853/2, N2-5508, NO-5710 |
| | | | | 35x9.00-17/14/200/M4-7304 |
| | | | | 35x9.00-17/16-200/10939/M/456 |
| | | | | 36x11/20/225/10955/M/469, N4-4867 |
| | | | | 36x11/22/225/083.091 |
| | | | | 37x14-14/24/225/M3-5890/1 |
| | | | | 39x13/14/210/M4-4258/1 |
| | | | | 39x13/16/200/10955/M/469, N4-4855 |
| | | | | 39x13/16/210/34-786, M1-7839, N3-4210 |
| | | | | 39x13/16/225/11297/M/805 |
| | | | | 40x14/20/210/M1-4830/1, 083786 |
| | | | | 40x14/22/200/M1-4832/2 |
| | | | | 40x14/22/225/NO-5749 Partiel 1, N1-4849, N4-4256, 083792 |
| | | | | 40x14/24/200/32-557, 34-719, N1-4831, M7-7187, N5-531200 |
| | | | | 40x14/24/210/M5558701, N6641-501 |
| | | | | 40x14/24/225/M1-4855/1, N9-4849,, 083832 NO-5716728 |
| | | | | 40x14/28/210/083820 |
| | | | | 40x14/28/225/083841 |
| | | | | 40x15.5-16/26/235/M3-5520/1 and /2 |
| | | | | 41x15.0-18/22/225/M1-4801, M2-4883/2/F, N3-5896 |
| | | | | 41x15.0-18/24/ |
| | | | | 41x15.0-18/22/225/084866 |
| | | | | 44x16/28/200/35503, 34747, N1-4816, N2-5237 |
| | | | | 44x16/28/225/M6-7180 |
| | | | | 44x16/30/225/M1-4805/2&3/, N1-4813, M7-7189, N5-558701, 084427 |
| | | | | 44x16/32/225/NO-4894 |
| | | | | 44.5x16.5-18/30/225/M9-4859/1, 084891 |
| | | | | 46x16/24/210/M3-4214 |
| | | | | 46x16/26/200/M9-4817/1&2/, N5-5047, 34696 |
| | | | | 46x16/26/210/N2-4874/1 |
| | | | | 46x16/26/225/M9-4818, 11015/M/529 |
| | | | | 46x16/28/200/M6-7141, M8-4269 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|----|-----------|--|
| | | | | 46x16/28/210/NO-5736, M5-5130, W2-5237, N3-5880, N1-5779/1, 084723, 084724 |
| | | | | 46x16/28/225/33691, M4-4237/1, NO-5707, N14822, N6612-001 |
| | | | | 46x16/30/210/N3-5857/1&/2, N1-4805/2&/3, N4-4859, N5 558601 |
| | | | | 46x16/30/225/N3-5858/1&2, 084.736, 084738, 084739 |
| | | | | 49x17/26/200/M9-4821/1 |
| | | | | 49x17/28/210/M7-7162, W2-4877/1, M9-4801/1&2, N5-530900, NO-5764/1&/2, N6641-900 |
| | | | | 49x17/30/200/NO-4889 |
| | | | | 49x17/30/210/084871 |
| | | | | 49x17/30/225/NO-5704, N1-4875, 084.888 |
| | | | | 49x17/32/225/084887, 084873 |
| | | | | 49x19-20/32/235/084892 |
| | | | | 50x20.0-20/30/225/085001 |
| | | | | 50x20-20/32/225/M1-4820, N2-4899/1&/2, 084896 |
| | | | | 50x20-20/34/225/084.893 |
| | | | | 50x21-20/28/210/N3-5523/2 |
| | | | | 50x21-20/30/210/M4-4869/1 |
| | | | | 50x21.0-20/28/210/084905 |
| | | | | 50x21.0-20/30/210/084906 |
| | | | | 52x20.5-20/34/225/085530 |
| | | | | 52x20.5-23/26/235/W2-5243, N4-4249/1 |
| | | | | 52x20.5-23/30/235/085562 |
| TSO-C62b | McCreary Tire & Rubber Co. 3901 Clipper Rd. Baltimore, MD 21211 | NE | | Tire Size/Ply Rating/Part Numbers 5.00-5/4/AA00, GA00 5.00-5/6/AA01, GA01, AA01A 5.00-5/10/AA03 6.00-6/4/AB00, GB00, GB00-A, BB00, 30422 6.00-6/6/AB01, GB01, GB01-TL, BB01, 30604 6.00-6/8/AB02, GB02, GB02-A, BB02 6.50-8/6/AF01, GF01, GF01-TL, AF01A 6.50-8/8/GF01, AF02, AF02-TL 6.50-10/6/AH01, GH01, GH01-TL 6.50-10/8/AH02, GH02, AH02A, 30114, 30122 6.50-10/10/AH03, 9903, 9903-TL, AH03A, GH03, GH03-TL 7.00-6/6/AC01, GC01 7.00-6/8/AC02, GC02 7.00-8/4/AG00 7.50-10/6/AJ01 8.00-6/4/AD00 8.00-6/6/AD01, GD01, ADO1A 8.50-6/4/AE00 8.50-6/6/AE01 8.50-10/6/AK01, AK01A 8.50-10/8/AK02, GK02, GK02-TL, AK02A 8.50-10/10/GK03, GK03-TL 11.00-12/8/AL02 15x6.00-6/4/AH01, GM00, BM00 15x6.00-6/6/AH02, GM01, BM01 17.5x25-6/10/GN03 17.5x6.25-6/10/30122 18x4.4/6/AN01-TL 18x5.5/8/AP02-TL 18x5.5/10/AP03-TL 22x6.75-10/8/GP02-TL, GR02-TL |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|----|-----------|---|
| TSO-C62b | McCreary Tire & Rubber Co. 16 W. Washington St. Indiana, PA 15701 | NE | | Tire Size/Ply Rating/Part Numbers 5.00-5/4/30601, 30901, 30801 5.00-5/6/2631A, 30602, 30902, 30802 6.00-6/4/307-00-501, 30603, 30903, 30803 6.00-6/6/30620, 30804, 30904 6.00-6/8/307-02-501-1, 30605, 30805, 30905 6.50-8/4/350-00-001 6.50-8/6/30611, 30811, 30909, 31401, 31501 6.50-8/8/350-02-001, 30612, 30812, 30910, 31112, 31402 6.50-10/6/30813, 30917, 30613, 31403 6.50-10/8/310-02-501, 30614, 30814, 30912, 31214, 31404 6.50-10/10/310-03-501, 30815, 30913, 30615 6.50-10/12/31219 7.00-6/6/318-02-001, 30606, 30906, 30806 7.00-6/8/2802A, 30607, 30907, 30807 7.00-8/4/360-00-001 7.00-8/6/360-01-001 7.50-10/6/30616 7.50-10/8/320-02-001 8.00-6/4/30608, 30808 8.00-6/6/30609, 30809, 30908 8.00-6/8/30820 8.50-6/4/29B 8.50-6/6/324-01-001, 30610 8.50-10/6/30617, 30816 8.50-10/8/330-02-501, 30618, 30817, 30819, 31406 8.50-10/10/31503 11.00-12/6/301-01-001, 301-01-501 11.00-12/8/301-02-001 12.50-16/12/306-04-002 15x6.00/4/30630 15x6.00-6/4/30930 15x6.00-6/6/420-01-001, 30631, 30931 17x6.00-8/4/425-00-001 17x6.00-8/8/425-02-001 17.5x6.25-6/8/415-02-901 17.5x6.25-6/10/31022 18x4.4/6/700-01-601 18x5.5/8/706-02-601, 31006 18x5.5/10/765-03-904 20.00-20/26/764-11-604 22x8.0-8/6/31024 24x7.7/14/761-05-914 24x7.75-10/10/430-03-501 26x6.6/14/710-05-104, 759-05-604 29x11.0-10/10/31033 32x11.50/12/728-04-954 34x9.9/12/735-04-954, 762-04-401 34x9.9/14/716-05-002 34x11/18/733-07-954 34x11/20/733-08-954 36x11/22/717-09-604, 757-09-604 39x13/14/736-05-954 39x13/16/721-06-954, 755-06-915 40x12/18/739-07-953, 739-07-953A 40x14/20/724-08-954, 746-08-915 40x14/24/744-10-954 44x16/28/722-12-954 44x16/32/745-11-915 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|--|
| | | | | 46x16/24/719-10-954 46x16/26/737-11-954 46x16/28/719-12-954 49x17/30/763-03-915 |
| TSO-C62b | Multi-Purpose Tire Co. 113 E. Hall Avenue San Ysidro, CA 92073 | NM | | 24x10x4 24x10x6 |
| TSO-C62b *F | Nippon Goodyear Kalushiki Kaisha 9-13, 1-Chome, Akasaka Minato-ku, Tokyo, Japan | M-L | | Tire Size/Ply Rating/Speed 26x6.6/10/225 36x11/22/225 40x14/24/200 41x15.0-18/22/225 |
| TSO-C62b *F | Sumitoma Rubber Ind., Ltd. 1-1, Tsutsui-cho, 1-chome, Fukiki-ku, Kobe City, Hyogo Prefecture, Japan | NM-L | | TIRE SIZE/PLY RATING/PART NUMBERS 40x15.5-16/26/DR21521T 50x20-20/32/DR17128T 52x20.5-23/28/DR21422T |
| TSO-C62b | UniRoyal Tire Company 6600 East Jefferson Ave. Detroit, MI 48232 | CE-C | | Tire Size/Ply Rating/Part Numbers 5.00-4/4/QTR C-133 5.00-5/2/4/C112TL, C113TL 5.00-5/4/C112-1, C-112TL, C113TL, 5941-949, 5912-009 5.00-5/6/C-114, C-114TL, C-114-1, QTR C-88, C-88TL, 5941-970, 5907-970 5.00-5/10/5941-086 6.00-6/4/5901-056, QTR C-92, C-92TL, C-188, C-188TL, C-188-1, C-108, C-108TL, C-109, C-109TL, 5907-056, 5941-950 6.00-6/6/C-110, C-110TL, C-97, QTR C-97TL C-110-1, C/N 5941-995 6.00-6/8/C-111, C-111TL, C/N 5941-062 6.50-8/4/QTR C-95, C-95TL, C-96, C-96TL 6.50-8/6/C-96, C-96TL, C-95, C-95TL, C/N 5941-042 6.50-8/8/QTR C-106, C/N 5941-998 6.50-10/4/C-82, C-82TL 6.50-10/6/C-230, C-83, C-83TL, C/N 5941-999 6.50-10/8/C-80, C-231, C-80TL, C/N 5941-048 7.00-6/4/QTR C-134, C-134TL 7.00-6/6/QTR C-135, C-135TL, C-135-1, 5960-955 7.00-6/8/QTR C-136, C-136-1, 5960-098 7.00-8/4/QTR C-146 7.00-8/6/QTR C-147, C-147TL, C/N 5960-036 7.50-10/6/QTR C-115, C/N 5960-957 7.50-14/8/C-54 7.50-14/10/C-55TL 7.50-14/12/C-56TL 8.00-4/4/QTR C-126 8.00-6/4/QTR C-141, C-141TL 8.00-6/6/QTR C-142, C-142TL, C/N 5941-022 8.00-6/8/QTR-143, 5941-046 (QTRC-288) 8.50-6/4/C-66 8.50-6/6/C-67, 5960-063 8.50-10/6/C-100, C/N 5932-961 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | | | | 8.50-10/8/QTR C-99, C-99TL, C/N 5932-023 |
| | | | | 8.50-10/10/C-98, C-98TL, 247TL, 5985-045 |
| | | | | QTR C-107TL, C/N 5960-045 |
| | | | | 8.90-12.50/4/QTR C-148 |
| | | | | 9.00-6/10/C-68 |
| | | | | 9.50-16/10/QTR C-149, C-149-1 |
| | | | | 10-1/2x4/8/QTR C-165, C/N 5943-926 |
| | | | | 11.00-12/6/QTR C-158 |
| | | | | 11.00-12/8/QTR C-159, C-159TL |
| | | | | 12-1/2x4-1/2 /10 |
| | | | | 12.5x4.5/10/C/N 5918-927 |
| | | | | 12.50-16/12/C-85, C-177TL |
| | | | | 12.50-16/14/C-139 |
| | | | | 13.50-16/24/C-7TL, C-65TL |
| | | | | 14.5x5.5-6/12/C-215TL |
| | | | | 15x6.00-6/4/QTR C-163, C-163-1, C-163TL, |
| | | | | C-163TL-1, C/N 5941-051 |
| | | | | 15x6.00-6/6/QTR C-164, C-164-1, C-164TL, |
| | | | | C-164TL-1, C/N 5941-057 |
| | | | | 15.00-16/10/QTR C-157 |
| | | | | 15.00-16/14/QTR C-150TL |
| | | | | 15.50-20/14/QTR C-151 |
| | | | | 15.50-20/16/QTR C-152 |
| | | | | 15.50-20/20/QTR C-153, C-153TL |
| | | | | 16.00-16/14/QTR C-154 |
| | | | | 17.00-16/10/QTR C-155 |
| | | | | 17.00-16/12/QTR C-156 |
| | | | | 17.00-20/16/QTR C-160 |
| | | | | 17.00-20/20/QTR C-161 |
| | | | | 17.00-20/22/QTR C-162, C-162TL, C-90TL |
| | | | | 18x4.4/6/C-81TL |
| | | | | 18x4.4/10/C-77TL |
| | | | | 18x4.4/12/QTR C-140TL, C-140TL-1, |
| | | | | C-184TL |
| | | | | 18x4.25-10/6/QTR C-125TL |
| | | | | 18x5/10 |
| | | | | 18x5.5/8/C-144TL, C-203, 5964-888 |
| | | | | 18x5.5/10 |
| | | | | 19.00-12/16/QTR C-93, C-124TL |
| | | | | 20.00-20/22/QTR C-84 |
| | | | | 21x7.25-10/8 |
| | | | | 22.0x8.00-18/10 |
| | | | | 22x8.08/6/C/N5941-885 |
| | | | | 22x8.08/10 |
| | | | | 23x7.00-12/10/QTR C-129TL |
| | | | | 24x7.7/10/C-182TL, C-200TL |
| | | | | 24x7.7/14/C-119TL, QTR C-138TL |
| | | | | 24x7.7/16/C-186TL, C-212TL |
| | | | | 24x7.7-12/10/QTR C-137TL, C-74TL, |
| | | | | C-74TL-1, C-74TL-2 |
| | | | | 26x6.6/8/C-78TL, C-78TL-1, C-172TL, |
| | | | | C-171TL, C-226TL-1 |
| | | | | 5902-935 |
| | | | | 26x6.6/10/C-181TL, QTR C-174TL, |
| | | | | C-207TL-1, QTR C-173TL, |
| | | | | C-172TL |
| | | | | 26x6.6/12/QTR C-132TL, C-132TL |
| | | | | 26x6.6/14/C-202TL, C-103TL, C-69TL |
| | | | | 26x7.75-13/10/C48, C48-1 |
| | | | | 28x7.7/10/C-53TL |
| | | | | 29x7.7/12/C-34TL, C-180TL, C-35TL |
| | | | | 29x7.7/16/C-36TL, C-37TL |
| | | | | 32x8.8/12/C-45TL |
| | | | | 32x11.50-15/12/C-60TL, C-179TL, C-60TL-1 |
| | | | | C-60TL-2, 6953-055 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|-----------------------------------|----|-----------|---|
| | | | | 34x9.25-16/16/C-216TL |
| | | | | 34x9.9/10/QTR C-166 |
| | | | | 34x9.9/12/QTR C-167, C-31TL |
| | | | | 34x11/18/C-25TL, C-25TL-3 |
| | | | | 34x11/20/C-28TL, C-75TL |
| | | | | 34x11/22/C-190TL, QTR C-121TL, C-121TL-1 |
| | | | | 6996-907 |
| | | | | 35x9.00-17/16/C-91TL |
| | | | | 36x10.75-16-1/2 /16/C-89TL, C-94TL |
| | | | | 36x11/20/C-208TL, 6902-939 |
| | | | | 36x11/22/C-63TL |
| | | | | 37x14.0-14/24/C-225TL, C-228TL |
| | | | | 6902-860 |
| | | | | 39x13/14/C-221, C-21TL, C-187 |
| | | | | 39x13/16/C-23TL, C-49TL |
| | | | | 39x13/20/C-27TL, C-39TL, C-42TL |
| | | | | 40x12/14/C-196 |
| | | | | 40x12/16/C-71TL, C-71TL-1 |
| | | | | 40x12/18/C-105TL-2, C-150TL, C-86TL, |
| | | | | C-194TL |
| | | | | 40x12/22/C-128TL |
| | | | | 40x14/18/C-79TL |
| | | | | 40x14/20/C-101TL, QTR C-191TL, C-101TL-1 |
| | | | | QTR C-170TL |
| | | | | 40x14/22/C-104TL, QTR C-116TL, C-116TL-1 |
| | | | | 40x14/24/C-64TL, C-214TL, C-192TL, |
| | | | | C-118TL, C-87TL, C-119TL, |
| | | | | C-123TL, C-123TL-1 |
| | | | | 6993-071 |
| | | | | 41x15.0-18/22/C-33TL, C-41TL |
| | | | | 41x15.0-18/24/C-40TL, C-43TL, C-43TL-2 |
| | | | | 44x16/26/C-26TL, C-76TL |
| | | | | 44x16/28/C-62TL, QTR C-117TL, C-213TL, |
| | | | | C-30TL |
| | | | | 44x16/30/C-189TL, C-189TL-1, QTR C-120TL, |
| | | | | C-120TL-1, C-183TL, |
| | | | | 6903-924 |
| | | | | 44x16/32/QTR C-176TL, 6902-997 |
| | | | | 44.5x16.5-18/30/C-210TL, C-185TL |
| | | | | 6996-100 |
| | | | | 46x16/20/C-22TL |
| | | | | 46x16/24/C-73TL, C-122TL, C-168TL |
| | | | | 6903-091 |
| | | | | 46x16/26/C-197TL, C-44TL, C-198, C-52TL, |
| | | | | C-102, C-169, C-76TL |
| | | | | 46x16/28/C-70TL, C-199TL, C-217TL, |
| | | | | C-233TL, C-169TL, C-169TL-1 |
| | | | | QTR C-102TL |
| | | | | 46x16/30/C-235TL |
| | | | | 49x17/24/C-51TL |
| | | | | 49x17/26/C-72TL, C-58TL |
| | | | | 49x17/28/C-92TL, QTR C-92TL-1, C-222TL, |
| | | | | C-234TL, C-237TL, 6903-985 |
| | | | | 49x17/30/C-219TL, C-220TL |
| | | | | 6903-972, 6902-972 |
| | | | | 50x20.0-20/30/C-224TL |
| | | | | 50x20.0-20/32/C-227TL, C-229TL |
| | | | | 56x20.0-20/22/C-131, QTR C-131-1 |
| | | | | 56x20.0-20/24/C-178TL |
| TSO-C62b | The Yokohama Rubber Co. Ltd. NM-L | | | Tire Size/Ply Rating/Speed |
| *F | 36-11, Shinbashi 5 Chome | | | 24x7.7/14/200 |
| | Minato-ku | | | 32x11.5-15/12/200 |
| | Tokyo 105, Japan | | | 34x11/20/200 |
| | | | | 36x11/22/225 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-------------------|--|
| | | | | 40x14/24/200 40x15.5-16/26/235 44x16/28/200 49x17/26/200 49x17/28/210 50x20-20/32/225 52x20.5-23/28/235 |
| TSO-C62c | DICO Tire Inc. Madine Road Clinton, TN 37716 | CE-A | AIRCRAFT TIRES | TIRE SIZE/PART NUMBER 5.00-5/6/46A260 5.00-5/4/451265 5.00-5/6/46A260 5.00-5/10/46A255 5.00-5/4/46A265 6.00-6/4/46A264 6.00-6/6/46A266 6.00-6/8/46A258 6.50-8/6/46A269 6.50-8/8/46A289 6.50-10/8/46A271 6.50-10/10/46A290 6.50-10/6/46A268 7.00-6/6/46A267 7.00-6/8/46A263 7.00-6/6/46A267 8.00-6/6/46A272 8.00-6/8/46A298 8.50-10/8/46A278 8.50-10/10/46A270 |
| TSO-C62c *F | Bridgestone Tire Co., Ltd. 2800-1, Ogawa, Higashi-cho Kodairo-shi, Tokyo, Japan | NM-L | | TIRE SIZE/PART NUMBER 6.00-6/6/APS01055-A 8.50-10/10/APS01110-A 8.90-12.50/6/APS01156A 11.00-12/8/APS01147-A 12.50-16/12/APS00170-B 12.50-16/12/APS01250-A 24x7.7/APS00362-A 24x7.7/10/APS01122-A 24x7.7/14/APS00358-B 24x7.7/14/APS01126-A 24x7.7/16/APS00362-B 24x7.25-12/10/APS01139 24x7.7/10/APS00330-B 24x7.7/12/APS00362-A 24.5x8.5/APS01140-A 26x6.6/APS00278-A, -B, APS00281, -A 26x6.6/10/APS0278-A-B-C 26x6.6/10/APS01162-A 26x6.6/12/APS00281-A-B 27x7.75-15/10/APS01205-A 28x9.00-12/8/APS01146 H31x13.0-12/20/APS01150-A 32x11.50-15/APS00569-B, -C 32x11.50-15/APS01210 32x11.50-15/12/APS01210A 32x11.50-15/12/APS00569-D 32x11.50-15/12/APS00569-B-C-D 34x11/APS00400-A 34x11/22/APS00400-B-A 34x10.75-16/10/APS01228 36x11/APS00407-A, -B, APS00413-A, -B 36x11/20APS0407-A-B-C 36x11/22/APS00413-A-B-E-F-D |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | | | | H37x14.0-15/APS01214 |
| | | | | H37x14.0-15/22/APS01214-A |
| | | | | 37-13.0-16/26/APS01241-A |
| | | | | 39x13/APS01253 |
| | | | | 39X13/14APS01253-A |
| | | | | 39X13/16/APS00417-B |
| | | | | 39X13/16/APS00419-B |
| | | | | 39X13/22/APS01258-A |
| | | | | H40x14.5-19/APS01330 |
| | | | | 40x14/APS00453-A, -B, APS00478-B, -C, APS00481-B, -C, -D, APS00483-A, -B |
| | | | | 40X14/16/APS01267-A |
| | | | | 40X12/20/APS01259 |
| | | | | H40X14.5-19/22/APS01330-A |
| | | | | 40X14/22/APS00453-C, APS00481-E |
| | | | | 40X14/24/APS00478-F |
| | | | | 40X14/28/APS00483-D |
| | | | | 40X14.5-19/24/APS00598-B |
| | | | | 40X15.5-16/26/APS00571-C |
| | | | | 40X15.5-16/28/APS00587-A |
| | | | | H40x14.5-19/APS00598, -A |
| | | | | 40x15.5-16/APS0051-B |
| | | | | 41x15.0-18/APS00576-B, -C, APS00588 |
| | | | | 41X15.0-18/22/APS00576-D |
| | | | | 41X15.0-18/24/APS00588-A |
| | | | | 44X16/30/APS00499-D |
| | | | | 44X16.5-18/30/APS00574-D |
| | | | | 44X16.5-20/28/APS01403-A |
| | | | | 44x16/APS00499-B, -C |
| | | | | 44.5x16.5-18/APS00552-A, APS00574-C |
| | | | | H44.5x16.5-20/APS00612A |
| | | | | H44.5x16.5/APS00612 |
| | | | | H44.5x16.5-20/APS00610, -A |
| | | | | H45x17.0-20/APS01405 |
| | | | | H45X17.0-20/26/APS01405-A, APS01404-A |
| | | | | 46x16/APS00516-B, -C, APS00524-B, -C, APS00528 |
| | | | | 46X16/30/APS0524-E |
| | | | | 46X16/28/APS00516-E |
| | | | | 46X16/32/APS00528-B |
| | | | | H46x18.0-20/APS01412 |
| | | | | H46X18.0-20/28/APS01412-A |
| | | | | 46X18/20/APS01410-A-B |
| | | | | 46X18/28/APS01001 |
| | | | | 49x17/APS00539-B, -C, APS00552-A, -B, APS00554-B, -C, APS00558-A, -B |
| | | | | 49X17/28/APS00539-E |
| | | | | 49X17/32/APS00558-C, AP501350 |
| | | | | 49x19.0-20/APS00563-A, -B, APS00591 |
| | | | | 50x20-20/APS00617-B, -C, APS00623-A, -B |
| | | | | 50X20/32/APS00617-F |
| | | | | 50X20/34/APS00623-C |
| | | | | 50x21-20/APS00625-B, -C, APS00635-B, APS01467 |
| | | | | 50X21/28/APS00625-D, APS00635-C |
| | | | | 50X21/30/APS01467-A |
| | | | | 52x20.5-20/APS00640-A, -B, APS00655-A, -B |
| | | | | 52x20.5-23/APS00700-A, -B, -C, -D |
| | | | | 52x20.5-23/APS00754-A |
| | | | | 52X20.5-20/34/APS00640-C |
| | | | | 52X20.5-20/36/APS00655-C |
| | | | | 52X20.5-23/30/APS00754-B, APS00754-C |
| | | | | 49X17/30/APS00554-D, APS01354 |
| | | | | 49X17/30/APS00552-C, APS01354 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|---|
| | | | | 49X19.0-20/APS00591-A 49X19.0-20/APS00563-C H49X19.0-22/32/APS01480 H46X18.0-20/32/APS01441 52X20.5-23/28/APS00700-E |
| TSO-C62c *F | Bridgestone Corporation 105 Kyomachi Kurume-Shi Fukuoka 830, Japan | NH-L | | TIRE SIZE/PLY RATING/PART NUMBER H46x18.0-20/26/APS06005 H49x19.0-22/24/APS01481 H46x18.0-20/32/APS06007 50x21.0-20/30/APS06004, APS06003 50x20.0-20/32/APS06000 27x7.75-15/10/APS01205-B 27.7.75-15/12/APS01207 30x8.8R15/16/APR05140 H37x14.0-15/24/APS01222 40x14/24/APS01291 40x14/24/APS01294 H40x14.5-19/24/APS01339 H40x14.5-19/26/APS01337 H42x16.0-19/26/APS01325 H44.5x16.5-20/28/APS01440 H44.5x16.5-20/24/APS01387 46x16/28/APS01347 46x16/30/APS01346 46x17R20/30/APR06750 H46x18.0-20/28/APS06006 H46x18.0R20/28/APR06803 H46x18.0 R20/28/APR03001 49x17/28/APS01355 49x17/32/APS01348 49x19.0-20/32/APS01450 49x19.0-20/34/APS01451 52x20.5-23/28/APS01486 52.20.5-23/30/APS01501 H54x21.0-24/34/APS01550 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|----|-----------|---|
| TSO-C62c *F | Continental Gummi-Werke AG Aktiengesellschaft Hannover, Germany | EU | | 32x11.50-15/12/136 40x14/22/132 40x14/24/133 49x17/28/137 49x17/30/134 49x17/32/135 52x20.5/23/28/139 |
| TSO-C62c *F | Dunlop of France 62, rue Camille Desmoulins Issy les Moulineaux France | EU | | TIRE SIZE/PART NUMBER 40x14/V1306 40x16/V1415 49x17/V1427, V1131 49x19.0-20/V1430 -14.5x5.5-6/V2150 -18x5.5/V3170 -22x5.75-12/V1310 -26x6/6/7/V3229 44.5x16.5-18/V2349 -52x20.5-23/V1670 |
| TSO-C62c *F | Dunlop of France Usine de Montlucon rue des Pasquis 03108 Montlucon Cedex BP539 France | EU | | TIRE SIZE/PART NUMBER H44.5x16.5-20/V1380 50x21-20/V1395 670x210-12/V1490 |
| TSO-C62c *F | Dunlop France 62 rue Camille Desmoulins BP 41 92133 Issy Les Moulineaux France | EU | | H40x14.5-19/V1382 H49x19.0-22/V1440 46x16/V2415 30x8.8/V1242 32x11.5-15/V1375 15x6.00-6/V1408 18x5.5/V3174 24x7.7/V1385 34x14.75-16/V1409 40x14/V4306 41x15.0-18/V1390 H44.5x16.5-20/V1381 46x16/V2414 52x20.5-23/V2670 |
| TSO-C62c *F | Dunlop Limited fort Dunlop Birmingham United Kingdom | EU | | 49x19.0-20/34/DR22729T 49x19.0-20/32/DR22728T 39x13/24/DR11745T H34.5x12.0-14/14/DR25422T 31x9.75-14/12/DR26221T 5.00-5/DR5873T 6.50-10/10/DR12330T 6.00-6/8/DR7730T 6.00-6/6/DR7729T 11.00-12/10/DR10627T 22x6.75-10/DR25520T 24x7.7/6/DR15845T 26x6.6/12/DR3632T 30x8.8/16/DR9624T 32/8.8/12/DR766T 34x10.75-16/12/DR0228T 37x11.75-16/12/DR19923T 37x11.75-16/12/DR19924T H40x14.5-19/24/DR23635T H40x14-19/20/DR26521T 41x15.0-18/22/DR21329T 42x15/22/DR20725T H44.5x16.5-20/26/DR22824T H44.5x16.5/28/DR22823T |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|----|-----------|---|
| | | | | 46x16/DR11660T, DR11661T, DR11662T 46x16/30/DR11659T 49x17/30/DR15349T 49/17/32/DR15350T H49x19.0-22/32/DR26020T H54x21.0-24/34/DR26620 |
| TSO-C62c *F | Dunlop LTD Coventry, United Kingdom | EU | | ANA 1737 Mod () |
| TSO-C62c *F | Dunlop Limited Fort Dunlop Erdington, Birmingham England | EU | | TIRE SIZE/PART NUMBER 5.00-5/DR5865, DR5865T, DR5866, DR5873T DR5866T 6.00-6/DR7727T, DR7728T 7.00-6/10/DR7925T 8.50-10/DR8630T/DR8628T 9.00-6x10/DR4626 9.00-6x10/DR4626T 11.00-12/DR10624T, DR10623T, DR10625T 15.99-16/DR10027/T 18x4.25-10/DR6385T 18x5.5/8/DR9835T 22x6.75/10/8/DR25523T 22x6.75-10/DR25520T 23x7-12/12/DR14621T 23x7.00-12/12/DR14628T 24.5x8.5-10/10/DR19621T 24x7.7/16/DR15844T, DR15846T 24.5x8.5-10/12/DR19620T 24x7.7/15833T, DR15840T, DR15842T 24x7.25-12/10/DR7152T 26.5x8-13/12/DR24221T 26x6.6/DR3629T, DR3630T 27x7.75-15/10/DR25820T 27x7.75-15/12/DR25821T 28x9.00/DR11323T 28x9.00-12/12/DR11332T H31x13-12/DR23720T, DR23721T, DR23722T 31x9.74-14/12/DR26220T 32x10.75-14/DR10728T, DR10728T 32x11.50-15/12/DR17220T 34x10.75-16/DR0226T 34x10.75-16/10/DR0223T 34x10.75-16/12/DR0226T H34.5x120-14/14/DR25421T 34x11/22/DR11922T 37x11.75-16/10/DR19921T 37x11.5-16/12/DR19922T 37x13.0-16/DR22521T 37x14-15/24/DR23224T 37x14-15/22/DR23220T 37x14-14/DR20522T 39x13/DR11741T, DR11737T 39x13/18/DR11739T 39x13/22/DR11743T 40x12/18/DR7558T, DR7564T, DR7561T 40x12/20/DR7559T, DR7562T, DR7565T 40x12/22/DR7563T 40x12/22/DR7566T 40x14/28/DR12669T 40x14/24/DR12668T 40x14/DR12653T, DR12654T, DR12655T, DR12637T, DR12642T H40x14.0-19/18/DR26520T |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--------------------------|----|-----------|---|
| | | | | H40x14.5-19/DR23620T, DR23621T, DR23622T, DR23628T, DR23629T, DR23632T |
| | | | | H40x14.5-19/26/DR23631T |
| | | | | H40x14.9-19/24/DR23633T |
| | | | | 40x14/16/DR12662T |
| | | | | 40x14/28/DR12661T |
| | | | | 40x15.5-16/DR21520T, DR21522T |
| | | | | H40x14.5-19/22/DR23626T, DR23627T |
| | | | | 42x15/18/DR20720T |
| | | | | 42x15/20/DR20723T |
| | | | | H42x16-19/24/DR24821T |
| | | | | H44.5x16.5-20/DR.22821T |
| | | | | 46x16/DR11651/T |
| | | | | 46x16/28/DR11643T, DR11643T, DR11657T |
| | | | | 46x16/30/DR11645T, DR11656T |
| | | | | 46x16/32/DR11655T |
| | | | | H46x18/20/25620T |
| | | | | H46x18-20/28/DR25620T |
| | | | | H46x18.0-20/32/DR25622T |
| | | | | H46x18.0-20/26/DR25621T |
| | | | | 49x17/30/DR15347T |
| | | | | 49x17/32/DR15348T |
| | | | | 49x17/DR15335/T, DR15339/T, DR1533T, |
| | | | | 49x19.0-20/34/DR22726T |
| | | | | 49x19.0-20/32/DR22727T |
| | | | | 49x19-20/DR22723T |
| | | | | 49x19.0-20/DR22721T, DR22722T, DR22723T, |
| | | | | 50x20.0-20/DR17131T, DR17133T, DR17134T, |
| | | | | DR17137T |
| | | | | 50x21.0-20/30/DR21721T |
| | | | | 52x20.5-20/DR22421T |
| | | | | 52x20.5-20/36/DR22422T, DR22423T |
| | | | | 52x20.5-23/DR21428T, DR21429T, DR21430T, |
| | | | | DR21431T |
| | | | | 56x20.0-20/24/DR22220T |
| TSO-C62c | Dunlop Olympic Tyres | EU | | 6.00x6/6/120/960100 |
| *F | Cross Street | | | 6.00x6/6/120/960101 |
| | West Footscray | | | H46x18.0/20/26/225/960420 |
| | Australia, Victoria 3012 | | | H46x18.0/20/28/225/960421 |
| TSO-C62c | Dunlop South Africa Ltd. | EU | | 24x7.7/16/225/DRR 15833T |
| *F | 265 Sydney Road | | | 34x10.75/16/10/190/DR 0223T |
| | Durban, 4001 | | | 40x14/24/225/DR 12655T |
| | | | | H40x14.5-19/24PR/225/DR 23621T |
| | | | | 46x16/28/225/DR 11643T |
| | | | | 46x16/30/225/DR 11654T |
| | | | | 49x17/32/235/DR 15331T |
| | | | | 49x19/20/34/235/DR 22721T |
| | | | | 56x20/20/24/200/15025T |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|---|
| TSO-C62c *F | Firestone Hispania S.A. Bassuri, Apartado 406 Bilbao, Spain | EU | | TIRE SIZE/PLY RATING/PART NUMBER C24.5x8.5-12/12/00540 26x6.6/10/RT00001 32x11.50-15/12/RT00003 40x14/24 C40x14.0-21/24/00532 C40X18.0-17LXX/20/00541 46X16/30/RT00008 41X15.0X18/22/00009 46x16/28/RT00006 49x19-20/32/RT00007 50x21/00-20/30 52x20.5-23/28/RT00005-A |
| TSO-C62c | B.F. Goodrich Tire Company 500 South Main Street Akron, OH 44318 | CE-C | | TIRE SIZE/PLY RATING/PART NUMBERS 5.00-5/8/021-310 5.00-5/4/083-308 5.00-5/6/083-309, 061-309 5.00-5/10/061-311, 083-315 6.00-6/4/061-315 6.00-6/6/021-316, 061-316, 083-316 6.00-6/8/021-317, 061-317, 083-317 6.50-8/8/021-338, 061-338, 083-338-0 6.50-10/6/021-344, 061-344, 083-344-0 6.50-10/8/061-345, 083-345-0 6.50-10/10/021-356, 061-356, 083-356-0 6.50X10/12/021-357, 028-357 7.00/6/061-320, 083-320-0 7.00-6/8/061-321, 083-321-0 7.00-8/8/021-353 7.00-8/10/021-332 7.5-14/8/021-360 7.50-14/12/028-362-1 8.50-10/8/021-349, 061-349, 083-349-0 8.50-10/10/021-350, 061-350, 083-350-0 8.50x10/12/004-351 8.90x12.50/6/021-436 9.50-16/12/028-366 11.00-12/8/021-354, M21-3542 11.00-12/10/021-355, M21-3550 14.5x5.5-6/14/031-629 15x6.0-6/6/061-501, 083-501-0 16x4.4/4/038-604 16x4.4/6/061-605 16x4.4/8/021-606 17.5x6.25-6/8/061-327, 021-625 17.5x6.25-6/10/061-326 17.5x5.75-8/12/038-627 18x4.25-10/6/031-595 18x4.4/6/021-611 18x4.4/10/031-613, -8 18x4.4/12/031-614 18x5.5/8/028-630 18x5.5/10/033-631 19.5x6.75-8/10/021-335, 028-335, 061-335, 063-335 20x4.4/028-619 21x7.25-10/8/031-507 21x7.25-10/10/031-506 22x5.72-12/8/028-519 22x5.75-12/10/028-520, 033-520 22x6.75-10/8/021-523 22x6.75-10/10/028-524 22x7.75-10/8/021-526 22x7.75-10/10/021-527 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | 22x8.0-10/10/028-699 |
| | | | | 22x8.0-10/12/028-700-0 |
| | | | | 23x7.00-12/10/033-505 |
| | | | | 24.5x8.5-10/10/M33-6410 |
| | | | | 24x7.7/10/033-674, 028-674 |
| | | | | 24x7.7/12/038-673, 033-673 |
| | | | | 24x7.7/14/028-675 |
| | | | | 24x7.7/16/033-677, 039-677, 033-677-1, 039-677-1 |
| | | | | 24x7.25-12/10/031-678, 028-678 |
| | | | | 26.5x8.0-13/12/028-691 |
| | | | | 26x6.6/10/035-657, 038-657, 039-657, M39-6572 |
| | | | | 26x6.6/12/032-658, 039-658 |
| | | | | 26x6.6/14/033-659 |
| | | | | 26x7.75-15/12/039-688 |
| | | | | 27x7.75-15/039-655 |
| | | | | 27x7.75-15/033-665, 039-665, -3 |
| | | | | 28x9.00-12/8/M28-6930 |
| | | | | 28x9.00-12/12/028-728 |
| | | | | 30x9.00-15/12/028-703 |
| | | | | 31x9.75/13/028-200 |
| | | | | 31x13.0-12/20/032-838 |
| | | | | 32x10.75/12/M21-7090 |
| | | | | 32x11.50-15/12/031-837, 035-837-1 |
| | | | | 33.5x10.75-15/12/028-717 |
| | | | | 34x9.25-16/18/033-841 |
| | | | | 34x10.75-16/10/028-729, M28-7291 |
| | | | | 34x10.75-16/028-732 |
| | | | | 34x11/22/039-735 |
| | | | | 34x12-12/14/028-541 |
| | | | | 37x13-16/26/039-763 |
| | | | | 37x14.0-14/24/039-747 |
| | | | | H37x14.0-15/22/032-744 |
| | | | | H37x14-15/24/039-739 |
| | | | | 39x13/14/028-754, 033-754 |
| | | | | 39x13/16/038-755, 039-755 |
| | | | | 37x13.0-16/039-765 |
| | | | | 39x13/22/039-758, 028-758 |
| | | | | 40x12/18/033-753 |
| | | | | 40x12/20/033-772 |
| | | | | 40x14/16/M33-8060 |
| | | | | 40x14/16/033-806 |
| | | | | 40x14/22/039-768 |
| | | | | 40x14/28/033-771 |
| | | | | 40x14/24/033-769, 039-769-1, -3, -8 |
| | | | | H40x14.5-19/22/032-775, 033-775, 032-775-2 |
| | | | | H40x14.5-19/24/033-781, 039-781 |
| | | | | H40x14.5-19/26/039-800 |
| | | | | H40x14.5-19/26/039-800-1 |
| | | | | 40x14.5-19/22/032-775 |
| | | | | 40x15.5-16/26/020-844 |
| | | | | 40x15.5-16/28/020-846 |
| | | | | 41x15.0-18/22/039-856 |
| | | | | 41x15.0-18/24/039-857 |
| | | | | 44x16/30/039-778, 033-778 |
| | | | | 44x16/32/032-779 |
| | | | | 44.5x16.5-18/30/032-865 |
| | | | | H44.5x16.5-20/24/032-864 |
| | | | | H44.5x16.5-20/26/039-861 |
| | | | | H44.5x16.5-20/28/039-853 |
| | | | | H45x17.0-20/26/032-862 |
| | | | | 46x16/24/033-782 |
| | | | | 46x16/28/032-784, 033-784, |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|--------------------------------------|
| | | | | 039-784 |
| | | | | 46x16/30/033-785, 039-785, M39-7853 |
| | | | | 46x16/32/033-803, 039-803, -2 |
| | | | | H46x18.0-20/26/032-863, 032-863-1 |
| | | | | H46x18.0-20/28/039-859 |
| | | | | H46x180.0-20/32/039-807 |
| | | | | 49x17/28/033-788, 039-788 |
| | | | | 49x17/30/032-789, 033-789, 039-789 |
| | | | | 49x17/32/032-791, 033-791, 032-791-3 |
| | | | | 49x17/34/039-801 |
| | | | | 49x19-20/32/020-870, -2 |
| | | | | 49x19-20/34/020-873, M20-8730 |
| | | | | H49x19-22/32/020-805, -2 |
| | | | | 50x20-20/30/038-784, 033-874, -1 |
| | | | | 50x20-20/32/039-875 |
| | | | | 50x20-20/34/039-876-3, -2 |
| | | | | 50x20-20/36/039-886-1 |
| | | | | 50x21-20/30/039-877 |
| | | | | 50x21.0-20/30/038-877, -1 |
| | | | | 52x20.5/36/039-890 |
| | | | | 52x20.5-20/34/039-883 |
| | | | | 52x20.5-23/30/020-885, 020-882 |
| | | | | 56x20.0-20/24/038-881, M38-8810 |
| | | | | 670x210-12/10/028-667 |
| TSO-C62c | B.F. Goodrich Co. Military & General Avn. Operations 250 N. Cleveland-Massillon Rd Akron, OH 44313-0501 | CE-C | | 6.50X10/12PR/160 mph 021-357-1 |
| | | | | 8.50x10/12PR mph 004-351 |
| | | | | 8.50X10/12PR/120 mph 004-351-1 |
| | | | | 17.5x5.75-8/12PR/120 mph 038-627-1 |
| | | | | 17.5x6.25-6/8PR/160 mph 061-327 |
| | | | | 18x4.4/10PR/190 mph 031-613-2 |
| | | | | 18x4.4/10PR/210 mph 031-613-5 |
| | | | | 19.5x6.75-8/10PR/190 mph 028-335-1 |
| | | | | 19.5x6.75-8/10PR/190 mph 063-335-1 |
| | | | | 22x6.75-10/10PR/160 mph 028-524 |
| | | | | 22x8.0-10/12PR/190 mph 028-700 |
| | | | | 24x7.7/16PR/225 mph 039-677-2 |
| | | | | 24x7.7/14PR/190 mph 028-675-1 |
| | | | | 24x7.25-12/10PR/190 mph 028-678 |
| | | | | 24x7.7/16PR/225 mph 039-677-1 |
| | | | | 24x7.7/16PR/210 mph 033-677-2 |
| | | | | 26x6.6/12PR/225 mph 039-658-1 |
| | | | | 27x7.75-15/10PR/225 mph 039-665-2 |
| | | | | 27x7.75-15/12PR/225 mph 039-688 |
| | | | | 34x10.75-16/12PR/160 mph 028-732-1 |
| | | | | 34x10.75-16/10PR/190 mph 028-729-1 |
| | | | | H37X14-15/24PR/225 mph 039-739-0 |
| | | | | H37x14.0-15/24PR/225 mph 039-739-1 |
| | | | | 40x12/20PR/210 mph 033-772 |
| | | | | 40x14/24PR/210 mph 033-769-2 |
| | | | | 40x14/16PR/210 mph 033-806 |
| | | | | 40x14/24PR/225 mph 039-769-2 |
| | | | | 40x14/24PR/225/M39-7692 |
| | | | | H40x14.5-19/26PR/225 mph 039-800-0 |
| | | | | 40x15.5-16/28PR/235 mph 020-846 |
| | | | | H44.5x16.5-20/28PR/225 mph 039-853 |
| | | | | 46x16/30PR/225 mph 039-785-3 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|--|
| | | | | 46x16/32PR/225 mph 039-803-1 49x17/32PR/225 mph 032-791-2 49x19-20/34PR/235 mph 020-873-1 H49x19-22/32PR/235 mph 020-805-1 |
| TSO-C62c | B. F. Goodrich Company Norwood, NC | CE-C | | 34x10.75-16/12/028-732-2 32x11.50-15/12/035-837-2 32x11.50-15/12/031-837-1 27.7.75-15/12/039-688-1 |
| TSO-C62c *F | Companhia Goodyear do Brazil S/A Rua dos Prozues No. 284 12.200 Sao Jose dos Campos Sao Paulo, SP Brazil | CE-A | | TIRE SIZE/PART NUMBER 5.00-5/505C81B1 6.00-6/606C61B3, 606C81B3 18x5.5/155F03B2 18x5.5/185F66B1 6.50-10/650T81B1 25x7.75-10/257K2SR1 26x6.6/266F48B2 28x7.50-14/285F08B2 32x11.50-15/321K22B2, 321K22B3 34x10.75-16/347K06B1 35x9.00-17/359R63B1 39x13/393F6253, 393F6332 40x12/402F03B1 40x14/404F42B1, 404F43B2 46x16/466F82B2, B3 49x17/497F02B2, 497F83B2 49x19.0-20/491K45B1 50x20.0-20/500K63B3 52x20.5-23/520K092B 56x20.0-20/560F43B1 450x190-5/459M09B1 B212:22x6.75-10/265K08B1 B205:16x4.4/164F68B1 B209:17.5x5.75-8/178K23B1 A051:8.90-12.50/892C66B1 A033:6.50-10/650T81B1 |
| TSO-C62c *F | Goodyear Tire & Rubber Co. Bangkok, Thailand | EU | | TIRE SIZE/PLY RATING/PART NUMBER 8.50-10/8/850C81T2 9.25-12/8/922C86T1 10.50-16/10/106C06T1 17.5x6.25-6/8/175K88-1 24.5x8.5/10/248F03T1 24x7.7/8/247F86T1 26x6.6/10/266F02T1 32x10.75-14/12/321R26T1 33.5x10.75-15/12/331K26-1 34x10.75-16/10.50-16/10/347K06T1 24x7.7/16/247F63T2 32x11.50/15/12/321K23T1 34x10.75-16/10.50-16/12/347K28T1 39x13/16/393F62T2 40x14/16/404F63T2 40x14/24/404F42T2 H40x14.5-19/24/419K42T1 H40x14.5-19/26/419K62T1 41x15.0-18/24/415K42-3 42x15/22/425F23T2 42x15/24/425F43T1 46x16/28/466F82T6 46x16/28/466F82T4, 466F82T3, 466F82GC 46x16/30/466F02T3, 466F02T2, 466F02GA 49x17/28/497F82T2 49x17/30/497F02T3 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|----|-----------|--|
| | | | | 49x17/32/497F22T2, 49F22T3 49x17/34/497F42T1 49x19.0-20/32/491K29T1, 491K29T2, 491K29T3 49x19.0-20/34/491K49T1 H49x19.0-22/32/499K29T1 50x20.0-20/32/500K22T2, 500F22T1 50x21.0-20/28/501K83T2 50x21.0-20/30/501K02T2, 501K03T2 |
| TSO-C62c *F | Goodyear S.A. Colmar-Berg Grand Duchy of Luxembourg | EU | | TIRE SIZE/PLY RATING/PART NUMBER 8.50-10/8/850C81G5, 850T81G2 8.50-10/10/850T01G2 9.25-12/8/922T86G1 9.25-12/28x9.00-12/8/982T86G1 9.25-12/28x9.00-12/12/982T26G1 12.50-16/12/126T26G1 15.00-16/16/156C66G1 18x5.5/8/185F88G2 18x5.5/10/185F03G2 22x5.75-12/8/226K88G4 22x5.75-12/10/226K08G2 23x7.25-10/6/235R66G1 24.5x8.5/10/248F03G2 24x7.7/8/247F86G1, G2 24x7.7/10/247F03G1, 247F02G1, 247F03G2 24x7.7/6/247F68G1 24x7.7/12/247F28G1 24x7.7/16/247F62G1, 247F63G2, G3, 247F62G2 24x7.7/16/247F63G3 24.5x8.5/10/248F03G1, 248F03G2 25.5x8.75-10/10/259K01G1 25.5x8.75-10/12/259K28G2 26x6.6/12/266F22G1 26x6.6/10/266F02G5, 266F02G6 26x6.6/12/266F22G1, 266F23G1 26x6.6/14/266F43G3 26x7.75-13/10/267R03G1 26.5x8.0R13/12/PT0375 30x8/8/12/308G22G1, 308F22G1 30x8.8/16/309F62G1 31x10.75-14/20/310K07G1 32x8/8R16/328Q08G4 32x8.8/10/328F08G1, G2, 328008G1, G2, G3 32x8.8/12/328G28G1 32x11.50/12/321K23G2 32x11.50-15/12/321K23G2 34x10.75-16/12/347K28G1 34x10.75-16/10.50-16/10/347K08G1 34x10.75/R16/347K08G1, 347K28G1, 347Q28G4 34x10.75/12/347K26G1, 347Q28G1, G2, G3 34x11/22/341F22G3 H34x10.0/R16/346Q48G1, G2, G3 H34x10.0-16/14/340K48G1 35x9.00-17/16/359R63G1 35x9.00-17/18/359R83G1 36x10.75-16.5/16/361R66G1 37x11.75-16/10/371K08G2 37x11.75-16/12/371K28G1 37x13.0-16/26/373K62G1 39x13/14/393F48G1 39x13/14/393F43G1 39x13/16/393F63G3, 393F62G5 40x12/20/402F03G1 40x14/16/404F63G4 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|----------------------------|------|-----------|--|
| | | | | 40x14/20/404F02G8 |
| | | | | 40x14/22/404F22G7 |
| | | | | 40x14/24/404F43G4, 404F43G5, 404F43G6, 404F42G5 |
| | | | | 40x14/28/404F82G2, 404F82G3 |
| | | | | H40x14.0/18/409K82G1 |
| | | | | H40x14.0-19/20/409K02G1, 409K82G1A |
| | | | | H40x14.5-19/24/419K42G1, G3 |
| | | | | H40x14.5-19/26/419K62G1 |
| | | | | 40x15.00-16/26/405K69G4 |
| | | | | 40x15.5-16/26/405K69G4 |
| | | | | 40x15.5-16/28/405K89G1 |
| | | | | 40x40/16/404F63G4 |
| | | | | 41x15.0-18/22/415K22G6, 415K22G7 |
| | | | | 41x15.0-18/24/415K42G5, G6 |
| | | | | 44.5x16.5-18/30/456F02G2, 456F02G3 |
| | | | | 44.5x16.5-18/32/456F22G1 |
| | | | | H44.5x16.5-20/24/446K42G1 |
| | | | | H44.5x16.5-20/26/446K62G1, 446K62G2 |
| | | | | H44.5x16.5-20/28/446K82G1 |
| | | | | H44.5x16.5-20/446K62G3 |
| | | | | H44.5x16.5-20/446K82G2 |
| | | | | 46x16/20/466F12G1 |
| | | | | 46x16/26/466F62G6 |
| | | | | 46x16/28/466F02G8, 466F82GA, 466F82GB, 466F82GC, 466F82G3 |
| | | | | 46x16/30/466F02G8, 466F02G9, 466F02GA |
| | | | | 46x16/32/466F22G1 |
| | | | | 46x17.0R20/28/467Q82G1 |
| | | | | 49x17/26/497F62G1 |
| | | | | 49x17/28/497F82G3, 497F82G4 |
| | | | | 49x17/30/487F22G3, 497F02G9 |
| | | | | 49x17/32/487F22G3, 497F22G3, 497F22G1, 497F22G4, 497F22G5 |
| | | | | 49x17/34/497F42G1 |
| | | | | 49x19.0-20/32/491K29G2, G4, G3 |
| | | | | 49x19.0-20/34/491K45G1, G2, G3 |
| | | | | 50x21.0-20/28/501K83G3 |
| | | | | 50x21.0-20/30/501F02G1 |
| | | | | 50x21.0-20/30/501K03G4 |
| | | | | 52x20.5-20/36/521K62G1, G2 |
| | | | | 52x20.5-23/28/520K89G3 |
| | | | | 52x20.5-23/30/520K09G1 |
| TSO-C62c | Goodyear Tire & Rubber Co. | CE-C | | 5.00-4/14/504T41-1 |
| | 1210 Massilon Road | | | 5.00-5/4/505C41-6 |
| | Akron, OH 44316 | | | 5.00-5/6/505C61-8, -9 |
| | | | | 5.00-5/10/505C01-2 |
| | | | | 6.00-6.5/4/607C41-1 |
| | | | | 6.00-6/8/606T86-1, 606T86-2 |
| | | | | 6.00-6/8/606C86-3 |
| | | | | 6.00-6/4/606C41-E |
| | | | | 6.00-6/6/606C61-A |
| | | | | 6.50-8/8/658C86-2, 658T86-2 |
| | | | | 6.50-10/8/650C81-5 |
| | | | | 8.00-6/6/806C61-4 |
| | | | | 8.00-6/8/806C81-1 |
| | | | | 8.50-6/6/856C61-3 |
| | | | | 8.50-10/6/805C61-2 |
| | | | | 9.00-6/10/906C06-1, 906T06-1, -2 |
| | | | | H13x13.0-12/20/313K02-1 |
| | | | | 14.5x5.5-6/0/145K13-1 |
| | | | | 14.5x5.5-6/12/145K21-2 |
| | | | | 14.5x5.5-6/14/145K41-1 |
| | | | | 15x6.00-6/6/156E66-1, -2 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|---|
| | | | | 16x4.4/4/164F43-2 |
| | | | | 16x4.4/6/164F63-1 |
| | | | | 16x4.4/6/164F63-2 |
| | | | | 17.5x5.75-8/14/178K43-1 |
| | | | | 17.5x5.75-8/12/178K23-3, -4, -5 |
| | | | | 17.5x6.25-6/8/175K88-2, -3 |
| | | | | 18x4.4/10/184F03-2, 184F10-2, 184F13-3, -4, 184F08-1 |
| | | | | 18x4.4/12/184F23-2 |
| | | | | 18x4.25-10/6/181K63-2 |
| | | | | 18x4.4/10/184F13-5 |
| | | | | 18x5.5/8/185F81-1, 185F88-4, -6 |
| | | | | 18x5.5/10/185F03-3, -4 |
| | | | | 18x5.75-8/8/186K88-5 |
| | | | | 19.5x6.75-8/10/196K08-3, 196K08-4, 196K08-5, 196K08-7 |
| | | | | H19.5x6.75-10/8/197K86-1 |
| | | | | H19.5x6.75-10/6/197K66-1 |
| | | | | 21x7.25-10/8/217F83-3 |
| | | | | 21x7.25-10/10/217F03-2 |
| | | | | 22x5.75-12/8/226K88-5, -6, -4 |
| | | | | 22x6.75-10/10/265K06-1 |
| | | | | 22x5.75-12/10/226K08-3 |
| | | | | 22x5.75-12/12/226K23-2 |
| | | | | 22x6.75-10/8/265F86-4 |
| | | | | 22x8.00-8/6/128K61-1 |
| | | | | 22x8.00-8/8/228K81-1 |
| | | | | 22x8.00-10/10/220K08-3 |
| | | | | 22x8.0-10/12/220K28-1 |
| | | | | 23x7.0-12/10/237K03-2 |
| | | | | 24x7.7/12/247K282, 247K283, 247K281, 247F26-1 |
| | | | | 23x7.00-12/237K23-1 |
| | | | | 24x7.7/14/8247P48-1 |
| | | | | 24x7.7/14/8247F48-1 |
| | | | | 24x7.7/16/247F62-1 |
| | | | | 24x7.7/16/247F63-2, -3 |
| | | | | B24x9.5-10.5/18/249K83-2, -3 |
| | | | | 25.75x6.75-14/14/256K43-1, -2 |
| | | | | 26x6.6/10/266F08-4, 266F08-5, 266F02-4, -3, -5, -6 |
| | | | | 26x6.6/14/266F43-2 |
| | | | | 26x6.6/12/266F22-3 |
| | | | | 26x6.6R14/10/266Q08-1 |
| | | | | 26x6.75-14/14/265K48-3 |
| | | | | 26x6.6R14/12/266Q22-1, -2 |
| | | | | 26x6.75-14/16/265K68-2 |
| | | | | 27x7.75-15/10/277K02-1 |
| | | | | 27x7.75-15/12/275K22-1 |
| | | | | 30x9.0R15/12/309Q26-1, -2 |
| | | | | 31x9.75-13/12/319K26-1 |
| | | | | 32x11.50-15/12/321K23-4, -6, 321K22-1 |
| | | | | 33.5x10.75-15/12/331K26-2 |
| | | | | 34x9.25-16/18/348F83-2 |
| | | | | 34x9.25-16/16/348F63-3 |
| | | | | 34x10.75-16/10.50-16/10/347K08T1 |
| | | | | 34x10.75-16/10.50-16/12/347K28-1, -2 |
| | | | | 34x11/22/341F22-2 |
| | | | | 36x11/22/361F22-2 |
| | | | | 37x13.0-16/26/373K62-2, -3 |
| | | | | 37x14.0-14/24/374F42-4 |
| | | | | H37x14.0-15/22/375K22-1 |
| | | | | 39x13/14/393F43-1 |
| | | | | 39x13/16/393F63-2 |
| | | | | 39x13/22/393F28-1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|----|-----------|--|
| | | | | 40x14/24/404F42-6, -8, 404F43-6 H40x14.5-19/22/419K22-1, -2 H40x14.5-19/24/419K42-1, 419K42-2, 419K43-1 H40x14.0-19/20/409K02-1 H40x14.5-19/26/419K62-1, -2 40x14/16/404F63-1 H40x15.5-16/26/405K69-3 40x15.5-16/28/405K89-2 41x15.0-18/24/415K42-3 H42x16.0-19/24/426K42-1 H42x16.0-19/26/426K62-1 44x16/30/446F02-4, 466F03-2 44.5x16.5-18/30/456F02-3, -4 H44.5x16.5-20/24/446K42-2 H44.5x16.5-20/26/446K62-2 H44.5x16.5-20/28/446K82-1 H45x17.0-20/26/457K62-1 46x16/28/466F82-6, 466F83-5, 466F82T5 46x16/30/466F02-4, -5, 466F03-4, 466F02T4, T5, 466F0253 H46x18.0-2/28/468K821, -2 H46x18.0-20/32/468K22-1 46x18.0-20/26/468K62-1, -2, -3 49x17/28/497F83-8 49x17/30/497F02-5, 497F03-5, 497F03-6 49x17/30/497F02T4, T5 49x17/32/497F22-1, -3, 497F22T4, 497F29-1 49x19.0-20/32/491K29-2, 491K25S1, 491K29-3 49x19.0-20/34/491K49-1, 491K4552 H49x19.0-22/32PR/499K29-1 49x19.0-20/34/491K49T3, T2 50x20.0-20/32/500K22-7, -8 50x20.0-20/34/500K42-2, -3, -4 50x21.0-20/30/501K02T3 50x21.0-20/30/501K02-1, 501K03-2 52x20.5-20/34/521K42-2 52x20.5-20/36/521K62-3 52x20.5-23/30/520K09-2, -5, -6 H54x21.0-24/34/541K49-1 H54x21.0-24/34/549K49-1 56x20.0-20/24/560F43-1, 560F4352 380x150/15x16.00-5/6/385M61-1 450x190.5/10/459M08-2 450x190-5/2250LR/459M08-1 670x210-12/10/670M06-1 |
| TSO-C62c | Goodyear - Danville Goodyear Tire & Rubber Co. Danville, VA 24541 | NE | | 5.00-4/14/504T41-2 6.50-10/12/650T26-2 7.50-14/12/754C26-2 8.50-10/14/850G4A-1 16x4.4/8/164F86-1 17.5x6.25-6/8/175K88-3 17.5x6.25-6/8/175K88-3 18x4.4/12/184F23-3 18x5.5/10/185F03-5 19.5x6.75-8/10/196K08-8 23x7.00-12/12/237K23-2 24x7.25-12/10/247R08-2 24x7.7/14/247F48-2 26x6.6/10/266F03-2 27.7.75-15/10/275K02-1 H29x9.0-15/16/299K63-1, 299K62-1 31x9.75-14/12/318K28-1 H31x13.0-12/20/313K02-1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|---|
| | | | | 32x8.8R16/10/328Q08-3 32x8.8R16/10/328Q08-1, -2 39x13/22/393F28-1 40x14/24/404F42-A 40.5x15.5-16/28/406K89-1 H40x14.5-19/24/419K42-3 46x16/30/466F02-6, -7 49x17/30/497F02-7 49x19.0-20/34/491K49-2 50x20.0-20/34/500K42-6 54x21.0-23/36/542K69-1 54x21.0-23/32/542K29-1 H54x21.0-24/36/541K69-1 H54x21.0-24/36/541K49-1A |
| TSO-C62c *F | Goodyear Tire & Rubber Co. Aircraft Tire Development Uitenhage, South Africa | EU | | 24x7.7/14/247F42S3 24x7.7/16/247F62S3 32x11.50-15/12/321K23S2 39x13/16/393F62S3 40x14/16/404F63S1, 404F6S2 40x14/24/404F49S1 H40x14.5-19/24/419K42S1 46x16/28/466F82S4 46x16/30/466F02S2 49x17/32/497F29S3 49x17/34/497F49S2 49x19.0-20/34/491K45S1 56x20.0-20/24/560F43S1 |
| TSO-C62c *F | Goodyear Tire & Rubber Co. (Great Britain) Ltd. Wolverhampton, England | EU | | Tire Size/Ply Rating/Part Number 6.50-10/10/650G01E1 9.00-6/10/906T06E1 37x13.0-16/20/273K03E1 37x13.0-16/26/373K62E2 39x13/16/393F62E2, 393F62E3 40x12/20/402F03E1, 402F03E2 46x16/28/466F02E4 46x16/30/466F82E4 46x16/32/466F22E1 50x20.0/32/500K22E3 50x20.0-20/34/500K42E1 50x20.0-20/36/500K62E1 52x20.5-20/34/521K42E2 52x20.5-20/36/521K62E1 56x20.0-20/24/560F43E1, 560F43E2 |
| TSO-C62c *F | Instituto de Fomento e Coordenacao Industrial 12.100 Sao Jose dos Campos Sao Paulo, Brazil | CE-A | | 40x14/404F4282 40x15.5-16/405K89E1 49x17/497F8383 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|--|
| TSO-C62c *F | Kleber Colombes o France Division of Aerospatiale P.O. Box 9-16 6, Avenue Kleber 75784 Paris, France | EU | | TIRE SIZE/PLY RATING/PART NUMBER 24x7.7/16/081443 26x6.6/10/081040, 081041 26x6.6/12/081120 32x11.5-15/12/084205 36x11/22/083091 37x13.0-16/26/083096 40x14/22/083792 40x14/24/083812, 083813, 083832, 083833 40x14/28/083820, 083841 41x15.0-18/22/084865, 084866 44x16/30/084427 44.5x16.5-18/30/084891 H44,5x16,5-20/26/084889 46x16/28/084740, 084742 46x16/28/084702 46x16/30/084736, 084738 49x17/28/084884 49x17/32/084877, 084887 49x17/30/084871, 084878, 084888 49x19.0-20/32/084892, 085051 49x19.0-20/34/084052 50x20.0-20/34/084893 50x21.0-20/30/084904 52x20.5-20/36/085531 52x20.5-23/26/085563 52x20.5-23/28/085564, 085567 52x20.5-23/30/085565 |
| TSO-C62c | McCreary Tire & Rubber Co. 16 West Washington Street Indiana, PA 15701 | NE | | 5.00-5/4/30841 5.00-5/6/31232, 30842 6.00-6/4/30843 6.00-6/6/30844 6.00-6/6/31234 6.00-6/8/30845 6.50-8/6 6.50-8/8 6.50-10/6/30853 6.50-10/8/30854, 31233 6.50-10/10/30855 6.50-10/10/31245 6.50-10/12/31249 7.00-6/8/30847 7.00-6/6/30846 7.00-6/6/31236 8.50-10/6/30856 8.50-10/8/30857, 31247 8.50-10/10/31248 29x11.0-10/4/31034 29x11.0-10/10/31042 30847 30846 30848 30849 30860 31239 31236 |
| TSO-C62c | Michelin Aircraft Tire Corp. 150 Springside Drive P.O. Box 5510 Akron, OH 44313-5510 | CE-C | | 6.00-6/6PR/M61-3160 6.00-6/8PR/M61-3170 11.00-12/8PR/M21-3543 11.00-12/10PR/M21-3551 34x10.75-16/12PR/M28-7322 46x16/30PR/M39-7853 46x16/28PR/M39-7848 49x19-20/32PR/M20-8700 H49x19.0-22/32/M20-8053 |
| TSO-C62c | Michelin Aircraft Tire | CE-C | | 6.50-8/6PR/061-337-1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|----|-----------|--|
| | Corp. Norwood, NC | | | 6.50-8/6PR/021-337-2 6.50-10/6PR/061-344-1 6.50-10/6PR/021-344-2 7.00-6/6PR/061-320-1 8.00-6/6PR/061-323-1 8.00-6/6PR/076-323-0 8.00-6/8PR/076-328-0 17.5x6.25-6/8PR/028-327 17.5x6.25-6/8PR/021-327 22/7.75-10/8PR/028-526 24x7.7/14PR/028-675-3 24x7.7/14PR/038-675-2 25.75x6.75-14/14PR/033-637 27x7.75-15/12PR/039-688-1 30x8.8/16PR/039-539-0 33.5x10.75-15/12PR/028-717-1 34x10.75-16/12PR/028-732-3 46x16/30PR/039-785-4 49x17/28PR/033-788-2 49x17/32PR/020-791-0 H49x19.0-22/32PR/020-805-3 5.00-5/4PR/076-308-0 5.00-5/6PR/076-309-0 5.00-5/10PR/083-311-0 5.00-5/10PR/061-311-1, 076-311-0 6.00-6/4PR/076-315-0 6.00-6/6PR/076-316-0 6.00-6/8PR/076-317-0 6.50-8/6PR/076-337-0 6.50-8/8PR/076-338-0 6.50-10/6PR/076-344-0 6.50-10/8PR/076-345-0 6.50-10/10PR/076-356-0 7.00-6/6PR/076-320-0 7.00-6/8PR/076-321-0 8.00-6/6PR/083-323-0 8.00-6/8PR/083-328-0 8.50-10/8PR/076-349-0 8.50-10/10PR/076-350-0 15x6.0-6/6PR/076-501-0 24x7.7/12PR/028-673-0 H31x13.0-12/20PR/032-838-1 39x13/14PR/033-754-1 39x13/16PR/039-755-1 40x14/28PR/033-771-1 40x15.5-16/28PR/020-848-0 |
| TSO-C62c | Michelin Aircraft Tire Corp. CE-C 1250 N. Cleveland-Massillon Rd. P.O. Box 5501 Akron, OH 44312-0501 | | | 11.00-12/8PR/M21-3542 11.00-12/10PR/M21-3550 24.5x8.5-10/10PR/M33-6410 24x7.7/16PR/M33-6771 26x6.6/10PR/M39-6572 28x9.0-12/8PR/M28-6930 32x10.75-14/12PR/M21-7090 34x10.75-16/10PR/M28-7291 39x13/16PR/M39-7550 40x14/16PR/M33-8060 40x14/24PR/M39-7692 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|---|
| | | | | 46x16/30PR/M39-7853 49x17/30PR/M39-7892 49x17/32PR/M32-7911 49x19-20/34PR/M20-8730 56x20-20/24PR/M38-8810 |
| TSO-C62c *F | Michelin Cy Usines de Bourges 3 Place A. Dieu B.P. 27 18230 St. Doulchard Bourges, France | EU | | 46x17-20/M01101 29x7.7-15/M02502 17.5x5.75/8/M02401 |
| TSO-C62c *F | Michelin C.E.R. Ladoux EDA 63040 Clermont Ferrand Cedex, France | EU | | 14.5x5.5/R6/M02102 15.5x7.5/R8/M02401 26x6.6/R14/M01301 29x7.7/R15/M02502, M06201 30x8.8/R15/M04201, M08201 32x8.8/16/M07901, M07902 40x14/R16/M01201, M11701, M12701 45x16/R20/M02701, M05701 46x17.0/R20/M01102 49x17.0/R20/M05301 435x190/R5/M09601 915x300/R16/M11801 1050x395/R16/M07601 1400x530/R23/M05101, M07001 |
| TSO-C62c *F | Sumitomo Rubber Ind., Ltd. 1-1, Tsutsui-cho, 1-Chrome Chuo-ku Kobe City Hyogo Prefecture, Japan | NM-L | | TIRE SIZE/PLY RATING/PART NUMBER 24.5x8.5-10-DR19621T 34x10.75-16 DR0226 H37x14.0-15/22/DR23221T H37x14.0-15/22/DR23222T H37x14.0-15/22/DR23222T 30x8.8R15/SR11261T 40x14/24/SR12654T 40x15.5-16/26/DR21524T 40x15.5-16/28/SR21525T 41x15.0-18/22/DR21328T H44.5x16.5-20/24/DR22822T H45x17.0-20/26/DR23421T 46x16/28/DR11652T 46x16/30/DR11650T 46x17R20/SR11252T 46x18.0-20/26/DR23521T 46x18.0-20/26/DR23521T 46x16/28/SR11653T H46x180.0-20/28/SR23522T 49x17/28/DR15344T 49x17/30/DR15343T 49x17/32/DR15341T, DR15346T 49x17/32/DR15346T, SR15347T, SR15348T, SR15349T 49x19.0-20/34/DR22725T 49x19.0-20/32/DR22724T 49x19.0-20/34/DR22725T H49x19.0-22/24/SR23634T H49x19.0-22/32/SR23632T, SR23633T 50x20-20/32/DR17135T, DR17136T 56x20-20/DR22220T H54x21.0-24/34/SR54211T |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|---|--|
| TSO-C62c *F | Sumitomo Rubber Ind., Ltd. 1-1, Tsutui-cho, 1-chome, Chuo-ku, Kobe P.O. Box 345 Kobe Port Kobe, 651-01 Japan | NM-L | | H37x14.0-15/24PR/SR23224T H46x18.0-20/32PR/SR23523T H49x19.0-22/32PR/SR23631T |
| TSO-C62c *F | Yokohama Rubber Co., Ltd. 36-11, Shimbashi 5 Chome Minato-ku Tokyo 105, Japan | NM-L | | 24x7.7/16/S0092 32x11.5-15/12/S0020A 36x11/22/S0056A H37x14.0-15/22/S0077 40x14/24/S0095 H45x17.0-20/26/S0078 46x16/30/S0094 46x16/28/S0093 H46x18.0-20/26/S0103 49x17/28/S0062A 49x17/30/S0089 49x17/32/S0090 49x19.0-20/32/S0101 50x20-20/32/S0074 50x21.0-20/30/S0102 |
| TSO-C62c *F | Yokohama Rubber Co. Ltd 2-1, Oiwake Hiratsuka-shi Kanagawa-Ken 254 Japan | NM-L | | TIRE SIZE/PLY RATING/PART NUMBER 49X17/32/S0112 H49X19.0-22/32/S0110 |
| TSO-C62d *F | Dunlop Ltd Fort Dunlop Birmingham United Kingdom | EU | AIRCRAFT TIRES | 5.00-5/DR5872 6.00-6/DR7729 6.00-6/DR7730 6.00-6/DR7731 H54X21/DR26621T H54X21.0-24/DR26621T |
| TSO-C62d | The Goodyear Tire & Rubber Co. Danville, Va | NE | | H44.5x16.5-20/28PR/446K82-2 |
| TSO-C63 | Bendix Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | AIRBORNE WEATHER RADAR EQUIPMENT | RDR-1ED() RDR-1E() RDR-1D() RDR-1; ANT-1() CON-1() PPI-1() RDR-1() SHK-1() SYN-1() |
| TSO-C63 | Bendix Radio Division Baltimore, MD 21233 | NE | | ANT-1() ANT-1S CON-1() PPI-1() RDR-1() RDR-1D SKH-1() SYN-1() RDR-1ED RT-101B-28 |
| TSO-C63 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 561G-4 WP-103 WP-103G WP-103S WP-103() |
| TSO-C63 | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Business & Commuter Avn. Systems Division 5353 W. Bell Road Glendale, AZ 85308 | NM-L | | WC-650:7008471-201 thru 204 WC-708A:M1585311-403 WC-708A:M1585312-403 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|---|---|--|
| TSO-C63 | King Radio Corporation 400 N. Rogers Rd. Olathe, KS 66061 | CE-W | | KT44() | K1240() | |
| TSO-C63 | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVQ-20 | AVQ-55 | |
| TSO-C63 | Sperry Piedmont Co. Div. of Sperry Rand Corp. Charlottesville, VA 22901 | NE | | AN/APN-59B | | |
| TSO-C63a | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | AIRBORNE WEATHER RADAR EQUIPMENT | PPI-1M RDR-100: AT-103B() RDR-110 IN-112() RDR-1F() PPI-1L2070411() CON-1R2070412() CON-1S2070552() ANT-1T2070409() MBA-1L2070499() IU-1405A:4000837-() DME-2030 MBA-1E2070035() MBA-1G0270514() | ANT-1S() RT-101B-2B MT-104A() RT-101B-2B() AT-113() RDR-1F2070410() | IN-102A |
| TSO-C63a | Bendix Radio Division Baltimore, MD 21233 | NE | | QA-1001 MT-104A() | RDR-100 IN-102A() | AT-103B |
| TSO-C63a | Collins Radio Company 5225 "C" Ave., N.E. Cedar Rapids, IA 52406 | CE-W | | WXR-80() | | |
| TSO-C63a *F | MEL Equipment Co. Ltd. Manor Royal Crawley, Essex England | EU | | E390/564 | | |
| TSO-C63a | Sperry Flight Systems Avionics Division 8500 Balboa Blvd. Van Nuys, CA 91409 | NM-L | | AVQ-30X AVQ-85D/S PRIMUS-20WXD PRIMUS-30A PRIMUS-50WXD PRIMUS-100 PRIMUS-300SL PRIMUS-500 | AVQ-30X(X) AVQ-95 PRIMUS-21WXD PRIMUS-31WXD PRIMUS-90 PRIMUS-200 PRIMUS-400SL | AVQ-47 PRIMUS-10 PRIMUS-30WXD PRIMUS-40WXD PRIMUS-90WXD PRIMUS-300 PRIMUS-400WXD |
| | | | | Weatherscout I Weatherscout II | | |
| TSO-C63b | AIL Division Cutler-Hammer Deer Park, NY 11729 | NE | AIRBORNE WEATHER RADAR EQUIPMENT | AN/APS-128-() | | |
| TSO-C63b | Allied/Bendix Aerospace P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | | CP-123-(), 809529 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------------|---|------|-----------|--|----------|------------|---------|--|----------------|--|-----------------|---------------------|---------|--|----------------|--|------------------|---------------------|-------------|--|---------|--|-----------------|---------------------|----------------|--|----------|--|-------------|--------------|---------|--|------------------|--------------------|---------|--|-------------------|-------------------------|---------------------|--|------------------|---------------------|------------------|---------------------|---------|--|------------------|---------------------|---------|--|------------------|---------------------|---------|--|------------------|---------------------|---------|--|------------------|--------------------|
| TSO-C63b | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | AA-1212A AA-1215A AA-1218A AA-4510A AA-4512A AA-4518A AA-5512A AA-5518A ANT-1T ART-161A AT-133A AT-143A 10" AT-143A 12" CC-2024() DA-1203A DAA-4B COM-1TS():3614657-() IN-152A IN-1102A IN-1202A IN-1302A IN-1402A IN-2021A IN-2022A IN-2025 IN-2026A IN-2027A IU-2023() MBA-4C MS-1305A PPI-1U PPI-1N PPI-1P PPI-1T RDR-1FB:8055393-() RDR-1FB RDR-4A RDR-130 RDR-140 RDR-150 RDR-230HP RDR-1100 RDR-1150HP RDR-1150(XL) RDR-1200 RDR-1300 RDR-1300B RDR-1300C RDR-1400B RDR-1300C:MS-1305A, RT-1301C, IU-1308A RDR-1400:IN-20258 RDR-1500:RT-1501A, IN1502B, IN1502A, DA1503A, REA-4D:3614070-0401 AA1504A, CN-1506A, IU-1507A, MT-1508A, MT-1501A RT-1201A RT-1301A RT-1401A RDS-82 RT-1301C WDR-4A:DAA-4B | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| TSO-C63b | Bendix/King Air Transport Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310 | CE-A | | IN 2025B:4001670-2511 thru -2517 RT-1401B:40000831-0105 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| TSO-C63b | Bendix/King General Aviation Avionic Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | <table border="0"> <tr> <td>King P/N</td> <td>Bendix P/N</td> </tr> <tr> <td>RS841A:</td> <td></td> </tr> <tr> <td>071-01318-0010</td> <td></td> </tr> <tr> <td>071-1318-00, 30</td> <td>3614863-8401, -8430</td> </tr> <tr> <td>RS861A:</td> <td></td> </tr> <tr> <td>071-01319-0010</td> <td></td> </tr> <tr> <td>071-1319-00, -30</td> <td>3614475-8601, -8630</td> </tr> <tr> <td>071-1319-20</td> <td></td> </tr> <tr> <td>RS181A:</td> <td></td> </tr> <tr> <td>071-1315-30, 00</td> <td>3614077-8130, -8101</td> </tr> <tr> <td>071-01315-0010</td> <td></td> </tr> <tr> <td>RS 811A:</td> <td></td> </tr> <tr> <td>071-1378-00</td> <td>0895536-8101</td> </tr> <tr> <td>CN863A:</td> <td></td> </tr> <tr> <td>071-1380-10, -11</td> <td>3614704-8610, 8611</td> </tr> <tr> <td>IN182A:</td> <td></td> </tr> <tr> <td>066-3084-10, -11,</td> <td>3614078-8210, -8211,</td> </tr> <tr> <td>3614078-8201, -8202</td> <td></td> </tr> <tr> <td>066-3084-30, -31</td> <td>3614078-8230, -8231</td> </tr> <tr> <td>066-3084-32, -33</td> <td>8095537-8101, -8102</td> </tr> <tr> <td>IN812A:</td> <td></td> </tr> <tr> <td>066-3114-00, -01</td> <td>8095537-8101, -8102</td> </tr> <tr> <td>IN842A:</td> <td></td> </tr> <tr> <td>066-3085-10, -11</td> <td>3614882-8410, -8411</td> </tr> <tr> <td>IN862A:</td> <td></td> </tr> <tr> <td>066-3086-10, -11</td> <td>3614477-8610, -8611</td> </tr> <tr> <td>IN862B:</td> <td></td> </tr> <tr> <td>066-3115-10, -11</td> <td>3614705-8610, 8611</td> </tr> </table> | King P/N | Bendix P/N | RS841A: | | 071-01318-0010 | | 071-1318-00, 30 | 3614863-8401, -8430 | RS861A: | | 071-01319-0010 | | 071-1319-00, -30 | 3614475-8601, -8630 | 071-1319-20 | | RS181A: | | 071-1315-30, 00 | 3614077-8130, -8101 | 071-01315-0010 | | RS 811A: | | 071-1378-00 | 0895536-8101 | CN863A: | | 071-1380-10, -11 | 3614704-8610, 8611 | IN182A: | | 066-3084-10, -11, | 3614078-8210, -8211, | 3614078-8201, -8202 | | 066-3084-30, -31 | 3614078-8230, -8231 | 066-3084-32, -33 | 8095537-8101, -8102 | IN812A: | | 066-3114-00, -01 | 8095537-8101, -8102 | IN842A: | | 066-3085-10, -11 | 3614882-8410, -8411 | IN862A: | | 066-3086-10, -11 | 3614477-8610, -8611 | IN862B: | | 066-3115-10, -11 | 3614705-8610, 8611 |
| King P/N | Bendix P/N | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| RS841A: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 071-01318-0010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 071-1318-00, 30 | 3614863-8401, -8430 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| RS861A: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 071-01319-0010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 071-1319-00, -30 | 3614475-8601, -8630 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 071-1319-20 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| RS181A: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 071-1315-30, 00 | 3614077-8130, -8101 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 071-01315-0010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| RS 811A: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 071-1378-00 | 0895536-8101 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| CN863A: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 071-1380-10, -11 | 3614704-8610, 8611 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| IN182A: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 066-3084-10, -11, | 3614078-8210, -8211, | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 3614078-8201, -8202 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 066-3084-30, -31 | 3614078-8230, -8231 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 066-3084-32, -33 | 8095537-8101, -8102 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| IN812A: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 066-3114-00, -01 | 8095537-8101, -8102 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| IN842A: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 066-3085-10, -11 | 3614882-8410, -8411 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| IN862A: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 066-3086-10, -11 | 3614477-8610, -8611 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| IN862B: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 066-3115-10, -11 | 3614705-8610, 8611 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| TSO-C63b | Command Systems Div. of Telephonics Corp. | NE | | AN/APS-128A() | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|--|
| | 815 Broad Hollow Road Farmingdale, NY 11735 | | | |
| TSO-C63b | Gables Engineering, Inc. P.O. Box 340880 Coral Gables, FL 33114 | CE-A | | G6207() G6226() |
| TSO-C63b | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 5353 West Bell Road Glendale, AZ 85308 | NM-L | | PRIMUS-708 WXD PRIMUS-800 WXD 150:DI-1007, DI-1008 |
| TSO-C63b | King Radio Corporation 400 N. Rogers Rd. Olathe, KS 66061 | CE-W | | KA49() KWX-40 KWX-50() KI 242-KW60 KI224 KA126 KA 116():KWX 50() KI244 KWX56:KI-244 KA126:071-1220-00/-01/-02 KA126:071-1220-03/-04/-05 KA128:071-1285-00 thru -03 KI244:066-3065-00 thru -04 KI248:066-3076-00 thru -04 |
| TSO-C63b | Rockwell International Collins Avionics Group Melbourne, FL | CE-W | | MFD-85C:622-9849-011, -012 |
| TSO-C63b | Rockwell International Collins Avionics Division 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | | ANT-310A:622-7444-001 WXR-200:622-4021-001, 622-4023-001/002, 622-2490-001, 622-2891-001/002, 622-2494-001/002, 622-2495-001/002 WXR-150: WXT-150, TMT-150, IND-150, ANT-152 ANT-212D:622-4020-001 ANT-210(): 622-2495-() EFD-85:622-6090-001/002 EFIS-86D(2) WXR-250(): 622-2490-001, -2491-001, -2499-001, -2501-001, -3338-001 WXR-250A:622-4022-001, 622-4027-001/002/ 003/004, 622-2490-001, 622-2491-001, 622-2501-001, 622-2502-001, 622-2504-001 IND-250C:622-4025-001 KFD-85A:622-7236-001/-002/-011/-012 WXR-220 WXR-270 WXR-700C WXR-700X WXI-701 WXT-250B 622-7337-001, -002 MFCP-1000A:622-7957-401 MFD-85:622-6090-001/002 MFD-85:622-6080-001/-002 MFD-85A:3/622-7236-001/-002 MFD-85A:4/622-7236-011/-012 MFD-85A:622-7236-001/-002/-011/-012 MFD-85A:622-7236-011/-012 MXP-85A:622-6092-0011/-002/-011/-012 WXP-85A:5/622-6092-011/-012 WXP-85B:5/622-6093-011/-012 WXP-85C:6/622-7338-001/-002 WXP-85D:6/622-7580-001/-002 WXP-85B:622-6093-011/-012 WXP-85A:622-6092-001/002/011/012 WXP-85B:622-6093-001/002/-011/-012 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-------------------------------------|---|
| | | | | 614E-55A (HSVD-800):622-6866-001 WXP-85C:622-7338-001/-002 WXP-85D:622-7580-001/-002 WXP-85C:622-7338-041, /-042 WXP-85D:622-7580-041, /-042 WMA-701X:622-5135-201, -202, -203 WMA-702X:622-5136-201, -202, -203 WRT-701X:622-5132-020 WXP-85A:622-6092-021, 022, 031, 032 WXP-85B:622-6093-021, 022, 031, 032 WMT-701X:622-5133-006, 007 WMI-701:622-5138-003 WXI-701:622-5128-109 WCP-701:622-5129-006 WCP-702:622-5130-006 |
| TSO-C63b | Sperry Flight Systems 8500 Balboa Boulevard P.O. Box 9028 Van Nuys, CA 91409 | NM-L | | AVQ-30X AVQ-30X(X) AVQ-47 AVQ-85 D/S AVQ-95 PRIMUS-10 PRIMUS-20WXD PRIMUS-21WXD PRIMUS-30A PRIMUS-30WXD PRIMUS-31WXD PRIMUS-40WXD PRIMUS-50WXD PRIMUS-90 PRIMUS-90WXD PRIMUS-100 PRIMUS-200 PRIMUS-300 PRIMUS-300SL PRIMUS-400SL PRIMUS-400WXD PRIMUS-500 PRIMUS-800 Weatherscout 1 Weatherscout 11 |
| TSO-C63b | Videotronics, Inc. 9119 Desoto Avenue Chatsworth, CA 91311 | NM-L | | VTA-1C |
| TSO-C63c | Allied Bendix Aerospace Bendix Air Transport Avionics Div. P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | AIRBORNE WEATHER RADAR EQUIPMENT | CN-863A:3614704-() IN-862B:3614705-() ED-102E:8095351 |
| TSO-C63c | Allied-Signal Aerospace Co. Bendix/King Air Transport Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310 | CE-A | | NC-104B:3614331-() NC-104B:3614331-1004 CP-113():3614278-1121 thru 1126 CP-123():8095296-1213 thru 1218 SG-101B:3614335-1012, -1013 |
| TSO-C63c | Bendix General Aviation Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | IN-812A:8095537-() IN-842A:3614882-() IN-1502B:8055613-() CP-103F:8095477-() RS-811A:8095536-() RS-841A:3614863-() EFS-10:CF-113() RDS-86 NC-104A:3614313-() NC-104B:3614331-() NC-105B:8095679-() SC-101B:3614335-1005 CP-103F:8095477-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|--|
| TSO-C63c | Bendix/King General Avn. Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 (Paola, KS) | CE-W | | CP 466A:071-01438-0501, 0601, 0701, 0801 CP 466B:071-01493-0501, 0601, 0701, 0801 |
| TSO-C63c | Bendix/King General Avn. Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | RS 861A:071-1319-00, 20, 30 RS 861A:071-01319-0010 CP 466A:071-01438-0301, 0401 CP 466B:071-01493-0301, 0401 KING PART NUMBER BENDIX PART NUMBER IN 842A: 066-3085-10, -11 3614882-8410, -8411 066-3085-00, -01 066-3085-30, -31 3614882-8430, -8431 IN 862A: 066-3086-10, -11 3614477-8610, -8611 066-3086-00, 01 066-3086-30, -31 3614477-8630, -8631 IN 862B: 066-3115-10, -11 3614705-8610, -8611 066-3115-01 066-3115-30, -31 3614705-8630, -8631 CN 863A: 071-1380-10, -11 3614704-8610, -8611 CP 466A:071-01438-0101, -0201 CP 466B:071-01493-0101, -0201 RS 841A: 071-1318-30 3614863-8430 |
| TSO-C63c | Collins Avionics Division 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | DU-1000:622-7484-250, -301 DU-1000A:622-8047-250, -411 DCP-1000:622-7485-201, -301 EFD-870:622-7391-101 MEM-871:622-7395-101 MEM-873:622-8009-101 MFCP-1000A:622-7957-201, -401 RTA-84X, -85X RTA-852:622-8439-001 RTA-854:622-8440-001 RTA-858:622-8441-001 RTA-842:622-9301-001 RTA-844:622-9302-001 RTA-848:622-9303-001 RTA-852L:622-9080-001 WXI-711:622-6514-102/-103/-105/ -106/-201/-203/-205/-207/ -208/-210/-410/-500 WXP-840A:622-9304-011/-012/-013/-014 WXP-850A:622-8393-001/002/003/004 WXP-850A:622-8393-011/-012/-013/-014 WXP-840B:622-9305-011/-012/-013/-014 WXP-850B:622-8394-001/002/003/004 WXP-850B:622-8394-011/-012/-013/-014 MFD-870:622-8528-002, -003, -004, -005, -006, -007, -008, -009, -010 WXA-850A:822-0053-001 WXR-840 WXI-711:622-6514-021, -006, -016, -223, -224 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|--|
| TSO-C63c | Collins Avionics Div. Rockwell International Melbourne, Fl | CE-A | | RTA-842:622-9301-001 RTA-844:622-9302-001 RTA-848:622-9303-001 RTA-852L:622-9080-001 WXP-700A:622-9905-001 WXI-711A:622-9736-223, -224 WXP-840A:622-9304-001, -002, -003, -004 WXP-840B:622-9305-001, -002, -003, -004 RTA-852:1/622-8439-001 RTA-854:1/622-8440-001 RTA-858:1/622-8441-001 1/Previously approved January 25, 1988. |
| TSO-C63c | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 5353 W. Bell Road Glendale, AZ 85038 | NM-L | | IU-410: 7607689-() MC-800: 7006921-(), 7007061-() DC-810, -811 ED-800:7003110-() ED-600:7003430-() ED-800:7003110-() EDZ-605/805 MC-800:7007062-() MG-603 MG-803 MG-800:7007062-(), 7007061-() MG-810:7007321-() MG-815, -816:7011675 MG-817 MG-820:7009289-() SC-800 SC-811 SG-600/800:7003400-() SG-610/810:7004544-() SG-705 SG-811:7004544-() SG-815, -816:7011674 SG-817 (SG)820:7007356-() PRIMUS 90(B) PRIMUS 450/650:7008470-(), 7008471-() PRIMUS 450/650:7007700-() PRIMUS 708A:MI-585306-() MI-585-307-() MI-585-308-() MI-585-311-() MI-585-312-() MI-585-309-() MI-585310-() WC-800:7006921-101, -102 WU-870:7012640-901, -902, -801, -701, -702, -601, -903, -904 WA-708A:MI585310-403, MI-585307-404, -405, -406, -410, -411, -412, -413 MI-585308-413 WC-874:7006921-415, -416 WR-700:7009330-901 WA-700:MI-585467-000 WI-700:7007700-705, -706 WC-700:7008471-701, -702, -703, -704 |
| TSO-C63c | King Radio Corporation 400 North Rogers Road Olathe, KS 66062-1212 | CE-W | | RS-861A:071-1319-20 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|--|---|---|------------------------|
| TSO-C63c | Marco Avionics Aerospace Div 2825 Laguna Canyon Road Laguna Beach, CA 92652 | NM-L | | 66-3065-00 071-1220-01 071-1220-03 071-1220-05 KWX-56 | 071-1220-00 071-1220-02 071-1220-04 | |
| TSO-C64 | Puritan-Bennett Aero Systems 111 Penn Street El Segundo, CA 90245 | NM | OXYGEN MASK ASSEMBLY, CONTINUOUS FLOW, PASSENGER (FOR AIR CARRIER AIRCRAFT) | C351-2000() 174080-() | Ser. 174006() 174081-() | |
| TSO-C64 | Puritan Equipment 10800 Pflumm Road Lenexa, KS 66211 | CE-W | | 114019 | | |
| TSO-C64 | Scott Aviation Div. of Fizzie Inter'l. 123 East Montecita Avenue Sierra Madre, CA 91024 | NM | | 289-601-() | | |
| TSO-C64 | Sierra Engineering Co. Sub. of CapTech, Inc. 123 E. Montecito Ave. Sierra Madre, CA 91024 | NM | | 289-() Ser. | 289-601-() Ser. | |
| TSO-C65 | Bendix Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33309 | CE-A | AIRBORNE DOPPLER RADAR GROUND SPEED AND/OR DRIFT ANGLE MEASURING EQUIP- MENT (FOR AIR CARRIER AIRCRAFT) | CNA-12() ANA-12() | DRA-12() MTA-12() | RTA-12() INA-12() |
| TSO-C65 | Bendix Radio Division Baltimore, MD 21204 | NE | | DRA-12() | | |
| TSO-C65 | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | DRA-12 | 37900 | 37902 |
| TSO-C65 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | 37903() | DRA-12 | |
| TSO-C65 *F | Canadian Marconi Company 2442 Trenton Ave. Montreal 301, Quebec Canada | NE | | AN/APN-147(V) CMA-650B-1 | | AN/APN-168 CMA-712 |
| TSO-C65 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 3388-1 339D-3B | 3388-1A DH-101 | 339D-() 714G-() |
| TSO-C65 *F | Decca Radar Limited Lyon Road, Walton-on-Thames Surrey, England | EU | | 72 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|----|---|--|--|--|
| TSO-C65 *F | Elliott Brothers(London)Ltd. EU Christopher Martin Road Basildon, Essex England | | | AD-560 | | |
| TSO-C65 | Singer-General Precision NE 68 Bedford Road Pleasantville, NY 10570 AND Kearfott Division 1150 McBride Ave. Little Falls, NY 07424 | | | AN/APN-153(V) 500 SKK-1000 AN/ADN-153 PC-212 | GPE-1000 | |
| TSO-C65a | Collins General Avn. Div. CE-A Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | | AIRBORNE DOPPLER RADAR GROUND SPEED AND/OR DRIFT ANGLE MEASURING EQUIP- MENT (FOR AIR CARRIER AIRCRAFT) | DME-42:622-6263-() | | |
| TSO-C65a *F | Racal Avionics Ltd EU 88 Busey Road Raynes Park London SW20 OJW United Kingdom | | | D90:810770DTTC() D90:810770DRTO() | D90:810770DDSTO() | |
| TSO-C66 | Bendix Avionics Division CE-A P. O. Box 9414 Ft. Lauderdale, FL 33310 | | AIRBORNE DISTANCE MEASURING EQUIP- MENT (FOR AIR CARRIER AIRCRAFT) | DMA-29: 3DMX-29() 6DMX-19() INA-29() | DMA-29() 4DMX-19() 8DMX-19() MSA-29() | 2DMX-29() 5DMX-29() PSA-29A |
| TSO-C66 | Bendix Radio Division NE Baltimore, MD 21204 | | | DMA-29 | | |
| TSO-C66 | Bendix Eclipse-Pioneer Div. NE Teterboro, NJ 07603 | | | 7912 190358T-C | 7913 | 1903576-() |
| TSO-C66 *F | Chelton (Electrostatics) Ltd EU Marlow Buckingham, United Kingdom | | | 10A() | | |
| TSO-C66 | Collins Radio Co. CE-W 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | | | 237Z-1 339D-3B 860E-1 614N-8 | 313N-() 349D-3B 860E-2 349D-6 | 339D-() 833A 614N-7 |
| TSO-C66 | Communications Components NM 3000 Airway Ave. Costa Mesa, CA 92626 | | | 35-5016 | EMB 10-14 | |
| TSO-C66 | Dorne and Margolin, Inc. NE 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | | | DM N18 DM N17-9 DM N17-8-3 DM N1-31-1 DM N149-2 DM N1 49-2L DM N1 50-3 DM N1 50-6 | DM N18-2 DM N17-8 DM N1-20 DM N135-2 DM N149-4 DM N1 70-2 DM N1 50-3 | DM N18-3 DM N17-8-2 DM N1-24-2 DM N149-1 DM N149-6 DM N1 50-2 DM N1 50-4 |
| TSO-C66 | ITT Federal Laboratories NE | | | AFN-3544C | AFN-3544-1 | DME-100() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|---|---|
| | 500 Washington Ave. Nutley, NJ 07110 | | | AIN-150() |
| TSO-C66 | King Radio Corporation 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KI-265() KNI-500/500L KDI-570 KDM-700 |
| TSO-C66 | NARCO Avionics Aerospace Div Div. NARCO Scientific Ind. 2825 Laguna Canyon Road Laguna Beach, CA 92652 | NM-L | | UDI-2A NAV-112 UDI-2AR NAV-114 NAV-111 |
| TSO-C66 | Radio Corp. of America Aviation Equipment Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVQ-70 AVQ-75 |
| TSO-C66 | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM | | S65-8262-3 S-2000() S65-8262-30 S65-8262-3A |
| TSO-C66 | Sperry Flight Systems Div. Sperry Rand Corp. 21111 N. 19th Ave. P.O. Box 21111 Phoenix, AZ 85036 | NM | | RD-250()Ser |
| TSO-C66 | Transco Products, Inc. 4241 Glencoe Ave. Venice, CA 90291 | NM | | 2338 |
| TSO-C66a | Aeronetics Div. of Brooks & Perkins Corp. 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-W | AIRBORNE DISTANCE MEASURING EQUIP- MENT (FOR AIR CARRIER AIRCRAFT) | 520 913() |
| TSO-C66a | Astronautics Corp. of America P.O. Box 523 Milwaukee, WI 53204 | CE-C | | 111302-4 |
| TSO-C66a | Avtech Corporation 3400 Wallingford North Seattle, WA 98103 | NM | | 6233-1-1, -1-2 |
| TSO-C66a | Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | DME-2030:DM-2031A, P/N 4000985-() IN-2032A, P/N 4000986-() AD-2034A, P/N 4000988-() CN-2011:IN-2014() DMA-37A:2041167 |
| TSO-C66a | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | 1903576-() 3809142-() 1990658-() 3809139-() |
| TSO-C66a | Bendix Navigation & Control Div. South Montrose, PA 18843 | NE | | 1903585 1903976 1925813 |
| TSO-C66a | Bendix/King Air Transport Avionics Division 2100 N.W. 62nd St. Ft. Lauderdale, FL 33309 | CE-A | | DMA-37A:2041167-(), -3706, -3707 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|-----------|--|--|---|
| TSO-C66a | Bendix/King 400 North Rogers Road Olathe, KS 66062 | CE-W | | KDM 7000B:066-1019-41, -53, -55, -61, -63, -66 KN 62A:066-01068-0000, 0001, 0002, 00003 KN 63:066-01070-0000, 0001 KDM7060:066-1093-12, 13, 20, 21, 22, 23 | | |
| TSO-C66a | Clifton Division Litton Industries Marple at Broadway Clifton Heights, PA 19038 | NE | | 59400000-() () () 59500000-() () () 66000000-() () () | | |
| TSO-C66a | Collins Avionics Div. Rockwell International 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | VIR-351 DMS-40 | CNC-23 | 339R-20 |
| TSO-C66a | Collins Avionics Division Rockwell International 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | | 225Y-1 860E-4A() ANS-31C CMS-80() CTL-30() CTL-41() CTL-90() DME-140 HCP-85 HSI-70/A IND-451 RPU-31A | 331A-10() 860E-5() ANS-31R CTL-20() CTL-31() CTL-60() CTL-91() DME-451 HCP-86 HSI-84() NCS-31R RPU-31W | 860E-4() 998K-1 CCD-806 CTL-21() CTL-40() CTL-61() DME-40() DME-700() HSI-45 HSI-85 RDMI-743() TCR-451() |
| TSO-C66a | Collins General Avn. Div. Rockwell International Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | 339F-12 339F-12C 339R-1B 462-A-1 ANS-31A GLS-350D IND-40A IND-41 IND-450() REU-84 VIR-315 | 339F-12A 339F-12D 339R-18 639U-1 ANS-31R HCP-85 IND-40B IND-41A IND-451() REU-84A VIR-350 | 339F-12B 339F-12K 339R-19 889P-1 GLS-350 IND-40 IND-40C IND-41C NCS-31A TCR-451() |
| TSO-C66a | Collins Radio Group Rockwell International 5225 "C" Avenue, NE Cedar Rapids, IA 52406 | CE-W | | 462A-1() | 462B-1() | 639U-1 |
| TSO-C66a | Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52498 | CE-W | | 339F-18()DME IND-450() IND-40() | IND-451()DME IND-41() | TCR-451() |
| TSO-C66a | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 339 F-8 B 339F-12 ANS-31 913Y-1 339R-8 339R-1 | 860E-3 390R-20 NCS-31 339R-2 339R-16 | 331A-9G DME-40 899P-1 339R-3 339R-17 |
| TSO-C66a | Colt Electronics Company 137 West Ninth Avenue North Kansas City, MO 64116 | CE-W | | CD400 | | |
| TSO-C66a | Comant Industries, Inc. 12920 Park Street | NM | | CI 100() | CI 105 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|--|
| | Santa Fe Springs, CA 90670 | | | |
| TSO-C66a | Dayton-Granger, Inc. West Coast Division 3000 Airway Avenue Costa Mesa, CA 92636 | NM | | L10-16 35-5018 L10-216() |
| TSO-C66a | Dorne and Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | AT-741A DM N1-7 DM N1-24 DM N1-29 DM N149-3L DM N1-70-1 DM N152-1 DM N152-2 |
| TSO-C66a | EDO-Aire Div. of EDO Corporation 216 Passaic Avenue Fairfield, NJ 07006 | NE | | CD888 CD-888(A) RT-888 RT-888() |
| TSO-C66a | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th Ave. Phoenix, AZ 85027 | NM | | RD350 Ser. DD-390C 2588654()Ser. 2592528-901 2594625-()Ser. |
| TSO-C66a | In-Flight Devices Corp. 6601 Huntley Rd. Columbus, OH 43229 | CE-C | | 210DME |
| TSO-C66a | King Radio Corp. 400 N. Rogers Rd. P.O. Box 106 Olathe, KS 66061 | CE-W | | KA-41() KA-43() KN 65() KD1-571() KDM-705() KD1-5700() KD1-5710() DKM-7000() KA 58 KDM 705A KI 266 KDA 699 KI 267:066-3052-00 KDM 7000B:066-1019-21, -22, -23, -24, -31, -32, -33, -34 KDM 706:066-1066-02 KA60-() KN62A:066-1068-00, -01 KN 63 KD1-572 KD1-573 KD1-574 KTU709 KDA689 KPI553A:KPN 066-3045-() KRT 707:066-1073-02 |
| TSO-C66a *F | L.M.T. Le Materiel Telephonique 46, Quai de Boulogne 92 Boulogne-Billancourt France | EU | | 35748 |
| TSO-C66a | NARCO Avionics Aerospace Div 2825 Laguna Canyon Road Laguna Beach, CA 92652 | NM-L | | DME 195 DME 190 NAV 121 NAV 122() NAV 124() |
| TSO-C66a | Northern Precision Lab, Inc. 11 Madison Road P.O. Box 1016 Fairfield, NJ 07006 | NE | | 100-3: 801248-2 100-5: 801196-2 801401-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|---|------|---|---|--|--|
| TSO-C66a | Pacific Electro Dynamics, Inc. 14220 S.E. Eastgate Way Bellevue, WA 98007 | NM | | 499-() | | |
| TSO-C66a | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM | | 665-5366() | 665-8280-(3) | |
| TSO-C66a | Sierra Research Corp. 247 Cuyuga Rd. Buffalo, NY 14225 | NE | | 7315-0050-1 | | |
| TSO-C66a | Sigma Tek, Inc. 17621 N. Black Canyon Hwy. Phoenix, AZ 85023 | NM | | 476A 1077A | 477A 1077B | 876A |
| TSO-C66a | Sperry Flight Systems Avionics Division 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVQ-30X AVQ-85D/S PRIMUS-20WXD PRIMUS-30WXD PRIMUS-50WXD PRIMUS-100 PRIMUS-300SL PRIMUS-500 Weatherscout I | AVQ-30X(X) AVQ-95 PRIMUS-21WXD PRIMUS-31WXD PRIMUS-90 PRIMUS-200 PRIMUS-400SL PRIMUS-500 Weatherscout II | AVQ-47 PRIMUS-10 PRIMUS-30A PRIMUS-40WXD PRIMUS-90WXD PRIMUS-300 PRIMUS-400WXD |
| TSO-C66a | Trivec-Avant Corporation 17351 Jamestown Lane Huntington Beach, CA 92647 | NM | | 56-80-() 56-80-01 56-80-05 | | |
| TSO-C66b | Aeronetics 2100 Touhy Avenue Elk Grove Village, IL 60007 | CE-C | DISTANCE MEASURING EQUIPMENT OPERATING WITHIN RADIO FREQ. RANGE 960-1215 MEGA HERTZ | BD1-303A:5203030() FKU-803A:5208030() MCU-804A:5208040() | | |
| TSO-C66b | Aeronetics Div. of AAR Brooks & Perkins Corp. 455 Kehoe Blvd. Carol Stream, IL 60188 | CE-C | | 520-3030() | HS1-4X1X | 520-2010-() |
| | | | | 421C:520-4212-001, 520-4212-002, 520-4212-003, 520-4212-004 421D:520-4213-001, 520-4213-002, 520-4213-003, 520-4213-004, 520-4213-005 431C:520-4312-001, 520-4312-002, 520-4312-003, 520-4312-004 431D:520-4313-001, 520-4313-002, 520-4313-003, 520-4313-004 DCU-201A:520-2010() DCU-201A-1():520-2010-003, -004 HS1-423A:520-4230-()() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|---|
| TSO-C66b | Bendix General Aviation Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | DRS-44A DME-44A:DM-441A, SD-442A EFS-10 CAD-31:6228332-001 CD-462A:3614024-() CP-103F:8095477() DMS-44A:DM-441A, SD-442A, DM-441B NC-104A:3614313-() NC-104B:3614331-() NC-105B:8095679-() NM-461A:3614023-() NM-461B:3614337-() SG-101A:3614311-1004 SG-101B:3614335-1004, -1005 |
| TSO-C66b | Bendix/King Air Transport Avionics Div. 2100 N.W. 62nd Street Fort Lauderdale, FL 33309 | CE-A | | SG-101B:3614335-1012, -1013 |
| TSO-C66b | Bendix Aerospace 2150 Northwest 62nd Street P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | | ED-102E:8095351 |
| TSO-C66b | Bendix/King General Avn Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | KING PART NUMBER BENDIX PART NO. DM 441A DME:066-1106-00 3614018-4401 DM 441B DMD:066-1107-00 3614019-4401 KN40:066-01130-0501, -0601, -0701, -0801 |
| TSO-C66b | Cessna Aircraft Co. ARC Avionics Div. Rockaway Valley Road P.O. Box 150 Boonton, NJ 07005 | NE | | 1077c |
| TSO-C66b | Collins General Avn. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | CTL-32:622-6521-() IND-42A, IND-42B, IND-42C DDA-42 CTL-32A:622-8738-() DME-442:622-7309() DME-42:622-6263-() DME-42:622-6263-003 DME-42:622-6263-002 DME-42:622-6263-001 RTU-870:622-7356-001 |
| TSO-C66b | Collins Avionics Division 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | | SDO-640:622-7207-001 SDU-640A:622-8336-001 DU-1000:622-7484-250, -301 DCP-1000:622-7485-201, -301 HPU-74B:622-9221-001 HCP-74B:622-9222-001/-002/-003/-004 |
| TSO-C66b | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM-W | | CI 105() Ser. CI 305() Series |
| TSO-C66b | Dorne & Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM 1601354 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|---|
| TSO-C66b *F | Electronique Aerospatiale (EAS) B.P. 51 93350 Le Bourget France | EU | | VOR/DME BCN 2223:899-2223() () () |
| TSO-C66b | Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43229 | CE-C | | LNS616/RNC 601 LNS616A/RNC601A 805C0620 DI-851:805D0770-01 805D0770-02 TX670:805D0601-01, -02 805D0602-00, -01, -02, -03 DME670:805D0601-07 DME675 |
| TSO-C66b | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G7005() G7016 G6692-() G7024() G6165() G6164() G6860() G6868() G6895() G6950() G6229() G7056() G7045() G4422() G6979() G7024():-01, -02, -03, -04, -07, -08, -09, -10, -11, -14, -15, -18, -19, -23, -24, -25, -26, -27 RTU-870A:622-9346-():-011, -012, -013 |
| TSO-C66b | Global-Wulfsberg Systems Div. of Sundstrand Data Control, Inc. 6400 Wilkinson Drive Prescott, AZ 86301 | NM | | GNS-1000-() |
| TSO-C66b | Gull Airborne Inst., Inc. 395 Oser Avenue P.O. Box 9400 Smithtown, NY 11787 | NE | | RCN-202 COMM/NAV:901-207-0011, 0012, 0013, 0014 RNC-202 NAV/COMM:901-208-0011, 0012, 0013, 0014 RNN-202 NAV/NAV:901-205-0011, 0012, 0013, 0014 RNT-202 NAV/TPDE:901-211-0011, 0012, 0013, 0014 RNX-202 NAV A/B 901-212-2025 |
| TSO-C66b | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 W. Bell Road Glendale, AZ 85308 | NM-L | | SRZ-850 RNZ-850:7510100-911, -912, -913, -914 RNZ-850:7510100-901, -902, -903, -904, -907 RM-850:7012100-943, -944, -953, -954 |
| TSO-C66b | King Radio Corp. 400 North Rogers Road Olathe, KS 66062-1212 | CE-W | | KA 120 KDA 689 KDA 1120 KDM 706A KDM 7060 KDM 7070 KDE-7060 KDI-5738 KFS-579A KFS-564A:071-1283-() KFS-579A:071-1281-() KPI-5538:066-3069-00, -01, -03, -04 KPI-573B:066-1091-00 DM-441A DM-441B SD-442A SD-442B |
| TSO-C66b | Rockwell International Corp. Collins Gen. Avn. Div. Avionics Group 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | | DME-442:622-7309-001, 101 CAD-870G:622-7695(), -001, -002 RTU-870A:622-9346-011, -012, -013 |
| TSO-C66b | Sensor Systems Inc. | NM-L | | S65-5366-7L |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|---|---|
| | 8929 Fullbright Avenue Chatsworth, CA 91311 | | | |
| TSO-C66b | Sigma Tek, Inc. 17621 N. Black Canyon Hwy. Phoenix, AZ 85023 | NM | | 1077c |
| TSO-C66b *F | TRT 5, Avenue Reaumur Zone Industrielle du Petit Clemart B.P.21, Le Plessid Robinson 92350 France | EU | | DMETDM 709 |
| TSO-C66b | Universal Navigation Corp. 3260 E. Lerdo Road Tucson, AZ 85706 | NM-L | | 15.6:1000-1-10, 11, 12, 13, 20, 21, 22, 23 1180-1-10, 11, 12, 13, 20, 21, 22, 23 1161-1-11, 12, 13, 14, 15, 21, 22, 23, 24, 25 10580-1-12 1058-01-10 |
| TSO-C66b | Universal Navigation Corp. 3545 W. Lomita Blvd (Unit B) Torrance, CA 90505 | NM | | UNS-1:1000 Series, 1100 Series:1101 1111 1120 1121 1122 1123 1131 1132 1133 1141 1151 1161 1162 1163 1171 1172 1173 UNS-1A:1000-() Series UNS-1 Jr.:1180, 1030 |
| TSO-C66c | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | AIRBORNE DISTANCE MEASURING EQUIP- MENT (FOR AIR CARRIER AIRCRAFT) | CI 201() CI210() |
| TSO-C66d | Rockwell International Corp. Collins Gen. Aviation Div. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | DISTANCE MEASURING EQUIPMENT | RTU-870(A):622-9346-001, 002, 003 |
| TSO-C67 | Collins Avionics Division 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | AIRBORNE RADAR ALTIMETER EQUIP- MENT (FOR AIR CARRIER AIRCRAFT) | DU-1000:622-7484-250, -301 DCP-1000:622-7485-201, -301 |
| TSO-C67 | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM-L | | S67-1000-()Ser. |
| TSO-C67 | Sperry Flight Systems Div. Sperry Rand Corp. 21111 N. 19th Ave. P. O. Box 21111 Phoenix, AZ 85036 | NM | | AD-200: 2588369-() |
| TSO-C67 | Wilcox Electric Co., Inc. 1400 Chestnut St. Kansas City, MO 64127 | CE-W | | 097836-() |
| TSO-C68 | Bendix Avionics Division | CE-A | AIRBORNE AUTOMATIC DEAD RECKONING | CPA-24: CPA-24() CNA-24() MTA-24() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|---|---|--|--|
| | P. O. Box 9414 Ft. Lauderdale, FL 33310 | | COMPUTER EQUIPMENT UTILIZING AIRCRAFT HEADING & DOPPLER OBTAINED GROUND- SPEED AND DRIFT ANGLE DATA (FOR AIR CARRIER AIRCRAFT) | | | |
| TSO-C68 | Bendix Radio Division Baltimore, MD 21204 | NE | | CPA-24() | | |
| TSO-C68 | Bendix Eclipse-Pioneer Div. Teterboro, NJ 07608 | NE | | CPA-24() 37900 | 37902 CPA-24 | CPA-12 |
| TSO-C68 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | 37903() CNA-24() | MTA-24() CPA-24() | DRA-12() |
| TSO-C68 *F | Canadian Marconi Company 2442 Trenton Ave. Montreal 301, Quebec Canada | NE | | AN/ASN-35 | AN/ASN-64 | AN/AYA-3 |
| TSO-C68 | Collins Radio Company 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | NC-103 | | |
| TSO-C68 *F | Elliott Brothers(London)Ltd. Christopher Martin Road Basildon, Essex England | EU | | AD.560 | | |
| TSO-C68 | Singer-General Precision Kearfott Division 63 Bedford Rd. Pleasantville, NY 10570 | NE | | GPQ-601 SKK-1000 | TNC-50 | SKQ-601 |
| TSO-C69 | Air Cruisers Co. P. O. Box 180 Belmar, NJ 07719-0180 | NE | EMERGENCY EVACUATION SLIDES | D22862 D29400-() D29740-() D29952-() D31020-() D31023-() D31037-() D31040-() D31073-() ERD29835-() 1502219-() 17022275-() 18022370-() 19022428-() 19022454-() 20022490-() 22022685-() 22022696-() 22022901-() 23029049-() 24029172-() 24029220-() | D29278-() D29401-() D29742-() D29953-() D31021-() D31027-() D31038-() D31041-() D31354-() ERD29857-() 15022093-() 17022319-() 19022368-() 19022434-() 20022483-() 20022507-() 22022689-() 22022861-() 22022977-() 23022978-() 23030022-() 24029217-() 24029221-() | D29279-() D29613-() D29734-() D31005-() D31022-() D31028-() D31039-() D31042-() D31355-() 15022129-() 17022344-() 19022409-() 19022439-() 20022485-() 21022573-() 22022860-() 22022900-() 23022978-() 24029154-() 24029218-() |
| TSO-C69 | American Safety | CE-A | | LS-132 | LSR-154() | LSR-160() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|-----------|---|---|--|
| | Inflatable Survival Systems P.O. Box 480213 7000 N.W. 46th Street Miami, FL 33148 | | | LA-165() LSR-174() LSR-200() LSR-225() LSR-255() D4000-() | LSR-165() LSR-185() LSR-201() LSR-226() LSR-273() D4001-() | LSR-166() LSR-190() LSR-210() LSR-240() D4018-() |
| TSO-C69 | Douglas Aircraft Co. 190th St. & Normandie Ave. Torrance, CA 90510 | NM | | 5956557-() Ser. | | |
| TSO-C69 | Global Systems, Inc. Rocket/Jet Airborne Res. Div. 1311 Grand Central Ave. Glendale, CA 91201 | NM | | 80056() | 80400() | |
| TSO-C69 | The B. F. Goodrich Company 3414 South 5th Street Phoenix, AZ 85040 | NM-L | | 11331() 15611() 17621() 122011() 100502-() 101616-() 101623-() 101655-() 1113800() 3156100() 4136800() 4156700() 5156100() 5196200() 5216800() 6146200() 6176700() 5LD230500 5LD230100-() 101607-() | 11611() 16661 18661() 22021() 100503-() 101618-() 101630-() 101656-() 1156800() 3156700() 4136700() 4156800() 5156200() 5196800() 6136100() 6160100() 5L9230100 5LD230600 101604-() 100108-100 | 13621-1() 17611() 13621-2() 100501-() 101614-() 101621-() 101654-() 1113100() 1461100() 4136100() 4156100() 4177800() 5196100() 5216100() 6156200() 6176100() 5LD230300 5LD260100 101605-() 100108-200 |
| TSO-C69 | B.F. Goodrich Company 500 S. Main Street Akron, OH 44318 | CE-C | | 7A1274 7A1323 7A1296 | 7A1275 7A1297-() 7A1299 | 7A1276 7A1298 |
| TSO-C69 | Hoover Aircraft Products Co. International Airport P. O. Box 337 Miami, FL 33148 | CE-A | | CH-3001 CH-3001-3221 CH-3002-3221 | CH-3001-3181 CH-3002-3181 DA-62() | CH-3001-3201 CH-3002-3201 DA-400() |
| TSO-C69 *F | R. F. D. - GQ, Limited Catteshall Lane Godalming, Surrey England | EU | | AES8 AES12 | AES9 | AES11 |
| TSO-C69 | Survival Equipment Corp. San Francisco, CA 94101 | NM | | 13-1/2 ft. 136XXX 16-1/1 ft. 166XX 18-1/2 ft. 186XX | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|--|--|--|
| TSO-C69 | Switlik Parachute Co., Inc. P.O. Box 1328 Trenton, NJ 08607 | NE | | 811 S-13000-() SPC-AM-6000-() SPC-AM-8000-() | 815 S-13050-() | 816 RA-6002-() SPC-AM-6100-() SPC-AM-8100-() |
| TSO-C69a *F | Aerazur 58 Bd Gallieni 92130 Issy les Moulineaux, France | EU | EMERGENCY EVACUATION SLIDES, RAMPS, AND SLIDE/ RAFT COMBI- NATIONS | 207 700-() D30664 | D31516() D30665 | D31517() D31865 |
| TSO-C69a | Air Cruisers Company P.O. Box 180 Belmar, NJ 07719-0180 | NE | | D31020 D31023 D30657 D31073 D31393 D31591 D31005-() D31037-() D31040-144/-145 D31041-146/-147 D31073-() D31354-109 D31354-115 D31355-109 D31355-115 D29400-() D29401-() D29740-() 15D22093-() 19D22368-() 19D22439-() 22D22685-() 22D22860-() 22D22901-() 23D29049-() 24D29172-() 24D29220-() D30664, Rev. F | D31021 D29985 D30658 D31354-117 D31518-Rev L D31735 D31027-() D31038-142 D31354-105 D31354-111 D31355-105 D31355-111 D31697 D29982 D29613-() D29742-() 17D22319-() 19D22387-() 19D22454-() 22D22689-() 22D22861-() 23D22977-() 23D29066-() 24D29217-() 24D29221-() D30665, Rev. F | D31022 D29984 D30659 D31355-117 D31793 D31028-() D31039-143 D31354-107 D31354-113 D31355-107 D31355-113 D29734-() D30543 18D22370-() 79D22409-() 20D22507-() 22D22696-() 22D22900-() 23D22978-() 24D29154-() 24D29218-() D30665, Rev. F |
| TSO-C69a | Air Cruisers Company Highway 34 Allaire Airport Wall Township, NJ | NE | | D31840-100 Rev. F | | |
| TSO-C69a | B.F. Goodrich Company 3414 South 5th Street Phoenix, AZ 85040 | NM-L | | E. Evacuation Slide 101659-() 101660-() 7A1469-() | | 7A1479-() 7A1489-() 7A1467-() |
| TSO-C69a | B.F. Goodrich Company Dept. 1831, Bldg. 17-F 500 South Main Street Akron, OH 44318 | CE-C | | Slide/Raft 7A1394-() 7A1437-() 7A1447-() 7A1359-() | 7A1296-() 7A1298-() 7A1439-() 7A1448-() | 7A1297-() 7A1299-() 7A1418-() 7A1300-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|---|---|-------------------------------|---|
| TSO-C69b | Air Cruisers Company Highway 34 S. Allaire Airport P.O. Box 180 Belmar, N.J. 07719-0180 | NE | EMERGENCY EVACUATION SLIDES, RAMPS, AND SLIDE/ RAFT COMBINATION | 61570-127 A320:D31865-() 767 Type 1:60176-() | 61570-128 | |
| TSO-C69b | Air Cruisers Company Highway 34 Allaire Airport Wall Township, NJ | NE | | MD-11:61283-Series 60289 Rev. J 60290 Rev. J 60291 Rev. J D31840-101 Rev. F | | EDR 09-963 Rev. M EDR 09-964 Rev. L EDR 09-965 Rev. P |
| TSO-C69b | B.F. Goodrich Company 3414 South 5th Street Phoenix, AZ 85040 | NM-L | | 7A1467-() | 7A1469-() | |
| TSO-C70 | American Safety Inflatable Survival Systems P.O. Box 480213 7000 N.W. 46th Street Miami, FL 33148 | CE-A | LIFE RAFTS (NONREVERSIBLE) | C-2 3058-() | C-4 | C-7 |
| TSO-C70 | Eastern Aero Marine P.O. Box 593513 Airport Mail Facility Miami, FL 33159 | CE-A | | EAM-T2 EAM-T9 | EAM-T4 | EAM-T6 |
| TSO-C70 | Elliott LifeRaft Div. 3874 Fiscal Court Riviera Beach, FL 33404 | CE-A | | A0600() | A0800() | A01200() |
| TSO-C70 | The BF Goodrich Company 3414 South 5th Street Phoenix, AZ 85040 | NM-L | | AR/6006-0 100102-() | AR/6006-()Ser. 100103-() | 100118-() |
| TSO-C70 | Inflatable Systems, Inc. - WITHDRAWN 9/28/89 Orange, CA 92666 | | | | | |
| TSO-C70 *F | R F D -GQ, Limited Godalming Catteshall Lane Surrey, England | EU | | 10U Mk 10 6U Mk 4 | 26U Mk 2 22 UA Mk 1A | 29U Mk 1 |
| TSO-C70 | R.P.R. Industries, Inc. P.O. Box 158 Apex, NC 27502 | CE-A | | CR-46 | CR-68 | CR-810 |
| TSO-C70 | Switlik Parachute Co., Inc. 1325 E. State St. P.O. Box 1328 Trenton, NJ 08607 | NE | | RA-30002 LWC-4101() LWC-6101() LWC-8101() | C-7 EX-6001-() | |
| TSO-C70a *F | Aerazur 58 Bd Gallientl 92130 Issy les Moulineaux, France | EU | LIFERAFTS | Type 606 A()210155() | | |
| TSO-C70a | Air Cruisers Services P.O. Box 180 Belmar, NJ 07719-0180 | NE | | 60485-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--|---|--|---|
| TSO-C70a *F | Autoflug GmbH, D-2084 Rellingren 2, Industriestrasse 10, Germany | EU | | Liferaft Petrel Series - L Petrel - LA | | |
| TSO-C70a *F | Beauford Air-Sea Equipment Beauford Road Birkenhead, Merseyside England | EU | | MK.6/5 ALR Series 1 ALR Series 2 | | |
| TSO-C70a *F | Dunlop-Beaufort Ltd. Birkenhead Merseyside, England | EU | | MK10 ALR Series 1 | | |
| TSO-C70a | Eastern Aero Marine P.O. Box 593513, AMF Miami, FL 33159 | CE-A | | EAM-T2, EAM-T6 EAM-T12 | EAM-T4 EAM-T9 EAM-T25 | EAM-T6A EAM-T46 |
| TSO-C70a | Hoover Industries, Inc. P.O. Box 522337 Miami, FL 33152 | CE-A | | Model FR-25:2500-() FR-10:1000-() FR-2, FR-4, FR-6, FR-8 | | |
| TSO-C70a *F | RFD Limited Godalming Surrey, England | EU | | 46RA MK.1 | | |
| TSO-C71 | Collins General Avn. Div. Rockwell International Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | AIRBORNE STATIC ("DC TO DC") ELECTRICAL POWER CONVERTER (FOR AIR CARRIER AIRCRAFT) | PWC-150 | | |
| TSO-C71 | Dayton Aviation Radio and Equipment Inc. P.O. Box 419 Troy, OH 45373 | CE-C | | DPC-1() | | |
| TSO-C71 | King Radio Company 400 North Rogers Road Olathe, KS 66061 | CE-W | | KA 579A:064-1034-() | | |
| TSO-C71 | NARCO Avionics Aerospace Div Div. Narco Scientific Ind. 2825 Laguna Canyon Road Laguna Beach, CA 92652 | NM-L | | MP-10 MP-20 | MP-11 MP-200 | MP-15 |
| TSO-C71 | Pacific Electro Dynamics, Inc. 14220 Sunset Highway Bellevue, WA 98007 | NM | | 593-() | | |
| TSO-C72 | Aircraft Mechanics Mechanical Division P.O. Box 370 Colorado Springs, CO 80901 | NM | INDIVIDUAL FLOTATION DEVICES | 5895214-1 917D10004-1 965J10624-1 971J14212-1() 973J11112-1() | 5895225-1() 918D10005-1 971J14210-1()) | 5901061-1 965J10624) 972J14212-1() 1056J18100-() |
| TSO-C72 | Air Cruisers Company P.O. Box 180 Belmar, NJ 07719 | NE | | 21021183(AD7) | | |
| TSO-C72 | AMCI, Inc. Monrovia, CA 91016 | NM | | FCA 100 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|--------------------------------|--|--|--|
| TSO-C72 | Castle Industries Inc. of CA. 601 South Dupont Avenue Ontario, CA 91761-1502 | NM | | 50159-7 | | |
| TSO-C72 | Fairchild-Burns Co. Div. of Fairchild Ind. Inc. 1455 Fairchild Dr. Winston-Salem, NC 27105 | CE-A | | C100() | | |
| TSO-C72 | Flight Line Corporation 8330 San Fernando Rd. Sun Valley, CA 91352 | NM | | A602-1 | A602-3 | A602-4 |
| TSO-C72 | Hardman Aerospace 1845 S. Bundy Dr. Los Angeles, CA 90825 | NM | | BC200() HC100() | HC100FR | HC200() |
| TSO-C72 *F | Koito Industries, Inc. Tokyo, Japan | NM-L | | KOITO 83 | | |
| TSO-C72 | PTC Aerospace Aerospace Division Bantam, CT 06750 | NE | | 45267 57619 | 57466 58814 | 57625 59874 |
| TSO-C72 *F | Siebelwerke ATG, GmbH Donauworth, Germany | EU | | 103.06 | | |
| TSO-C72 | Stearns Manufacturing Co. Division St. at Thirtieth St. Cloud, MN 56301 | CE-C | | ST-5709 | | |
| TSO-C72 | Stebco Industries, Inc. 1020 W. 40th St. Chicago, IL 56301 | CE-C | | LP-AA | | |
| TSO-C72 | Taylor-tec, Inc. 2400 South Range Road Hammond, LA 70401 | SW | | APV-17.5 | MOD-1.5/68. | |
| TSO-C72 *F | Tenryu Industries Co., Ltd. 4-1, Soharakocho Kakamigohara, Gifu Japan | NM-L | | T 100 | | |
| TSO-C72 | Weber Aircraft Company Special Products Division 1300 East Valencia Drive Fullerton, CA 92631 | NM | | 801613-401 805416-409 805423-409 805424-407 807292 | 802731-401 805416-411 805423-411 805424-409 809308 | 805416-407 805423-407 805423-413 805424-411 809580 |
| TSO-C72 | Weber Aircraft 2000 Weber Drive Gainesville, TX 76240 | SW | | 727 Cushions | | |
| TSO-C72a | A & D Associates 1115 Santee St. Los Angeles, CA 90015 | NM | INDIVIDUAL FLOATING DEVICES | 1115() Ser. | 1117() Ser. | |
| TSO-C72a | Aerosmith Products Corp. P. O. Box 542 Miami, FL 33144 | CE-A | | F101-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|--|---|---|
| TSO-C72a | Air Carriers Interiors, Inc. Boeing Field 8167 Perimeter Rd. Seattle, WA 98108 | NM | | AC-3000 | | |
| TSO-C72a *F | Aircraft Furnishing Ltd. Hersham Station Works Walton-on-Thames, England | EU | | Type 174 | | |
| TSO-C72a | Aircraft Mechanics, Inc. P. O. Box 370 Colorado Springs, CO 80901 | NM | | 1056J18003-() | 5895225-501 | |
| TSO-C72a | AMCI, Inc. 1818 S. Shamrock Ave. Monrovia, CA 91016 | NM | | FCA 100() Ser. | | |
| TSO-C72a | American Safety Inflatable Survival Systems P.O. Box 480213 7000 N.W. 46th Street Miami, FL 33148 | CE-A | | HA-5() | PA-5() | |
| TSO-C72a | Emergency Systems Inter'l Gillespie Airport 7940 John Towers Ave. Santee, CA 92071 | NM | | 20000100-()Ser. | | |
| TSO-C72a | Expanded Rubber & Plastics - WITHDRAWN 10/30/89 Gardena, CA 90247 | | | | | |
| TSO-C72a | Fairchild Burns Co. Div. of Fairchild Ind. Inc. 1455 Fairchild Dr. Winston Salem, NC 27105 | CE-A | | C100 | C200() | |
| TSO-C72a *F | Flying Service Engineering & Equipment Ltd. Springfield Road Chesham, Buckinghamshire HP5 1PP. England | EU | | MD/1246 Type () | | |
| TSO-C72a | 4/Flight Custom Products 11626 Tuxford St. Sun Valley, CA 91352 | NM | | 962()() 1434()() 2893()() 4227()() 33958()() | 963()() 1922()() 3020()() 4228()() | 1349()() 2696()() 3249()() 33855()() |
| TSO-C72a | General Plastics Mfg. Co. P. O. Box 65-S Tacoma, WA 98409 | NM | | 65-58270 | | |
| TSO-C72a | B. F. Goodrich Co. - WITHDRAWN Sponge Products Division 37 Canal St. Shelton, CT 06484 | | | | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|--------------------------------|--|--|--|
| TSO-C72a | Herdman Aerospace 1845 S. Bundy Dr. Los Angeles, CA 90825 | NM | | HC100FR BC200() | HC100 | HC100() |
| TSO-C72a | Jepson Burns Corporation 1455 Fairchild Road Winston-Salem, NC 27105-4588 | CE-A | | Model C-101 | | |
| TSO-C72a | Keystone Bros. 755 Mission St. San Francisco, CA 94103 | NM | | KB 755()Ser. | | |
| TSO-C72a | Marsh-Armfield, Inc. P.O. Box 1407 High Point, NC 27260 | CE-A | | 100-() | 101-() | |
| TSO-C72a | PTC Aerospace Aerospace Division Bantam, CT 06750 | NE | | SK-5035 59883 61964 66676 69848 | 55258 61306 66674 69160 69881 | 55790 61340 66675 69749 |
| TSO-C72a | Reliatex, Inc. 2201 N. W. 72nd Ave. Miami, FL 33144 | CE-A | | RT-632A() RT-632E() RT-722() | RT-632C() RT-603() | RT-632D() RT-WA2() |
| TSO-C72a | Schlobohm Company 814 San Fernando Rd. Los Angeles, CA 90065 | NM | | 10 538 814 | 224 1238 | 521 350 |
| TSO-C72a | Switlik Parachute Co. 1325 E. State St. Trenton, NJ 08607 | NE | | AV-5B | AV-8A | AV-7AF A & B |
| TSO-C72a | Tharco Precision 2222 Grant Avenue San Lorenzo, CA 94580 | NM | | 1000()Ser. 2000()Ser. 4000()Ser. | 1001()Ser. 2001()Ser. | 1002()Ser. 3000()Ser. |
| TSO-C72a | Trans-Aero Industries 4060 Glencoe Ave. Marina Del Rey, CA 90291 | NM | | 90140-() | | |
| TSO-C72a | Weber Aircraft Co. Speical Products Division 1300 East Valencia Drive Fullerton, CA 92631 | NM | | 807292-401 807292-417 807292-427 810870 816322() 817737() | 807292-403 807292-419 809580-403 812261 816550() 818858() | 807292-405 807292-421 810826 812281 817736() 819526() |
| TSO-C72b | A & D Foam Products 2820 E. La Cresta Anaheim, CA 92806 | NM | INDIVIDUAL FLOATING DEVICES | A1115-() | A1117-() | |
| TSO-C72b | Aero Interior Corp. 1521 22nd N.W. Auburn, WA 98001 | NM-S | | Model UH-B | | |
| TSO-C72b *F | Aircraft Furnishing International Ltd. Walton-on-Thames Surrey, England | EU | | 3008.12() 3540.12() | 3046.12() | 3100.12() |
| TSO-C72b | Aircraft Industries Corp. 320 E. Buffalo St. | CE-C | | 00704-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | |
|----------------|--|------|-----------|--|--|
| | Milwaukee, WI 53202-5888 | | | | |
| TSO-C72b *F | Air New Zealand Christchurch Engineering Base Christchurch, New Zealand | NM | | B25-20-180-1 | B25-20-230-1 |
| TSO-C72b *F | ALVEN s.r.l. Viale delle Industrie 80040 San Sebastino Al Vesurio Napilo, Italy | EU | | DM 198 DM 02190-01A DM 02190-05A DM 02211-1 | DM 1912-1 DM 02190-03A DM 02209-1 DM 02211-2 |
| TSO-C72b | American Classic Cushion - WITHDRAWN 8/24/89 Molders | | | | |
| TSO-C72b | AMI Industries, Inc. P.O. Box 370 Colorado Springs, CO 80901 | NM | | 2030-7002-() AMI Models 917D14505-() 918D14505-() 965D14501-() | |
| TSO-C72b *F | Ansair Pty Ltd. Aircraft Equipment Div. P.O. Box 63 Tullamarine Victoria 3043, Australia | NM | | SA424 | SA425 |
| TSO-C72b *F | Avioninteriors S.p.A. Luigi Antonelli 4 00145 Rome Italy | EU | | 411000857()() 310284400000 310286200000 310304100000 310409500000 310409900000 310410300000 310466900000 12002-01()()85 12007-01-00L6 12010-01()()T9 12011-01()()T8 | 310286100000 310304000000 310304200000 310409700000 310410100000 310423700000 12002-02()()85 12007-02()()L6 12010-02()()T9 12011-02()()T8 |
| TSO-C72b | Castle Industries, Inc. of CA. 601 South Dupont Avenue Ontario, CA 91761-1502 | NM | | 0730801-() | |
| TSO-C72b | Cline & Associates, Inc. P.O. Box 12285 Raleigh, NC 27605 | CE-A | | CP-8 | |
| TSO-C72b | Crown Products Corp. Plaza Square Building 309 North 17th Street St. Louis, MO 63103 | CE-W | | OZ1 | |
| TSO-C72b | Custom Acft. Interiors Inc. 3701 Industry Ave. Lakewood, CA 90712 | NM-L | | Model 881:1077-() | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--------------------|--|---|--|
| TSO-C72b | Custom Products, Inc. P.O. Box 1141 1113 No. Main St. Mooresville, NC 28115 | CE-A | | 13101() F-309-1 8132-() () 104945-1 13117() 13123-() 13129 13134 13137 13143() 13160() 13174() 13184() 13191() 13205() 14210() 14221() | 13102() F309-2 104183-2, -10 13116-1 13118() 13127001 13130 13133() 13139 13144 13161() 13175() 13185() 13192() 13219() 14216() | 13103() 13106-1 13116-2 13122-() 13128 13131-001 13135-001 13142() 13151() 13173() 13178() 13189() 13200() 14169() 14217() |
| TSO-C72b | Eastern Aero Marine P.O. Box 480006 Inter'l Airport Branch Miami, FL 33148 | CE-A | | GA-12() | | |
| TSO-C72b | East Wind Industries, Inc. 800 Delaware Avenue Penthouse Suite Wilmington, DE 19801 | NE | | MD-4 | | |
| TSO-C72b | Expanded Rubber & Plastics Corp. 14000 S. Western Ave. Gardena, CA 92049 | | WITHDRAWN 10/30/89 | | | |
| TSO-C72b | 4/Flight 11626 Tuxford St. Sun Valley, CA 91352 | NM | | 3879() () 3249() () 9475() () | 5797() () 4845() () 11474() () | 1434() () 9465() () |
| TSO-C72b | Fairchild Burns Company 1455 Fairchild Drive Winston-Salem, NC 27105 | CE-A | | C-101() C-104 | C-102 | C-103 |
| TSO-C72b | Flight Equipment & Engineering Corp. P. O. Box 522173 Miami, FL 33148 | CE-A | | 29931()/29876 Cover 30990() Cushion 31090-() Cushion 31290() Cushion 31607-() Cushion 32218() Cushion 32527() Cushion 33034() Cushion 33220() Cushion 34322() 34708() | | |
| TSO-C72b *F | Flying Service Engineering & Equipment Ltd. Springfield Rd. Chesham, Buckinghamshire HP5 IPP. England | EU | | MD-715 3277-051 | F2173-C-007() 3277-D-013 | |
| TSO-C72b | General Plastics Manufacturing Company P.O. Box 9097 Tacoma, WA 98409 | NM | | 65-58270 | | |
| TSO-C72b | Hardman Aerospace | NM | | BC200() | HC100() | HC100 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|---|
| | 1845 S. Bundy Dr. Los Angeles, CA 90025 | | | HC100FR |
| TSO-C72b | Hoover Industries P.O. Box 522337 Miami, FL 33166 | CE-A | | FC-21 FD-18 |
| TSO-C72b | Heath Tecna Corp. Precision Structures Div. 19819 84th Ave., S. Kent, WA 98031 | NM | | MPD2-1129-2() MPD2-1129-2E MPD2-3347-1() MPD2-3347-1E MPD2-3347-2() MPD2-3347-2E MPD2-5506-18 |
| TSO-C72b *F | Kay-Metzeler Ltd. Dukinfield, Cheshire England | EU | | Type Southwest D.A.C. 047() |
| TSO-C72b | Keyston Brothers 1000 Brannon Street San Francisco, CA 94103 | NM | | K81002-() K89010-1() K89011-() K89012-() |
| TSO-C72b *F | Koito Industries, Limited 100, Maeda-cho, Totsuka-ku Yokohama, Japan | NM-L | | K.F.D.-96 |
| TSO-C72b | MARAVIA Corporation 857 Thorton St. P. O. Box 395 San Leandro, CA 94577 | NM | | 4000() |
| TSO-C72b | Marsh-Armfield, Inc. P. O. Box 1407 High Point, NC 27260 | CE-A | | 102() 200-() |
| TSO-C72b | Matlock Industries, Inc. P.O. Box 217 Centre, AL 35960 | CE-A | | 101-450-002 102-450-001 101-450-003 102-450-011 101-450-004 102-450-013 101-450-007 102-450-014 101-450-008 102-450-015 101-450-013 102-450-016 |
| TSO-C72b | PTC Aerospace Aerospace Division Bantam, CT 06750 | NE | | CUSHIONS 1100-01() 78357-1 79919-1 CUSHIONS/COVERS 74781-1/74762-17 74781-3/74762-19 74979-1/64227 74949-3/65618 76365-1/76529-5, 76530-5, 76531-5 77364-1/77375-5, 77374-5, 80011-5 77364-3/76852-5, 76853-5, 76854-4 77674-1/77396-3 78427-1/77373-5, 77374-5, 77375-5 79192/79680-3, -17 79202-1/79680-5 79894-1/79856-3 81386-1/76852-5 81854-1/82463-11, 82464-11, 82465-11 82759-1/82867-11, -13, -15 82785-1/82492-3 83169-1/82114-5 84301-1/84674-5 84301-3/84900-3 84517-1/8444-5 84517-3/84721-3, -9, -15, -21 84517-5/84244-3, -9, -15, -21 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|--|---------------------------------|--------------------------|
| | | | | 84517-9/84867-9 | | |
| | | | | 84517-11/84867-3 | | |
| | | | | 84517-7/84721-3, -9, -15, -21 | | |
| | | | | 84517-17/85978-11, -17, -23, -29 | | |
| | | | | 84517-19/85383-5, -13, -21 | | |
| | | | | 84517-21/85383-29, -37, -45 | | |
| | | | | 85931-1/85978-3 | | |
| TSO-C72b | Reliatex, Inc. 2201 N. W. 72nd Ave. Miami, FL 33144 | CE-A | | RT-722() | RT-723() | |
| TSO-C72b *F | RFD Inflatables, Ltd. 66 Catteshall Lane Godalming Surrey GU71LH, England | EU | | 102 MK 28A | | |
| TSO-C72b | R.P.R. Industries, Inc. P.O. Box 30338 Raleigh, NC 27602 | CE-A | | CP-8 | | |
| TSO-C72b *F | L. A. Rumbold, Ltd. Old Oak Common Lane London, England | EU | | M1600-639() SK2266() SK2267() | M1700-811() | |
| TSO-C72b | Schlobohm Company 814 San Francisco Road Los Angeles, CA 90065 | NM | | 50 450 9955A 403A 86 6900 | 88 731 9955B 66 86A | 333 962 403 66A |
| TSO-C72b *F | Societe Aerazur 58 Bd. Gallieni 92130 Issy les Moulineaux France | EU | | C1-1()()() C1 PN-1()()() | | |
| TSO-C72b *F | Speca Europe Ltd. Southend on Sea Essex England | EU | | OA090-0511 | | |
| TSO-C72b | Stearns Manufacturing Co. P. O. Box 1498 St. Cloud, MN 56301 | CE-C | | ST 5714 | ST-5716 | |
| TSO-C72b | Switlik Parachute Co. 1325 E. State St. Trenton, NJ 08607 | NE | | AV-7AF A & B | C-1: S-4050-() | |
| TSO-C72b | Taylor-tec, Inc. 2400 South Range Road Hammond, LA 70401 | SW | | VVC-30 2A | VVC-31 | VVC-32 |
| TSO-C72b *F | Tenryu Industries Co., Ltd. 4-1, Soharakocho Kakamigohara, Gifu Japan | NM-L | | T200 | | |
| TSO-C72b | Tharco Precision 2222 Grant Ave. San Lorenzo, CA 94580-1892 | NM-L | | Model 7000() | Series 405-211-0485 | |
| TSO-C72b | Trans-Aero Industries 12641 Beatrice Street | NM-L | | Model 90140-1 91607-53, -54, -55 | | 91612-3 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|---|--|---|
| | Hillsboro, OR 97124 | | | | | |
| TSO-C72c | Flight Equip. & Eng. Corp. P.O. Box 522173 Miami, FL 33152 | CE-A | | FC-(35311), 35186() | | |
| TSO-C72c *F | Ipeco Europe Ltd Aviation Way, Southend Arprt Southend-on-Sea Essex SS2 6UN United Kingdom | EU | | 0A134-0055F 0A138-0717F 0A134-0055 0A138-0717 0A134-0661(F) | 0A134-0057F 0A138-0718F 0A134-0057 0A138-0718 0A134-0662(F) | 0A134-0058F 0A134-0663(F) 0A134-0058 |
| TSO-C72c | Jepson Burns Corp. 1455 Fairchild Road Winston-Salem, NC 27105-4588 | CE-A | | C-105:43173() | | |
| TSO-C72c *F | Keiper Recaro Steinbeisweg 25-29 7170 Schwabish Hall Germany | NE | | Type 132:132-E-056 | | |
| TSO-C72c | PTC Aerospace 11752 Markon Dr. Garden Grove, CA 92641 | NM-L | | 109000-() 109500 | 109050-() 109600-()-() Series | |
| TSO-C72c | PTC Aerospace Route 202 Bantam, CT 06750 | NE | | Model 1100-01() Cushions | | |
| TSO-C72c *F | Sigma Aero Seat 7 Avenue Bugeaud 75116 Paris, France | EU | | 90-0007(x)(x)C330-(x) | | |
| TSO-C72c | Trans-Aero Industries, Inc. 502 North Oak Street Inglewood, CA 90302-2942 | NM-L | | 94586-1 40021-101 40075-112 92923-1 93237-101 93271-61 93365-1 711-1005-1 721-1001-19 727-1000-1 40005-101 40134-101 92930-2 93168-101 91248-7 93271-1, -2, -4, -62 93567-1, -11 93565-1, -11 711-1001-29 | 40015-101 40075-101 40091-101 92928-1 92961-1 93362-1 711-1001-1 716-1005-1 721-1001-27 40001-101 40023-101 92508-83 92930-3 93961-13 91612-27 94348-1 93677-1 | 40017-101 40075-111 92752-1 92929-1 93271-51 93375-1 711-1001-17 721-1001-1 722-1024-1 40003-101 40105-101 92930-1 92930-4 94029-1 91712-65 93560-1, -11 94394-1 94433-1 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-------------------------------------|--|--|--|
| TSO-C72c | Weber Aircraft Inc. Special Products Division 1300 East Valencia Drive Fullerton, CA 92631 | NM-L | | 835838() 836499-() | 835839() | 835841() |
| TSO-C72c | Weber Aircraft 2000 Weber Drive Gainesville, TX 76240 | SW | | 833733-() 841133-() | 840829() 833644-433 | 840941() 833644-435 |
| TSO-C73 | Avionics Instruments, Inc. 943 E. Hazelwood Ave. P.O. Box 1102B Rahway, NJ 07065 | NE | STATIC ELECTRICAL POWER INVERTER | 1A250-(1A) 1A250-(1D) 1A1000-(1B) 1A2500-2B 1A2500-2C/2 1A125-() 1B100-() 1B350-() 2A250-() 3A125-() | 1A250-(1B) 1A700-(1B) 1A1000-(1C) 1A2500-2C 1A350-() 2A1000-() 1B800-() 2A50-() 2A350-() 3A250-() | 1A250-(1C) 1A700-(1C) 1A1000-(1D) 1A2500-2B/1 1A250-() 3A1000-() 1B250-() 2A125-() 3A50-() 3A350-() |
| TSO-C73 | Avionic Instruments Inc. 1414 Randolph Ave. P.O. Box 49B Avenel, NJ 07001 | NE | | 2A800-1G | 1C2400-1A | 1B1100-1G |
| TSO-C73 | Bendix Electric Power Division Eatontown, NJ 07724 | NE | | 39B153-() | | |
| TSO-C73 *F | Garrett Canada 255 Atwell Dr. Rexdale, Ontario Canada | NE | | 1S-01 617856-2 | 250 VA: 617856-3 | 617836-1 |
| TSO-C73 | Gulton Industries, Inc. Engineered Magnetics Div. 13041 Cerise Ave. Hawthorne, CA 90250 | NM | | EMIR 164 | EMIR 164()Ser. | |
| TSO-C73 | Jet Electronics and Technology, Inc. 5353 52nd St. Grand Rapids, MI 49508 | CE-C | | SI-2500B SI-3000-() SI-1500-() | SI-2500-() SI-2500B/P SI-3003B | SI-2500D SI-1250A-() SI-1000() |
| TSO-C73 | K.G.S. Electronics, Inc. 2029 North Lincoln Avenue Pasadena, CA 91103-1393 | NM-L | | SPC-5() SPC-60() SPC-75() | SPC-10() SPC-38() | SPC-30() |
| TSO-C73 | Leland Electrosystems, Inc. P.O. Box 128 740 E. National Road Vandalia, OH 45377 | CE-C | | ASH564-1, -2, -3, -4, -6 ASH-574-1 ASH574-()/ASH574-()P ASH584-1 ASH671-2 ASH500-() ASH674-1 ASH732-1P ASH734-() | ASH634-() ASH564B-2, -9, -11, -6 ASH664-1P ASH564B-2A ASH674-3P ASH664-1PF ASH250-1P | ASH 664-() ASH450-() ASH664-1PB ASH564B-6 ASH704-1 ASH250-2P |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|--|--|--|---|
| TSO-C73 | Marathon Flite-Tronics Co., Inc. 2525 N. Naomi Street Burbank, CA 91504 | NM | | PC-14() PC-14D PL-3-S1 PC-14B() PC-51() PC-350() MSI-806-() | PC-14B PC-15B() PC-158C() PC-50() PC-250-() PC-450-() MSI-805-() | PC-14C PC-17() PC-15H() PC-125() PC-251-() MSI-800-() |
| TSO-C73 *F | (S.F.E.N.A.) Societe Francaise d'Equipment pour la Navigation Aerienne Aerodrome de Villacoublay P. O. Box 59 78140 Velizy - Villocoublay France | EU | | TSG-102 | TSG 420-103 limited to SFENA gyro Type 705()() | |
| TSO-C73 *F | Spar Aerospace Products Toronto, Ontario Canada | NE | | SFS48:5590F-1-1 | | |
| TSO-C73 | Tracor Aerospace 6500 Tracor Lane Austin, TX 78721 | SW | | 154900-() | 154925-() | |
| TSO-C74 | Admiral Corporation Gov. Electronics Div. 3800 Courtland St. Chicago, IL 60647 | CE-C | AIRBORNE ATC TRANSPONDER EQUIPMENT | C-6280(P)/APX | | |
| TSO-C74 | Bendix Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | TR-601A() TRA-61A 2TRX-61 TRA-61B TRU-1/1() 3TRX-61() | TR-601B() MT-603A() ANA-29/61() TRU-1 ANA-61B MSA-61() | CN-602A() TRA-61: MSA-61B TRU-1/2() |
| TSO-C74 | Bendix Radio Division Baltimore, MD 21204 | NE | | TFR-600() TRA-61B | TRA-61 | TRA-61A |
| TSO-C74 | Collins Radio Company 5225 "C" Avenue, N. E. Cedar Rapids, IA 52406 | CE-W | | 621A-3 | 350E-30 | |
| TSO-C74 *F | Cossor Electronics Ltd. The Pinnacles Harlow, Essex England | EU | | SSR1600/1 SSR1601/1 SSR1601/4 | SSR1600/2 SSR1601/2 SSR1601/5 | SSR1600/3 SSR1601/3 SSR1501/7 |
| TSO-C74 | Dorne & Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM N17 DM N18 DM N1-24 DM N135-2 DM N149-3 DM N150-3 DM N170-2 | DM N17-8 DM N18-2 DM N1-29 DM N141-1 DM N149-6 DM N150-4 | DM N17-9 DM N18-3 DM N131-1 DM N149-2 DM N150-2 DM N150-6 |
| TSO-C74 | Hazeltine Corporation Little Neck, NY 11363 | NE | | RT-731(XA-1) | APX-6A(V) | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|--|-------------------------|------------------|------------|
| TSO-C74 | King Radio Corp. 400 N. Rogers Rd. P.O. Box 106 Olathe, KS 66061 | CE-W | | KTR-75() | KFS-575 | KXP-750() |
| TSO-C74 | MARCO Avionics Aerospace Div Div. Marco Scientific Ind. 2825 Laguna Canyon Road Laguna Beach, CA 92652 | NM-L | | UAT-1 | UDA-3 | AT-50 |
| TSO-C74 | Radio Corp. of America Aviation Equipment Dept. 8550 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVQ-60D | AVQ-60E | AVQ-65 |
| TSO-C74 | Randam Electronics Corp. 3091 Shadycrest Dr. Cincinnati, OH 45239 | CE-C | | 113-10289 | C-3926(P)APX46 | |
| TSO-C74 | Regency Avionics Indianapolis, IN 46206 | CE-C | | 505 | | |
| TSO-C74 | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM | | S65-5366-1L | S65-5366-()Ser. | |
| TSO-C74 | Transco Products, Inc. 4241 Glencoe Ave. Venice, CA 90291 | NM | | 2338 | 2338-50 | |
| TSO-C74 *F | Toyo Communication Equipment Company, Ltd. 484 Tsukojoshi 3-Chome Kawasaki, Kanagawa Japan | NM-L | | TKK-ATR-1000A | | |
| TSO-C74 | Wilcox Electric Co., Inc. 1400 Chestnut St. Kansas City, MO 64127 | CE-W | | 814A | 814B | |
| TSO-C74a | Bendix P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | AIRBORNE ATC TRANSPONDER EQUIPMENT | TR-611() | | |
| TSO-C74a | Collins General Aviation Division Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | 899P-1:622-1737-001/002 | | |
| TSO-C74a | Collins Radio Co. 5225 "C" Avenue, N. E. Cedar Rapids, IA 52406 | CE-W | | 621A-6 | | |
| TSO-C74a | Dorne & Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM N170-1 | | |
| TSO-C74a | Gables Engineering, Inc. P. O. Box 880 Coral Gables, FL 33134 | CE-A | | G-3223() | | |
| TSO-C74a | MARCO Avionics Aerospace | NM-L | | AT6-A | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|--|--|--|----------------------------------|
| | Division Div. Narco Scientific Ind. 2825 Laguna Canyon Road Laguna Beach, CA 92652 | | | | | |
| TSO-C74a | Radio Corp. of America Aviation Equip. Dept. 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVQ-61 | | |
| TSO-C74a | Stewart-Warner Electronics 1300 N. Kosner Ave. Chicago, IL 60651 | CE-C | | TS-1843A/APX | | |
| TSO-C74b | ASC Systems Corp. 155 W. Main St. Rockville, CT 06066 TSO Surrendered 8/1/84 | | AIRBORNE ATC TRANSPONDER EQUIPMENT | | | |
| TSO-C74b | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | TPR-650: CN-652B MTA-63A TR641A | TR-651A AT914A TR-611A & B TR641B | CN-625A TRA-63A TR611C & D |
| TSO-C74b | Collins Radio Co. 5225 "C" Avenue, N. E. Cedar Rapids, IA 52406 | CE-W | | 621A-6 | | |
| TSO-C74b | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | CI 100() | | |
| TSO-C74b | General Aviation Electronics 4141 Kingman Dr. Indianapolis, IN 46226 | CE-C | | BETA/5000 ATC LAMBDA/1000 | | |
| TSO-C74b | King Radio Corp. 400 N. Rogers Rd. P.O. Box 106 Loathe, KS 66061 | CE-W | | KT-76 | KT-78 | |
| TSO-C74b *F | L.M.T. Le Materiel Telephonique 46, Quai de Boulogne 92 Boulogne - Billancourt France | EU | | ATC3560E | ATC3560F | ATC3560G |
| TSO-C74b | NARCO Avionics Aerospace Div Div. Narco Scientific Ind. 2825 Laguna Canyon Road Laguna Beach, CA 92652 | NM-L | | AT-50A | | |
| TSO-C74b | Sentinel Electronics, Inc. One Wynnewood Road Suite 207 Wynnewood, PA 19096 | NE | | 134 134C | 134A 134D | 134B |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|--|---|
| TSO-C74b | Sperry Flight Systems Avionics Division 8500 Balboa Blvd. Van Nuys, CA 91409 | NM | | AVQ-30X AVQ-30X(X) AVQ-47 AVQ-85D/S AVQ-95 PRIMUS-10 PRIMUS-20WXD PRIMUS-21WXD PRIMUS-30A PRIMUS-30WXD PRIMUS-31WXD PRIMUS-40WXD PRIMUS-50WXD PRIMUS-90 PRIMUS-90WXD PRIMUS-100 PRIMUS-200 PRIMUS-300 PRIMUS-300SL PRIMUS-400SL PRIMUS-400WXD PRIMUS-500 Weatherscout I Weatherscout II |
| TSO-C74c | Aire-Sciences, Inc. 216 Passaic Avenue Fairfield, NJ 07006 | NE | AIRBORNE ATC TRANSPONDER EQUIPMENT | RT-887:PS-667, P/N 11485 Antenna RT-787:PS-667, P/N 11485 Antenna |
| TSO-C74c | ARC Avionics Division P.O. Box 150 Boonton, NJ 07005 | NE | | 1060A |
| TSO-C74c | ASC Systems Corp. 155 W. Main St. Rockville, CT 06066 TSO Surrendered 8/1/84 | | | |
| TSO-C74c | Avtech Corporation 3400 Wallingford North Seattle, WA 98103 | NM | | 6394-1 5201-1 |
| TSO-C74c *F | Becker Flugfunkwerk GmbH Rastatt, Germany | EU | | ATC 2000 ADF 2000:ADF 2079, ADF 2080, ADF 2081 |
| TSO-C74c *F | Becker Flugfunkwerk Niederwaldstrasse 20 D-7550 Rastatt, Germany | EU | | ATC 200 ATC 2000/R-(2) |
| TSO-C74c | Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | | TPR-660: TR-661A AT-662A TPR-2060: TR-661A, TR-2061A, AT-2062A, P/N 4007341-0502 TRU-2 TRA-65 TR-421:3614008() CD-422A:3614010() TR5-42A:TR-421A, TR-422A, TR-421B |
| TSO-C74c | Bendix/King Allied-Signal Aerospace Co. General Aviation Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | 071-01345-0010/8095261-4211 071-01345-0011/8095261-4212 071-01345-0012/8095261-4213 071-01345-0013/8095261-4214 KAT 1110:068-1011-06 |
| TSO-C74c | Bruno-New York Industries Corporation 40 Smith Street Farmingdale, NY 11735 | NE | | C-6280A(P)/APX:318-4000 |
| TSO-C74c | BVR, Inc. 5459 Eleventh St. P.O. Box 6336 Rockford, IL 61125-1336 | CE-C | | 275175-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|--|---|--|
| TSO-C74c | Cessna Aircraft Co. ARC Avionics Division Rockaway Valley Road P.O. Box 150 Boonton, NJ 07005 | NE | | ARC 360A | | |
| TSO-C74c *F | Chelton (Electrostatics) Ltd Marlow, Buckingham United Kingdom | EU | | 10A() | | |
| TSO-C74c | Collins Avionics Rockwell International 5225 "C" Avenue, N. E. Cedar Rapids, IA 52406 | CE-W | | TDR-90 | 621A-6() | |
| TSO-C74c | Collins Avionics Group Rockwell International 5225 "C" Avenue, NE Cedar Rapids, IA 52406 | CE-W | | 462A-1() | 462B-() | 639U-1 |
| TSO-C74c | Collins Gen. Aviation Div. Rockwell International Melbourne Operations P.O. Box 1060 Melbourne, FL 32902-1060 | CE-A | | TDR-950 462-A-1 CAD-62:622-6590() CTL-92:622-6523() CAD870:622-7346-() CTL-92A:622-8740-() RTU-870:622-7356-() | TDR-950L 639U-1 | NCS-31A |
| TSO-C74c | Collins General Avn. Div. Avionics Group Rockwell International Corp. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | | CTL-92:622-6523-201 thru -216 CTL-92A:622-8740-201 thru -216 RTU-870A:622-9346-011, -012, -013 RTU-870A:622-9346-001, -002, -003 CAD-870G:622-7695-001, -002 | | |
| TSO-C74c | Collins General Avn. Div. P.O. Box 1060 Miami, FL 32901 | CE-A | | RTU-870:622-7356-001 CAD-870G:622-7695-001 CAD-870:622-7346-001 | | |
| TSO-C74c | Collins Avionics Division Rockwell International 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | | D13-1572-() CTL-20() CTL-31() CTL-60() CTL-91() TDR-90:622-1270-001 390R-18:622-1194-001 | TPR-710() CTL-21() CTL-40() CTL-61() | DTP-702 CTL-30() CTL-41() CTL-90() |
| TSO-C74c | Collins Radio Co. 5225 "C" Avenue, N. E. Cedar Rapids, IA 52406 | CE-W | | TDR-90 913Y-1 339A-6 339R-16 | NCS-31 913Y-2 339R-9 339R-17 | 899P-1 339R-4 339R-12 |
| TSO-C74c | Collins Radio Group Rockwell International 400 Collins Road, NE Cedar Rapids, IA 52498 | CE-W | | NCS-31R 559W-2: 622-3768-() | RPU-31M | |
| TSO-C74c | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | CI 100() CI 201() | CI 101 CI 210() | CI 105() Ser C 1305() Ser |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|---|------|-----------|---|--|--|
| TSO-C74c *F | Cossor Electronics Ltd. The Pinnacles Harlow, Essex England | EU | | SSR2700 | 2720 | |
| TSO-C74c | Dayton-Granger, Inc. West Coast Division 3000 Airway Ave. Costa Mesa, CA 92636 | NM | | L10-216() | | |
| TSO-C74c | Delta Electronic Mfrg. Co. Suite 605 11311 Harry Hines Blvd. Dallas, TX 75229 | SW | | DE166ATC | DE-159 | DE-166 |
| TSO-C74c | Dorne & Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM N152-1 | DM N152-2 | DM 1601354 |
| TSO-C74c *F | EAS B.P.51 93350 Le Bourget Principal Paris, France | EU | | 879-2525()()() | | |
| TSO-C74c | Gables Engineering, Inc. P.O. Box 340880 Coral Gables, FL 33114 | CE-A | | G6206() G6286() G7010() G6950() G6861() G7046() | G6230() G6692() G6436() G6868() G6967() | G7003() G7017() G7025() G6944() G7057() |
| TSO-C74c | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G6206:G6206-13 G7025-02, -03, -04, -06, -09, -10, -11 | | |
| TSO-C74c | Gull Airborne Inst., Inc. 395 Oser Avenue P.O. Box 9400 Smithtown, NY 11787 | NE | | RCT 202 COM/TPDR:901-203-0011, 0012, 0013, 0014 RNT 202 NAV/TPDR:901-211-0011, 0012, 0013, 0014 TPDR/ADF:901-209-0001, 0002, 0003, 0004 | | |
| TSO-C74c | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KXP 755() KAT 1110: 068-1011-() KA60() KT79() | KCU 578() KFS 576A TR 4218:066-1103-00 | KXP 7500 KXP 756 |
| TSO-C74c | NARCO Avionics Aerospace Div 2825 Laguna Canyon Road Laguna Beach, CA 92652 | NM-L | | AT-5A AT-200 | AT-6A | AT 150 |
| TSO-C74c | Sensor Systems, Inc. 8929 Fullbright Avenue Chatsworth, CA 91311 | NM | | S65-8280-(3) S65-5366-7L | | |
| TSO-C74c | Sigma Tek, Inc. 17621 N. Black Canyon Hwy. Phoenix, AZ 85023 | NM | | 359A 859A | 360A 1060A | 459A |
| TSO-C74c | Terra Corporation, Inc. 3520 Pan Amer. Freeway, NE Albuquerque, NM 87107 | SW | | 250 TRT 250: 0900-0250-() | R250 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|------------------------------|--|
| TSO-C74c | Trivec Avant Corporation 17351 Jamestown Lane Huntington, CA 92647 | NM | | 56-80-(01) |
| TSO-C75 *F | Aeroquip Aerospace S.A. 14 rue du Morvan SILIC 112 94153 Rungis Cedex France | EU | HYDRAULIC HOSE ASSEMBLIES | Type I-B-P AT2017-4-6-8-10-12-16 Type I-B-P-F AT2124-4-6-8-10-12-16 TYPE II-A-S/P AR1117-3, -4, -5, -6, -8, -10, -12, -16, -20 TYPE III-A-S/P AR1011-4, -5, -6, -8, -10, -12 AR1017-3, -4, -6, -8, -10, -12, -16, -20, -24 AR1048-4, -5, -6, -8, -10, -12, -16 TYPE III-A-S/P-F AR1117-3, -4, -5, -6, -8, -10, -12, -16, -20, -24 AR1130-4, -5, -6, -8, -10, -12, -16, -20, -24 AR1132-3, -4, -5, -6, -8, -10, -12, -16, -20, -24 AR1136-3, -4, -5, -6, -8, -10, -12, -16, -20 AR1158-4, -5, -6, -8, -10, -12, -16 TYPE III-B-S/P AR1417-4, -6, -8, -10, -12 AR1418-4, -6, -8, -10, -12 TYPE III-B-S/P-F AR1519-4, -6, -8, -10, -12 AR1520-4, -6, -8, -10, -12 |
| TSO-C75 | Aeroquip Corporation Aeroquip Aerospace Div. 300 S. East Avenue Jackson, MI 49203 AND Aero Hardware & Supply, Inc. 4301 N.W. 36th Street Miami Springs, FL 33166 AND Aerotech World Trade Corp. P.O. Box 218 Purchase, NY 10577 AND Airparts Company, Inc. 5801 West Harry Wichita, KS 67277 AND VanDusen Aircraft Engineering, Inc. 3327 North Seventh Street Kansas City, KS 66115 AND Boeing Comm. Airplane Co. Building 17-55, Bay 1 Auburn, WA 98124 | CE-C | | Type I-A-S/P AR1011-3-4 AR1012-5, -6, -8, -10 AR1013, -12, -16, -20 Type I-A-S/P-F AR1111-3, -4 AR1112-5, -6, -8, -10 AR1113-12, -16, -20 AR1117 AR1118 AR1119 Type I-B-P AR1412-4 AR2017-4 thru -16 Type I-B-P-F AR1511-4 AT2124-4 thru -16 AT2177-4, -6, -8, -10, -12, -16 Type I-B-S/P AR1211-4 AR1212-4 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-------------------------------|----|-----------|-------------------------------------|
| | AND | | | AR1214-4 |
| | Bailey Hose, Inc. | | | AR1215-4 |
| | 1845 Levee Street | | | AR1216-6 |
| | Dallas, TX 75207 | | | |
| | AND | | | Type I-B-S/P-F |
| | Aeroquip Corporation | | | AR1311-4 |
| | Aeroquip Aerospace Div. | | | AR1312-4 |
| | P.O. Box 369, Highway 264 | | | AR1314-4 |
| | Middlesex, NC 29557 | | | AR1315-4 |
| | AND | | | AR1321-6 |
| | Nelson-Dunn, Inc. | | | AR1323 |
| | 940 South Vail Avenue | | | AR1324 |
| | Montebello, CA 90640 | | | |
| | AND | | | Type II-A-S/P |
| | Piedmont Aviation, Inc. | | | AR1014-4 thru -20 |
| | Smith Reynolds Airport | | | AR1015-4 thru -20 |
| | Winston-Salem, NC 27102 | | | AR1016-4 thru -20, -24 |
| | AND | | | AR1059-20, -24 |
| | Grumman Aerospace Corp. | | | Type II-A-S/P-F |
| | Martin County Airport | | | AR1122-24 |
| | Stuart, FL 33494 | | | AR1128-24 |
| | AND | | | AR1134-4 thru -20, -24 |
| | Grumman Aerospace Corp. | | | AR1137-4 thru -20 |
| | Bethpage, L.I., NY 11714 | | | AR1138-4 thru -20 |
| | AND | | | AR1180-8, -10, -12, -16 |
| | Hoses Unlimited, Inc. | | | AR1182 |
| | 618 Doolittle Drive | | | AR1183-20, -24 |
| | San Leandro, CA 94577 | | | B830 |
| | AND | | | Type II-B-S/P |
| | Alamo Accessories, Inc. | | | AR1216-6 AR1428-4 |
| | 10843 Vandale | | | AR1434-6, -8 |
| | San Antonio, TX 78216 | | | Type II-B-S/P-F |
| | AND | | | AR1321-6 |
| | Herber Aircraft Service, Inc. | | | Type III-A-S/P |
| | 120 Center Street | | | AR1011-() |
| | El Segundo, CA 90245 | | | AR1012-() |
| | AND | | | AR1013-() |
| | Eastern Aero Supply, Inc. | | | AR1017-() |
| | Municipal Airport | | | AR1048-10, -12, -16 |
| | Millville, NJ 08332 | | | AR1051-3 |
| | AND | | | AR1052-4, -5, -6, -8, -10, -12 |
| | Ni-Cad, Inc. | | | AR1164-4, -5, -6, -8 |
| | 24800 U.S. 20 | | | AR1119-24 |
| | South Bend, IN 46628 | | | AR1125-24 |
| | | | | AR1130-24 |
| | | | | AR1131-24 |
| | | | | AR1132-() |
| | | | | AR1133-() |
| | | | | AR1135-() |
| | | | | AR1136-() |
| | | | | AR1172-3, -4, -6, -12, -16 |
| | | | | AR1063-05, -06, -08, -10, -12 |
| | | | | Type III-A-S/P-F |
| | | | | AR1048-10, -12, -16 |
| | | | | AR1136-24 |
| | | | | AR1158-10, -12, -16 |
| | | | | AR1164-10 |
| | | | | AR1165-3/-4, -4, -5, -6, -8, |
| | | | | -10, -12, -16, -20 |
| | | | | AR1166-3/-4, -4, -5, -6, -8, -10 |
| | | | | AR1167-24 |
| | | | | AR1168-3, -4, -5, -6, -8, -10, -12, |
| | | | | -16 |
| | | | | AR1170-3 |
| | | | | AR1171-3, -4, -5, -6, -8, -10, -12, |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|-------------------------------------|
| | | | | -16, -20 |
| | | | | AR1172-5, -8, -10 |
| | | | | AR1173-3 |
| | | | | AR1174-3, -4, -6, -8, -10, -12, -16 |
| | | | | AR1175-20, -24 |
| | | | | AR1178-20 |
| | | | | AR1186-4, -5, -6, -8, -10, -12 |
| | | | | AR1192-05, -06, -08, -10, -12 |
| | | | | AR1193-06, -08, -10, -12 |
| | | | | AR1194-06, -08, -10, -12 |
| | | | | AR1198-16 |
| | | | | Type III-A-B-S/P |
| | | | | AR1063-05, -06, -08, -10, -12 |
| | | | | AR1211-4 |
| | | | | AR1212-4, -8, -10 |
| | | | | AR1213-4, -6, -8 |
| | | | | AR1214-4, -6 |
| | | | | AR1215-4, -6 |
| | | | | AR1216-6, -8, -10, -12 |
| | | | | AR1219-10, -12, -16 |
| | | | | AR1411-4, -6, -8 |
| | | | | AR1412-4, -6, -8, -10 |
| | | | | AR1413-10, -12 |
| | | | | AR1410-10, -12, -16 |
| | | | | AR1417-4, -6, -8, -10 |
| | | | | AR1418-4, -6, -8, -10 |
| | | | | AR1428-6, -8, -10, -12 |
| | | | | Type III-B-S/P-F |
| | | | | AR1311-4 |
| | | | | AR1312-4 |
| | | | | AR1313-4 |
| | | | | AR1314-4, -6 |
| | | | | AR1315-4, -6 |
| | | | | AR1316-8 |
| | | | | AR1317-10, -12 |
| | | | | AR1318-6 |
| | | | | AR1320-4, -6 |
| | | | | AR1321-6 |
| | | | | AR1322-4, -6 |
| | | | | AR1325-8 |
| | | | | AR1326-6, -8 |
| | | | | AR1327-10, -12, -16 |
| | | | | AR1511-4 |
| | | | | AR1512-4 |
| | | | | AR1513-10, -12 |
| | | | | AR1514-6 |
| | | | | AR1515-10, -12 |
| | | | | AR1516-4, -6, -8, -10 |
| | | | | AR1517-4, -6, -8 |
| | | | | AR1518-10, -12, -16 |
| | | | | AR1519-4, -6, -8, -10 |
| | | | | AR1520-4, -6, -8, -10 |
| | | | | AR1528-6 |
| | | | | AR1529-10, -12 |
| | | | | AR1530-10, -12 |
| | | | | AR1531-16 |
| | | | | AR1532-4, -6, -8, -10, -12 |
| | | | | AR1533-4, -6, 8, -10, -12 |
| | | | | AR1534-4, -6, -8, -10 |
| | | | | AR1535-4, -6, -8, -10, -12 |
| | | | | AR1536-4, -6, -8, -10, -12 |
| | | | | AR1537-16 |
| | | | | AR1538-16 |
| | | | | AR1540-16 |
| | | | | AR1048-4, -5 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|-----------|--|
| | | | | AR1158-4, -5 AR1542-10 AR1543-10, -4, -6, -8, -12 AR1546-12 AR1547-12 |
| TSO-C75 *F | Aeroquip (Canada) Limited 287 Bridgeland Avenue Toronto, Ontario Canada M6A 1Z7 | NE | | Type III-A-S/P-F AR1174-4, -6, -8, -12 AR1171-4, -5, -6, -8, -10, -12, -16, -20 Type III-B-S/P-F AR1535-4, -6, -8, -10, -12 AR1536-4, -6, -8, -10, -12 |
| TSO-C75 | Aero Systems Mfg. and Overhaul, Inc. Hangar No. 17, JFK Int. Arpt. Jamaica, NY 11430 | NE | | R502XXCC R503XXCC R38XXCC R98XXCC XXXAE5X-XT XXXAE9X-XT |
| TSO-C75 *F | Anglo American Aviation Co. (Singapore) Pte. Ltd. Block 1, Unit 1011, 10th Floor PSA Multi-Storey Complex, Republic of Singapore 0511 | EU | | Type I-A-S/P AR101203 thru -20 Type I-B-P AT2017-4, -6, -8, -10, -12, -16 Type I-B-P-F AT2177-4, -6, -8, -10, -12, -16 Type I-B-S/P AR1412-4 Type II-A-S/P AR1014-4, -5, -6, -8, -10, -12, -16, -20 AR1015-4, -5, -6, -8, -10, -12, -16, -20 Type II-A-S/P-F AR1137-4, -5, -6, -8, -10, -12, -16, -20 AR1138-4, -5, -6, -8, -10, -12, -16, -20 Type III-A-S/P AR1011-4 thru -12, -16, -20 AR1012-3 thru -20 AR1048-4, -5, -6, -8, -10, -12, -16 AR1013-4, -5, -6, -8, -10, -12 AR1158-10, -12, -16 AR1051-3 Type III-A-S/P-F AR1158-4, -5, -6, -8 AR1135-4, -5, -6, -8, -10, -12 AR1136-4, -5, -6, -8, -10, -12, -24 AR1165-3/4, -4, -5, -6, -8, -10, -12, -16, -20 AR1166-3/4, -4, -5, -6, -8, -10 AR1170-3 AR1167-24 AR1168-6-8-10-12 AR1174-6, -8, -12 Type III-S-B-S/P AR1412-4, -6, -8, -10 AR1417-4, -6, -8, -10, -12 AR1418-10, -12 Type III-B-S/P-F AR1516-4, -6, -8, -10 AR1519-4, -6, -8, -10, -12 AR1520-10, -12 |
| TSO-C75 | Deutsch Metal Components 14800 S. Figueroa St. Los Angeles, CA 90248-1795 AND Air Pro | NH-L | | Type IIIA 70A0100004CL 70A0100008CL 70E0100004CL 70E0100008CL Type IIIB 71E0100004CL 71E0100006CL |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|----|-----------|--|
| | 2921 N.W. 79th Ave. Miami, FL 33152 AND Go Air 3562 Elm Street Atlanta, GA 30364 AND Hoseco, Inc. 5775 W. 56th St. Arvada, CO 80002 | | | 71A0100004CL 71A0100006CL TYPE A, TYPE B, TYPE IIA, TYPE IIB, CLASS A-S/P, TYPE III A-S/P, A-S/P-F, I, II 50A 0101-X-XXX-XXX 50A 0102-X-XXX-XXX 50A 0103-X-XXX-XXX 50A 0104-X-XXX-XXX 50A 0105-X-XXX-XXX 50A 0106-X-XXX-XXX 50A 0201-X-XXX-XXX 50A 0202-X-XXX-XXX 50A 0203-X-XXX-XXX 50A 0204-X-XXX-XXX 50A 0205-X-XXX-XXX 50A 0206-X-XXX-XXX 50A 0301-X-XXX-XXX 50A 0302-X-XXX-XXX 50A 0303-X-XXX-XXX 50A 0304-X-XXX-XXX 50A 0305-X-XXX-XXX 50A 0306-X-XXX-XXX 50A 0401-X-XXX-XXX 50A 0402-X-XXX-XXX 50A 0403-X-XXX-XXX 50A 0404-X-XXX-XXX 50A 0405-X-XXX-XXX 50A 0406-X-XXX-XXX 50A 0501-X-XXX-XXX 50A 0502-X-XXX-XXX 50A 0503-X-XXX-XXX 50A 0504-X-XXX-XXX 50A 0505-X-XXX-XXX 50A 0506-X-XXX-XXX Types IA-S/P, IIA-S/P, III-S/P 79B0100004C 79B01100006C 79B0100008C S79B90201-0167, -L S79B90202-0205 S79B902-L S79M8B001-04-(1) S79B90362-L S79M8B002-04-(1 thru 9) S79B90363-L S79M8B003-04-(1) S79B90364-L S79M8B001-05-(1 and 2) S79M8B001-06-(1 thru 2) S79M8B001-08-(1 thru 8) S79M8B002-08-(1 thru 5) S79M8B003-08-(1 thru 7) S79M8B001-10-(1 thru 3) S79M8B003-10-(1 thru 3) S79M8B005-04-(1) S79M8B006-04-(1 and 2) 79(B,D,J,X)(XX)00(34 thru 16)CL 79A(XX)000(04 thru 08)CL Type IA-S/P, Type IIA-S/P, Type IIIA-S/P 79B0100010CL 79B0700010CL 79B0800010CL 79B0900010CL 79B1000010CL 79B1100010CL 79B5700010CL 79B5800010CL 79B5900010CL 79B6000010CL 79B6100010CL 79B6200010CL 79B0100012CL 79B0700012CL 79B0800012CL 79B0900012CL 79B1000012CL 79B1100012CL 79B5700012CL 79B5800012CL 79B5900012CL 79B6000012CL 79B6100012CL 79B6200012CL Types IA-S/PF, IIA-S/PF, IIIA-S/PF 79E(XX)000(04 thru 08)(C or Z)L Types IA-S/P-F, IIA-S/P-F, IIIA-S/P-F 79F0100004C 79F0100006C 79F0100008C Types IA-S/PF, IIA-S/PF, IIIA-S/PF 79F0100005CL 79F01000052L 79F0200005CL 79F02000052L 79F0300005CL 79F03000052L 79F0400005CL 79F04000052L 79F0500005CL 79F05000052L 79F0600005CL 79F06000052L 79F5700005CL 79F57000052L Types IA-S/PF, IIA-S/PF, IIIA-S/PF 79(F or H)(XX)000(34 thru 16)(C or Z)L Type IA-S/P-F, Type IIA-S/P-F, Type IIIA-S/P-F 79F0100010CL 79F0700010CL 79F0800010CL |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|------------------------|----|-----------|---------------------------------------|--------------|----------------|
| | | | | 79F0900010CL | 79F1000010CL | 79F1100010CL |
| | | | | 79F5700010CL | 79F5800010CL | 79F5900010CL |
| | | | | 79F6000010CL | 79F6100010CL | 79F6200010CL |
| | | | | 79F0100012CL | 79F0700012CL | 79F0800012CL |
| | | | | 79F0900012CL | 79F1000012CL | 79F1100012CL |
| | | | | 79F5700012CL | 79F5800012CL | 79F5900012CL |
| | | | | 79F6000012CL | 79F6100012CL | 79F6200012CL |
| | | | | Types 1B-S/P, 11B-S/P, 111B-S/P | | |
| | | | | 86A0100004C | | 86A0100006C |
| | | | | 86A0100008C | | 86A0100010C |
| | | | | 84A0100012C | | |
| | | | | Types 1B-S/P-F, 11B-S/P-F, 111B-S/P-F | | |
| | | | | 86E0100004C | | 86E0100006C |
| | | | | 86E0100008C | | 86E0100010C |
| | | | | 84E0100012C | | |
| | | | | 79B010003/4CL | | 79B0100005CL |
| | | | | 79B0100016CL | | 79B020003/4CL |
| | | | | 79B0200005CL | | 79B030003/4CL |
| | | | | 79B0300005CL | | 79B040003/4CL |
| | | | | 79B0400005CL | | 79B050003/4CL |
| | | | | 79B0500005CL | | 79B060003/4CL |
| | | | | 79B0600005CL | | 79B0700016CL |
| | | | | 79B0800016CL | | 79B0900016CL |
| | | | | 79B1000016CL | | 79B1100016CL |
| | | | | 79B570003/4CL | | 79B5700005CL |
| | | | | 79B5700016CL | | 79B5800016CL |
| | | | | 79B5900016CL | | 79B6000016CL |
| | | | | 79B6100016CL | | 79B6200016CL |
| | | | | 79B710003/4CL | | 79B720003/4CL |
| | | | | 79B7200005CL | | 79B730003/4CL |
| | | | | 79B7300005CL | | 79B740003/4CL |
| | | | | 79B7400005CL | | 79B750003/4CL |
| | | | | 79B7500005CL | | 79F0100012CL |
| | | | | 79F0100016CL | | 79F01000162L |
| | | | | 79F0700016CL | | 79F07000162L |
| | | | | 79F0800016CL | | 79F08000162L |
| | | | | 79F0900016CL | | 79F09000162L |
| | | | | 79F1000016CL | | 79F10000162L |
| | | | | 79F1100016CL | | 79F11000162L |
| | | | | 79F5700016CL | | 79F57000162L |
| | | | | S79B90349-12-L | | S79MBB005-04-1 |
| | | | | S79MBB006-04-1 | | S79MBB006-04-2 |
| | | | | HOSE ASSEMBLY BRAKE LINE | | |
| | | | | S79B90362-() | | S79B90363-() |
| | | | | S79B90364-() | | |
| TSO-C75 | Fenwick S.A., 15 | EU | | 130 | 370 | 400 |
| *F | rue Fenelon 75480 | | | 660 | | |
| | Paris, France | | | | | |
| TSO-C75 | ITALA S.p.A. | EU | | 98X XXXX XX XX XXX X | | |
| *F | Vis Piane 13 | | | 99X XXXX XX XX XXX X | | |
| | Somma, Lombardo, Italy | | | 99 XX XXX X | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|----|-----------|--|
| TSO-C75 *F | Palmer Aero Products Ltd Pen Fold Street Edgware Road London, NW88PL England | EU | | Type II-A-S/P-F 813521508 813521509 813512505 813521506 Type II-B-S/P-F 813521510 813521504 813521507 |
| TSO-C75 *F | Pirelli Itala S.P.A. Via Piave 13 Somma Lombardo (Varese), Italy | EU | | 95 E xxxx xx xx xxx x 95 G xxxx xx xx xxx x 95 H xxxx xx xx xxx x 95 J xxxx xx xx xxx x 95 K xxxx xx xx xxx x |
| TSO-C75 | Resistoflex Corporation Roseland, NJ 07068 | NE | | Type II-A-P R28XX -3 thru -24 Type II-A-S R371 -3 thru -16 Type II-A-P-F SR28XX -3 thru -24 Type II-B-P MS28759 -4 thru -16 MS28762 -4 thru -16 Type II-B-S R618 -4 thru -16 Type IIIA & IIIA PR502XXCC PR503XXCC PR1220X PR1221X PR1222X R502XXCC -4, -5, -6, -8, -10, -12, -16Z, -20Z R503XXCC -4, -5, -6, -8, -10, -12, -16Z, -20Z Type IIIA TR502XXCC-4, -6, -8, -10, -12, -16Z, -20Z TR503XXCC-4, -6, -8, -10, -12, -16Z, -24Z Type III-A-S/P R38XX -4 thru -24Z R38XXCC-4, -5, -6, -8, -10, -12, -16Z, -20Z, -24Z R38XXDD -4 thru -24Z J38XX -4 thru -24Z J38XXDD -4 thru -24Z R98XX -4 thru -24Z R98XXCC-4, -5, -6, -8, -10, -12, -16Z, -20Z, -24Z R98XXDD -4 thru -24Z J98XX -4 thru -24Z J98XXDD -4 thru -24Z R8960 -4, -5, -6, -8, -10, -12, -16, -20, -24 Type III-A-S/P-F TR8960 -4, -5, -6, -8, -10, -12, -16, -20, -24 Type III-AS/P/P SR38XXCC -4 thru -24 SR98XXCC -4 thru -24 Type IIIB 000AE50T-4, -6, -8, -10, -12, -16 000AEXXT-4, -6, -8, -10, -12, -16 TR1220X-4, -6, -8, -10, -12 TR1221X-4, -6, -8, -10, -12 TR1222X-4, -6, -8, -10, -12 Type III-B-S/P |

TSO NO. HOLDER NAME & ADDRESS RG TSO TITLE MODELS OR PART NUMBERS
 =====

R258XX -4, -6, -8
 R2958XX -4, -6, -8
 R258BXX -4, -6, -8
 R259BXX -4, -6, -8
 R328BXX -4
 R3928BXX -4
 R328XX -4
 R3928XX -4
 R348XX -6, -8
 R3948XX -6, -8
 R348BXX -6, -8
 R349BXX -6, -8
 R348ECXX -4, -6
 R349ECXX -4, -6
 R348CCOX -4, -6, -8
 R349BCO -10
 R358XX -8 thru -16Z
 R3958XX -8 thru -16Z
 R358XX -8, -10, -12
 R359BXX -8, -10, -12
 R358CXX -8
 R359CXX -8
 R27493-()XXXX -4, -6, -8
 R27493M-()-XXXX -4, -6, -8
 R27499-()-XXXX -4, -6, -8
 R27711-()-XXXX -4, -6, -8, -12, -16
 R27711L-()-XXXX -4, -6, -8, -12, -16
 R32800CC -4
 R62800CC -4, -6, -8
 XXXAA5X -4, -6
 XXXAA7X -4
 XXXAA9X -4, -6
 XXXAB5X -4, -6, -8, -10, -12
 XXXAB9X -4, -6, -8, -10, -12
 XXXAE5X -4, -6, -8, -10, -12, -16
 XXXAE4X -4, -6, -8, -10, -12, -16
 XXXAE7X -4, -6, -8, -10, -12, -16
 XXXAE9X -4, -6, -8, -10, -12, -16
 XXXAJ5X -6
 XXXAJ7X -6
 XXXAJ9X -6
 XXXAA5XX -4T, -6T
 XXXAB5XX -8T, -10T, -12T
 XXXAE5X-XT -4, -6, -8, -10, -12, -16
 XXXAE9X-XT -4, -6, -8, -10, -12, -16
 TR348BCO -10
 TR349BCO -10
 R8961 -4, -6, -8, -10, -12, -16
 Type III-S/P-F
 TR8961 -4, -6, -8, -10, -12, -16
 XXXAE4X-XT -4, -6, -8, -10, -12, -16

TSO-C75 Star Tech Avn.
 *F Industries, Inc.
 2840-C Olafson Avenue
 Richmond, B.C. V6X 2R3

NE

DAE 246()E() DAE 246()G()
 DAE 246()H() DAE 246()J()
 DAE 246()K()

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|----|-----------|---|
| TSO-C75 | Stratoflex, Inc. Aerospace & Military Connectors Division 220 Roberts Cut Off Road P.O. Box 10398 Fort Worth, TX 76114 AND Aviall 8210 Haskell Avenue Van Nuys, CA 91406 AND Hangar One, Inc. Opa Locka Airport 15001 42nd Street Miami, FL 33054 AND Durham Aircraft Services, Inc. 3701 NW. 66th Avenue Miami, FL 33166 AND Western Skyways, Inc. Troutdale Airport Troutdale, OR 97060 AND Sacramento Skybranch Executive Airport Sacramento, CA 95822 AND Hatfield Aviation 8109 Braniff Houston, TX 77017 AND Aviall 16260 Raymer Street Van Nuys, CA 91406 AND Aviall 2742 Burbank St. Dallas, TX 75235 AND The Zee Company, Inc. 123 Braniff Drive P.O. Box 32842 San Antonio, TX 78216 AND Fas-Orient 21 Loyang Crescent Singapore 1750 AND Integrated Aircraft Systems 39 Milford Drive Hudson, OH 44236 AND Precision Hose Technology 3324 N. 74th Ave. Tulsa, OK 74115 AND Integrated Aircraft Systems, Inc. Commerce Center, Suite 9 1337 Commerce Drive Stow, OH 44224 | SW | | Type I-A-P 111302-4-length 111302-6-length 111302-8-length Type III A-S/P-F:124J (XXX) size -24, -20 Type III B-S/P-F:170J (XXX) size -16 Type III B-S/P-F:3164H (xxx) size -4, -6 Type III A-S/P-F:124H (xxx) size -16 Type III B-S/P-F:171J (xxx) size -6 Type III B-S/P-F:3164 (xxx) sizes -4, -6 Type III B-S/P-F:175H (xxx) size -6 Type B-S/P-F:175H (xxx) size -10 Type III B-S/P:175 (xxx) size -8, -10 111302-10-length 111302-12-length 111 () sizes -3 thru -24 156001-3S-length 156001-4S-length 156001-5S-length 156001-6D-length 156003-3S-length 156003-4S-length 156003-5S-length 156003-6D-length 156005-3S-length 156005-4S-length 156005-5S-length 156005-6D-length 156060-3S-length 156060-4S-length 156060-5S-length 156060-6D-length 156060-8D-length 156060-10D-length 156060-12D-length 156060-16D-length 156062-3S-length 156062-4S-length 156062-5S-length 156062-6D-length 156115-3S-length 156115-4S-length 156115-5S-length 156115-6D-length Type I-A-P-F 111F302-4-length 111F302-6-length 111F302-8-length 111F302-10-length 111F302-12-length 111D(XXX) sizes -4 thru -24 111E () sizes -3 thru -24 111F () sizes -3 thru -24 156F001-3S-length 156F001-4S-length 156F001-5S-length 156F001-6D-length 156F003-3S-length 156F003-4S-length 156F003-5S-length |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|-----------------------------------|
| | AND | | | 156F003-6D-length |
| | Aviall | | | 156F005-3S-length |
| | 500 Industrial Avenue | | | 156F005-4S-length |
| | Teterboro Airport | | | 156F005-5S-length |
| | Teterboro, NJ 07608 | | | 156F005-6D-length |
| | | | | 156F060-3S-length |
| | | | | 156F060-4S-length |
| | | | | 156F060-5S-length |
| | | | | 156F060-6D-length |
| | | | | 156F062-3S-length |
| | | | | 156F062-4S-length |
| | | | | 156F062-5S-length |
| | | | | 156F062-6D-length |
| | | | | 156F115-3S-length |
| | | | | 156F115-4S-length |
| | | | | 156F115-5S-length |
| | | | | 156F115-6D-length |
| | | | | Type II-A-P |
| | | | | 111302-16-length |
| | | | | 111302-20-length |
| | | | | 124 () sizes -3 thru -24 |
| | | | | 124F () Series |
| | | | | 141 () |
| | | | | 141F () |
| | | | | 156 () Series |
| | | | | Type II-A-P & Type II-A-P-F |
| | | | | 156F () Series |
| | | | | Type II-A-P-F |
| | | | | 111F302-16-length |
| | | | | 111F302-20-length |
| | | | | Type II-A-S/P-F |
| | | | | 8809 176F(XXX) |
| | | | | 176H(XXX) |
| | | | | Type I-B-P |
| | | | | 112-313-313-4-length |
| | | | | 112-313-313-5-length |
| | | | | 112-313-313-6-length |
| | | | | 112-313-313-8-length |
| | | | | 112-313-313-10-length |
| | | | | 112-313-313-12-length |
| | | | | 112-313-313-16-length |
| | | | | 112-342-342-4-length |
| | | | | 112-342-342-5-length |
| | | | | 112-342-342-6-length |
| | | | | 112-342-342-8-length |
| | | | | 112-342-342-10-length |
| | | | | 112-342-342-12-length |
| | | | | 112-342-342-16-length |
| | | | | Type I-B-P-F |
| | | | | 112-313F313-4-length |
| | | | | 112-313F313-5-length |
| | | | | 112-313F313-6-length |
| | | | | 112-313F313-8-length |
| | | | | 112-313F313-10-length |
| | | | | 112-313F313-12-length |
| | | | | 112-313F313-16-length |
| | | | | 112-342F342-4-length |
| | | | | 112-342F342-5-length |
| | | | | 112-342F342-6-length |
| | | | | 112-342F342-8-length |
| | | | | 112-342F342-10-length |
| | | | | 112-342F342-12-length |
| | | | | 112-342F342-16-length |
| | | | | Type I-A-S |
| | | | | 3121466-4C-length |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--------------------------------|
| | | | | 3121466-6C-length |
| | | | | 3121466-8C-length |
| | | | | 3121466-10C-length |
| | | | | 3121466-4S-length |
| | | | | 3121466-6S-length |
| | | | | 3121466-8S-length |
| | | | | 3121466-10S-length |
| | | | | 3121466-8D-length |
| | | | | 3121466-10D-length |
| | | | | 3121003-4C-length |
| | | | | 3121003-6C-length |
| | | | | 3121003-8C-length |
| | | | | 3121003-10C-length |
| | | | | 3121003-4S-length |
| | | | | 3121003-6S-length |
| | | | | 3121003-8S-length |
| | | | | 3121003-10S-length |
| | | | | 3121003-8D-length |
| | | | | 3121003-10D-length |
| | | | | 3121005-4C-length |
| | | | | 3121005-6C-length |
| | | | | 3121005-8C-length |
| | | | | 3121005-10C-length |
| | | | | 3121005-4S-length |
| | | | | 3121005-6S-length |
| | | | | 3121005-8S-length |
| | | | | 3121005-10S-length |
| | | | | 3121005-8D-length |
| | | | | 3121005-10D-length |
| | | | | 3121060B(length)C(twist angle) |
| | | | | 3121060D(length)C(twist angle) |
| | | | | 3121060E(length)C(twist angle) |
| | | | | 3121060F(length)C(twist angle) |
| | | | | 3121060B(length)S(twist angle) |
| | | | | 3121060D(length)S(twist angle) |
| | | | | 3121060E(length)S(twist angle) |
| | | | | 3121060F(length)S(twist angle) |
| | | | | 3121060E(length)D(twist angle) |
| | | | | 3121060F(length)D(twist angle) |
| | | | | 3121062B(length)C(twist angle) |
| | | | | 3121062D(length)C(twist angle) |
| | | | | 3121062E(length)C(twist angle) |
| | | | | 3121062F(length)C(twist angle) |
| | | | | 3121062B(length)S(twist angle) |
| | | | | 3121062D(length)S(twist angle) |
| | | | | 3121062E(length)S(twist angle) |
| | | | | 3121062F(length)S(twist angle) |
| | | | | 3121062E(length)D(twist angle) |
| | | | | 3121062F(length)D(twist angle) |
| | | | | 3121115B(length)C(twist angle) |
| | | | | 3121115D(length)C(twist angle) |
| | | | | 3121115E(length)C(twist angle) |
| | | | | 3121115F(length)C(twist angle) |
| | | | | 3121115B(length)S(twist angle) |
| | | | | 3121115D(length)S(twist angle) |
| | | | | 3121115E(length)S(twist angle) |
| | | | | 3121115F(length)S(twist angle) |
| | | | | 3121115E(length)D(twist angle) |
| | | | | 3121115F(length)D(twist angle) |
| | | | | 3121141-4C length |
| | | | | 3121141-6C length |
| | | | | 3121141-8C length |
| | | | | 3121141-10C length |
| | | | | 3121141-4S length |
| | | | | 3121141-6S length |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | | | | 3121141-8S length |
| | | | | 3121141-10S length |
| | | | | 3121141-8D length |
| | | | | 3121141-10D length |
| | | | | 3121143-4C length |
| | | | | 3121143-6C length |
| | | | | 3121143-8C length |
| | | | | 3121143-10C length |
| | | | | 3121143-4S length |
| | | | | 3121143-6S length |
| | | | | 3121143-8S length |
| | | | | 3121143-10S length |
| | | | | 3121143-8D length |
| | | | | 3121143-10D length |
| | | | | 3121145-4C length |
| | | | | 3121145-6C length |
| | | | | 3121145-8C length |
| | | | | 3121145-10C length |
| | | | | 3121145-4S length |
| | | | | 3121145-6S length |
| | | | | 3121145-8S length |
| | | | | 3121145-10S length |
| | | | | 3121145-8D length |
| | | | | 3121145-10D length |
| | | | | 3121190B(length)C(twist angle) |
| | | | | 3121190D(length)C(twist angle) |
| | | | | 3121190E(length)C(twist angle) |
| | | | | 3121190F(length)C(twist angle) |
| | | | | 3121190B(length)S(twist angle) |
| | | | | 3121190D(length)S(twist angle) |
| | | | | 3121190E(length)S(twist angle) |
| | | | | 3121190F(length)S(twist angle) |
| | | | | 3121190E(length)D(twist angle) |
| | | | | 3121190F(length)D(twist angle) |
| | | | | 3121192B(length)C(twist angle) |
| | | | | 3121192D(length)C(twist angle) |
| | | | | 3121192E(length)C(twist angle) |
| | | | | 3121192F(length)C(twist angle) |
| | | | | 3121192B(length)S(twist angle) |
| | | | | 3121192D(length)S(twist angle) |
| | | | | 3121192E(length)S(twist angle) |
| | | | | 3121192F(length)S(twist angle) |
| | | | | 3121192E(length)D(twist angle) |
| | | | | 3121192F(length)D(twist angle) |
| | | | | 3121235B(length)C(twist angle) |
| | | | | 3121235D(length)C(twist angle) |
| | | | | 3121235E(length)C(twist angle) |
| | | | | 3121235F(length)C(twist angle) |
| | | | | 3121235B(length)S(twist angle) |
| | | | | 3121235D(length)S(twist angle) |
| | | | | 3121235E(length)S(twist angle) |
| | | | | 3121235F(length)S(twist angle) |
| | | | | 3121235E(length)D(twist angle) |
| | | | | 3121235F(length)D(twist angle) |
| | | | | 3131(XXX) size -12, -16 thru -24 |
| | | | | 8810 8811 8812 |
| | | | | 8813 8814 8815 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|-----------------------|----|-----------|--|
| | | | | B816 B821 B822 |
| | | | | B823 B824 B825 |
| | | | | B826 |
| | | | | Type I-A-S & Type I-A-S-F |
| | | | | 3121 Series |
| | | | | 3131() Series |
| | | | | 3131F() Series |
| | | | | Type I-A-S-F |
| | | | | B810 thru B816 |
| | | | | B821 thru B826 |
| | | | | 313F(XXX) -12 and -16 thru -24 |
| | | | | 313D(XXX) sizes -8 thru -24 |
| | | | | Type I-A-S/P-F |
| | | | | 170(XXX) 176F(XXX) |
| | | | | 176H(XXX) 176F(XXX) |
| | | | | Type I-B-S |
| | | | | Item 3122(XXX)-4CR-L |
| | | | | Item 3122(XXX)-6CR-L |
| | | | | Item 3122(XXX)-8CR-L |
| | | | | 3122(XXX)-10 |
| | | | | Type II-A-S/P-F |
| | | | | 3130562 |
| | | | | Type IIB, -B-SP |
| | | | | 124F(XXX):AS10558 |
| | | | | Type III-B-S/P |
| | | | | 140001B length C |
| | | | | 140001D length C |
| | | | | 140001E length C |
| | | | | 140001F length C |
| | | | | 140001G length C |
| | | | | 140141B length C |
| | | | | 140141D length C |
| | | | | 140141E length C |
| | | | | 140141F length C |
| | | | | 140141G length C |
| | | | | 171(XXX)-4CR-L, -6CR-L, -8CR-L, -10 |
| | | | | Type III-B-S/P-F |
| | | | | 140DH001B length C |
| | | | | 140D001D length C |
| | | | | 140D001E length C |
| | | | | 140D001F length C |
| | | | | 140D001G length C |
| | | | | 140DH141B length C |
| | | | | 140D141D length C |
| | | | | 140D141E length C |
| | | | | 140D141F length C |
| | | | | 140D141G length C |
| | | | | 170D(XXX)-4CR-length |
| | | | | 170D(XXX)-6CR-length |
| | | | | 170D(XXX)-8CR-length |
| | | | | 170D(XXX)-10CR-length |
| | | | | 170D(XXX)-12CR-length |
| | | | | 170D(XXX)-16CR-length |
| | | | | 140D143 140F143 |
| | | | | B414 thru B418 |
| | | | | B445 |
| | | | | B808 |
| | | | | Type III-A-S/P & Type III-A-S/P-F |
| | | | | 124027 () Series |
| | | | | 124(XXX)-3 |
| | | | | 124(XXX)-4CR-L |
| | | | | 124(XXX)-6CR-L |
| | | | | 124(XXX)-8CR-L |
| | | | | 124(XXX)-10CR-L |
| | | | | 124(XXX)-12CR-L |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|----|-----------|---|
| | | | | 124(XXX)-16CR-L 124H(XXX)-4 through -12, -3 4124(XXX)-4, -5, -6, -8, -10, -12 124J-3 Type III-A-S/P-F 124DS(XXX)-8CR-L 124DS(XXX)-10CR-L 124DS(XXX)-12CR-L 124DS(XXX)-16CR-L 4124(XXX)-6 124J(XXX) Type III-B-S/P & Types III-8-S/P-F 170(XXX)-4CR-L Series 170(XXX)-6CR-L Series 170(XXX)-8CR-L Series 170(XXX)-10CR-L Series 170(XXX)-12CR-L Series 170(XXX)-16CR-L Series 175(XXX) B462 B463 B464 B472 B473 B474 |
| TSO-C75 *F | Tecalemit Flexibles Co. Route de Chateaudun 41000 Blois, France | EU | | Type III AS/P and S/PE 661 Module 4 661 Module 5 661 Module 6 661 Module 8 662 Module 10 662 Module 12 662 Module 16 Type III BS/P and S/PF 662 Module 4 662 Module 6 663 Module 8 663 Module 10 663 Module 12 |
| TSO-C75 *F | Tecalemit Flexibles Avenue de Chateaudun BP815 41008 Blois Cedex France | EU | | 660 (xx)(xx)(xx)T(xxxxx) 665(xx)(xx)20T(xxxxx) |
| TSO-C75 | Titeflex Division Atlas Corporation 603 Hendee St. Springfield MA 01109 AND Alaska Transportation Co. ATCO Spad Division 4211 Donald Douglas Blvd. Long Beach, CA 90801 AND Boeing-Vertol Company Essington, PA 19029 AND Titeflex Europe BP73 77833 Ozoir La Ferriere France AND Grumman Aerospace Corp. South Oyster Bay Rd. Bethpage, NY 11714 | NE | | Type II-A-S/P 97036-() 97037-() 400000X() -8, -12, -16, -20, -23, -32 Type II-A-S/P-F 97036-()S 97037-()S 400000XX-()S -8, -12, -16, -20, -24, -32 F41 XXXX XX-() Type II B-S/P 22XXXX XX-(), -04, -06, -08 Type III-A-S/P 120000XX-() -3 thru -202 130000XX-() -3 thru -242 Type III-A-S/P-F 120000XX-()S -3 thru -202 130000XX-()F -3 thru -202 130000XX-()S -4 thru -202 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|-----------|---|
| | AND Air-Pro Inc. 2981 NW 79th Ave. Miami, FL 33172 | | | 130000XX-()W -4, -5, -6, -8, -10, -12 136060XX-()F -4 thru -20Z M13 XXXX XX-() |
| | AND Air-Pro Inc. 10763 Ambassador Dr. Kansas City, Mo 64153 | | | Type III-B-S/P 660000XX-() -4, -6, -8, -10, -12, 16 22XXXX XX-()-04, -06, -08 23XXXX(Size)-(Length) Size 04, 06, 08, 10 23XXXX XX-() 23XXXX XX-()S M23XXXX XX-() 23000012-() 23000012-()-S 24XXXX XX-()-12, -16 Type III-B-S/P-F 360000XX-()F -4, -6, -8, -12, -16 360000XX-()S -4, -6, -8, -10, -12, -16 660000XX-()F -4, -6, -8, -10, -12, -16 660000XX-()S -4, -6, -8, -10, -12, -16 23XXXX(Size)-(Length)S Size 04, 06, 08, 10 23XXXX(Size)-(length)-W Size 04, 06, 08, 10, 12 S23XXXX("-")-(") Size 04, 06, 08, 10 23000012-() 23000012-()-S F23XXXXXX-() M23 XXXX XX-() 24000004 thru 24000010 24000004S thru 24000010S M24XXXX XX-()-12, -16 24XXXX XX-()S-12, -16 |
| TSO-C75 *F | Titeflex Europe BP 73 77833 Ozoir La Ferriere France | EU | | Series 130 230/240 400/410 660 |
| TSO-C75 | The Weatherhead Co. P. O. Box 399 Sun Valley, CA 91352 | NM | | 70A0100004CL 70A0100008CL 71A0100004CL 71A0100006CL 70E0100004CL 70E0100008CL 71E0100004CL 71E0100006CL |
| TSO-C75 | Western Coupling Corp. Building 67, Mohave Airport Mohave, CA 93501 | NM-L | | A1(XXXXXXXXXXXXXX) N Series Type I-A-P A2(XXXXXXXXXXXXXX) N Series Type I-A-P A3(XXXXXXXXXXXXXX) N Series Type I-A-P B3(XXXXXXXXXXXXXX) N Series Type I-A-S C3(XXXXXXXXXXXXXX) F Series Type I-A-S-F D1(XXXXXXXXXXXXXX) F Series Type I-A-P-F D2(XXXXXXXXXXXXXX) F Series Type I-A-P-F D3(XXXXXXXXXXXXXX) F Series Type I-A-P-F E3(XXXXXXXXXXXXXX) N Series Type II-A-P F3(XXXXXXXXXXXXXX) F Series Type II-A-P-F G3(XXXXXXXXXXXXXX) N Series Type II-A-S H3(XXXXXXXXXXXXXX) F Series Type II-A-S-F J3(XXXXXXXXXXXXXX) N Series Type III-A-P K3(XXXXXXXXXXXXXX) N Series Type III-A-S L3(XXXXXXXXXXXXXX) F Series Type III-A-S-F M3(XXXXXXXXXXXXXX) F Series Type III-A-P-F N4(XXXXXXXXXXXXXX) N Series Type I-B-P P4(XXXXXXXXXXXXXX) F Series Type I-B-P-F Q5(XXXXXXXXXXXXXX) F Series Type I-B-S-F R5(XXXXXXXXXXXXXX) N Series Type I-B-S S5(XXXXXXXXXXXXXX) N Series Type II-B-S |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|---|---|---|--|
| | | | | T5(XXXXXXXXXXXXXX) | F Series Type II-B-S-F | |
| | | | | U5(XXXXXXXXXXXXXX) | N Series Type II-B-P | |
| | | | | V5(XXXXXXXXXXXXXX) | F Series Type II-B-P-F | |
| | | | | W5(XXXXXXXXXXXXXX) | N Series Type III-B-S | |
| | | | | X5(XXXXXXXXXXXXXX) | F Series Type III-B-S-F | |
| | | | | Y5(XXXXXXXXXXXXXX) | N Series Type III-B-P | |
| | | | | Z5(XXXXXXXXXXXXXX) | F Series Type III-B-P-F | |
| TSO-C76 | APCO Accessory Products Div. Hydraulic & Mfgrg. Co. 10445 Glenoaks Blvd. Pacoima, CA 91331 | NM | FUEL DRAIN VALVES | 771600-() | 770800-() | |
| TSO-C76 | Auto Valve, Inc. 1705 Guenther Rd. Dayton, OH 45401 | CE-C | | BJ10000-BH | | |
| TSO-C76 | Curtis Dyna-Products Corp. P. O. Box 297 Westfield, IN 46074 | CE-C | | CCA-1250 CCA-1400 CCA-1650 CCA-3600 CCA-4800 CCA-4950 CCA-7450 CCA-36400 | CCA-1300 CCA-1550 CCA-1700 CCA-4300 CCA-4850 CCA-5800 CCA-9950 CCB-36650 | CCA-1350 CCA-1600 CCA-1800 CCA-4350 CCA-4900 CCA-5800-1 CCA-36150 CCB-36750 |
| TSO-C76 | Essex Cryogenics Ind. Inc. 8213 Gravois Ave. St. Louis, MO 63123 | CE-W | | 0330010200-1 | | |
| TSO-C76 | Essex Industries, Inc. Manufacturing Div. 3235 Big Bend Blvd. St. Louis, MO 63143-3903 | CE-W | | 0330010200-1, -2 | | |
| TSO-C76 | HR Textron, Inc. A Subsidiary of Textron, Inc. 10445 Glenoaks Boulevard Pacoima, CA 91331 | NM | | 706200 770800-() 771600() 772300() | 770000 771000 772200 | 770400 771100 |
| TSO-C77 | Garrett Turbine Engine Co. 111 S. 34th Street Phoenix, AZ 85010 | NM | GAS TURBINE AUXILIARY POWER UNITS | GTCP30-92 GTP30-141 GTCP36-4A GTCP36-28 GTCP85-98C GTCP85-98J GTCP85-98D GTCP85-115C GTCP85-134 GTCP660-4R TSCP700-4A GTCP85-98DCK GTP30-92C GTCP36-100() GTCP85-98DHF-() GTCP30-92() GTCP331-200(A) GTCP331-250() | GTP-30-54 GTCP30-142C GTCP36-6 GTCP85-98 GTCP85-98CK() GTCP85-98J GTCP85-98W GTCP85-115H GTCP85-139H TSCP700-4 TSCP700-5 GTCP85-129CK GTCP85-185L() GTCP85-98C-()) :381276-1 GTCP30-92(A) GTCP331-200(AC) GTCP331-250(E) | GTP30-95 GTCP36-4 GTCP36-16 GTCP85-98A GTCP85-115CK GTCP85-115 GTCP85-129() GTCP660-4 TSCP700-4B GTCP85-163CK GTCP36-16A GTCP660-4D-() GTCP331-200() GTCP331-200(AC) |
| TSO-C77 *F | Microturbo Chemin du Pont de Rupe 31019 Toulouse France | EU | | SAPHIR I SAPHIR IV | SAPHIR II | SAPHIR III |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|---|--|
| TSO-C77 *F | Pratt & Whitney Aircraft P. O. Box 10 Longueil, Quebec Canada | NE | | ST6L-73 |
| TSO-C77 *F | Saurer Adolphe, Ltd. Arbon, Switzerland | EU | | 7 660 001 200 GT 15 |
| TSO-C77 | Sundstrand Power Systems Div. of Sundstrand Corp. 4400 Ruffin Road San Diego, CA 92138-5757 | NM | | T-62T-2C T-62T-25() T-62T-29() T-62T-38-() T-62T-39() T-62T-40C() |
| TSO-C77a *F | Astadyne 408 av. des Etats Unis 31016 Toulouse Cedex, France | EU | GAS TURBINE AUXILIARY POWER UNITS | APU AST 600 1() |
| TSO-C77a | Garrett Auxilliary Power Div. Allied-Signal Aerospace Co. 2739 E. Washington Street Phoenix, AZ 85016-5227 | NM-L | | GTCP36-280() 3800502-1 GTCP36-280(B) 3800516-1 |
| TSO-C77a | Garrett Turbine Engine Co. 111 South 34th Street Phoenix, AZ 86010 | NM | | GTCP36-180() GTCP36-300() |
| TSO-C77a *F | Microturbo Chemin du Pont de Rupe Toulouse, France | EU | | Saphir 20 Model 095 |
| TSO-C77a *F | Pratt & Whitney Canada, Inc. 1000 Marie-Victorin Longueice, Quebec J4G 1A1 | | | PW901A-APU |
| TSO-C77a | Sundstrand Power Systems Div. of Sundstrand Corp. 4400 Ruffin Road P.O. Box 85757 San Diego, CA 92138-5757 | NM-L | | T-62T-40C7E(Series):16840-100 T-62T-46C1()Series:167900-100 T-62T-46C()Series:167900-100 T-62T-47C():170100 T-20G-10C() |
| TSO-C78 *F | E.R.O.S. Equipements Respiratoires a Oxygene de Secours P. O. Box 10 78370 Plaisir France | EU | CREWMEMBER DEMAND OXYGEN MASKS | MA10()() MB10()() MC5 MC10()() MC 10-08-00 MC 10-13-02 MC 10-14-00 MC 10-15-01 MC 10-19-01 MXM23 MC 10-25-01 MXP210() MC 10-()()-(1)()() MF10-()()-()() |
| TSO-C78 | Puritan-Bennett Aero Systems 10800 Pflumm Rd. Lenexa, KS 66211 | CE-W | | 114020-() 114021-() 114022-() 114023-() 114024-() 114025-() 114026-() 114027-() 114028-() 114029-() 114120-() 114121-() 114122-() 114123-() 114220-() 114320-() 114321-() 114322-() 114323-() 174100-() 174101-() |
| TSO-C78 | Robertshaw Controls Co. Aeronautical & Instrument Div 333 N. Euclid Way Anaheim, CA 92803 | NM | | 900-002-006-() 900-002-066-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|---|--|
| TSO-C78 | Sabre Industries, Inc. 120 W. Providencia Avenue Burbank, CA 91502 | NM | | 900-002-066-() |
| TSO-C78 | Scott Aviation 225 Erie Street Lancaster, NY 14086 | NE | | 802601 802602 |
| TSO-C78 | Scott Aviation Div. of Figgie Inter'l. 123 East Montecito Avenue Sierra Madre, CA 91021 | NM | | 358-() 359-8-() |
| TSO-C78 | Sierra Engineering Co. Div. of CapTech Inc. 123 E. Montecito Ave. Sierra Madre, CA 91024 | NM | | 358() Series |
| TSO-C79 | Fenwal, Inc. 400 Main St. Ashland, MA 01721 | NE | FIRE DETECTORS (RADIATION SENSING TYPE) | SFD-500 |
| TSO-C79 | Japan Aircraft Maint. (America), Inc. 8227 - 44th Avenue West Mukilteo, WA 98275 | NM | | PU90-21 |
| TSO-C79 | Pyrotector, Inc. 333 Lincoln St. Hingham, MA 02043 | NE | | Flame Detectors (with P/N 20-440 filter attached) 30-208 30-213 30-304 30-207-21 30-207-22 30-207-23 30-207-24 30-207-26 Control Amplifiers 30-303 30-303A-T 30-303B-T 30-304-T 30-309 30-309-T 30-310 30-310-T 30-326E 30-328E 30-326(-)-(-) Thermal Sensors S-435: 30-159 |
| TSO-C79 | Pyrotector, Inc. 333 Lincoln St. Hingham, MA 02043 | NE | | Flame Detectors 30-207-168 30-207-17 30-207-18 30-207-19 30-215-7 |
| TSO-C80 | Aero Tech Laboratories, Inc. Spear Road Industrial Park Ramsey, NJ 07446 | NE | FLEXIBLE FUEL AND OIL CELL MATERIAL | ATL-435-B-805 |
| TSO-C80 | Advanced Industrial Resources, Inc. 2845 Hangar Road Memphis, TN 38118 | CE-A | | P2315 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|-----------|--|---|---|
| TSO-C80 | AMFUEL Box 887 U.S. Highway 828 West Magnolia, AR 71753 | SW | | E-1367-2 1550-1 | E-1389 E-1628 | E-1567 |
| TSO-C80 | Engineered Fabrics Corp. 669 Goodyear Street Rockmart, GA 30153 | CE-A | | BTC-103 | | |
| TSO-C80 | Firestone Coated Fabrics Co. P. O. Box 887 Magnolia, AR 71753 | SW | | E-1389 1550-1 | E-1567 | E-1367-2 |
| TSO-C80 | Firestone Tire & Rubber Co. 2525 Firestone Blvd. Los Angeles, CA 90054 | NM | | E-1389 | E-1425 | |
| TSO-C80 *F | F. P. T. Industries, Ltd. Portsmouth, Hants PO35PE England | EU | | FPT/PF/480/K804 FPT/PF/481() FPT/PF/500 FPT/PF/612() FPT/PF/500() FPT/NS/677 FPT/HL.869 | FPT/NS/678 FPT/CR.918 | FPT/PF/480() FPT/PF/482() FPT/PF/612 FPT/PF/482/K804 FPT/CR.831 FPT/CR.615 |
| TSO-C80 | K and F Industries Engineered Fabrics Corp. P.O. Box 548 Rockmart, GA 30153 | CE-A | | BTC-107 BTC-101 BTC-95 BTC-86 BTC-85B BTC-54A BTC-39-1 | BTC-106 BTC-100 BTC-94 BTC-85 BTC-69 BTC-49 BTC-17 | BTC-102 BTC-99 BTC-88 BTC-85-1 BTC-67 BTC-39 |
| TSO-C80 | Loral Systems Group Div. of Loral Corp. P.O. Box 548 Rockmart, GA 30153-0548 | CE-A | | BTC-85 BTC-95 BTC-101 BTC-99 BTC-100 BTC-106 | BTC-86 BTC-85B BTC-67 BTC-102 BTC-49 BTC-107 | BTC-94 BTC-17 BTC 39 BTC-39-1 BTC-54A |
| TSO-C80 | Goodyear Tire & Rubber Co. Akron, OH 44316 | CE-C | | BTC-17 BTC-39-A BTC-43 BTC-48A BTC-51 BTC-54 BTC-55 BTC-67 BTC-88 | BTC-39 BTC-41 BTC-44 BTC-49 BTC-52 BTC-54A BTC-61 BTC-69 | BTC-39-1 BTC-41-1 BTC-48 BTC-50 BTC-53 BTC-54A-2 BTC-62 BTC85-1 |
| TSO-C80 | Goodyear Tire & Rubber Co. Aviation Products Div. Rockmart, GA 30153 | CE-A | | BTC-54 BTC-69 BTC-49 BTC-67() | BTC-54-1 BTC-39 BTC-54A | BTC-54A-2 BTC-39-1 BTC-17 |
| TSO-C80 | Royal Industries Energy Products Division 2040 East Dyer Road P. O. Box 1618 Santa Ana, CA 92702 | NM | | "TUFTITE" No. 235, No. P2315 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|---------------------------|--|--|---------|
| TSO-C80 | UniRoyal Plastics Products Div. of UniRoyal, Inc. Mishawaka, IN 46544 | CE-C | | US-943 US-764 | US-581 | US-566R |
| TSO-C80 | Urecoat, Inc. 2856 - 8 Lambs Place Memphis, TN 38118 | CE-A | | Tuf-Tite "235" | | |
| TSO-C80 | Verco Industries 12101 Industry Street Garden Grove, CA 92641 | NM | | Tuf-Tite No. | 235 | |
| | | | | Tuf-Tite No. | P2315 | |
| TSO-C80 *F | The Yokohama Rubber Co, Ltd. 36-11, Shinbashi 5 chome Minato-ku Tokyo 105, Japan | NM-L | | Y-3926 | | |
| TSO-C81 | NONE | | | | | |
| TSO-C82 | NONE | | | | | |
| TSO-C83 | NONE | | | | | |
| TSO-C84 | B & D Instruments & Avionics Inc. 209 W. Main Valley Center, KS 67147 | CE-W | COCKPIT VOICE RECORDER | 89090-003101, -003102, -003111, -003112, -003121, -003122, -003201, -003202, -003211, -003212, -003221, -003222 89091-003101, -003102, -003111, -003112, -003121, -003122, -003201, -003202, -003211, -003212, -003221, -003222 89094-003101, -003102, -003111, -003112, -003121, -003122, -003201, -003202, -003211, -003212, -003221, -003222 25000-00310, -00311, -00320, -00321 25001-00310, -00311, -00320, -00321 25005-0031, -0032, 35001-003 | | |
| TSO-C84 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | 390Y-5 | 642C-1 | 914F-1 |
| TSO-C84 | Collins Avionics Division Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | 642C-1 | | |
| TSO-C84 | Lockheed Aircraft Svc., Co. Ontario Inter'l Airport P. O. Box 33 Ontario, CA 91761-0033 | NM-L | | 180A-() Series | | |
| TSO-C84 | Loral Fairchild Corp. Loral Data Systems Fairchild Avn Recorders P.O. Box 3041 Sarasota, FL 33578 | CE-A | | A100:93-A100-() A152:93-A152-() A151:93-A151-() A55:93-A055-() A55B:93-A055-(6X) Where X is 1 thru 9 A150:93-A150-() GA100:GA100-() | A100A:93-A100-() A152B:93-A152-() A151B:93-A151-() A55B:93-A055-() A140:93-A140-() A150:93-A150-20 | |
| TSO-C84 | Microdot, Inc. 220 Pasadena Ave. | NM | | 1410 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|---|------|----------------------------|--|--------------|-------|
| | S. Pasadena, CA 91030 | | | | | |
| TSO-C84 | Spec Tool Company 9626 E. Beverly Rd. Pico Rivera, CA 90661 | NM | | 25625-() | | |
| TSO-C84 | Sundstrand Data Control, Inc Building 2114 Grant County Airport Moses Lake, WA 98837 | NM-S | | 980-6017-001, -002, -003 980-6109-001, -002 980-6109-003 thru -009 980-6109-010, -011, -012 thru -016 980-6109-017 thru -032 980-6114-001, -002 981-3096-002, -003, -004, -005 | | |
| TSO-C84 | Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052 | NM | | V557()980-6001-() | AV-557B | |
| | | | | AV557()980-6005-() | | |
| | | | | 980-6100-0XX | 980-6101-00X | |
| | | | | 980-6102-001 | 980-6017-001 | |
| | | | | CVR-V557:980-1062-() | | |
| TSO-C84 | Sundstrand Data Control 15001 NE 36th St. P.O. Box 97001 Redmond, WA 98073-9701 | NM-S | | 980-6017-003 AV5570:980-6019-001 | | |
| TSO-C84 | Universal Navigation Corp. 3260 East Lerdo Road Tucson, AZ 85706 | NM-L | | 1600-(), 1610-(), 1615-(), 16101 | | |
| TSO-C85 | ACR Electronics 112 Voice Road Carle Place, NY 11514 | NE | SURVIVOR LOCATOR LIGHTS | ACR-4F() | ACR-31() | L8() |
| TSO-C85 | ACR Electronics, Inc. 3901 N. 29th Ave. Hollywood, FL 33020 | CE-A | | ACR/LB-1() | ACR/4F() | |
| TSO-C85 | American Cyanamid Company Wayne, NJ 07470 | NE | | 95270-58 | | |
| TSO-C85 | Eureka Williams Co. Advanced Science Div. 1201 Bell St. Bloomington, IL 61701 | CE-C | | EW-101-WL-48()-12() EW-108-WL-()-8 | | |
| TSO-C85 | Holcombe Industries, Inc. 1602 Tacoma Way Redway City, CA 94063 | NM | | 40-1050() | | |
| TSO-C85 | Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577 | NM | | 40-1050-() | | |
| TSO-C85 | Marine Resources, Inc. 755 Highway 17 & 92 Fern Park, FL 32730 | CE-A | | B-L8-501() | EL-12() | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|---|---|--|--|
| TSO-C85 *F | McMurdo Instrument Co. Ltd. Rodney Road Portsmouth, Hants PO4 85G England PO4 85G | EU | | L8-1 L18-1/PL()A | L18-1/AL()A LJ1 | |
| TSO-C85 | Ortronix, Inc. P. O. Box 14185 Orlando, FL 32803 | CE-A | | Sea Lite I | Sea Lite II | |
| TSO-C85 *F | Pains Wessex Ltd High Post Salisbury, England | EU | | Jaklite:5675-001, -002, -003 | | |
| TSO-C85 *F | SAFT Company 125 Rue du Pres. Wilson 92302 Levallois Perret, France | EU | | BLS 122 | | |
| TSO-C85 | Trinity Star Systems, Inc. 30-15 50th Street Woodside, NY 11377 | NE | | TS300 | | |
| TSO-C86 | NONE | | | | | |
| TSO-C87 | Bendix General Aviation Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | AIRBORNE LOW-RANGE RADIO ALTIMETER | ALA-51: ANA-51() INA-51V EFS-10 CP-103F:8095477-() NC-104A:3614313-() NC-104B:3614331-() NC-105B:8095679-() SC-101B:3614355-1005 | ALA-51() MBA-51() ALA-B1() SG-101A | INA-51() MSA-51() ALA-52A SG-101B |
| TSO-C87 | Bendix Radio Division Baltimore, MD 21204 | NE | | ANA-51() MBA-51() | INA-51() MSA-51() | ALA-51A |
| TSO-C87 | Bendix Aerospace 2150 Northwest 62nd Street P.O. Box 9327 Fort Lauderdale, FL 33310 | CE-A | | ED-102E:8095351 | | |
| TSO-C87 | Bendix/King Air Transport 2100 N.W. 62nd Street Fort Lauderdale, FL 33310 | CE-A | | ALA-52A:2041166-5209, -5207, -5211 SG-101B:3614335-1012, -1013 | | |
| TSO-C87 | Clifton Precision 5100 State Road Drexel Hill, PA 19026 | NE | | 77100000-() () () 89700000-() | | |
| TSO-C87 | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32902-1060 | CE-A | | DRI-55:622-4160-001 thru -008/-011 thru -018 RAC-870:622-7209-002 | | |
| TSO-C87 | Collins Avionics Division Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | 437X-1 | ALI-55() | |
| TSO-C87 | Collins Avionics Division | CE-W | | AD1-85 | AD1-85A | ALT-50A |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|--|------|-----------|--|
| | Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52498 | | | ALT-55() ALT-55B DRI-55 LRA-700 RAI-742() 339H-5 860F-4 AD1-85A:622-4808-001/002/003/004 339H-6:622-4563-001/002/004/005/006/ 007/008 LRA-700:622-4542-220, -020, -121 860F-4:622-3890-021 |
| TSO-C87 | Collins Radio Co. 5225 "C" Ave., N. E. Cedar Rapids, IA 52406 | CE-W | | AL-101 339H() 339H-1 339H-1B 339H-2 437X() 790S() 860F-() 860F-1 339H-1D ALT-50 339H-4 |
| TSO-C87 | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | | C1 155() 01-34-04531 C1 158() C1 159() |
| TSO-C87 | Dorne & Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM PN 3-1/B DM PN 3-3/A DM PN 3-4/A DM PN 3-5/A DM PN 3-3/B DM PN 3-4/B DM PN 3-6/B DM PN 3-12A |
| TSO-C87 | Gould, Inc. - WITHDRAWN 8/23/88 El Monte, CA 91731-1997 | | | |
| TSO-C87 | Hoffman NavCom Systems 4323 Arden Drive ElMonte, CA 91734 | NM | | HRA-100-() |
| TSO-C87 | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. Avionics Facility 5353 West Bell Road Glendale, AZ 85308 | NM | | AD-600/AD-650:7000466-() AA-220 4014267() AA-215 AA-235 ED2-605/805 DC-810, -811 DC-820:7007277-() ED600:7003430-()/ED800:7003110-() MC-800:7007062-() MG-800:7007061-() MG-603 MG-803 MG-810:7007321-() MG-817 RA-315/335:700839-() RI-820:7008703-() SC-800 SG-600/800:7003400-() SG-610/810:7004544-() SG-705 SG-817 SG-811 SG-820:7007356-() RM-850:7012100-943, -944, -953, -954 |
| TSO-C87 | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Sys. Div. P.O. Box 21111 Phoenix, AZ 85036-1111 | CE-C | | HG9000 HG9050D HG9010D HG9025 LG81A JG2060 MS91405-A1B YG7602AC() HG7602AC() JG1072AC() LG81J1 HG7500 LG81T HG75028C() HG7502AJ() HG7505AJ() HG7602AJ() HG7605AJ() JG1072AJ() JG1075AJ() LG81AJ01 |
| TSO-C87 | Honeywell, Inc. 8840 Evergreen Blvd. Minneapolis, MN 55433-6040 | CE-C | | JG1075AJ01 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|---|--|---|--|
| TSO-C87 *F | Japan Aviation Electronics Industry, Ltd. 21-6 1-Chome, Dogenzaka Shibuya-Ku Tokyo 150, Japan | NM-L | | JAE-JRA-100;JAE-JID-106, -107, JAE-JRTA-100 | | |
| TSO-C87 | King Radio Corp. 400 N. Rogers Rd. P. O. Box 106 Olathe, KS 66061 | CE-W | | KRA 405() KPI 5538:066-3069-00, -01, -03, -04 KPA 430:065-5030-001-01/-02/-03/-04 KAM 432:065-0091-00 KDI 573:066-1091-02 | KNI 415() | KNI 416() |
| TSO-C87 | Kollzman/IDC Avionics Gp. 170 Coolidge Ave. Englewood, NJ 07631 | NE | | 29007-() 29702-() 39711-() 29790-() 44000-() | 29711-() 29400-() 29704-() 49707-() | 26400-() 39007-() 49711-() 44400-() |
| TSO-C87 | Litton Systems, Inc. Anecom Division 2115 Calvert Rd. College Park, MD 20740 | NE | | 502 | 506 | |
| TSO-C87 | Sensor Systems, Inc. 8929 Fullbright Avenue Chatsworth, CA 91311 | NM | | S67-2002-() | | |
| TSO-C87 *F | T.R.T. Telecommunications Radioelectriques et Telephonique 5 Avenue Reaumur Zone Ind. du Petit Clamart B.P. 21, Le Plessis Robinson 92350, France | EU | | AHV3 AHV5-221() AHV502() SGR-341 IND-231A 9599 607 14932 | AHV3-04 AHV6() AHV-10 AHV-530 ERT-160 | AHV5() AHV8() AHV20 AHV-530A ANT-140 9599 607 14938 |
| TSO-C87 | U B Corporation 9829 Wilsky Blvd. Tampa, FL 33614 | CE-A | | AD43013-() | AD43011-01 | AD43011-12 |
| TSO-C88 | Aero Mechanism 20327 Nordhoff Street Chatsworth, CA 91405 | NM | AUTOMATIC PRESSURE ALTITUDE DIGITIZER EQUIPMENT | AR-800 8060-() 8142B() AM150-() 8112-M3XX() AM270-() | AR800B() 8140() 8200() 8111-X3XX() 8142 AM275-() | 8040B() 8140B() 8141B() 8211-X3XX() AM-135 |
| TSO-C88 | The Aerosonic Corporation P. O. Box 4627 Clearwater, FL 33518 | CE-A | | 10225-() AR-25-MA-() 101535-() 101435-() 101627-() 101945-() | 10250-() AR-35-MA-() 101550-() 101450-() 101635-() 102200-() | AR-15-MA-() AR-50-MA-() 101420-() 101617-() 101920-() |
| TSO-C88 | Aircraft Instruments & Development, Inc. 317 E. Lewis St. Wichita, KS 67202 | CE-W | | 37-1001-() | 37-1000 | AM250() |
| TSO-C88 | Bendix Avionics Div. P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | | 3757183-() | | |
| TSO-C88 | Bendix | NE | | 3757183-() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------|---|------|-----------|---|
| | Flight Systems Division Teterboro, NJ 07608 | | | |
| TSO-C88 | Bendix Navigation & Control Div. Teterboro, NJ 07608 | NE | | 1880512-() 1993506-() |
| TSO-C88 | Clifton Division Litton Systems, Inc. 5100 State Rd. Drexel Hill, PA 19018 | NE | | 9822-02()() |
| TSO-C88 | Clifton Precision Instrument & Life Support Div. 2734 Hickory Grove Rd. Davenport, IA 52808 | CE-W | | 3252013-() 3252014-() 3252027-() 3252028-() |
| TSO-C88 | Collins General Avn. Div. Rockwell International Melbourne Operations 1100 West Hibiscus Avenue Melbourne, FL 32901 | CE-A | | ALI-80:622-2292-001 thru -008 ALI-80A:622-3975-001 thru -008 ALI-80M:622-2701-001/-011 thru -018 |
| TSO-C88 | Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52498 | CE-W | | ADS-80: ALI-80, ALI-80A ADS-81: ALI-80A ALI-80:622-2292-001 thru -008 ALI-80A:622-3975-001 thru -008 ALI-80B:622-4425-001 thru -008 ALI-80L:622-6238-001 thru -008 ALI-80M:622-2701-001 |
| TSO-C88 | Dorne & Margolin, Inc. 2950 Veterans Memorial Hwy Bohemia, NY 11716 | NE | | DM C50-() DM-C50-3 |
| TSO-C88 | EDO-AIRE Wichita Division 1326 S. Walnut St. Wichita, KS 67213 | CE-W | | 1U 306 1U 309 |
| TSO-C88 | Evergreen Systems Int'l 31336 Via Colinas #103 Westlake Village, CA 91362 | NM | | 580-() |
| TSO-C88 | Hamilton Standard Div of United Aircraft Corp Windsor Locks, CT 06096 | NE | | HSA 101 HSA101():748430-() HSA102():748430-() |
| TSO-C88 | Harrowe Systems, Inc. 255 Great Valley Parkway Malvern, PA 19355 | NE | | 4019-() |
| TSO-C88 | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Sys. Div. P.O. Box 21111 Phoenix, AZ 85036-1111 | CE-C | | HG-180 HG-180U-() HG-180V-() HG280D-() HG 9050D HG 180U/V HG 280D-() HG280D80-() HG-480B() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|-----------|--------------------------|--------------|---------------|
| TSO-C88 | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. 21111 N. 19th St. Phoenix, AZ 85027 | NM | | 2587400-176 | 2587400-196 | 2587400-436 |
| | | | | 2587400-437 | 2587400-542 | 2587400-637 |
| | | | | 2587400-844 | 2587400-936 | |
| | | | | 2590005-146 | 2592800-() | 2593200-() |
| | | | | 4013243-() | 4031800-() | |
| | | | | HG2800-() | HG280080-() | HG480B() |
| TSO-C88 | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. Avionics Facility 5353 W. Bell Road Glendale, AZ 85308 | NM-L | | 4010317-() | 4013241-() | 4013242-() |
| | | | | 4013244-() | 7000700-() | |
| | | | | 4013242-726, -727 | | |
| | | | | 401A | 801A | |
| | | | | AZ-800:7000700-942 | | 7000700-944 |
| | | | | AZ-810:7000700-940 | | 7000700-937 |
| | | | | AZ-800:7000700-936 | | 7000700-939 |
| | | | | AZ-800:7000700-943 | | |
| | | | | AZ-800:7000700-938 | | |
| | | | | AZ-800:7000706-938 | | |
| | | | | AZ-800:7000700-834 | | |
| | | | | AZ-800:7000700-948 | | |
| TSO-C88 | H T Instruments Inc. 4121 Redwood Ave. Los Angeles, CA 90066 | NM | | AD/100() | | |
| TSO-C88 | Instruments & Flight Research, Inc. 2716 Geo. Washington Blvd. Wichita, KS 67210 | CE-W | | E41-20 IFR41:5934-() | E41-25 | E41-34 |
| TSO-C88 *F | Jaeger Division of Aeronautique 92303 Levallois - Perret France | EU | | 64111-3()-() | | |
| TSO-C88 | Kollzman/IDC Avionics Gp. 170 Coolidge Ave. P.O. Box 81 Englewood, NJ 07631 | NE | | 15790-() | 16000-() | 16000-8 |
| | | | | 16007-() | 16007-11 | 16007-12 |
| | | | | 16007-13 | 16007-14 | 16007-21 |
| | | | | 16007-22 | 16007-40 | 16007-41 |
| | | | | 16007-42 | 16007-43 | 16007-44 |
| | | | | 16007-45 | 16007-46 | 16007-47 |
| | | | | 16007-48 | 16007-60 | 16007-211 |
| | | | | 16007-212 | 16007-213 | 16007-214 |
| | | | | 16007-215 | 16007-216 | 16007-217 |
| | | | | 16007-218 | 16007-221 | 16007-222 |
| | | | | 17000-500 | 17000-() | 17000-12 |
| | | | | 17000-22 | 18152-1 | 18152-2 |
| | | | | 18210-() | 18210-5 | 18711-() |
| | | | | 23080-() | 24929-() | 519-22702-() |
| | | | | 25005-() | 29711-() | 29007-() |
| | | | | 29702-() | 28007-() | 28711-() |
| | | | | 28702-() | 30510-() | 38007-() |
| | | | | 39007-() | 39711-() | 32935-() |
| | | | | 29704-() | 28704-() | 49711-() |
| | | | | 34100-() | 32979-() | 48711-() |
| | | | | 38620-() | 36920-() | 46000-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-----------|---|--|---|
| TSO-C88 | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Hwy. S. Merrimack, NH 03054 | NE | | 4515()-()-() A-4154()-()-() A4430-()-()-() A4446-()-()-() A4513()-()-() A4545()-()-() ()38410 00 () B4154()-()-() B4545()-()-() ()4550()-()-() ()4552()-()-() ()4553()-()-() ()4580()-()-() ()4381()-()-() ()4583()-()-() E4245-()-()-() E4245-9-10-118 E42452-10-009 E42459-10-113 E42459-10-114 E42459-10-119 KS-200() | | |
| TSO-C88 *F | Kollsman Instrument, Ltd. Southampton, Hampshire England | EU | | L.8312()-()-() - () () () L8345()-()-() - () () () | | |
| TSO-C88 | LEARAVIA 5980 Alpha Avenue Reno, NV 89506 | NM | | 662-()Ser. | | |
| TSO-C88 *F | Leigh Instruments Ltd. Carleton Place Ontario, Canada | NE | | LE300: 01-200-102 | | 01-200-103 |
| TSO-C88 | Leigh Systems, Inc. 6081 Court Street Road Syracuse, NY 13206 | NE | | ARM-1:P/W 1201002 | | ARM-2 |
| TSO-C88 | Michel Electronics Corp. 14811 N. 73rd St. Scottsdale, AZ 85254 | NM | | L115-() | | |
| TSO-C88 | NARCO Avionics Aerospace Division 2825 Laguna Canyon Road Laguna Beach, CA 92652 | NM-L | | AR-500 | | |
| TSO-C88 | Pointer, Inc. 1027 N. Stadem Drive Tempe, AZ 85282 | NM-L | | L-115() | | |
| TSO-C88 | Sigma Tek, Inc. 17621 Black Canyon Hwy. Phoenix, AZ 85023 | NM | | 401A | | 801A |
| TSO-C88 | Smiths Industries SLI Avionic Systems Corp. 4141 Eastern Ave., S. E. Grand Rapids, MI 49518-8727 | CE-C | | 80070-() 80072-() 80090-() 80090-81104 80090-81109 80090-81112 80090-81115 80090-81130 80090-82114 | 80070-14102 80072-81101, 81102, 81103 80090-81101 80090-81107 80090-81110 80090-81113 80090-81127 80090-81131 | 80070-14103 80090-81102 80090-81108 80090-81111 80090-81114 80090-81129 80090-82113 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|--|--|
| | | | | 80070-():80070:14102, 14103 4440A1:314200-01-01 4440A2:314200-02-01 4440A3:314200-03-01 4440A4:314200-04-01 4440A5:314200-05-01 4440A6:314200-06-01 4440A7:314200-07-01 4440A8:314200-08-01 4440A17:314200-17-01 4440A18:314200-18-01 4440A19:314200-19-01 4440A20:314200-20-01 4442A1:314202-01-01 4442A2:314202-02-01 4442A3:314202-03-01 4442A4:314202-04-01 4442A5:314202-05-01 4442A6:314202-06-01 4442A7:314202-07-01 4442A8:314202-08-01 |
| TSO-C88 *F | Smiths Industries, Ltd. Aviation Division Bishops Cleeve Cheltenham, Gloucestershire England | EU | | 1101AM/() 1102AM/() 1103AM/() 1104AM/() 1106AM/() 1109AM/() 1110AM/() 1112AM/() 1113AM/() 1350AM/() 1401AM/() 1403AM/() 1404AM/() 1407AM/() 701AM 708AM thru 729AM WL1107 AM() WL1152AM() WL1381AM() WL1307AM() |
| TSO-C88 | T.C.I. Trans-Cal Ind. Inc. 16141 Cohasset St. Van Nuys, CA 91406 | NM | | DI()-P2-T Series |
| TSO-C88 | United Instruments, Inc. 2415 S. Glendale Wichita, KS 67210 | CE-W | | 5035 5500-() 5035P2-P43 5035P2-P44 5035P-P45 5035P-P46 |
| TSO C88a | ACK Technologies, Inc. 424 W. Julian St. San Jose, CA 95110 | NM-L | AUTOMATIC PRESSURE ALTITUDE REPORTING CODE GENERATING EQUIP. | AE Model A-30 |
| TSO-C88a | Aero Mechanism 20327 Nordhoff Street Chatsworth, CA 91311-6161 | NM-L | | AM 2030 |
| TSO-C88a | Ameri-King Corp. 20902 Brookhurst Street Unit 107 Huntington Beach, CA 92646 | NM-L | | AK-350 |
| TSO-C88a | B & D Instrument, Inc. 209 West Main Valley Center, KS 67147-2298 | CE-W | | ADC 2800-XXX 2800A() |
| TSO-C88a *F | I.E.I. (Aust.) Pty. Ltd 15-17 Normandy Road Clayton, Victoria, Australia 3168 | NM-L | | E9001 |
| TSO-C88a | King Radio Corporation 400 N. Rogers Road Olathe, KS 66062 | CE-W | | KDC-481:065-0082-00 |
| TSO-C88a | Kollsman/IDC Avionics Group 170 Coolidge Avenue Englewood, NJ 07631 | NE | | 34929-() |
| TSO-C88a | NARCO Avionics Aerospace Division 2825 Laguna Canyon Road | NM-L | | AR-850 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|--|---|
| | Laguna Beach, CA 92652 | | | |
| TSO-C88a | Rosetta Micro Systems, Inc. 14272 N. 23rd Ave. Plymouth, MN 55447 | CE-C | | 8800 8900() |
| TSO-C88a *F | Smiths Industries Ltd. Defense Systems Bishops Cleeve Cheltenham, Glos. GL52 4SF United Kingdom | EU | | 503 FAD ()-() |
| TSO-C88a | Trans-Cal Industries, Inc. 16141 Cohasset Street Van Nuys, CA 91406 | NM-L | | SSD-120-() |
| TSO-C89 *F | E.R.O.S. Equipments Respiratoires a Oxygene de Secours P.O. Box 10 78370 Plaisir, France | EU | OXYGEN REGULATORS, DEMAND | MA10()() MB10()() MC5 MC10()() MC 10-08-00 MC 10-13-02 MC 10-14-00 MC 10-15-01 MC 10-19-01 MC 10-25-01 MC 10-()()-(1)()() MXM 23 MXP2 10(--) MF 10()()-()() |
| TSO-C89 | Puritan-Bennett Aero Systems 111 Penn Street El Segundo, CA 90245 | NM | | 112140-() 112145-() 112146-() |
| TSO-C89 | Robertshaw Controls Co. Aeronautical and Instrument Division 333 N. Euclid Way Anaheim, CA 92803 | NM | | 900-002-016() Series 900-700-016-() Series 900-700-040-() Series |
| TSO-C89 | Sabre Industries, Inc. 120 W. Providencia Avenue Burbank, CA 91502 | NM | | 900-002-016-() 900-700-040-() |
| TSO-C89 | Scott Aviation 225 Erie Street Lancaster, NY 14086 | NE | | 802601, -03, -41, -42, -43, -44 802602 802730-() |
| TSO-C90 *F | L'Aiglou S.A. P.O. Box 236 1, Blvd. Gaston Birge 49009 Angers, France | EU | CARGO PALLETS, NETS AND CONTAINERS | 2A6N()()()() 2M1N()()()() |
| TSO-C90 | Air Cargo Container, Inc. 3030 South Oak Street Santa Ana, CA 92707 No longer manufacturing at this address. | | | |
| TSO-C90 | Air Cargo Equipment Corp. 1550 N. 105th East Avenue Box 15630 Tulsa, OK 74112 | SW | | 441(DCT 1201) 101(1304) DCT 1250 DCT 1505 (-1, -501, -503, -505) DCT 1165 |
| TSO-C90 | Air Cargo Equipment Corp. 17923 South Santa Fe Ave. Compton, CA 90220 AND Transequip Inc. 17923 South Santa Fe Ave. | NM-W | | 441(DCT1201) 101(DCT1304) DCT1250-() DCT1505-() DCT1168-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|-------------------|---|------|-----------|---|--|---|
| Compton, CA 90220 | | | | | | |
| TSO-C90 *F | Aluminium-Walzwerke Singen GmbH Singen, West Germany | EU | | Type 2.1 2.4 LD-3:2-1-(), 2-2-(), 2-3-(), 2-4-(), 2-5-(), 2-6-(), 2-10-(), 2-11(), 2-12(), 2-13(), 2-14-(), 2-15-(), 2-16-(), 2-21-(), 2-22-(), 2-23-() | 2.2 2.5 1-2 6-5 | 2.3 2.6 1-4 |
| TSO-C90 | ANCRA Corporation 4880 W. Rosecrans Ave. Hawthorne, CA 90250 | NM-L | | 40143-10 40516-10 40652-10 41945-10 42709-11 43146-10 43209-10 | 40445-10 41052-10/-11 41375-10 41846-10 42939-10 43153-10 43214-10 | 40178-10 40600-10 41746-10 42397-10 43137-10 43163-10 4335-10 |
| TSO-C90 *F | A/S Nordisk Aluminiumindustri (N.A.I.) P.O. Box 222 N-3081 Holmestrand, Norway | EU | | UA 110800 UA.111176-A UA.111422-A UA-111422W-A UA-111460A UA 111460W-A UA-111422-H UA-113343W-A | UA 110801 UA.111176-B UA-111422-B UA-111422W-B UA-111460-B UA-111460W-B UA 111422W-H UA-113343W-B | UA 110881 UA.111176-E UA-111422-E UA-111422W-E UA-111460-E UA-111460W-E UA-112651 UA-113343W-H |
| TSO-C90 *F | Autoflug GmbH Industriestrasse 10 Postfach 1180 D 2804 Rollingen 2 Germany | EU | | LSN-1 | LSN-2 | |
| TSO-C90 *F | Bridport-Gundry, Ltd. Bridport, Dorset England | EU | | BG/FN/790() BG/FN/845() BG/FN/956() BG/FN/940() BG/FN/965() BG/FN/1140() BG/FN/1196() BG/FN/1530() | BG/FN/816() BG/FN/790/B() BG/FN/965() BG/FN/948 BG/FN/1139() BG/FN/1171() BG/FN/1008() | BG/FN/795() BG/FN/924() BG/FN/1051() |
| TSO-C90 | Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150 AND 30030 Minglewood Land Farmington, MI 48024 | CE-C | | 17227-100 17355-100 17348-100 17385-100 17429-101 17430-100-3 17437-100 17510-100 17453-500 17437-100 17557-100 17628-E-100 17662-E-100 17678-E-100 17708-E-100 17731-E-100 17728-E-100 17734-E-100 17789-E-100 17809-E-100 17853-E-100 | 17277-100 17360-100-() 17360-101-() 17429-100-1 17430DL 17430-100-2 17450-100 17469-500-1 17543-100 17436-100 17590-E-100 17618-E-100 17666-E-100 17694-E-100 44325() 17721-E-100 17748-E-100 17741-E-100 17796-E-100 17828-E-100 17865-E-100 | 17348 17429-100-2 17430-100 17436-100 17481-100 17497-100 17550-100 17557-E-100 17593-E-100 17632-E-100 17671-E-100 17699-E-100 17715-E-100 17572-E-100 17766-E-100 17773-E-100 17804-E-100 17831-E-100 17881-E-100 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------|--|----|-----------|-------------------------|-------------|-----------------|
| | | | | 17886-E-100 | | |
| TSO-C90 | Brownline/Brooks & Perkins An AAR Company 2950 W. Lomita Blvd. Torrance, CA 90505 | NM | | 24276() | 24545() | 24540() |
| | | | | 40160() | 40535() | 40560() |
| | | | | 40978() | 41661() | 41675() |
| | | | | 41985() | 42291() | 42292() |
| | | | | 42380() | 42380-301 | 42381() |
| | | | | 42610() | 47385() | 43833() |
| | | | | 43968() | 44325() | 44344() |
| | | | | 44660() | 45156() | 45869() |
| | | | | 46400() | 46389-() | 46474-() |
| TSO-C90 | Brownline Ltd. Hounslow, Middlesex England | EU | | 10-41675() | 10-40144() | LON.BL.509() |
| *F | | | | 10-40309() | 10-42380() | 10-40850() |
| | | | | 10-42380-301 | | |
| | | | | 88 x 125: 42380() | | LON-BL-2010() |
| | | | | LON-BL-2001() | | LON-BL-2080() |
| | | | | LON.BL.2083() | | LON-BL-2128 |
| | | | | LON BL 2340() | | LON-BL-2300-101 |
| | | | | LON-BL-2285() | | LON-BL-2095() |
| | | | | LON-BL-2001-103, -104 | | LON-BL-2001-104 |
| | | | | LON-BL-2850-101 | | LON-BL-2849-101 |
| | | | | LON-BL-2650() | | |
| TSO-C90 | Bruggemann & Brand KG 5802 Wetter - Ruhr4 Wengern, West Germany | EU | | 210112 | 210312 | 210422 |
| *F | | | | 210411() | 210442 | 210522 |
| | | | | 210542 | 211011 | 211212 |
| | | | | 211212() | 2103424() | 2103428() |
| | | | | 2101123-11 | 210322-11 | 221032 |
| | | | | 223012 | 224072 | 224082 |
| | | | | 224110 | 224162 | 224172 |
| | | | | 224192 | 224202 | 22427 |
| | | | | 224192-() | 224372 | 224352-() |
| | | | | 224382 | 224402 | 225022 |
| | | | | 225062 | 2104421() | 2104422 |
| | | | | 2112121 | 2210011 | 2104423 |
| | | | | 2104424 | 2104425 | 2104426 |
| | | | | 2104428 | 2241723-() | 2241726 |
| | | | | 2241921 | 2241922 | 2243221 |
| | | | | 2243222 | 2250121 | 2250221 |
| | | | | 2250223 | 2250621 | 226042-31 |
| | | | | 2260121 | 2105421 | 270300-11 |
| | | | | 270300-12 | 270734() | 270580-() |
| | | | | 270580-11 | 270580-12 | 270580-14 |
| | | | | 270580-15 | 270233 | 270620 |
| TSO-C90 | Burger Eisenwerke AG 6348 Herborn West Germany | EU | | 33.61.01-20.000.00.00 | | |
| *F | | | | 33.61.01-30.000.00.00 | | |
| | | | | 33.61.01-30.000.00.00-R | | |
| TSO-C90 | Envirosales Corporation 449 North Oak Street Inglewood, CA 90302 | NM | | V8-1110 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|-----------|--|---|---|
| TSO-C90 | Fleet Equipment Corp. P.O. Box 90452 World Way Center Los Angeles, CA 90009 | NM | | 27800-() 578000-101 | 27801-() 578000-103 | 27802-() |
| TSO-C90 *F | Fokker-VFW B.V. Plant Avio-Fokker Vliegveld Ypenburg Rijswijk (Z-H) The Netherlands | EU | | 6038-1-0000-401 X10630-801/803 X.10630-813 X.10646-401 X.10397-405 X.10155-801 | X.10630-815 X.10646-402 X.10397-701 | X.10251-803 X.10630-805 X.10630-817 X.10397-403 X.10397-703 |
| TSO-C90 | Fruehauf Corporation Research & Development Div. P.O. Box 238 10900 Harper Ave. Detroit, MI 48232 | CE-C | | KF2-10-AIR/P() KF2-10-AIR/E() KF2-20-AIR-P() KF2-20-AIR/E() | | |
| TSO-C90 | Goodyear Aerospace Corp. Arizona Division Litchfield Road Litchfield Park, AZ 85340 | NM | | 625A307-001-101 625A407-001-101 625A303-001-() 625A407-001-() 625A300-001-101 625A303-001-101 625A405-001-101 625A406-001-101 625A300-001-103 625A300-001-105 | | |
| TSO-C90 | Irvin Industries, Inc. California Division 15001 S. Figueroa St. P. O. Box 300 Gardena, CA 90248 | NM | | 410033() 409053() 125001-() | 410034 415111() | 415019 125019() |
| TSO-C90 *F | Irvin Manifatture Industriali S.p.A. Aprilia, Italy | EU | | IMI 6.1.48 IMI 6.1.54() | IMI 6.1.58() IMI 6.1.64() | |
| TSO-C90 *F | Carl Fouche Languepin 55, Rue d'Amsterdam 75366 Paris, France | EU | | C11-1M() | | |
| TSO-C90 | Litewate Transport Equip. Div. of Stanray Corp. Boulevard & Grape St. Vineland, NJ 08306 | NE | | 622004() | | |
| TSO-C90 *F | Messerschmitt-Bolkow-Blohm 8850 Donauworth Hamburg, Germany | EU | | 4054 4065 4053 4080 | 4061 4055 4067 4088 | 4064 4069 4070 |
| TSO-C90 *F | Nippon Sharyo Seizo Kaisha, Ltd. Aircraft Container Eng. 33, 2-chome, Nihonbashi Kabutocho, Chuo-ku Tokyo 103, Japan | NM-L | | M2:P/N R20891-111 | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-----------|---|---|---|
| TSO-C90 *F | Nordisk Aluminium A/S P.O. Box 222 N-8081 Holmestrand Norway | EU | | UA-114054 UA-115169 | UA-114641 UA-114960 | UA-113270 |
| TSO-C90 | Omni Equipment, Inc. 2454 N.W. 151st St. Opa Locka, FL 33054 | CE-A | | OP-15() | | |
| TSO-C90 *F | SABENA Brussels National Airport B-1930 Zaventem Belgium | EU | | 1-8230 1-A19973 | 1-8341 1-A19774 | |
| TSO-C90 | Satco, Inc. 1509 E. El Segundo Blvd. El Segundo, CA 90245 | NM | | 31084-() 31122-() 31121-501 31089-503 31322-() 31500-() 31607-() 31630-() 31855-() | 31089-() 31084-501 31122-501 31121-503 31324-() 31601-() 31086-() 31663-() 31930-() | 31121-() 31089-501 31084-503 31122-503 31440-() 31605-() 31608-() 31831-() 31931-() |
| TSO-C90 *F | Showa Aircraft Industry Co. No. 3.3 Chome Nihon bashi-Muromachi Chuo-kee Tokyo, Japan | NM-L | | LD3-86000 | | |
| TSO-C90 | Transequip, Inc. 17923 South Santa Fe Avenue Compton, CA 90220 AND Air Cargo Equipment Corp. 17923 S. Santa Fe Avenue Compton, CA 90220 | NM | | 210411() 210511() 224192() 225132 225230 235720() 235809() 235974() 300128() 300203() 300320-3, -5, -7 300349() 300674() 300698() 300888() 301203() 301325() 301325() 301475() 301505() 301600() 301686() 301843() 301850() 301933() 302145() 302375() 302639() 302719() 302927() 303098() 303296() 303920() 303972() 2241726() | 210412-() 224042() 225012-() 235530() 235720 235890() 235979-1 300155() 300320() 300551() 300683() 300699() 301015() 301261() 301397() 301397() 301498() 301566() 301645() 301707() 301848() 301860() 301935() 302158() 302422() 302648() 302756() 302933() 303107() 303298() 303925() 303985() 2104421-() | 210442() 224110() 225122 235530-00 235750() 235899() 270580() 300173() 300575() 300915() 300872() 301148() 301307() 301446() 301446() 301500() 301590() 301676() 301838() 301849() 301911() 301972() 302250() 302598() 302689() 302853() 302966() 303289 303916() 303927() 304021() 2243221() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|--|--|--|--|
| | | | | 304376() | 107J420-() | 107J318-1 |
| TSO-C90 *F | Transequip Limited Feltham, Middlesex England | EU | | 210411 210512 235530-11 224192() 235979-1 301015-() 2250621() 302639() 301848() | 210412 210611 224110 2243221() 235974() 301645() 301860() 303098() | 210511 235530 224202 235889() 224082-() 302145() 301972() 303916() |
| TSO-C90 | The Vinnedge Corporation 1125 12th NW., Bldg. B Issaquah, WA 98027 | NM | | V8-1110 | | |
| TSO-C90a | AAR Brooks & Perkins Brownline Division 2950 West Lomita Blvd. Torrance, CA 90509-2966 | CE-C | CARGO PALLETS, NETS AND CONTAINERS | 47161() 47675() 47697() | 47194() 47690() 47861() | 47361() |
| TSO-C90a | AAR Brooks & Perkins Cadillac Mfg. Division P.O. Box 550 Cadillac, MI 49601 | CE-C | | 45156-() 47161-() | 45869-() | 46400-() |
| TSO-C90a *F | Additainer AB (ATAB) Box 7096 S-30007 Halmstad Sweden | EU | | Container Coaltainer LD-3 NAS-3610 | | |
| TSO-C90a | Aero Canvas Products of Ohio, Inc. 1714 John Street Cincinnati, OH 45214 | CE-C | | 7-727-TR | | |
| TSO-C90a *F | L'Aiglon S.A. P.O. Box 1926 1, Blvd. Gaston-Birge 49009 Angers, France | EU | | 2AIN()()()() | | |
| TSO-C90a | Air Cargo Equipment Corp. 17923 S. Santa Fe Avenue Compton, CA 90220 AND Transequip, Inc. 17923 S. Santa Fe Avenue Compton, CA 90220 | NM-W | | DCT2165-() DCT2215-() 43502-() 45903() 46823-() 47177() 47258() 47510() 47576() 47623() 47841() 48130() 020011() DCT-2730 42291-() 43785-() 47484-() | DCT2100-() DCT2219() 43975() 45999() 46823-201 47256() 47392() 47566-201 47784() 47679() 48000() 48140() DCT-2563 40978-() 42292-() 43833-() | DCT2108-() 43191() 45870-201 46631-6 46902() 47257() 47394() 47566() 43191() 47786() 48004() 020001() DCT-2694 41675-() 422610-() 44344-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|--|
| TSO-C90a | Air Freight Containers, Inc. 7650 South 196th Kent, WA 98031 | NM | | Model I 30100() 31100() Model II() 20110 Model I(-3):20000() 35000() 10000-() |
| TSO-C90a *F | Aluminum Walzwerke Singen GmbH Alusingen Platz 1 P.O. Box 160 D-7700 D-7700 Singen/Hogentwiel, Germany | EU | | 2-12/2-15/2-16 2-21(B)- () 2-21(BS)- () 2-22(B)- () 2-22(BS)- () 2-24(B)- () 2-24(BS)- () 2-26(B)- () 2-26(BS)- () 5-2(), 5-12() 60.4x125x64, Series 3-2, 006112- NAS 3610-2L2C LD-1 1-2A 1-4A LD-3:003111, 003211, 003214, 003311, 003122-, 003112, 003212, 003216, 003312, 003121, 003221, 003321, 003224, 003222, 003322, 003226, 003233, C-3226 PA-6(), PB-6, PM-3 001121 001123 001221 001222 001321 001322 001224 001226 Series 001111 001211 001311 001112 001212 001312 001214 001216 LD-3:CL3111, CL3112, CL3211, CL3212, CL3311, CL3312 4M-3111, -3112, -3211, -3212 4M-3311, -3312 4M31SI |
| TSO-C90a *F | Aluteam Geratebau, GmbH Postfach 1160 5440 Mayen Germany | EU | | LD-3: 02252() 02450-() |
| TSO-C90a | American Igloo Corp. 7845 N.W. 66th Street Miami, FL 33166 | CE-A | | AIC-1000 02 02008-0() 02009-0() 02010-0() 02028-0() 02029-0() 02030-0() |
| TSO-C90a | Ankra Corporation 4880 W. Rosecrans Avenue Hawthorne, CA 90250 | NM-L | | 43405-10 43521-10 43532-10 43542-10, -11 43539-10 43541-10, -11 43552-10 43683-10 43412-10 43820-10 43966-10 43974-10 44015-10 44016-10 44024-10, -11, -12, -13 44025-10, -11, -12, -13 44026-10, -11, -12, -13 44027-10, -11, -12, -13 44079-10 4080-10 44124-10 44229-10 |
| TSO-C90a *F | Bridport-Gundry Ltd. Bridport, Dorset England | EU | | 3G 125"x88"x96" BG/FN/965() 3G 240"x96"x96" BG/FN/1140() 3G 108"x88"x80" or 96" 3G 125"x60.4"x80" 3G 125"x80"x96" or 118" 3G 125"x88"x96" or 118" BG/FN/940() BG/FN/1706() BG/FN/1123() BG/FN/1790() BG/FN/2117() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|---|--|---|
| TSO-C90a *F | Bristol Air Cargo Containers, Ltd. Unit 7, Weston Industrial Estate Winterstake Road Weston super Mare Avon, England | EU | | LD3:BACC 1000() | | LD6:BAAC6000() |
| TSO-C90a | Brownell & Company, Inc. Moodus, CT 06469 | NE | | BG/FN/BR 1139 BG/FN/BR 1140 BG/FN/BR 1205 BG/FN/BR 1530 BG/FN/BR 1560 BG/FN/BR 1706-() BG/FN/BR 1790-() BG/FN/BR 1975 | | |
| TSO-C90a *F | Brownline, Ltd. Hounslow Middlesex, England | EU | | LON-BL-2592() LON-BL-2769() LON-BL-2900() LON-BL-3760() 10-42381() 10-47690-() | | LON-BL-2756() LON-BL-2804-() LON-BL-3200() LON-BL-3697() 10-47675() 10-47697() |
| TSO-C90a *F | Bruggeman & Brand KG 5802 Wetter, Ruhr 4 Wengern, West Germany | EU | | 274330-11 2101127-11, 12, 14 2103424-11 2103427-11 210352-() D3:274799-L, 274799-R, 280360-L 221033-31, 221033-32 223022-31, -32, -33 223022-34, -35 2125122-11 2125123-11 | 2104427-11 14 2103425-11 2103428-11 210452-() | 2101124-11 2101129-11, -12 2103426-11 2103424-12 |
| TSO-C90a | C & J Enterprises 106 North Street Wilder, KY 41071 | CE-A | | 8610-101 | | |
| TSO-C90a | Cargo Systems, Inc. P.O. Box 241 Edmond, OK 73083 | SW | | CS-8501 CS-8502 | | |
| TSO-C90a | Century Aero Products 1435 S. Sante Fe Ave. Compton, CA 90221 | NM-L | | ULD 2A5 LD1 LD26 | LD6 LD3 | LD29 ULD2K2 |
| TSO-C90a *F | Coder Industries 189 blvd de la Valbareille BP4 13367 Marseille Cedex, France | EU | | Codair Alpha 302(XXX) | | |
| TSO-C90a *F | Construction Ferroviaires & Metalliques S.A. 1400 Nivelles Belgium | EU | | 40N.409.446 40N.409.478 | 40N.409.476 | 40N.409.477 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|---|
| TSO-C90a *F | Diethelm Industries Pte., Ltd. 303 Alexandra Road Republic of Singapore 0315 | NM | | NAS-3610-2K2C:2-21B/BS, 2-22B/BS, 2-24B/BS, 2-26B/BS NAS3510-2K2C NAS 3610-2MIC:1-2A NAS 3610-2MIC:1-4A |
| TSO-C90a | Envirosales Corporation 449 North Oak Street Inglewood, CA 90301 | NM | | LD-3R: EVS-2110-() |
| TSO-C90a *F | Field Aviation South Africa LTD. Rand Airport Germilston, S. Africa | EU | | NAS 3610 LD 3 A.K.E. |
| TSO-C90a | Fleet Equipment Corp. P.O. Box 90452 World Way Center Los Angeles, CA 90009 | NM | | 27803() |
| TSO-C90a *F | Frigotainer AB Norslunda, Gard S19040 Rosersberg, Stockholm, Sweden | EU | | FT-RAK FT-120001 FT-130001 FT-140001 |
| TSO-C90a *F | Grapei International B.P. No. 1 Zone Artisanale de la Bohalle 49800 Brain-sur-l'Authion France | EU | | NAS3610-2A1N: A11301(XXXX)(XXXX)(X) NAS3610-2N2N: M11301(XXXX)(XXXX)(X) |
| TSO-C90a *F | Hydro Aluminium A/S Nordisk Aviation Product Holmestrand Norway | EU | | UA-P18 990 UA-120030-A UA-120030-B UA-120030-M UA-118 990 UA-118996 UA-115607-1 NAS 3610-2K2C UA-P15 324-2 UA-P15 324-3 UA-P15 479-3 UA-P15 479-5 UA-P15 180-1 UA-P15 180-2 UA-P15 180-3 UA-P15 180-4 UA-P15 180-5 UA-P15 169-1 UA-P15 169-2 UA-P15 169-3 UA-P15 169-4 UA-P15 169-5 UA-P15 169-5H |
| TSO-C90a *F | Innovationsbolaget Frigotainer AB Norslunda Gard S-19040 Rosersberg Sweden | EU | | 140003 |
| TSO-C90a | M.C. Gill Corp. 4056 Easy St. El Monte, CA 91731-1087 | NM-L | | Model 577 LD3 |
| TSO-C90a | Morgan Trailer Mfg. P.O. Box 258 Morgantown, PA 19543 | NE | | M-2 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|-----------|---|--|--|
| TSO-C90a *F | Nippon Sharyo Seizo Kaisha, Ltd. 13, 2-Chome, Nihombashi Kabuto-cho Chuo-ku Tokyo 103, Japan | NM-L | | LD-3V LD-3V LD-3V LD-3V LD-3V LD-2EX LD-2EX LD-2EX LD-2EX | R21222-101A, B, C, D, E, F R21222-102A, B, C, D, E, F R21222-104A, B, C, D, E, F R21222-111A, B, C, D, E, F R21222-112A, B, C, D, E, F R21222-114A, B, C, D, E, F R21255-101A, B, C, D, E, F R21255-104A, B, C, D, E, F R21255-111A, B, C, D, E, F R21255-114A, B, C, D, E, F | |
| TSO-C90a *F | Nordisk Aluminum A/S P.O. Box 222 N-8081 Holmestrand Norway | EU | | UA-115180 UA-115324, -2 UA-115905 UA-115169-1, -5, -5H UA-115169-2 UA-115169-4 UA-115180-2, -5 UA-115516 UA-117501 UA-117658 UA-118040-A UA-118848 | UA-115328 UA-115633 UA-115169 UA-115169-3 UA-115180-1 UA-115479-3, -5 UA 115607, -1 UA-118 320 UA-118040-B UA-118404-A, -B, -M | UA-115013 UA-114960 UA-115789 UA-118040-M |
| TSO-C90a *F | Nordskog-Diethelm Pte', Ltd. 303 Alexander Road Singapore 0315 Republic of Singapore | | | LD-1 | LD-3 | |
| TSP-C90a *F | Ribeco GmbH Postfach 101525 D-6900 Heidelberg W. Germany | EU | | NWA-D18 NWB-S18 NWL-S14 | NWB-D18 NWC-D18 NWM-D18 | NWA-S28 NWG-D40 NWM-S28 |
| TSO-C90a | Satco, Inc. 1509 E. El Segundo Blvd. El Segundo, CA 90245 | NM | | 31089-() 32075-() 32347-() 32460-() 32612-() 32660-() 32939-() 33245() | 31324-() 32123() 32380-() 32558-() 32613-() 32675-() 31930-() 33275-() | 31855-() 32265-() 32443-() 32611-() 32719-() 32764-() 33160-() 33475-() |
| TSO-C90a *F | SGH GmbH Postfach 950169 2103 Hamburg 95 Germany | EU | | 067-1000-00 | | |
| TSO-C90a | Transequip, Inc. 17923 S. Santa Fe Avenue Compton, CA 90220 AND Air Cargo Equipment Corp. 17923 S. Santa Fe Avenue Compton, CA 90220 | NM | | 210442() 235230() 235720() 300155() 300349() 300915() 301498() 301686() 301860() 302250() 302422() 302928() 2K1C/2K2C 303985() 304365() 304630() 304745() | 224042() 235530() 235750() 300203() 300575() 301307() 301500() 301838() 301935() 302598() 302853() 303920() 303925() 304021-() 304376() 304642() 304746() | 225012() 235570() 235889() 300320() 300699() 301397() 301566() 301849() 301972() 302689-() 302927() 303916() 303972() 303296() 304620() 304675() 304778() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------|--|------|---|--|---------------|------------------|
| | | | | 304821() | 304851() | 304859() |
| | | | | 305168() | 305184() | 305272() |
| | | | | 305492() | 305550() | |
| | | | | 305990() | 306000-() | |
| | | | | A-A3X-DC-() | A-A3N-DA-() | |
| TSO-C90a | Transequip Ltd. | EU | | 301686() | 301860() | 236733() |
| *F | Feltham, Middlesex England | | | 236682() | 236853() | 236854() |
| | | | | 236930(-1, -2) | | |
| | | | | 302719() | 302966() | A-A6A-DC-() |
| | | | | A-A29U-N() | A-A16U-N() | A-A26F-N() |
| TSO-C90a | Van Riemsdijk Rotterdam | EU | | 441.077 | 489.003 | 725.001 |
| *F | Air Cargo & Ground Sup. Eq. Pottermstraat 21 P.O. Box 5013 3008 AA Rotterdam The Netherlands | | | | | |
| TSO-C90b | AAR Brooks & Perkins | CE-C | CARGO PALLETS, NETS, AND CONTAINERS | 40309-() | 15924-() | 50021-() |
| | P.O. Box 550 Cadillac, MI 49601 | | | 40144-() | 24545-() | 24546-() |
| | | | | 50043-() | | |
| TSO-C90b | Air Cargo Equipment Corp. | NM-L | | 2K3N:DNT2733 | | M-3:DCT2800-() |
| | 17923 S. Santa Fe Ave. Rancho Dominguez, CA 90220 | | | 2K3P:DPA2739 | | NAS3610 2A5P |
| | | | | M-3:DCT3050() | | LD-3:DCT2865-() |
| | | | | M-1:DCT3125 | | |
| TSO-C90b | Airline Container Manufacturing Co., Inc. | NE | | Cargo Container | | |
| | 1300-A Access Road Oceanside, NY 11572 | | | | | |
| TSO-C90b | Aluminium-Walzwerke | EU | | LD3:Type CL3N:Series CL3N22 | | |
| *F | Singen GmbH Alusingen Platz 1 P.O. Box 160 D-7700 Singen/Hogentwiel Germany | | | LD3:Type CL3:Series CL3214, CL3216, C13218, CL3219, CL3121, CL3122, CL3221, CL3222, CL3321, CL3322, CL3224, CL3226, CL3228, CL3229 | | |
| | | | | LD3:Type CB3:Series CB3111, CB3112, CB3211, CB3212, CB3311, CB3312, CB3214, CB3216, CB3218, CB3219, CB3111S, CB3112S, CB3211S, CB3212S, CB3311S, CB3312S | | |
| TSO-C90b | Alusingen GmbH | EU | | Type PK 3(60,4" x 61,5"):Series PK327, PK330, PK334, PK338, PK348 | | |
| *F | Platz 1 P.O. Box 160 D-7700 Singen/Hogentwiel Germany | | | A320 LD:Type H1:Series H1-() 88" x 125"x 64":Type AAPN: Series AAPN-() LD1:Type CB1:Series CB1-() A320 LD:Type 5H:Series 5H112, 5H212 60.4"x125"x64":Type ALPN:Series ALPN-() 60.4" x 125":Type PL3:Series PL3() | | |
| TSO-C90b | Bridport Gundry Ltd. | EU | | AC10-02250() | | |
| *F | United Kingdom | | | | | |
| TSO-C90b | Bridport Aviation Products | EU | | AC10-02270() | AC10-02163() | |
| *F | United Kingdom | | | | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|----------------------------------|--|
| TSO-C90b *F | British Columbia Research Corp. 3650 Wesbrook Mall Vancouver, B.C. V6S 2L2 | NE | | LD3-45 |
| TSO-C90b | C & J Enterprises 4086 Limaburg Road Wilder, KY 41048 | CE-A | | CJE-90 |
| TSO-C90b | Century Aero Products International Inc. 1515 South Santa Fe Avenue Compton, CA 90221 | NM-L | | LD3-45:T45DR-B(*)-(**) T45 DOR-B(*)-(**) (*) value of pallet plate thickness must be 106 inch or greater (**) Panel minimum thickness 0.06 Polycarbonate (15p), or 0.024 Aluminum (6A) |
| TSO-C90b *F | Hydro Aluminium A/S Nordisk Aviation Products Holmestrand, Norway | EU | | UA-115 324-5 UA-P15 324-5 UA-119 622 UA-119 622-1 UA-119 622-2 NAS 3610-2A2C:UA-115633-2 NAS 3610-2K3P:UA-117506 NS 3610-2K2C:UA-115479-6 NAS 3610-2G1P:UA-118318 NAS 3610-2K2C:UA 115324-7 NAS 3610-2K2:UA-119622-4 NAS 3610-2K2:UA-P19622-4 NAS 3610-2M3C:UA-120865 NAS 3610-2M3C:UA-120865-1 |
| TSO-C90b *F | Japan ACE Company, Ltd. 1-5 Minaminoma Haguroshinden, Inuyama City Aichi Prefecture, Japan | NM-L | | LD-3J02001:J020001-102 LD-3J02001:J020001-101, 102A LD-3J020011:J020011-101 LD-1J020051:J020051-101 LD-3J020061:J020061-101 |
| TSO-C90b | Satco Inc. 1509 East El Segundo El Segundo, CA 90245 | NM-L | | NAS3610-2K2C:33675-() NAS3610-2A2C:3370-() NAS3616-2M1CD:33977-() NAS3610-2A5C:33903-() |
| TSO-C90b *F | Transequip Limited Unit 12, Space Waye, Feltham, Middlesex TW140th England | EU | | A-A6F-N () NAS 3610:A-AB58082() 96"x125"/3160:PMC-() 88"x125"/3160:PAG-() |
| TSO-C90b *F | Van Riemsdijk Rotterdam Air Cargo & Ground Support Equipment Stolwijkstraat 57 3079 DN Rotterdam The Netherlands | EU | | 441.139 545.001 |
| TSO-C91 | ACR Electronics 112 Voice Road Carle Place, NY 11514 | NE | EMERGENCY LOCATOR TRANSMITTER | RLB-6 |
| TSO-C91 | ACR Electronics, Inc. 3901 N. 29th Avenue Hollywood, FL 33020 | CE-A | | ACR/RLB-101() |
| TSO-C91 | Aero Electronics Development Company, Inc. | NM | | POINTER-11() Type (P)2000-1 2000()Ser. |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|-----------|---|
| | 112 Industrial Dr. Tempe, AZ 85281 | | | Type AP/AF3000-1 3000()Ser. |
| TSO-C91 | Aircraft Products Div. Pacific Communications, Inc. 2041-A South Grand Ave. P. O. Box 10392 Santa Ana, CA 92705 | NM | | 50 - 010-01070-5() 60 - 010-01070-1() 70 - 010-01070-3() |
| TSO-C91 | Anderson Manufacturing Co. 4601 E. 18th St. #32 Vancouver, WA 98661 | NM | | GS-21:RA-65 |
| TSO-C91 | Artex Acft. Supplies, Inc. 24368 South Skyline Drive Canby, OR 97013 | NM | | SHARC 7 ELT Magnesium Battery Pack - ELT Lithium Battery Pack - ELT 10, ELT 11 00-10-009, 00-10-006 Magnesium Battery Pack - Garrett Rescu 88 ELT Alkaline Battery Pack 00-22-006 Alkaline Battery Pack 00-25-004, 00-50-004 Alkaline Battery Pack 00-60-13, 00-60-14 Magnesium Battery Pack 00-60-02, 00-60-07, 00-30-004 Rescu 99 R99 R-88-9V ELT Battery Pack 1800 ELT 6.0 Battery Pack - 00-60-62, 00-60-61 |
| TSO-C91 *F | Burndep Electronics, Ltd. St. Fidelis Road Erith - Kent DA8 1AU England | EU | | BE.369 Mk.2 |
| TSO-C91 | Communications Components 3000 Airway Ave. Costa Mesa, CA 92626 | NM | | CIR-10() CIR-11() |
| TSO-C91 | Dayton Aircraft Products MarTech Division 812 N. W. First St. Ft. Lauderdale, FL 33310 | CE-W | | EB-2B(CD) EB-2B(W) |
| TSO-C91 | Dayton-Granger, Inc. West Coast Division 3000 Airway Avenue Costa Mesa, CA 92626 | NM | | CIR-10-() CIR-11-() |
| TSO-C91 | Dayton-Granger, Inc. P.O. Box 350550 Fort Lauderdale, FL 33335 | CE-A | | EB-2BW EB-2BCD EB-23CD CIR-11-7 ELT10-234-2 ELT10-209 ELT10-214-2 |
| TSO-C91 | Deft Laboratories, Inc. 7 Adler Drive East Syracuse, NY 13057 | NE | | SHARC-7 DEFT-1 |
| TSO-C91 | DME Corporation 111 SW. 33rd Street Fort Lauderdale, FL 33315 | CE-A | | RLB-5() RLB-9() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|---|------|-----------|--|
| TSO-C91 | Dorne & Margolin, Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM ELT1-3 DM ELT 1-3-1 DM ELT 4-1 DM ELT 4-2 DM ELT 1-3(AF,AP) DM ELT 5-2 DM ELT5-2A DM ELT 6() DM ELT-8 DMU-96-1 DMU 97-2 DM Q18-2 DM Q18-3 DM Q18-4 |
| TSO-C91 | ELI's Unlimited, Inc. 15 River Street P.O. Box 1683 New Rochelle, NY 10801 | NE | | DEFT-1:05-01-002A,B Share-7: 00-04-002 |
| TSO-C91 | Emergency Beacon Corp. 13 River St. New Rochelle, NY 10801 | NE | | EBC-102A EMC-202B EBC-302 EBC 302V EBC-302VR EBC-302H EBC-302VH EBC-302VRH |
| TSO-C91 *F | Garrett Canada 255 Atwell Dr. Rexdale, Ontario Canada | NE | | Rescu/88 - 627674-() Rescu/99 - 607690-2, -3, -4, -1 Rescu/88 - 627810-() Rescu 77 - 627878-() |
| TSO-C91 | Glatzer Industries 268 Huguenot St. New Rochelle, NY 10801 | NE | | GS-21 GS-51 |
| TSO-C91 | Granger Associates 1360 Willow Rd. Menlo Park, CA 94025 | NM | | 142-() |
| TSO-C91 | Larago Electronics Mfg. Inc. 3120 44th Ave. N. St. Petersburg, FL 33730 | CE-A | | LELT 1005-AF() LELT 1005-AP() LELT 1005-P() |
| TSO-C91 *F | Leigh Instruments, Ltd. Carleton Place Ontario, Canada | NE | | ELT-132 |
| TSO-C91 | Leigh Systems, Inc. 6081 Court Street Road Syracuse, NY 13206 | NE | | Sharc 7 Series: 7A, 7B, 7E 00 07002A 05 07002 05 04 002F |
| TSO-C91 | Merl, Inc. 1777 N. Colony Road P.O. Box 188 Meriden, CT 06450 | NE | | BP-1005 79007-P 79007-AP 79007-AF BP-1010 BP-1015 BP-1020 BP-1025 BP-1037 BP-1026 BP-1030 BP-1040 BP-1045 |
| TSO-C91 | Micro Electronics, Inc. 911 Commercial Ave. Anacortes, WA 98221 | NM | | 1800()Ser. |
| TSO-C91 | NARCO Avionics Aerospace Division Div. Narco Scientific Ind. 2825 Laguna Canyon Road Laguna Beach, CA 92652 | NM-L | | ELT 10 |
| TSO-C91 | Pointer, Inc. 1027 N. Stadem Drive Tempe, AZ 85282 | NM-L | | POINTER 11-() 3000-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|--|------|---|--|------------------------|-----------------|
| TSO-C91 *F | Technisonic Industries Ltd. Unit 55 450 Matheson Blvd. Mississauga, Ontario Canada L4Z 1N5 | NE | | RESCU 88 | | |
| TSO-C91 | Trivec Avion Corporation 17351 Jamestown Lane Huntington, CA 92647 | NH | | 65-66-() | | |
| TSO-C91a | ACK Technologies, Inc. 424 W. Julian Street San Jose, CA 95110 | NH-L | EMERGENCY LOCATOR TRANSMITTER (ELT) EQUIPMENT | E-01 | | |
| TSO-C91a | Artex Acft. Supplies, Inc. 24368 S. Skyland Drive P.O. Box 1270 Canby, OR 97013 | NH-S | | 00-30-006 00-04-006A | 00-50-006 ELT 110-4 | R-88A ELS-10 |
| TSO-C91a | Arnav Systems, Inc. 16100 S.W. 72nd Ave. P.O. Box 23939 Portland, OR 97223 | NH-S | | ELT-100 | ELS-10 | |
| TSO-C91a | Aviall A Ryder System Co. 38 Industrial Park Drive Mt. Juliet, TN 37122 | CE-A | | BS2166 BS2190 | BS2173 | |
| TSO-C91a | Litton Clifton Precision 750 West Sproul Road Springfield, PA 19064-4084 | NE | | ELT:92900000-03 | | |
| TSO-C91a | MARCO Avionics Aerospace Division 2825 Laguna Canyon Road Laguna Beach, CA 92652 | NH-L | | ELT 910 | | |
| TSO-C91a | T.B.S.I. 38 Industrial Park Drive Mt. Juliet, TN 37122 | CE-A | | NA60 | DM70 | |
| TSO-C92 | Bendix Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | GROUND PROXIMITY WARNING GLIDE SLOPE DEVIATION ALERTING EQUIPMENT | CPA-83A: 2041033-() MTA-83A: 2041052-() PRA-83A: 2041053-() MTA-83B: 2041054-() PRA-83B: 2041062-() | | |
| TSO-C92 | Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | FPC-75 | | |
| TSO-C92 | Harowe Systems, Inc. 255 Great Valley Parkway Malvern, PA 19355 | NE | | 4030-01 | 4030-03 | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|---|--|
| TSO-C92 | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Sys. Div. P.O. Box 21111 Phoenix, AZ 85036-1111 | CE-C | | PG1002AA() PG1003AA() PG1004AA() |
| TSO-C92 | Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303 | NM | | 456540-() |
| TSO-C92 | Sundstrand Data Control Inc Overlake Industrial Park Redmond, WA 98052 | NM | | 965-0376-(xxx) |
| TSO-C92a | Bendix Avionics Division P. O. Box 9414 Ft. Lauderdale, FL 33310 | CE-A | GROUND PROXIMITY WARNING GLIDE SLOPE DEVIATION ALERTING EQUIPMENT | CPA-83A:2041033-() PRA-83A:2041053-() MTA-83B:2041054-() PRA-83B:2041062-() |
| TSO-C92a | Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406 | CE-W | | FPC-75 |
| TSO-C92a | Kollsman Instrument Co. Div. of Sun Chemical Corp. Daniel Webster Hwy. So. Merrimack, NH 03054 | NE | | A4598000001 |
| TSO-C92a | Litton Systems, Inc. Aero Products Div. 21050 Burbank Blvd. Woodland Hills, CA 93164 | NM | | 456540-() |
| TSO-C92a *F | Plessey Company, Ltd. West Leigh Havant Hants, England | EU | | 612/1/39898/003(Mod. 1080) |
| TSO-C92a | Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052 | NM | | 965-03760(XXX) |
| TSO-C92a *F | TRT-Telecommunications Radioelectrique & Teleph. 88, rue Brillat-Sauarin 75 Paris 13, France | EU | | AP5500() |
| TSO-C92b | Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | GROUND PROXIMITY WARNING GLIDE SLOPE DEVIATION ALERTING EQUIPMENT | CPA-83A:P/N 2041033-() MTA-83A:P/N 2041052-() |
| TSO-C92b | Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52498 | CE-W | | FPC-75:CPN622-2615-211, -212, -213, -214, -216, -226 |
| TSO-C92b | Harowe Systems, Inc. 255 Great Valley Parkway | NE | | 4030-04 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|----------------|--|------|--|--|-----------------------|--|
| ===== | | | | | | |
| | Malvern, PA 19355 | | | | | |
| TSO-C92b | Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98108 | NM | | 965-0389-004 965-0412-001, -002 965-0440-001, -002, -030 965-0476-088 965-0576-001 965-0577-001 965-0648-001 965-0650-001 965-0676-004 965-0676-006 | | 965-0576-020 965-0577-002 965-0577-015 965-0676-002 965-0676-005 |
| TSO-C92b | Sundstrand Data Control, Inc. 15001 NE 36th St. P.O. Box 97001 Redmond, WA 98073-9701 | NM-S | | 965-0876-001-(B01-B01) 965-0876-001-(A01-A01) 965-0676-008 965-0676-003 965-0648-005 965-0676-007 | | 965-0648-004 965-0284-001 965-0648-003 965-0648-003 |
| TSO-C92b *F | T.R.T. Societe de Telecommunications Radio Electriques et Telephoniques 88, Rue Brillat-Sauarin 75 Paris 13, France | EU | | APS-500 | | |
| TSO-C93 | Comant Industries, Inc. 12920 Park Street Santa Fe Springs, CA 90670 | NM | AIRBORNE INTERIM STANDARD MICROWAVE LANDING SYSTEM CONVERTER EQUIPMENT (ISMLS) | CI 153 | | |
| TSO-C93 | Tull Aviation Corp. 4 Kaysall Court Armonk, NY 10504 | NE | | 1002 Converter 1200 Antenna | | |
| TSO-C93 | U.B. Corporation 9829 Wilsky Boulevard Tampa, FL 33614 | CE-A | | TAC-1200-1 | | |
| TSO-C93 | Wilcox Electric, Inc. Microwave Landing System 2001 NE 46 Street Kansas City, MO 64116 | CE-W | | TAC 1002 | TAC 1200 | TAC 1202 |
| TSO-C94 | Bendix Flight Systems Division Teterboro, NJ 07608 | NE | AIRBORNE OMEGA RECEIVING EQUIPMENT | ONS-25-():Type | 3856107-1 | |
| TSO-C94 *F | Canadian Marconi Company 2442 Trenton Avenue Montreal, Quebec Canada H3P 1Y9 | NE | | CHA734 418-312() | CMA740 473-157-() | 418-334() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|---------------|--|------|-----------|--|
| TSO-C94 | Collins General Avn. Div. Rockwell International Costa Mesa Operations 3000 Airway Avenue Costa Mesa, CA 92626 | NM | | FMS-90 FMS-90:622-5615-(), -004 622-5614-(), -020 021, 103, 104 LRN-85T:597-0594-001 LRN-85:622-5492-()-020, -021 LRN-85A:622-5495-()-011, -012 LRN-85T:622-5492-()-202, -203 LRN-70 LRN-80 |
| TSO-C94 | Collins General Avn. Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | LRN-70 LRN-80 LRN-85 LRN-85A FMS-90 597-0594-001 |
| TSO-C94 | Communications Components Corporation 3000 Airway Avenue Costa Mesa, CA 92626 | NM | | Ontrac III: VLF1010 Ontrac IIIA |
| TSO-C94 *F | Crouzet 25 Rue Jules Vedrines 26010 Valence, Cedex France | EU | | Omega Equinox EQX 100 Omega Equinox EQX 200 |
| TSO-C94 | Dynell Electronics Corp. Melville, NY 11746 | NE | | ONS VII |
| TSO-C94 | Global-Wulfsberg Systems Div. Sundstrand Data Control, Inc. 6400 Wilkinson Drive Prescott, AZ 86301 | NM | | GNS-500A VLF: 11442-1, 11444-1, 11455-1 GNS-500A:11725-() GNS-500A-3:11600-() GNS-500A-3A Vandling NDB-2() |
| TSO-C94 | Litton Aero Products Airworthiness Engineering 6101 Condor Drive Moorpark, CA 93021-2699 | NM | | LTN 201: System P/N 457400() LTN 201: Antenna Models 6-714 AM040, 6-714 AC04, 6-714 AM042S, 599BS-04, 599C-04 LTN-211: System P/N 458280-(), 458880-01-01, -01-02, -01-03, 458286-(), 456280() LTN-211: Antenna 510028-1 LTN-211: Alternate E-Field Antenna Coupler P/Ns 458880-02-01, -02-02, -02-03, 458880-03 LTN-211: Alternate Develco Antenna 510051-1, -2, -3, -4, -5, -6 LTN-211: E-Field Coupler P/N 458710-01, 460710-01 |
| TSO-C94 | Norden Systems 75 Maxess Road Melville, NY 11746 | NE | | ONS VII: 701G - P/N 160293 ONS VII: 703 - P/N 160244 701A:P/N 165364-002 701F:P/N 160272-() 701V:P/N 165375-007 |
| TSO-C94 | Tracor, Inc. 6500 Tracor Lane Austin, TX 78721 | SW | | 7640A: 137751-() 137856-0001, 137913-0001, 137857-() 137899-0001, 137751-0003/1003, 137751-() 137954-() 137987 137000-() 138000-() 138047-0001/-0003 7800 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|---|--|
| TSO-C94 | Vandling Corporation 16270 Raymer Street Van Nuys, CA 91406 | NM | | NDB-2:20110-1-01, -02 |
| TSO-C94a *F | AWA Electronic Service Ltd 67 Lords Road Leichhardt, NSW 2024 Australia | NM-L | OMEGA RECEIVING EQUIPMENT OPERATING WITHIN RADIO FREQUENCY RANGE OF 10.2 - 13.6 KILOHERTZ | AWA 3100:8003100, 8003108, 8003175 |
| TSO-C94a | Bendix/King General Avn Avionics Div. 400 W Rogers Road Olathe, KS 66062-1212 | CE-W | | KNC 667:066-4011-12-03, -13-03 KNC 667:066-4011-24-03 KNC 667:066-4011-25-03 KNC 667:066-4011-24-05 KNC 667:066-4011-25-05 KNC 667:066-4011-00, -01, -02, -03, , -04, -05, -08, -09, -13, -11, -18, -19, -21, -23, -24, -25, -26, -27, -30, -31, -32, -33, -34, -35, -38, -39, -40, -41, -42, -43, -44, -45, -46, -47, -48, -49 KNC 667:066-4018-00, -01, -25 KNC 667:066-4019-00-07 KNC 667:006-4019-01-07 KNC 667:066-4011-24-03 KNC 667:066-4011-25-03 KNC 667:066-4011-26-00 KNC 667:066-4011-27-00 KCU 568:066-4013-62 KNC 667:066-4022-00-05 KNC 667:066-4022-01-05 KNC 667:066-4022-03 KNC 667:066-4030-01 |
| TSO-C94a *F | Canadian Marconi Company 2442 Trenton Avenue Montreal, Quebec Canada H3P 1YF | NE | | CMA-771 CHA-771 Mark III CMA-734 CMA-764-1 |
| TSO-C94a | Collins Avionics Division Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | EFD-870:622-7391-101 MEM-873:622-8009-101 FMC-851A:622-8682-001 FMC-852A:622-8683-001 CDC-850A:622-8681-001 MFD-870:622-8528-002, -003, -004, -005, -006, -007, -008, -009, -010 FMC-851A:622-8682-003 FMC-852A:622-8683-003 CDC-850A:622-8681-003 CDU-851:622-9578-001, -002 |
| TSO-C94a | Collins General Avn Div. Rockwell International Costa Mesa Operations 2990 Airway Avenue Costa Mesa, CA 92626 | NM | | FMS-90 LRN-85 LRN-85A |
| TSO-C94a | Collins General Avn Div. Melbourne Operations P.O. Box 1060 Melbourne, FL 32901 | CE-A | | LRN-70 LRN-80 LRN-85 LRN-85T LRN-85A FMS-90 597-0594-001 |
| TSO-C94a | Crouzet SA Division | EU | | Equinox 110A 87-452-068 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|-----------|---|
| *F | "Aerospatiale" Rue Jules Vedrines, 25 26027 Valence Cedex, France | | | RPU 100A 87-272-051 CDU 20 87-252-251 ACU 40 87-232-276 Equinox 210A 87-452-068 RPU 200A 87-272-051 CDU 20 87-252-251 ACU 40 87-232-276 Senson T410 RPU 400 87-272-054() Antenna Coupler Type 50 87-292-303() |
| TSO-C94a | Global-Wulfsberg Systems Div. Sundstrand Data Control, Inc. 6400 Wilkinson Drive Prescott, AZ 86301 | NM-L | | GNS-500A GNS-1000-() Ser GNS-100 GNS-X GNS-500A AFIS() 10070-() C10085-() 11455-() 20110-()-() 20204-() 30050-()-() 30054-() 30150-()-()-() 30154-() 30190-() 30300-()-()-() 30360-()-()-() 30380-()-()-() 30485-() 30490-() 30600-() 30605-() 40000-() 42000-()-()-() 42701-() 43000-()-()-() 43010-() 43005-() GNS-500A:10050-5-48-xxxx, 10050-5-4N-xxxx GNS-X:30050-0606-(xxxx) GNS-X:30050-05-05 GNS-1000:30050-2-02, Mod 10, 30050-3-03, Mod 5, 30050-5-05, Mod 6 GNS-500A:11555-() GNS-500A:10050-()-5M-() Mod N/C GNS-1000:30150-04-05, 30050-0707, -0808 |
| TSO-C94a | King Radio Corporation 400 N. Rogers Road Olathe, KS 66062 | CE-W | | KNS-660 KNC 667:066-4011-04-03/-05-03/-06-00/ -07-00/-12-00/-13-00/-22/-23/-04-04/ -05-04/-36-00/-37-00/-42/-43/-02-02/ -03-02/-24-25/-10-06/-11-06/ 066-4018-00/-01 066-4019-00-06/-01-06 066-4022-00-01/-00-04/-01-04 066-4019-00-03/-01-03 KA 168:071-1447-00 KA 167 KA-676 KA-677 KA 678 KA-679 KA-676:071-1295-00 KA-167:071-1292-00, -01 KCU-567:066-4012-00, -01, -02, -03, -10, -11, -12, -13, -20, -21, -22, -23, -30, -31, -32, -33, -52 KCU-568:066-4013-00, 01, -02, -03, -04, -05, -10, -11, -12, -13, -20, -21, -22, -23, -30, -31, -32, -33, -52 |
| TSO-C94a | Litton Systems, Inc. Airworthiness Engineering 6101 Condor Drive Moorpark, CA 93021-2699 | NM-L | | LTM-3000 Omega/VLF/RNAV LTM-311 LTM-311:461355-02-05 510028-3 461355-02-01-04 463155-02-05 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|-------------------------------------|--|------------------------|--------------------------------|
| TSO-C94a | Sperry Flight System Commercial Division 21111 N. 19th Ave. Phoenix, AZ 85036 | NM | | 4049210-() 4049214-() 4050201-() | | |
| TSO-C94a | Tracor, Inc. 6500 Tracor Lane Austin, TX 78721 | SW | | 7800 TA 7900 | TA 7880 TA 7880RCS | TA 7880S |
| TSO-C94a | Universal Navigation Corp. 3260 E. Lerdo Road Tucson, AZ 85706 | NM-L | | 15.6:1000-1-10, 11, 12, 13, 20, 21, 22, 23 1180-1-10, 11, 12, 13, 20, 21, 22, 23, 1161-1-11, 12, 13, 14, 15, 21, 22, 23, 24, 25 10305 | | |
| TSO-C94a | Universal Navigation Corp. 3545 W. Lomita Blvd. (Unit B) Torrance, CA 90505 | NM | | UNS-1:1100 Series 1101 1111 1120 1121 1122 1123 1131 1132 1133 1141 1151 1161 1162 1163 1171 1172 1173 UNS-1A:1000 Series UNS-1 Jr:1180 1030 | | |
| TSO-C95 | Avionix 8 Romanelli Street South Hackensack, NJ 07606 | NE | MACH METERS | 2C1300281() 2C130(XXXXXX) | | 2C131(XXXXXX) 3C175(XXXXXX) |
| TSO-C95 | Collins Avionics Div. M/S 124-111 Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | ADC-850:622-7208-002 ADH-85:622-8692-011 | | |
| TSO-C95 | King Radio Corporation 400 N. Rogers Road Olathe, KS 66062 | CE-W | | KDC-481:065-0082-00 | | |
| TSO-C95 | Kollzman/IDC 170 Coolidge Avenue Englewood, NJ 07631 | NE | | 40860-() 49939-() | 39310-() 44105-() | 47230-() 39310 |
| TSO-C96 *F | Flight Components AG, Zurich | EU | ANTICOLLISION LIGHTS SYSTEM | ACL-1000 | | |
| TSO-C96 | Whelen Engineering Co., Inc. Rt 145 Winthrop Road Chester, CT 06412 | NE | | Model 90033-() | | |
| TSO-C97 *F | Leigh Instruments, Ltd. P.O. Box 82 Carleton Place Ontario, Canada, K7C 3PC | NE | LITHIUM SULFUR DIXOIDE BATTERIES | 127187-1 136165-1 | 127187-2 136609-1 | 126568-1 |
| TSO-C97 | Mallory Battery Co. South Broadway Tarrytown, NY 10591 | NE | | 305061 305097 | 305078() | 305079() |
| TSO-C97 | Power Conversion, Inc. 495 Boulevard | NE | | 89529() | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | | |
|---------------|---|------|--------------------------------------|--|---|---|
| | Elmwood Park, NJ 07407 | | | | | |
| TSO-C98 | NONE | | | | | |
| TSO-C99 *F | EROS Intertechnique 8P-10 78371 Plaisir Cedex, France | EU | PROTECTIVE BREATHING EQUIPMENT | MF10()()-()() MF1902-(x) | | |
| TSO-C99 *F | L'Air Liquide Div. Techn. Avancees Les Ingenieres, BP15 38360 Sassenage, France | EU | | 1540 | 1540F() | |
| TSO-C99 | Puritan Bennett Aero Sys. 111 Penn Street P.O. Box 808 El Segundo, CA 90245 | NM-L | | 118075 | | |
| TSO-C99 | Sabre Industries, Inc. 120 West Providencia Ave. Burbank, CA 91502 | NM-L | | 900-700-036 | 900-700-040 | |
| TSO-C99 | Scott Aviation 225 Erie Street Lancaster, NY 14086 | NE | | 802300-11 10800C | 10800A 10800D | 10800B 802300-14 |
| TSO-C99 | Scott Aviation Div. of Figgie Int'l Inc. 123 East Montecito Ave. Sierra Madre, CA 91024 | NM | | 322-70:358-1030V, 358-1002V, 359-1X8XX, 359-3X8XX 359-1-(), 359-3-(), 359-6-(), 359-8-(), 358-()-V-() 10800A, B, C, D | | |
| TSO-C100 | Century Products, Inc. 1366 Commerce Drive Stow, OH 44224 | CE-W | CHILD RESTRAINT SYSTEMS | 4100 4500 | 4200 | 4300 |
| TSO-C100 | COSCO 2525 State Street Columbus, IN 47201 | CE-W | | 78() 178() 283() 378() 478() 682() | 81() 181() 313() 383() 483() | 83() 183() 323() 423() 582() |
| TSO-C100 | Pride-Trimble Corporation P.O. Box 450 Southern Pines, NC 28387 | CE-A | | 820-01 835 | 830-01 | 825 |
| TSO-C100 | Strolee of California 19067 Reyes, P.O. Box 5786 Rancho Dominguez, CA 90224-5786 | NM | | 599 609 618 | 602 610 | 604 612 |
| TSO-C101 | Collins Avionics Div. M/S 124-111 Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | OVER SPEED WARNING INSTRUMENTS | ADC-850:622-7208-002 ADM-85:622-8692-011 | | |
| TSO-C102 | NONE | | | | | |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|---|--|
| TSO-C103 | NONE | | | |
| TSO-C104 | Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | MICROWAVE LANDING SYSTEMS (MLS) AIR- BORNE RECEIVING EQUIPMENT | AT-203A ML-201A:2041975-2018 ML-211B:8095300-() CD-212B:8095301-() ML-211B:8095300(-1110) |
| TSO-C104 *F | Canadian Marconi Company 2442 Trenton Ave. Montreal, Quebec H3P 1Y9 | NE | | 100-600024-() 169-606975-(001) 100-600023-(000) CMA-2000:100-601538-() CMA-2000:169-612750-(012) CMA-2000:100-601391-() CMA-2000:100-601280-() CMA-2000:169-611465-(002) CMA-2000:100-601273-() |
| TSO-C104 *F | Chelton (Electrostatics) Ltd Marlow, Buckinghamshire United Kingdom | EU | | 10-71 10-72 |
| TSO-C104 | Dayton-Granger, Inc. P.O. Box 350550 Ft. Lauderdale, FL 33335 | CE-A | | 17950() 810001() |
| TSO-C104 | Foster AirData Systems, Inc. 7020 Huntley Rd. Columbus, OH 43229 | CE-C | | CM-850:80500760-() |
| TSO-C104 | Hazeltine Corporation Greenlawn, NY 11740 | NE | | Receiver P/M 125570-1 thru -10 Controller 125567-1 thru -4 Antenna 125568-1, -2 Antenna Preamplifier 125763 Tray, Mounting 20613 |
| TSO-C104 | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. Avionics Facility 5353 W. Bell Road Glendale, AZ 85308 | NM-L | | MLZ-900 SRZ-850 RM-850:7012100-943, -944, -953, -954 |
| TSO-C104 | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. Air Transport Facility P.O. Box 52029 Phoenix, AZ 85072-2029 | NM-L | | |
| TSO-C104 | King Radio Corporation 400 N. Rogers Road Olathe, KS 66062 | CE-W | | KFS 521A |
| TSO-C104 | Rockwell International Collins Avionics Div. 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | HPU-74B:622-9221-001 HCP-74B:622-9222-001 thru 004 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|--|--|
| TSO-C104 | Sensor Systems, Inc. 8929 Fullbright Ave. Chatsworth, CA 91311 | NM-L | | S65-5366-() |
| TSO-C105 | Bendix/King Air Transport Avionics Div. 2100 N.W. 62nd Street Fort Lauderdale, FL 33310 | CE-A | OPTIONAL DISPLAY EQUIPMENT FOR WEATHER AND GROUND MAPPING RADAR INDICATORS | CCA-4A:8056014-() |
| TSO-C105 | Bendix/King General Aviation Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | GC362A:071-01505-0101 GC360A:071-1313-10, -11, -12, -13 GC381A:071-1359-10, -11, -12, -13 |
| TSO-C105 | Collins Avionics Division 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | EFD-870:622-7391-101 MEM-873:622-8009-101 MFD-870:622-8528-002, -003, -004, 005, -006, -007, -008, -009, -010 |
| TSO-C105 | King Radio Corporation 400 N. Rogers Road Olathe, KS 66062 | CE-W | | GC-360A GC-361A:071-1312-00 thru -03 KGR-358:071-1294-00 thru -03 KGR-356:071-1261-00, -01, -02, -03 GC-381A:071-1359-00, -01, -02, -03 |
| TSO-C106 | Collins Avionics Div., M/S 124-111 Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | AIR DATA COMPUTER | ADC-850:622-7208-002 ADM-85:622-8692-011 |
| TSO-C106 | Honeywell, Inc. Comm. Flt. Sys. 8840 Evergreen Blvd. Minneapolis, MN 55433-6040 | CE-C | | HG1150AC() CG1151AC() |
| TSO-C106 *F | Smiths Industries Ltd. Defense Systems Bishops Cleeve Cheltenham, Glos. GL52 4SF United Kingdom | EU | | 503 FAD ()-() |
| TSO-C107 | NONE | | | |
| TSO-C108 | NONE | | | |
| TSO-C109 | Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 73229 | CE-C | AIRBORNE NAVIGATION DATA STORAGE SYSTEM | DB680 Data Base System 805D0590 |
| TSO-C109 | Global-Wulfsberg Systems Div. of Sundstrand Data Control, Inc. 6400 Wilkinson Drive Prescott, AZ 86301 | NM-L | | GNS-1000:42000-02-02 NDB-() Series NDB-2 400-045500-0001/-0002 400-045500-0001 42000-01-01/-02 400-04550-0002 43000-01-01-X |
| TSO-C109 *F | Racal Avionics Limited Raynes Park | EU | | Type RNS-5000 80792B()007 80792C()007 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS | |
|----------------|--|------|---|---|---------------------------|
| | London | | | 80792G()007 80794C()003 | 80794A()003 |
| TSO-C109 *F | Racal Avionics Ltd 88 Bushey Road Raynes Park London SW20 0JW United Kingdom | EU | | RNS 5000, RNAV-2: NCU 80792 B() S0 () NCU 80792 B() R2 () NCU 80792 B() R4 () NCU 80792 B() R7 () NCU 80792 C() S0 () NCU 80792 C() R2 () NCU 80792 C() R4 () NCU 80792 C() R7 () NCU 80792 D() S0 () NCU 80792 D() R2 () NCU 80792 D() R4 () NCU 80792 D() R7 () NCU 80792 E() S0 () NCU 80792 E() R2 () NCU 80792 E() R4 () NCU 80792 E() R7 () NCU 80792 G() S0 () NCU 80792 G() R2 () NCU 80792 G() R4 () NCU 80792 G() R7 () NCU 80792 H() S0 () NCU 80792 H() R2 () NCU 80792 H() R4 () NCU 80792 H() R7 () NCU 80792 J() S0 () NCU 80792 J() R2 () NCU 80792 J() R4 () NCU 80792 J() R7 () NCU 80792 K() S0 () NCU 80792 K() R2 () NCU 80792 K() R4 () NCU 80792 K() R7 () NCU 80792 B() R8 () NCU 80792 C() R8 () NCU 80792 D() R8 () NCU 80792 E() R8 () NCU 80792 G() R8 () NCU 80792 H() R8 () NCU 80792 J() R8 () NCU 80792 K() R8 () CDU 80794 AS 0 () CDU 80794 BS 0 () CDU 80794 CS 0 () CDU 80794 ES 0 () 80792M()010 | |
| TSO-C110 | Aviation Safety Systems Project/3M 6530 Singletree Drive Columbus, OH 43229 | CE-C | AIRBORNE PASSIVE THUNDER-STORM DETECTION SYSTEM | WX-1000 WX-11J | WX-1000+ WX-10A, WX-11 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|-----------|---|------|---|---|
| TSO-C110 | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Business & Commuter Av. Systems Div. 5353 W. Bell Road Glendale, AZ 85308 | NM-L | | LU-860:7012738-() LSZ850 LP-850:7011822-() AT-850:4057697-() LU-850:7011865-() LU-860:7012738-905, -906 AT-855:7014062-() LP-850:7011822-903, Mod F |
| TSO-C110a | Aviation Safety Systems Project/3M 6530 Singletree Drive Columbus, OH 43229 | CE-C | AIRBORNE PASSIVE THUNDERSTORM DETECTION SYSTEM | WX-1000, WXD-1000+, WDX-1000E |
| TSO-C110a | Eventide Inc. One Alsan Way Little Ferry, NJ 07643 | NE | | WDA 7005 |
| TSO-C112 | Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310 | CE-A | AIRTRAFFIC CONTROL RADAR BEACON SYSTEM MODE SELECT (ATCRBS/MODE S) AIRBORNE EQUIP. | TRA-66A:8055359-() CNA-66A:8055360-() |
| TSO-C112 | Bendix/King General Aviation Avionics Div. 400 North Rogers Road Olathe, KS 66062-1212 | CE-W | | CTA 81A:071-01476-0000 thru -0015 CTA 81A:071-01476-0020 thru -0027 CTA-81A:071-01477-0000 thru -0016 CTA 81A:071-01477-0017, -0018, -0019 CTA-81A:071-01477-0020 thru 0027 CTA-81A:071-01477-0028, -0029, -0030 CTA-81A:071-01477-0036 CTA 81A:071-01477-0050 thru -0066 CTA 81A:071-01477-0070 thru -0077 CTA-81A:071-01503-0101, -0201, -0301, -1301, -1401, -1501, -1601, -2101, -2201, -2301, -2501, -2601, -2701, -2801, -3701 CTA 81A:071-01503-3801, -3901, -4001, -4101, -4201, -4301 CTA 81B:071-01480-0000 thru -0015 CTA 81B:071-01480-0016, -0017 CTA 81B:071-01480-0020 thru -0035 CTA 81B:071-01480-0036, -0037, -0038, -0039 CTA 81B:071-01480-0050 thru -0065 CTA 81B:071-01480-0070 thru -0085 CTA 81B:071-01492-1401, -3401 CNA 67A:071-01475-0000 thru -0007 CNA 67A:071-01478-0000 thru -0007 CNA 67A:021-01478-0050 thru -0057 CNA-67A:071-01478-0036 CNA-67A:071-01478-0050 thru 0057 CNA-67A:071-01502-0201, -0301, -0401, -0601, -0701, -0801, -3701 TRA-67A:066-01127-0000, -0001, -0002, 1101, -1201 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|---|------|-----------|--|
| TSO-C112 | Bendix/King Gen. Avn. Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 (Paola, KS) | CE-W | | CTA 81A: 071-01503-4601 CTA-81C:071-01515-0101, -0201, -1301, -1401, -2101, -2201, -2501, -2601 CTA 81A:071-01503-4701 KFS 578A:071-01507-0101, -0201, -0301, -0401, -0501, -0601, -0701, -0801, -0901, -1001, -1101, -1201, -1301, -1401, -1501, -1601, -1701, -1801, -1901, -2001, -2101, -2201, -2301, -2401, -2501, -2601, -2701, -2801, -2901, -3001, -3101, -3201 |
| TSO-C112 | Bendix/King Gen. Avn. Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 (Lawrence, KS) | CE-W | | TRA-67A:066-01127-1301 MST 67A:066-01143-0101, -0201, -0301 |
| TSO-C112 *F | Bendix/King Gen. Avn. Avionics Div. 400 N. Rogers Road Olathe, KS 66062-1212 (Singapore) | CE-W | | KT70:066-01141-0101 |
| TSO-C112 | Collins General Avn. Div. Avionics Group Rockwell International Corp. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-W | | TDR-94:622-9352-001, -002 TDR-94D:622-9210-001, -002 CTL-92T:622-9614-() |
| TSO-C112 | Collins Avionics Div. M/S 124-111 Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | DTP-722:622-8594-001, -011, -021, -022, -023 TPR-720:622-7878-200 TTC-920:622-8974-001, -002, -003, -004, -005, -006, -007, -008, -009, -010, -011, -012, -013, -032, -101, -102, -103, -104, -105, -106, -107, -108, -109, -110, -111, -112, -113, -132, -201, -202, -203, -204, -205, -206, -207, -208, -209, -210, -211, -212, -213, -232, -301, -302, -303, -304, -305, -306, -307, -308, -309, -310, -311, -312, -313, -332, -901 TTC-920A:622-9288-001, -002, -003, -004, -005, -006, -101, -102, -103, -104, -105, -106, -201, -202, -203, -204, -205, -206, -301, -302, -303, -304, -305, -306 TTC-920G:822-0078-001, -101, -201, -301 |
| TSO-C112 | Dorne & Margolin Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DM N150-2-1, -2, -3, -4 DM 1601354 |
| TSO-C112 | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G6990-05, -06, -07, -08, -09, -10, -12, -13, -17, -19, 27 G6992-08 G6969() G6993-03 G7112() |
| TSO-C112 | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 W. Bell Road Glendale, AZ 85308 | NM-L | | SRZ-850 RCZ-850:7510700-901 RM-850:7012100-943, -944, -953, -954 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|--|------|---|---|
| TSO-C112 | Honeywell Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Division 21111 N. 19th Avenue Phoenix, AZ 86036-1111 | NM-L | | 4061400-() 4061400-902, -903 4052190-() 4067620-() |
| TSO-C112 | Sensor Systems Inc. 8929 Fullbright Avenue Chatsworth, CA 91311 | NM-L | | S65-5366-7L |
| TSO-C113 | Bendix General Aviation Avionics Div. Configuration Control & Cert. 2100 N.W. 62nd St. Fort Lauderdale, FL 33310 | CE-A | AIRBORNE MULTI- PURPOSE ELECTRONIC DISPLAY | SG-101B 3614335-1003 Control Panel 8056522-0501 SG-101B:3614335-1009 |
| TSO-C113 | Bendix/King General Aviation Div. Avionics Div. 400 North Rogers Road Olathe, KS 66062-1212 | CE-W | | CP 467:071-1439-00, -01, -02, -03, -04, -05 CP467:071-01439-3100, 3200 CP 468:071-1439-10, -11, -12, -13, -14, -15 CP468:071-01439-4100, -4200, -4300, -4400 CP469:071-01439-5100, -5200 ED 551:066-03137-0100, -0200, -0300, -0400 ED 551A:066-03137-1100, -1200, -1300, -1400 ED 461:066-3123-00, -01, -02, -03, -04, -05, -06, -07 ED 462:066-3125-00, -01, -02, -03, -04, -05, -06, -07, -10, -11, -12, -13, -14, -15, -16, -17 SG 464:066-04020-0102, -0202, -0103, -0203, -0101, -0201, -0105, -0205, -0104, -0204 SG 465:066-04021-0402, -0502, 0403, -0503, -0405, -0505, -0105, -0205, -0104, -0204, -0404, -0504 SG 465:066-4021-04, -05 |
| TSO-C113 | Bendix/King General Avn Avionics Div. 400 North Rogers Road Olathe, KS 66062-1212 (Lawrence, KS) | CE-W | | SU 463:071-00074-0100, -0200, -0300, -0400, -0500 |
| TSO-C113 | Bendix/King General Avn Avionics Div. 400 North Rogers Road Olathe, KS 66062-1212 (Paola, KS) | CE-W | | KA-163A:071-01303-0001 |
| TSO-C113 | Collins Avionics Division Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | ALI-850A:622-8334-001 ASI-850A:622-8335-001, -002, -003, -010, -011, -012 ALI-850B:622-9238-001/-002 SDD-640:622-7207-001 SDU-640A:622-8336-001 MFD-870:622-8528-002, -003, -004, -005, -006, -007, -008, -009, -010 DU-1000:622-7484-250, -301 DU-1000A:622-8047-250, -411 DCP-1000:622-7485-201, -301 RLS-1000:622-7573-201 MFCP-1000A:622-7957-201 MEM-871:622-7395-101 BZL-871:622-7392-001 BZL-873:622-7394-001 CHP-850:622-7397-001 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|---|------|--|--|
| | | | | CDU-850A:622-8363-001 CDU-851:622-9578-001, -002 EFD-870:622-7391-101 MEM-873:622-8009-101 BZL-874:622-7402-001 AAP-850:622-7398-001 ECD-870:622-8529-002, -003, -004, 005, -006, -007, -008, -009, -010 TVI-920D:622-9728-001/-002/-011/-012/-021/ -022/-031/-032/-201/-202/-211/-212/-221/ -222/-231/-232 |
| TSO-C113 | Collins Avionics Division Rockwell International Melbourne, FL | CE-W | | EFD-86S:622-8677-001 TTA-920:622-9739-001 CHP-850A:622-9435-001, -002 ALI-850C:622-9751-001, -002 |
| TSO-C113 | Eventide Avionics Division of Eventide, Inc. One Alsan Way Little Ferry, NJ 07643 | NE | | 5000-10-07 7000-xx-xx |
| TSO-C113 | Honeywell, Inc. Sperry Comm. Flt. Sys. Gp. Avionics Facility 5353 West Bell Road Glendale, AZ 85308 | NH-L | | SRZ-850 RM-850:7012100-943, -944, -953, -954 |
| TSO-C113 | Skylight Avionics Company 38629 6th Street East Palmdale, CA 93550 | NH-L | | IND-5000 50-50-(XX-XX) |
| TSO-C114 | Pacific Scientific 22715 Savi Ranch Parkway Yorba Linda, CA 92686 | NH-L | TORSO RESTRAINT SYSTEMS | 1117007() |
| TSO-C115 | ACK Technologies, Inc. 424 W. Julian Street San Jose, CA 95110 | NH-L | AIRBORNE AREA NAVIGATION EQUIPMENT USING MULTI-SENSOR INPUTS | E-01 |
| TSO-C115 | Bendix/King General Aviation Avionics Division 400 North Rogers Road Olathe, KS 66062-1212 | CE-W | | KLN 670:066-1124-00 KNC 667:066-4011-26-00 KNC 667:066-4011-27-00 KNC 667:066-4011-24, -25, -26, -27, -28, -38, -39, -44, -45, -46, -47, -48, -49 KNC 667:066-4011-24-05 KNC 667:066-4011-25-05 |
| TSO-C115 | Collins Avionics Division Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | CHP-850:622-7397-001 CDU-850:622-8363-001 FMC-851A:622-8682-001 CDC-850A:622-8681-001 FMC-852A-622-8683-001 PWR-851A:622-8365-001 IOC-851:622-7405-XXX ICC-850A:622-8364-001 OU-1000:622-7484-250, -301 OCP-1000:622-7485-201, -301 MFD-870:622-8528-002, -003, -004, -005, -006, -007, -008, -009, -010 FMC-851A:622-8682-003 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|--|
| | | | | FMC-852A:622-8683-003 CDC-850A:622-8681-003 CDU-851:622-9578-001, -002 KNC 667:KPN 066-4011-44, 45 |
| TSO-C115 | Collins Avionics Div. Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | CHP-850A:622-9435-001, -002 |
| TSO-C115 | Global-Wulfsberg Systems Div. of Sundstrand Data Control, Inc. 6400 Wilkinson Drive Prescott, AZ 86301 | NM-L | | GNS-X NMU 14141-0101 CDU 141347-0101-XX 30150-04-04 GNS-X:30050-0909-() GNS-X::14141-0202-(), Mod 6 GNS-X:121-014379-(), Mod N/C 30150-04-04 GNS-1000:30150-04-04 GNS-X:14141-0101(xxxx) GNS-500A:10050-()-5M-() Mod N/C GNS-X:14141-0220-()Mod NC GNS-X:40200-0101-()Mod NC GNS-1000:30150-04-05, 30050-0707, 0808 GNS-X:14141-0203-() |
| TSO-C115 | Honeywell, Inc. Commercial Aviation Div. P.O. Box 38 Minneapolis, MN 55440 | CE-C | | NDU CG1230AC-() |
| TSO-C115 | Honeywell, Inc. Commerical Aviation Div. 8840 Evergreen Boulevard Minneapolis, MN 55433-6040 (Coon Rapids, MN) | CE-C | | CG1230AG() HG2021AB() |
| TSO-C115 | Honeywell, Inc. Sperry Comm. Flt. Sys. Div. Avionics Facility 5353 W. Bell Road Glendale, AZ 85308 | NM-L | | NZ-600/800:7004402-() 7004403-() 7007549-() NZ-910:7004402-903 NZ-820/920:7004402-833, -834, -904, -845, -905 NZ-820:7004402-814, -907 NZ-620:7004402-654 NZ-810:7004402-804, -806 NZ-910:7004402-906 CD-810:7007549-905, -906 |
| TSO-C115 | King Radio Corporation 400 N. Rogers Road Olathe, KS 66062-1212 | CE-W | | KNC-667:066-4011-24, -25 KCU-567:066-4012-00, -01, -02, -03, -10, -11, -12, -13, -20, -21, -22, -23, -30, -31, -32, -33, -52 KCU-568:066-4013-00, -01, -02, -03, -04, -05, -10, -11, -12, -13, -20, -21, -22, -23, -30, -31, -32, -33, -52 KNR-620:066-1126-00 KA-670:066-1124-00 KA-670:066-1361-00 |
| TSO-C115 *F | Racal Avionics Ltd., Raynes Park London | EU | | Nav. Systems Type RNS 5000 80792B () 007 80792C () 007 80792G () 007 80794A () 003 80794C () 003 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|-----------|---|
| | | | | MEM-871:622-7395-101 |
| TSO-C115 *F | Racal Avionics Ltd 88 Bushey Road Raynes Park London SW20 0JW United Kingdom | EU | | RNS 5000, RNAV-2: NCU 80792 B() S0 () NCU 80792 B() R2 () NCU 80792 B() R4 () NCU 80792 B() R7 () NCU 80792 C() S0 () NCU 80792 C() R2 () NCU 80792 C() R4 () NCU 80792 C() R7 () NCU 80792 D() S0 () NCU 80792 D() R2 () NCU 80792 D() R4 () NCU 80792 D() R7 () NCU 80792 E() S0 () NCU 80792 E() R2 () NCU 80792 E() R4 () NCU 80792 E() R7 () NCU 80792 G() S0 () NCU 80792 G() R2 () NCU 80792 G() R4 () NCU 80792 G() R7 () NCU 80792 H() S0 () NCU 80792 H() R2 () NCU 80792 H() R4 () NCU 80792 H() R7 () NCU 80792 J() S0 () NCU 80792 J() R2 () NCU 80792 J() R4 () NCU 80792 J() R7 () NCU 80792 K() S0 () NCU 80792 K() R2 () NCU 80792 K() R4 () NCU 80792 K() R7 () NCU 80792 B() R8 () NCU 80792 C() R8 () NCU 80792 D() R8 () NCU 80792 E() R8 () NCU 80792 G() R8 () NCU 80792 H() R8 () NCU 80792 J() R8 () NCU 80792 K() R8 () CDU 80794 AS 0 () CDU 80794 BS 0 () CDU 80794 CS 0 () CDU 80794 ES 0 () 80792M()010 |
| TSO-C115 | Universal Navigation Corp. 3260 E. Lerdo Road Tucson, AZ 85706 | NM-L | | 105() 1056-01-10 1161-21-XX 1180-21-XX 1180-24-XX 1161-30-() 1180-30-() 1161-21-110, 120, 130, 140, 150, 111, 121, 131, 141, 151, 210, 220, 230, 240, 250, 211, 221, 231, 241, 251 1180-21-20, -21, -22, -23, -24 1180-24-20 |
| TSO-C115 | Universal Navigation Corp. 3545 W. Lomita Blvd., Unit B Torrance, CA 90505 | NM-L | | UNS-1A:1180-30-() 1180-21-() 1180-24-() 105() 1016-1-() |
| TSO-C115 | Universal Navigation Corp. | NM-L | | UNS-1A:1161-21-() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------------|--|------|--|---|
| | 3260 E. Lerdo Road Tucson, AZ 85706 | | | NCU-1161-21-XX 1180-21-XX 1180-24-XX |
| TSO-C116 *F | Dragerwerk AG Lubeck, Germany | NE | CREWMEMBER PROTECTIVE BREATHING EQUIPMENT | E 28180 |
| TSO-C116 | Essex PB & R Corp. P.O. Box 791 505 Blue Ball Road Elkton, MD 21921 | NE | | 4566M37-B |
| TSO-C116 *F | L'Air Liquide Division des Techniques Avancees Les Engevinieres B.P. 15, 38360 Sassenage France | EU | | 15-40 F (xx) |
| TSO-C116 | Scott Aviation 225 Erie Street Lancaster, NY 14086 | NE | | 802300-14 |
| TSO-C118 | NONE | | | |
| TSO-C119 | Bendix/King Air Transport Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310 | CE-A | TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) AIRBORNE EQUIP., TCAS II | ANT-81ATCAS:071-50001-() |
| TSO-C119 | Collins General Avn. Div. Avionics Group Rockwell International Corp. 1100 W. Hibiscus Blvd. Melbourne, FL 32902-1060 | CE-A | | CTL-92T:622-9614-() |
| TSO-C119 | Collins Avionics Divisions Rockwell International Corp. M/S 124-111 Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | TTC920:622-8974-001, -002, -003, -004, -005, -006, -007, -008, -009, -010, -011, -012, -013, -032, -101, -102, -103, -104, -105, -106, -107, -108, -109, -110, -111, -112, -113, -132, -201, -202, -203, -204, -205, -206, -207, -208, -209, -210, -211, -212, -213, -232, -301, -302, -303, -304, -305, -306, -307, -308, -309, -310, -311, -312, -313, -332. -901 |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|-----------|--|------|--|---|
| | | | | TTC-920A:622-9288-001, -002, -003, -004, -005, -006, -101, -102, -103, -104, -105, -106, -201, -202, -203, -204, -205, -206, -301, -302, -303, -304, -305, -306 TTC-920G:822-0078-001, -101, -201, -301 |
| TSO-C119 | Dorne & Margolin Inc. 2950 Veterans Memorial Hwy. Bohemia, NY 11716 | NE | | DH 1601354 |
| TSO-C119 | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G6990-05, 06, -07, -08, -09, -10, -12, -13, -17, -19, -27 G6992-08 G6993-03 |
| TSO-C119 | Honeywell Inc. Sperry Comm. Flt. Sys. Gp. Business & Commuter Avn. Sys. Div. 5353 West Bell Road Glendale, AZ 85308 | NM-L | | 7514060-() |
| TSO-C119 | Sensor Systems, Inc. 8929 Fullbright Avenue Chatsworth, CA 91311 | NM-L | | S65-5366-7L S65-5366-735 S72-1735 |
| TSO-C119a | Bendix/King Air Transport Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310 | CE-A | TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) AIRBORNE EQUIP., TCAS II | TPA-81A:066-50000-8101 ITA-81A:066-50003-0101, -0301, -0401, -0501, -0601 RA/VS1:066-50002-8101 thru -8104 TA/VS1:066-50001-8101 thru -8108 TA/VS1:066-50001-0901 thru -1201 |
| TSO-C119a | Collins Avionics Div. M/S 106-113 Rockwell International 400 Collins Road NE Cedar Rapids, IA 52498 | CE-W | | TTR-920:622-8971-001, -101 TRE-920:622-8973-001, -002, -003, -004, -101, -102, -103, -104 TTR-920:622-8971-002, -102 |
| TSO-C119a | Gables Engineering, Inc. P.O. Box 140880 Coral Gables, FL 33114 | CE-A | | G6969() |
| TSO-C119a | Honeywell Inc. Sperry Comm. Flt. Sys. Gp. Air Transport Division 21111 N. 19th Avenue Phoenix, AZ 85036-1111 | NM-L | | 4066010-() |
| TSO-C120 | NONE | | | |
| TSO-C121 | Dukane Corporation 2900 DuKane Drive St. Charles, IL 60174 | CE-C | UNDERWATER LOCATING DEVICES (ACOUSTIC) (SELF- POWERED) | DK100() |

| TSO NO. | HOLDER NAME & ADDRESS | RG | TSO TITLE | MODELS OR PART NUMBERS |
|----------|-----------------------|----|-----------|------------------------|
| TSO-C122 | NONE | | | |
| TSO-C123 | NONE | | | |
| TSO-C124 | NONE | | | |