



AC NO: 91-14C M-494.6

DATE: 6/14/78

ADVISORY CIRCULAR

DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

SUBJECT: ALTIMETER SETTING SOURCES

1. PURPOSE. This advisory circular provides the aviation public and industry with guidelines for setting up reliable altimeter setting sources.

2. CANCELLATION. Advisory Circular (AC) 91-14B, dated 10/1/71 is canceled.

3. GUIDELINES. An altimeter setting source should either:

a. Consist of the Standard Altimeter Setting Indicator (ASI); or

b. Meet the minimum technical requirements specified in paragraphs (1) and (2) below and be operated in accordance with paragraph (3).

(1) Instrumentation. Two aircraft-type sensitive altimeters should meet the specifications of TSO-C10b or be calibrated in accordance with Federal Aviation Regulation (FAR) Part 43, Appendix E. One aircraft-type sensitive altimeter meeting these specifications may be utilized at locations where a Part 121 operator has established a procedure for periodic cross-checking of the altimeter as specified in paragraph 3b(2)(c). The height (of the instruments) above mean sea level, surveyed accurately within one foot, is marked on the instruments or posted immediately adjacent to them. Outside venting of the altimeter or altimeters is necessary only when the room in which the instruments are located is shown to be subject to a pressure differential compared to ambient atmospheric pressure.

(2) Calibration. The instruments should be calibrated and recertified to the specifications of Part 43, Appendix E, by an FAA-approved instrument repair station:

(a) Within 30 days prior to initial installation or retention as a spare, and every 24 months thereafter.

(b) At stations utilizing two altimeters, anytime a difference of more than .05 of an inch of mercury exists between the two instruments

Initiated by: AFS-804

with indicator hands set to the instrument elevation. Immediately after calibration, the difference between the two instruments should not exceed .02 of an inch of mercury.

(c) At stations utilizing one altimeter, any time a difference of more than .04 of an inch of mercury exists on two successive cross-checks between the station reference altimeter and the mean of the readings obtained from the two altimeters installed in an aircraft maintained under the provisions of Part 121.

(d) The instruments should be calibrated to achieve maximum accuracy in the altitude range at which they will be used. (Instruments so calibrated should be marked "not for use in aircraft.") All readings should be adjusted as required by the altimeter correction card furnished by the calibration station. The instrument should be kept in a temperature-controlled environment similar to the temperature at which the instrument was calibrated.

(3) Procedures. The operator should establish procedures to ensure that responsible persons are competent to obtain accurate altimeter settings.

(a) At stations employing two altimeters, a tested method is as follows:

1 Set both instruments to the posted height, tap or vibrate each to remove friction effects, then reset if necessary.

2 Adjust the readings as required by the altimeter correction card.

3 The altimeter setting, in inches of mercury, appears in the small window. The difference between instrument readings may not exceed .05 of an inch. The lower of the two settings is the official altimeter setting.

4 The difference between instrument readings should be logged in a permanent record at least once a day.

(b) At stations using one altimeter, a tested method is as follows:

1 Set the instrument to posted height, tap or vibrate to remove friction effects, then reset if necessary.

2 Adjust the reading as required by the altimeter correction card, and record the reading.

3 From a company aircraft parked on an adjacent ramp area, secure altimeter readings from both captain's and first Officer's altimeters which should be adjusted to indicate the actual elevation of the ramp plus the height of the instruments above the ramp before the altimeters are read.

4 Determine the mean of the two aircraft altimeter readings and compare the mean with the reading from the station altimeter. If the difference between the mean and the station altimeter exceeds .04 of an inch, the altimeter setting should be reported as "missing," and if the difference exceeds .04 of an inch on two successive cross-checks, the altimeter should be recalibrated before further use.

5 The cross-check should be performed daily, if an aircraft is available. The cross-check should be performed at least three days per week. The difference between the reference instrument and the mean of the aircraft altimeter readings should be logged in a permanent record.

(4) System Approvals. Altimeter setting sources installed in accordance with this AC and intended for use with approved instrument approach procedures will require initial approval and periodic inspection by the FAA. Initial approval and annual inspections should be accomplished by the appropriate FAA district office (General Aviation District Office, Air Carrier District Office or Flight Standards District Office).

(5) Future Systems. The FAA and private industry are developing automatic altimeter setting reporting systems that may include wind and other weather elements. Automatic weather reporting systems will be required to meet FAA and National Weather Service accuracy and reliability standards before they can be used to support IFR operations.



JAMES M. VINES
Acting Director
Flight Standards Service

U.S. DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION
Washington, D.C. 20591
Official Business
Penalty for Private Use, \$300

POSTAGE AND FEE PAID
FEDERAL AVIATION
ADMINISTRATION
DOT 515

