A CENTER OF EXCELLENCE FOR
# RURAL AND INTERMODAL TRANSPORTATION

MPC REPORT NO. 99-101

Evaluation of Pavement Shoulders

Khaled Ksaibati
Israel Crowe

May 1999

Mountain-Plains Consortium

REPORT DOCUMENTATION PAGE

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson ... '02, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

PB99-145716

2. REPORT DATE	3. REPORT TYPE AND DATES COVERED
May 1999	project technical

4. TITLE AND SUBTITLE

Evaluation of Pavement Shoulders

5. FUNDING NUMBERS

6. AUTHOR(S)

Khaled Ksaibati and Israel Crowe
University of Wyoming

7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)

Mountain Plains Consortium
North Dakota State University
Fargo, ND 58105

8. PERFORMING ORGANIZATION REPORT NUMBER

MPC 99-101

9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)

U.S. Department of Transportation
Research and Special Programs Administration
400 7th Street SW
Washington, DC 20590-0001

10. SPONSORING/MONITORING AGENCY REPORT NUMBER

11. SUPPLEMENTARY NOTES

12a. DISTRIBUTION/AVAILABILITY STATEMENT

12b. DISTRIBUTION CODE

13. ABSTRACT (Maximum 200 words)

In this study the researchers examined the effect of pavement shoulders on the safety and structural strength of highways in Wyoming. The costs of adding shoulders to various types of highways also was examined. The study consisted of selecting representative highway sections, collecting accident data on all test sections over a five-year analysis period, obtaining geometric information on the sections, and summarizing all collected data in a computerized database. A statistical analysis using the Poisson distribution was used to analyze the collected data. Accident costs and shoulder construction costs were obtained from the Wyoming Department of Transportation. In addition, a structural analysis was performed using finite element analysis and BISAR. The following main conclusions can be drawn from this study: accidents can be reduced by increasing shoulder widths and shoulders slightly reduce the vertical stresses.

14. SUBJECT TERMS

pavement, highway, shoulder

15. NUMBER OF PAGES

105

16. PRICE CODE

17. SECURITY CLASSIFICATION OF REPORT	18. SECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CLASSIFICATION OF ABSTRACT	20. LIMITATION OF ABSTRACT
			UL

EVALUATION OF PAVEMENT SHOULDERS

Khaled Ksaibati and Israel Crowe
Department of Civil and Architectural Engineering
University of Wyoming
Laramie, Wyoming 82071-3295

May 1999

Acknowledgment

Disclaimer

ABSTRACT

This report describes a study conducted at the University of Wyoming by Dr. Khaled Ksaibati, Associate Professor of Civil Engineering, and Israel Crowe, Graduate student of Civil Engineering. In this study the researchers examined the effect of pavement shoulders on the safety and structural strength of highways in Wyoming. The costs of adding shoulders to various types of highways also was examined. The study consisted of: selecting representative highway sections, collecting accident data on all test sections over a five-year analysis period, obtaining geometric information on the sections, and summarizing all collected data in a computerized database. A statistical analysis using the Poisson distribution was used to analyze the collected data. Accident costs and shoulder construction costs were obtained from the Wyoming Department of Transportation. In addition, a structural analysis was performed using finite element analysis and BISAR. The following main conclusions can be drawn from this study: accidents can be reduced by increasing shoulder widths and shoulders slightly reduce the vertical stresses.

TABLE OF CONTENTS

LIST OF TABLES

LIST OF FIGURES

CHAPTER 1

INTRODUCTION

Background

Pavement shoulder widths are highly variable in rural roadways. Some rural highway sections are even constructed without any pavement shoulders. Pavement shoulders generally are provided to improve the safety characteristics of roadways. They also help in increasing roadway capacity. One theory states that shoulders may help increase the service life of pavements by reducing stresses due to loadings.

Shoulder width is the distance from the edge of the traveled way to the edge of the roadway. They are used to accommodate stopped vehicles for emergency use and are commonly used by pedestrians and bicyclists. Shoulder widths vary depending on traffic volumes, terrain, and the cost of added width to the roadway section. The materials used to construct shoulders are variable, and include concrete, asphalt, grass, gravel, and bituminous surface treatments. This study examined only paved shoulders, including asphalt and concrete.

The increased width to the roadway that shoulders offer helps to improve the safety of that roadway section. The extra space provides a place in case of emergencies, such as a flat tire. This additional roadway width also helps motorists to avoid potential accidents or reduce their severity. The increased width gives the driver room to maneuver and avoid conflicts. It also helps to accommodate driver errors. Drivers will have a little more time to react and compensate before they go off the road. Improving safety is a major advantage of pavement shoulders.

Some additional advantages of shoulders are: increased sight distance in cut sections, improved highway capacity and added lateral clearance for signs and guardrail. Storm water can be discharged farther from the traveled way. The use of shoulders has many advantages, however, there are some

disadvantages. These disadvantages include: additional construction cost and improper use by motorists, such as, using the shoulder as an additional driving lane.

Problem Statement and Objectives

State highway agencies select shoulder width primarily according to traffic volumes. The possible increasing structural strength normally is a secondary factor. Thus, some of the rural roadways do not have any shoulders. They have low traffic volumes and it is more economical not to construct shoulders in these situations, however these are the conditions where advantages of shoulders come into play and show that shoulders probably should be built.

The main objective of this research was to utilize the performance and accident rates in evaluating effectiveness of pavement shoulders in rural areas. The results of this research will help to determine appropriate widths of shoulders to be used under different conditions. This objective was accomplished by collecting extensive data on various roadway sections throughout Wyoming, analyzing the data and drawing conclusions from the analysis.

Report Organization

This research project was performed in two phases. The first phase of the research concentrated on collecting information related to pavement shoulders. It also emphasized collection of necessary data for the project. A literature search was conducted to retrieve information on pavement shoulders. Chapter 2 summarizes findings of the literature review. Chapter 3 outlines the data collection process, which examines the selection of test sections and the type of data that was collected for these test sections.

The second phase of the research was to analyze collected data. A complete statistical analysis of the accident data is presented in Chapter 4. Chapter 4 also examines accident costs relating to pavement shoulder widths. The structural effect of shoulders is discussed in Chapter 5. Finally, Chapter 6 presents a summary of the research. Conclusions and recommendations also are offered in Chapter 6.

2

CHAPTER 2

LITERATURE REVIEW

Introduction

As part of this study, a comprehensive literature review was performed on pavement shoulders. This chapter summarizes the findings of this review. The literature considered for review were studies related to shoulder widths and accident rates. Literature concerning the structural strength of roadways also were examined. AASHTO design guidelines were included for review.

Safety Studies

A number of studies have been performed to study the relationship between safety and roadway design. Some of these studies examined geometrics of the roadways; and others looked at cross sectional characteristics of the roadways. The following section looks at some of the studies that examined effects of lane and shoulder widths on accident rates. They also examined other benefits of adjusting lane and shoulder widths.

Shoulders and Accident Rates

In 1987, the Federal Highway Administration (FHWA) prepared the report, Safety Effects of Cross-Section Design for Two-Lane Roads, about a study that was intended to determine the effects of lane width, shoulder width, shoulder type, sideslope and roadside condition on accidents for two lane roads in the United States. Expected accident reductions and construction costs were quantified for lane and shoulder widening, shoulder surfacing, sideslope flattening, and roadside improvement projects.

Detailed accident, traffic, and roadway data were collected from 1944 roadway sections in the United States. These sections accounted for 4,951 miles of two-lane roads in seven states: Alabama, Michigan, Montana, North Carolina, Utah, Washington, and West Virginia.

3

The study concluded that many traffic and roadway features were associated with a reduced rate of single vehicle accidents. These features include: wider lanes, wider shoulders, greater recovery distance, lower roadside hazard rating and flatter terrain. Paved shoulders had lower accident rates than unpaved shoulders.Using the predictive model developed in the study, effects of lane width and shoulder widening on accidents were quantified. A 12 percent reduction in accidents occurred with the first 0.3 m (1 ft) of lane widening. Lane widening of 0.6 m (2 ft) corresponded to a 23 percent reduction in accidents. With 0.9 m (3 ft) of lane widening, a 32 percent reduction was found and 1.2 m (4 ft) of widening resulted in a 40 percent reduction in accidents. These reductions only apply for lane widths between 2.4 m (8 ft) and 3.6 m (12 ft). Adding paved shoulders of 0.6 m (2 ft) resulted in a 16 percent reduction in accidents. 1.2 m (4 ft) of widening corresponded to a 29 percent reduction and 1.8 m (6 ft) of widening resulted in a 40 percent reduction in accidents [1].

The study presented in NCHRP (National Cooperative Highway Research Program) Report 369 was performed to evaluate using shoulders with or without narrow lanes to increase the capacity of urban freeways. Another objective of this project was to develop recommendations and design guidelines for the strategies. The operational and safety performance of various applications of the strategies were concentrated on in this research. Eleven corridors throughout the country were selected for this research. They are located in: Boston, MA; Alexandria, VA; Seattle, WA; Atlanta, GA; Minneapolis, MN; and Los Angeles, CA. The project evaluated 42 altered sites and 10 unaltered sites. Analysis on the operational data was performed for all the corridors. Accident data were analyzed for five corridors.

The NCHRP study found that shoulders and narrow lanes can be used to increase capacity in congested urban corridors. The safety analysis indicated higher accident rates on three of the corridors. Two of the corridors showed a decrease, possibly attributed to a smooth traffic flow. The report suggests that the strategies should only be employed to improve traffic flow in congested corridors. The first modification that is recommended by the study should be to reduce the traveled way to 11 feet. Also,

reduction of the left shoulder should be considered before reducing the right shoulder. Table 2.1 summarizes the advantages and disadvantages of altering shoulder widths.

Recommendations of NCHRP Report 369 follow:

- Use of shoulders and narrow lanes to achieve an additional travel lane normally should not be considered as an option to a traditional widening project for adding capacity to a freeway corridor.

- For areas of limited length and having turbulent flow conditions, use of shoulder(s) and narrow lanes should be considered as one alternative for achieving smother flow. Such use typically should be limited to sections of 1 mile or less.

- Where large truck traffic is a significant proportion of peak period (i.e., 5 to 10 percent), use of shoulders and narrow lanes is not recommended.

- For projects involving possible application of shoulders and narrow lanes, a step-by-step approach (site specific) must be used to ensure an adequate evaluation.

- Additional research efforts on traffic flow and safety impacts of the use of shoulders and narrow lanes should be made part of other freeway-oriented research projects [2].

Geometrics and Safety Considerations

The research study presented in Transportation Research Record 960 examined relationships between geometric design elements and accidents on two lane rural roads. Two data sets with traffic volumes greater than 2,000 vehicles per day were used for analysis in this project. The first data set was a national data set, which represented two-lane rural total accident experience from 14 states with 152 sections. These sections account for 800 miles with 3,224 accidents in the year of the study. This data set used the following information to model their effect on total accident occurrence: driveway and intersectional conflict frequency, roadside obstacle characteristics, and geometric design elements. The second data set included information on 137, two-mile sections of Michigan state highway with 1,300

Table 2.1: Primary Advantages and Disadvantages of Design Alternatives [2]

Design Alternative	Advantages	Disadvantages
Use of Left Shoulder	Left shoulder not used as much for emergency stop/or emergency enforcement Least expensive if width is available Trucks often restricted from left lane	Usually requires restriping Sight distance problem with some median treatments
Use of Right Shoulder	Often the easiest to implement	Right shoulder is preferred area for emergency stops and enforcement Sight distance changes at merge and diverge areas of ramps
Use of Both Shoulders	Not recommended Use ONLY in extreme cases	Requires restriping Safety concerns (no refuge) Enforcement is difficult Incident response longer Maintenance more difficult and expensive

off-road accidents. Five hundred and fourteen of these accidents resulted in injuries. This data set was used to examine the effect of off-road accident frequency and severity on total accident occurrence.

The study concludes that for the prediction of accidents, the effects of average daily traffic (ADT) was the most important factor, followed by driveway and intersection density and the geometric elements. An interaction between access point density and geometric characteristics was found to effect accidents as well as an interaction between access point density and volume. This study found that no significant independent effects of cross sectional elements in total accident prediction [3].

Structural Strength Due to Pavement Shoulders

The structural strength of a pavement section can be contributed to several factors within the following cross sectional elements of the roadway system: the number of layers, types of materials used, condition of these materials, and the dimensions of the layers and cross section. The combination of these variables determine the structural strength of the pavements. When heavy traffic loads are applied to pavement surfaces, the pavement will be subjected to variable levels of stresses. The main objective of pavement engineers is to insure that these stresses do not exceed the strength of materials used in different pavement layers. Some pavement designers suggest that the addition of pavement shoulders can reduce edge stresses in pavements and therefore increase pavement service life. The following two sections describe stresses experienced by flexible and rigid pavements.

Stresses in Flexible Pavements

Flexible pavements normally have a relatively thin asphalt wearing course with layers of granular base and subbase used to protect the subgrade from being overstressed. The basic concept of granular base flexible pavements is to provide a base thickness that insures that the vertical compressive subgrade stress or deflection is reduced to some limiting value less than the allowable distress level. This pavement system consists of built up layers having successively higher modulus values in the upper

7

layers. The load spreading capabilities of this system must occur primarily through the thickness of the granular base and subbase layers.

Employing stiffer and stiffer materials in the upper layers result in a noticeable reduction of subgrade stress or deflection. For any given subgrade soil type, this allows a reduction of thickness of a stiffer layer over similar thickness of unbound granular material to satisfy the requirements of an allowable subgrade distress or limiting deflection criteria. This is a direct result of better load spreading capabilities of stiff or rigid layers. However, it is important to note that even though stiffer materials reduce the risk associated with a subgrade mode of distress, such as shear, the presence of this stiff layer brings about an increase in the tensile stress magnitude at the bottom of this layer as well as a marked increase in the horizontal shearing stresses [4].

Asphalt Institute procedures for designing asphalt pavements consider two specific stress-strain conditions. In the first condition, the wheel load is transmitted to the pavement surface through the tire as an approximately uniform vertical pressure. The pavement structure then spreads the load stresses, thus reducing their intensity until, at the surface of the subgrade, the vertical pressure has a maximum intensity. If the vertical pressure on top of the subgrade is higher than the strength of that subgrade, rutting may develop due to repeated loading. The second condition results from the wheel load deflection of the pavement structure, which causes tensile and compressive stresses and strains in the asphalt layer. When the tensile stress exceeds the strength of the asphalt mix, cracks will start developing in the asphalt layer [5].

Stresses in Rigid Pavements

Rigid pavements have a relatively thin slab placed on a subgrade or base course. A major portion of the load carrying capacity is derived from the concrete slab, since its modulus of elasticity is much greater than that of the foundation material.

A variety of causes contribute to stresses in rigid pavements including: wheel loads, cyclic changes in temperature (warping and shrinkage or expansion), changes in moisture, and volumetric changes in the subgrade or base course. These changes tend to deform the slab, causing stresses of widely varying intensity. Additionally, the magnitude of stresses depends upon continuity of subgrade support. In analyzing rigid pavements, the stress inducing factors may be placed into several categories: restrained temperature and moisture deformations, externally applied loads, volume changes of the supporting material, including frost action, and continuity of the subgrade support [4].

The Portland Cement Association (PCA) pavement design procedure, has a section that helps in the effect of pavement shoulders in reducing stresses. Comparing equivalent stresses for single axle loads on a section with and without shoulders, there is a decrease in the stress. For example, with a slab thickness of six inches and the k of subgrade-subbase of 100 pci the stress of the section with no shoulders is 411 psi and for the section with concrete shoulders the stress is 327 psi. Also, by using this design procedure and implementing concrete shoulders can help to decrease the necessary slab thickness [6].

A study performed by the FHWA in 1982 determined that concrete shoulders, if tied to the traveled lane, have an effect on deflections and stresses. The study found that shoulders greater than 1.5 m (5 ft) have a significant effect on deflections and that for widths less than 1.5 m (5 ft) the deflections increase rapidly. Widening the concrete shoulder from 0.9 m to 1.5 m (3 - 5 ft) reduces stress 20 percent for a 20 cm (8 in) thick slab and widening the shoulder from 1.5 m to 3.0 m (5 - 10 ft) causes a decrease of only 5 percent. The effect of shoulder width on tensile stress is about the same regardless of slab thickness. Thus, a concrete shoulder wider than 1.5 m (5 ft) has a reduced effect on stresses from encroaching truck traffic near the longitudinal joint [7].

Thickness Recommendations for Pavement Shoulders

Asphalt Institute recommends that shoulders be designed using the same principles and procedures as for the main travel lanes. This is recommended because shoulders must withstand encroachment of moving vehicles and often must serve as temporary driving lanes during construction or maintenance activities. Also, at times shoulders are used by slow moving vehicles as travel lanes. It also is practical for future traffic usage [5].

AASHTO has no specific design criteria for shoulder thicknesses. However, the AASHTO design guide states that the use of tied shoulders has proven to be beneficial to overall performance of rigid pavements. Paved shoulders adjacent to flexible pavements will provide lateral support for the base and surface courses. AASHTO recommends that local practice, experience and cost analysis should be considered as factors in shoulder design [8].

A Policy on Geometric Design Of Highways and Bridges

The AASHTO manual A Policy on Geometric Design of Highways and Streets (1994) states that a 3.0 m (10 ft) shoulder should be used along high volume highways. This may not be possible for mountainous or low volume roadways, thus a minimum of 0.6 m (2 ft) should be used. However, shoulder widths of 1.8 m (6 ft) to 2.4 m (8 ft) are preferable. High speed and heavily traveled highways and those carrying a large number of trucks should use a shoulder width of 3.0 m (10 ft) to 3.6 m (12 ft). A minimum of 1.2 m (4 ft) should be used where bicyclists are common [9]. Table 2.2 shows AASHTO guidelines for using shoulder widths with respect to traffic volumes.

Table 2.2: Minimum Width of Traveled Way and Graded Shoulder [9]

Design Speed (km/h)	Design Traffic Volumes			
	ADT Less Than 400	ADT 400 - 1500	ADT 1500 - 2000	ADT over 2000
Width of Traveled Way (m)^c				
30	5.4	6.0^a	6.6	7.2
40	5.4	6.0^a	6.6	7.2
50	5.4	6.0^a	6.6	7.2
60	5.4	6.0^a	6.6	7.2
70	6.0	6.6	6.6	7.2
80	6.0	6.6	6.6	7.2
90	6.6	6.6	7.2	7.2
100	6.6	6.6	7.2	7.2
Width of Graded Shoulder - Each Side (m)^c				
All Speeds	0.6	1.5^{a,b}	1.8	2.4

a. Mountainous Terrain - ADT 400 - 600 5.4 m width and 0.6 m shoulders.

b. May be adjusted to achieve a minimum roadway width of 9 m for design speed of 60 km/h or less.

c. Where the width of traveled way is shown to be 7.2 m, the width of the traveled way may remain at 6.6 m on reconstructed highways where alinement and safety results are satisfactory.

Chapter Summary

This chapter summarizes the various studies related to pavement shoulder widths and accident rates. These studies showed that shoulder widths do affect accident rates. Increasing the shoulder width helps to decrease the number of accidents. A discussion of the stresses present in pavement sections also were presented. In addition, AASHTO design guidelines for shoulder widths and recommendations for pavement shoulder thickness were presented.

CHAPTER 3

DESIGN OF EXPERIMENT

Experiment Methodology

The major objectives of this study were to evaluate the effect of various shoulder widths on the safety and structural strength of roadways in Wyoming. To achieve this objective, several roadway sections were included in the experiment. Accident and geometric data were collected on all test sections. The data collection procedures are presented in this chapter. The data were summarized in a computerized database. A statistical data analysis was performed on the database. This statistical analysis used Normal regression and Poisson regression to predict accident numbers based on shoulder width. The SAS program was used to conduct all regression analysis.

Structural strength of roadways was examined with finite element analysis and BISAR. These analysis methods determined the stresses directly under a load application at the bottom of the surface layer and at the top of the subgrade. The finite element analysis was performed by using a software package called Patran. Both concrete and asphalt pavements were analyzed with finite element method. BISAR only was used to determine stresses in asphalt pavements. BISAR was developed to solve for stresses in asphalt pavements. The results from these two procedures were then compared. Conclusions were drawn pertaining to the effect of shoulders on accident numbers and on the structural strength of pavements.

Selection of Test Sections

To determine the effect of pavement shoulders on safety, test sections were selected from all over Wyoming to represent various climatic conditions and traffic characteristics. Interstate, Primary, and Secondary highway sections were obtained from each of the five highway districts in Wyoming. In each district, approximately five concrete and five asphalt pavement sections were selected for each of

13

the highway functional classifications. These sections had various shoulder widths. This selection criteria

resulted in a total of 153 pavement sections for inclusion in this study. A list of the test sections is shown

in Table 3.1. The test sections account for 1,488 kilometers (924 mi) of highway in Wyoming. Of this,

409 km (254 mi) were interstate highways, 401 km (249 mi) were primary highways and 678 km (421

mi) were secondary highways. The shoulder widths for these test sections vary from 0 to 3.0 m (10 ft).

Table 3.1: List of Test Sections

SYS[a]	RT[b]	BMP[c]	EMP[d]	DI[e]	SECTION NAME	AADT	ESAL
I	25	0.00	8.40	1	COLORADO NORTH	5290	945
I	25	13.60	17.00	1	VANDEHEI-TORRINGTON	2900	637
I	25	25.86	30.75	1	WHITAKER SOUTH	2055	493
I	80	186.60	199.00	1	CHEROKEE SECTION	3911	2136
I	80	216.20	221.20	1	SINCLAIR WEST	4241	2011
I	80	233.70	240.00	1	WALCOTT JCT EAST	3870	1923
I	80	285.00	289.90	1	QUEALY DOME SECTION	3785	1970
I	80	319.10	322.50	1	TELEPHONE CANYON	4050	1303
I	80	348.50	358.40	1	OTTO ROAD EAST	3965	1311
I	80	358.40	360.10	1	CHEYENNE WEST	3920	1343
P	21	22.81	33.15	1	RAWLINS-MUDDY GAP JCT.	945	307
P	22	8.42	13.07	1	JCT FAI-80 - SARATOGA	555	70
P	22	13.07	20.60	1	SARATOGA NORTH	715	70
P	23	272.19	278.98	1	MED BOW-ALBANY CO	315	60
P	23	278.98	286.49	1	ALBANY CO LINE EAST	410	60
P	23	327.35	327.39	1	LARAMIE	2350	100
P	23	421.64	424.50	1	TIE SIDING-COLO ST LINE	1690	665
P	23	424.50	425.42	1	TIE SIDING-COLO ST LINE	1690	665
SYS[a]	RT[b]	BMP[c]	EMP[d]	DI[e]	SECTION NAME	AADT	ESAL
P	25	8.31	8.47	1	CHEYENNE	7650	260
P	25	16.94	17.23	1	CHEYENNE	625	140
P	25	17.23	18.67	1	CHEYENNE-GOSHEN CO	740	130
P	25	18.67	19.82	1	CHEYENNE-GOSHEN CO	790	130
P	25	19.82	23.20	1	CHEYENNE-GOSHEN CO	790	130
P	25	23.20	24.18	1	CHEYENNE-GOSHEN CO	790	130
P	25	24.18	27.06	1	CHEYENNE-GOSHEN CO	790	130
P	25	27.06	31.42	1	CHEYENNE-GOSHEN CO	790	130
P	26	1.26	1.38	1	LARAMIE	4735	150
P	26	2.60	15.94	1	LARAMIE-WOODS LANDING	785	80

SYS	RT	BMP	EMP	DI	SECTION NAME	AADT	ESAL
P	26	16.02	27.06	1	LARAMIE-WOODS LANDING	490	70
P	26	32.93	42.04	1	WOODS LANDING-COLORADO	342	50
P	54	211.87	211.99	1	RAWLINS	2315	320
P	56	359.55	359.73	1	CHEYENNE; I-80 BUSINESS	2420	245
S	102	0.00	10.94	1	CENTENNIAL-ALBANY	148	15
S	103	11.81	16.94	1	LARAMIE-CENTENNIAL	456	32
S	103	16.94	21.69	1	LARAMIE-CENTENNIAL	449	15
S	103	21.69	22.13	1	LARAMIE-CENTENNIAL	370	28
S	103	22.13	27.75	1	LARAMIE-CENTENNIAL	365	26
S	103	27.75	33.72	1	CENTENNIAL-SARATOGA	255	14
S	104	0.00	0.02	1	WYO 130-HERRICK LANE	85	15
S	104	0.02	1.70	1	WYO 130-HERRICK LANE	85	15
S	104	1.70	2.46	1	WYO 130-NORTHWEST	85	15
S	104	2.46	2.78	1	WYO 130-NORTHWEST	85	15
S	104	2.78	3.01	1	WYO 130-NORTHWEST	85	15
S	104	3.01	12.18	1	WYO 130-HERRICK LANE	85	15
S	105	0.00	1.25	1	ROCK RIVER-MCFADDEN	109	25
S	105	1.25	9.53	1	ROCK RIVER-MCFADDEN	74	16
S	105	9.53	17.19	1	MCFADDEN-ARLINGTON	78	19
S	107	10.38	20.39	1	HAPPY JACK ROAD	412	27
S	107	20.39	26.45	1	HAPPY JACK ROAD	287	25
S	107	26.45	32.45	1	HAPPY JACK ROAD	195	23
S	401	46.97	49.61	1	SAVERY-ENCAMPMENT	60	8
S	401	51.10	55.95	1	SAVERY-ENCAMPMENT	255	18
S	410	241.66	252.59	1	WALCOTT JCT-MED BOW	413	72
S	410	252.59	263.67	1	WALCOTT JCT-MED BOW	213	50
S	410	263.67	266.90	1	WALCOTT JCT-MED BOW	215	50
S	1104	0.88	17.14	1	PINE BLUFFS-ALBIN	175	22
SYS[a]	RT[b]	BMP[c]	EMP[d]	DI[e]	SECTION NAME	AADT	ESAL
S	1105	9.32	18.54	1	JCT US 85-ALBIN	99	15
I	25	47.84	51.60	2	CHUGWATER SOUTH	2005	493
I	25	75.31	81.50	2	WHEATLAND MARGINAL	2024	483
I	25	109.11	120.82	2	GLENDO NORTH	2115	540
I	25	134.90	141.42	2	DOUGLAS MARGINAL	2160	603
I	25	141.42	150.00	2	DOUGLAS NORTH	2610	675
I	25	175.10	185.40	2	CASPER SOUTH	2965	644
I	25	185.40	190.00	2	CASPER MARGINAL	6533	755
I	25	219.00	228.00	2	NATRONA CO LINE SOUTH	1065	285
I	25	263.70	271.14	2	BUFFALO SOUTH	1005	263
P	21	44.77	51.06	2	MUDDY GAP-NA CO LINE	655	230
P	21	57.01	58.89	2	NA CO LINE-CASPER	695	230

P	21	117.15	117.21	2	CASPER	4860	485
P	24	46.03	55.98	2	NA CO LINE-JCT P-21	300	40
P	25	72.30	74.49	2	GOSHEN CO-HAWK SPRINGS	865	150
P	25	93.12	93.63	2	HAWK SPR-TORRINGTON	3810	350
P	25	150.22	160.52	2	LUSK-MULE CR	795	200
P	27	15.51	18.50	2	GUERNSEY-FT. LARAMIE	920	214
P	34	1.10	3.87	2	CASPER-NATRONA	5436	331
P	34	39.23	41.86	2	PWD RIV-HELL'S 1/2 ACRE	885	228
P	42	100.00	102.05	2	MIDWEST-JOHNSON CO	1065	210
P	57	79.00	79.42	2	WHEATLAND	2215	115
P	58	135.47	135.83	2	DOUGLAS	1185	205
S	406	4.28	4.64	2	LAMONT-BAIROIL	235	88
S	502	8.28	9.26	2	DOUGLAS-ORPHA	161	28
S	502	9.26	14.38	2	ORPHA-ROSS	135	25
S	505	166.22	172.44	2	GLENROCK-CASPER	607	85
S	807	0.00	7.73	2	TORRINGTON-HUNTLEY	365	55
S	807	7.73	10.99	2	HUNTLEY-NEBR ST LINE	262	49
S	807	10.99	14.07	2	TABLE MT RD-NEB ST LINE	180	35
S	811	0.00	7.03	2	YODER JCT-HUNTLEY	140	30
S	1000	100.00	107.53	2	KAYCEE-BARNUM	80	13
S	1002	15.88	35.64	2	KAYCEE-LINCH	91	27
S	1400	517.30	523.28	2	HARTVILLE-MANVILLE	81	11
S	1604	0.09	3.37	2	WHEATLAND EAST	302	40
S	1604	3.37	11.91	2	WHEATLAND EAST	66	16
S	1610	0.00	0.47	2	WHEATLAND-DWYER JCT	1035	38
S	1610	0.47	1.94	2	WHEATLAND-DWYER JCT	775	35
S	1610	1.94	2.47	2	WHEATLAND-DWYER JCT	625	33
SYS[a]	RT[b]	BMP[c]	EMP[d]	DI[e]	SECTION NAME	AADT	ESAL
I	80	0.00	2.90	3	UTAH ST LINE	4730	2363
I	80	6.90	12.30	3	EVANSTON EAST	4585	2237
I	80	22.70	27.50	3	BIGELOW BENCH	4305	2125
I	80	44.00	49.00	3	LYMAN EAST	3956	2029
I	80	83.00	86.00	3	GREEN RIVER WEST	5850	2752
I	80	92.20	101.70	3	GREEN RIVER EAST	7121	2668
I	80	120.30	130.00	3	POINT OF ROCKS WEST	4860	2473
I	80	143.00	148.50	3	PATRICK DRAW SECTION	3910	2105
I	80	153.80	161.00	3	TABLE ROCK EAST	3900	2105
I	80	153.80	161.00	3	TABLE ROCK EAST	3900	2105
I	80	171.70	186.60	3	SWEETWATER CO LINE WEST	3925	2105
P	10	85.59	87.16	3	AFTON	1864	175
P	10	154.25	155.12	3	JACKSON STREETS	4206	302

SYS[a]	RT[b]	BMP[c]	EMP[d]	DI[e]	SECTION NAME	AADT	ESAL
P	11	36.58	38.20	3	KEMMERER-LABARGE	2130	160
P	11	85.92	93.04	3	SUBLETTE CO LINE	430	100
P	12	48.79	52.09	3	SAGE JCT-KEMMERER	845	495
P	12	52.42	52.63	3	KEMMERER	814	488
P	13	70.94	88.59	3	SB CO LINE-PINEDALE	640	60
P	17	504.19	511.40	3	FLMNG GRG INT-UTAH LINE	230	40
P	52	89.75	91.63	3	GREEN RIVER	3530	230
P	53	105.86	106.48	3	ROCK SPRINGS	2310	215
S	1207	0.13	0.88	3	US 89-FREEDOM	440	38
S	1800	0.50	4.56	3	BIG PINEY-WEST	493	55
S	1903	20.00	30.15	3	ROCK SPRINGS-HIAWATHA	138	28
S	1906	0.00	4.78	3	GREEN RIVER-FONTENELLE	812	254
S	1906	4.78	8.08	3	GREEN RIVER-FONTENELLE	795	250
S	2000	6.58	13.71	3	WILSON-IDAHO ST LINE	1112	49
I	25	279.40	285.00	4	BUFFALO SOUTH	1005	263
I	25	293.81	299.30	4	BUFFALO MARGINAL	1015	263
I	90	19.96	21.50	4	SHERIDAN NORTH	2379	454
I	90	85.50	93.20	4	POWDER RIVER EAST	1735	250
I	90	106.70	112.50	4	WILD HORSE CR SECTION	1740	255
I	90	124.30	129.60	4	GILLETTE MARGINAL	2680	357
I	90	145.20	152.20	4	MOORCROFT WEST	2015	435
I	90	155.10	160.30	4	MOORCROFT EAST	1625	310
I	90	185.70	195.00	4	SUNDANCE MARGINAL	1742	310
I	90	202.00	207.14	4	STATE LINE WEST	1770	318
P	25	209.56	211.95	4	WESTON CO-NEWCASTLE	395	110
P	35	62.05	71.12	4	BURGESS JCT-DAYTON	400	45
SYS[a]	RT[b]	BMP[c]	EMP[d]	DI[e]	SECTION NAME	AADT	ESAL
P	35	89.38	89.87	4	RANCHESTER	1225	85
P	36	91.96	92.12	4	BUFFALO	3420	145
P	43	56.51	62.19	4	CAMPBELL CO-WRIGHT	365	95
P	43	72.42	83.73	4	CAMPBELL CO-WRIGHT	953	238
P	43	118.83	119.56	4	GILLETTE-MONTANA ST	315	60
P	43	122.64	123.84	4	GILLETTE-MONTANA ST	310	60
P	43	146.11	152.93	4	GILLETTE-MONTANA ST	165	38
P	48	4.64	7.10	4	S DAKOTA-MONTANA ST	525	239
P	49	0.39	1.08	4	NEWCASTLE	2330	70
P	60	22.97	23.48	4	SHERIDAN	8240	110
P	62	125.47	126.25	4	GILLETTE	6610	270
S	300	31.90	38.88	4	SAVAGETON	314	59
S	300	38.88	45.25	4	SAVAGETON	235	30
S	300	45.25	52.67	4	SAVAGETON	235	30

17

SYS	RT	BMP	EMP	DI	SECTION NAME	AADT	ESAL
S	302	89.26	99.33	4	CLEARMONT-GILLETTE	233	51
S	600	16.46	28.21	4	SUNDANCE-UPTON	216	28
S	604	7.62	13.20	4	HULETT-ALZADA	89	13
S	604	13.20	21.69	4	HULETT-ALZADA	60	10
S	604	21.69	29.50	4	HULETT-ALZADA	60	10
S	607	167.18	174.63	4	MOORCROFT-SUNDANCE	331	45
S	1003	100.00	104.01	4	BUFFALO-SHERIDAN	192	28
S	1006	289.15	295.05	4	KAYCEE-BUFFALO	115	13
S	1006	297.55	299.30	4	KAYCEE-BUFFALO	340	18
S	1704	1.22	11.52	4	SHERIDAN	198	20
S	2300	32.00	44.91	4	CLARETON-RENO JCT	170	33
S	2300	44.91	50.66	4	CLARETON-RENO JCT	170	33
S	2302	0.68	13.45	4	UPTON-HAY CREEK	65	18
S	2302	13.45	19.98	4	HAY CREEK-CLARETON	65	18
S	2302	19.98	25.06	4	HAY CREEK-CLARETON	65	18
S	2302	25.06	32.46	4	HAT CREEK-CLARETON	65	18
P	20	68.18	72.87	5	JEFFERY CITY-LANDER	305	70
P	30	40.71	46.88	5	MORAN JCT-DUBOIS	690	63
P	31	10.00	20.00	5	YELLOWSTONE-CODY	810	60
P	31	45.06	45.89	5	YELLOWSTONE-CODY	1035	80
P	31	51.78	52.96	5	CODY	5880	290
P	31	72.71	75.72	5	CODY-BIGHORN CO LINE	650	70
P	33	57.66	62.98	5	MEETEETSE-CODY	730	120
P	34	116.14	116.44	5	SHOSHONI-THERMOPOLIS	1025	322
P	34	236.26	237.42	5	LOVELL	2292	251
SYS[a]	RT[b]	BMP[c]	EMP[d]	DI[e]	SECTION NAME	AADT	ESAL
P	37	0.00	0.25	5	GREYBULL-SHERIDAN CO	1370	70
S	200	112.06	116.90	5	BASIN-BURLINGTON	245	25
S	202	12.16	127.33	5	FOSTER GULCH RD	210	35
S	708	22.73	24.15	5	SAND DRAW-SWEETWATER	185	38
S	1505	7.66	12.17	5	WILLWOOD-POWELL	527	59
S	2203	0.55	7.27	5	TENSLEEP-BIG TRAILS	125	15

a. SYS = Highway System
   I = Interstate
   P = Primary
   S = Secondary
b. RT = Route Number
c. BMP = Beginning Milepost
d. EMP = Ending Milepost
e. DI = District

Data Collection and Database Preparation

Extensive data were collected on all test sections from the Highway Safety Branch of the

Wyoming Department of Transportation (WYDOT) and from the WYDOT Pavement Management

System. Information also was gathered from the Wyoming's Comprehensive Report on Traffic Crashes

published by WYDOT. The collected data were then summarized into a computerized database for

analysis.

Accident Data

Accident data collected from the Highway Safety Branch included the time and location of each

accident as well as vehicle and driver information. The data also contained information on surface and

light conditions, and road alignment. Accident data were collected for a five-year period between 1991

and 1995. Data pertaining to accidents included: route number, year of accident, rural or urban route,

county, highway system (interstate, primary or secondary), milepost, highway element involved in

accident, highway district, divided highway, side of highway, accident date, day of week, time of

accident, number of vehicles involved, number of pedestrians, number injured, number killed, first

harmful event, location of first harmful event, number of lanes, type of road surface, light conditions,

conditions of the road, weather conditions, road alignment, junction relationship, adverse road

conditions, collision type, functional classification, drinking involved, traffic control, repair cost, posted

speed, estimated speed, vehicle type, visual obstruction, damage severity, human contributing factor,

activity prior to crash, direction of travel, driver's age and sex. All of the possible data fields pertaining

to each item listed above are included in Appendix A. Examples of the collected data can be seen in

Appendix A.

Test Section Data

Information related to the materials and dimensions of test sections also was collected from the

WYDOT Pavement Management System. The data included shoulder width, lane width, thickness of the

various layers, material type for the shoulder and traveled way. WYDOT's Pavement Management System also contained the Average Annual Daily Traffic (AADT) and the Equivalent Single Axle Loads (ESAL) for each section. These AADTs and the ESALs are presented in Table 3.1 with their corresponding test section.

Database Preparation

After gathering the required data on all test sections, data was organized into a format that could be used in the analysis. A comprehensive statistical analysis was performed using the SAS statistical software package. Various statistical methods were considered. It was decided that the generalized linear model using the Poisson distribution would best represent the data for analysis.

The data was organized to include number of accidents that occurred on each test section, length of the test section, and AADT for each section. Also, for each section, information was included on light conditions, surface conditions, alignment of the roadway, and whether accidents were fatal or non-fatal. Finally, vehicle kilometers traveled (VKMT) were calculated and included in the database. VKMTs were calculated using the following equation: VKMT = length (km) * AADT * 365(days) * 5(years). The number of accidents for each functional classification and year can be seen in Table 3.2. It is clear from this table that the total number of accidents over the five-year analysis period for the test sections was 8,785.

Table 3.2: Number of Accidents in Analysis

Year	1991	1992	1993	1994	1995	Total
Interstate	646	1122	784	718	683	3953
Primary	711	777	1020	846	871	4225
Secondary	120	90	119	122	156	607
Total						8785

Chapter Summary

This chapter described the research project organization and test sections selection process. The data to be used in the analysis was presented. In addition, the process of preparing the database for analysis was described.

CHAPTER 4

SAFETY ANALYSIS

Statistical Terminology

After collecting accident and related data on all test sections, a comprehensive analysis was performed on the data. Two regression techniques were used to conduct the analysis: Normal regression and Poisson regression. This chapter describes the regression methods and other statistical terms used. In addition, results of the analysis on the accident data are summarized in this chapter.

Regression Analysis

Regression analysis is a statistical method that uses the relationship between two or more quantitative variables so that one variable can be predicted from the other or others. Regression analysis is widely used in business, the social and behavioral sciences, and the biological sciences in addition to transportation studies. Regression analysis results in a regression model to predict an outcome based on the predictor variable or variables. When more than one predictor variable is used, it is referred to as multiple regression. This study uses multiple regression techniques [10].

Normal Regression

Normal regression is a linear regression model. The general linear regression model follows [10]:

$$Y_i = \beta_0 + \beta_1 X_{i1} + \beta_2 X_{i2} + \cdots + \beta_{p-1} X_{i,p-1} + \varepsilon_i \qquad (4.1)$$

where: $\beta_0, \beta_1, ..., \beta_{p-1}$ are parameters,

$X_{i1}, ..., X_{i,p-1}$ are known constants,

ε_i are independent normally distributed, with mean 0 and variance σ^2, and

$i = 1, ..., n.$

In matrix terms, the general linear regression model (4.1) is [10]:

$$\mathbf{Y} = \mathbf{X}\,\boldsymbol{\beta} + \boldsymbol{\varepsilon} \qquad (4.2)$$

where: $\mathbf{Y}$ is a vector of responses,

$\boldsymbol{\beta}$ is a vector of parameters,

$\mathbf{X}$ is a matrix of constants, and

$\boldsymbol{\varepsilon}$ is a vector of independent normal random variables.

The random vector $\mathbf{Y}$ has expectation [10]:

$$\mathbf{E}\,(\mathbf{Y}) = \mathbf{X}\boldsymbol{\beta} \qquad (4.3)$$

In this study, two linear models were examined. The first model (4.4) looks at the expectation of the number of accidents that will occur for the analysis period. The second model (4.5) examines the expectation of the rate of accidents.

$$E\,(\,Y_i\,) = X_i\beta + VKMT_i\beta_v \qquad (4.4)$$

$$E\,(\,RY_i\,) = X_i\beta \qquad (4.5)$$

Coefficient of Determination

The coefficient of determination, usually denoted as R^2, is interpreted as the proportionate reduction of total variation associated with use of the predictor variable X. Therefore, the larger the R^2 is, the more the total variation of Y is reduced by introducing the predictor variable X. The R^2 value can vary between zero and one. Thus, the closer the R^2 value is to one, the stronger the relationship, and an R^2 close to zero shows that the relationship is weak [10].

Poisson Regression

Poisson regression is a nonlinear regression model where the response outcomes are discrete. It is a log-linear model. Poisson regression often is used when the outcome is a count, such as the number of accidents [10]. It has one parameter μ equal to the mean, which must be non-negative, as compared to

24

the parameter of the Normal distribution, which is unrestricted. The ideas of a regression model remain the same as for the Normal model, except that now the parameters β measure effects on the scale of log frequencies [11]. This study concentrated on estimating the number of accidents that occur with various shoulder widths and thus, Poisson regression was used. The following is the log-linear Poisson model used in the analysis [12]:

$$\log\{n_i\} = \log\{N_i\} + x_i\beta. \tag{4.6}$$

where: n_i is the expected number of events,

N_i is the offset,

x_i is the variable matrix, and

β is the vector of coefficients.

For this analysis, the events are accidents, the offset is vehicle kilometers traveled (VKMT) and the variables include: alignment, light, and surface conditions. The coefficients are determined by analysis. In this report, log is base e. To use the Poisson regression, an assumption was made that, all other factors being equal, with twice the VKMT there would be twice the number of accidents.

Analysis of Test Sections

Analyses were performed using Normal and Poisson regressions as described in the above sections. This was done using the SAS software package [12]. An example of the SAS input can be seen in Appendix B. Appendix B also contains the output for the statistical analysis conducted on SAS. This section presents the results of this analysis.

Results from Statistical Analysis

The statistical analysis, using Normal regression, did not yield adequate models for the prediction of accident numbers or accident rates. The coefficient of determination for the models were very low, which means that the relation between the accident numbers or rates and the specific conditions considered was weak. Some of these R^2 values were equal to: 0.000171, 0.0633, 0.000051 and

25

0.149. Furthermore, with count data, model assumptions for Normal regression are less appropriate than are assumptions for Poisson regression. Therefore, Poisson regression was examined, and it was found to give better models.

The statistical analysis, using Poisson regression, yielded prediction models for the conditions analyzed. The following model was developed to predict accidents by considering shoulder width only and regardless of functional classification, surface conditions, light conditions or roadway alignment:

$$\log(n) = \log(\text{VKMT}) - 12.046 - 0.358 * \text{ShWidth}. \tag{4.7}$$

where: n = number of accidents for a five year period,

VKMT = vehicle kilometers traveled and

ShWidth = shoulder width in meters.

Similar models were developed to predict accident numbers based on surface conditions, light conditions and alignment. These conditions and the models are summarized in Table 4.1. The models are applicable to roadways of any functional classification. The equations can be used to predict the number of accidents that would occur with various shoulder widths. The general model, equation (4.7), was examined by plugging information from typical test sections with the lowest, average and highest VKMT. The results from these calculations are shown in Table 4.2. These predicted accident numbers are for the five-year analysis period. For example, on a highway with a VKMT of 21,574,000 and 0.6 m shoulders, it would be expected to have approximately 102 accidents over a five-year period.

Table 4.1: Models for Predicting Accident Numbers for a Five-Year Analysis Period

Conditions		Equation
All Conditions		log(n)=log(VKMT) - 12.046 - 0.358*ShWidth
Surface Conditions	Dry	log(n)=log(VKMT) - 12.357 - 0.483*ShWidth
	Poor	log(n)=log(VKMT) - 13.320 - 0.162*ShWidth
Light Conditions	Daylight	log(n)=log(VKMT) - 12.391 - 0.400*ShWidth
	Dark	log(n)=log(VKMT) - 13.428 - 0.269*ShWidth
	Dawn or Dusk	log(n)=log(VKMT) - 15.208 - 0.313*ShWidth
Alignment	Straight	log(n)=log(VKMT) - 12.204 - 0.363*ShWidth
	Curved	log(n)=log(VKMT) - 13.970 - 0.330*ShWidth

Table 4.2: Predicted Accident Numbers for Sections with Variable VKMTs for a Five-Year Period

VKMT	Shoulder Width (m)[a]					
	0	0.6	1.2	1.8	2.4	3.0
lowest value: 248,600	1.46	1.18	0.95	0.77	0.62	0.50
average value: 21,574,000	126.54	102.10	82.38	66.47	53.63	43.27
highest value: 198,770,600	1165.88	940.70	759.02	612.43	494.14	398.71

a. 0.3 m = 1.0 ft

In addition, using Poisson regression, the number of lanes and fatalities were considered but they resulted in poor models. Also, the Poisson regression was performed based on the following functional classifications: interstate, primary, and secondary roadways. Surface conditions, light conditions and roadway alignment were included in the analysis. Table 4.3 presents the models for the the interstate sections, Table 4.4 includes the models for the primary sections. Similar appropriate models could not be obtained on secondary roadways.

27

Table 4.3: Interstate Models

Conditions		Equation
Shoulders Only		log(n)=log(VKMT) - 12.859 - 0.171*ShWidth
Road Conditions	Dry	log(n)=log(VKMT) - 13.632 - 0.212*ShWidth
	Poor	log(n)=log(VKMT) - 13.529 - 0.138*ShWidth
Light Conditions	Daylight	log(n)=log(VKMT) - 13.140 - 0.269*ShWidth
	Dark	log(n)=log(VKMT) - 14.482 - 0.023*ShWidth
	Dawn or Dusk	log(n)=log(VKMT) - 16.400 - 0.0003*ShWidth
Alignment	Straight	log(n)=log(VKMT) - 13.403 - 0.072*ShWidth
	Curved	log(n)=log(VKMT) - 13.775 - 0.409*ShWidth

Table 4.4: Primary Models

Conditions		Equation
Shoulders Only		log(n)=log(VKMT) - 11.613 - 0.155*ShWidth
Road Conditions	Dry	log(n)=log(VKMT) - 11.956 - 0.169*ShWidth
	Poor	log(n)=log(VKMT) - 12.932 - 0.121*ShWidth
Light Conditions	Daylight	log(n)=log(VKMT) - 12.002 - 0.119*ShWidth
	Dark	log(n)=log(VKMT) - 12.950 - 0.249*ShWidth
	Dawn or Dusk	log(n)=log(VKMT) - 15.029 - 0.225*ShWidth
Alignment	Straight	log(n)=log(VKMT) - 11.734 - 0.124*ShWidth
	Curved	log(n)=log(VKMT) - 13.847 - 0.558*ShWidth

Effect of Shoulder Width on Accident Numbers

After models were developed for predicting accident numbers, an analysis was performed to estimate the percent reduction in accidents due to variable increases in shoulder widths. Table 4.5 shows the percent reduction in accidents when compared to the number of accidents that would occur at locations with no shoulders. From this table, it can be seen that when considering all conditions in the analysis, if a 1.8 m (6 ft) shoulder was in place instead of a 0 m shoulder, there would be a 47.5 percent reduction in accidents. It also is clear from Table 4.5, that shoulders are more effective under dry conditions than in poor conditions. In other words, when the pavement is slippery, wider shoulders will not be as effective as when the pavement is dry. Also, this table indicates that shoulders are more effective during daylight and on straight sections.

28

Another analysis was performed on the database to determine the percent reduction in accidents due to incremental increase in shoulder width by 0.6 meters (2 ft). Table 4.6 shows that adding 0.6 m (2 ft) of shoulder to a location with no shoulders has the largest effect on the percent reduction in accidents. The percent reduction in the number of accidents steadily decreases after this point. This clearly indicates that the first 0.6 m (2 ft) of shoulders is the most effective in reducing accidents.

Table 4.5: Percent Reduction in Accidents Due to the Addition of Shoulders with Variable Widths

Conditions		Shoulder Width (m)[a]					
		0	0.6	1.2	1.8	2.4	3.0
All Conditions		0.0	19.3	34.9	47.5	57.6	65.8
Surface Conditions	Dry	0.0	25.2	44.0	58.1	68.7	76.5
	Poor	0.0	9.3	17.7	25.3	32.3	38.6
Light Conditions	Daylight	0.0	21.3	38.1	51.3	61.7	69.9
	Dark	0.0	14.9	27.6	38.4	47.6	55.4
	Dawn or Dusk	0.0	17.1	31.3	43.1	52.9	60.9
Alignment	Straight	0.0	19.6	35.3	48.0	58.2	66.3
	Curved	0.0	17.9	32.7	44.8	54.7	62.8

a. 0.3 m = 1.0 ft

Table 4.6: Percent Reduction in Accidents Due to the Incremental Increase in Shoulder Width by 0.6 m

Conditions		Shoulder Width (m)[a]					
		0	0.6	1.2	1.8	2.4	3.0
All Conditions		0.0	19.3	15.6	12.6	10.1	8.2
Surface Conditions	Dry	0.0	25.2	18.8	14.1	10.5	7.9
	Poor	0.0	9.3	8.4	7.6	6.9	6.3
Light Conditions	Daylight	0.0	21.3	16.8	13.2	10.4	8.2
	Dark	0.0	14.9	12.7	10.8	9.2	7.8
	Dawn or Dusk	0.0	17.1	14.2	11.8	9.8	8.1
Alignment	Straight	0.0	19.6	15.7	12.7	10.2	8.2
	Curved	0.0	17.9	14.7	12.1	9.9	8.1

a. 0.3 m = 1.0 ft

Effect of Shoulder Width on Accident Costs

The next step in this study examined cost-effectiveness of increasing shoulder widths. Accident costs were estimated using Wyoming's Comprehensive Report on Traffic Accidents [13 - 17]. Statewide, the total number of accidents and total cost were determined over the analysis period. The average cost per accident then was calculated. The accident numbers and costs are summarized in Table 4.7. The average cost per accident for the five-year study period was $21,777.35. Using this estimate and the predicted number of accidents, it was possible to determine cost of the accidents corresponding to various shoulder widths. Once again, the highest, lowest, and average VKMTs were used in the calculations. The costs of accidents with respect to shoulder widths and VKMTs are summarized in Table 4.8. It is clear from this table that building high volume highways with no shoulders will result in extremely high accident costs. However, building a low volume road with no shoulders can be tolerated since accident costs are relatively low. Table 4.9 shows the reduction in accident costs due to the addition of shoulders with variable widths.

Table 4.7: Accident Costs in the State of Wyoming

Year	Cost	Accidents	VKMT	Average Cost
1991	$172,462,100	12,677	9,658,390,000	$13,604
1992	$198,192,500	13,081	9,980,390,000	$15,151
1993	$347,135,500	14,443	10,899,700,000	$24,035
1994	$371,248,800	14,227	10,772,510,000	$26,095
1995	$432,775,000	14,425	NA	$30,002
Total				$108,887
Average Cost				$21,777

Table 4.8: Cost of Accidents for a Five Year Period

VKMT	Shoulder Width (m)[a]		
	0	0.6	1.2
248,600 lowest value	$31,753	$25,620	$20,672
198,770,600 highest value	$25,389,684	$20,486,025	$16,529,438
21,574,000 average value	$2,755,725	$2,223,495	$1,794,059

VKMT	Shoulder Width (m)[a]		
	1.8	2.4	3.0
248,600 lowest value	$16,679	$13,458	$10,859
198,770,600 highest value	$13,337,011	$10,761,155	$8,682,790
21,574,000 average value	$1,447,562	$1,167,985	$942,406

a. 0.3 m = 1.0 ft

Table 4.9: Reduction in Costs for a Five Year Period

VKMT	Shoulder Width (m)[a]		
	0	0.6	1.2
248,600 lowest value	$0.00	$6,133	$11,081
198,770,600 highest value	$0.00	$4,903,659	$8,860,245
21,574,000 average value	$0.00	$532,229	$961,666

VKMT	Shoulder Width (m)[a]		
	1.8	2.4	3.0
248,600 lowest value	$15,073	$18,295	$20,894
198,770,600 highest value	$12,052,673	$14,628,528	$16,706,893
21,574,000 average value	$1,308,163	$1,587,739	$1,813,319

a. 0.3 m = 1.0 ft

Chapter Summary

In this chapter, the methods used to analyze accident data and the results of this analysis were presented. Poisson regression was performed. Then the results of this regression were used to predict accident numbers for various shoulder widths. It is clear from this analysis that wider pavement shoulders will result in lower accident numbers. This accident reduction depends on traffic level and the length of the section.

CHAPTER 5

STRUCTURAL ANALYSIS

Analysis Methods

The finite element analysis and the BISAR computer program were used in the structural analysis of pavement shoulders. The model characteristics, procedures used in these methods, and results are described in this chapter.

Finite Element Analysis

Finite element analysis is used in all types of applications to calculate a field quantity. This field quantity could be displacement or stress for a stress analysis, temperature or heat flux in a thermal analysis or the stream function or the velocity potential in a fluid flow analysis. Finite element analysis is a way of getting a numerical solution to a specific problem. The solution to a finite element analysis is approximate unless the problem is so simple that a convenient exact formula already is available.

Finite element analysis consists of dividing a structure into several elements, describing the behavior of each element in a simple way, then reconnecting elements at "nodes" as if nodes were pins or drops of glue that hold elements together. This process results in a set of simultaneous algebraic equations. In stress analysis the equations are equilibrium equations of nodes. There may be several hundred or several thousand equations, which makes computer analysis mandatory.

A more complex description of the finite element method regards it as piecewise polynomial interpolation. That is, over an element, a field quantity such as displacement is interpolated from values of the field quantity at nodes. By connecting elements together, the field becomes interpolated over the entire structure in a piecewise fashion, by as many polynomial expressions as there are elements. The "best" values of the field quantity at nodes are those that minimize some function such as total energy. The minimization process generates a set of simultaneous algebraic equations for values of the field

33

quantity at nodes. Matrix symbolism for this set of equations is $\mathbf{KD} = \mathbf{R}$, where $\mathbf{D}$ is a vector of

unknowns (values of the field quantity at nodes), $\mathbf{R}$ is a vector of known loads and $\mathbf{K}$ is a matrix of

known constants. In stress analysis, $\mathbf{K}$ is known as a "stiffness matrix."

The finite element method is a versatile tool for structural analysis. The structure analyzed can

be of any shape, type of supports, and loading configuration [18].

Patran

Patran is a software package developed by PDA Engineering that was used to perform the finite

element analysis in this study. It allows the user to solve many types of structural problems using finite

element analysis. The following is the input that Patran required for this analysis: the geometrics of the

problem, loading conditions, and boundary conditions. Geometrics included the shape and dimensions of

the structure and the number of elements to be used in the structure.

BISAR

BISAR is an acronym for Bituminous Structures Analysis in Roads. It was developed by the

Shell Oil Company. BISAR is a program to find stresses, strains, and displacements in asphalt pavement

structures. It assumes that the pavement structure is infinite in the x and y directions. The z direction is

the depth and is dependent on the input. The bottom layer in the z direction is assumed to be infinite in

depth. The pavement structures are a N-Layer System in BISAR. Examples of the input and output for

this program are included in Appendix C.

BISAR solves various asphalt pavement problems. To solve these problems, certain information

about the problem must be specified in the input coding. The required input for BISAR includes number

of layers in the structural system, modulus of elasticity, and Poisson's ratio for each of those layers,

thickness of each layer, number of loads being applied to the system, horizontal and vertical components

of these loads, position of the loads, radius of the loads, number of points where the displacement, stress

and strain are to be determined, and the location of the points. Furthermore, all the units for the input

must be the same, so the units of the output are known. The output from BISAR does not specify the units being used, neither does the input [19].

Model Characteristics

Characteristics of the models used for the two analysis methods are quite similar. These characteristics include thickness of the layers, types of materials, and properties for the various materials. BISAR only uses the information pertaining to asphalt pavement structures. This section examines these characteristics for each analysis procedure.

A three-layer system was used in the analysis. The materials incorporated in the surface layer were asphalt or concrete. Base materials included granular base course, asphalt treated base (ATB), or cement treated base (CTB). Subgrade is the existing in place soil. Table 5.1 summarizes the modulus of elasticity (E) and Poisson's ratio (v) for the materials analyzed in this study.

Table 5.1: Material Properties

Material	E(kPa)[a]	υ
Concrete	24,131,650	0.15
Asphalt	2,757,900	0.35
CTB	4,136,850	0.25
ATB	1,378,950	0.37
Granular Base	172,370	0.40
Subgrade	103,420	0.43

a. 1.0 psi = 6.89 kPa

Maximum and minimum layer thicknesses were used in this analysis. Minimum concrete thickness used was 152.4 mm (6 inches) while the maximum was 304.8 mm (12 inches). Minimum asphalt thickness was 76.2 mm (3 inches) and the maximum was 304.8 mm (12 inches). The base layer thickness used in the analysis was the average base layer thickness of all test sections, which was 152.4 mm (6 inches).

Finite Element Analysis

The finite element model used in this study represented a typical driving lane and a shoulder. This was done for simplicity and ease of analysis. The pavement structure consists of a 3.6 m (12 ft) traveled way and a variable shoulder width. The material properties described in the previous section were used to create various models for analysis. An example of one of the finite element models is shown in Figure 5.1. The nodes that previously were described are represented by points where the lines intersect in Figure 5.1. Plane strain analysis was used for this model. The materials were assumed to be isotropic and linearly elastic. Plane strain is a situation in which $\varepsilon_z = 0$, because physical constraints prevent the strain from occurring in that direction. Furthermore, plane sections that are perpendicular to the longitudinal axis remain plane and at the same distance apart. An isotropic material is one in which the material properties are the same regardless of direction. A material is elastic if the strains caused by the application of a given load disappear when the load is removed [20]. It is linearly elastic if the strains increase or decrease linearly. Rollers were used as the boundary condition along the bottom of the model and on the left side of the model.

Figure 5.1: Finite Element Model

A unit load was applied to the model at 0.3 m (1 ft) away from the edge of the traveled way. This load was applied as one foot wide to approximately represent the width of a truck tire. This method yielded stresses and strains for the entire pavement structure. For the purpose of this analysis the stresses were found directly under the load, at the edge between the traveled way and the shoulder and at the edge of the shoulder. More specifically, stresses located at the bottom of the surface layer, middle of the surface layer, bottom of the surface layer, bottom of the base, and at the top of the subgrade were collected. This collected data can be seen in Appendix C for all of the models that were analyzed.

BISAR

In the BISAR analysis, the basic model characteristics described above were used only for the asphalt pavement structures. BISAR only can be used to analyze asphalt pavement systems. The load used in this analysis was 40 kN(9000 lbs.), to represent one wheel of the standard 80 kN (18 kip) axle. The tire pressure was assumed to be 689.5 kPa (100 psi). With a circular contact area. The load and tire pressure yield a tire patch radius of 135.9 mm (5.35 in.) by using the equation $F = P/A$ where: F is a force, P is a pressure, and A is the area. In this case, F = 40 kN (9000 lbs.), P = 689.5 kPa (100 psi) and A equals the area of a circle ($A = \pi r^2$). A representation of the conditions for the BISAR analysis can be seen in Figure 5.2. The stresses that were found by this analysis were the ones located directly below the load; at the bottom of the surface and at the top of the subgrade.

Figure 5.2: BISAR Model

Results of Analysis

The two structural analysis methods yielded stresses and strains for the various locations of interest. The locations include stresses at the bottom of the base layer and the top of the subgrade. The results of the two analysis methods are summarized in the following sections.

Finite Element Analysis

The finite element analysis was conducted by using Patran. The stresses were determined by obtaining the stress at a node on the model that was of interest. At locations where there was a transition from one material to another (material interface) the stresses for the specific layer could not be obtained by specifying the node. This is because the finite element method averages stresses from around the node. Thus the stresses would be the same at the bottom of one material and at the top of the other. Stresses normally change at material interfaces. To get these stresses, strains were determined at these nodes. The strain remains the same across the material interface, no matter the change in materials. Then

the following equation was used to obtain the stresses from the strains obtained. The equation is the plane stress-strain relation of a linearly elastic and isotropic material.

$$
\begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix} = \frac{E}{(1+v)(1-2v)} * \begin{bmatrix} (1-v) & v & 0 \\ v & (1-v) & 0 \\ 0 & 0 & (\frac{1-2v}{2}) \end{bmatrix} * \begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} \qquad (5.1)
$$

where: σ_x = x stress,

σ_y = y stress,

τ_{xy} = xy shear,

E = modulus of elasticity,

υ = Poisson's ratio,

ε_x = x strain,

ε_y = y strain, and

γ_{xy} = xy strain.

The stresses at material interfaces were calculated with equation 5.1. Other stresses were obtained by examining the node of interest. The stresses obtained from the finite element analysis are summarized in Tables 5.2 through 5.5. Tables 5.2 and 5.3 contain stresses for the asphalt sections and Tables 5.4 and 5.5 include stresses for the concrete sections. Strains obtained from the finite element analysis are summarized in Tables 5.6 and 5.7 for asphalt and concrete sections, respectively.

Table 5.2: Stresses Under the Load in the Vertical Direction from Finite Analysis on Asphalt Sections

Materials		Thickness (mm)[a]		Shoulder	Stresses (kPa)[c]	
Surface	Base	Surface	Base	Width (m)[b]	Top of Subgrade	Percent Change
Asphalt	Untreated	76.2	152.4	0	-188.1	- - -
Asphalt	Untreated	76.2	152.4	3.0	-218.5	16.2
Asphalt	ATB	76.2	152.4	0	-74.6	- - -
Asphalt	ATB	76.2	152.4	3.0	-71.8	-3.8
Asphalt	CTB	76.2	152.4	0	-47.0	- - -
Asphalt	CTB	76.2	152.4	3.0	-44.7	-4.9
Asphalt	Untreated	304.8	152.4	0	-82.8	- - -
Asphalt	Untreated	304.8	152.4	3.0	-80.3	-3.0
Asphalt	ATB	304.8	152.4	0	-40.2	- - -
Asphalt	ATB	304.8	152.4	3.0	-39.0	-3.0
Asphalt	CTB	304.8	152.4	0	-27.6	- - -
Asphalt	CTB	304.8	152.4	3.0	-26.4	-4.3

a. 1.0 inch = 25.4 mm
b. 1.0 ft = 0.3 m
c. 1.0 psi = 6.89 kPa

Table 5.3: Stresses Between Traveled Way and Shoulder in the Vertical Direction from Finite Element Analysis on Asphalt Sections

| Materials | | Thickness (mm)[a] | | Shoulder | Stresses (kPa)[c] | |
Surface	Base	Surface	Base	Width (m)[b]	Bottom of Base	Percent Change
Asphalt	Untreated	76.2	152.4	0	-112.0	- - -
Asphalt	Untreated	76.2	152.4	3.0	-99.5	-11.2
Asphalt	ATB	76.2	152.4	0	-513.2	- - -
Asphalt	ATB	76.2	152.4	3.0	-467.1	-9.0
Asphalt	CTB	76.2	152.4	0	-1051.4	- - -
Asphalt	CTB	76.2	152.4	3.0	-956.6	-9.0
Asphalt	Untreated	304.8	152.4	0	-97.0	- - -
Asphalt	Untreated	304.8	152.4	3.0	-91.4	-5.8
Asphalt	ATB	304.8	152.4	0	-383.5	- - -
Asphalt	ATB	304.8	152.4	3.0	-362.0	-5.6
Asphalt	CTB	304.8	152.4	0	-741.1	- - -
Asphalt	CTB	304.8	152.4	3.0	-702.8	-5.2

a. 1.0 inch = 25.4 mm
b. 1.0 ft = 0.3 m
c. 1.0 psi = 6.89 kPa

Table 5.4: Stresses Under the Load in the Vertical Direction from Finite Element Analysis on Concrete Sections

| Materials | | Thickness (mm)[a] | | Shoulder | Stresses (kPa)[c] | |
Surface	Base	Surface	Base	Width (m)[b]	Top of Subgrade	Percent Change
Concrete	Untreated	152.4	152.4	0	-88.3	- - -
Concrete	Untreated	152.4	152.4	3.0	-83.2	-5.8
Concrete	CTB	152.4	152.4	0	-32.0	- - -
Concrete	CTB	152.4	152.4	3.0	-27.8	-13.1
Concrete	Untreated	304.8	152.4	0	-53.4	- - -
Concrete	Untreated	304.8	152.4	3.0	-49.3	-7.7
Concrete	CTB	304.8	152.4	0	-23.4	- - -
Concrete	CTB	304.8	152.4	3.0	-20.7	-11.5

a. 1.0 inch = 25.4 mm
b. 1.0 ft = 0.3 m
c. 1.0 psi = 6.89 kPa

Table 5.5: Stresses Between Traveled Way and Shoulder in the Vertical Direction from Vertical Direction from Finite Element Analysis on Concrete Sections

Materials		Thickness (mm)[a]		Shoulder	Stresses (kPa)[c]	
Surface	Base	Surface	Base	Width (m)[b]	Bottom of Base	Percent Change
Concrete	Untreated	152.4	152.4	0	-3488.6	- - -
Concrete	Untreated	152.4	152.4	3.0	-3292.1	-5.6
Concrete	CTB	152.4	152.4	0	-831.6	- - -
Concrete	CTB	152.4	152.4	3.0	-745.5	-10.4
Concrete	Untreated	304.8	152.4	0	-71.1	- - -
Concrete	Untreated	304.8	152.4	3.0	-61.6	-13.4
Concrete	CTB	304.8	152.4	0	-577.4	- - -
Concrete	CTB	304.8	152.4	3.0	-530.0	-8.2

a. 1.0 inch = 25.4 mm
b. 1.0 ft = 0.3 m
c. 1.0 psi = 6.89 kPa

Table 5.6: Strains at the Bottom of the Base in the Vertical Direction from Finite Element Analysis on Asphalt Sections

Materials		Thickness (mm)[a]		Shoulder	Strains			
Surface	Base	Surface	Base	Width (m)[b]	Under the Load	Percent Change	Between Trvld Wy & Shldr	Percent Change
Asphalt	Untreated	76.2	152.4	0	-1.725 e-7	- - -	-5.397 e-8	- - -
Asphalt	Untreated	76.2	152.4	3.0	-1.69 e-8	-90.2	-4.04 e-8	-25.1
Asphalt	ATB	76.2	152.4	0	-8.386 e-8	- - -	-3.817 e-8	- - -
Asphalt	ATB	76.2	152.4	3.0	-8.232 e-8	-1.8	-3.26 e-8	-14.6
Asphalt	CTB	76.2	152.4	0	-5.137 e-8	- - -	-2.962 e-8	- - -
Asphalt	CTB	76.2	152.4	3.0	-5.025 e-8	-2.2	-2.645 e-8	-10.7
Asphalt	Untreated	304.8	152.4	0	-6.868 e-8	- - -	-5.316 e-8	- - -
Asphalt	Untreated	304.8	152.4	3.0	-6.53 e-8	-4.9	-4.69 e-8	-11.8
Asphalt	ATB	304.8	152.4	0	-4.27 e-8	- - -	-3.151 e-8	- - -
Asphalt	ATB	304.8	152.4	3.0	-4.151 e-8	-2.8	-2.90 e-8	-8.0
Asphalt	CTB	304.8	152.4	0	-2.811 e-8	- - -	-2.154 e-8	- - -
Asphalt	CTB	304.8	152.4	3.0	-2.766 e-8	-1.6	-2.045 e-8	-5.1

a. 1.0 inch = 25.4 mm
b. 1.0 ft = 0.3 m

44

Table 5.7: Strains at the Bottom of the Base in the Vertical Direction from Finite Element Analysis on Concrete Sections

Materials		Thickness (mm)[a]		Shoulder	Strains			
Surface	Base	Surface	Base	Width (m)[b]	Under the Load	Percent Change	Between Trvld Wy & Shldr	Percent Change
Concrete	Untreated	152.4	152.4	0	-6.311 e-8	- - -	-5.35 e-8	- - -
Concrete	Untreated	152.4	152.4	3.0	-5.85 e-8	-7.3	-4.34 e-8	-18.9
Concrete	CTB	152.4	152.4	0	-2.943 e-8	- - -	-2.34 e-8	- - -
Concrete	CTB	152.4	152.4	3.0	-2.89 e-8	-1.8	-2.15 e-8	-8.1
Concrete	Untreated	304.8	152.4	0	-3.253 e-8	- - -	-3.192 e-8	- - -
Concrete	Untreated	304.8	152.4	3.0	-3.037 e-8	-6.6	-2.696 e-8	-15.5
Concrete	CTB	304.8	152.4	0	-1.768 e-8	- - -	-1.593 e-8	- - -
Concrete	CTB	304.8	152.4	3.0	-1.741 e-8	-1.5	-1.503 e-8	-5.6

a. 1.0 inch = 25.4 mm
b. 1.0 ft = 0.3 m

Looking at Table 5.2 for stresses under the load on asphalt sections, it is observed that when shoulder width is increased from 0 m to 3.0 m (10 ft), the stresses decrease slightly. This is true for stresses at the interface between the traveled way and the shoulder on asphalt sections, as prsented in Table 5.3. Examining Table 5.4 for stresses under the load for concrete sections a similar trend can be observed. Table 5.5 indicates the same trend for stresses at the edge between the traveled way and shoulder for concrete sections. Tables 5.6 and 5.7 display the strains that occur at the bottom of the base in the vertical direction for asphalt and concrete sections respectively. These tables indicate that as the shoulder width increses the strains decrease slightly.

BISAR

Input files were created for various conditions, and stresses were calculated using BISAR. The BISAR output was printed and stresses were obtained from this printed output. The stresses from the BISAR analysis are summarized in Table 5.8. All of the printed output from BISAR is included in Appendix C.

Table 5.8: BISAR Stresses

Base	Thickness (mm)[a]		Stresses (kPa)[b]
Type	Surface	Base	Top of Subgrade
Untreated	76.2	152.4	-136.4
ATB	76.2	152.4	-81.4
CTB	76.2	152.4	-48.9
Untreated	304.8	152.4	-23.0
ATB	304.8	152.4	-19.7
CTB	304.8	152.4	-14.9

a. 1.0 inch = 25.4 mm
b. 1.0 psi = 6.89 kPa

Comparison of BISAR and Finite Element Analysis

To conduct a comparison of the two methods, the results had to be converted to the same units. Therefore, stresses from the finite element analysis were converted from pounds per square feet (psf) to pounds per square inch (psi). Also, since the load applied in the finite element method was a unit load and the load applied using BISAR was 9,000 pounds (40 kN), the stresses from the finite element analysis were then multiplied by 9,000. The results of the conversion and the comparison can be seen in Table 5.9. From Table 5.9, it is observed that the two methods yielded different results. However, both methods showed similar trends, such as when the base material becomes stiffer the stresses decreased.

Table 5.9: Comparison of Results

| Base Type | Thickness (mm)[a] | | Stresses (kPa)[b] | | Percent Difference |
| | Surface | Base | Top of Subgrade | | |
			BISAR	Finite Element	
Untreated	76.2	152.4	-136.4	-188.1	27.5
ATB	76.2	152.4	-81.4	-71.8	13.4
CTB	76.2	152.4	-48.9	-44.7	9.4
Untreated	304.8	152.4	-23.0	-80.3	71.4
ATB	304.8	152.4	-19.7	-39.0	49.5
CTB	304.8	152.4	-14.9	-26.4	43.6

a. 1.0 inch = 25.4 mm
b. 1.0 psi = 6.89 kPa

Chapter Summary

This chapter presented the methods of structural analysis used in this research study. Finite element analysis was performed and the BISAR program was run. The results of this analysis provided stresses and strains at the desired locations with variable shoulder widths.

The stresses and strains indicated that shoulder width had a minimal effect on stresses and strains at the top of the subgrade and the bottom of the base layer. The stresses and strains were only slightly

reduced when no shoulder is compared to a 3.0 m (10 ft) shoulder. The comparison between BISAR and

the finite element method showed that the results were different from each other.

CHAPTER 6

CONCLUSIONS AND RECOMMENDATIONS

The main objectives of this study were to examine the effect of pavement shoulders on the safety and structural strength of highways. This was performed by collecting data on representative highway sections from throughout Wyoming for a five-year period. A statistical and structural analysis were performed on the data. This chapter summarizes conclusions drawn from the analyses. Recommendations also are included in this chapter.

Safety Effectiveness of Shoulders

This study was performed to determine the effectiveness of pavement shoulders on the safety of highways in Wyoming. It was determined that significant reductions in accidents can be expected when shoulder widths were increased or if shoulders were added to a roadway. Adding 0.6 m (2 ft) of shoulder width to a section with no shoulders has the most effect in reducing accident numbers. For each increment of 0.6 m (2 ft) of increased width thereafter, accident numbers will decrease, but not as significantly. These findings are consistent with similar studies performed at the national level.

Structural Effectiveness of Shoulders

This study also was performed to determine the effect of pavement shoulder width on stresses in the base and subgrade layers. Stresses under the load were examined to determine if there is a reduction in stresses with the added width of shoulders. This analysis indicated that shoulder width would result in a slight reduction of vertical stresses.

Effectiveness of Shoulders

Effectiveness of adding pavement shoulders also was examined. Adding shoulders or increasing shoulder widths on roadways with relatively high traffic volumes reduced accident costs significantly. However, on roadways with very low traffic volumes it was determined that increasing the shoulder width would result in insignificant reduction in accident numbers.

Recommendations

The findings of this research have led to the following recommendations:

• Pavement shoulders should be implemented on roadways with high volumes. These shoulders will help in significantly reducing the number of accidents.

• Wide shoulders are not effective on low volume roadways. However, the first 0.6 m (2 ft) of shoulder widening should be considered since it is quite effective in reducing accident numbers.

REFERENCES

1. Zegeer, C.V., J. Hummer, D. Reinfurt, L. Herf and W. Hunter. Safety Effects of Cross-Section Design for Two-Lane Roads. Report FHWA-RD-87/088. FHWA, U.S. Department of Transportation, 1987.

2. Curren, J. E. Use of Shoulders and Narrow Lanes to Increase Freeway Capacity. National Cooperative Highway Research Program Report 369. National Academy Press, Washington, D. C., 1995.

3. Cleveland, Donald A. , Lidia P. Kostyniuk and Kuo-Liang Ting. Geometric Design Element Groups and High-Volume Two-Lane Rural Highway Safety. Transportation Research Record 960. Transportation Research Board, Washington, D. C., 1984.

4. Yoder, E. J. and M. W. Witczak. Principles of Pavement Design, 2nd ed. New York, NY: John Wiley & Sons, Inc., 1975.

5. Thickness Design: Asphalt Pavements for Highways and Streets. Manual Series No. 1(MS - 1). Asphalt Institute, 1991.

6. Thickness Design for Concrete Highway And Street Pavements. Report EB109.01P. Portland Cement Association, 1984.

7. Sawan, Jihad S., Michael I. Darter and Barry J. Dempsey. Structural Analysis and Design of PCC Shoulders. Report FHWA-RD-81/122. FHWA, U.S. Department of Transportation, 1982.

8. AASHTO Guide for Design of Pavement Structures. American Association of State Highway and Transportation Officials, 1986.

9. A Policy on Geometric Design of Highways and Streets. American Association of State Highway and Transportation Officials, 1994.

10. Neter, John, et al. Applied Linear Regression Models, 3rd ed. Chicago, IL: Irwin, 1996.

11. McCullagh, P. and J. A. Nelder. Generalized Linear Models. New York, NY: Chapman and Hall, Ltd., 1983.

12. Stokes, Maura E., et al. Categorical Data Analysis Using the SAS System. Cary, NC: SAS Institute Inc., 1995.

13. Call, Dalene A. and Thomas F. Fanter. Wyoming's Comprehensive Report on Traffic Crashes. Wyoming Department of Transportation, 1991.

14. Call, Dalene A. and Thomas F. Fanter. Wyoming's Comprehensive Report on Traffic Crashes. Wyoming Department of Transportation, 1992.

15. Call, Dalene A. and Thomas F. Fanter. <u>Wyoming's Comprehensive Report on Traffic Crashes</u>. Wyoming Department of Transportation, 1993.

16. Call, Dalene A. and Thomas F. Fanter. <u>Wyoming's Comprehensive Report on Traffic Crashes</u>. Wyoming Department of Transportation, 1994.

17. Call, Dalene A. and Thomas F. Fanter. <u>Wyoming's Comprehensive Report on Traffic Crashes</u>. Wyoming Department of Transportation, 1995.

18. Cook, Robert D. <u>Finite Element Modeling for Stress Analysis</u>. New York, NY: John Wiley & Sons, Inc., 1995.

19. Ksaibati, Khaled. "Pavement Design for Highways." University of Wyoming. Laramie, WY, 11 March 1996.

20. Beer, Ferdinand P. and E. Russell Johnston, Jr. <u>Mechanics of Materials</u>, 2nd ed. New York, NY: McGraw-Hill, Inc., 1992.

APPENDIX A

INFORMATION ON ACCIDENT DATA

List of Data Collected for each Accident for the Test Sections

Column 1 (A): Route Number

Column 2 (B): Year

Column 3 (C): Rural/Urban

    1 - Rural   2 - Urban

Column 4 (D): County

1 - Albany	13 - Natrona
2 - Big Horn	14 - Niobrara
3 - Campbell	15 - Park
4 - Carbon	16 - Platte
5 - Converse	17 - Sheridan
6 - Crook	18 - Sublette
7 - Fremont	19 - Sweetwater
8 - Goshen	20 - Teton
9 - Hot Springs	21 - Uinta
10 - Johnson	22 - Washakie
11 - Laramie	23 - Weston
12 - Lincoln	

Column 5 (E): Highway System

    1 - Interstate   2 - Primary   3 - Secondary

Column 6 (F): Highway Section

Column 7 (G): Milepost

Column 8 (H): Highway Element

1 - None	15 - Bikeway or Bikelane
2 - Parallel Parking	16 - Port of Entry/Rest Area
3 - Alley	17 - Diagonal Parking
4 - Driveway	18 - Median Crossover
5 - Business Entrance	19 - Bridge Involved
6 - 4-Way Intersection	20 - Detour/Construction
7 - 2-Way Intersection	21 - Left Turn Lane
8 - T Intersection	22 - Right Turn Lane
9 - One Way Street	23 - Continuous 2-Way Left Turn

```
10 - Interchange            24 - Tunnel
11 - Ramp                   25 - Rock Falling/Rock Slide
12 - Service/Frontage Road     26 - Cattleguard
13 - Access/Approach Road      27 - Train
14 - Emergency Park Lane
```

Column 9 (I): Highway District

Column 10 (J): Divided Highway

    1 - Yes   2 - No   X - Unknown

Column 11 (K): Side of Highway

    1 - Ascending   2 - Descending   - or X Unknown

Column 12 (L): Accident Date

Column 13 (M): Day of Week

```
1 - Sunday        5 - Thursday
2 - Monday        6 - Friday
3 - Tuesday       7 - Saturday
4 - Wednesday
```

Column 14 (N): Time of Accident

Column 15 (O): Accident Report Number

Column 16 (P): Number of Vehicles

Column 17 (Q):Number of Pedestrians

Column 18 (R): Number Injured

Column 19 (S): Number Killed

Column 20 (T): Road Surface

```
1 - Concrete      3 - Gravel/Rock    5 - Brick/Stone
2 - Asphalt       4 - Dirt           X- Unknown
```

Column 21 (U): Light Conditions

    1 - Daylight   3 - Dark, Lighted   X - Unknown
    2 - Dark, Unlighted 4 - Dawn or Dusk

Column 22 (V): Road Conditions

    1 - Dry   4 - Snowy 7 - Slippery (oil, fuel, etc.)
    2 - Wet   5 - Muddy   X - Unknown
    3 - Icy   6 - Slush

Column 23 (W): Weather Conditions

    1 - Clear or Cloudy 4 - Fog   7 - Ground Blizzard
    2 - Raining   5 - Dust 8 - Sleet/Hail/Freezing Rain
    3 - Snowing   6 - Strong Wind   X - Unknown

Column 24 (X): Road Alignment

    1 - Straight and Level   6 - Curved, Downgrade
    2 - Straight, Downgrade   7 - Curved, Upgrade
    3 - Straight, Upgrade   8 - Curved, Hillcrest
    4 - Straight, Hillcrest   9 - Other
    5 - Curved and Level   X - Unknown

Column 25 (Y): Junction Relationship

    1 - Non-junction   3 - Intersection Related
    2 - Intersection   4 - Driveway Access

Column 26 (Z): First Harmful Event

    Collision With:
    1 - Pedestrian   28 - Fence
    2 - Motor Vehicle in Transport 29 - Raised Median
                                    or Curb
    3 - Motor Vehicle on Other Road 30 - Delineator Post
    4 - Parked Motor Vehicle   31   -   Bridge
                                    Structure
    5 - Train   32   -   Utility
                                    Pole/Fixture
    6 - Pedacycle   33   - Barricade /
                                    Traffic Barrels

```
 9 - Other Object (Not Fi          34     -     E a r t h
                                   Embankment / Berm /
                                   Ditch
10 - Overturned                    35 - Snow Embankment
11 - Fire/Explosion                36 - Crash Cushion
12 - Carbon Monoxide Poisoning     37 - Mailboxes
13 - Falling / Jumping / Pushed
     from Vehicle                  38 - Bridge Railing
14 - Injuries by being thrown
     against vehicle          39 - Other Non-collision
15 - Immersion or Submersion       40 - Stop Sign
16 - Guardrail End                 41 - Yield Sign
17 - Guardrail Protecting Sign     42 - Other Sign
18 - Guardrail Protecting
     Highway Structure        43 - Other Fixed Object
19 - Guardrail in Median              44 - Horse
20 - Guardrail Along Fill             45 - Cow
21 - Other Guardrail                  46 - Pig
22 - Tree/Shrubbery                   47 - Sheep
23 - Cut Slope            48 - Other Domestic Animal
24 - Road Approach                    49 - Elk
25 - Rock/Boulder                     50 - Deer
26 - End of Drainage Pipe             51 - Moose
27 - Building or Other Structure      52 - Antelope
                             53 - Other Wild Animal
```

Column 27 (AA): Location of First Harmful Event

```
1 - On Roadway          5 - On Other Roadway
2 - Off Roadway         6 - Roadside
3 - Shoulder            7 - Outside of Right-of-Way
4 - Median              X - Unknown
```

Column 28 (AB): Number of Lanes

Column 29 (AC): Adverse Road Conditions

```
1 - Under Construction
     or Repair        6 - Obstructed by Previous Accident
2 - Reduced Road Width          7 - Worn or Polished
                                    Surface
3 - Debris              8 - No Unusual Road Condition
4 - Lane Markings Faded or Missing      9 - Other
5 - Traffic Control Device Missing or Disabled
```

Column 30 (AD): Collision Type

1 - Head On
2 - Rear End
3 - Angle Collision
4 - Sideswipe Meeting
5 - Sideswipe Passing
6 - not used

7 - Involves Left Turn
8 - Involves Right Turn
9 - Involves Right Turn on Red
10 - Other
X - Unknown

Column 31 (AE): Functional Classification

Rural: Urban:
1 - Principal Arterial-Interstate   11 - Principal Arterial-Interstate
2 - Principal Arterial-Other   12 - Principal Arterial-Other
3 - Minor Arterial   16 - Minor Arterial
4 - Major Collector   17 - Collector
5 - Minor Collector   19 - Local
6 - Local

Column 32 (AF): Drinking Involved

1 - Drinking Pedestrian   2 - Drinking Driver
3 - Both Drinking

Column 33 (AG): Traffic Control

1 - None
2 - Stop Sign
3 - Yield Sign
4 - Flashing Lights
5 - Railroad Crossing
6 - Do Not Enter Sign

7 - Traffic Signals
8 - Traffic Signals w/ Ped. Sign
9 - Flagman
10 - Pedestrian or School Crossing

11 - No Passing Zone
12 - Warning Sign
13 - Pavement Markings
14 - Other
15- Traffic Barrels/Cones
16 - School Bus Flashing Stop Lamps
17 - Temporary Jersey Barrier
X - Unknown

Column 34 (AH): Repair Cost

Column 35 (AI): Posted Speed

58

Column 36 (AJ): Estimated Speed

Column 37 (AK): Vehicle Type

1 - Passenger Car   10 - School Bus
2 - Pickup   11 - Construction/Road Maintenance
3 - Pickup w/ Camper   12 - Farm Equipment
4 - Truck (1 ton and above)   13 - Snowmobile
5 - Motorcycle   14 - Moped
6 - Bicycle   15 - Emergency Vehicle
7 - Motorhome   16 - Semi-Tractor and Trailer
8 - Bus   17 -Semi-Tractor Only
9 - Van   18 - Other
X - Unknown

Column 38 (AL): Visual Obstruction

1 - None   8 - Fog/Dust/Smoke/ or Blowing Snow
2 - Buildings   9 - Other Vehicle
3 - Vegetation   10 - Other
4 - Rain/Snow/ Windshield Ice 11 - Driver's Vehicle
5 - Embankment   12 - Pedestrian's Dark Clothing
6 - Hillcrest   13 - Tinted Vehicle Windows
7 - Sun or Headlight Glare   14 - Vehicle Cargo

Column 39 (AM): Damage Severity

1 - Disabling   4 - Other Property Damage
2 - Functional Damage   5 - No Damage
3 - Other Damage   X - Unknown

Column 40 (AN): Human Contributing Factor

1 - Alcohol   12 - Passenger Distraction
2 - Fell Asleep   13 - Improper or No Signal
3 - Following Too Close   14 - Drugs
4 - Illness   15 - Improper Passing
5 - Failure to Yield ROW   16 - Ped. Error or
                     Confusion
6 - Backing Unsafely   17 - Driver Inexperience
7 - Turning Improperly   18 - Driver Inattention
8 - Unsafe Speed   19 - No Violations
9 - Traffic Control Disregarded   20 - Driver Fatigue
10 - Medication   21 - Other
11 - Physical Disability   22 - No driver

Column 41 (AO): Activity Prior to Crash

1 - Going Straight Ahead   10 - Starting in Traffic
2 - Slowing   11 - Parked
3 - Stopped in Traffic   12 - Changing Lanes
4 - Making Right Turn   13 - Avoiding Object
5 - Making Left Turn   14 - Driving Stolen Vehicle
6 - Making U Turn   15 - Other
7 - Passing   16 - Evading Police
8 - Backing   17 - Roadway Maintenance
9 - Entering or Leaving Parked Position
X - Unknown

Column 42 (AP): Direction of Travel

1 - North   6 - Southwest
2 - Northeast   7 - West
3 - East   8 - Northwest
4 - Southeast   X - Unknown
5 - South

Column 43 (AQ): Driver's Age

Column 44 (AR): Driver's Sex

1 - Female   2 - Male

Column 45 (AS): Shoulder Width

Example of Collected Accident Data

YR	TYPE	COUNTY	HIGHWAY	ST	MP	HIGHWAY ELEMENT	DI	D	S
91	RURAL	LA	INTERSTATE	3	40	BRIDGE INVOLVED	1	Y	A
91	RURAL	LA	INTERSTATE	3	50	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	85	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	90	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	110	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	110	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	150	NONE	1	Y	D
91	RURAL	LA	INTERSTATE	3	200	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	257	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	257	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	325	BRIDGE INVOLVED	1	Y	A
91	RURAL	LA	INTERSTATE	3	329	BRIDGE INVOLVED	1	Y	A
91	RURAL	LA	INTERSTATE	3	329	BRIDGE INVOLVED	1	Y	A
91	RURAL	LA	INTERSTATE	3	329	BRIDGE INVOLVED	1	Y	A
91	RURAL	LA	INTERSTATE	3	330	BRIDGE INVOLVED	1	Y	A
91	RURAL	LA	INTERSTATE	3	330	BRIDGE INVOLVED	1	Y	A
91	RURAL	LA	INTERSTATE	3	350	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	358	NONE	1	Y	D
91	RURAL	LA	INTERSTATE	3	358	NONE	1	Y	D
91	RURAL	LA	INTERSTATE	3	395	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	396	NONE	1	Y	D
91	RURAL	LA	INTERSTATE	3	396	NONE	1	Y	D
91	RURAL	LA	INTERSTATE	3	400	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	415	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	440	NONE	1	Y	D
91	RURAL	LA	INTERSTATE	3	450	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	450	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	455	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	470	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	470	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	485	NONE	1	Y	D
91	RURAL	LA	INTERSTATE	3	500	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	500	NONE	1	Y	D
91	RURAL	LA	INTERSTATE	3	500	NONE	1	Y	D
91	RURAL	LA	INTERSTATE	3	570	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	665	NONE	1	Y	D
91	RURAL	LA	INTERSTATE	3	740	MEDIAN CROSSOVER	1	Y	D
91	RURAL	LA	INTERSTATE	3	740	MEDIAN CROSSOVER	1	Y	D
91	RURAL	LA	INTERSTATE	3	750	NONE	1	Y	A
91	RURAL	LA	INTERSTATE	3	750	NONE	1	Y	A

DATE	DAY	TIME	NUM	VEH	PED	INJ	KILD	SFC	LIGHT COND
32791	WE	700	2110	1	0	0	0	CONCRETE	DAYLIGHT
112291	FR	1515	10619	1	0	0	0	BLACKTOP	DAYLIGHT
92391	MO	530	8455	1	0	0	0	CONCRETE	DARK LIGHTED
22891	TH	935	1634	1	0	0	0	CONCRETE	DAYLIGHT
112291	FR	1730	10609	2	0	9	0	CONCRETE	DARK UNLIGHTED
112291	FR	1730	10609	2	0	9	0	CONCRETE	DARK UNLIGHTED
60691	TH	2205	4573	1	0	0	0	CONCRETE	DARK UNLIGHTED
51191	SA	1110	3896	1	0	0	0	CONCRETE	DAYLIGHT
112291	FR	1425	10617	2	0	0	0	CONCRETE	DAYLIGHT
112291	FR	1425	10617	2	0	0	0	CONCRETE	DAYLIGHT
123191	TU	1630	12449	1	0	0	0	CONCRETE	DAWN OR DUSK
31591	FR	840	2259	1	0	0	0	CONCRETE	DAYLIGHT
31591	FR	850	2263	1	0	0	0	CONCRETE	DAYLIGHT
31591	FR	855	2262	1	0	0	0	CONCRETE	DAYLIGHT
31591	FR	2155	1994	1	0	0	0	CONCRETE	DARK UNLIGHTED
41191	TH	800	2982	1	0	0	0	CONCRETE	DAYLIGHT
22391	SA	1845	1660	1	0	0	0	BLACKTOP	DARK UNLIGHTED
31591	FR	1800	2264	2	0	0	0	CONCRETE	DAWN OR DUSK
31591	FR	1800	2264	2	0	0	0	CONCRETE	DAWN OR DUSK
51691	TH	1600	3993	1	0	0	0	CONCRETE	DAYLIGHT
110691	WE	1702	9995	2	0	0	0	CONCRETE	DARK UNLIGHTED
110691	WE	1702	9995	2	0	0	0	CONCRETE	DARK UNLIGHTED
31591	FR	1845	2268	1	0	0	0	BLACKTOP	DARK UNLIGHTED
72991	MO	225	6062	1	0	1	1	CONCRETE	DARK UNLIGHTED
31591	FR	1755	1968	1	0	0	0	BLACKTOP	DAYLIGHT
112291	FR	X	10610	2	0	1	0	BLACKTOP	DAYLIGHT
112291	FR	X	10610	2	0	1	0	BLACKTOP	DAYLIGHT
101391	SU	200	8893	1	0	2	0	CONCRETE	DARK UNLIGHTED
123191	TU	1700	12451	2	0	2	0	BLACKTOP	DARK UNLIGHTED
123191	TU	1700	12451	2	0	2	0	BLACKTOP	DARK UNLIGHTED
112291	FR	1700	10621	1	0	0	0	CONCRETE	DARK UNLIGHTED
70591	FR	2345	5555	1	0	2	0	CONCRETE	DARK UNLIGHTED
60191	SA	1930	4681	2	0	0	0	BLACKTOP	DAWN OR DUSK
60191	SA	1930	4681	2	0	0	0	BLACKTOP	DAWN OR DUSK
70891	MO	1400	5676	1	0	2	0	CONCRETE	DAYLIGHT
111691	SA	650	10267	1	0	0	0	CONCRETE	DAYLIGHT
82691	MO	1400	7571	2	0	1	0	CONCRETE	DAYLIGHT
82691	MO	1400	7571	2	0	1	0	CONCRETE	DAYLIGHT
30891	FR	2350	2103	2	0	1	0	CONCRETE	DARK UNLIGHTED
30891	FR	2350	2103	2	0	1	0	CONCRETE	DARK UNLIGHTED

ROAD	WEATHER	ALIGN	
ICY	CLEAR	STRAIGHT UPGRADE	NON-JUNCTION
ICY	SNOWING	STRAIGHT UPGRADE	NON-JUNCTION
DRY	CLEAR	STRAIGHT UPGRADE	NON-JUNCTION
DRY	CLEAR	STRAIGHT LEVEL	NON-JUNCTION
ICY	SNOWING	STRAIGHT LEVEL	NON-JUNCTION
ICY	SNOWING	STRAIGHT LEVEL	NON-JUNCTION
SLIPPERY	CLEAR	STRAIGHT DOWNGRADE	NON-JUNCTION
DRY	CLEAR	STRAIGHT UPGRADE	NON-JUNCTION
ICY	SNOWING	STRAIGHT UPGRADE	NON-JUNCTION
ICY	SNOWING	STRAIGHT UPGRADE	NON-JUNCTION
ICY	SNOWING	STRAIGHT LEVEL	NON-JUNCTION
ICY	FOG	STRAIGHT UPGRADE	NON-JUNCTION
ICY	FOG	STRAIGHT UPGRADE	NON-JUNCTION
ICY	FOG	STRAIGHT LEVEL	NON-JUNCTION
ICY	FOG	STRAIGHT UPGRADE	NON-JUNCTION
ICY	SNOWING	STRAIGHT UPGRADE	NON-JUNCTION
DRY	CLEAR	STRAIGHT UPGRADE	NON-JUNCTION
ICY	CLEAR	STRAIGHT DOWNGRADE	NON-JUNCTION
ICY	CLEAR	STRAIGHT DOWNGRADE	NON-JUNCTION
DRY	CLEAR	STRAIGHT UPGRADE	NON-JUNCTION
ICY	CLEAR	STRAIGHT LEVEL	NON-JUNCTION
ICY	CLEAR	STRAIGHT LEVEL	NON-JUNCTION
ICY	SNOWING	CURVE AND LEVEL	NON-JUNCTION
DRY	CLEAR	CURVE AND LEVEL	NON-JUNCTION
ICY	CLEAR	CURVED UPGRADE	NON-JUNCTION
ICY	SNOWING	STRAIGHT LEVEL	NON-JUNCTION
ICY	SNOWING	STRAIGHT LEVEL	NON-JUNCTION
DRY	CLEAR	STRAIGHT UPGRADE	NON-JUNCTION
ICY	SNOWING	STRAIGHT LEVEL	NON-JUNCTION
ICY	SNOWING	STRAIGHT LEVEL	NON-JUNCTION
ICY	SNOWING	CURVED UPGRADE	NON-JUNCTION
DRY	CLEAR	CURVED DOWNGRADE	NON-JUNCTION
WET	SLEET/HAIL	STRAIGHT LEVEL	NON-JUNCTION
WET	SLEET/HAIL	STRAIGHT LEVEL	NON-JUNCTION
WET	CLEAR	STRAIGHT LEVEL	NON-JUNCTION
ICY	FOG	STRAIGHT LEVEL	NON-JUNCTION
DRY	CLEAR	STRAIGHT LEVEL	INTERSECTION
DRY	CLEAR	STRAIGHT LEVEL	INTERSECTION
DRY	CLEAR	STRAIGHT LEVEL	NON-JUNCTION
DRY	CLEAR	STRAIGHT LEVEL	NON-JUNCTION

FIRST EVENT	LOCATION	L		COLLISION TYPE	
BRIDGE RAIL	MEDIAN	2	NONE	-	1
FENCE	OFF ROADWAY	2	NONE	-	1
FENCE	OFF ROADWAY	2	NONE	-	1
DELINEATOR POST	SHOULDER	2	NONE	-	1
MV OTHER ROADWAY	OTHER RDWAY	2	NONE	HEAD ON	1
MV OTHER ROADWAY	OTHER RDWAY	2	NONE	HEAD ON	1
OTHER NON-COLLISION	MEDIAN	2	NONE	-	1
OVERTURN	OFF ROADWAY	2	NONE	-	1
PARKED MV	MEDIAN	2	NONE	OTHER	1
PARKED MV	MEDIAN	2	NONE	OTHER	1
BRIDGE RAIL	MEDIAN	2	NONE	-	1
GUARDRAIL IN MEDIAN	MEDIAN	2	NONE	-	1
GUARDRAIL IN MEDIAN	MEDIAN	2	NONE	-	1
GUARDRAIL BY STRUCTURE	OFF ROADWAY	2	NONE	-	1
BRIDGE RAIL	SHOULDER	2	NONE	-	1
BRIDGE RAIL	OFF ROADWAY	2	NONE	-	1
DEER	-	-	-	-	1
MV-MV	ON ROADWAY	2	NONE	SIDESWIPE PASSING	1
MV-MV	ON ROADWAY	2	NONE	SIDESWIPE PASSING	1
GUARDRAIL END	OFF ROADWAY	2	NONE	-	1
GUARDRAIL BY FILL	OFF ROADWAY	2	NONE	-	1
GUARDRAIL BY FILL	OFF ROADWAY	2	NONE	-	1
GUARDRAIL BY FILL	-	-	-	-	1
OVERTURN	OFF ROADWAY	2	NONE	-	1
OVERTURN	MEDIAN	2	NONE	-	1
MV-MV	-	-	-	REAR END	1
MV-MV	-	-	-	REAR END	1
OVERTURN	OFF ROADWAY	2	NONE	-	1
MV OTHER ROADWAY	OTHER RDWAY	2	NONE	HEAD ON	1
MV OTHER ROADWAY	OTHER RDWAY	2	NONE	HEAD ON	1
OVERTURN	OFF ROADWAY	2	NONE	-	1
ELK	ON ROADWAY	2	NONE	-	1
MV-MV	-	-	-	SIDESWIPE PASSING	1
MV-MV	-	-	-	SIDESWIPE PASSING	1
OVERTURN	MEDIAN	2	NONE	-	1
FENCE	MEDIAN	2	NONE	-	1
MV-MV	ON ROADWAY	2	NONE	REAR END	1
MV-MV	ON ROADWAY	2	NONE	REAR END	1
MV-MV	ON ROADWAY	2	NONE	REAR END	1
MV-MV	ON ROADWAY	2	NONE	REAR END	1

D	TRAFFIC CONTROL	COST	SPEED		VEHICLE TYPE
-	PAVEMENT MARKINGS	500	65	55	PASSENGER CAR
-	PAVEMENT MARKINGS	2631	65	60	PASSENGER CAR
-	PAVEMENT MARKINGS	582	65	65	PASSENGER CAR
-	PAVEMENT MARKINGS	2303	65	70	PASSENGER CAR
-	PAVEMENT MARKINGS	500	65	X	PASSENGER CAR
-	PAVEMENT MARKINGS	9300	65	45	VAN
-	PAVEMENT MARKINGS	1000	65	65	VAN
-	PAVEMENT MARKINGS	5025	65	65	PICKUP
2	PAVEMENT MARKINGS	500	65	65	PASSENGER CAR
2	PAVEMENT MARKINGS	7475	65	0	PASSENGER CAR
-	PAVEMENT MARKINGS	3711	65	50	PASSENGER CAR
-	PAVEMENT MARKINGS	2695	65	65	PICKUP
-	PAVEMENT MARKINGS	1749	65	65	PASSENGER CAR
-	PAVEMENT MARKINGS	1100	65	65	PASSENGER CAR
-	PAVEMENT MARKINGS	500	65	45	PASSENGER CAR
-	PAVEMENT MARKINGS	4100	65	55	PICKUP
-	NONE	1233	65	60	PICKUP
-	PAVEMENT MARKINGS	1200	65	45	PASSENGER CAR
-	PAVEMENT MARKINGS	500	65	50	PASSENGER CAR
-	PAVEMENT MARKINGS	500	65	55	PASSENGER CAR
-	PAVEMENT MARKINGS	3798	65	65	PASSENGER CAR
-	PAVEMENT MARKINGS	473	65	50	PASSENGER CAR
-	WARNING SIGN	2180	65	50	PICKUP
-	PAVEMENT MARKINGS	5225	65	70	PASSENGER CAR
-	PAVEMENT MARKINGS	4596	65	60	PICKUP
-	PAVEMENT MARKINGS	500	65	40	PASSENGER CAR
-	PAVEMENT MARKINGS	500	65	X	PASSENGER CAR
-	PAVEMENT MARKINGS	500	65	55	PASSENGER CAR
-	PAVEMENT MARKINGS	500	65	X	PICKUP
-	PAVEMENT MARKINGS	14591	65	50	PASSENGER CAR
-	PAVEMENT MARKINGS	500	65	60	PICKUP
-	PAVEMENT MARKINGS	500	65	60	PASSENGER CAR
-	NONE	4200	65	55	PASSENGER CAR
-	NONE	500	65	X	PICKUP
-	PAVEMENT MARKINGS	500	65	55	PASSENGER CAR
-	PAVEMENT MARKINGS	2288	65	65	PASSENGER CAR
-	PAVEMENT MARKINGS	957	65	35	PASSENGER CAR
-	PAVEMENT MARKINGS	500	65	X	MOTORCYCLE
2	PAVEMENT MARKINGS	5777	65	75	PASSENGER CAR
2	PAVEMENT MARKINGS	200	65	55	TRACTOR/TRAILER

OBSTRUCTION	DAMAGE SEVERITY	HUMAN FACTOR	ACTIVITY PRIOR
NONE	DISABLED	UNSAFE SPEED	STRAIGHT AHEAD
NONE	DISABLED	INATTENTIVE DRIVER	STRAIGHT AHEAD
NONE	DISABLED	FELL ASLEEP	STRAIGHT AHEAD
NONE	FUNCTIONAL DAMAGE	FELL ASLEEP	STRAIGHT AHEAD
NONE	DISABLED	UNSAFE SPEED	STRAIGHT AHEAD
NONE	DISABLED	NO VIOLATIONS	STRAIGHT AHEAD
NONE	DISABLED	NO VIOLATIONS	STRAIGHT AHEAD
NONE	DISABLED	FELL ASLEEP	STRAIGHT AHEAD
NONE	DISABLED	ALCOHOL RELATED	STRAIGHT AHEAD
NONE	DISABLED	NO DRIVER	PARKED
FOG/DUST/SMOKE	DISABLED	INEXPERIENCED DRIVER	STRAIGHT AHEAD
NONE	DISABLED	UNSAFE SPEED	STRAIGHT AHEAD
NONE	FUNCTIONAL DAMAGE	UNSAFE SPEED	STRAIGHT AHEAD
NONE	DISABLED	UNSAFE SPEED	STRAIGHT AHEAD
FOG/DUST/SMOKE	DISABLED	INATTENTIVE DRIVER	STRAIGHT AHEAD
NONE	DISABLED	UNSAFE SPEED	STRAIGHT AHEAD
-	-	-	STRAIGHT AHEAD
NONE	DISABLED	UNSAFE SPEED	STRAIGHT AHEAD
NONE	FUNCTIONAL DAMAGE	NO VIOLATIONS	STRAIGHT AHEAD
NONE	DISABLED	NO VIOLATIONS	PASSING
NONE	DISABLED	UNSAFE SPEED	PASSING
NONE	FUNCTIONAL DAMAGE	NO VIOLATIONS	STRAIGHT AHEAD
-	-	-	STRAIGHT AHEAD
NONE	DISABLED	FELL ASLEEP	STRAIGHT AHEAD
NONE	DISABLED	UNSAFE SPEED	STRAIGHT AHEAD
-	-	-	STRAIGHT AHEAD
-	-	-	STRAIGHT AHEAD
NONE	DISABLED	FELL ASLEEP	STRAIGHT AHEAD
NONE	DISABLED	UNSAFE SPEED	STRAIGHT AHEAD
NONE	DISABLED	NO VIOLATIONS	STRAIGHT AHEAD
NONE	DISABLED	UNSAFE SPEED	STRAIGHT AHEAD
NONE	FUNCTIONAL DAMAGE	NO VIOLATIONS	STRAIGHT AHEAD
-	-	-	STRAIGHT AHEAD
-	-	-	PASSING
NONE	DISABLED	NO VIOLATIONS	STRAIGHT AHEAD
NONE	FUNCTIONAL	UNSAFE SPEED	STRAIGHT AHEAD
NONE	OTHER MV DAMAGE	IMPROPER TURNING	LEFT TURN
NONE	DISABLED	NO VIOLATIONS	PASSING
NONE	DISABLED	ALCOHOL RELATED	STRAIGHT
NONE	OTHER MV DAMAGE	NO VIOLATIONS	STRAIGHT

DIR	AGE	SEX
NORTH	26	M
NORTH	55	M
NORTH	30	M
NORTH	22	M
NORTH	22	M
SOUTH	29	M
SOUTH	31	M
NORTH	24	M
NORTH	37	F
NORTH	-	-
NORTH	46	F
NORTH	47	F
NORTH	60	M
NORTH	18	M
NORTH	45	F
NORTH	38	M
NORTH	44	M
SOUTH	20	F
SOUTH	32	M
NORTH	31	M
SOUTH	23	M
SOUTH	39	M
NORTH	27	M
NORTH	17	F
SOUTH	20	M
NORTH	24	F
NORTH	18	M
NORTH	47	F
NORTH	24	M
SOUTH	26	M
SOUTH	27	M
N EAST	50	M
SOUTH	44	F
SOUTH	X	M
NORTH	54	F
SOUTH	29	M
SOUTH	17	F
SOUTH	44	F
NORTH	50	M
NORTH	57	M

APPENDIX B

STATISTICAL INFORMATION

An Example of SAS Input

```
OPTION LS=76;
DATA INT;
INPUT SECTION NUMBER LENGTH AADT VMT RATE LWIDTH RWIDTH FATAL
LIGHT
ROAD ALIGN LANES;
LVMT = LOG(VMT);
CARDS;
    1   42   8.4   5290    81095700     51.791   4  10   0 0 0 0 1
    1    8   8.4   5290    81095700      9.865   4  10   0 0 0 1 1
   82   32   4.8   4305    37711800     84.854   4  10   0 0 1 0 1
   82    1   4.8   4305    37711800      2.652   4  10   0 0 1 1 1
   85   16   9.5   7121   123460337.5   12.960   4  10   0 1 1 1 1
   85    5   9.5   7121   123460337.5    4.050   4  10   0 2 0 0 1
  111    0   7     2015    25741625      0.000   4  10   1 0 1 1 1
  112    0   5.2   1625    15421250      0.000   2   6   1 0 1 1 1
  112    0   5.2   1625    15421250      0.000   2   6   1 1 0 0 1
  112    0   5.2   1625    15421250      0.000   2   6   1 1 0 1 1
  112    0   5.2   1625    15421250      0.000   2   6   1 1 1 0 1
  112    0   5.2   1625    15421250      0.000   2   6   1 1 1 1 1
  112    0   5.2   1625    15421250      0.000   2   6   1 2 0 0 1
  113    0   9.3   1742    29566095      0.000   4  10   1 1 0 1 1
  113    0   9.3   1742    29566095      0.000   4  10   1 1 1 0 1
  113    0   9.3   1742    29566095      0.000   4  10   1 1 1 1 1
  113    0   9.3   1742    29566095      0.000   4  10   1 2 0 0 1
;;;;
PROC SORT;
BY SECTION ALIGN;
PROC MEANS SUM MEAN;
VAR NUMBER RATE VMT RWIDTH LVMT;
BY SECTION ALIGN;
OUTPUT OUT=ALIGN2 SUM=NUMA RATEA VX WX LVX
MEAN=NX RX VMTA RWIDA LVMTA;
PROC SORT REVERSE;
BY ALIGN;
PROC GENMOD;
CLASS ALIGN;
MODEL NUMA = RWIDA / DIST=POISSON LINK=LOG OFFSET=LVMTA;
BY ALIGN;
RUN;
```

SAS Output

Only Shoulder Width in Analysis

The GENMOD Procedure

Model Information

Description	Value
Data Set	WORK.SHLDR1
Distribution	POISSON
Link Function	LOG
Dependent Variable	NUMSH
Offset Variable	LVMTSH
Observations Used	153

Criteria For Assessing Goodness Of Fit

Criterion	DF	Value	Value/DF
Deviance	151	10668.4390	70.6519
Scaled Deviance	151	10668.4390	70.6519
Pearson Chi-Square	151	25346.6322	167.8585
Scaled Pearson X2	151	25346.6322	167.8585
Log Likelihood	.	29437.5818	.

Analysis Of Parameter Estimates

Parameter	DF	Estimate	Std Err	ChiSquare	Pr>Chi
INTERCEPT	1	-11.5702	0.0210	303062.466	0.0000
RWSH	1	-0.1073	0.0027	1530.9807	0.0000
SCALE	0	1.0000	0.0000	.	.

NOTE: The scale parameter was held fixed.

Light Conditions

> **0 - Daylight**
> **1 - Dark**
> **2 - Dawn or Dusk**

------------------------------- LIGHT=0 -------------------------------

The GENMOD Procedure

Model Information

Description	Value
Data Set	WORK.LIGHT1
Distribution	POISSON
Link Function	LOG
Dependent Variable	NUML
Offset Variable	LVMTL
Observations Used	153

Criteria For Assessing Goodness Of Fit

Criterion	DF	Value	Value/DF
Deviance	151	8723.4624	57.7713
Scaled Deviance	151	8723.4624	57.7713
Pearson Chi-Square	151	21670.3535	143.5123
Scaled Pearson X2	151	21670.3535	143.5123
Log Likelihood	.	16447.6395	.

Analysis Of Parameter Estimates

Parameter	DF	Estimate	Std Err	ChiSquare	Pr>Chi
INTERCEPT	1	-11.9151	0.0252	223942.609	0.0000
RWIDL	1	-0.1199	0.0033	1285.1239	0.0000
SCALE	0	1.0000	0.0000	.	.

NOTE: The scale parameter was held fixed.

71

------------------------------ LIGHT=1 ------------------------------

The GENMOD Procedure

Model Information

            Description   Value

            Data Set   WORK.LIGHT1
            Distribution   POISSON
            Link Function   LOG
            Dependent Variable   NUML
            Offset Variable   LVMTL
            Observations Used   153

Criteria For Assessing Goodness Of Fit

        Criterion   DF   Value   Value/DF

        Deviance   151   2397.4855   15.8774
        Scaled Deviance   151   2397.4855   15.8774
        Pearson Chi-Square   151   5081.8507   33.6546
        Scaled Pearson X2   151   5081.8507   33.6546
        Log Likelihood   .   5988.4185   .

Analysis Of Parameter Estimates

    Parameter   DF   Estimate   Std Err   ChiSquare   Pr>Chi

    INTERCEPT   1   -12.9518   0.0412   98958.0932   0.0000
    RWIDL   1   -0.0807   0.0052   241.4484   0.0000
    SCALE   0   1.0000   0.0000   .   .

NOTE: The scale parameter was held fixed.

Road Conditions

    0 - Dry
    1 - Poor

-------------------------------- ROAD=0 --------------------------------

The GENMOD Procedure

Model Information

Description	Value
Data Set	WORK.ROAD1
Distribution	POISSON
Link Function	LOG
Dependent Variable	NUMROAD
Offset Variable	LVMTROAD
Observations Used	153

Criteria For Assessing Goodness Of Fit

Criterion	DF	Value	Value/DF
Deviance	151	8222.2717	54.4521
Scaled Deviance	151	8222.2717	54.4521
Pearson Chi-Square	151	22735.3121	150.5650
Scaled Pearson X2	151	22735.3121	150.5650
Log Likelihood	.	13379.0312	.

Analysis Of Parameter Estimates

Parameter	DF	Estimate	Std Err	ChiSquare	Pr>Chi
INTERCEPT	1	-11.8810	0.0251	223339.878	0.0000
RWROAD	1	-0.1450	0.0035	1744.3295	0.0000
SCALE	0	1.0000	0.0000	.	.

NOTE: The scale parameter was held fixed.

------------------------------- LIGHT=2 -------------------------------

The GENMOD Procedure

Model Information

        Description   Value

        Data Set   WORK.LIGHT1
        Distribution   POISSON
        Link Function   LOG
        Dependent Variable   NUML
        Offset Variable   LVMTL
        Observations Used   153

Criteria For Assessing Goodness Of Fit

        Criterion   DF   Value   Value/DF

        Deviance   151   427.1937   2.8291
        Scaled Deviance   151   427.1937   2.8291
        Pearson Chi-Square   151   675.3602   4.4726
        Scaled Pearson X2   151   675.3602   4.4726
        Log Likelihood   .   150.4446   .

Analysis Of Parameter Estimates

    Parameter   DF   Estimate   Std Err   ChiSquare   Pr>Chi

    INTERCEPT   1   -14.7315   0.1012   21196.4316   0.0000
    RWIDL   1   -0.0940   0.0130   52.5124   0.0000
    SCALE   0   1.0000   0.0000   .   .

NOTE: The scale parameter was held fixed.

73

------------------------------ ROAD=1 ------------------------------

The GENMOD Procedure

Model Information

Description	Value
Data Set	WORK.ROAD1
Distribution	POISSON
Link Function	LOG
Dependent Variable	NUMROAD
Offset Variable	LVMTROAD
Observations Used	153

Criteria For Assessing Goodness Of Fit

Criterion	DF	Value	Value/DF
Deviance	151	3577.0324	23.6890
Scaled Deviance	151	3577.0324	23.6890
Pearson Chi-Square	151	6964.8788	46.1250
Scaled Pearson X2	151	6964.8788	46.1250
Log Likelihood	.	10219.3199	.

Analysis Of Parameter Estimates

Parameter	DF	Estimate	Std Err	ChiSquare	Pr>Chi
INTERCEPT	1	-12.8439	0.0381	113722.478	0.0000
RWROAD	1	-0.0487	0.0046	110.5734	0.0000
SCALE	0	1.0000	0.0000	.	.

NOTE: The scale parameter was held fixed.

Alignment

    0 - Straight
    1 - Curved

-------------------------------- ALIGN=0 --------------------------------

The GENMOD Procedure

Model Information

Description	Value
Data Set	WORK.ALIGN1
Distribution	POISSON
Link Function	LOG
Dependent Variable	NUMA
Offset Variable	LVMTA
Observations Used	153

Criteria For Assessing Goodness Of Fit

Criterion	DF	Value	Value/DF
Deviance	151	11047.7952	73.1642
Scaled Deviance	151	11047.7952	73.1642
Pearson Chi-Square	151	28570.7018	189.2099
Scaled Pearson X2	151	28570.7018	189.2099
Log Likelihood	.	23397.0183	.

Analysis Of Parameter Estimates

Parameter	DF	Estimate	Std Err	ChiSquare	Pr>Chi
INTERCEPT	1	-11.7281	0.0228	265373.919	0.0000
RWIDA	1	-0.1089	0.0030	1336.3857	0.0000
SCALE	0	1.0000	0.0000	.	.

NOTE: The scale parameter was held fixed.

------------------------------ ALIGN=1 ------------------------------

The GENMOD Procedure

Model Information

Description	Value
Data Set	WORK.ALIGN1
Distribution	POISSON
Link Function	LOG
Dependent Variable	NUMA
Offset Variable	LVMTA
Observations Used	153

Criteria For Assessing Goodness Of Fit

Criterion	DF	Value	Value/DF
Deviance	151	1768.6044	11.7126
Scaled Deviance	151	1768.6044	11.7126
Pearson Chi-Square	151	3420.4645	22.6521
Scaled Pearson X2	151	3420.4645	22.6521
Log Likelihood	.	2258.8146	.

Analysis Of Parameter Estimates

Parameter	DF	Estimate	Std Err	ChiSquare	Pr>Chi
INTERCEPT	1	-13.4935	0.0547	60919.9470	0.0000
RWIDA	1	-0.0989	0.0071	196.5261	0.0000
SCALE	0	1.0000	0.0000	.	.

NOTE: The scale parameter was held fixed.

APPENDIX C

Collected Data
from the
Structural Analysis

Pavement Stress Worksheet

Surface Thickness: ___3 in.___   Surface Material: ___Asphalt___

Base Thickness: ___6 in.___   Base Material: ___Untreated___

Shoulder Width: ___0___

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-5.365	-1.0426	0
Middle of Surface	-0.535	-0.894	-0.014
Bottom of Surface	1.75	-5.43	-0.216
Bottom of Base	0.15	-0.638	-0.026
Top of Subgrade	0.0275	-0.4364	-0.0153
Edge between Shoulder and Traveled Way			
Top of Surface	0.746	0.0167	-0.00484
Bottom of Surface	-1.177	-0.78	0.9052
Bottom of Base	-0.041	-0.26	0.145
Edge of Shoulder			
Top of Surface	- - -	- - -	- - -
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	7.11 e-8	-9.697 e-8	-1.0145 e-8
Bottom of Base	1.346 e-7	-1.725 e-7	-2.025 e-8
Edge between Shoulder and Traveled Way			
Bottom of Surface	-1.154 e-8	-2.22 e-9	4.243 e-8
Bottom of Base	3.061 e-8	-5.397 e-8	1.1263 e-7
Edge of Shoulder			
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

$E_{surface}$ = ___57,600,000 psf___ $\upsilon_{surface}$ = ___0.35___

E_{base} = ___3,600,000 psf___ υ_{base} = ___0.40___

$E_{subgrade}$ = ___2,160,000 psf___ $\upsilon_{subgrade}$ = ___0.43___

79

Pavement Stress Worksheet

Surface Thickness: _____3 in._____   Surface Material: _____Asphalt_____

Base Thickness: _____6 in._____   Base Material: _____Untreated_____

Shoulder Width: _____10 ft._____

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-5.1093	-1.0429	0
Middle of Surface	-0.294	-0.893	-0.004
Bottom of Surface	1.972	-5.4213	-0.031
Bottom of Base	0.929	-0.547	-0.008
Top of Subgrade	0.7314	-0.507	-0.00454
Edge between Shoulder and Traveled Way			
Top of Surface	1.432	-0.00146	-0.0012
Bottom of Surface	-1.016	-0.647	1.2651
Bottom of Base	-0.087	-0.231	0.184
Edge of Shoulder			
Top of Surface	-0.0116	0	0.0014
Bottom of Surface	-0.121	-0.31	-0.068
Bottom of Base	0.0025	0.0054	-0.0072

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	7.452 e-8	-9.877 e-8	1.435 e-9
Bottom of Base	1.3167 e-7	-1.69 e-8	6.01 e-9
Edge between Shoulder and Traveled Way			
Bottom of Surface	-1.0168 e-8	-1.524 e-9	5.93 e-8
Bottom of Base	1.5602 e-8	-4.04 e-8	1.43 e-7
Edge of Shoulder			
Bottom of Surface	6.99 e-10	-3.73 e-9	-3.203 e-9
Bottom of Base	-2.55 e-10	8.64 e-10	-5.59 e-9

$E_{surface} =$ _____57,600,000 psf_____ $\upsilon_{surface} =$ _____0.35_____

$E_{base} =$ _____3,600,000 psf_____ $\upsilon_{base} =$ _____0.40_____

$E_{subgrade} =$ _____2,160,000 psf_____ $\upsilon_{subgrade} =$ _____0.43_____

Pavement Stress Worksheet

Surface Thickness: _____ 3 in. _____   Surface Material: _____ Asphalt _____

Base Thickness: _____ 6 in. _____   Base Material: _____ ATB _____

Shoulder Width: _____ 0 _____

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-3.722	-1.0379	0
Middle of Surface	-1.8761	-0.9504	-0.0186
Bottom of Surface	-0.389	-1.21	-0.042
Bottom of Base	1.256	-2.06	-0.164
Top of Subgrade	0.0655	-0.173	-0.0118
Edge between Shoulder and Traveled Way			
Top of Surface	-0.7655	0.01796	-0.00739
Bottom of Surface	-0.315	-0.062	0.463
Bottom of Base	-0.141	-1.191	0.3
Edge of Shoulder			
Top of Surface	- - -	- - -	- - -
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	3.99 e-9	-1.52 e-8	-1.959 e-9
Bottom of Base	7.39 e-8	-8.386 e-8	-1.558 e-8
Edge between Shoulder and Traveled Way			
Bottom of Surface	-4.286 e-9	1.635 e-9	2.169 e-8
Bottom of Base	2.52 e-8	-3.817 e-8	2.83 e-8
Edge of Shoulder			
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

$E_{surface}$ = _____ 57,600,000 psf _____ $\upsilon_{surface}$ = _____ 0.35 _____

E_{base} = _____ 28,800,000 psf _____ υ_{base} = _____ 0.37 _____

$E_{subgrade}$ = _____ 2,160,000 psf _____ $\upsilon_{subgrade}$ = _____ 0.43 _____

Pavement Stress Worksheet

Surface Thickness: __3 in.__   Surface Material: __Asphalt__

Base Thickness: __6 in.__   Base Material: __ATB__

Shoulder Width: __10 ft.__

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-3.49	-1.038	0
Middle of Surface	-1.681	-0.95	0.00178
Bottom of Surface	-0.236	-1.21	0.00964
Bottom of Base	1.2665	-2.00	0.0255
Top of Subgrade	0.0683	-0.1666	0.00183
Edge between Shoulder and Traveled Way			
Top of Surface	-0.237	0.0144	-0.00359
Bottom of Surface	-0.052	-0.0745	0.532
Bottom of Base	0.0068	-1.084	0.557
Edge of Shoulder			
Top of Surface	-0.0144	0	0.00138
Bottom of Surface	0.014	0.0041	-0.0071
Bottom of Base	0.03	0.0182	-0.05

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	6.324 e-9	-1.648 e-8	4.517 e-10
Bottom of Base	7.321 e-8	-8.232 e-8	2.425 e-9
Edge between Shoulder and Traveled Way			
Bottom of Surface	-1.792 e-10	-7.089 e-10	2.496 e-8
Bottom of Base	1.928 e-8	-3.26 e-8	5.297 e-8
Edge of Shoulder			
Bottom of Surface	1.754 e-10	-5.0 e-11	-3.32 e-10
Bottom of Base	5.74 e-10	2.02 e-11	-4.78 e-9

$E_{surface}$ = __57,600,000 psf__ $\upsilon_{surface}$ = __0.35__

E_{base} = __28,800,000 psf__ υ_{base} = __0.37__

$E_{subgrade}$ = __2,160,000 psf__ $\upsilon_{subgrade}$ = __0.43__

Pavement Stress Worksheet

Surface Thickness: _____3 in._____ Surface Material: _____Asphalt_____

Base Thickness: _____6 in._____ Base Material: _____CTB_____

Shoulder Width: _____0_____

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-3.332	-1.036	0
Middle of Surface	-2.256	-0.9524	-0.015
Bottom of Surface	-1.3614	-0.952	-0.0187
Bottom of Base	2.85	-3.785	-0.537
Top of Subgrade	0.0358	-0.1091	-0.0117
Edge between Shoulder and Traveled Way			
Top of Surface	-1.182	0.0187	-0.007.03
Bottom of Surface	-0.486	-0.0896	0.28
Bottom of Base	0.882	-2.44	0.24
Edge of Shoulder			
Top of Surface	- - -	- - -	- - -
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	-1.293 e-8	-3.336 e-9	-8.746 e-10
Bottom of Base	4.458 e-8	-5.137 e-8	-1.555 e-8
Edge between Shoulder and Traveled Way			
Bottom of Surface	-6.674 e-9	2.624 e-9	1.297 e-8
Bottom of Base	1.838 e-8	-2.962 e-8	6.819 e-9
Edge of Shoulder			
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

$E_{surface}$ = __57,600,000 psf__ $\upsilon_{surface}$ = _____0.35_____

E_{base} = __86,400,000 psf__ υ_{base} = _____0.25_____

$E_{subgrade}$ = __2,160,000 psf__ $\upsilon_{subgrade}$ = _____0.43_____

83

Pavement Stress Worksheet

Surface Thickness: _____3 in._____   Surface Material: _____Asphalt_____

Base Thickness: _____6 in._____   Base Material: _____CTB_____

Shoulder Width: _____10 ft._____

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-3.159	-1.036	0
Middle of Surface	-2.1125	-0.952	0.0015
Bottom of Surface	-1.246	-0.937	0.00449
Bottom of Base	2.85	-3.68	0.0523
Top of Subgrade	0.0389	-0.1038	0.00114
Edge between Shoulder and Traveled Way			
Top of Surface	-0.779	0.0121	-0.0031
Bottom of Surface	-0.248	-0.0655	0.3051
Bottom of Base	0.65	-2.22	1.073
Edge of Shoulder			
Top of Surface	-0.018	0	0.0018
Bottom of Surface	-0.00217	0.004	-0.0018
Bottom of Base	0.0641	0.039	-0.185

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	-1.13 e-8	-4.046 e-9	2.106 e-10
Bottom of Base	4.423 e-8	-5.025 e-8	1.513 e-9
Edge between Shoulder and Traveled Way			
Bottom of Surface	-3.242 e-9	1.037 e-9	1.43 e-8
Bottom of Base	1.51 e-8	-2.645 e-8	3.104 e-8
Edge of Shoulder			
Bottom of Surface	-6.53 e-11	7.77 e-11	-8.42 e-11
Bottom of Base	5.55 e-10	1.91 e-10	-5.35 e-9

$E_{surface}$ = ___57,600,000 psf___ $\upsilon_{surface}$ = _____0.35_____

E_{base} = ___86,400,000 psf___ υ_{base} = _____0.25_____

$E_{subgrade}$ = ___2,160,000 psf___ $\upsilon_{subgrade}$ = _____0.43_____

Pavement Stress Worksheet

Surface Thickness: ___12 in.___ Surface Material: ___Asphalt___

Base Thickness: ___6 in.___ Base Material: ___Untreated___

Shoulder Width: ___0___

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-2.786	-1.0243	0
Middle of Surface	0.0414	-0.6682	-0.0128
Bottom of Surface	1.522	-1.966	-0.169
Bottom of Base	0.0295	-0.275	-0.024
Top of Subgrade	-0.014	-0.1922	-0.0141
Edge between Shoulder and Traveled Way			
Top of Surface	-1.041	0.0111	-0.007
Bottom of Surface	-0.113	-1.649	0.285
Bottom of Base	0.004	-0.225	0.018
Edge of Shoulder			
Top of Surface	- - -	- - -	- - -
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	3.931 e-8	-4.243 e-8	-7.926 e-9
Bottom of Base	4.961 e-8	-6.868 e-8	-1.863 e-8
Edge between Shoulder and Traveled Way			
Bottom of Surface	1.1813 e-8	-2.42 e-8	1.337 e-8
Bottom of Base	3.59 e-8	-5.316 e-8	1.364 e-8
Edge of Shoulder			
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

$E_{surface}$ = ___57,600,000 psf___ $\upsilon_{surface}$ = ___0.35___

E_{base} = ___3,600,000 psf___ υ_{base} = ___0.40___

$E_{subgrade}$ = ___2,160,000 psf___ $\upsilon_{subgrade}$ = ___0.43___

85

Pavement Stress Worksheet

Surface Thickness: ___12 in.___ Surface Material: ___Asphalt___
Base Thickness: ___6 in.___ Base Material: ___Untreated___
Shoulder Width: ___10 ft.___

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-2.6196	-1.0243	0
Middle of Surface	-0.11865	-0.6662	0.01234
Bottom of Surface	1.523	-1.93	0.027
Bottom of Base	0.022	-0.265	0.0031
Top of Subgrade	-0.018	-0.1864	0.0018
Edge between Shoulder and Traveled Way			
Top of Surface	-0.7701	0.0099	-0.00244
Bottom of Surface	0.411	-1.272	0.55
Bottom of Base	-0.0167	-0.212	0.0504
Edge of Shoulder			
Top of Surface	0	0	0
Bottom of Surface	0.05	0.05	-0.11
Bottom of Base	0.003	0.011	-0.013

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	3.904 e-8	-4.19 e-8	1.266 e-9
Bottom of Base	4.63 e-8	-6.53 e-8	2.38 e-9
Edge between Shoulder and Traveled Way			
Bottom of Surface	1.668 e-8	-2.275 e-8	2.565 e-8
Bottom of Base	2.91 e-8	-4.69 e-8	3.922 e-8
Edge of Shoulder			
Bottom of Surface	3.906 e-10	2.842 e-10	-5.116 e-9
Bottom of Base	-8.76 e-10	1.981 e-9	-1.00 e-8

$E_{surface}$ = ___57,600,000 psf___ $\upsilon_{surface}$ = ___0.35___

E_{base} = ___3,600,000 psf___ υ_{base} = ___0.40___

$E_{subgrade}$ = ___2,160,000 psf___ $\upsilon_{subgrade}$ = ___0.43___

Pavement Stress Worksheet

Surface Thickness: __12 in.__ Surface Material: __Asphalt__

Base Thickness: __6 in.__ Base Material: __ATB__

Shoulder Width: __0__

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-2.282	-1.0226	0
Middle of Surface	-0.2454	-0.7376	-0.0089
Bottom of Surface	1.038	-0.516	-0.022
Bottom of Base	0.5813	-1.083	-0.124
Top of Subgrade	0.0263	-0.0933	-0.0089
Edge between Shoulder and Traveled Way			
Top of Surface	-0.8432	0.0105	-0.001007
Bottom of Surface	0.5133	-0.219	0.289
Bottom of Base	0.2799	-0.89	0.02
Edge of Shoulder			
Top of Surface	- - -	- - -	- - -
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	2.004 e-8	-1.637 e-8	-1.0315 e-9
Bottom of Base	3.649 e-8	-4.27 e-8	-1.179 e-8
Edge between Shoulder and Traveled Way			
Bottom of Surface	9.613 e-9	-7.54 e-9	1.355 e-8
Bottom of Base	2.40 e-8	-3.151 e-8	1.856 e-9
Edge of Shoulder			
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

$E_{surface}$ = __57,600,000 psf__ $\upsilon_{surface}$ = __0.35__

E_{base} = __28,800,000 psf__ υ_{base} = __0.37__

$E_{subgrade}$ = __2,160,000 psf__ $\upsilon_{subgrade}$ = __0.43__

Pavement Stress Worksheet

Surface Thickness: _____12 in._____   Surface Material: _____Asphalt_____
Base Thickness: _____6 in._____   Base Material: _____ATB_____
Shoulder Width: _____10 ft._____

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-2.158	-1.0226	0
Middle of Surface	-0.1776	-0.7374	0.01082
Bottom of Surface	1.0474	-0.513	0.0172
Bottom of Base	0.568	-1.052	0.0175
Top of Subgrade	0.0259	-0.0905	0.0013
Edge between Shoulder and Traveled Way			
Top of Surface	-0.6803	0.00943	-0.00701
Bottom of Surface	0.516	-0.226	0.362
Bottom of Base	0.2184	-0.84	0.204
Edge of Shoulder			
Top of Surface	0.01232	0.00091	-0.00205
Bottom of Surface	0.0105	0.0146	-0.0213
Bottom of Base	0.0248	0.0641	-0.0685

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	2.016 e-8	-1.64 e-8	8.07 e-10
Bottom of Base	3.552 e-8	-4.151 e-8	1.668 e-9
Edge between Shoulder and Traveled Way			
Bottom of Surface	9.715 e-9	-7.678 e-9	1.696 e-8
Bottom of Base	2.312 e-8	-2.90 e-8	1.942 e-8
Edge of Shoulder			
Bottom of Surface	4.00 e-11	1.36 e-10	-9.98 e-10
Bottom of Base	-3.84 e-10	1.483 e-9	-6.513 e-9

$E_{surface}$ = _____57,600,000 psf_____ $\upsilon_{surface}$ = _____0.35_____

E_{base} = _____28,800,000 psf_____ υ_{base} = _____0.37_____

$E_{subgrade}$ = _____2,160,000 psf_____ $\upsilon_{subgrade}$ = _____0.43_____

Pavement Stress Worksheet

Surface Thickness: __12 in.__   Surface Material: __Asphalt__
Base Thickness: __6 in.__   Base Material: __CTB__
Shoulder Width: __0__

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-2.004	-1.0215	0
Middle of Surface	-0.4522	-0.7843	-0.00505
Bottom of Surface	0.354	-0.294	-0.0038
Bottom of Base	1.459	-2.104	-0.364
Top of Subgrade	0.0137	-0.0641	-0.008
Edge between Shoulder and Traveled Way			
Top of Surface	-0.763	0.00995	-0.01189
Bottom of Surface	0.25	-0.0513	0.234
Bottom of Base	0.801	-1.72	-0.16
Edge of Shoulder			
Top of Surface	- - -	- - -	- - -
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	7.809 e-9	-7.384 e-9	-1.778 e-10
Bottom of Base	2.344 e-8	-2.811 e-8	-1.053 e-8
Edge between Shoulder and Traveled Way			
Bottom of Surface	4.224 e-9	-2.829 e-9	1.098 e-8
Bottom of Base	1.491 e-8	-2.154 e-8	-4.60 e-9
Edge of Shoulder			
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

$E_{surface}$ = __57,600,000 psf__ $\upsilon_{surface}$ = __0.35__

E_{base} = __86,400,000 psf__ υ_{base} = __0.25__

$E_{subgrade}$ = __2,160,000 psf__ $\upsilon_{subgrade}$ = __0.43__

Pavement Stress Worksheet

Surface Thickness: <u>12 in.</u>   Surface Material: <u>Asphalt</u>

Base Thickness: <u>6 in.</u>   Base Material: <u>CTB</u>

Shoulder Width: <u>10 ft.</u>

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-1.9397	-1.022	0
Middle of Surface	-0.4062	-0.784	0.0096
Bottom of Surface	0.378	-0.289	0.013
Bottom of Base	1.479	-2.056	0.043
Top of Subgrade	0.0161	-0.0612	0.0009
Edge between Shoulder and Traveled Way			
Top of Surface	-0.6935	0.0093	-0.00969
Bottom of Surface	0.284	-0.0626	0.272
Bottom of Base	0.761	-1.631	0.393
Edge of Shoulder			
Top of Surface	0.0198	0.00116	-0.0029
Bottom of Surface	0.0083	0.01132	-0.0128
Bottom of Base	-0.049	-0.015	-0.202

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	8.1234 e-9	-7.498 e-9	6.0654 e-10
Bottom of Base	2.348 e-8	-2.766 e-8	1.23 e-9
Edge between Shoulder and Traveled Way			
Bottom of Surface	4.835 e-9	-3.28 e-9	1.276 e-8
Bottom of Base	1.415 e-8	-2.045 e-8	1.137 e-8
Edge of Shoulder			
Bottom of Surface	3.324 e-11	1.045 e-10	-6.003 e-10
Bottom of Base	-4.744 e-10	1.671 e-11	-5.844 e-9

$E_{surface}$ = <u>57,600,000 psf</u> $\upsilon_{surface}$ = <u>0.35</u>

E_{base} = <u>86,400,000 psf</u> υ_{base} = <u>0.25</u>

$E_{subgrade}$ = <u>2,160,000 psf</u> $\upsilon_{subgrade}$ = <u>0.43</u>

Pavement Stress Worksheet

Surface Thickness: _____ 6 in. _____   Surface Material: _____ Concrete _____

Base Thickness: _____ 6 in. _____   Base Material: _____ Untreated _____

Shoulder Width: _____ 0 _____

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-10.195	-1.0246	-0.0017
Middle of Surface	0.092	-0.649	-0.0263
Bottom of Surface	8.08	-13.3	-2.325
Bottom of Base	-0.0195	-0.284	-0.034
Top of Subgrade	-0.05	-0.205	-0.0197
Edge between Shoulder and Traveled Way			
Top of Surface	-4.233	0.0095	0.0164
Bottom of Surface	2.918	-8.096	-0.55
Bottom of Base	-0.023	-0.245	-0.0119
Edge of Shoulder			
Top of Surface	- - -	- - -	- - -
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	2.022 e-8	-2.854 e-8	-1.061 e-8
Bottom of Base	3.954 e-8	-6.311 e-8	-2.61 e-8
Edge between Shoulder and Traveled Way			
Bottom of Surface	8.43 e-9	-1.67 e-8	-2.511 e-9
Bottom of Base	3.27 e-8	-5.35 e-8	-9.23 e-9
Edge of Shoulder			
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

$E_{surface}$ = _ 504,000,000 psf _ $\upsilon_{surface}$ = _____ 0.15 _____

E_{base} = _ 3,600,000 psf _ υ_{base} = _____ 0.40 _____

$E_{subgrade}$ = _ 2,160,000 psf _ $\upsilon_{subgrade}$ = _____ 0.43 _____

Pavement Stress Worksheet

Surface Thickness: 6 in.   Surface Material: Concrete

Base Thickness: 6 in.   Base Material: Untreated

Shoulder Width: 10 ft.

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-10.15	-1.0248	0
Middle of Surface	0.223	-0.645	0.0124
Bottom of Surface	8.584	-11.602	0.087
Bottom of Base	-0.024	-0.267	0.0015
Top of Subgrade	-0.051	-0.193	0.0009
Edge between Shoulder and Traveled Way			
Top of Surface	-3.73	0.01564	0.04155
Bottom of Surface	2.94	-7.64	3.31
Bottom of Base	-0.0465	-0.217	0.04
Edge of Shoulder			
Top of Surface	-0.0492	-0.0049	0.00507
Bottom of Surface	0.18	0.311	-1.24
Bottom of Base	0.0042	0.0085	-0.0141

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	2.062 e-8	-2.544 e-8	3.97 e-10
Bottom of Base	3.59 e-8	-5.85 e-8	1.16 e-9
Edge between Shoulder and Traveled Way			
Bottom of Surface	8.313 e-9	-1.582 e-8	1.51 e-8
Bottom of Base	2.29 e-8	-4.34 e-8	3.08 e-8
Edge of Shoulder			
Bottom of Surface	2.43 e-10	5.412 e-10	-5.64 e-9
Bottom of Base	-3.30 e-10	1.32 e-9	-1.10 e-8

$E_{surface}$ = 504,000,000 psf $\upsilon_{surface}$ = 0.15

E_{base} = 3,600,000 psf υ_{base} = 0.40

$E_{subgrade}$ = 2,160,000 psf $\upsilon_{subgrade}$ = 0.43

Pavement Stress Worksheet

Surface Thickness: _____6 in._____   Surface Material: _____Concrete_____

Base Thickness: _____6 in._____   Base Material: _____CTB_____

Shoulder Width: _____0_____

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-6.633	-1.0181	0
Middle of Surface	-1.069	-0.787	-0.0136
Bottom of Surface	4.00	-1.683	-0.074
Bottom of Base	1.368	-2.256	-0.491
Top of Subgrade	0.005	-0.0743	-0.011
Edge between Shoulder and Traveled Way			
Top of Surface	-2.847	0.00596	-0.0011
Bottom of Surface	1.574	-0.471	1.166
Bottom of Base	0.679	-1.93	-0.436
Edge of Shoulder			
Top of Surface	- - -	- - -	- - -
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	8.32 e-9	-4.63 e-9	-3.37 e-10
Bottom of Base	2.30 e-8	-2.943 e-8	-1.42 e-8
Edge between Shoulder and Traveled Way			
Bottom of Surface	3.215 e-9	-1.453 e-9	5.32 e-9
Bottom of Base	1.435 e-8	-2.34 e-8	-1.262 e-8
Edge of Shoulder			
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

$E_{surface} =$ _____504,000,000 psf_____ $\upsilon_{surface} =$ _____0.15_____

$E_{base} =$ _____86,400,000 psf_____ $\upsilon_{base} =$ _____0.25_____

$E_{subgrade} =$ _____2,160,000 psf_____ $\upsilon_{subgrade} =$ _____0.43_____

93

Pavement Stress Worksheet

Surface Thickness: ___6 in.___ Surface Material: ___Concrete___
Base Thickness: ___6 in.___ Base Material: ___CTB___
Shoulder Width: ___10 ft.___

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-6.941	-1.0182	0
Middle of Surface	-1.09	-0.786	0.00907
Bottom of Surface	4.251	-1.684	0.0392
Bottom of Base	1.531	-2.153	0.0304
Top of Subgrade	0.016	-0.0645	0.0007
Edge between Shoulder and Traveled Way			
Top of Surface	-2.982	0.0108	0.01134
Bottom of Surface	1.86	-0.538	1.43
Bottom of Base	0.768	-1.73	0.411
Edge of Shoulder			
Top of Surface	0.014	0.0018	-0.00321
Bottom of Surface	0.015	0.0267	-0.0745
Bottom of Base	0.021	0.164	-0.21

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	8.82 e-9	-4.72 e-9	1.787 e-10
Bottom of Base	2.44 e-8	-2.89 e-8	8.80 e-10
Edge between Shoulder and Traveled Way			
Bottom of Surface	3.796 e-9	-1.68 e-9	6.52 e-9
Bottom of Base	1.457 e-8	-2.15 e-8	1.19 e-8
Edge of Shoulder			
Bottom of Surface	2.053 e-11	4.66 e-11	-3.40 e-10
Bottom of Base	-3.63 e-10	1.70 e-9	-6.09 e-9

$E_{surface}$ = ___504,000,000 psf___ $\upsilon_{surface}$ = ___0.15___

E_{base} = ___86,400,000 psf___ υ_{base} = ___0.25___

$E_{subgrade}$ = ___2,160,000 psf___ $\upsilon_{subgrade}$ = ___0.43___

Pavement Stress Worksheet

Surface Thickness: _____12 in._____   Surface Material: _____Concrete_____

Base Thickness: _____6 in._____   Base Material: _____Untreated_____

Shoulder Width: _____0_____

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-4.876	-1.047	0
Middle of Surface	0.1586	-0.598	0.0086
Bottom of Surface	3.733	-6.33	-1.69
Bottom of Base	-0.041	-0.166	-0.0274
Top of Subgrade	-0.05	-0.124	-0.0161
Edge between Shoulder and Traveled Way			
Top of Surface	-2.639	-0.00374	-0.00223
Bottom of Surface	1.924	-5.59	-1.687
Bottom of Base	-0.042	-0.165	-0.0312
Edge of Shoulder			
Top of Surface	- - -	- - -	- - -
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	9.405 e-9	-1.355 e-8	-7.704 e-9
Bottom of Base	1.643 e-8	-3.253 e-8	-2.13 e-8
Edge between Shoulder and Traveled Way			
Bottom of Surface	5.644 e-9	-1.15 e-8	-7.70 e-9
Bottom of Base	1.58 e-8	-3.192 e-8	-2.424 e-8
Edge of Shoulder			
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

$E_{surface}$ = _____504,000,000 psf_____ $\upsilon_{surface}$ = _____0.15_____

E_{base} = _____3,600,000 psf_____ υ_{base} = _____0.40_____

$E_{subgrade}$ = _____2,160,000 psf_____ $\upsilon_{subgrade}$ = _____0.43_____

Pavement Stress Worksheet

Surface Thickness: _____12 in._____ Surface Material: _____Concrete_____

Base Thickness: _____6 in._____ Base Material: _____Untreated_____

Shoulder Width: _____10 ft._____

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-5.305	-1.0048	0
Middle of Surface	0.207	-0.595	0.0135
Bottom of Surface	4.28	-6.21	0.013
Bottom of Base	-0.036	-0.154	0
Top of Subgrade	-0.045	-0.1144	0
Edge between Shoulder and Traveled Way			
Top of Surface	-3.058	0.00587	0.0067
Bottom of Surface	2.511	-5.203	0.866
Bottom of Base	-0.0415	-0.143	0.0079
Edge of Shoulder			
Top of Surface	0.0954	0.00645	-0.0147
Bottom of Surface	-0.118	0.491	-1.029
Bottom of Base	0	0.032	-0.014

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	1.042 e-8	-1.351 e-8	5.864 e-11
Bottom of Base	1.56 e-8	-3.037 e-8	-1.10 e-10
Edge between Shoulder and Traveled Way			
Bottom of Surface	6.65 e-9	-1.095 e-8	3.95 e-9
Bottom of Base	1.26 e-8	-2.696 e-8	6.135 e-9
Edge of Shoulder			
Bottom of Surface	-3.97 e-10	9.93 e-10	-4.695 e-9
Bottom of Base	-4.90 e-9	7.382 e-9	-1.084 e-8

$E_{surface}$ = _____504,000,000 psf_____ $\upsilon_{surface}$ = _____0.15_____

E_{base} = _____3,600,000 psf_____ υ_{base} = _____0.40_____

$E_{subgrade}$ = _____2,160,000 psf_____ $\upsilon_{subgrade}$ = _____0.43_____

Pavement Stress Worksheet

Surface Thickness: _____12 in._____ Surface Material: ____Concrete____

Base Thickness: _____6 in._____ Base Material: ____CTB____

Shoulder Width: _____0_____

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-4.136	-1.0032	0
Middle of Surface	-0.1802	-0.658	0.00148
Bottom of Surface	3.101	-0.898	-0.0524
Bottom of Base	0.604	-1.428	-0.368
Top of Subgrade	-0.01	-0.0544	-0.008
Edge between Shoulder and Traveled Way			
Top of Surface	-2.212	-0.00421	-0.00545
Bottom of Surface	1.912	-0.452	0.381
Bottom of Base	0.39	-1.34	-0.433
Edge of Shoulder			
Top of Surface	- - -	- - -	- - -
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	6.322 e-9	-2.803 e-9	-2.39 e-10
Bottom of Base	1.172 e-8	-1.768 e-8	-1.065 e-8
Edge between Shoulder and Traveled Way			
Bottom of Surface	3.864 e-9	-1.532 e-9	1.74 e-9
Bottom of Base	9.05 e-9	-1.593 e-8	-1.253 e-8
Edge of Shoulder			
Bottom of Surface	- - -	- - -	- - -
Bottom of Base	- - -	- - -	- - -

$E_{surface}$ = __504,000,000 psf__ $\upsilon_{surface}$ = _____0.15_____

E_{base} = __86,400,000 psf__ υ_{base} = _____0.25_____

$E_{subgrade}$ = __2,160,000 psf__ $\upsilon_{subgrade}$ = _____0.43_____

Pavement Stress Worksheet

Surface Thickness:	12 in.	Surface Material:	Concrete
Base Thickness:	6 in.	Base Material:	CTB
Shoulder Width:	10 ft.		

Location	σ_x	σ_y	τ_{xy}
Under the Load			
Top of Surface	-4.453	-1.0032	0
Middle of Surface	-0.187	-0.658	0.00903
Bottom of Surface	3.397	-0.912	0.0196
Bottom of Base	0.72	-1.364	0.0039
Top of Subgrade	-0.0024	-0.048	0
Edge between Shoulder and Traveled Way			
Top of Surface	-2.5661	0.0045	0
Bottom of Surface	2.231	-0.534	0.628
Bottom of Base	0.466	-1.23	0.112
Edge of Shoulder			
Top of Surface	0.094	0.00572	-0.014
Bottom of Surface	-0.125	0.04	-0.0052
Bottom of Base	-0.052	0.267	-0.183

Location	ε_x	ε_y	γ_{xy}
Under the Load			
Bottom of Surface	6.90 e-9	-2.932 e-9	8.93 e-11
Bottom of Base	1.275 e-8	-1.741 e-8	1.14 e-10
Edge between Shoulder and Traveled Way			
Bottom of Surface	4.51 e-9	-1.80 e-9	2.864 e-9
Bottom of Base	9.50 e-9	-1.503 e-8	3.25 e-9
Edge of Shoulder			
Bottom of Surface	-2.56 e-10	1.20 e-10	-2.35 e-11
Bottom of Base	-1.53 e-9	3.082 e-9	-5.30 e-9

$E_{surface}$ = 504,000,000 psf $\upsilon_{surface}$ = 0.15

E_{base} = 86,400,000 psf υ_{base} = 0.25

$E_{subgrade}$ = 2,160,000 psf $\upsilon_{subgrade}$ = 0.43

Example of BISAR Input

12untreated
1
3 0 0
400000 .35 12 0
25000 .4 6 0
15000 .43
1
9000 5.35 0 0 0 0
2
1 0 0 12 0
3 0 0 18 0

BISAR Output

3untreated

                        SYSTEM NUMBER   1

LAYER NUMBER	CALCULATION METHOD	YOUNG'S MODULUS	POISSON'S RATIO	THICKNESS	INTERFACE SPRINGCOMPL
1	ROUGH	400000.	0.35	3.00	0.00
2	ROUGH	25000.	0.40	6.00	0.00
3		15000.	0.43		

LOAD NUMBER	NORMAL LOAD	SHEAR STRESS	RADIUS OF LOADED AREA	LOAD - POSITION X	Y	SHEAR DIRECTION
1	9000.	0.00	5.35	0.00	0.00	0.00

＊＊
　　　　 POSTION NO.　 1　　　 LAYER NO.　 1
　　　　　　 X-COORDINATE==>　　　　 0.00
　　　　　　 Y-COORDINATE==>　　　　 0.00
　　　　　　 Z-DEPTH======>　　　　 3.00

        TOTAL　 STRESSES , STRAINS AND DISPLAEMENTS
        HORIZ IN X　　 HORIZ IN Y　 VERITCAL　　 SHEAR　 YZ　 SHEAR　 XZ　 SHEAR　 XY

	HORIZ IN X	HORIZ IN Y	VERITCAL	SHEAR YZ	SHEAR XZ	SHEAR XY
STRESS	0.275E+03	0.275E+03	-0.476E+02	0.000E+00	0.000E+00	0.000E+00
STRAIN	0.489E-03	0.489E-03	-0.601E-03	0.000E+00	0.000E+00	0.000E+00
DISPLT	0.000E+00	0.000E+00	0.280E-01			

＊＊
　　　　 POSTION NO.　 2　　　 LAYER NO.　 3
　　　　　　 X-COORDINATE==>　　　　 0.00
　　　　　　 Y-COORDINATE==>　　　　 0.00
　　　　　　 Z-DEPTH======>　　　　 9.00

        TOTAL　 STRESSES , STRAINS AND DISPLAEMENTS
        HORIZ IN X　　 HORIZ IN Y　 VERITCAL　　 SHEAR　 YZ　 SHEAR　 XZ　 SHEAR　 XY

	HORIZ IN X	HORIZ IN Y	VERITCAL	SHEAR YZ	SHEAR XZ	SHEAR XY
STRESS	-0.158E+01	-0.158E+01	-0.198E+02	0.000E+00	0.000E+00	0.000E+00
STRAIN	0.508E-03	0.508E-03	-0.123E-02	0.000E+00	0.000E+00	0.000E+00
DISPLT	0.000E+00	0.000E+00	0.205E-01			

　　　　 ＊＊＊＊＊ T H E　　 E N D ＊＊＊＊＊

3atb

```
                    SYSTEM NUMBER     1

    LAYER    CALCULATION  YOUNG'S   POISSON'S  THICKNESS   INTERFACE
    NUMBER   METHOD       MODULUS   RATIO                  SPRINGCOMPL

         1    ROUGH        400000.    0.35       3.00        0.00
         2    ROUGH        150000.    0.37       6.00        0.00
         3                  15000.    0.43


    LOAD     NORMAL       SHEAR     RADIUS OF     LOAD - POSITION     SHEAR
    NUMBER   LOAD         STRESS    LOADED AREA   X           Y      DIRECTION

      1      9000.        0.00        5.35        0.00        0.00        0.00

***************************************************
     POSTION NO.  1     LAYER NO.  1
          X-COORDINATE==>        0.00
          Y-COORDINATE==>        0.00
          Z-DEPTH=======>        3.00


          TOTAL   STRESSES , STRAINS AND DISPLAEMENTS
          HORIZ IN X   HORIZ IN Y  VERITCAL    SHEAR  YZ   SHEAR  XZ   SHEAR  XY

STRESS  0.300E+02    0.300E+02   -0.709E+02   0.000E+00   0.000E+00   0.000E+00
STRAIN  0.111E-03    0.111E-03   -0.230E-03   0.000E+00   0.000E+00   0.000E+00
DISPLT  0.000E+00    0.000E+00    0.172E-01

***************************************************
     POSTION NO.  2     LAYER NO.  3
          X-COORDINATE==>        0.00
          Y-COORDINATE==>        0.00
          Z-DEPTH=======>        9.00


          TOTAL   STRESSES , STRAINS AND DISPLAEMENTS
          HORIZ IN X   HORIZ IN Y  VERITCAL    SHEAR  YZ   SHEAR  XZ   SHEAR  XY

STRESS -0.111E+01   -0.111E+01   -0.118E+02   0.000E+00   0.000E+00   0.000E+00
STRAIN  0.298E-03    0.298E-03   -0.726E-03   0.000E+00   0.000E+00   0.000E+00
DISPLT  0.000E+00    0.000E+00    0.152E-01
```

```
               **************
     DATE====>  9/ 2/1997

     TIME====> 23:11:32.18
               ************


     ***** T H E    E N D *****
```

101

3ctb

SYSTEM NUMBER   1

LAYER NUMBER	CALCULATION METHOD	YOUNG'S MODULUS	POISSON'S RATIO	THICKNESS	INTERFACE SPRINGCOMPL
1	ROUGH	400000.	0.35	3.00	0.00
2	ROUGH	600000.	0.25	6.00	0.00
3		15000.	0.43		

LOAD NUMBER	NORMAL LOAD	SHEAR STRESS	RADIUS OF LOADED AREA	LOAD - POSITION X	Y	SHEAR DIRECTION
1	9000.	0.00	5.35	0.00	0.00	0.00

```
***************************************************
     POSTION NO.  1    LAYER NO.  1
          X-COORDINATE==>      0.00
          Y-COORDINATE==>      0.00
          Z-DEPTH=======>      3.00
```

TOTAL   STRESSES , STRAINS AND DISPLAEMENTS

	HORIZ IN X	HORIZ IN Y	VERITCAL	SHEAR YZ	SHEAR XZ	SHEAR XY
STRESS	-0.602E+02	-0.602E+02	-0.816E+02	0.000E+00	0.000E+00	0.000E+00
STRAIN	-0.264E-04	-0.264E-04	-0.987E-04	0.000E+00	0.000E+00	0.000E+00
DISPLT	0.000E+00	0.000E+00	0.124E-01			

```
***************************************************
     POSTION NO.  2    LAYER NO.  3
          X-COORDINATE==>      0.00
          Y-COORDINATE==>      0.00
          Z-DEPTH=======>      9.00
```

TOTAL   STRESSES , STRAINS AND DISPLAEMENTS

	HORIZ IN X	HORIZ IN Y	VERITCAL	SHEAR YZ	SHEAR XZ	SHEAR XY
STRESS	-0.166E+01	-0.166E+01	-0.709E+01	0.000E+00	0.000E+00	0.000E+00
STRAIN	0.140E-03	0.140E-03	-0.378E-03	0.000E+00	0.000E+00	0.000E+00
DISPLT	0.000E+00	0.000E+00	0.119E-01			

```
          **************
DATE====>  9/ 2/1997

TIME====> 23:12: 3.87
          *************
```

***** T H E   E N D *****

12untreated

```
                    **************
          DATE====>  9/ 2/1997

          TIME====> 23:15: 2. 0
                    *************
```

```
                    SYSTEM NUMBER     1

     LAYER     CALCULATION  YOUNG'S    POISSON'S   THICKNESS   INTERFACE
     NUMBER    METHOD       MODULUS    RATIO                   SPRINGCOMPL

          1    ROUGH         400000.    0.35        12.00       0.00
          2    ROUGH          25000.    0.40         6.00       0.00
          3                   15000.    0.43
```

```
     LOAD     NORMAL      SHEAR      RADIUS OF      LOAD - POSITION      SHEAR
     NUMBER   LOAD        STRESS     LOADED AREA    X          Y        DIRECTION

       1      9000.       0.00        5.35          0.00       0.00         0.00
```

```
**************************************************
     POSTION NO.  1     LAYER NO.  1
          X-COORDINATE==>        0.00
          Y-COORDINATE==>        0.00
          Z-DEPTH=======>       12.00


          TOTAL   STRESSES , STRAINS AND DISPLAEMENTS
          HORIZ IN X   HORIZ IN Y  VERITCAL    SHEAR  YZ   SHEAR  XZ   SHEAR  XY

STRESS  0.602E+02    0.602E+02   -0.575E+01   0.000E+00    0.000E+00    0.000E+00
STRAIN  0.103E-03    0.103E-03   -0.120E-03   0.000E+00    0.000E+00    0.000E+00
DISPLT  0.000E+00    0.000E+00    0.935E-02
```

```
**************************************************
     POSTION NO.  2     LAYER NO.  3
          X-COORDINATE==>        0.00
          Y-COORDINATE==>        0.00
          Z-DEPTH=======>       18.00


          TOTAL   STRESSES , STRAINS AND DISPLAEMENTS
          HORIZ IN X   HORIZ IN Y  VERITCAL    SHEAR  YZ   SHEAR  XZ   SHEAR  XY

STRESS -0.274E+00   -0.274E+00   -0.333E+01   0.000E+00    0.000E+00    0.000E+00
STRAIN  0.850E-04    0.850E-04   -0.206E-03   0.000E+00    0.000E+00    0.000E+00
DISPLT  0.000E+00    0.000E+00    0.816E-02
```

```
                    **************
          DATE====>  9/ 2/1997

          TIME====> 23:15: 2. 5
                    *************

          ***** T H E    E N D *****
```

12atb

SYSTEM NUMBER   1

LAYER NUMBER	CALCULATION METHOD	YOUNG'S MODULUS	POISSON'S RATIO	THICKNESS	INTERFACE SPRINGCOMPL
1	ROUGH	400000.	0.35	12.00	0.00
2	ROUGH	150000.	0.37	6.00	0.00
3		15000.	0.43		

LOAD NUMBER	NORMAL LOAD	SHEAR STRESS	RADIUS OF LOADED AREA	LOAD - POSITION X	Y	SHEAR DIRECTION
1	9000.	0.00	5.35	0.00	0.00	0.00

****
POSTION NO. 1   LAYER NO. 1
  X-COORDINATE==>   0.00
  Y-COORDINATE==>   0.00
  Z-DEPTH=======>   12.00

TOTAL   STRESSES , STRAINS AND DISPLAEMENTS
HORIZ IN X   HORIZ IN Y VERITCAL   SHEAR YZ   SHEAR XZ   SHEAR XY

	HORIZ IN X	HORIZ IN Y	VERITCAL	SHEAR YZ	SHEAR XZ	SHEAR XY
STRESS	0.304E+02	0.304E+02	-0.112E+02	0.000E+00	0.000E+00	0.000E+00
STRAIN	0.591E-04	0.591E-04	-0.810E-04	0.000E+00	0.000E+00	0.000E+00
DISPLT	0.000E+00	0.000E+00	0.786E-02			

****
POSTION NO. 2   LAYER NO. 3
  X-COORDINATE==>   0.00
  Y-COORDINATE==>   0.00
  Z-DEPTH=======>   18.00

TOTAL   STRESSES , STRAINS AND DISPLAEMENTS
HORIZ IN X   HORIZ IN Y VERITCAL   SHEAR YZ   SHEAR XZ   SHEAR XY

	HORIZ IN X	HORIZ IN Y	VERITCAL	SHEAR YZ	SHEAR XZ	SHEAR XY
STRESS	-0.132E+00	-0.132E+00	-0.285E+01	0.000E+00	0.000E+00	0.000E+00
STRAIN	0.767E-04	0.767E-04	-0.182E-03	0.000E+00	0.000E+00	0.000E+00
DISPLT	0.000E+00	0.000E+00	0.730E-02			

***** T H E   E N D *****

12ctb

SYSTEM NUMBER   1

LAYER NUMBER	CALCULATION METHOD	YOUNG'S MODULUS	POISSON'S RATIO	THICKNESS	INTERFACE SPRINGCOMPL
1	ROUGH	400000.	0.35	12.00	0.00
2	ROUGH	600000.	0.25	6.00	0.00
3		15000.	0.43		

LOAD NUMBER	NORMAL LOAD	SHEAR STRESS	RADIUS OF LOADED AREA	LOAD - POSITION X	Y	SHEAR DIRECTION
1	9000.	0.00	5.35	0.00	0.00	0.00

```
* * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * *
      POSTION NO.   1     LAYER NO.   1
          X-COORDINATE==>       0.00
          Y-COORDINATE==>       0.00
          Z-DEPTH=======>      12.00
```

      TOTAL   STRESSES , STRAINS AND DISPLAEMENTS
          HORIZ IN X   HORIZ IN Y VERITCAL   SHEAR YZ   SHEAR XZ   SHEAR XY

	HORIZ IN X	HORIZ IN Y	VERITCAL	SHEAR YZ	SHEAR XZ	SHEAR XY
STRESS	0.748E+00	0.749E+00	-0.177E+02	0.000E+00	0.000E+00	0.000E+00
STRAIN	0.167E-04	0.167E-04	-0.456E-04	0.000E+00	0.000E+00	0.000E+00
DISPLT	0.000E+00	0.000E+00	0.644E-02			

```
* * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * *
      POSTION NO.   2     LAYER NO.   3
          X-COORDINATE==>       0.00
          Y-COORDINATE==>       0.00
          Z-DEPTH=======>      18.00
```

      TOTAL   STRESSES , STRAINS AND DISPLAEMENTS
          HORIZ IN X   HORIZ IN Y VERITCAL   SHEAR YZ   SHEAR XZ   SHEAR XY

	HORIZ IN X	HORIZ IN Y	VERITCAL	SHEAR YZ	SHEAR XZ	SHEAR XY
STRESS	-0.415E+00	-0.415E+00	-0.216E+01	0.000E+00	0.000E+00	0.000E+00
STRAIN	0.461E-04	0.461E-04	-0.120E-03	0.000E+00	0.000E+00	0.000E+00
DISPLT	0.000E+00	0.000E+00	0.627E-02			

          ***** T H E   E N D *****