TREASURY DEPARTMENT UNITE STATES COAST GUARD

COMMANDANT (MMT-3) U.S. COAST GUARD WASHINGTON, DC 20226

3 March 1965

NAVIGATION AND VESSEL INSPECTION CIRCULAR NO. 1-65

- Subj: 24.0' x 8.0' x 3.58' steel lifeboats with removable interiors, oar-propelled (App. No. 160.035/398/0), hand-propelled (App. No. 160.035/411/0), and motor-propelled (App. No. 160.035/412/0), manufactured by Welin Davit & Boat, Perth Amboy, New Jersey, replacement of short breast plates.
- 1. <u>Purpose</u>. This circular is to advise all Officers in Charge, Marine Inspection, shipowners and operators of the possibility of a lateral misalignment of the release gear hooks and hoist plates, causing distortion of the stem and stern post sections of the keel under unsymmetrical loading conditions, and to describe proper means to prevent possible injury and Loss of life.
- 2. Background. Since 1958 there have been manufactured 105 of these 241 steel lifeboats, having short breast plates and removable interiors (74 oar-propelled, 27 hand-propelled and 4 motor-propelled, with a total rated capacity of 4188-perspns).
- 3. <u>Discussion</u>. These lifeboat with the short breast plate installed have been successfully subjected to the 110% overload installation tests since 1958. However, a recent installation test was conducted where uneven loading occurred which caused the lateral misalignment of the release hooks and hoist plates and bending at the stem and stem post sections f the keel, since there was not any lateral support in this area. This movement off the centerline of the boast caused the load to shift, moving the weights to one side, causing parts of the weights to fall overboard from the lifeboat. The shifting of the weights also caused the stem to bend further out of line and the rivets to be pulled out of half the length of the boat. Fortunately, the above incident occurred during a test using weights and not under abandon-ship conditions where persons might have been involved.
- 4. <u>Action Required</u>. All vessels known to be outfitted with any of the subject 24' steel Welin lifeboats with the removable interior, shall have the lifeboats carefully inspected at the next inspection for certification, or the next mid-period examination, whichever occurs first.
 - a. These lifeboats that have the short breast plates, i.e., those that do not extend from the gunwales to the hoist plate and are fastened to each, shall have the short plate removed and a new extended breast plate conforming to the attached plan installed. This new extended breast plate will give the hoist plate and hook assembly the necessary lateral support that is needed.
 - b. The present short breast plate may be attached to the gunwale by rivets, bolts or possibly by welding. In order to expedite this repair project, the new plate should be welded in place, since trying to line up the new plate with the old existing holes in the gunwale flange would be difficult and time consuming. If possible, the repair work should be done by Welin or one of their representatives since this is an approved item manufactured by them.

- c. Attached are lists of the subject lifeboats by serial number, date, inspector's initial, approval numbers, and customer to whom sold and a sketch of the new plate to be installed. Also enclosed is a list of Welin's representatives.
- d. After the work has been completed to the satisfaction of the Officer in Charge, Marine Inspection, the boat shall be subjected to the 110% overload tests, lowered and disengaged from the falls as required by the installation tests.
- e. The cognizant Officer in Charge, Marine Inspection, shall advise the Commandant (MMT-3) when this work has been completed, including in the report the serial number, approval number of the lifeboat, the name and official number of the vessel, and who performed the repairs.


Rear Admiral, U.S. Coast Guard

Chief, Office of Merchant Marine Safety

Attachments:

- 1. Dwg. SK-640908 Breast Plate for 24' Steel Lifeboats
- 2. List of Lifeboats
- 3. List of Welin Representatives

DIST (SDL NO. 80)



24' STEEL LIFEBOAT (CAR) (DWG. 80226)

SERIAL NO.	DATE	INSP.	APP. NO.	CUSTOMER	GEAR CENT.	TYPE
A-17794	9/30/59	J.R.M.	160.035/398/0	Robt. & Sch.	21.1 -011	299
A-17795	9/30/59	J.R.M.	n	- 11 II M	21 1 -0"	rı
A-17800	10/9/59	J.R.M.	π	Dreyfus	21 ' -0"	18
A-17802	10/21/59	J.R.M.	u	Bernuth-	21 -0"	17
A-17807	11/2/59	J.R.M.	Ħ	Lembeke Dreyfus	21 ' -0"	n
A-17808	11/6/59	J.R.M.	n	!1	21 - 0"	n
A-17810	11/6/59	J.R.M.	, n	· 11	21 ' -0"	
A-17813	11/13/59	J.R.M.	II.	II	21 ' -0"	II.
A-17815	11/19/39	A.S.K.	u	н	21' -0"	11
A-17820	11/30/59	A.S.K.	11	Amer.Trading	21 ' -0"	11
A-17843	1/4/60	A.S.K.	n	Dreyfus	21 - 0"	n
A-17848	1/5/60	A.S.K.	≥ n	Argentine Lines	21 1 -0"	it.
A-17866	3/1/60	A.S.K.	·_ "		21 -0"	ti.
A-17926	8/30/61	E.S.C.	tt	Dreyfus	21 ' -0"	18
A-17927	8/30/61	E.S.C.	, u	n	21' -0"	If
A-17928	9/8/61	E.S.C.	u ,	Bulk-Trans.	21! -0"	rī
A-17929	9/21/61	R.E.H.	n	Beth. Steel	21' -0"	:1
A-17930	10/27/61	E.S.C.	19	Dreyfus	21 ! -0"	18
A-17931	11/3/61	R.E.H.	н	Robt. & Sch.	21 1 -0"	ıı
A-17956	12/7/61	E.S.C.	22	m m m	21 ' -0"	п
A-17957	1/10/61	A.B.S.	Ħ	Esso	21' -0"	IT
A-17958	1/10/61	No. CG	tt .	27	21 ' -0"	11

SERIAL NO.	DATE	INSP.	APP. NO.	CUSTONER .	GEAR CENT.	TYPE
A-17959	1/31/62	R.E.H.	160.035/389/0	Beth. Steel	21 1 (-0"	299
A-17966	2/19/62	E.S.C.	. п	Scony-Mobile	21 -0"	ıı
A-17967	2/28/62	E.S.C.	n .	Jaish-Hendg. Co		f‡
A-17968	3/22/62	E.S.C.	· n	Gibbs Corp.	21 ' =0"	:1
A-17969	4/10/62	E.S.C.	11	Gibbs Corp.	21 -0"	n
A-17970	4/11/62	E.S.C.	IT	Robt. & Sch.	21 -0"	11
A-17971	4/24/62	J.H.B.	• #	11 11 11	21 -0"	iŧ
A-17974	5/17/62	H.W.C.	ĦŢ	Isthmian	21 -0"	IT
A-17975	6/7/62	E.S.C.	n	Cont. Amer.	21 -0"	
A-17976	6/21/62	E.S.C.	, , , , , , , , , , , , , , , , , , ,	Panama Trans.		"
A-17977	7/19/62	E.S.C.	II	Cont. Amer.	21 ' -0"	ff.
A-17989	9/5/62	H.W.C.	IT	Keystone	21' -0"	
A-17990	9/27/62	J.E.H.	H 👊	n n	21' -0"	, #
A-17991	9/27/62	J.E.H.	rr		2; ' =0"	17
A-17992	10/9/62	J.E.H.	n *•	Socony-Mobile	21' -0"	n
A-18011	10/19/62	J.E.H.	ite.	Bell & Co.	21 -0"	11
A-18012	10/22/62	J.E.H.	if	, n n n	21' -0"	rt .
A-18013	11/5/62	H.W.C.	17		21' -0"	51
A-18014	11/23/62	H.W.C.	п	Del-Mar	21' -0"	IT
A-18015	11/26/62	H.W.C.	* -	Reynolds	21 0 !!	11
A-18017	-11/29/62	-	18	TF .	211 -0"	17
A-18019		H.W.C.	11	u J	21 0 "	u
	12/3/62	H.W.C.	ti	Amer. Foreign Overseas-Nav.	21 -0"	Iŧ
	12/11/62	H.W.C.	n	if if	21 ' -0"	II
A-18021	1/8/63	J.E.H.	11	Reynolds	21' -0"	TT .

SERIAL NO.	DATE	INSP.	APP. NO.	CUSTOMER G	EAR CENT.	Ti
A-18022	1/11/63	H.W.C.	160.035/398/0	Robt. & Sch.	21 1 -0#	299
A-18023	1/10/63	J.E.H.	п	Reynolds	21' -0"	n
A-18024	2/1/63	H.W.C.	n · — -	n n	21 1 -0"	п
A-18039	2/14/63	H.W.C.	π	Esso-Inter.	21 · -0"	π
A-18040	2/28/63	J.E.H.	. #	Dreyfus	21' -0"	π
A-18041	3/11/63	H.W.C.	H	π	21' -0"	, п
A-18042	3/13/63	H.W.C.	, n	Robt. & Sch.	21 - 0"	π
A-18043	6/7/63 	J.E.H.	н .	Pittsburgh St. Co.	217 -0"	п
A-18044	6/11/63	J.E.H.	tt	Lloyd-Bras.	21' -0"	п
A-18066	6/27/63	J.E.H.		пп	21 ' -0"	п
A-18067	7/18/63	J.E.H.	tf	Joshua-Hendy Co.	21' -0"	π
A-18068	7/18/63	J.Z.Ĥ.	11	Dreyfus	211 -0"	प्र
A-18069	8/2/63	J.E.H.	≈ π	Haritime-Overseas	211 -0"	л
A-18070	9/4/63	J.E.H.	18	Dreyíus	21' -0"	π
A-18071	12/3/63	J.E.H.	,•	π .	211 -0"	π
A-18077	12/4/63	J.E.H.	. 11	Beth. Stl.	21 1 -0"	π
A-18Q78	1/9/64	R.F.B.	n ,	Hercury Marine	21' -0"	. #
A-18079	1/9/64	R.F.B.	t r	Dreyfus	21' -0"	Ħ
A-18080	2/13/64	R.F.B.	17	Stock	21 -0"	π
A-18081	2/14/64	R.F.B.	n	nt	21 t -Om	я
<u>A-18082</u>	2/19/64	R.F.A.	π	Sum Oil Co.	21 t -0"	7
-A-18090	4/29/64	R.F.B.	п	Stock	21 t -0 ⁿ	R
A-18091	5/8/64	R.F.B.	11	п	21" -0"	77

SERIAL NO.	DATS	INSP.	APP. NO.	CUSTOMER	GEAR CENT.	TYPE
A-18092	6/22/64	R.F.B.	160.035/398/0	Stock	21 ' -0"	299
A-18093	6/22/64	R.F.3.	π	Amer. Ship	21 - 0"	. n
A-18094	9/3/64	R.F.B.	и	Newport News	21 ' -0"	tt.
A-18095	9/8/64	2.7.3.	π	п п	21 -0"	15
A-letos	2/21/64	R.F.B.	. "	m if	21 * =0"	ıt

24' STEEL LIFEBOAT (H.P.) (DWG. 80275)

SERIAL NO.	DATE	ĬMSP.	APP. HO.	CUSTOMER	GEAR CENT.	GEAR TYPE
A-17864	2/23/60	A.S.K.	160.035/611/0	Drayfus	21! -0"	299
A-17867	3/2/60	A.S.K.	•	Marine-Nav.	21' -0"	11
A-17835	6/22/60	W.D.		Alabama D.D.	21 -0"	11
A-17896	2/22/60	w.D.	. п	п п	211 -0"	
A-17916	2/28/61	E.S.C.	11 ~	Sinclair-Ref.	21 -0"	11
A-17917	2/28/51	E.S.C.	n	Todd-Texas	21 * -0 **	Ħ
A-17938	9/1/61	E.S.C.	я •_	Dreyfus	21 ' -0"	11
A=17939	9/11/61	E.S.C.	n	Bulk-Trans.	21 -0"	rt
A-17960	12/18/61	E.S.C.	π	Robt. &. Sch.	21 ' -0"	π .
A-17961	1/18/62	E.S.C.	u	Maritime Supp.	21 ' -0"	п
A-17962	3/15/62	E.S.C.	n .	Robt. & Sch.	21 -0"	tī.
A-17963	4/27/62	E.S.C.	r II	11 14 14	21 ' -0"	!*
A-17972	8/16/62	H.W.C.	n	и и и	21: -0"	17 .
A-17973	9/13/62	J.E.H.	17	Keystone	21' -0"	
A-17987	10/26/62	J.E.H.	Ħ	Del-Mar	21 - 0"	11
A-17988	10/31/62	H.W.C.	tt .	Bulk-Trans.	21 1 -0"	Ħ

SERIAL NO.	DATE	Insp.	APP. NO.	CUSTOMER	GEAR CENT.	GEAR TYPE
A-18018	11/30/62	H.W.C.	160.035/411/0	Raynoids	21 * -0"	29
A-18035	2/1/63	H.W.C.	"	и п	21	
A-18036	6/10/63	J.E.H.	11	Mathiasen	21 -0"	ıt
A-18072	10/16/63	J.E.H.	ır	Todd	21 -0"	11
A-18073	10/31/63	J.E.H.	11	TransAmer.	21 -0"	n
A-18074	11/12/63	J.E.H.	tf	Dreyfus	21 1 -0"	. 11
À-18075	12/3/63	J.E.H.	a tt	Stock -	21 ' _0"	11
A-18083	3/16/64			Grandcolumbian		299
A-18084	4/3/64	R.F.B.		AmerShip	211 -0#	233 It
A-18085	4/3/64		n	Grandcolumbian	41 -Q#	ı ,
A-18086	4/16/64	R.F.B.	tt	AmerShip	21' -0"	π
-						
		(MOT	24' STEEL LIFER OR PROPELLED (DWG.		DIESEL ENGINE	
SERIAL NO.	DATE	INSP.	APP. NO.	CUSTOMER	CEAR	
A-18087	4/28/64	R.F.B.	160.035/412/1	Robt. & Sch.	CENT. 21' -0"	<u>TYPE</u> 299
A-18106	9/28/64	****	н ,	C-7009 Newport News	21' -0"	ÌŦ
					GAS ENGINE	
-18004	6/6/63	J.E.H.	160.035/412/0	Stock	21' -0"	299

The agents representing Welin in this country. capable of supervising or install the new extended type breast plate are as follows:

- Welin Davit and Boat Division of Continental Copper & Steel Industries, Inc. 500 Market Street Perth Amboy, New Jersey
- Bell and Company
 255 Beauregard Street
 Mobile, Alabama
- 3. Del-Mar Corporation 8601 Gulf Freeway Houston 17, Texas
- Dreyfus Supply & Machine Company
 2122 Kentucky Street
 New Orleans, Louisiana
- Roberton & Schwartz, Inc.
 163 Main Street
 San Francisco, California